

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
A-01	9/17/2026 7:39:23 AM	57.7	40.3	0.0	2.0			1.4	0.0	84.5		-25.51				25.633		-25.01		28.85	1174	34.4312288	-118.6437712	
A-02	9/17/2026 7:48:47 AM	57.5	40.7	0.0	1.8			1.4	0.0	90.9	91.0	-13.75	-13.77			13.793	13.865	-13.25	-13.35	28.85	1162	34.4316565	-118.6433610	
A-03	9/17/2026 8:00:42 AM	48.1	38.3	1.9	11.7			1.3	6.2	80.0	80.1	-25.28	-25.32			25.399	25.471	-24.40	-24.51	28.85	1193	34.4319923	-118.6428522	
A-04	9/17/2026 8:10:05 AM	56.4	41.2	0.0	2.4			1.4	0.0	95.5	95.5	-24.19	-24.30			24.331	24.471	-23.70	-23.43	28.85	1204	34.4322172	-118.6422053	
A-05	9/28/2026 8:50:32 AM	58.5	40.0	0.0	1.5			1.5	0.0	88.1	88.1	-21.69	-21.63			21.774	21.670	0.00	0.00	28.59	1195	34.4325068	-118.6416402	
B-01	9/17/2026 9:22:43 AM	5.5	20.4	0.0	74.1			0.3	0.0	76.1	76.2	-1.52	-1.51	2.1	2.1	1.119	1.077	-22.12	-21.94	28.81	1238	34.4338618	-118.6396167	
B-02R	9/17/2026 9:16:57 AM	30.3	29.4	0.0	40.3			1.0	0.0	75.0	75.0	-3.44	-3.74	2.3	3.0	0.552	0.890	-22.29	-22.18	28.81	1239	34.4335615	-118.6395132	
B-03R	9/16/2026 1:51:26 PM	21.9	26.7	0.0	51.4			0.8	0.0	87.2	87.1	-0.92	-0.92	1.7	1.8	0.751	0.846	-20.73	-20.85	28.74	1224	34.4337940	-118.6388338	
B-05	9/16/2026 2:03:40 PM	11.9	25.0	0.3	62.8			0.5	209.3	92.5	92.6	-0.40	-0.46	5.6	5.6	0.189	0.186	-20.90	-20.61	28.73	1208	34.4336167	-118.6382465	
B-06	9/17/2026 8:53:22 AM	21.9	27.2	0.0	50.9			0.8	0.0	79.2	79.3	-0.71	-0.74	3.8	4.2	0.087	0.103	-21.12	-20.78	28.82	1220	34.4340185	-118.6377473	
B-07R	9/16/2026 10:45:52 AM	26.7	26.9	1.6	44.8			1.0	28.0	89.0	90.0	-0.96	-0.87	8.5	7.7	18.741	15.405	-21.67	-21.81	28.78	1215	34.4342898	-118.6374210	Valve Adjustment: NSPS/EG CAI
B-07R	9/16/2026 10:52:10 AM	32.0	29.4	0.5	38.1			1.1	76.2	94.8	94.9	-1.37	-1.33	3.5	5.3	0.248	0.564	-20.76	-21.96	28.78	1211	34.4342747	-118.6374130	Valve Adjustment: NSPS/EG CAC, Orifice Plate Changed (See OP Log)
B-08	9/17/2026 8:39:40 AM	0.4	1.7	20.5	77.4			0.2	3.8	69.6	69.8	-20.91	-20.86	1.0	1.2	0.007	0.008	-20.49	-20.46	28.83	1231	34.4337560	-118.6373313	Valve Adjustment: NSPS/EG CAI, High O2, Valve 100% Open
B-08	9/17/2026 8:44:20 AM	4.2	6.3	15.3	74.2			0.7	4.8	68.1	68.3	-21.00	-21.00	0.5	0.7	0.004	0.010	-20.53	-20.50	28.82	1222	34.4337668	-118.6373377	Valve Adjustment: NSPS/EG CAI, Orifice Plate Changed (See OP Log), No Flow Measurement, High O2
B-09	9/16/2026 9:27:25 AM	34.0	32.8	0.0	33.2			1.0	0.0	93.0	93.0	-0.44	-0.43			0.433	0.428	-18.99	-19.08	28.77	1200	34.4342120	-118.6370480	
B-10	9/16/2026 9:20:22 AM	26.4	29.1	0.0	44.5			0.9	0.0	90.5	90.9	-0.27	-0.38			0.266	0.375	-19.00	-19.03	28.74	1223	34.4340105	-118.6365542	
B-11	9/16/2026 8:54:56 AM	26.3	30.0	0.3	43.4			0.9	144.7	106.2	106.2	-0.42	-0.41	12.1	15.1	0.332	0.514	-18.82	-18.99	28.81	1149	34.4348338	-118.6368885	
B-12	9/16/2026 1:43:21 PM	15.2	26.0	0.0	58.8			0.6	0.0	96.1	96.3	-1.29	-1.29	10.4	10.1	0.655	0.619	-20.77	-20.95	28.74	1218	34.4340710	-118.6385075	
B-13	9/16/2026 1:37:34 PM	28.6	30.6	0.1	40.7			0.9	407.0	93.8	93.8	-0.90	-0.87			0.862	0.869	-20.97	-21.27	28.74	1210	34.4344482	-118.6378995	
B-14	9/16/2026 8:34:59 AM	14.4	27.4	0.0	58.2			0.5	0.0	104.6	105.1	-0.73	-1.41	2.5	2.7	0.670	0.788	-19.54	-19.53	28.81	1127	34.4349353	-118.6370485	
C-03	9/14/2026 1:58:34 PM	54.2	38.4	0.5	6.9			1.4	13.8	97.3	97.3	-28.42	-28.06			28.451	28.061	-28.21	-27.91	28.62	1174	34.4314085	-118.6435793	
C-07	9/30/2026 3:03:49 PM	50.5	41.1	0.0	8.4			1.2	419.5	98.0	97.9	-14.02	-14.02			14.179	14.076	-14.09	-14.01	28.59	1186	34.4326427	-118.6414348	Valve Adjustment: Valve 100% Open, Reduce Sys. Vac. - Flare Down
C-08	9/17/2026 10:13:25 AM	26.8	25.5	6.9	40.8			1.1	5.9	84.8	85.0	-23.42	-23.61			23.561	23.704	-22.94	-23.11	28.85	1200	34.4336425	-118.6408665	Valve Adjustment: NSPS/EG CAI, High O2
C-08	9/17/2026 10:15:37 AM	30.4	28.3	4.9	36.4			1.1	7.4	84.9	85.1	-23.49	-23.36			23.672	23.569	-23.13	-22.92	28.85	1201	34.4336492	-118.6408757	Valve Adjustment: NSPS/EG CAI
C-10	9/17/2026 10:44:49 AM	55.6	40.5	0.2	3.7			1.4	18.5	93.0	93.0	-23.70	-23.95			23.989	24.172	-23.27	-23.50	28.86	1217	34.4347212	-118.6411873	
C-11	9/3/2026 11:22:35 AM	56.7	40.3	0.0	3.0			1.4	0.0	98.8	98.9	-14.94	-15.07	17.5	15.5	0.705	0.555	-14.87	-14.97	28.76	1217	34.4352285	-118.6413333	Valve Adjustment: Audible Flow
C-12	9/3/2026 11:48:07 AM	55.7	40.6	0.0	3.7			1.4	0.0	95.3	96.2	-15.85	-16.02	11.0	10.4	0.762	0.687	-17.11	-17.22	28.77	1224	34.4359657	-118.6408995	Valve Adjustment: Audible Flow
C-15	9/3/2026 11:44:12 AM	49.1	37.1	2.3	11.5			1.3	5.0	97.8	97.9	-13.88	-13.86	17.3	16.2	0.690	0.606	-13.96	-13.88	28.78	1223	34.4362487	-118.6410603	Valve Adjustment: Audible Flow
C-17B	9/29/2026 9:29:28 AM	54.2	42.1	0.0	3.7			1.3	0.0	110.2	110.2	-16.75	-16.45			16.692	16.465	-17.52	-17.07	28.49	1229	34.4373565	-118.6419128	
C-18	9/29/2026 10:05:18 AM	53.0	41.7	0.2	5.1			1.3	28.1	114.8	114.8	-13.09	-12.82			13.039	12.854	-12.96	-12.92	28.49	1227	34.4379753	-118.6426142	Valve Adjustment: Valve 100% Open
C-19	9/29/2026 9:49:37 AM	55.2	41.6	0.0	3.2			1.3	0.0	98.8	98.9	-17.14	-17.12			17.151	17.051	-17.11	-17.11	28.49	1223	34.4375627	-118.6421395	Valve Adjustment: Valve 100% Open
C-20	9/29/2026 9:55:47 AM	55.2	41.5	0.0	3.4			1.3	0.0	110.7	111.0	-17.12	-17.12			17.115	17.169	-17.11	-17.11	28.49	1220	34.4377778	-118.6424007	Valve Adjustment: Valve 100% Open
C-24	9/29/2026 9:39:17 AM	35.6	32.8	5.2	26.4			1.1	5.1	102.3	102.8	-1.73	-1.82			1.721	1.812	-17.23	-17.11	28.5	1216	34.4375213	-118.6421202	Valve Adjustment: NSPS/EG CAI, High O2, Increased Flow/Vacuum
C-24	9/29/2026 9:44:02 AM	36.9	33.6	4.5	25.1			1.1	5.6	103.7	103.6	-2.67	-2.62			2.637	2.668	-17.03	-17.20	28.49	1246	34.4375273	-118.6421290	Valve Adjustment: NSPS/EG CAC
C-25	9/25/2026 12:09:01 PM	0.1	0.6	21.0	78.3			0.2	3.7	124.3	124.5	-14.61	-14.62			15.091	15.132	-14.54	-14.55	28.71	1217	34.4371087	-118.6416640	Valve Comment: broken valve, Valve Adjustment: NSPS/EG CAI, Positive Static Press.
C-25	9/25/2026 12:10:05 PM	0.2	0.5	20.9	78.4			0.4	3.8	125.1	125.3	-14.82	-14.85			15.259	15.220	-14.56	-14.59	28.72	1220	34.4371008	-118.6416723	Valve Adjustment: NSPS/EG CAI, Positive Static Press.
C-26	9/25/2026 12:01:24 PM	47.6	44.1	0.0	8.3			1.1	0.0	110.0	110.0	-16.15	-16.25			16.569	16.617	-16.24	-16.25	28.72	1214	34.4366432	-118.6412978	
C-27	9/3/2026 11:37:39 AM	0.9	2.4	20.3	76.4			0.4	3.8	95.3	95.4	-13.49	-13.43	5.3	5.2	0.587	0.569	-13.98	-14.43	28.78	1228	34.4361717	-118.6409792	Valve Adjustment: NSPS/EG CAI, High O2, Decreased Flow/Vacuum, Barely Open, Surging Liquid in Well (Watered In)
C-27	9/3/2026 11:38:33 AM	0.1	0.8	20.6	78.5			0.1	3.8	95.8	95.8	-13.43	-13.43	5.0	5.0	0.522	0.522	-14.04	-13.80	28.76	1231	34.4361723	-118.6409863	
C-28	9/3/2026 11:18:29 AM	56.3	39.8	0.0	3.9			1.4	0.0	103.6	103.6	-8.39	-9.07	3.0	3.8	2.450	3.745	-15.77	-15.71	28.77	1225	34.4354082	-118.6413798	Valve Adjustment: Audible Flow, Increased Flow/Vacuum
C-29	9/21/2026 8:03:56 AM	47.0	49.8	0.0	3.2			0.9	0.0	109.4	109.2	-5.80	-5.83			5.883	5.887	-19.29	-19.01	28.7	1223	34.4348462	-118.6412337	
C-30	9/17/2026 10:25:51 AM	0.0	0.1	20.8	79.1			0.0	3.8	82.4	82.4	-0.52	-0.51	0.5	0.8	0.001	0.004	-22.63	-22.74	28.85	1241	34.4342405	-118.6412652	Valve Adjustment: NSPS/EG CAI, No Flow Measurement, High Temp
C-30	9/17/2026 10:32:06 AM	48.9	39.4	1.1	10.6			1.2	9.6	112.3	113.3	-2.44	-2.44	5.5	5.6	0.193	0.195	-23.36	-23.34	28.83	1240	34.4342668	-118.6412558	Valve Adjustment: NSPS/EG CAC, Increased Flow/Vacuum
CV-02	9/21/2026 10:39:51 AM	25.5	29.4	0.0	45.1			0.9	0.0	120.8	122.4	-0.81	-1.65	0.7	1.3	0.051	0.186	-25.35	-25.41	28.7	1248	34.4335690	-118.6413535	
CV-03	9/21/2026 12:58:06 PM	38.7	36.2	0.0	25.1			1.1	0.0	120.7	120.7	-10.10	-10.00	21.1	20.9	2.920	2.872	-20.99	-20.83	28.7	1237	34.433167	-118.6414605	
CV-04	9/30/2026 8:15:05 AM	37.2	36.6	0.7	25.6			1.0	39.3	118.1	118.0	-1.57	-1.56			1.572	1.573	-21.56	-21.58	28.57	1229	34.4331157	-118.6416692	
CV-05	9/4/2026 8:19:06 AM	55.5	40.8	0.0	3.8			1.4	0.0	106.0	106.0	-12.55	-12.66	3.3	3.1	0.228	0.210	-12.75	-12.87	28.68	1229	34.4328347	-118.6422322	Valve Adjustment: Increased Flow/Vacuum
CV-06	9/28/2026 3:58:30 PM	47.6	46.4	0.0	6.0			1.0	0.0	100.5	100.4	-18.39	-13.54	4.0	3.7	0.103	0.086	-21.10	-20.75	28.48	1227	34.4326880	-118.6428460	Valve Adjustment: Decreased Flow/Vacuum
CV-108-52	9/1/2026 7:25:00 AM																							

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [\"H2O]	Adj Stat Press [\"H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [\"H2O]	Adj Diff Press [\"H2O]	Sys Pressure [\"H2O]	Adj Avail Press [\"H2O]	Baro Press [\"Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-108-52	9/1/2026 7:25:00 AM						130000																	Air Tech Lab; [User entered 13%]
CV-108-52	9/2/2026 7:35:40 AM	15.6	69.0	0.0	15.4			0.2	0.0	61.0	60.7	10.57	12.65	0.0	0.0	-0.009	-0.011	12.63		28.68	1289	34.4333565	-118.6506533	NSPS/EG CAI,Positive Static Press.,Reduced System Vacuum
CV-108-52	9/2/2026 7:36:35 AM	15.6	71.2	0.0	13.2			0.2	0.0	59.0	59.0	11.01	11.01	0.0	0.0	-0.014	-0.012	11.02		28.68	1325	34.4333477	-118.6506358	NSPS/EG CAI,Positive Static Press.,Reduced System Vacuum
CV-108-52	9/10/2026 3:44:09 PM	48.6	51.3	0.0	0.1			0.9	0.0	107.3	108.9	1.07	-1.86			0.900	0.126	-3.51	-2.80	28.54	1288	34.434013	-118.6507085	Valve Adjustment: NSPS/EG CAC,Increased Flow/Vacuum,Barely Open
CV-108-52	9/10/2026 3:44:53 PM	49.6	50.4	0.0	0.0			1.0	0.0	108.7	108.6	-2.85	-2.89			0.209	0.209	-3.79	-4.04	28.53	1290	34.4333983	-118.6507048	
CV-108-52	9/22/2026 11:11:22 AM	40.7	35.6	4.5	19.2			1.1	4.3	97.8	97.9	-9.72	-9.17			0.004	0.011	-9.88		28.62	1260	34.4334630	-118.6506818	
CV-113	9/4/2026 7:00:00 AM					37																		AirTech Lab
CV-113	9/4/2026 7:00:00 AM						0																	AirTech Lab; [User entered 0%]
CV-113	9/14/2026 9:34:21 AM	0.3	1.6	18.7	79.4			0.2	4.2	97.6	97.8	-0.02	-0.02	0.8	0.8	0.004	0.004	-6.79	-6.79	28.56	1331	34.4369800	-118.6467277	Valve Adjustment: NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In)
CV-113	9/14/2026 9:35:35 AM	2.4	1.9	18.0	77.7			1.3	4.3	98.9	98.9	-0.03	-0.02	0.9	0.7	0.005	0.003	-6.83	-6.77	28.58	1352	34.4369782	-118.6467027	
CV-113	9/25/2026 10:33:54 AM	12.8	19.1	13.0	55.1			0.7	4.2	106.0	106.1	-0.01	-0.01	1.9	1.9	0.022	0.023	-7.89	-7.78	28.57	1328	34.4369592	-118.6467337	Valve Adjustment: High O2,Barely Open
CV-114	9/4/2026 8:22:00 AM					2200																		AirTech Lab
CV-114	9/4/2026 8:22:00 AM						180000																	AirTech Lab; [User entered 18%]
CV-114	9/8/2026 9:33:48 AM	0.8	81.3	0.0	17.9			0.0	0.0	189.9	189.8	-4.74	-4.61			4.706	4.592	-4.67	-4.76	28.61	1347	34.4367228	-118.6476567	Valve Adjustment: No Flow Measurement,High Temp
CV-114	9/8/2026 9:39:00 AM					3460																		AtmAA
CV-114	9/14/2026 8:28:09 AM	1.5	82.9	0.0	15.6			0.0	0.0	188.9	189.0	-7.52	-7.31			7.604	7.365	-7.53	-7.39	28.49	1341	34.4367189	-118.6476122	Valve Adjustment: No Flow Measurement,High Temp
CV-114	9/14/2026 8:30:00 AM					3730																		AtmAA
CV-114	9/21/2026 8:22:00 AM	3.0	79.4	0.0	17.6			0.0	0.0	189.0	189.0	-4.77	-4.56			4.808	4.687	-7.74	-7.12	28.6	1321	34.4367257	-118.6476236	Valve Adjustment: No Flow Measurement,High Temp
CV-114	9/21/2026 8:25:00 AM					3480																		AtmAA
CV-114	9/28/2026 8:16:00 AM	2.6	0.0	0.0	97.4				0.0	188.8	188.8	-8.17	-8.17			8.319	8.363	-8.81	-8.46	28.46	1353	34.4367287	-118.6476203	Valve Adjustment: No Flow Measurement,High Temp
CV-114	9/28/2026 8:20:00 AM					3070																		AtmAA
CV-114	9/28/2026 8:20:00 AM					3070																		AtmAA
CV-1424	9/3/2026 1:47:43 PM	49.0	40.3	0.0	10.7			1.2	0.0	106.5	106.6	-4.12	-3.36	29.6	24.8	5.602	3.900	-20.20	-21.13	28.45	1391	34.4351257	-118.6450895	Valve Adjustment: Decreased Flow/Vacuum
CV-1532A	9/1/2026 7:30:00 AM					1400																		Air Tech Lab
CV-1532A	9/1/2026 7:30:00 AM						230000																	AirTech Lab; [User entered 23%]
CV-1532A	9/1/2026 1:33:46 PM	1.2	70.8	1.1	26.9			0.0	24.5	101.4	102.1	-3.50	-3.64			3.465	3.487	-3.36	-3.50	28.69	1277	34.4338658	-118.6508396	Valve Adjustment: No Flow Measurement
CV-1532A	9/30/2026 3:06:52 PM	0.7	75.5	0.9	22.9			0.0	25.4	167.0	167.2	-7.59	-7.76			7.849	7.937	-7.69	-7.70	28.45	1281	34.4338700	-118.6508292	
CV-1534A-PI	9/2/2026 10:23:59 AM	7.9	78.1	0.0	14.0			0.1	0.0	135.3	131.1	-6.56	-6.40			6.986	6.748	0.53	0.67	28.72				Valve Adjustment: No Flow Measurement,High Temp
CV-1534A-PI	9/30/2026 3:09:20 PM	0.0	16.8	18.6	64.6			0.0	3.5	121.9	121.8	-0.09	-0.07			0.070	0.027	-0.07	-0.09	28.44	1276	34.4336273	-118.6508055	
CV-1535	9/1/2026 9:18:24 AM	45.5	48.3	0.0	6.2			0.9	0.0	105.4	105.5	-0.58	-0.53	0.0	0.0	0.643	0.554	-1.67		28.63	1296	34.4331213	-118.6502692	
CV-1535	9/4/2026 7:22:00 AM					2800																		AirTech Lab
CV-1535	9/4/2026 7:22:00 AM						180000																	AirTech Lab; [User entered 18%]
CV-1535	9/22/2026 11:06:11 AM	28.1	36.2	0.0	35.7			0.8	0.0	125.6	125.5	-6.94	-5.60	0.0	0.0	0.012	0.001	-9.75		28.59	1286	34.4333205	-118.6503402	
CV-1535	9/24/2026 2:43:07 PM	29.6	40.2	0.0	30.2			0.7	0.0	126.1	125.8	-5.40	-4.58			0.000	0.000	-7.31	-10.52	28.51	1298	34.4333198	-118.6503462	Valve Adjustment: Decreased Flow/Vacuum,Surging Liquid in Header
CV-1601D	9/15/2026 11:02:56 AM	51.2	42.2	0.0	6.6			1.2	0.0	112.2	113.5	-0.94	-1.18	7.2	12.8	1.088	3.446	-14.31	-13.96	28.67	1315	34.4311130	-118.6486610	Valve Adjustment: Audible Flow,Increased Flow/Vacuum
CV-1601D	9/21/2026 11:29:39 AM	44.9	43.8	0.0	11.3			1.0	0.0	115.5	115.1	-1.48	-1.28	13.0	9.6	3.558	1.950	-16.02	-17.73	28.69	1328	34.4311047	-118.6486582	Valve Adjustment: Audible Flow,Decreased Flow/Vacuum
CV-1601S	9/15/2026 11:06:57 AM	50.1	42.8	0.0	7.1			1.2	0.0	113.2	115.2	-1.21	-1.50	5.2	10.9	0.563	2.521	-13.96	-14.29	28.68	1314	34.4310925	-118.6486713	Valve Adjustment: Audible Flow,Increased Flow/Vacuum
CV-1601S	9/21/2026 11:25:45 AM	43.0	45.8	0.0	11.2			0.9	0.0	118.7	117.7	-1.81	-1.54	11.8	6.5	2.959	0.900	-17.09	-18.80	28.67	1323	34.4310993	-118.6486612	Valve Adjustment: Audible Flow,Decreased Flow/Vacuum
CV-1604	9/24/2026 10:50:44 AM	50.8	44.5	0.0	4.7			1.1	0.0	115.0	115.0	-0.18	-0.07	1.4	2.2	0.040	0.101	-13.70	-13.42	28.6	1296	34.4321622	-118.6450182	Valve Adjustment: Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-1701D	9/1/2026 8:45:21 AM	9.3	69.0	0.0	21.7			0.1	0.0	104.8	104.6	-14.14	-14.14	1.1	1.1	0.342	0.325	-16.83	-16.71	28.64	1323	34.4335742	-118.6433220	Valve Adjustment: Barely Open,Surging Liquid in Header,Plugged/Pinched Suspected
CV-1701S	9/1/2026 8:41:19 AM	22.5	65.0	0.0	12.5			0.3	0.0	130.8	130.5	-0.32	-0.31	1.3	1.1	0.011	0.008	-16.75	-16.76	28.65	1302	34.4335962	-118.6433337	Valve Adjustment: Barely Open
CV-1901	9/14/2026 9:48:47 AM	23.1	68.2	0.1	8.6			0.3	86.0	117.4	117.2	-4.42	-1.79	1.6	1.4	0.053	0.040	-7.68	-7.87	28.48	1339	34.4356837	-118.6508192	Valve Adjustment: Decreased Flow/Vacuum,Barely Open
CV-1901	9/16/2026 2:06:50 PM	16.9	73.8	0.2	9.1			0.2	45.5	109.6	108.1	-0.53	-0.72	2.0	1.9	0.083	0.072	-4.31	-4.69	28.57	1317	34.4356995	-118.6507963	Valve Adjustment: Barely Open
CV-1902A	9/1/2026 7:35:00 AM					310																		Air Tech Lab
CV-1902A	9/1/2026 7:35:00 AM						43000																	Air Tech Lab; [User entered 4.3%]

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [\"H2O]	Adj Stat Press [\"H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [\"H2O]	Adj Diff Press [\"H2O]	Sys Pressure [\"H2O]	Adj Avail Press [\"H2O]	Baro Press [\"Hg]	Elev [ft]	Latitude	Longitude	Comments	
CV-1902A	9/8/2026 10:47:01 AM	2.5	75.0	0.2	22.3			0.0	111.5	158.4	159.4	-5.70	-5.63	0.0	0.0	5.732	5.463	-5.27		28.65	1283	34.4345907	-118.6503337	NSPS/EG CAI,High Temp,Reduced System Vacuum	
CV-1902A	9/8/2026 10:50:00 AM					1290																			AtmAA
CV-1902A	9/16/2026 2:31:00 PM					869.5																			AtmAA
CV-1902A	9/16/2026 2:32:50 PM	12.4	72.3	1.3	14.0			0.2	10.8	157.7	157.8	-6.63	-6.42			6.857	6.629	-6.80	-6.60	28.61	1323	34.4345944	-118.6503040	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed	
CV-1902A	9/23/2026 2:32:08 PM	10.3	77.5	0.0	12.2			0.1	0.0	182.5	181.6	-7.43	-7.12			7.637	7.265	-7.73	-7.37	28.49	1311	34.4345912	-118.6502988	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed	
CV-1902A	9/23/2026 2:37:00 PM					1210																			AtmAA
CV-1902A	9/30/2026 2:35:00 PM					719																			AtmAA
CV-1902A	9/30/2026 2:40:44 PM	9.6	64.4	2.6	23.4			0.1	9.0	154.5	155.0	-6.05	-6.02			6.098	5.977	-6.06	-5.89	28.44	1312	34.4345939	-118.6502987	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed	
CV-1905	9/14/2026 1:14:41 PM	15.0	11.0	14.8	59.2			1.4	4.0	100.4	89.1	-0.42	-0.42	1.2	1.2	0.008	0.008	-23.43	-23.15	28.37	1389	34.4334972	-118.6459933	Valve Adjustment:Barely Open	
CV-1905	9/22/2026 9:36:40 AM	42.3	33.7	4.1	19.9			1.3	4.9	78.9	89.6	-0.30	-1.49	1.1	8.4	0.008	0.429	-14.08	-13.89	28.54	1398	34.4335026	-118.6459849	Valve Adjustment:Increased Flow/Vacuum,Barely Open	
CV-1905	9/24/2026 2:08:39 PM	53.1	45.7	0.0	1.2			1.2	0.0	111.3	111.4	-0.97	-1.11	10.2	9.1	0.663	0.520	-12.29	-11.71	28.45	1386	34.4334710	-118.6460140	Valve Adjustment:Increased Flow/Vacuum	
CV-2001	9/2/2026 8:39:57 AM	9.5	69.9	2.0	18.6			0.1	9.3	79.4	79.5	-8.38	-8.03	0.0	1.3	-0.229	0.042	-8.32		28.7	1224	34.4322745	-118.6505838	Reduced System Vacuum,	
CV-2001	9/9/2026 7:20:00 AM					1100																			AirTech Lab
CV-2001	9/9/2026 7:20:00 AM						100000																		AirTech Lab; [User entered 10%]
CV-2001	9/23/2026 8:47:00 AM	4.6	54.5	7.5	33.4			0.1	4.5	85.7	86.5	-11.67	-11.60	3.8	4.7	0.019	0.028	-11.68	-11.65	28.58	1262	34.4322705	-118.6505628	Valve Comment:Well too tall	
CV-2002	9/1/2026 2:10:00 PM					3900																			AtmAA
CV-2002	9/1/2026 2:10:00 PM						117100																		AtmAA; [User entered 11.71%]
CV-2002	9/1/2026 2:10:13 PM	12.4	71.4	0.3	15.9			0.2	53.0	185.8	185.8	-6.92	-6.94			6.991	7.031	-7.08	-7.10	28.71	1266	34.4328169	-118.6511726	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed	
CV-2002	9/8/2026 1:42:58 PM	15.2	73.0	0.6	11.2			0.2	18.7	185.6	185.6	-5.92	-5.00	0.0	0.0	-6.163	-5.003	-4.44		28.68	1289	34.4326590	-118.6510465	NSPS/EG CAI,High Temp,Reduced System Vacuum	
CV-2002	9/8/2026 1:45:00 PM					4130																			AtmAA
CV-2002	9/9/2026 7:25:00 AM					2900																			AirTech Lab
CV-2002	9/9/2026 7:25:00 AM						140000																		AirTech Lab; [User entered 14%]
CV-2002	9/17/2026 8:11:35 AM	24.9	67.9	0.4	6.8			0.4	17.0	183.5	183.4	-6.40	-6.23			6.612	6.322	-10.78	-9.77	28.79	1274	34.4328224	-118.6511977	Valve Adjustment:No Flow Measurement,High Temp	
CV-2002	9/17/2026 8:13:00 AM					2270																			AtmAA
CV-2002	9/24/2026 9:58:49 AM	9.8	72.3	0.0	17.9			0.1	0.0	184.2	184.3	-10.65	-10.45			11.109	10.957	-11.71	-10.76	28.64	1268	34.4328016	-118.6511557	Valve Adjustment:No Flow Measurement,High Temp	
CV-2002	9/24/2026 10:10:00 AM					2900																			AtmAA
CV-2003	9/2/2026 7:38:27 AM	15.0	69.9	0.0	15.1			0.2	0.0	99.9	101.4	10.59	10.61	0.0	1.5	-0.051	0.298	10.62		28.68	1316	34.4332298	-118.6506550	NSPS/EG CAI,Positive Static Press.,Reduced System Vacuum	
CV-2003	9/2/2026 7:41:22 AM	15.3	71.9	0.0	12.8			0.2	0.0	98.4	98.8	13.76	13.25	2.5	2.3	0.787	0.666	13.25		28.68	1286	34.4335605	-118.6509697	NSPS/EG CAI,Positive Static Press.,Reduced System Vacuum	
CV-2003	9/10/2026 3:49:41 PM	48.3	51.7	0.0	0.0			0.9	0.0	123.9	123.9	-5.01	-5.03	1.5	1.5	0.234	0.252	-5.46	-5.66	28.55	1291	34.4333900	-118.6507330	Valve Adjustment:NSPS/EG CAC,Valve 100% Open	
CV-2003	9/10/2026 3:50:31 PM	24.9	68.6	0.0	6.5			0.4	0.0	123.9	123.8	-5.16	-5.22	1.3	1.3	0.183	0.178	-5.58	-5.39	28.53	1291	34.4333900	-118.6507330		
CV-2003	9/22/2026 11:14:52 AM	16.0	73.2	0.0	10.8			0.2	0.0	113.2	113.2	-9.57	-9.05	0.7	1.0	0.072	0.150	-9.90		28.62	1204	34.4334478	-118.6508902		
CV-2006	9/8/2026 10:53:00 AM	2.8	76.5	0.0	20.7			0.0	0.0	185.6	185.8	-3.36	-3.37	0.0	0.0	-0.010	-0.010	-5.67		28.64	1362	34.4352133	-118.6507100	NSPS/EG CAI,High Temp,Reduced System Vacuum	
CV-2006	9/8/2026 11:05:00 AM					2560																			AtmAA
CV-2006	9/16/2026 2:22:00 PM					3660																			AtmAA
CV-2006	9/16/2026 2:23:56 PM	12.8	77.6	0.0	9.6			0.2	0.0	186.3	186.2	-4.30	-4.30	17.9	17.1	0.470	0.429	-7.08	-7.20	28.6	1328	34.4352240	-118.6506578	Valve Adjustment:High Temp	
CV-2006	9/23/2026 2:26:56 PM	12.7	66.8	0.0	20.5			0.2	0.0	185.0	185.0	-4.39	-4.34	16.3	12.1	0.392	0.216	-8.24	-7.83	28.49	1318	34.4352382	-118.6506570	Valve Adjustment:High Temp	
CV-2006	9/23/2026 2:29:00 PM					3680																			AtmAA
CV-2006	9/30/2026 2:25:00 PM					4140																			AtmAA
CV-2006	9/30/2026 2:27:51 PM	8.5	78.2	0.0	13.3			0.1	0.0	185.9	185.9	-5.43	-4.67	13.2	17.2	0.257	0.437	-8.43	-8.59	28.44	1326	34.4352046	-118.6506651	Valve Adjustment:High Temp	
CV-2007	9/3/2026 10:00:55 AM	16.8	76.7	0.0	6.5			0.2	0.0	126.2	126.3	-1.12	-1.15	4.3	5.0	0.051	0.068	-5.37	-5.39	28.53	1379	34.4361438	-118.6470322	Valve Adjustment:Barely Open	
CV-2007	9/4/2026 7:48:00 AM					470																			AirTech Lab
CV-2007	9/4/2026 7:48:00 AM						62000																		AirTech Lab; [User entered 6.2%]
CV-2007	9/25/2026 2:05:13 PM	9.6	40.3	2.3	47.8			0.2	20.8	147.0	147.2	-1.11	-1.15	2.5	1.3	0.018	0.005	-9.99	-10.10	28.45	1367	34.4361393	-118.6469917	Valve Adjustment:High Temp,Barely Open	
CV-2007	9/28/2026 10:15:15 AM	8.3	37.5	2.7	51.5			0.2	19.1	152.5	152.5	-2.02	-2.02	10.2	8.6	0.071	0.050	-11.82	-11.84	28.44	1381	34.4361788	-118.6469867	Valve Adjustment:High Temp,Decreased Flow/Vacuum	
CV-2007	9/30/2026 10:12:39 AM	8.3	36.1	3.0	52.6			0.2	17.5	150.5	148.3	-1.88	-1.23	3.5	2.5	0.036	0.018	-10.69	-10.76	28.47	1374	34.4361776	-118.6470183	Valve Adjustment:High Temp,Well Comment:Bad valve on well head;Well Condition:Fair;Well Repairs:Valve	
CV-2007	9/30/2026 10:14:47 AM	8.0	36.4	3.3	52.3			0.2	15.8	146.5	146.4	-1.14	-1.13	1.4	1.0	0.006	0.003	-10.28	-10.29	28.47	1374	34.4361770	-118.6470180		

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading	H2 Reading	CH4:CO2	BalO2	Init Temp	Adj Temp	Init Stat Press	Adj Stat Press	Init Flow	Adj Flow	Init Diff Press	Adj Diff Press	Sys Pressure	Adj Avail Press	Baro Press	Elev	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]	[ppmv]	[ppmv]		[%]	[°F]	[°F]	[\"H2O]	[\"H2O]	[scfm]	[scfm]	[\"H2O]	[\"H2O]	[\"H2O]	[\"H2O]	[\"Hg]	[ft]			
CV-2008	9/3/2026 9:55:07 AM	45.9	54.1	0.0	0.0			0.8	0.0	96.3	96.4	-2.31	-2.08	0.0	0.0	0.001	0.000	-2.37	-2.39	28.52	1361	34.4361932	-118.6462488	Valve Adjustment:Decreased Flow/Vacuum
CV-2008	9/25/2026 2:19:23 PM	41.2	57.0	0.0	1.8			0.7	0.0	101.7	101.7	-0.93	-0.79	0.8	0.4	0.177	0.032	-2.08	-2.06	28.45	1372	34.4362572	-118.6462565	Valve Adjustment:Barely Open,Surgling Liquid in Header
CV-2009	9/10/2026 1:22:30 PM	41.0	58.4	0.6	0.0			0.7	0.0	138.0	138.0	-0.57	-0.59	19.0	18.8	0.484	0.478	-2.08	-2.08	28.49	1355	34.4362693	-118.6452872	Valve Adjustment:Barely Open
CV-2009A	9/14/2026 1:25:59 PM	35.5	61.1	0.0	3.4			0.6	0.0	149.9	150.4	-2.50	-2.29	1.1	1.0	0.009	0.008	-3.95		28.4	1348	34.4360450	-118.6453020	NSPS/EG CAI,High Temp
CV-2009A	9/14/2026 1:27:41 PM	32.5	63.7	0.0	3.8			0.5	0.0	150.2	150.3	-2.24	-2.23	1.3	1.3	0.013	0.013	-4.00		28.4	1312	34.4358952	-118.6453217	NSPS/EG CAI,High Temp
CV-2009A	9/14/2026 2:27:00 PM					913																		AtmAA
CV-2009A	9/14/2026 2:28:48 PM	30.1	63.9	0.0	6.0			0.5	0.0	151.4	151.3	-2.86	-2.87	4.9	5.1	0.167	0.176	-4.87	-4.84	28.38	1395	34.4359809	-118.6452555	Valve Adjustment:Audible Flow,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2009A	9/21/2026 1:44:33 PM	35.2	64.5	0.0	0.3			0.5	0.0	151.5	151.6	-2.27	-2.25	7.5	7.4	0.381	0.366	-3.79	-3.85	28.49	1392	34.4359827	-118.6452533	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2009A	9/21/2026 1:45:00 PM					1300																		AtmAA
CV-2010	9/22/2026 9:53:51 AM	41.3	51.2	0.1	7.4			0.8	74.0	89.1	89.2	-19.70	-19.69	1.4	1.8	0.002	0.004	-19.35		28.57	1394	34.4355675	-118.6435675	.
CV-2010A	9/22/2026 9:49:39 AM	43.1	44.1	0.3	12.5			1.0	41.7	85.1	85.4	-17.16	-17.09	34.1	31.5	3.092	2.638	-19.66		28.57	1312	34.4357355	-118.6435607	.
CV-2011	9/1/2026 10:17:28 AM	47.1	37.6	0.0	15.3			1.3	0.0	128.3	127.6	-8.44	-6.03	16.8	12.9	0.380	0.222	-14.70	-15.29	28.6	1336	34.4342182	-118.6434390	Valve Adjustment:Decreased Flow/Vacuum
CV-2011A	9/2/2026 2:08:11 PM	30.8	56.0	0.0	13.2			0.6	0.0	152.0	152.0	-2.29	-2.31	60.1	66.6	1.000	1.231	-10.01	-11.58	28.6	1334	34.4345479	-118.6431825	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2011A	9/2/2026 2:10:00 PM					1005																		AtmAA
CV-2011A	9/2/2026 2:10:00 PM						201200																	AtmAA; [User entered 20.12%]
CV-2011A	9/10/2026 9:14:08 AM	41.1	51.5	0.0	7.4			0.8	0.0	152.6	152.6	-3.35	-3.30	69.0	66.7	1.323	1.238	-11.35	-11.35	28.6	1327	34.4345323	-118.6431649	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2011A	9/10/2026 9:16:00 AM					719.5																		AtmAA
CV-2011A	9/11/2026 9:29:31 AM	28.1	46.4	0.0	25.5			0.6	0.0	152.7	152.7	-3.59	-3.60	80.0	84.5	1.789	1.996	-12.57	-12.51	28.53	1331	34.4345648	-118.6431363	Valve Adjustment:High Temp
CV-2011A	9/17/2026 10:27:00 AM					1250																		AtmAA
CV-2011A	9/17/2026 10:27:38 AM	36.0	50.8	0.0	13.2			0.7	0.0	151.4	151.3	-5.86	-5.79	64.1	49.0	1.142	0.666	-16.72	-14.99	28.75	1331	34.4345592	-118.6431607	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2011A	9/24/2026 2:22:16 PM	39.1	52.3	0.1	8.5			0.7	85.0	151.9	151.9	-4.17	-4.11	56.2	55.5	0.880	0.859	-12.93	-14.08	28.52	1337	34.4345394	-118.6431843	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2011A	9/24/2026 2:25:00 PM					800																		AtmAA
CV-2012	9/28/2026 1:57:34 PM	39.0	55.2	0.0	5.8			0.7	0.0	137.9	134.1	-3.50	-1.50	6.7	2.8	0.061	0.010	-15.00	-15.00	28.37	1329	34.4350002	-118.6433187	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2201-PLF	9/3/2026 7:56:39 AM	2.8	76.4	1.0	19.8			0.0	19.8	139.1	138.6	-9.55	-9.45			9.617	9.531	-9.62	-9.48	28.6	1349	34.4355665	-118.6488462	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2201-PLF	9/3/2026 7:57:44 AM	2.8	77.0	0.9	19.3			0.0	21.4	138.5	139.8	-9.56	-9.45			9.608	9.531	-9.60	-9.48	28.6	1343	34.4355577	-118.6488687	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2201-PLF	9/21/2026 8:20:29 AM	2.9	77.1	0.9	19.1			0.0	21.2	143.8	143.6	-10.08	-10.03			10.048	10.052	-9.97	-9.99	28.63	1356	34.4355463	-118.6488482	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2201-PLF	9/21/2026 8:21:42 AM	3.0	76.6	0.8	19.6			0.0	24.5	144.3	144.8	-9.95	-9.95			9.940	10.045	-9.82	-10.07	28.63	1355	34.4355523	-118.6488412	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2204-PLF	9/8/2026 2:13:18 PM	9.4	64.6	0.0	26.0			0.1	0.0	192.2	192.4	-1.24	-0.98			1.312	1.006	0.28	0.27	28.6	1379	34.4357913	-118.6474824	Valve Adjustment:No Flow Measurement,High Temp
CV-2204-PLF	9/8/2026 2:17:00 PM					1640																		AtmAA
CV-2204-PLF	9/14/2026 10:19:07 AM	11.8	69.4	0.0	18.8			0.2	0.0	191.9	191.9	-3.03	-2.86			3.154	2.836	0.34	0.34	28.49	1361	34.4357541	-118.6474728	Valve Adjustment:No Flow Measurement,High Temp
CV-2204-PLF	9/14/2026 10:26:00 AM					1540																		AtmAA
CV-2204-PLF	9/21/2026 10:25:45 AM	19.2	71.2	0.0	9.6			0.3	0.0	189.8	190.3	-7.94	-7.82			8.385	8.256	0.29	0.32	28.58	1350	34.4357693	-118.6474752	Valve Adjustment:No Flow Measurement,High Temp
CV-2204-PLF	9/21/2026 10:28:00 AM					1330																		AtmAA
CV-2204-PLF	9/28/2026 10:21:59 AM	15.3	72.1	0.0	12.6			0.2	0.0	192.6	193.5	-6.85	-5.24			7.305	5.732	0.34	0.34	28.46	1344	34.4357756	-118.6474776	Valve Adjustment:No Flow Measurement,High Temp
CV-2204-PLF	9/28/2026 10:25:00 AM					1320																		AtmAA
CV-2205	9/22/2026 10:12:14 AM	10.1	71.8	0.0	18.1			0.1	0.0	136.1	136.1	3.39	3.37	0.0	10.1	-0.034	0.033	3.37		28.54	1348	34.4341150	-118.6440615	NSPS/EG CAI,High Temp,Positive Static Press.
CV-2205	9/22/2026 10:43:00 AM	12.2	66.9	0.0	20.9			0.2	0.0	136.8	148.0	3.23	-0.12	0.0	28.3	-0.032	0.257	-21.52		28.53	1286	34.4342123	-118.6440915	NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-2205	9/22/2026 10:44:32 AM	10.1	72.7	0.0	17.2			0.1	0.0	148.6	148.5	-0.28	-0.15	18.6	19.3	0.115	0.123	-21.96		28.53	1319	34.4342518	-118.6441378	NSPS/EG CAI,High Temp
CV-2205	9/22/2026 1:55:00 PM					2840																		AtmAA
CV-2207	9/3/2026 1:27:19 PM	46.3	53.4	0.0	0.3			0.9	0.0	125.7	125.5	-0.24	-0.28	7.1	5.4	0.013	0.008	-16.17	-15.48	28.47	1395	34.4359843	-118.6442125	Valve Adjustment:Barely Open
CV-2208A	9/10/2026 9:58:00 AM					1150																		AtmAA
CV-2208A	9/11/2026 6:08:06 PM	20.2	61.2	0.0	18.6			0.3	0.0	149.8	152.6	-4.10	-4.08	4.6	3.4	0.006	0.003	-8.18	-8.22	28.45	1335	34.4365660	-118.6449336	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2208A	9/14/2026 1:18:15 PM	34.8	60.1	0.1	5.0			0.6	50.0	156.8	156.9	-2.78	-2.78	18.1	19.4	0.091	0.105	-7.20	-7.24	28.46	1345	34.4365576	-118.6449547	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2208A	9/14/2026 1:19:00 PM					1090																		AtmAA
CV-2208A	9/24/2026 2:05:00 PM					896																		AtmAA
CV-2208A	9/24/2026 2:07:36 PM	27.3	64.5	0.1	8.1			0.4	81.0	156.7	156.9	-2.76	-2.76	18.4	14.9	0.094	0.062	-6.59	-6.48	28.53	1361	34.4365752	-118.6449529	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [°H2O]	Adj Stat Press [°H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [°H2O]	Adj Diff Press [°H2O]	Sys Pressure [°H2O]	Adj Avail Press [°H2O]	Baro Press [°Hg]	Elev [ft]	Latitude	Longitude	Comments	
CV-2301	9/2/2026 9:11:34 AM	20.2	64.6	0.0	15.2			0.3	0.0	179.1	179.0	-9.44	-9.27			9.897	9.746	-11.32	-11.00	28.64	1359	34.433538	-118.6492161	Valve Adjustment:No Flow Measurement,High Temp	
CV-2301	9/2/2026 9:13:00 AM						775																		AtmAA
CV-2301	9/2/2026 9:13:00 AM																								AtmAA; [User entered 5.57%]
CV-2301	9/3/2026 6:40:00 AM						470																		AirTech Lab
CV-2301	9/3/2026 6:40:00 AM																								AirTech Lab; [User entered 5.5%]
CV-2301	9/8/2026 9:59:02 AM	22.0	48.9	3.9	25.2			0.4	6.5	167.1	167.3	-6.41	-6.37	76.3	74.3	6.462	6.133				28.62	1302	34.4334958	-118.6493157	NSPS/EG CAI,High Temp
CV-2301	9/8/2026 10:00:00 AM					1170																			AtmAA
CV-2301	9/16/2026 1:43:00 PM						830																		AtmAA
CV-2301	9/16/2026 1:46:53 PM	25.4	69.6	0.0	5.0			0.4	0.0	179.6	177.6	-5.55	-5.05			5.696	5.152	-5.80	-5.05	28.58	1342	34.4335202	-118.6492498	Valve Adjustment:No Flow Measurement,High Temp	
CV-2301	9/23/2026 1:27:45 PM	44.1	55.9	0.0	0.0			0.8	0.0	175.3	174.9	-6.56	-6.44			6.805	6.812	-6.92	-6.11	28.48	1341	34.4335060	-118.6492387	Valve Adjustment:No Flow Measurement,High Temp	
CV-2301	9/23/2026 1:31:00 PM						552																		AtmAA
CV-2301	9/30/2026 10:14:35 AM	43.3	46.5	10.2	0.0			0.9	0.0	174.4	174.6	-9.58	-8.80			10.143	9.533	-9.92	-8.63	28.49	1344	34.4335029	-118.6492130	Valve Adjustment:No Flow Measurement,High Temp	
CV-2301	9/30/2026 10:15:00 AM						495																		AtmAA
CV-2302	9/2/2026 8:56:46 AM	43.0	45.2	1.1	10.7			1.0	9.7	125.8	125.7	-12.16	-12.16			12.202	12.167	-12.30	-12.26	28.62	1350	34.4340338	-118.6492053	Valve Comment:Valve stuck open;Valve Adjustment:Valve 100% Open	
CV-2302	9/3/2026 6:45:00 AM					0																			AirTech Lab
CV-2302	9/3/2026 6:45:00 AM																								AirTech Lab; [User entered 3.5%]
CV-2302	9/17/2026 10:41:57 AM	44.5	45.0	1.1	9.4			1.0	8.5	113.0	113.3	-11.03	-12.03			11.395	12.325	-11.61	-12.93	28.71	1335	34.4340333	-118.6491978		
CV-2303	9/3/2026 6:50:00 AM					1700																			AirTech Lab
CV-2303	9/3/2026 6:50:00 AM																								AirTech Lab; [User entered 19%]
CV-2303	9/3/2026 7:49:00 AM						2165																		AtmAA
CV-2303	9/3/2026 7:49:00 AM																								AtmAA; [User entered 18.75%]
CV-2303	9/3/2026 7:52:16 AM	2.1	73.6	0.0	24.3			0.0	0.0	190.5		0.45				0.000		0.35		28.57	1353	34.4353804	-118.6496919	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press,Valve 100% Open,Well Condition:Lorentz Pump Installed	
CV-2303	9/3/2026 7:53:05 AM	3.2	79.0	0.0	17.8			0.0	0.0	188.1	189.1	0.46	0.41			0.000	0.000	0.47	0.27	28.57	1353	34.4353804	-118.6496916	Valve Adjustment:No Flow Measurement,High O2,Well Condition:Lorentz Pump Installed	
CV-2303	9/9/2026 8:46:47 AM	8.8	39.4	0.2	51.6			0.2	258.0	188.7	188.8	-0.25	-0.23			0.208	0.215	-0.58	-0.59	28.66	1367	34.4353876	-118.6496789	Valve Adjustment:No Flow Measurement,High Temp,Well Condition:Lorentz Pump Installed	
CV-2303	9/9/2026 8:50:00 AM						2470																		AtmAA
CV-2303	9/15/2026 9:24:00 AM	9.7	61.8	0.0	28.5			0.2	0.0	188.5	189.6	0.43	0.44			0.000	0.000	0.46	0.50	28.57	1365	34.4353806	-118.6496105	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press,Valve 100% Open,Well Condition:Lorentz Pump Installed	
CV-2303	9/15/2026 9:25:00 AM						2620																		AtmAA
CV-2303	9/22/2026 9:19:07 AM	6.4	78.9	0.0	14.7			0.1	0.0	192.6	193.1	0.26	0.22			0.000	0.000	0.08	0.00	28.57	1342	34.4353779	-118.6496979	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press,Valve 100% Open,Well Condition:Lorentz Pump Installed	
CV-2303	9/22/2026 9:21:00 AM						275																		AtmAA
CV-2304-PLR	9/3/2026 8:30:11 AM	4.0	74.2	0.1	21.7			0.1	217.0	173.4	173.7	-7.34	-7.39			7.956	8.023	-7.80	-7.94	28.59	1342	34.4345708	-118.6487343	Valve Adjustment:No Flow Measurement,High Temp	
CV-2304-PLR	9/3/2026 8:32:00 AM						1980																		AtmAA
CV-2304-PLR	9/3/2026 8:32:00 AM																								AtmAA; [User entered 19.02%]
CV-2304-PLR	9/9/2026 9:38:00 AM																								AtmAA
CV-2304-PLR	9/9/2026 9:42:30 AM	8.4	73.1	0.0	18.5			0.1	0.0	177.5	177.4	3.03	3.13			0.000	0.000	7.21	7.23	28.68	1336	34.4345555	-118.6487491	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.	
CV-2304-PLR	9/11/2026 2:24:49 PM	2.6	74.4	0.0	23.0			0.0	0.0	173.4	173.3	-4.86	-5.01			5.181	5.285	-5.13	-5.25	28.46	1338	34.4345404	-118.6487454	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum	
CV-2304-PLR	9/11/2026 2:25:38 PM	2.7	72.8	0.0	24.5			0.0	0.0	172.5	172.9	-4.98	-5.14			5.259	5.374	-5.23	-5.26	28.47	1341	34.4345383	-118.6487426		
CV-2304-PLR	9/15/2026 10:21:48 AM	15.9	69.0	0.0	15.1			0.2	0.0	176.0	176.8	-5.23	-5.05			5.737	5.501	-5.45	-5.14	28.58	1355	34.4345517	-118.6487781	Valve Adjustment:No Flow Measurement,High Temp	
CV-2304-PLR	9/15/2026 10:22:00 AM						1620																		AtmAA
CV-2304-PLR	9/22/2026 10:45:24 AM	15.0	72.1	0.0	12.9			0.2	0.0	175.7	176.4	-8.89	-8.72			0.440	0.527	-9.43	-9.16	28.57	1338	34.4345606	-118.6487636	Valve Adjustment:No Flow Measurement,High Temp	
CV-2304-PLR	9/22/2026 10:46:00 AM						1470																		AtmAA
CV-2304-PLR	9/29/2026 9:11:59 AM	26.1	60.7	0.0	13.2			0.4	0.0	177.6	178.0	-10.65	-10.78			11.139	11.202	-10.92	-10.95	28.39	1350	34.4345511	-118.6487367	Valve Adjustment:No Flow Measurement,High Temp,Well Condition:Lorentz Pump Installed	
CV-2304-PLR	9/29/2026 9:20:00 AM						1930																		AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [”H2O]	Adj Stat Press [”H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [”H2O]	Adj Diff Press [”H2O]	Sys Pressure [”H2O]	Adj Avail Press [”H2O]	Baro Press [”Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
CV-2305	9/1/2026 10:04:00 AM					2310																		AtmAA
CV-2305	9/1/2026 10:04:00 AM						50300																	AtmAA; [User entered 5.03%] Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	9/1/2026 10:04:41 AM	36.5	59.2	0.0	4.3			0.6	0.0	158.7	158.8	-4.76	-4.73			0.335	0.246	-14.45	-14.72	28.58	1377	34.4352305	-118.6465370	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	9/9/2026 8:05:00 AM					1200																		AirTech Lab
CV-2305	9/9/2026 8:05:00 AM						47000																	AirTech Lab; [User entered 4.7%] Valve Adjustment:High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2305	9/9/2026 10:42:39 AM	27.0	71.2	0.0	1.8			0.4	0.0	155.5	155.6	-4.99	-3.44			0.000	0.000	-13.18	-13.79	28.66	1395	34.4352253	-118.6465235	Valve Adjustment:High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2305	9/9/2026 10:43:11 AM	35.9	57.4	0.0	6.7			0.6	0.0	155.7	155.7	-2.38	-2.34			0.025	0.040	-9.22	-9.31	28.64	1395	34.4352253	-118.6465245	
CV-2305	9/9/2026 11:00:00 AM					2760																		AtmAA
CV-2305	9/15/2026 2:00:00 PM					2740																		AtmAA
CV-2305	9/15/2026 2:02:20 PM	26.5	73.5	0.0	0.0			0.4	0.0	163.4	163.8	0.86	-1.38			0.575	0.156	-4.09	-3.33	28.49	1393	34.4352168	-118.6465431	Valve Adjustment:NSPS/EG CAC,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-2305	9/15/2026 2:04:55 PM	26.3	73.7	0.0	0.0			0.4	0.0	163.6	163.7	-1.56	-1.51			0.144	0.173	-3.41	-3.44	28.5	1394	34.4352189	-118.6465414	Valve Adjustment:NSPS/EG CAC,High Temp;Well Condition:Lorentz Pump Installed
CV-2305	9/22/2026 2:28:38 PM	16.0	81.6	0.0	2.4			0.2	0.0	157.9	157.9	-5.10	-5.10			0.196	0.175	-8.03	-7.98	28.44	1384	34.4352159	-118.6465303	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	9/22/2026 2:31:00 PM					1530																		AtmAA
CV-2305	9/29/2026 1:49:58 PM	35.5	60.1	0.0	4.4			0.6	0.0	158.9	159.0	-6.52	-6.61			0.576	0.465	-9.17	-9.18	28.29	1385	34.4352313	-118.6465493	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	9/30/2026 10:00:00 AM					1380																		AtmAA
CV-2305	9/30/2026 10:01:12 AM	20.9	51.5	0.0	27.6			0.4	0.0	157.5	157.6	-8.45	-8.56			0.026	0.017	0.41	0.50	28.47	1384	34.4352078	-118.6465434	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2306-PLF	9/8/2026 1:31:32 PM	2.9	76.3	0.4	20.4			0.0	51.0	182.1	182.0	-5.62	-5.39			5.810	5.524	0.24	0.25	28.6	1360	34.4360807	-118.6478155	Valve Adjustment:No Flow Measurement,High Temp
CV-2306-PLF	9/8/2026 1:32:00 PM					1390																		AtmAA
CV-2306-PLF	9/14/2026 10:15:56 AM	13.0	71.2	0.4	15.4			0.2	38.5	144.5	144.9	-7.50	-7.08			7.932	7.460	0.34	0.34	28.49	1351	34.4360801	-118.6478323	Valve Adjustment:No Flow Measurement,High Temp
CV-2306-PLF	9/14/2026 10:16:00 AM					1530																		AtmAA
CV-2306-PLF	9/28/2026 10:16:32 AM	18.1	71.2	0.4	10.3			0.3	25.8	131.7	132.0	-10.16	-9.98			10.646	10.512	0.34	0.34	28.46	1348	34.4360900	-118.6478094	Valve Adjustment:No Flow Measurement,High Temp
CV-2306-PLF	9/28/2026 10:20:00 AM					1080																		AtmAA
CV-2308-PLF	9/3/2026 8:03:28 AM	3.4	77.8	0.5	18.3			0.0	36.6	121.3	120.6	-8.78	-8.90			8.964	9.016	-9.90	-9.82	28.6	1330	34.4350900	-118.6489253	Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump
CV-2308-PLF	9/21/2026 8:50:45 AM	4.4	76.6	0.6	18.4			0.1	30.7	118.8	117.4	-11.61	-11.63			11.543	11.534	-11.89	-12.19	28.63	1339	34.4350907	-118.6488948	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2310-PLF	9/3/2026 7:36:11 AM	2.1	70.2	0.0	27.7			0.0	0.0	197.6	198.2	-4.24	-3.15			4.503	3.049	0.04	0.04	28.53	1358	34.4353272	-118.6491432	Valve Adjustment:No Flow Measurement,High Temp
CV-2310-PLF	9/3/2026 7:40:00 AM					1770																		AtmAA
CV-2310-PLF	9/3/2026 7:40:00 AM						172000																	AtmAA; [User entered 17.2%] Valve Adjustment:No Flow Measurement,High Temp
CV-2310-PLF	9/9/2026 8:56:24 AM	6.3	84.5	0.0	9.2			0.1	0.0	192.2	192.6	-5.19	-5.05			4.685	5.478	0.08	0.08	28.67	1365	34.4353443	-118.6491270	Valve Adjustment:No Flow Measurement,High Temp
CV-2310-PLF	9/9/2026 8:59:00 AM					1680																		AtmAA
CV-2310-PLF	9/15/2026 9:36:20 AM	6.6	72.7	0.0	20.7			0.1	0.0	190.5	190.6	-6.34	-5.86			4.980	6.200	0.30	0.34	28.57	1350	34.4353240	-118.6491389	Valve Adjustment:No Flow Measurement,High Temp
CV-2310-PLF	9/15/2026 9:38:00 AM					1250																		AtmAA
CV-2310-PLF	9/22/2026 9:28:31 AM	6.7	70.6	0.0	22.7			0.1	0.0	191.6	191.7	-7.80	-7.58			8.368	8.181	0.34	0.34	28.57	1347	34.4353372	-118.6491464	Valve Adjustment:No Flow Measurement,High Temp
CV-2310-PLF	9/22/2026 9:31:00 AM					1060																		AtmAA
CV-2310-PLF	9/29/2026 8:57:01 AM	12.2	76.1	0.0	11.7			0.2	0.0	190.2	147.2	-11.12	-11.27			11.547	11.686	-11.25	-11.41	28.38	1368	34.4353250	-118.6491155	Valve Adjustment:Audible Flow,No Flow Measurement,High Temp,Valve 100% Open
CV-2310-PLF	9/29/2026 9:00:00 AM					1630																		AtmAA
CV-2311	9/8/2026 3:18:24 PM	17.6	61.0	0.0	21.4			0.3	0.0	164.5	166.2	-2.87	-2.90			2.912	3.027	-6.19	-6.44	28.6	1367	34.4362903	-118.6498959	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2311	9/8/2026 3:20:00 PM					1310																		AtmAA
CV-2311	9/15/2026 8:20:03 AM	24.8	66.9	0.0	8.3			0.4	0.0	169.4	169.6	-3.86	-3.85			3.868	3.877	-9.09	-8.88	28.51	1369	34.4363251	-118.6498674	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2311	9/15/2026 8:21:00 AM					766																		AtmAA
CV-2311	9/21/2026 2:22:27 PM	28.9	65.5	0.0	5.6			0.4	0.0	164.2		-4.57				4.552		-8.15		28.5	1368	34.4363155	-118.6498575	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2311	9/21/2026 2:26:00 PM					1400																		AtmAA
CV-2311	9/28/2026 3:16:00 PM					1380																		AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [”H2O]	Adj Stat Press [”H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [”H2O]	Adj Diff Press [”H2O]	Sys Pressure [”H2O]	Adj Avail Press [”H2O]	Baro Press [”Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
CV-2311	9/28/2026 3:16:22 PM	26.6	64.8	0.0	8.6			0.4	0.0	154.6	156.5	-6.40	-6.40			6.567	6.567	-10.61	-10.69	28.35	1374	34.4363078	-118.6498885	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2312-PLR	9/2/2026 8:09:16 AM	3.5	83.0	0.0	13.5			0.0	0.0	168.3	168.3	-3.87	-3.44	36.1	34.0	3.896	3.450	-5.03	-5.16	28.6	1380	34.4342335	-118.6473823	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	9/3/2026 7:00:00 AM					2600																		AirTech Lab
CV-2312-PLR	9/3/2026 7:00:00 AM						160000																	AirTech Lab; [User entered 16%]
CV-2312-PLR	9/9/2026 1:24:41 PM	17.4	71.0	0.1	11.5			0.2	115.0	169.7	169.6	-3.71	-3.72	35.4	33.4	3.747	3.340	0.01	0.00	28.63	1369	34.4342328	-118.6473481	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	9/9/2026 1:35:00 PM					3410																		AtmAA
CV-2312-PLR	9/16/2026 10:30:00 AM					3530																		AtmAA
CV-2312-PLR	9/16/2026 10:44:19 AM	5.0	79.9	0.0	15.1			0.1	0.0	169.6	169.5	-2.65	-2.15	29.4	27.0	2.568	2.167	-3.08	-2.32	28.6	1371	34.4342158	-118.6473707	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	9/23/2026 10:29:16 AM	43.9	53.5	2.6	0.0			0.8	0.0	170.0	170.1	-34.37	-34.04	98.5	98.6	33.361	33.361	-7.12	-8.04	28.49	1353	34.4342124	-118.6473826	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2312-PLR	9/23/2026 10:31:00 AM					2893																		AtmAA
CV-2312-PLR	9/23/2026 1:10:56 PM	6.8	79.1	0.0	14.1			0.1	0.0	169.8	169.8	-4.53	-4.39	39.0	37.6	4.586	4.276	-5.21	-5.07	28.45	1393	34.4342099	-118.6473883	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	9/30/2026 9:44:29 AM	6.4	79.0	0.0	14.6			0.1	0.0	169.9	170.0	-9.62	-9.44	57.5	57.1	10.190	10.059	-8.33	-8.88	28.46	1387	34.4342013	-118.6473798	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	9/30/2026 9:50:00 AM					2700																		AtmAA
CV-2314-PLR	9/1/2026 1:32:37 PM	11.3	76.9	0.0	11.8			0.1	0.0	187.2	187.3	-13.88	-13.98			14.092	14.231	-14.00	-14.19	28.54	1382	34.4346889	-118.6467118	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	9/1/2026 1:38:00 PM					4010																		AtmAA
CV-2314-PLR	9/1/2026 1:38:00 PM						120100																	AtmAA; [User entered 12.01%]
CV-2314-PLR	9/4/2026 7:56:00 AM					2700																		AirTech Lab
CV-2314-PLR	9/4/2026 7:56:00 AM						130000																	AirTech Lab; [User entered 13%]
CV-2314-PLR	9/9/2026 1:40:13 PM	23.0	76.3	0.0	0.7			0.3	0.0	188.1	188.1	-7.74	-7.41			7.812	7.556	-8.12	-7.75	28.57	1369	34.4346946	-118.646922	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	9/9/2026 1:46:00 PM					2810																		AtmAA
CV-2314-PLR	9/16/2026 9:36:00 AM					3550																		AtmAA
CV-2314-PLR	9/16/2026 9:39:58 AM	6.1	84.0	0.1	9.8			0.1	98.0	187.9	187.8	-4.97	-5.18			5.213	5.421	-5.38	-5.78	28.6	1372	34.4346964	-118.6467225	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	9/23/2026 9:37:50 AM	9.3	79.1	0.6	11.0			0.1	18.3	186.3	186.2	-12.90	-12.87			13.379	13.383	-13.61	-13.85	28.49	1375	34.4346966	-118.6469901	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	9/23/2026 9:40:00 AM					2960																		AtmAA
CV-2314-PLR	9/30/2026 8:54:14 AM	5.1	82.0	0.2	12.7			0.1	63.5	185.5	185.5	-11.15	-11.08			11.637	11.483	-11.77	-11.12	28.45	1372	34.4347186	-118.6467117	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	9/30/2026 9:00:00 AM					4010																		AtmAA
CV-2315	9/3/2026 9:13:05 AM	14.8	74.0	0.1	11.1			0.2	111.0	184.9	185.1	-2.07	-2.39			2.064	2.464	-2.51	-3.24	28.56	1377	34.4355163	-118.6472132	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	9/3/2026 9:17:00 AM					2450																		AtmAA
CV-2315	9/3/2026 9:17:00 AM						123800																	AtmAA; [User entered 12.38%]
CV-2315	9/4/2026 8:04:00 AM					2200																		AirTech Lab
CV-2315	9/4/2026 8:04:00 AM						170000																	AirTech Lab; [User entered 17%]
CV-2315	9/8/2026 1:48:37 PM	4.4	79.7	0.0	15.9			0.1	0.0	179.1	180.6	-0.43	-0.46			0.385	0.438	-0.83	-1.09	28.59	1393	34.4355047	-118.6471882	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	9/8/2026 1:51:00 PM					2730																		AtmAA
CV-2315	9/14/2026 10:40:35 AM	17.7	69.7	0.0	12.6			0.3	0.0	191.7	191.8	-1.77	-1.67			1.777	1.730	-2.12	-1.87	28.46	1375	34.4355061	-118.6471957	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	9/14/2026 10:44:00 AM					1710																		AtmAA
CV-2315	9/21/2026 10:37:20 AM	29.6	64.3	0.0	6.1			0.5	0.0	187.2	187.3	-4.79	-4.52			4.776	4.390	-6.84	-6.11	28.57	1368	34.4355172	-118.6472012	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	9/21/2026 10:41:00 AM					1530																		AtmAA
CV-2315	9/28/2026 10:36:48 AM	23.8	66.4	0.0	9.8			0.4	0.0	187.5	187.5	-5.20	-4.66			5.630	4.804	-6.34	-4.55	28.43	1371	34.4355098	-118.6471987	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	9/28/2026 10:40:00 AM					1360																		AtmAA
CV-2316	9/2/2026 1:39:54 PM	27.5	68.8	0.0	3.7			0.4	0.0	149.9	150.0	-2.23	-2.22	57.5	57.7	2.233	2.244	-3.12	-3.13	28.57	1401	34.4360321	-118.6463818	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2316	9/2/2026 1:45:00 PM					2030																		AtmAA
CV-2316	9/2/2026 1:45:00 PM						88600																	AtmAA; [User entered 8.86%]
CV-2316	9/3/2026 9:48:34 AM	20.4	69.4	0.0	10.2			0.3	0.0	149.7	149.8	-2.06	-2.06	55.1	55.2	2.049	2.061	-2.46	-2.44	28.51	1384	34.4360245	-118.6463840	Valve Adjustment:High Temp
CV-2316	9/10/2026 10:21:00 AM					2370																		AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading	H2 Reading	CH4: CO2	BalO2	Init Temp	Adj Temp	Init Stat Press	Adj Stat Press	Init Flow	Adj Flow	Init Diff Press	Adj Diff Press	Sys Pressure	Adj Avail Press	Baro Press	Elev	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]	[ppmv]	[ppmv]		[%]	[°F]	[°F]	[\"H2O]	[\"H2O]	[scfm]	[scfm]	[\"H2O]	[\"H2O]	[\"H2O]	[\"H2O]	[\"Hg]	[ft]			
CV-2316	9/10/2026 10:23:35 AM	29.7	67.3	0.0	3.0			0.4	0.0	150.3	150.3	-1.32	-1.30	44.2	43.8	1.313	1.293	-1.96	-1.94	28.53	1395	34.4360408	-118.6463790	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2316	9/14/2026 1:56:00 PM					1625																		AtmAA
CV-2316	9/14/2026 2:22:00 PM	27.0	66.3	0.0	6.7			0.4	0.0	149.9	150.0	-2.80	-2.77	63.3	63.2	2.732	2.717	-3.76	-3.87	28.38	1404	34.4360329	-118.6463813	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2316	9/21/2026 1:35:00 PM					2270																		AtmAA
CV-2316	9/21/2026 1:37:31 PM	34.4	65.5	0.0	0.1			0.5	0.0	150.0	150.1	-2.16	-2.15	56.4	56.4	2.154	2.150	-2.87	-2.82	28.49	1394	34.4360366	-118.6463749	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2319	9/2/2026 1:50:00 PM					4290																		AtmAA
CV-2319	9/2/2026 1:50:00 PM						80200																	AtmAA; [User entered 8.02%]
CV-2319	9/2/2026 1:58:16 PM	12.6	83.0	0.0	4.4			0.2	0.0	161.1	161.2	0.89	-1.49			0.000	0.000	-14.57	-14.77	28.55	1408	34.4353020	-118.6458036	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2319	9/2/2026 1:59:13 PM	12.9	80.8	0.0	6.3			0.2	0.0	161.2	161.2	-1.75	-1.77			0.000	0.000	-15.04	-14.86	28.53	1408	34.4353000	-118.6457999	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2319	9/9/2026 12:48:41 PM	47.6	52.3	0.1	0.0			0.9	0.0	160.6	160.6	-3.58	-3.20			0.000	0.000	-17.22	-17.26	28.62	1407	34.4352842	-118.6457913	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2319	9/9/2026 1:00:00 PM					2990																		AtmAA
CV-2319	9/15/2026 2:22:47 PM	36.4	63.6	0.0	0.0			0.6	0.0	167.3	167.3	-2.48	-2.46			0.000	0.000	-19.67	-19.54	28.47	1395	34.4353008	-118.6457986	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2319	9/15/2026 2:25:00 PM					3030																		AtmAA
CV-2319	9/22/2026 9:40:58 AM	10.1	81.4	0.1	8.4			0.1	84.0	172.8	173.6	-2.25	-1.72	153.3	145.2	6.697	5.998	-19.75	-22.01	28.5	1397	34.4353070	-118.6458138	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2319	9/22/2026 2:35:00 PM					48.9																		AtmAA
CV-2319	9/22/2026 2:40:31 PM	26.3	72.7	0.0	1.0			0.4	0.0	174.7	173.3	-0.08	-1.61			0.000	0.000	-14.14	-16.04	28.42	1392	34.4352891	-118.6457993	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2319	9/22/2026 2:41:24 PM	19.4	78.4	0.0	2.2			0.2	0.0	173.1	173.1	-1.84	-1.73			0.000	0.000	-16.53	-17.52	28.42	1394	34.4352976	-118.6457940	Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Lorentz Pump Installed
CV-2319	9/29/2026 1:53:56 PM	35.3	64.7	0.0	0.0			0.5	0.0	171.8	171.8	-3.83	-3.85			0.000	0.000	-19.96	-19.75	28.27	1373	34.4352995	-118.6458137	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2319	9/29/2026 2:00:00 PM					4180																		AtmAA
CV-2321	9/1/2026 8:55:00 AM					3590																		AtmAA
CV-2321	9/1/2026 8:55:00 AM						76600																	AtmAA; [User entered 7.66%]
CV-2321	9/1/2026 8:56:13 AM	18.1	78.9	0.3	2.7			0.2	9.0	148.2	148.2	-1.67	-1.70			0.031	0.027	-19.14	-19.16	28.56	1406	34.4346429	-118.6453729	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2321	9/9/2026 10:11:41 AM	33.7	66.3	0.0	0.0			0.5	0.0	145.3	145.3	-3.13	-3.14	6.5	6.5	0.121	0.120	-20.07	-19.89	28.64	1396	34.4346090	-118.6453764	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2321	9/9/2026 10:15:00 AM					3130																		AtmAA
CV-2321	9/15/2026 1:25:04 PM	39.1	60.5	0.4	0.0			0.6	0.0	139.3	139.2	-3.20	-3.17			0.225	0.261	0.03	0.10	28.49	1408	34.4346343	-118.6454037	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2321	9/22/2026 9:56:29 AM	13.7	77.0	0.4	8.9			0.2	22.3	147.2	147.4	-2.09	-1.64	3.3	1.4	0.031	0.005	-12.42	-13.27	28.52	1374	34.4346362	-118.6453545	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open
CV-2321	9/29/2026 1:15:00 PM					2840																		AtmAA
CV-2321	9/29/2026 1:21:59 PM	24.4	75.3	0.2	0.1			0.3	0.5	148.4	147.8	-0.74	-4.54			0.049	0.412	-11.63	-11.09	28.31	1399	34.4346180	-118.6453840	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2321	9/29/2026 1:22:57 PM	30.9	68.9	0.2	0.0			0.4	0.0	147.7	147.7	-4.65	-4.67			0.471	0.549	-11.40	-11.26	28.31	1400	34.4346237	-118.6453867	Well Condition:Lorentz Pump Installed
CV-2322	9/1/2026 1:56:33 PM	9.6	77.3	0.0	13.1			0.1	0.0	165.0	165.2	-6.34	-6.23			6.496	6.467	-6.48	-6.40	28.54	1371	34.4352744	-118.6475555	Valve Adjustment:No Flow Measurement,High Temp
CV-2322	9/1/2026 2:00:00 PM					2140																		AtmAA
CV-2322	9/1/2026 2:00:00 PM						109200																	AtmAA; [User entered 10.92%]
CV-2322	9/10/2026 8:31:00 AM					2640																		AtmAA
CV-2322	9/10/2026 8:31:01 AM	6.2	85.1	0.0	8.7			0.1	0.0	167.5	168.6	-6.33	-6.36			6.587	6.643	-7.12	-7.08	28.56	1378	34.4352672	-118.6475025	Valve Adjustment:No Flow Measurement,High Temp
CV-2322	9/17/2026 12:50:31 PM	14.1	80.5	0.1	5.3			0.2	53.0	118.6	119.3	-9.21	-8.87			9.436	9.061	-9.22	-8.88	28.68	1370	34.4352801	-118.6475496	Valve Adjustment:No Flow Measurement
CV-2324	9/3/2026 1:08:01 PM	45.8	51.9	0.0	2.3			0.9	0.0	124.9	125.2	-0.56	-0.59	4.1	3.4	0.011	0.008	-19.76	-20.86	28.48	1390	34.4345000	-118.6442427	Valve Adjustment:Barely Open
CV-2326	9/3/2026 9:35:00 AM					3110																		AtmAA
CV-2326	9/3/2026 9:35:00 AM						153800																	AtmAA; [User entered 15.38%]
CV-2326	9/3/2026 9:35:50 AM	12.9	69.3	0.3	17.5			0.2	58.3	175.7	84.1	-3.31	-3.31			3.309	3.282	-6.91	-6.74	28.56	1373	34.4361365	-118.6504865	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2326	9/3/2026 1:14:03 PM	57.8	40.7	0.0	1.5			1.4	0.0	91.5	95.7	0.07	-0.25			0.000	0.000	-19.50	-21.41	28.48	1380	34.4345763	-118.6441043	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Barely Open,Surging Liquid in Header
CV-2326	9/8/2026 3:25:00 PM					3480																		AtmAA
CV-2326	9/8/2026 3:25:03 PM	16.6	62.7	0.0	20.7			0.3	0.0	168.8	168.8	-3.06	-2.86			3.048	2.891	-6.19	-5.68	28.59	1369	34.4361090	-118.6504464	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [""H2O]	Adj Stat Press [""H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [""H2O]	Adj Diff Press [""H2O]	Sys Pressure [""H2O]	Adj Avail Press [""H2O]	Baro Press [""Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
CV-2326	9/15/2026 8:24:00 AM					3020																		AtmAA
CV-2326	9/15/2026 8:25:39 AM	20.9	62.6	0.0	16.5			0.3	0.0	175.6	175.7	-6.60	-6.40			6.779	6.703	-4.71	-4.51	28.51	1372	34.4361394	-118.6504627	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2326	9/21/2026 2:28:46 PM	25.7	64.7	0.0	9.6			0.4	0.0	173.1	173.1	-4.43	-4.30			4.322	4.325	-7.92	-7.68	28.5	1366	34.4361214	-118.6504334	Valve Adjustment:Audible Flow,High Temp;Well Condition:Lorentz Pump Installed
CV-2326	9/21/2026 2:31:00 PM					3000																		AtmAA
CV-2326	9/28/2026 3:18:43 PM	26.2	62.1	0.0	11.7			0.4	0.0	169.8	169.8	-6.40	-6.40			6.561	6.567	-10.74	-10.76	28.35	1375	34.4361087	-118.6504566	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2326	9/28/2026 3:20:00 PM					2350																		AtmAA
CV-2327	9/14/2026 10:24:05 AM	3.0	81.5	0.0	15.5			0.0	0.0	181.5	181.5	-4.19	-4.18	0.0	0.0	4.219	3.901			28.48	1299	34.4349290	-118.6479637	NSPS/EG CAI,High Temp
CV-2327	9/14/2026 10:26:47 AM	2.7	81.7	0.0	15.6			0.0	0.0	180.4	180.9	-4.59	-4.64	0.0	0.0	4.668	4.640			28.48	1325	34.4349483	-118.6478963	NSPS/EG CAI,High Temp
CV-2327	9/14/2026 1:30:00 PM					2360																		AtmAA
CV-2327	9/21/2026 8:50:00 AM					1280																		AtmAA
CV-2327	9/21/2026 8:58:34 AM	1.1	40.8	10.2	47.9			0.0	4.7	181.0	182.4	-12.62	-3.39			12.776	3.372	-11.03	-11.00	28.58	1361	34.4348928	-118.6479362	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2327	9/21/2026 9:11:07 AM	1.8	81.4	0.3	16.5			0.0	55.0	179.4	179.7	-2.34	-2.20			2.369	2.228	-10.96	-10.84	28.58	1366	34.4348934	-118.6479396	Valve Adjustment:No Flow Measurement,High Temp
CV-2327	9/30/2026 9:14:10 AM	24.3	75.7	0.0	0.0			0.3	0.0	128.3	128.0	-0.74	-0.68			0.741	0.671	-10.26	-10.19	28.49	1356	34.4348937	-118.6479513	Valve Adjustment:No Flow Measurement,High Temp
CV-2328	9/1/2026 2:21:10 PM	43.1	56.9	0.0	0.0			0.8	0.0	152.5	152.9	-3.85	-3.75	18.4	20.1	0.839	1.008	-6.84	-6.53	28.57	1355	34.4343036	-118.6483598	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2328	9/1/2026 2:25:00 PM					1690																		AtmAA
CV-2328	9/1/2026 2:25:00 PM						2600																	AtmAA; [User entered 0.26%]
CV-2328	9/9/2026 7:45:00 AM					630																		AirTech Lab
CV-2328	9/9/2026 7:45:00 AM						62000																	AirTech Lab; [User entered 6.2%]
CV-2328	9/9/2026 1:45:59 PM	50.5	49.5	0.0	0.0			1.0	0.0	119.1	119.1	-2.47	-2.38	8.5	10.8	0.166	0.274	-4.20	-5.00	28.65	1357	34.4343150	-118.6483458	Well Condition:Lorentz Pump Installed
CV-2328	9/24/2026 10:56:47 AM	37.6	56.8	0.1	5.5			0.7	55.0	151.3	151.3	-7.73	-7.05	11.5	22.7	0.036	0.141	-10.98	-10.99	28.6	1364	34.4343292	-118.6483413	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2328	9/24/2026 10:58:35 AM	36.2	57.1	0.0	6.7			0.6	0.0	151.1	151.3	-7.05	-7.05	32.5	36.5	0.289	0.365	-11.29	-11.38	28.63	1357	34.4343182	-118.6483530	
CV-2328	9/28/2026 2:24:07 PM	35.2	63.1	0.0	1.7			0.6	0.0	148.1	148.4	-7.55	-7.56	18.2	10.5	0.091	0.030	-10.71	-10.79	28.41	1343	34.4343018	-118.6483585	Valve Adjustment:High Temp
CV-2328	9/30/2026 8:52:17 AM	38.1	55.8	0.0	6.1			0.7	0.0	145.4	145.4	-8.94	-8.94	10.3	11.3	0.267	0.319	-11.39	-11.57	28.47	1357	34.4343249	-118.6483597	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2328	9/30/2026 8:55:00 AM					887																		AtmAA
CV-2333	9/3/2026 7:45:00 AM					2700																		AirTech Lab
CV-2333	9/3/2026 7:45:00 AM						190000																	AirTech Lab; [User entered 19%]
CV-2333	9/8/2026 9:30:41 AM	1.2	65.8	0.0	33.0			0.0	0.0	184.2	184.4	-5.48	-5.22			5.811	5.546	-6.11	-5.64	28.6	1365	34.4365099	-118.6473866	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2333	9/8/2026 9:35:00 AM					4040																		AtmAA
CV-2333	9/14/2026 8:23:05 AM	1.9	84.2	0.0	13.9			0.0	0.0	186.5	186.6	-7.65	-7.58			7.717	7.592	-8.39	-8.17	28.46	1363	34.4365145	-118.6473733	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2333	9/14/2026 8:25:00 AM					5050																		AtmAA
CV-2333	9/21/2026 8:18:24 AM	2.4	80.9	0.0	16.7			0.0	0.0	187.9	187.9	-5.73	-5.73			5.732	5.687	-8.80	-8.80	28.57	1348	34.4365245	-118.6473638	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2333	9/21/2026 8:21:00 AM					4470																		AtmAA
CV-2333	9/28/2026 8:05:00 AM					4280																		AtmAA
CV-2333	9/28/2026 8:08:07 AM	1.0	78.3	0.0	20.7			0.0	0.0	189.0	189.0	-9.52	-9.10			9.705	9.302	-10.44	-9.96	28.46	1358	34.4365184	-118.6473623	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2334	9/3/2026 7:50:00 AM					2600																		AirTech Lab
CV-2334	9/3/2026 7:50:00 AM						140000																	AirTech Lab; [User entered 14%]
CV-2334	9/9/2026 12:10:26 PM	9.0	77.9	0.2	12.9			0.1	64.5	145.6	145.6	-1.32	-1.44	33.1	33.8	3.130	3.268	-3.07	-3.37	28.6	1384	34.4366652	-118.6467085	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2334	9/9/2026 12:10:43 PM	8.5	79.4	0.3	11.8			0.1	39.3	145.6	145.6	-1.49	-1.49	34.6	34.6	3.426	3.426	-3.70	-3.70	28.59	1361	34.4366657	-118.6467037	Valve Adjustment:High Temp,Barely Open
CV-2334	9/17/2026 12:59:56 PM	13.2	73.2	0.0	13.6			0.2	0.0	147.7	147.7	-3.43	-3.44	37.0	34.9	3.930	3.489	-7.57	-7.15	28.68	1357	34.4366728	-118.6466527	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2334	9/17/2026 1:03:00 PM					3390																		AtmAA
CV-2334	9/24/2026 1:25:00 PM					3530																		AtmAA
CV-2334	9/24/2026 1:44:17 PM	13.3	77.9	0.0	8.8			0.2	0.0	154.5	154.5	0.96	-0.98	33.7	43.8	3.285	5.601	-1.69	-5.78	28.51	1376	34.4366794	-118.6466942	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum,Valve 100% Open;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [""H2O]	Adj Stat Press [""H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [""H2O]	Adj Diff Press [""H2O]	Sys Pressure [""H2O]	Adj Avail Press [""H2O]	Baro Press [""Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
CV-2334	9/24/2026 1:45:33 PM	11.5	74.4	0.0	14.1			0.2	0.0	154.7	154.7	-1.01	-1.00	44.3	44.6	5.726	5.802	-6.04	-5.96	28.49	1375	34.4366780	-118.6467040	Valve Adjustment: NSPS/EG CAC, High Temp; Well Condition: Lorentz Pump Installed
CV-2335	9/14/2026 9:41:03 AM	51.2	45.1	0.4	3.3			1.1	8.3	91.5	91.6	-1.00	-0.99			0.992	0.982	-6.48	-6.37	28.46	1320	34.4364225	-118.6509372	Valve Adjustment: Barely Open
CV-2335	9/16/2026 2:27:40 PM	54.4	45.4	0.1	0.1			1.2	1.0	100.0	100.2	-0.08	-0.19			0.029	0.149	-5.16	-5.12	28.56	1325	34.4363800	-118.6509645	Valve Adjustment: Increased Flow/Vacuum; Barely Open
CV-2336	9/14/2026 9:45:07 AM	21.0	55.0	4.2	19.8			0.4	4.7	76.5	76.4	-0.91	-0.91			0.896	0.896	-7.65	-7.67	28.48	1346	34.4359667	-118.6508977	Valve Adjustment: Barely Open
CV-2336	9/16/2026 2:20:41 PM	18.7	63.8	2.5	15.0			0.3	6.0	87.0	87.1	-4.34	-4.64			4.165	4.568	-4.49	-4.84	28.56	1325	34.4359835	-118.6508803	Valve Adjustment: Barely Open
CV-2337	9/8/2026 10:57:52 AM	4.7	79.0	0.1	16.2			0.1	162.0	153.3	153.4	-1.73	-1.72	0.0	0.0	-2.247	-2.057			28.63	1289	34.4354205	-118.6507197	NSPS/EG CAI, High Temp, Reduced System Vacuum
CV-2337	9/8/2026 11:00:00 AM					4780																		AtmAA
CV-2337	9/10/2026 9:00:00 AM					2000																		AirTech Lab
CV-2337	9/10/2026 9:00:00 AM						100000																	AirTech Lab; [User entered 10%]
CV-2337	9/16/2026 2:13:00 PM					4360																		AtmAA
CV-2337	9/16/2026 2:19:44 PM	15.3	0.0	0.0	84.7				0.0	153.7	153.8	-1.09	-1.06	24.2	24.2	1.684	1.683	-4.71	-4.59	28.6	1332	34.4354445	-118.6507553	Valve Adjustment: High Temp; Well Condition: Lorentz Pump Installed
CV-2337	9/23/2026 2:21:00 PM					3390																		AtmAA
CV-2337	9/23/2026 2:21:55 PM	13.4	75.9	0.0	10.7			0.2	0.0	144.7	144.6	-7.37	-7.16	12.5	13.3	0.452	0.514	-8.13	-7.71	28.46	1314	34.4354555	-118.6507592	Valve Adjustment: High Temp; Well Condition: Lorentz Pump Installed
CV-2337	9/30/2026 2:15:00 PM					4335																		AtmAA
CV-2337	9/30/2026 2:20:16 PM	7.9	76.1	0.0	16.0			0.1	0.0	138.8	138.7	-7.92	-7.71	13.9	11.2	0.555	0.363	-7.94	-7.82	28.42	1330	34.4354513	-118.6507534	Valve Adjustment: High Temp; Well Condition: Lorentz Pump Installed
CV-2338	9/8/2026 11:13:27 AM	2.7	71.9	0.5	24.9			0.0	49.8	149.9	152.5	-4.27	-4.27	0.0	0.0	4.366	4.503	-4.27		28.64	1385	34.4348540	-118.6505495	NSPS/EG CAI, High Temp, Reduced System Vacuum
CV-2338	9/8/2026 11:15:00 AM					891																		AtmAA
CV-2338	9/16/2026 2:23:00 PM					1140																		AtmAA
CV-2338	9/16/2026 2:28:52 PM	10.7	76.9	0.0	12.4			0.1	0.0	175.6	176.3	-4.88	-4.84			5.152	5.048	-5.16	-5.05	28.62	1313	34.4348596	-118.6504742	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed
CV-2338	9/23/2026 2:29:15 PM	10.2	77.7	0.0	12.1			0.1	0.0	173.6	175.6	-5.71	-5.64			5.927	5.950	-6.00	-5.98	28.5	1308	34.4348637	-118.6504801	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed
CV-2338	9/23/2026 2:34:00 PM					1040																		AtmAA
CV-2338	9/30/2026 2:30:00 PM					616																		AtmAA
CV-2338	9/30/2026 2:35:34 PM	8.0	77.2	0.0	14.8			0.1	0.0	146.0	149.1	0.04	0.00			0.000	0.000	0.11	0.00	28.45	1313	34.4348405	-118.6504515	Valve Adjustment: No Flow Measurement, High Temp, Positive Static Press.; Well Comment: Vacuum line being worked on; Well Condition: Lorentz Pump Installed
CV-2339	9/14/2026 2:04:24 PM	3.7	17.1	15.3	63.9			0.2	4.2	99.8	99.8	-7.16	-7.15	0.0	0.0	7.277	7.314	-7.01		28.48	1289	34.4342345	-118.6501797	NSPS/EG CAI, High O2
CV-2339	9/14/2026 2:06:28 PM	3.8	13.9	16.1	66.2			0.3	4.1	99.4	99.4	-7.26	-7.21	0.0	0.0	7.194	6.962	-7.34		28.48	1276	34.4342873	-118.6502115	NSPS/EG CAI, High O2
CV-2339	9/30/2026 3:45:57 PM	0.5	35.4	11.2	52.9			0.0	4.7	132.6	130.4	-9.43	-9.44			9.529	9.570	-9.99	-10.14	28.41	1299	34.4341737	-118.6502555	Valve Adjustment: NSPS/EG CAI, Surging Liquid in Header, Surging Liquid in Well (Watered In)
CV-2341	9/10/2026 8:29:15 AM	1.5	75.0	0.1	23.4			0.0	234.0	87.3	87.7	4.01	-1.90			0.000	1.877	-7.21	-8.26	28.67	1319	34.4336210	-118.6501692	Valve Adjustment: NSPS/EG CAI, Positive Static Press., Increased Flow/Vacuum; Barely Open
CV-2341	9/10/2026 8:30:27 AM	1.4	75.5	0.0	23.1			0.0	0.0	88.0	88.0	-2.28	-2.26			2.225	2.241	-7.92	-8.08	28.69	1315	34.4336098	-118.6501748	Valve Adjustment: NSPS/EG CAC
CV-2341	9/10/2026 8:45:00 AM					1500																		AirTech Lab
CV-2341	9/10/2026 8:45:00 AM						220000																	AirTech Lab; [User entered 22.%]
CV-2341	9/24/2026 2:48:06 PM	5.5	69.3	0.4	24.8			0.1	62.0	102.0	102.0	-8.55	-8.44			8.685	8.598	-10.35	-10.46	28.49	1298	34.4336428	-118.6502110	Valve Adjustment: Decreased Flow/Vacuum
CV-2342A-PI	9/1/2026 1:37:03 PM	4.0	63.3	0.0	32.7			0.1	0.0	136.7	136.8	-4.06	-4.19			4.043	4.112	-6.30	-6.11	28.69	1281	34.4342130	-118.6508421	Valve Adjustment: No Flow Measurement
CV-2342A-PI	9/8/2026 2:08:22 PM	9.3	74.2	0.0	16.5			0.1	0.0	159.7	158.3	-3.10	-2.97	0.0	0.0	3.125	3.039	-4.83		28.67	1283	34.4341195	-118.6508555	NSPS/EG CAI, High Temp, Reduced System Vacuum
CV-2342A-PI	9/8/2026 2:17:58 PM	11.3	75.3	0.0	13.4			0.2	0.0	156.2	151.2	-2.48	-2.53	0.0	0.0	2.483	2.776	-4.98		28.67	1240	34.4342202	-118.6509147	NSPS/EG CAI, High Temp, Reduced System Vacuum
CV-2342A-PI	9/8/2026 2:20:00 PM					672																		AtmAA
CV-2342A-PI	9/14/2026 1:57:27 PM	6.1	66.8	0.1	27.1			0.1	450.8	189.8	189.9	-4.77	-4.98			4.765	4.721	-4.65	-4.49	28.53	1285	34.4342257	-118.6508585	Valve Adjustment: No Flow Measurement, High Temp
CV-2342A-PI	9/14/2026 2:10:00 PM					1250																		AtmAA
CV-2342A-PI	9/24/2026 9:32:37 AM	8.8	69.5	0.0	21.7			0.1	0.0	182.3	182.1	-4.82	-4.80			5.134	4.798	-6.78	-6.63	28.63	1295	34.4342028	-118.6508542	Valve Adjustment: No Flow Measurement, High Temp
CV-2342A-PI	9/24/2026 9:35:00 AM					1070																		AtmAA
CV-2343-PIR	9/1/2026 1:05:42 PM	2.3	75.8	0.0	21.9			0.0	0.0	156.4	156.7	1.96	1.42			0.000	0.000	-1.59	-7.06	28.72	1290	34.4332371	-118.6506988	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed
CV-2343-PIR	9/1/2026 1:25:00 PM					3600																		AtmAA
CV-2343-PIR	9/1/2026 1:25:00 PM						157700																	AtmAA; [User entered 15.77%]

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [\"H2O]	Adj Stat Press [\"H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [\"H2O]	Adj Diff Press [\"H2O]	Sys Pressure [\"H2O]	Adj Avail Press [\"H2O]	Baro Press [\"Hg]	Elev [ft]	Latitude	Longitude	Comments	
CV-2343-PLR	9/8/2026 1:57:49 PM	4.6	82.2	0.2	13.0			0.1	65.0	160.7	160.7	1.97	-0.39	0.0	0.0	-1.849	-1.210	-3.54		28.66	1243	34.4333050	-118.6508090	NSPS/EG CAI,High Temp,Positive Static Press.,Reduced System Vacuum,Increased Flow/Vacuum	
CV-2343-PLR	9/8/2026 1:59:45 PM	5.0	79.0	0.0	16.0			0.1	0.0	161.7	162.0	-1.53	-1.56	0.0	0.0	0.343	-2.141	-3.88		28.66	1280	34.4332792	-118.6507595	NSPS/EG CAI,High Temp,Reduced System Vacuum	
CV-2343-PLR	9/8/2026 2:00:00 PM					3810																			AtmAA
CV-2343-PLR	9/14/2026 1:47:19 PM	3.9	66.9	0.1	29.1			0.1	323.0	100.6	99.7	-7.63	-7.39			7.618	7.619	0.00	0.00	28.53	1284	34.4332413	-118.6506910	Valve Adjustment:No Flow Measurement,High Temp	
CV-2343-PLR	9/14/2026 1:50:00 PM					4970																			AtmAA
CV-2343-PLR	9/16/2026 12:27:21 PM	0.9	72.6	0.3	26.2			0.0	77.0	180.6	178.9	-5.72	-5.23			5.646	5.238	-5.81	-6.13	28.68	1284	34.4332342	-118.6506825	Valve Adjustment: NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Comment:wellhead exchanged	
CV-2343-PLR	9/24/2026 9:22:03 AM	13.7	68.1	0.0	18.2			0.2	0.0	189.4	189.6	-7.55	-7.31			7.760	7.429	-8.55	-8.38	28.62	1295	34.4332384	-118.6506933	Valve Adjustment:No Flow Measurement,High Temp	
CV-2343-PLR	9/24/2026 9:25:00 AM					3890																			AtmAA
CV-2344	9/1/2026 7:15:00 AM					1500																			Air Tech Lab
CV-2344	9/1/2026 12:55:13 PM	10.7	76.2	0.0	13.1			0.1	0.0	141.6	142.2	-3.39	-3.41			3.393	3.400	-9.48	-9.90	28.69	1303	34.4329697	-118.6504470	Valve Adjustment:No Flow Measurement;Well Condition:Lorentz Pump Installed	
CV-2344	9/1/2026 7:15:00 PM						110000																		Air Tech Lab; [User entered 11%]
CV-2344	9/8/2026 1:49:02 PM	12.4	80.3	0.0	7.3			0.2	0.0	150.4	150.5	-1.60	-1.56	0.0	0.0	1.465	1.461	-6.09		28.65	1312	34.4329567	-118.6504552	NSPS/EG CAI,High Temp,Reduced System Vacuum	
CV-2344	9/8/2026 1:50:00 PM					2700																			AtmAA
CV-2344	9/8/2026 1:50:10 PM	12.1	80.1	0.0	7.8			0.2	0.0	150.8	150.8	-1.50	-1.50	0.0	0.0	1.530	1.532	-6.55		28.65	1312	34.4329982	-118.6504473	NSPS/EG CAI,High Temp,Reduced System Vacuum	
CV-2344	9/14/2026 10:26:52 AM	12.3	67.3	0.0	20.4			0.2	510.8	147.1	147.4	-5.64	-5.66			5.925	5.943	-8.18	-8.22	28.53	1261	34.4329687	-118.6504562	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed	
CV-2344	9/14/2026 10:32:00 AM					2050																			AtmAA
CV-2344	9/24/2026 9:12:30 AM	11.1	69.4	0.0	19.5			0.2	0.0	158.7	158.9	-6.09	-6.07			6.259	6.219	-8.83	-8.46	28.6	1294	34.4329704	-118.6504398	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed	
CV-2344	9/24/2026 9:15:00 AM					1700																			AtmAA
CV-2345	9/1/2026 7:10:00 AM					450																			Air Tech Lab
CV-2345	9/1/2026 7:10:00 AM						33000																		Air Tech Lab; [User entered 3.3%]
CV-2345	9/2/2026 7:32:38 AM	19.8	65.4	0.0	14.8			0.3	0.0	93.5	93.6	-3.62	-3.60	57.4	57.4	3.479	3.474			28.65	1250	34.4327250	-118.6502150	Reduced System Vacuum,	
CV-2345	9/22/2026 11:32:10 AM	17.6	65.8	0.3	16.3			0.3	54.3	109.5	109.5	-3.85	-3.85	61.1	61.1	4.086	4.086			28.59	1309	34.4327020	-118.6502423	.	
CV-2346	9/1/2026 7:05:00 AM					540																			Air Tech Lab
CV-2346	9/1/2026 7:05:00 AM						53000																		Air Tech Lab; [User entered 5.3%]
CV-2346	9/1/2026 10:35:00 AM					532																			AtmAA
CV-2346	9/1/2026 10:35:00 AM						16600																		AtmAA; [User entered 1.66%]
CV-2346	9/1/2026 10:36:56 AM	2.2	78.3	0.0	19.5			0.0	0.0	180.8	180.2	-7.84	-7.85			8.121	8.114	-9.55	-9.54	28.66	1296	34.4326020	-118.6500622	Valve Adjustment:No Flow Measurement,High Temp	
CV-2346	9/8/2026 2:30:00 PM					2740																			AtmAA
CV-2346	9/8/2026 2:32:55 PM	11.4	81.2	0.1	7.3			0.1	73.0	179.4	179.6	-4.99	-4.97	0.0	0.0	4.541	4.631	-6.33		28.64	1365	34.4325310	-118.6501422	NSPS/EG CAI,High Temp,Reduced System Vacuum	
CV-2346	9/14/2026 10:07:15 AM	2.2	74.4	0.0	23.5			0.0	0.0	184.5	184.6	-6.55	-6.54			6.728	6.802	-8.47	-8.57	28.53	1309	34.4325858	-118.6500830	Valve Adjustment:No Adjustments Made	
CV-2346	9/14/2026 10:09:25 AM	1.6	76.0	0.0	22.4			0.0	0.0	184.7	184.6	-7.13	-6.89			7.322	7.112	-9.06	-8.87	28.53	1310	34.4325877	-118.6500700	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed	
CV-2346	9/14/2026 10:10:00 AM					1720																			AtmAA
CV-2346	9/24/2026 9:05:00 AM					1525																			AtmAA
CV-2346	9/24/2026 9:07:33 AM	4.5	81.8	0.0	13.7			0.1	0.0	187.3	187.2	-6.30	-6.14			6.318	6.208	-8.17	-7.87	28.6	1297	34.4325957	-118.6500783	Valve Adjustment:No Flow Measurement,High Temp	
CV-2347	9/1/2026 6:55:00 AM					610																			Air Tech Lab
CV-2347	9/1/2026 6:55:00 AM						46000																		Air Tech Lab; [User entered 4.6%]
CV-2347	9/2/2026 7:17:45 AM	14.4	48.6	0.2	36.8			0.3	184.0	91.2	91.0	-3.87	-3.88	61.9	61.9	3.812	3.810			28.65	1316	34.4323070	-118.6498862	.	
CV-2347	9/22/2026 12:05:58 PM	14.6	47.0	1.1	37.3			0.3	33.9	117.6	117.7	-3.52	-3.53	60.1	61.0	3.744	3.856			28.56	1302	34.4324020	-118.6497328	.	
CV-2348	9/1/2026 6:50:00 AM						28000																		Air Tech Lab; [User entered 2.8%]
CV-2348	9/1/2026 6:50:00 PM					380																			Air Tech Lab
CV-2348	9/2/2026 7:12:27 AM	19.9	51.5	0.1	28.5			0.4	285.0	131.4	131.4	-9.05	-9.02	0.0	0.0	8.966	8.748	-9.01		28.64	1342	34.4322007	-118.6496217	NSPS/EG CAI,High Temp	
CV-2348	9/2/2026 7:13:13 AM	19.9	51.7	0.1	28.3			0.4	283.0	131.4	131.5	-9.18	-9.11	0.0	0.0	9.160	8.743	-9.06		28.64	1362	34.4321802	-118.6497023	NSPS/EG CAI,High Temp	
CV-2348	9/22/2026 12:12:09 PM	19.0	51.4	0.0	29.6			0.4	0.0	137.6	137.6	-8.62	-8.65	0.0	0.0	8.890	9.240	-8.66		28.55	1217	34.4321953	-118.6496317	NSPS/EG CAI,High Temp	
CV-2348	9/22/2026 12:13:11 PM	18.8	53.3	0.0	27.9			0.4	0.0	137.9	137.9	-8.79	-8.76	0.0	0.0	8.916	8.643	-8.72		28.55	1296	34.4320917	-118.6496172	NSPS/EG CAI,High Temp	
CV-2349	9/1/2026 2:05:00 AM						151900																		AtmAA; [User entered 15.19%]
CV-2349	9/1/2026 2:02:58 PM	3.1	71.2	0.7	25.0			0.0	35.7	162.2	161.7	-2.58	-2.59			2.679	2.440	-2.77	-2.61	28.69	1270	34.4331388	-118.6512676	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [""H2O]	Adj Stat Press [""H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [""H2O]	Adj Diff Press [""H2O]	Sys Pressure [""H2O]	Adj Avail Press [""H2O]	Baro Press [""Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
CV-2349	9/1/2026 2:05:00 PM					2770																		AtmAA
CV-2349	9/2/2026 7:50:00 AM					2900																		AirTech Lab
CV-2349	9/2/2026 7:50:00 AM						200000																	AirTech Lab; [User entered 20%]
CV-2349	9/8/2026 1:35:00 PM					3020																		AtmAA
CV-2349	9/8/2026 1:37:23 PM	9.1	77.3	0.7	12.9			0.1	18.4	164.0	163.8	2.35	1.83			-2.508	-1.933			28.68	1227	34.4331148	-118.6512575	NSPS/EG CAI, High Temp, Positive Static Press., Reduced System Vacuum
CV-2349	9/8/2026 1:38:01 PM	9.5	80.8	0.3	9.4			0.1	31.3	163.4	163.5	1.50	1.56			-1.689	-1.730			28.68	1247	34.4330518	-118.6511642	NSPS/EG CAI, High Temp, Positive Static Press., Reduced System Vacuum
CV-2349	9/17/2026 9:37:56 AM	10.3	75.6	0.0	14.1			0.1	0.0	176.9	178.0	1.36	0.12			0.000	0.000	-2.25	-2.20	28.79	1265	34.4331102	-118.6512541	Valve Adjustment: NSPS/EG CAI, Positive Static Press., Increased Flow/Vacuum, Valve 100% Open, Surging Liquid in Header; Well Condition: Lorentz Pump Installed
CV-2349	9/17/2026 9:40:00 AM					2410																		AtmAA
CV-2349	9/24/2026 9:55:30 AM	10.2	72.1	0.0	17.7			0.1	0.0	181.6	181.7	-1.34	-1.31			1.395	1.315	-3.83	-3.54	28.67	1252	34.4331430	-118.6512350	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed
CV-2349	9/24/2026 10:05:00 AM					2680																		AtmAA
CV-2350	9/1/2026 7:20:00 AM					3400																		Air Tech Lab
CV-2350	9/1/2026 7:20:00 AM						170000																	Air Tech Lab; [User entered 17%]
CV-2350	9/2/2026 8:27:52 AM	6.2	69.6	1.0	23.2			0.1	23.2	75.8	75.6	-8.15	-7.24	0.0	0.0	8.283	5.953	-8.24		28.69	1247	34.4327690	-118.6508805	Reduced System Vacuum,
CV-2350	9/23/2026 9:06:15 AM	5.1	79.7	0.3	14.9			0.1	49.7	117.3	117.4	-11.21	-11.98			11.335	12.172	-11.31	-11.77	28.57	1281	34.4327615	-118.6509092	Well Comment: valve stuck open
CV-2351	9/2/2026 7:15:00 AM					220																		AirTech Lab
CV-2351	9/2/2026 7:15:00 AM						27000																	AirTech Lab; [User entered 2.7%]
CV-2351	9/10/2026 12:26:23 PM	19.0	47.9	5.4	27.7			0.4	5.1	118.4	118.2	-4.07	-3.88			4.140	3.752	-4.02	-3.77	28.7	1304	34.4351275	-118.6511270	Valve Adjustment: NSPS/EG CAI, High O2, Surging Liquid in Well (Watered In)
CV-2351	9/10/2026 12:27:25 PM	18.2	45.7	5.5	30.6			0.4	5.6	118.0	117.9	-3.76	-4.02			3.903	4.001	-3.55	-3.89	28.71	1287	34.4351427	-118.6511517	
CV-2351	9/23/2026 9:53:22 AM	0.0	9.2	19.0	71.8			0.0	3.8	96.7	96.6	-7.22	-7.02			7.484	7.428	-7.15	-7.23	28.54	1285	34.4351298	-118.6511233	Valve Adjustment: High O2, Surging Liquid in Header, Surging Liquid in Well (Watered In), Plugged/Pinched Suspected; Well Comment: valve stuck open
CV-2352	9/2/2026 7:20:00 AM					820																		AirTech Lab
CV-2352	9/2/2026 7:20:00 AM						190000																	AirTech Lab; [User entered 19%]
CV-2352	9/10/2026 11:57:24 AM	3.8	73.5	0.6	22.1			0.1	36.8	146.1	144.6	-3.85	-2.44			3.838	2.385	-3.76	-3.75	28.71	1280	34.4348732	-118.6510500	Valve Adjustment: NSPS/EG CAI, High Temp, Decreased Flow/Vacuum, Surging Liquid in Well (Watered In); Well Condition: Pneumatic Pump Installed
CV-2352	9/10/2026 11:59:11 AM	3.7	74.6	0.2	21.5			0.0	107.5	144.6	144.6	-2.47	-2.61			2.413	2.569	-3.99	-3.91	28.71	1292	34.4348675	-118.6510410	
CV-2352	9/30/2026 3:26:31 PM	18.1	68.1	0.1	13.7			0.3	137.0	189.3	190.5	-2.82	-2.85			2.809	2.862	-6.73	-6.77	28.43	1286	34.4348750	-118.6510445	Valve Adjustment: High Temp
CV-2353-PLF	9/2/2026 7:54:07 AM	4.1	68.4	1.0	26.5			0.1	26.5	90.4	91.2	-5.78	-5.73	0.0	0.0	5.867	5.479	-5.68		28.67	1312	34.4345678	-118.6509308	Reduced System Vacuum,
CV-2353-PLF	9/10/2026 8:40:00 AM					560																		AirTech Lab
CV-2353-PLF	9/10/2026 8:40:00 AM						230000																	AirTech Lab; [User entered 23%]
CV-2353-PLF	9/30/2026 4:20:22 PM	1.9	39.9	8.9	49.3			0.0	5.5	140.6	142.2	-9.79	-9.79			9.905	9.995	-10.06	-10.06	28.44	1278	34.4345265	-118.6508893	Valve Adjustment: High Temp, High O2
CV-2354	9/2/2026 7:45:00 AM					1400																		AirTech Lab
CV-2354	9/2/2026 7:45:00 AM						150000																	AirTech Lab; [User entered 15%]
CV-2354	9/2/2026 8:05:50 AM	7.2	73.8	0.0	19.0			0.1	0.0	163.2	163.4	5.27	4.47	0.0	0.0	-3.733	-4.968	0.88		28.71	1263	34.4336987	-118.6514048	NSPS/EG CAI, High Temp, Positive Static Press.
CV-2354	9/2/2026 8:06:24 AM	7.4	74.5	0.1	18.0			0.1	180.0	162.5	162.2	2.07	4.58	0.0	0.0	-2.887	-4.318	3.97		28.71	1240	34.4337187	-118.6514173	NSPS/EG CAI, High Temp, Positive Static Press.
CV-2354	9/8/2026 8:08:52 AM	5.4	74.5	0.0	20.1			0.1	0.0	187.3	188.2	1.40	-0.48			0.000	0.501	-2.15	-2.78	28.68	1266	34.4336934	-118.6513447	Valve Adjustment: No Flow Measurement, High Temp, Increased Flow/Vacuum, Valve 100% Open; Well Condition: Lorentz Pump Installed
CV-2354	9/8/2026 8:10:05 AM	5.3	70.3	0.0	24.4			0.1	0.0	188.7	188.0	-0.13	-0.10			0.124	0.072	-2.27	-1.98	28.68	1266	34.4336935	-118.6513427	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed
CV-2354	9/8/2026 9:08:00 AM					1530																		AtmAA
CV-2354	9/17/2026 9:46:30 AM	11.4	75.6	0.0	13.0			0.2	0.0	187.6	188.0	-4.82	-4.72			4.787	5.170	-7.31	-7.37	28.82	1265	34.4337095	-118.6513658	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed
CV-2354	9/17/2026 9:50:00 AM					2210																		AtmAA
CV-2354	9/24/2026 9:34:17 AM	9.4	72.7	0.0	17.9			0.1	0.0	182.2	182.3	-9.36	-8.93			9.779	9.333	-12.07	-11.79	28.61	1295	34.4342026	-118.6508543	Valve Adjustment: No Flow Measurement, High Temp

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading	H2 Reading	CH4: CO2	Bal/O2	Init Temp	Adj Temp	Init Stat Press	Adj Stat Press	Init Flow	Adj Flow	Init Diff Press	Adj Diff Press	Sys Pressure	Adj Avail Press	Baro Press	Elev	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]	[ppmv]	[ppmv]		[%]	[°F]	[°F]	[\"H2O]	[\"H2O]	[scfm]	[scfm]	[\"H2O]	[\"H2O]	[\"H2O]	[\"H2O]	[\"Hg]	[ft]			
CV-2354	9/24/2026 9:47:15 AM	7.7	71.3	0.3	20.7			0.1	69.0	110.3	110.5	-10.53	-10.30			11.066	10.776	-10.57	-10.46	28.65	1254	34.4337008	-118.6513581	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2354	9/24/2026 9:50:00 AM					1210																		AtmAA
CV-24001	9/10/2026 9:02:39 AM	53.4	44.3	0.0	2.3			1.2	0.0	105.6	106.3	-1.23	-2.04			1.209	2.004	-4.96	-4.87	28.67	1352	34.4366348	-118.6508967	Valve Adjustment:Increased Flow/Vacuum
CV-24001	9/16/2026 2:35:59 PM	51.9	45.1	0.1	2.9			1.2	29.0	97.2	97.4	-2.33	-2.30			2.277	2.246	-4.80	-4.92	28.56	1332	34.4366398	-118.6509068	Valve Adjustment:Barely Open
CV-24002	9/10/2026 8:53:47 AM	35.4	49.0	0.0	15.6			0.7	0.0	112.6	111.9	-4.31	-3.21			4.240	3.148	-11.09	-11.06	28.64	1361	34.4367377	-118.6504760	Valve Adjustment:Decreased Flow/Vacuum
CV-24002	9/16/2026 2:44:36 PM	35.4	49.1	0.1	15.4			0.7	154.0	111.0	110.3	-3.19	-3.18			3.147	3.155	-11.81	-11.83	28.54	1311	34.4366973	-118.6504535	Valve Adjustment:Barely Open
CV-24003	9/14/2026 9:33:43 AM	26.1	40.5	0.6	32.8			0.6	54.7	104.8	105.0	-2.27	-2.27	2.6	2.4	0.018	0.016	-12.96	-12.87	28.45	1333	34.4368852	-118.6500838	Valve Adjustment:Barely Open
CV-24003	9/16/2026 2:48:11 PM	30.2	54.6	0.2	15.0			0.6	75.0	106.5	106.6	-1.52	-1.53	2.8	2.9	0.021	0.022	-11.88	-11.78	28.54	1339	34.4368830	-118.6500785	Valve Adjustment:Barely Open
CV-24004	9/1/2026 11:16:57 AM	38.7	53.1	0.0	8.2			0.7	0.0	122.3	122.4	-1.28	-1.28	3.5	3.6	0.034	0.034	-6.82	-6.77	28.68	1348	34.4370328	-118.6496633	Valve Adjustment:Audible Flow
CV-24004	9/16/2026 12:39:13 PM	31.8	52.3	0.0	15.9			0.6	0.0	121.3	121.2	-1.87	-1.83	7.4	6.5	0.147	0.114	-10.30	-10.45	28.69	1364	34.4370578	-118.6496768	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24006	9/1/2026 11:38:09 AM	20.5	66.6	1.5	11.4			0.3	7.6	132.3	130.8	-0.80	-0.63	4.7	0.2	0.062	0.000	-3.85	-3.75	28.67	1375	34.4363523	-118.6504703	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24006	9/1/2026 11:38:58 AM	19.2	67.4	1.8	11.6			0.3	6.4	130.2	130.4	-0.59	-0.62	2.1	4.9	0.012	0.066	-3.73	-3.75	28.67	1372	34.4363530	-118.6504393	Valve Adjustment:NSPS/EG CAC
CV-24006	9/16/2026 1:53:51 PM	11.4	77.0	1.6	10.0			0.1	6.3	111.5	111.6	-0.19	-0.20	2.0	4.7	0.011	0.059	-2.22	-2.25	28.55	1349	34.4363735	-118.6504443	Valve Adjustment:Barely Open
CV-24007	9/1/2026 1:41:17 PM	26.5	46.2	0.1	27.2			0.6	272.0	145.5	145.7	-3.05	-2.88	55.8	51.8	9.035	7.765	-10.42	-10.68	28.52	1361	34.4365283	-118.6501310	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24007	9/3/2026 7:10:00 AM					400																		AirTech Lab
CV-24007	9/3/2026 7:10:00 AM						51000																	AirTech Lab; [User entered 5.1%]
CV-24007	9																							

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading	H2 Reading	CH4: CO2	BalO2	Init Temp	Adj Temp	Init Stat Press	Adj Stat Press	Init Flow	Adj Flow	Init Diff Press	Adj Diff Press	Sys Pressure	Adj Avail Press	Baro Press	Elev	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]	[ppmv]	[ppmv]		[%]	[°F]	[°F]	[\"H2O]	[\"H2O]	[scfm]	[scfm]	[\"H2O]	[\"H2O]	[\"H2O]	[\"H2O]	[\"Hg]	[ft]			
CV-24011	9/15/2026 8:38:24 AM	19.0	67.0	0.0	14.0			0.3	0.0	185.6	185.6	-2.89	-3.02	39.7	38.9	4.827	4.639	-7.68	-7.67	28.53	1384	34.4362010	-118.6501764	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24011	9/22/2026 8:35:45 AM	18.9	68.4	0.0	12.7			0.3	0.0	183.9	183.8	-3.14	-3.12	45.3	46.3	6.286	6.570	-9.47	-9.59	28.54	1341	34.4361923	-118.6501664	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24011	9/22/2026 8:37:00 AM					1880																		AtmAA
CV-24011	9/29/2026 8:04:57 AM	18.1	65.5	0.0	16.4			0.3	0.0	181.9	181.8	-4.65	-4.58	45.1	43.5	6.286	5.838	-11.07	-10.81	28.37	1361	34.4362013	-118.6501706	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24011	9/29/2026 8:10:00 AM					2250																		AtmAA
CV-24012	9/10/2026 1:34:00 PM					2600																		AtmAA
CV-24012	9/10/2026 1:36:19 PM	8.6	79.7	0.0	11.7			0.1	0.0	182.7	181.8	-5.62	-5.05			5.690	5.179	-5.79	-5.39	28.5	1369	34.4361742	-118.6493643	Valve Adjustment:No Flow Measurement,High Temp
CV-24012	9/15/2026 8:57:47 AM	5.6	60.0	0.0	34.4			0.1	0.0	187.7	187.7	-7.75	-7.79			8.063	8.231	-9.09	-8.86	28.56	1369	34.4361759	-118.6493347	Valve Adjustment:No Flow Measurement,High Temp
CV-24012	9/15/2026 8:59:00 AM					1450																		AtmAA
CV-24012	9/22/2026 8:52:16 AM	5.3	78.7	0.0	16.0			0.1	0.0	181.8	183.2	-6.37	-6.19			6.672	6.567	-10.64	-10.11	28.57	1353	34.4361728	-118.6493825	Valve Adjustment:No Flow Measurement,High Temp
CV-24012	9/22/2026 8:55:00 AM					1740																		AtmAA
CV-24012	9/29/2026 8:25:00 AM					2020																		AtmAA
CV-24012	9/29/2026 8:26:34 AM	3.5	78.5	0.0	18.0			0.0	0.0	175.0	174.6	-11.42	-6.19			11.644	6.427	-12.29	-12.18	28.35	1356	34.4361859	-118.6493574	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum,Barely Open
CV-24012	9/29/2026 8:27:45 AM	4.3	81.9	0.0	13.8			0.1	0.0	175.5	175.2	-6.40	-6.40			6.611	6.649	-12.46	-12.46	28.38	1358	34.4361736	-118.6493564	Well Condition:Lorentz Pump Installed
CV-24013	9/8/2026 2:55:00 PM					2320																		AtmAA
CV-24013	9/8/2026 2:55:38 PM	3.8	75.7	0.2	20.3			0.1	101.5	189.7	190.1	-6.23	-6.23			6.420	6.308	-6.58	-6.61	28.6	1387	34.4365995	-118.6492325	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24013	9/14/2026 2:41:00 PM					1700																		AtmAA
CV-24013	9/14/2026 2:45:29 PM	8.9	73.4	0.3	17.4			0.1	58.0	189.6	188.7	-7.96	-7.75			8.343	7.973	-8.64	-8.08	28.42	1371	34.4366229	-118.6492451	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24013	9/21/2026 2:06:00 PM					1605																		AtmAA
CV-24013	9/21/2026 2:06:42 PM	9.4	73.9	0.3	16.4			0.1	54.7	189.6	190.6	-8.70	-8.42			9.025	8.562	-9.61	-8.46	28.5	1367	34.4366246	-118.6492122	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24013	9/22/2026 9:07:43 AM	7.2	78.3	0.0	14.5			0.1	0.0	185.8	186.0	-3.06	-2.86			3.067	2.894	0.34	0.34	28.56				Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24013	9/28/2026 2:25:03 PM	6.4	46.3	6.6	40.7			0.1	6.2	190.6	190.2	-35.13	-3.31			33.379	3.271	-10.29	-10.08	28.36	1376	34.4366042	-118.6492379	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24013	9/28/2026 2:34:21 PM	6.9	52.6	5.0	35.5			0.1	7.1	190.2	189.5	-40.68	-0.05			33.379	0.000	-10.56	-10.82	28.37	1376	34.4366053	-118.6492389	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24013	9/28/2026 2:46:14 PM	7.1	53.1	4.1	35.7			0.1	8.7	190.8	190.0	-15.12	-13.82			15.439	14.005	-10.24	-10.36	28.35	1377	34.4366090	-118.6492370	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-24013	9/28/2026 3:05:00 PM					105.5																		AtmAA
CV-24014	9/8/2026 10:27:00 AM					1580																		AtmAA
CV-24014	9/8/2026 10:29:18 AM	1.9	73.6	0.0	24.5			0.0	0.0	182.9	182.9	-2.29	-2.33	27.3	27.6	2.266	2.315	-5.43	-5.36	28.61	1361	34.4367643	-118.6489806	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24014	9/14/2026 9:42:29 AM	13.6	71.7	0.4	14.3			0.2	35.8	183.6	183.7	-6.88	-6.74	48.4	48.3	7.294	7.256	-7.51	-7.66	28.49	1363	34.4367784	-118.6489729	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24014	9/14/2026 9:47:00 AM					1560																		AtmAA
CV-24014	9/21/2026 9:59:00 AM					1540																		AtmAA
CV-24014	9/21/2026 10:01:34 AM	14.2	69.3	0.8	15.7			0.2	19.6	183.8	183.8	-8.65	-8.64	54.0	54.0	9.101	9.111	-10.37	-9.98	28.57	1365	34.4367976	-118.6489447	Valve Adjustment:No Flow Measurement,High Temp
CV-24014	9/28/2026 9:50:00 AM					1370																		AtmAA
CV-24014	9/28/2026 9:51:51 AM	12.1	66.5	1.4	20.0			0.2	14.3	183.0	183.0	-9.77	-9.77	57.2	57.2	10.313	10.322	-10.78	-10.78	28.44	1347	34.4367763	-118.6489531	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24015	9/8/2026 10:15:00 AM					1390																		AtmAA
CV-24015	9/8/2026 10:15:01 AM	1.5	66.3	0.0	32.2			0.0	0.0	187.9	188.3	-2.93	-3.23			2.900	3.181	0.28	0.27	28.6	1352	34.4368700	-118.6486089	Valve Adjustment:No Flow Measurement,High Temp
CV-24015	9/14/2026 9:33:41 AM	11.0	73.9	0.0	15.1			0.1	0.0	179.6	179.9	-4.58	-4.09			4.549	4.078	-5.89	-4.95	28.49	1346	34.4368816	-118.6486166	Valve Adjustment:No Flow Measurement,High Temp
CV-24015	9/14/2026 9:37:00 AM					2390																		AtmAA
CV-24015	9/21/2026 9:43:08 AM	9.4	73.0	0.0	17.6			0.1	0.0	189.6	189.8	-4.91	-4.89			5.215	5.261	-8.80	-9.18	28.57	1350	34.4368824	-118.6486319	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [”H2O]	Adj Stat Press [”H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [”H2O]	Adj Diff Press [”H2O]	Sys Pressure [”H2O]	Adj Avail Press [”H2O]	Baro Press [”Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
CV-24015	9/21/2026 9:47:00 AM					1690																		AtmAA
CV-24015	9/28/2026 9:20:40 AM	10.3	76.3	0.0	13.4			0.1	0.0	163.2	163.3	-6.44	-6.23			6.745	6.522	-8.37	-8.13	28.45	1343	34.4368759	-118.6486242	Valve Adjustment:No Flow Measurement,High Temp
CV-24015	9/28/2026 9:25:00 AM					1660																		AtmAA
																								Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24016	9/10/2026 1:20:58 PM	24.6	49.0	0.2	26.2			0.5	131.0	167.3	167.9	-3.95	-3.88			3.934	3.805	-4.36	-4.38	28.52	1391	34.4358974	-118.6502815	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24016	9/10/2026 1:23:00 PM					1270																		AtmAA
																								Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24016	9/15/2026 8:42:34 AM	18.1	64.5	0.0	17.4			0.3	0.0	161.4	161.6	-6.07	-6.07			6.351	6.413	-7.73	-7.79	28.54	1383	34.4359138	-118.6502500	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24016	9/15/2026 8:46:00 AM					418																		AtmAA
																								Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24016	9/22/2026 8:41:38 AM	16.7	54.7	0.0	28.6			0.3	0.0	176.5	176.4	-5.23	-5.22			5.519	5.551	-7.64	-7.54	28.57	1355	34.4359252	-118.6502371	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24016	9/22/2026 8:43:00 AM					959																		AtmAA
																								Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24016	9/29/2026 8:07:47 AM	14.9	56.7	0.0	28.4			0.3	0.0	167.6	167.5	-6.74	-6.74			6.681	6.674	-8.45	-8.44	28.38	1357	34.4359123	-118.6502410	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24016	9/29/2026 8:15:00 AM					1410																		AtmAA
CV-24017	9/9/2026 7:35:00 AM					1400																		AirTech Lab
CV-24017	9/9/2026 7:35:00 AM						160000																	AirTech Lab; [User entered 16%]
																								Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	9/9/2026 8:19:35 AM	20.9	71.3	0.4	7.4			0.3	18.5	176.0	176.4	-5.05	-4.88			5.057	4.866	-9.71	-10.11	28.64	1355	34.4361280	-118.6497792	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	9/9/2026 8:21:00 AM					1095																		AtmAA
																								Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	9/15/2026 8:47:21 AM	17.7	52.5	0.0	29.8			0.3	0.0	186.7	186.8	-4.81	-4.72			5.101	5.134	-8.61	-8.46	28.54	1373	34.4361095	-118.6498125	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	9/15/2026 8:51:00 AM					1110																		AtmAA
CV-24017	9/22/2026 8:31:00 AM					1250																		AtmAA
																								Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	9/22/2026 8:31:48 AM	19.7	69.8	0.7	9.8			0.3	14.0	174.5	174.0	-4.46	-4.45			4.461	4.444	-9.22	-10.19	28.54	1362	34.4361166	-118.6497614	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
																								Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	9/29/2026 8:02:00 AM	19.2	66.5	0.9	13.4			0.3	14.9	167.3	167.1	-7.79	-7.85			7.846	7.797	-11.62	-11.55	28.38	1359	34.4361115	-118.6497831	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	9/29/2026 8:05:00 AM					1275																		AtmAA
																								Valve Adjustment:NSPS/EG CAl,High Temp,Decreased Flow/Vacuum,Barely Open
CV-24018	9/1/2026 1:52:46 PM	11.0	65.9	0.2	22.9			0.2	114.5	132.4	131.9	-1.67	-1.50			1.684	1.453	-6.71	-6.72	28.54	1354	34.4356177	-118.6500745	Valve Adjustment:NSPS/EG CAl,High Temp,Decreased Flow/Vacuum,Barely Open
CV-24018	9/1/2026 1:53:33 PM	10.9	66.1	0.2	22.8			0.2	114.0	131.6	131.7	-1.50	-1.49			1.495	1.494	-6.76	-6.77	28.54	1360	34.4356027	-118.6500740	Valve Adjustment:High Temp
																								Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24018	9/15/2026 9:11:09 AM	5.1	72.5	0.0	22.4			0.1	0.0	133.9	133.8	-1.70	-1.70			1.705	1.704	-8.30	-8.23	28.56	692	34.4355956	-118.6500720	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
																								Valve Adjustment:NSPS/EG CAl,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24018	9/24/2026 8:57:40 AM	11.0	60.8	0.0	28.2			0.2	0.0	140.1	135.3	-2.33	-1.26			2.287	1.233	-8.98	-9.04	28.59	1371	34.4355977	-118.6500652	Valve Adjustment:NSPS/EG CAl,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24018	9/24/2026 8:58:59 AM	9.0	65.8	0.0	25.2			0.1	0.0	134.8	134.6	-1.16	-1.14			1.137	1.119	-8.83	-8.84	28.59	1374	34.4355913	-118.6500765	Valve Adjustment:NSPS/EG CAl,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24019	9/3/2026 7:27:00 AM					2300																		AtmAA
CV-24019	9/3/2026 7:27:00 AM						158000																	AtmAA; [User entered 15.8%]
																								Valve Adjustment:No Flow Measurement,High Temp
CV-24019	9/3/2026 7:27:22 AM	4.0	82.5	0.1	13.4			0.0	134.0	181.6	181.8	-3.33	-3.14			3.343	3.180	-8.54	-7.20	28.55	1379	34.4357832	-118.6497926	Valve Adjustment:No Flow Measurement,High Temp
																								Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24019	9/9/2026 8:36:17 AM	6.5	77.9	0.4	15.2			0.1	38.0	180.7	181.9	-2.18	-2.00			2.185	2.007	-8.76	-8.72	28.66	1362	34.4357937	-118.6497838	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24019	9/9/2026 8:39:00 AM					1740																		AtmAA
																								Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24019	9/15/2026 9:06:46 AM	4.5	75.6	0.0	19.9			0.1	0.0	184.0	183.7	-4.11	-4.05			4.100	3.985	-8.34	-8.25	28.55	1350	34.4357762	-118.6497832	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24019	9/15/2026 9:09:00 AM					1600																		AtmAA
CV-24019	9/22/2026 9:08:00 AM					1980																		AtmAA
CV-24019	9/24/2026 10:45:00 AM					2050																		AtmAA
																								Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24019	9/24/2026 10:45:17 AM	9.9	73.1	0.0	17.0			0.1	0.0	190.5	190.8	-1.71	-1.61			1.676	1.562	-9.80	-8.67	28.55	1335	34.4357863	-118.6497607	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
																								Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24019	9/29/2026 8:43:49 AM	8.8	70.1	2.1	19.0			0.1	9.0	175.6	175.3	-5.22	-5.05			5.530	5.252	-11.14	-11.20	28.38	1355	34.4357927	-118.6497724	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24019	9/29/2026 8:45:00 AM					1970																		AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [\"H2O]	Adj Stat Press [\"H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [\"H2O]	Adj Diff Press [\"H2O]	Sys Pressure [\"H2O]	Adj Avail Press [\"H2O]	Baro Press [\"Hg]	Elev [ft]	Latitude	Longitude	Comments	
CV-24020	9/3/2026 8:44:20 AM	0.6	8.1	16.6	74.7			0.1	4.5	80.5	81.2	-8.03	-8.07	10.4	10.4	0.278	0.277	-8.11	-8.13	28.63	1370	34.4359895	-118.6493590	Valve Adjustment: NSPS/EG CAI, High O2, Barely Open, Surging Liquid in Well (Watered In); Well Comment: No pump	
CV-24020	9/3/2026 8:45:27 AM	0.6	10.0	16.1	73.3			0.1	4.6	81.7	81.7	-7.99	-8.10	10.3	9.6	0.274	0.237	-8.07	-8.13	28.63	1348	34.4359842	-118.6493688	Valve Adjustment: NSPS/EG CAI, High O2, Barely Open, Surging Liquid in Well (Watered In); Well Comment: No pump	
CV-24020	9/21/2026 8:32:06 AM	0.0	9.2	17.2	73.6			0.0	4.3	69.4	69.4	-10.62	-10.96	10.5	10.7	0.282	0.290	-10.74	-10.92	28.63	1351	34.4360042	-118.6493535	Valve Adjustment: NSPS/EG CAI, High O2, Barely Open, Surging Liquid in Well (Watered In); Well Comment: No pump	
CV-24020	9/21/2026 8:33:17 AM	0.1	10.1	16.5	73.3			0.0	4.4	69.4	69.3	-11.17	-11.29	10.4	10.6	0.273	0.288	-11.30	-11.30	28.63	1353	34.4359973	-118.6493502	Valve Adjustment: NSPS/EG CAI, High Temp, Decreased Flow/Vacuum; Well Condition: Pneumatic Pump Installed	
CV-24021	9/3/2026 8:33:42 AM	9.0	66.0	3.5	21.5			0.1	6.1	147.1	147.1	-7.97	-4.67			8.039	4.584	-8.60	-8.37	28.61	1358	34.4361612	-118.6490398	Valve Adjustment: NSPS/EG CAI, High Temp, Decreased Flow/Vacuum; Well Condition: Pneumatic Pump Installed	
CV-24021	9/3/2026 8:39:22 AM	11.7	64.4	3.3	20.6			0.2	6.2	145.9	146.0	-4.36	-4.34			4.290	4.272	-8.43	-8.13	28.63	1375	34.4361472	-118.6490668	Valve Adjustment: NSPS/EG CAI, High Temp, Decreased Flow/Vacuum; Well Condition: Pneumatic Pump Installed	
CV-24021	9/3/2026 1:27:00 PM					260																			AtmAA
CV-24021	9/3/2026 1:27:00 PM						83000																		AtmAA; [User entered 8.3%]
CV-24021	9/10/2026 1:38:53 PM	8.5	76.5	0.0	15.0			0.1	0.0	109.6	109.8	-5.39	-5.35			5.501	5.347	-5.73	-5.54	28.51	1370	34.4361774	-118.6490491	Valve Adjustment: No Flow Measurement	
CV-24021	9/21/2026 8:38:36 AM	0.0	1.0	19.2	79.8			0.0	4.2	75.4	76.4	-12.38	-12.37			12.527	12.516	-12.53	-12.53	28.63	1356	34.4361513	-118.6490468	Valve Adjustment: NSPS/EG CAI, High O2, Decreased Flow/Vacuum, Surging Liquid in Well (Watered In); Well Comment: NO PUMP	
CV-24021	9/21/2026 8:39:59 AM	0.1	0.3	19.3	80.3			0.3	4.2	76.4	76.3	-12.48	-12.22			12.529	12.234	-12.39	-12.19	28.63	1357	34.4361525	-118.6490430	Valve Adjustment: NSPS/EG CAI, High O2, Decreased Flow/Vacuum, Surging Liquid in Well (Watered In); Well Comment: NO PUMP	
CV-24022-Pl	9/8/2026 10:34:00 AM					1860																			AtmAA
CV-24022-Pl	9/8/2026 10:34:57 AM	2.4	71.9	0.0	25.7			0.0	0.0	194.7	194.8	-4.96	-4.72			5.452	5.324	-5.44	-5.39	28.6	1365	34.4365224	-118.6488159	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed	
CV-24022-Pl	9/14/2026 9:47:06 AM	10.2	70.7	0.4	18.7			0.1	46.8	194.7	194.8	-7.61	-7.62			8.044	8.057	-7.81	-7.75	28.47	1373	34.4364986	-118.6488295	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed	
CV-24022-Pl	9/17/2026 1:14:16 PM	14.6	74.2	0.0	11.2			0.2	0.0	194.5	194.7	-7.84	-7.75			8.172	7.900	-8.44	-8.17	28.67					Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed
CV-24022-Pl	9/17/2026 1:15:00 PM					2220																			AtmAA
CV-24022-Pl	9/21/2026 10:04:00 AM					2060																			AtmAA
CV-24022-Pl	9/21/2026 10:05:58 AM	11.8	67.0	0.0	21.2			0.2	0.0	194.4	194.4	-7.83	-7.83			8.299	8.354	-11.16	-10.99	28.59	1361	34.4365111	-118.6488035	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed	
CV-24022-Pl	9/28/2026 9:56:17 AM	9.4	68.2	0.5	21.9			0.1	43.8	194.6	194.7	-10.34	-10.24			10.672	10.633	-10.44	-10.44	28.46	1361	34.4365163	-118.6488077	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed	
CV-24022-Pl	9/28/2026 10:05:00 AM					1970																			AtmAA
CV-24023	9/8/2026 10:21:52 AM	1.5	66.5	0.0	32.0			0.0	0.0	196.3	196.4	-3.13	-3.09			3.119	3.085	-4.91	-4.57	28.6	1362	34.4365840	-118.6484290	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed	
CV-24023	9/8/2026 10:23:00 AM					1530																			AtmAA
CV-24023	9/14/2026 9:37:06 AM	10.5	74.6	0.0	14.9			0.1	0.0	196.1	196.2	-4.81	-4.69			4.802	4.685	-6.17	-6.23	28.48	1355	34.4366167	-118.6484493	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed	
CV-24023	9/14/2026 9:41:00 AM					1210																			AtmAA
CV-24023	9/21/2026 9:52:32 AM	11.2	58.9	3.3	26.6			0.2	8.1	185.2	188.3	-6.44	-6.40			6.782	6.694	-9.27	-9.14	28.57	1363	34.4366003	-118.6484342	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed	
CV-24023	9/21/2026 9:53:00 AM					1080																			AtmAA
CV-24023	9/28/2026 9:32:30 AM	15.3	63.8	0.0	20.9			0.2	0.0	196.4	196.4	-6.68	-6.49			0.000	0.000	0.27	0.33	28.46	1360	34.4365946	-118.6484382	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed	
CV-24023	9/28/2026 9:33:25 AM	15.0	70.4	0.0	14.6			0.2	0.0	196.4	196.5	-6.67	-6.57			7.023	6.991	-8.72	-8.74	28.46	1360	34.4365945	-118.6484378	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed	
CV-24023	9/28/2026 9:35:00 AM					1570																			AtmAA
CV-24024-Pl	9/14/2026 1:05:56 PM	1.5	72.6	0.5	25.4			0.0	50.8	162.8	165.5	-4.74	-4.80			4.661	4.715	-6.09	-6.43	28.56	1344	34.4368068	-118.6481622	Valve Adjustment: NSPS/EG CAI, High Temp, Barely Open	
CV-24024-Pl	9/14/2026 1:07:36 PM	1.4	73.8	0.2	24.6			0.0	123.0	165.6	163.3	-4.86	-4.76			4.778	4.671	-6.34	-5.76	28.56	1348	34.4367917	-118.6481548	Valve Adjustment: NSPS/EG CAI, High Temp, Barely Open	
CV-24024-Pl	9/14/2026 2:45:00 PM					1440																			AtmAA
CV-24024-Pl	9/21/2026 9:33:56 AM	10.8	72.7	0.0	16.5			0.1	0.0	139.0	139.0	-7.90	-7.96			8.269	8.317	-9.84	-9.73	28.6	1338	34.4367904	-118.6481458	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed	
CV-24025	9/3/2026 7:56:02 AM	3.6	80.6	0.0	15.8			0.0	0.0	174.3	174.4	-2.54	-2.53			2.519	2.515	-4.61	-4.61	28.57	1348	34.4352944	-118.6499458	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed	
CV-24025	9/3/2026 8:00:00 AM					2190																			AtmAA
CV-24025	9/3/2026 8:00:00 AM						127300																		AtmAA; [User entered 12.73%]

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [\"H2O]	Adj Stat Press [\"H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [\"H2O]	Adj Diff Press [\"H2O]	Sys Pressure [\"H2O]	Adj Avail Press [\"H2O]	Baro Press [\"Hg]	Elev [ft]	Latitude	Longitude	Comments	
CV-24025	9/9/2026 8:43:21 AM	12.2	51.5	0.3	36.0			0.2	120.0	168.6	167.7	-4.94	-4.82			4.910	4.770	-6.66	-6.57	28.65	1365	34.4353054	-118.6499108	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed	
CV-24025	9/9/2026 8:45:00 AM					1460																			AtmAA
CV-24025	9/15/2026 9:18:02 AM	13.0	68.1	0.0	18.9			0.2	0.0	178.2	178.6	-2.46	-2.44			2.443	2.439	-4.28	-4.29	28.56	1358	34.4352859	-118.6499373	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed	
CV-24025	9/15/2026 9:19:00 AM					1970																			AtmAA
CV-24025	9/22/2026 9:13:58 AM	8.7	64.0	0.0	27.3			0.1	0.0	184.0	184.1	-2.07	-2.06			2.048	2.040	-4.80	-4.80	28.57	1350	34.4352819	-118.6499411	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed	
CV-24025	9/22/2026 9:16:00 AM					2110																			AtmAA
CV-24025	9/29/2026 8:49:38 AM	10.8	60.2	0.0	29.0			0.2	0.0	170.7	171.0	-3.24	-3.23			3.233	3.216	-5.86	-5.77	28.38	1351	34.4353089	-118.6499223	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed	
CV-24025	9/29/2026 8:50:00 AM					2010																			AtmAA
CV-24026	9/3/2026 7:33:18 AM	2.7	81.2	0.0	16.1			0.0	0.0	179.6	179.5	-4.45	-4.26			4.462	4.245	-7.86	-8.41	28.55	1356	34.4356545	-118.6492903	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed	
CV-24026	9/3/2026 7:34:00 AM					1990																			AtmAA
CV-24026	9/3/2026 7:34:00 AM						196700																		AtmAA; [User entered 19.67%]
CV-24026	9/9/2026 8:31:27 AM	7.3	70.0	0.0	22.7			0.1	0.0	142.6	142.2	-7.70	-7.41			7.976	7.565	-9.11	-8.67	28.67	1349	34.4356773	-118.6492750	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed	
CV-24026	9/21/2026 8:25:41 AM	1.0	79.9	0.0	19.1			0.0	0.0	184.9	184.5	-6.46	-6.26			6.380	6.273	-9.89	-9.39	28.63	1353	34.4356482	-118.6492617	Valve Adjustment:NoSPS/EG CA;High Temp;Well Condition:Lorentz Pump Installed	
CV-24026	9/21/2026 8:26:47 AM	1.0	79.6	0.0	19.4			0.0	0.0	184.3	184.4	-6.50	-6.59			6.543	6.706	-10.48	-9.99	28.63	1358	34.4356468	-118.6492583		
CV-24026	9/28/2026 10:42:46 AM	0.9	87.7	0.0	11.4			0.0	0.0	184.4	184.5	-6.75	-6.71			7.171	7.224	-10.20	-10.97	28.48	1351	34.4356470	-118.6492477	Valve Adjustment:NoSPS/EG CA;High Temp	
CV-24026	9/29/2026 8:35:00 AM					2320																			AtmAA
CV-24026	9/29/2026 8:35:11 AM	3.7	78.8	0.0	17.5			0.0	0.0	179.6	179.4	-6.89	-6.78			7.176	7.117	-10.67	-9.70	28.38	1346	34.4356668	-118.6492720	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed	
CV-24027	9/9/2026 11:08:00 AM	7.9	37.8	7.9	46.4			0.2	5.9	117.6	117.7	-5.49	-5.32			5.878	5.686	-4.38	-4.88	28.63	1351	34.4361385	-118.6487050	Valve Adjustment:High O2,Barely Open	
CV-24027	9/21/2026 8:45:43 AM	0.2	11.2	16.2	72.4			0.0	4.5	82.3	84.5	-11.08	-11.69			11.092	11.758	-10.88	-11.69	28.63	1354	34.4361070	-118.6487170	Valve Adjustment:NoSPS/EG CA;High O2,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In);Well Comment:Pump not working;Well Condition:Pumatic Pump Installed	
CV-24027	9/21/2026 8:46:35 AM	0.2	11.0	16.2	72.6			0.0	4.5	83.2	83.9	-12.34	-12.34			12.495	12.515	-12.53	-12.53	28.63	1353	34.4361088	-118.6487290		
CV-24028	9/8/2026 10:39:56 AM	1.8	70.7	0.0	27.5			0.0	0.0	198.6	198.5	-5.33	-5.15			5.854	5.669	-6.04	-5.92	28.61	1370	34.4363459	-118.6484646	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pumatic Pump Installed	
CV-24028	9/8/2026 10:45:00 AM					1330																			AtmAA
CV-24028	9/14/2026 9:52:00 AM					1110																			AtmAA
CV-24028	9/14/2026 9:59:11 AM	11.4	69.4	0.0	19.2			0.2	0.0	195.6	195.7	-7.35	-7.25			7.846	7.762	-7.65	-7.56	28.49	1361	34.4363435	-118.6484890	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pumatic Pump Installed	
CV-24028	9/21/2026 10:10:45 AM	11.2	70.5	0.0	18.3			0.2	0.0	195.8	195.4	-9.53	-9.44			10.008	9.814	-11.81	-11.49	28.58	1362	34.4363335	-118.6484631	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pumatic Pump Installed	
CV-24028	9/21/2026 10:13:00 AM					1110																			AtmAA
CV-24028	9/28/2026 10:02:58 AM	11.8	69.7	0.0	18.5			0.2	0.0	196.6	196.4	-11.86	-11.67			12.315	12.259	-12.20	-12.15	28.46	1360	34.4363352	-118.6484677	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pumatic Pump Installed	
CV-24028	9/28/2026 10:10:00 AM					1080																			AtmAA
CV-24029	9/9/2026 10:30:51 AM	2.3	66.1	3.7	27.9			0.0	7.5	117.9	118.3	-4.99	-4.81			4.993	4.972	-4.29	-4.25	28.64	1350	34.4363975	-118.6480672	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)	
CV-24029	9/25/2026 10:15:36 AM	0.1	3.1	19.2	77.6			0.0	4.0	97.0	96.7	-9.79	-9.79			10.041	10.284	-9.70	-9.83	28.56	1350	34.4364608	-118.6480642	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)	
CV-24030	9/8/2026 9:51:00 AM					244																			AtmAA
CV-24030	9/8/2026 9:52:46 AM	1.1	66.4	3.6	28.9			0.0	8.0	86.2	91.1	-3.05	-2.53			2.946	2.561	-4.72	-4.76	28.64	1351	34.4366496	-118.6478841	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed	
CV-24030	9/14/2026 8:52:00 AM					1680																			AtmAA
CV-24030	9/14/2026 9:02:11 AM	3.8	63.6	4.5	28.1			0.1	6.2	185.0	185.0	-4.98	-2.69			4.560	2.688	-6.90	-6.91	28.49	1339	34.4366591	-118.6478892	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

[illegible]

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading	H2 Reading	CH4: CO2	Bal:O2	Init Temp	Adj Temp	Init Stat Press	Adj Stat Press	Init Flow	Adj Flow	Init Diff Press	Adj Diff Press	Sys Pressure	Adj Avail Press	Baro Press	Elev	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]	[ppmv]	[ppmv]		[%]	[°F]	[°F]	[\"H2O]	[\"H2O]	[scfm]	[scfm]	[\"H2O]	[\"H2O]	[\"H2O]	[\"H2O]	[\"Hg]	[ft]			
CV-24033	9/15/2026 9:28:55 AM	5.1	65.3	0.0	29.6			0.1	0.0	196.9	196.7	-0.65	-0.44			0.648	0.462	-0.74	-0.63	28.57	1356	34.4353369	-118.6494400	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24033	9/15/2026 9:32:00 AM					2480																		AtmAA
CV-24033	9/22/2026 9:22:23 AM	5.7	76.4	0.0	17.9			0.1	0.0	194.7	194.4	-0.90	-0.86			0.902	0.896	-1.89	-1.35	28.57	1336	34.4353373	-118.6494663	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24033	9/22/2026 9:27:00 AM					2060																		AtmAA
CV-24033	9/29/2026 8:53:18 AM	11.3	74.0	0.0	14.7			0.2	0.0	193.8	193.3	-6.02	-6.02			6.222	6.204	-6.53	-6.74	28.38	1344	34.4353258	-118.6494611	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24033	9/29/2026 8:55:00 AM					1675																		AtmAA
CV-24034	9/8/2026 1:21:00 PM					1040																		AtmAA
CV-24034	9/8/2026 1:24:32 PM	2.2	78.9	0.7	18.2			0.0	26.0	153.4	153.9	-4.06	-3.99			4.045	3.985	-5.81	-5.73	28.6	1375	34.4361096	-118.6481328	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24034	9/14/2026 10:06:34 AM	10.7	69.9	0.0	19.4			0.2	0.0	163.6	163.2	-4.72	-4.57			5.134	5.084	0.34	0.34	28.49	1353	34.4360935	-118.6481341	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24034	9/14/2026 10:09:00 AM					960																		AtmAA
CV-24034	9/21/2026 10:18:00 AM					994																		AtmAA
CV-24034	9/21/2026 10:19:16 AM	13.5	71.4	0.0	15.1			0.2	0.0	182.8	197.3	16.10	-3.01			0.000	3.004	-12.05	-11.67	28.6	1357	34.4361107	-118.6481153	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24034	9/21/2026 10:20:16 AM	12.1	69.9	0.0	18.0			0.2	0.0	196.8	196.4	-5.04	-4.72			5.353	5.052	-11.94	-11.24	28.6	1357	34.4361086	-118.6481128	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24034	9/28/2026 10:07:28 AM	12.8	70.6	0.0	16.6			0.2	0.0	177.0	177.6	-11.46	-11.46			12.017	12.063	-12.22	-12.34	28.46	1351	34.4361086	-118.6481199	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24034	9/28/2026 10:15:00 AM					1110																		AtmAA
CV-24035-PI	9/8/2026 9:27:31 AM	1.4	75.1	0.0	23.5			0.0	0.0	189.3	190.0	-5.10	-5.05			5.409	5.406	-5.50	-5.56	28.59	1364	34.4363796	-118.6477371	Valve Adjustment:No Flow Measurement,High Temp
CV-24035-PI	9/8/2026 9:29:00 AM					1980																		AtmAA
CV-24035-PI	9/14/2026 8:17:00 AM					1520																		AtmAA
CV-24035-PI	9/14/2026 8:17:07 AM	2.2	83.6	0.1	14.1			0.0	141.0	176.6	174.6	-6.81	-6.74			6.765	6.612	-						

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [\"H2O]	Adj Stat Press [\"H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [\"H2O]	Adj Diff Press [\"H2O]	Sys Pressure [\"H2O]	Adj Avail Press [\"H2O]	Baro Press [\"Hg]	Elev [ft]	Latitude	Longitude	Comments	
CV-24039	9/3/2026 8:43:35 AM	1.1	6.2	17.9	74.8			0.2	4.2	94.7	94.5	-7.27	-7.23			7.978	7.875	-7.74	-7.42	28.57	1352	34.4352957	-118.6486971	Valve Adjustment:No Flow Measurement,High O2,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed	
CV-24039	9/3/2026 8:45:09 AM	1.1	6.8	17.8	74.3			0.2	4.2	94.3	94.5	-7.07	-7.10			7.735	7.764	-7.44	-7.41	28.6	1352	34.4352968	-118.6486993	Well Condition:Lorentz Pump Installed	
CV-24039	9/29/2026 9:17:59 AM	0.0	1.5	17.8	80.7			0.0	4.5	97.3	95.8	-11.49	-11.49			11.520	11.500	-11.45	-11.40	28.43	1357	34.4352862	-118.6486928	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Comment:Pump is off	
CV-24039	9/29/2026 9:18:59 AM	0.1	1.3	17.5	81.1			0.1	4.6	98.6	97.5	-11.37	-11.29			11.469	11.483	-11.35	-11.41	28.41	1345	34.4352903	-118.6486710		
CV-24040	9/3/2026 8:50:25 AM	3.9	72.4	1.1	22.6			0.1	20.5	172.8	172.5	-4.63	-4.60			4.619	4.595	-7.65	-7.75	28.57	1344	34.4356455	-118.6483919	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed	
CV-24040	9/3/2026 8:52:00 AM					1960																			AtmAA
CV-24040	9/3/2026 8:52:00 AM						197000																		AtmAA; [User entered 19.7%]
CV-24040	9/9/2026 9:53:48 AM	15.1	74.3	0.0	10.6			0.2	0.0	176.2	176.6	-4.42	-4.38			4.342	4.906	-5.59	-6.61	28.68	1348	34.4356539	-118.6483790	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed	
CV-24040	9/9/2026 9:55:00 AM					2690																			AtmAA
CV-24040	9/15/2026 10:32:00 AM					2370																			AtmAA
CV-24040	9/15/2026 10:35:47 AM	4.0	65.0	2.3	28.7			0.1	12.5	145.3	146.1	-4.81	-2.70			5.365	2.686	-5.03	-5.49	28.57	1340	34.4356452	-118.6483970	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed	
CV-24040	9/15/2026 10:38:31 AM	3.5	67.5	1.2	27.8			0.1	23.2	143.0	143.5	-2.47	-2.47			2.459	2.459	-5.73	-5.73	28.57	1341	34.4356455	-118.6483986	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed	
CV-24040	9/21/2026 8:14:52 AM	0.5	11.5	16.5	71.5			0.0	4.3	74.6	75.1	-9.17	-9.28			9.106	9.190	-9.15	-9.19	28.62	1367	34.4356300	-118.6483590	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In);Well Comment:Pump is off	
CV-24040	9/21/2026 8:16:09 AM	0.5	12.5	16.5	70.5			0.0	4.3	75.5	75.8	-9.61	-9.61			9.563	9.522	-9.63	-9.82	28.62	1363	34.4356305	-118.6483698		
CV-24041	9/9/2026 11:11:38 AM	3.3	22.3	15.7	58.7			0.1	3.7	114.6	114.8	-5.46	-5.36			5.883	5.707	-5.27	-5.05	28.64	1344	34.4358672	-118.6480342	Valve Adjustment:High O2,Barely Open	
CV-24041	9/23/2026 1:19:53 PM	0.0	0.3	20.3	79.4			0.0	3.9	108.2	108.1	-0.03	-0.02			0.000	0.000	-8.98	-9.04	28.45	1346	34.4358730	-118.6480412	Valve Adjustment:High O2,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected	
CV-24042	9/8/2026 1:36:57 PM	5.4	73.9	0.0	20.7			0.1	0.0	180.9	180.4	-4.85	-4.69			4.853	4.807	-5.67	-5.47	28.59	1367	34.4362411	-118.6474634	Valve Adjustment:No Flow Measurement,High Temp	
CV-24042	9/8/2026 1:37:00 PM					1400																			AtmAA
CV-24042	9/14/2026 10:23:07 AM	12.8	75.5	0.0	11.7			0.2	0.0	181.5	182.9	-6.87	-6.82			7.363	7.256	-7.54	-7.52	28.46	1365	34.4362201	-118.6474804	Valve Adjustment:No Flow Measurement,High Temp	
CV-24042	9/14/2026 10:27:00 AM					1540																			AtmAA
CV-24042	9/21/2026 10:29:12 AM	25.0	65.8	0.0	9.2			0.4	0.0	176.1	175.2	-10.13	-9.77			10.579	10.322	-12.04	-11.83	28.57	1367	34.4362388	-118.6474614	Valve Adjustment:No Flow Measurement,High Temp	
CV-24042	9/21/2026 10:32:00 AM					1040																			AtmAA
CV-24042	9/28/2026 10:28:10 AM	16.0	72.8	0.0	11.2			0.2	0.0	182.3	179.2	-11.16	-11.12			11.755	11.728	-12.13	-11.92	28.45	1365	34.4362405	-118.6474694	Valve Adjustment:No Flow Measurement,High Temp	
CV-24042	9/28/2026 10:30:00 AM					1850																			AtmAA
CV-24043	9/14/2026 2:27:14 PM	42.7	57.3	0.0	0.0			0.7	0.0	104.9	105.0	-4.93	-4.91	70.8	70.8	4.777	4.779			28.45	1276	34.4340498	-118.6497925		
CV-24043	9/30/2026 4:24:40 PM	37.9	56.9	0.1	5.1			0.7	51.0	122.0	122.0	-9.11	-9.09			9.065	9.061	-0.03	-0.11	28.37	1323	34.4340767	-118.6497155		
CV-24044	9/3/2026 8:17:38 AM	23.0	69.9	0.0	7.1			0.3	0.0	149.0	149.4	-4.75	-4.67			4.746	4.665	-8.61	-8.46	28.57	1344	34.4343905	-118.6494041	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed	
CV-24044	9/3/2026 8:23:00 AM					596																			AtmAA
CV-24044	9/3/2026 8:23:00 AM						67000																		AtmAA; [User entered 6.7%]
CV-24044	9/9/2026 9:15:54 AM	29.2	69.2	0.0	1.6			0.4	0.0	151.3	152.4	-1.83	-1.82			1.831	1.825	-5.23	-5.24	28.67	1346	34.4343820	-118.6493877	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed	
CV-24044	9/9/2026 9:17:00 AM					596																			AtmAA
CV-24044	9/14/2026 9:52:00 AM					2440																			AtmAA
CV-24044	9/15/2026 10:10:54 AM	33.3	66.0	0.0	0.7			0.5	0.0	157.9	159.7	-2.12	-2.07			2.113	2.065	-6.22	-5.81	28.57	1348	34.4343821	-118.6494143	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed	
CV-24044	9/15/2026 10:12:00 AM					584																			AtmAA
CV-24044	9/22/2026 9:50:00 AM					530																			AtmAA
CV-24044	9/22/2026 9:56:36 AM	36.8	63.1	0.0	0.1			0.6	0.0	158.2	157.7	-4.92	-4.91			4.907	4.887	-10.25	-10.11	28.6	1338	34.4343900	-118.6494035	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading	H2 Reading	CH4: CO2	BalO2	Init Temp	Adj Temp	Init Stat Press	Adj Stat Press	Init Flow	Adj Flow	Init Diff Press	Adj Diff Press	Sys Pressure	Adj Avail Press	Baro Press	Elev	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]	[ppmv]	[ppmv]		[%]	[°F]	[°F]	[\"H2O]	[\"H2O]	[scfm]	[scfm]	[\"H2O]	[\"H2O]	[\"H2O]	[\"H2O]	[\"Hg]	[ft]			
CV-24044	9/29/2026 9:08:25 AM	36.6	63.4	0.0	0.0			0.6	0.0	154.6	154.9	-4.72	-4.72			5.152	5.134	-10.92	-11.12	28.38	1343	34.4343999	-118.6493894	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24044	9/29/2026 9:15:00 AM					577																		AtmAA
CV-24045	9/3/2026 8:23:14 AM	25.5	70.7	0.0	3.8			0.4	0.0	185.3	185.5	-7.74	-7.46			8.283	8.127	-8.36	-8.08	28.6	1338	34.4347424	-118.6490782	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24045	9/3/2026 8:27:00 AM					1750																		AtmAA
CV-24045	9/3/2026 8:27:00 AM						161100																	AtmAA; [User entered 16.11%]
CV-24045	9/9/2026 9:26:00 AM					458																		AtmAA
CV-24045	9/9/2026 9:29:21 AM	15.0	65.6	1.3	18.1			0.2	13.9	188.3	188.6	-4.96	-4.88			5.422	4.847	-5.32	-4.82	28.68	1343	34.4347416	-118.6490725	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24045	9/15/2026 10:14:44 AM	33.2	66.7	0.0	0.1			0.5	0.0	187.7	187.9	-5.08	-4.75			5.475	5.262	-5.45	-5.15	28.6	1348	34.4347478	-118.6490696	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24045	9/15/2026 10:18:00 AM					1150																		AtmAA
CV-24045	9/22/2026 10:34:00 AM					1600																		AtmAA
CV-24045	9/22/2026 10:37:26 AM	18.9	71.5	0.4	9.2			0.3	23.0	190.1	189.4	-8.85	-8.55			9.415	9.315	-9.14	-9.09	28.6	1327	34.4347373	-118.6491014	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24045	9/29/2026 9:16:50 AM	18.4	70.5	0.5	10.6			0.3	21.2	184.9	185.3	-10.45	-4.85			10.878	5.322	-10.74	-10.70	28.39	1342	34.4347419	-118.6490643	Valve Adjustment:NSPS/EG CAI, No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24045	9/29/2026 9:17:31 AM	18.2	70.8	0.4	10.6			0.3	26.5	185.8	186.0	-4.52	-4.50			4.496	4.483	-10.67	-10.69	28.4	1341	34.4347456	-118.6490647	Well Condition:Lorentz Pump Installed
CV-24045	9/29/2026 9:25:00 AM					1910																		AtmAA
CV-24046	9/14/2026 10:32:13 AM	1.0	73.1	0.3	25.6			0.0	85.3	180.2	180.4	-1.47	-1.45	34.3	32.2	1.601	1.417			28.49	1302	34.4350398	-118.6483622	NSPS/EG CAI,High Temp
CV-24046	9/14/2026 10:32:44 AM	1.1	74.5	0.4	24.0			0.0	60.0	182.1	182.3	-1.56	-1.57	33.9	33.4	1.584	1.539			28.49	1289	34.4350448	-118.6484187	NSPS/EG CAI,High Temp
CV-24046	9/21/2026 9:20:00 AM					1830																		AtmAA
CV-24046	9/21/2026 9:25:30 AM	0.2	72.2	1.1	26.5			0.0	24.1	184.8	185.5	-5.64	-1.53			5.922	1.526	-9.07	-9.26	28.6	1352	34.4350889	-118.6483739	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24046	9/21/2026 9:27:21 AM	0.2	73.0	0.1	26.7			0.0	267.0	184.0	184.7	-1.65	-1.86			1.625	1.774	-8.97	-10.71	28.59	1352	34.4350885	-118.6483742	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24046	9/22/2026 1:28:16 PM	8.8	75.2	0.0	16.0			0.1	0.0	147.0	146.9	-0.09	-3.04			0.092	3.002	-8.00	-7.29	28.49	1353	34.4350997	-118.6483721	Valve Adjustment:NSPS/EG CAI, No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24046	9/22/2026 1:32:00 PM	8.9	73.2	0.2	17.7			0.1	88.5	147.0	146.8	-3.69	-3.62			3.615	3.545	-7.25	-8.38	28.49	1355	34.4350919	-118.6483670	Valve Adjustment:NSPS/EG CAI, No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24046	9/29/2026 9:35:00 AM					1740																		AtmAA
CV-24046	9/29/2026 9:38:38 AM	10.4	71.9	0.0	17.7			0.1	0.0	172.7	173.5	-1.30	-1.41			1.300	1.374	-4.40	-4.36	28.39	1347	34.4350592	-118.6483815	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24048	9/9/2026 11:14:18 AM	4.4	29.0	11.7	54.9			0.2	4.7	120.2	120.5	-4.71	-4.71			5.005	4.701	-5.16	-5.26	28.64	1346	34.4355710	-118.6477875	Valve Adjustment:High O2,Barely Open
CV-24048	9/23/2026 1:23:23 PM	6.5	76.6	0.1	16.8			0.1	168.0	106.2	107.2	-7.49	-7.64			7.452	7.639	-9.06	-9.17	28.45	1351	34.4355672	-118.6477890	Valve Adjustment:Barely Open
CV-24049	9/10/2026 9:20:00 AM					1700																		AirTech Lab
CV-24049	9/10/2026 9:20:00 AM					150000																		AirTech Lab; [User entered 15%]
CV-24049	9/14/2026 9:39:50 AM	4.0	77.2	0.0	18.8			0.1	0.0	183.4	183.4	-5.97	-5.97	0.0	0.0	5.988	6.116			28.47	1345	34.4359687	-118.6471783	NSPS/EG CAI,High Temp
CV-24049	9/14/2026 9:40:16 AM	4.2	78.7	0.0	17.1			0.1	0.0	183.8	183.8	-5.71	-5.78	0.0	0.0	5.869	6.107			28.47	1355	34.4359942	-118.6471752	NSPS/EG CAI,High Temp
CV-24049	9/14/2026 10:45:00 AM					2200																		AtmAA
CV-24049	9/21/2026 9:35:00 AM					1820																		AtmAA
CV-24049	9/21/2026 9:40:32 AM	4.5	71.0	0.0	24.5			0.1	0.0	187.6	188.7	-10.06	-4.11			10.352	4.132	-11.45	-12.32	28.57	1378	34.4359493	-118.6471965	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24049	9/21/2026 9:41:36 AM	4.5	74.2	0.0	21.3			0.1	0.0	189.2	189.3	-5.33	-5.26			5.582	5.505	-12.14	-12.10	28.57	1378	34.4359493	-118.6471964	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24049	9/28/2026 2:11:38 PM	8.0	78.8	0.0	13.2			0.1	0.0	187.9	187.8	-4.47	-4.46			4.481	4.446	-10.12	-9.60	28.38	1381	34.4359389	-118.6472044	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24049	9/28/2026 2:40:00 PM					1750																		AtmAA
CV-24050	9/14/2026 2:38:57 PM	47.5	41.7	0.0	10.8			1.1	0.0	121.8	121.8	-9.54	-10.14	0.0	0.0	9.939		-7.98		28.46	1293	34.4337753	-118.6498962	
CV-24050	9/30/2026 2:26:44 PM	27.6	36.5	0.0	35.9			0.8	0.0	119.4	118.7	-7.97	-7.99			8.526	8.567	-8.08	-8.18	28.47	1332	34.4337245	-118.6499719	Valve Adjustment:No Flow Measurement
CV-24051	9/14/2026 11:02:47 AM	28.6	47.6	3.4	20.4			0.6	6.0	107.7	108.0	-5.99	-5.40	0.0	0.0	6.008	5.213	-7.05		28.51	1289	34.4344652	-118.6491165	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading	H2 Reading	CH4: CO2	BalO2	Init Temp	Adj Temp	Init Stat Press	Adj Stat Press	Init Flow	Adj Flow	Init Diff Press	Adj Diff Press	Sys Pressure	Adj Avail Press	Baro Press	Elev	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]	[ppmv]	[ppmv]		[%]	[°F]	[°F]	[\"H2O]	[\"H2O]	[scfm]	[scfm]	[\"H2O]	[\"H2O]	[\"H2O]	[\"H2O]	[\"Hg]	[ft]			
CV-24051	9/24/2026 11:45:13 AM	25.4	62.0	2.4	10.2			0.4	4.3	111.8	114.0	-7.53	-6.38			7.614	6.383	-10.87	-10.67	28.61	1356	34.344693	-118.6490308	Valve Adjustment:Decreased Flow/Vacuum
CV-24052	9/14/2026 10:13:38 AM	21.9	42.1	4.2	31.8			0.5	7.6	126.3	126.3	-6.87	-6.42	0.0	0.0	6.941	6.696	-6.88		28.48	1332	34.4351138	-118.6481183	
CV-24052	9/14/2026 10:14:40 AM	26.9	49.8	1.8	21.5			0.5	11.9	127.4	127.5	-6.25	-6.25	0.0	0.0	6.316	6.315	-6.79		28.48	1342	34.4350830	-118.6481057	Valve Adjustment:Decreased Flow/Vacuum
CV-24052	9/23/2026 1:29:49 PM	32.5	39.7	0.5	27.3			0.8	54.6	113.0	115.7	-7.45	-5.33			7.386	5.347	-8.22	-7.48	28.41	1348	34.4350733	-118.6480637	Valve Adjustment:Decreased Flow/Vacuum
CV-24053	9/8/2026 7:40:00 AM					58																		AirTech Lab
CV-24053	9/8/2026 7:40:00 AM						8800																	AirTech Lab; [User entered 0.88%]
CV-24053	9/14/2026 10:03:36 AM	31.7	46.1	0.0	22.2			0.7	0.0	106.3	106.7	-7.56	-6.96	0.0	0.0	7.718	7.271	-7.77		28.48	1329	34.4352268	-118.6478772	Valve Adjustment:Decreased Flow/Vacuum
CV-24053	9/23/2026 1:26:37 PM	28.6	49.0	0.2	22.2			0.6	111.0	118.6	119.2	-8.20	-7.30			8.166	7.337	-8.53	-8.58	28.44	1338	34.4352458	-118.6478037	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24054	9/8/2026 1:44:40 PM	8.9	77.3	0.0	13.8			0.1	0.0	171.5	171.4	-5.79	-5.87			6.044	6.077	-6.33	-6.36	28.57	1375	34.4356411	-118.6471945	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24054	9/8/2026 1:48:00 PM					894.5																		AtmAA
CV-24054	9/14/2026 10:33:37 AM	28.0	0.0	0.0	72.0				0.0	167.8	167.9	-6.73	-6.53			7.178	7.039	-7.10	-6.86	28.47	1373	34.4356267	-118.6471907	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24054	9/14/2026 10:34:00 AM					1080																		AtmAA
CV-24054	9/21/2026 10:34:28 AM	27.3	59.7	0.0	13.0			0.5	0.0	177.0	177.0	-11.12	-11.12			11.556	11.524	-12.59	-12.53	28.57	1371	34.4356359	-118.6471815	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24054	9/21/2026 10:37:00 AM					977																		AtmAA
CV-24054	9/28/2026 10:42:38 AM	22.8	65.3	0.0	11.9			0.3	0.0	161.1	161.9	-11.40	-11.37			11.810	11.764	-11.89	-11.71	28.43	1374	34.4356326	-118.6471962	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24054	9/28/2026 10:45:00 AM					1360																		AtmAA
CV-24055	9/10/2026 9:25:00 AM					1400																		AirTech Lab
CV-24055	9/10/2026 9:25:00 AM						85000																	AirTech Lab; [User entered 8.5%]
CV-24055	9/14/2026 9:36:06 AM	4.9	55.9	3.0	36.2			0.1	12.1	122.0	122.3	-0.89	-0.88	0.0	0.0	0.865	0.856	-8.62		28.45	1391	34.4358657	-118.6469608	Valve Adjustment:NSPS/EG CAI,High Temp,High O2;Well Condition:Lorentz Pump Installed
CV-24055	9/30/2026 8:16:47 AM	4.6	41.3	5.3	48.8			0.1	9.2	151.0	151.0	-1.29	-1.28			1.262	1.253	-12.27	-12.26	28.44	1397	34.4358563	-118.6469278	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24055	9/30/2026 8:17:55 AM	4.5	41.9	5.1	48.5			0.1	9.5	151.0	151.0	-1.27	-1.27			1.249	1.244	-12.22	-12.23	28.44	1393	34.4358568	-118.6469233	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24055	9/30/2026 10:20:00 AM					322																		AtmAA
CV-24056	9/1/2026 9:14:34 AM	23.1	66.2	0.0	10.7			0.3	0.0	99.1	99.2	-0.51	-0.50	0.0	0.0	0.515	0.513			28.62	1335	34.4332992	-118.6500930	Valve Adjustment:Audible Flow,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24056	9/22/2026 11:03:33 AM	25.0	45.7	0.0	29.3			0.5	0.0	117.8	117.7	-4.96	-4.65	0.0	0.0	4.985	4.728			28.58	1322	34.4333415	-118.6501477	Valve Adjustment:Audible Flow,High Temp
CV-24057	9/14/2026 2:15:25 PM	34.7	58.8	0.0	6.5			0.6	0.0	147.4	146.9	-1.89	-1.23			0.846	0.235	-8.14		28.46	1316	34.4334453	-118.6496745	Valve Adjustment:Audible Flow,High Temp
CV-24057	9/14/2026 2:16:28 PM	34.2	65.8	0.0	0.0			0.5	0.0	145.7	145.5	-0.60	-0.56			0.291	0.279	-8.00		28.46	1339	34.4334505	-118.6496667	Valve Adjustment:Audible Flow,High Temp
CV-24057	9/14/2026 3:00:00 PM					1540																		AtmAA
CV-24057	9/17/2026 10:27:01 AM	14.3	74.9	0.1	10.7			0.2	107.0	148.9	148.6	-1.00	-1.02	15.2	8.0	0.656	0.184	-11.38	-11.52	28.71	1320	34.4334902	-118.6496335	Valve Adjustment:Audible Flow,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24057	9/21/2026 10:46:29 AM	19.4	72.3	0.0	8.3			0.3	0.0	149.3	152.4	-0.73	-2.26	13.2	19.5	0.494	1.091	-10.63	-9.67	28.62	1331	34.4334532	-118.6496669	Valve Adjustment:Audible Flow,High Temp;Well Condition:Lorentz Pump Installed
CV-24057	9/21/2026 10:47:11 AM	19.3	72.3	0.0	8.4			0.3	0.0	152.7	152.8	-2.36	-2.33	19.5	19.2	1.097	1.067	-9.95	-9.83	28.62	1331	34.4334530	-118.6496667	Valve Adjustment:Audible Flow,High Temp
CV-24057	9/21/2026 10:50:00 AM					1250																		AtmAA
CV-24058	9/11/2026 1:53:52 PM	45.8	37.2	0.1	16.9			1.2	169.0	111.4	112.8	-3.59	-3.84			3.600	3.828	-4.48	-4.52	28.46	1363	34.4337995	-118.6494456	Valve Adjustment:No Flow Measurement,increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24058	9/11/2026 1:55:09 PM	44.2	35.8	0.0	20.0			1.2	0.0	111.7	112.0	-4.14	-4.13			4.113	4.131	-4.77	-4.82	28.48	1355	34.4337894	-118.6494639	Valve Adjustment:No Flow Measurement,increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24058	9/17/2026 10:38:59 AM	30.9	36.0	0.3	32.8			0.9	109.3	100.9	101.0	-6.99	-7.00			7.346	7.233	-8.18	-7.92	28.71	1336	34.4338113	-118.6494502	Valve Adjustment:Barely Open
CV-24059	9/2/2026 9:05:00 AM					684																		AtmAA
CV-24059	9/2/2026 9:05:00 AM						150200																	AtmAA; [User entered 15.02%]
CV-24059	9/2/2026 9:06:09 AM	20.6	65.5	0.0	13.9			0.3	0.0	156.5	156.6	-0.83	-0.82	1.6	3.2	0.008	0.029	-11.63	-11.45	28.64	1362	34.4337805	-118.6490978	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24059	9/8/2026 9:49:40 AM	13.0	66.7	0.3	20.0			0.2	66.7	154.3	155.9	0.53	-1.15	0.0	0.0	-0.004	-0.005	-7.44		28.62	1319	34.4338325	-118.6489450	NSPS/EG CAI,High Temp,Positive Static Press.,Reduced System Vacuum
CV-24059	9/8/2026 9:50:00 AM					489.5																		AtmAA
CV-24059	9/8/2026 9:51:20 AM	12.6	69.0	0.1	18.3			0.2	183.0	155.5	155.9	-1.21	-1.23	7.7	7.6	0.213	0.210	-7.80		28.62	1329	34.4338568	-118.6488995	NSPS/EG CAI,High Temp
CV-24059	9/16/2026 1:37:00 PM					691																		AtmAA
CV-24059	9/16/2026 1:42:42 PM	25.8	71.4	0.0	2.8			0.4	0.0	160.2	159.9	-0.23	-0.19	4.8	5.6	0.068	0.092	-5.85	-6.57	28.6	1345	34.4337596	-118.6490772	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24059	9/23/2026 1:24:51 PM	29.7	70.3	0.0	0.0			0.4	0.0	156.7	156.9	-6.78	-6.78	12.1	12.3	0.434	0.447	-9.31	-8.72	28.49	1351	34.4337572	-118.6490860	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24059	9/23/2026 1:27:00 PM					431																		AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [\"H2O]	Adj Stat Press [\"H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [\"H2O]	Adj Diff Press [\"H2O]	Sys Pressure [\"H2O]	Adj Avail Press [\"H2O]	Baro Press [\"Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24059	9/30/2026 10:05:00 AM					339																		AtmAA
CV-24059	9/30/2026 10:08:00 AM	45.3	54.7	0.0	0.0			0.8	0.0	155.4	155.4	-9.77	-9.56	12.5	12.5	0.460	0.462	-12.17	-11.79	28.49	1352	34.4337412	-118.6491124	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24060	9/2/2026 9:45:32 AM	31.8	61.7	0.2	6.3			0.5	31.5	133.0	130.7	-8.44	-7.09			8.655	7.417	-11.16	-11.15	28.63	1345	34.4340368	-118.6487882	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Plugged/Pinched Suspected
CV-24060	9/17/2026 11:02:39 AM	29.4	62.2	0.3	8.1			0.5	27.0	126.1	126.7	-7.48	-7.48			7.977	8.015	-12.52	-11.76	28.71	1352	34.4340405	-118.6487990	Valve Adjustment:Barely Open
CV-24061	9/2/2026 9:52:58 AM	44.6	54.6	0.0	0.8			0.8	0.0	102.4	102.5	-1.76	-1.75			1.754	1.745	-6.88	-6.57	28.63	1343	34.4343435	-118.6486292	Valve Adjustment:Barely Open
CV-24061	9/28/2026 10:31:48 AM	7.2	80.4	0.0	12.4			0.1	0.0	147.6	147.3	-0.42	-0.48			0.145	0.454	-11.41	-11.41	28.45	1356	34.4343257	-118.6486043	Valve Adjustment:Barely Open
CV-24062	9/1/2026 2:14:11 PM	35.7	64.2	0.0	0.1			0.6	0.0	175.4	175.7	-4.89	-4.89			5.086	5.016	-6.37	-6.36	28.57	1364	34.4345859	-118.6481037	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	9/1/2026 2:15:00 PM					942.5																		AtmAA
CV-24062	9/1/2026 2:15:00 PM						102100																	AtmAA; [User entered 10.21%]
CV-24062	9/3/2026 7:20:00 AM					840																		AirTech Lab
CV-24062	9/3/2026 7:20:00 AM						110000																	AirTech Lab; [User entered 11%]
CV-24062	9/10/2026 8:48:00 AM					1200																		AtmAA
CV-24062	9/16/2026 10:09:38 AM	29.5	65.0	0.0	5.5			0.5	0.0	173.3	173.7	-3.86	-3.78			3.856	3.789	-4.72	-4.35	28.61	1359	34.4345857	-118.6480850	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	9/16/2026 10:13:00 AM					940.5																		AtmAA
CV-24062	9/23/2026 10:16:47 AM	40.6	59.4	0.0	0.0			0.7	0.0	178.3	178.8	-9.64	-9.56			10.182	10.141	-11.12	-10.95	28.53	1361	34.4345692	-118.6480866	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	9/23/2026 10:19:00 AM					175																		AtmAA
CV-24062	9/30/2026 9:17:26 AM	19.7	75.5	0.0	4.8			0.3	0.0	170.1	170.4	-9.06	-9.06			9.460	9.451	-10.40	-10.40	28.47	1362	34.4345872	-118.6480768	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	9/30/2026 9:20:00 AM					1800																		AtmAA
CV-24063	9/1/2026 2:00:39 PM	8.4	79.6	0.0	12.0			0.1	0.0	186.3	186.3	-4.86	-4.53			4.965	4.651	-5.61	-4.76	28.54	1366	34.4349637	-118.6475249	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	9/1/2026 2:05:00 PM					1970																		AtmAA
CV-24063	9/1/2026 2:05:00 PM						96900																	AtmAA; [User entered 9.69%]
CV-24063	9/3/2026 7:20:00 AM					1400																		AirTech Lab
CV-24063	9/3/2026 7:20:00 AM						110000																	AirTech Lab; [User entered 11%]
CV-24063	9/10/2026 8:38:00 AM					1230																		AtmAA
CV-24063	9/10/2026 8:38:14 AM	17.9	79.7	0.0	2.4			0.2	0.0	188.1	185.2	9.05	-3.06			0.000	3.043	-7.14	-6.92	28.57	1367	34.4349463	-118.6475114	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24063	9/10/2026 8:39:09 AM	17.9	76.6	0.0	5.5			0.2	0.0	184.9	184.7	-3.25	-3.27			3.225	3.293	-7.28	-6.82	28.57	1367	34.4349657	-118.6475070	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	9/14/2026 2:32:38 PM	11.5	76.5	0.0	12.0			0.2	0.0	183.6	183.7	-1.34	-1.21	42.7	43.0	2.665	2.701	-6.00	-5.79	28.47	1368	34.4349453	-118.6475110	Valve CommentInstalled new flow device well head;Valve Adjustment:Orifice Plate Changed (See OP Log).Valve 100% Open
CV-24063	9/15/2026 10:47:20 AM	11.5	74.0	0.0	14.5			0.2	0.0	183.9	184.0	-3.66	-3.66	52.6	52.5	4.063	4.044	-1.26	-1.29	28.58	1363	34.4349572	-118.6475364	
CV-24063	9/17/2026 12:22:16 PM	9.6	75.9	0.0	14.5			0.1	0.0			-4.20	-4.22	41.6	39.6	2.042	1.851	-7.62	-7.33	28.71	1360	34.4349487	-118.6475366	
CV-24063	9/17/2026 1:33:24 PM	21.7	70.2	0.0	8.1			0.3	0.0	167.8	167.7	-3.30	-3.27			3.310	3.292	-5.49	-5.43	28.68	1367	34.4349575	-118.6475331	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	9/17/2026 1:34:00 PM					1190																		AtmAA
CV-24063	9/23/2026 10:11:45 AM	32.2	67.7	0.0	0.1			0.5	0.0	167.4	167.5	-6.71	-6.44			7.172	6.893	-8.53	-8.38	28.49	1364	34.4349518	-118.6475207	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	9/23/2026 10:13:00 AM					1410																		AtmAA
CV-24063	9/30/2026 9:08:35 AM	24.7	75.3	0.0	0.0			0.3	0.0	133.5	133.1	-5.16	-5.14			5.651	5.518	-7.33	-6.65	28.46	1363	34.4349454	-118.6475303	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	9/30/2026 9:15:00 AM					731.5																		AtmAA
CV-24064-Pl	9/1/2026 1:18:43 PM	37.6	58.3	0.0	4.1			0.6	0.0	191.4	191.5	-12.71	-12.97			12.964	13.211	-13.91	-13.92	28.58	1376	34.4352293	-118.6471673	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-Pl	9/1/2026 1:25:00 PM					2350																		AtmAA
CV-24064-Pl	9/1/2026 1:25:00 PM						121100																	AtmAA; [User entered 12.11%]
CV-24064-Pl	9/3/2026 7:30:00 AM					1600																		AirTech Lab
CV-24064-Pl	9/3/2026 7:30:00 AM						140000																	AirTech Lab; [User entered 14%]

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading	H2 Reading	CH4: CO2	BalO2	Init Temp	Adj Temp	Init Stat Press	Adj Stat Press	Init Flow	Adj Flow	Init Diff Press	Adj Diff Press	Sys Pressure	Adj Avail Press	Baro Press	Elev	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]	[ppmv]	[ppmv]		[%]	[°F]	[°F]	[\"H2O]	[\"H2O]	[scfm]	[scfm]	[\"H2O]	[\"H2O]	[\"H2O]	[\"H2O]	[\"Hg]	[ft]			
CV-24064-Pl	9/9/2026 1:28:11 PM	47.8	52.2	0.0	0.0			0.9	0.0	191.7	192.6	-6.37	-5.83			6.327	5.730	-8.01	-7.42	28.57	1374	34.4352301	-118.6471435	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-Pl	9/9/2026 1:32:00 PM					1940																		AtmAA
CV-24064-Pl	9/10/2026 8:45:01 AM	18.7	75.7	0.0	5.6			0.2	0.0	175.2	175.6	-5.39	-5.10			5.649	5.605	-6.95	-6.99	28.57	1362	34.4345767	-118.6480934	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24064-Pl	9/16/2026 9:05:32 AM	35.8	64.2	0.0	0.0			0.6	0.0	190.2	191.1	-3.71	-3.34			4.051	3.533	-5.05	-4.74	28.6	1364	34.4352208	-118.6471720	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-Pl	9/16/2026 9:14:00 AM					2030																		AtmAA
CV-24064-Pl	9/23/2026 9:22:59 AM	46.5	53.5	0.0	0.0			0.9	0.0	188.2	189.7	-11.55	-11.46			12.007	11.810	-13.15	-13.07	28.49	1372	34.4352217	-118.6471656	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-Pl	9/23/2026 9:25:00 AM					1340																		AtmAA
CV-24064-Pl	9/30/2026 8:25:00 AM					2020																		AtmAA
CV-24064-Pl	9/30/2026 8:38:49 AM	37.9	56.7	0.0	5.4			0.7	0.0	188.1	188.5	-9.75	-9.65			10.059	9.946	-11.62	-11.41	28.46	1366	34.4352409	-118.6471663	Valve Adjustment:No Flow Measurement,High Temp
CV-24065-Tr	9/3/2026 8:57:02 AM	12.8	53.4	2.0	31.8			0.2	15.9	113.3	113.3	-4.29	-3.61			4.241	3.596	-7.98	-7.97	28.52	1365	34.4355762	-118.6468408	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24065-Tr	9/8/2026 7:50:00 AM					290																		AirTech Lab
CV-24065-Tr	9/8/2026 7:50:00 AM						15000																	AirTech Lab; [User entered 1.5%]
CV-24065-Tr	9/22/2026 10:39:59 AM	14.0	42.9	0.9	42.2			0.3	46.9	126.3	126.5	-5.40	-4.94			5.700	4.970	-11.02	-10.84	28.5	1381	34.4355865	-118.6468232	Valve Adjustment:Decreased Flow/Vacuum
CV-24066	9/1/2026 9:11:21 AM	21.0	41.6	0.1	37.3			0.5	373.0	89.1	89.3	-1.60	-1.58	0.0	0.0	1.555	1.551	-10.61		28.62	1296	34.4330013	-118.6498730	.
CV-24066	9/10/2026 8:15:00 AM					250																		AirTech Lab
CV-24066	9/10/2026 8:15:00 AM						23000																	AirTech Lab; [User entered 2.3%]
CV-24066	9/22/2026 11:00:28 AM	16.9	44.9	0.0	38.2			0.4	0.0	102.6	103.9	-1.50	-1.52	0.0	0.0	1.549	1.454	-8.18		28.57	1319	34.4330323	-118.6498247	.
CV-24066	9/24/2026 2:36:50 PM	18.0	42.6	0.0	39.4			0.4	0.0	123.0	122.8	-1.48	-1.48			1.468	1.453	-10.40	-10.78	28.49	1323	34.4330125	-118.6498187	Valve Adjustment:Barely Open
CV-24067	9/29/2026 2:12:24 PM	16.4	47.7	0.0	36.0			0.3	0.0	156.2	156.7	-6.00	-5.33	44.7	42.4	5.960	5.338	-9.73	-6.38	28.36	1310	34.4331878	-118.6497418	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
																								Valve Comment:corrected differential port;Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24067	9/29/2026 2:14:48 PM	16.9	45.9	0.0	37.1			0.4	0.0	156.8	156.8	-5.16	-4.99	9.2	10.6	0.248	0.333	-6.71	-6.38	28.36	1320	34.4331927	-118.6497357	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24068	9/3/2026 10:45:39 AM	38.9	49.3	0.2	11.6			0.8	58.0	151.1	151.2	-3.79	-3.78			3.751	3.761	-6.45	-6.32	28.57	1308	34.4332665	-118.6493682	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24068	9/3/2026 10:47:00 AM					644																		AtmAA
CV-24068	9/3/2026 10:47:00 AM						42300																	AtmAA; [User entered 4.23%]
CV-24068	9/8/2026 10:05:00 AM					545																		AtmAA
CV-24068	9/8/2026 10:06:07 AM	25.6	50.6	0.2	23.6			0.5	118.0	145.2	145.3	-3.84	-3.89	0.0	0.0	3.901	4.108	-6.80		28.62	1283	34.4332867	-118.6493442	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24068	9/17/2026 1:41:53 PM	24.9	72.0	0.0	3.1			0.3	0.0	140.0	139.9	-5.74	-5.73			5.989	6.018	-9.18	-9.62	28.68	1367	34.4332668	-118.6493867	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24069	9/2/2026 8:53:53 AM	21.7	49.7	0.1	28.5			0.4	285.0	117.5	116.7	-1.22	-1.22			1.230	1.228	-11.78	-12.02	28.62	1365	34.4334253	-118.6489433	Valve Adjustment:Barely Open
CV-24069	9/8/2026 7:00:00 AM					580																		AirTech Lab
CV-24069	9/8/2026 7:00:00 AM						64000																	AirTech Lab; [User entered 6.4%]
CV-24069	9/28/2026 10:46:59 AM	11.9	44.8	0.2	43.1			0.3	215.5	126.3	126.4	-1.48	-1.49			1.467	1.468	-11.19	-11.63	28.43	1345	34.4334198	-118.6489247	Valve Adjustment:Barely Open
CV-24070	9/2/2026 8:55:00 AM					1590																		AtmAA
CV-24070	9/2/2026 8:55:00 AM						64200																	AtmAA; [User entered 6.42%]
CV-24070	9/2/2026 8:55:24 AM	29.3	64.5	0.0	6.2			0.5	0.0	149.4	149.4	-2.30	-2.33	22.8	22.9	3.524	3.536	-12.57	-12.82	28.64	1367	34.4337238	-118.6486983	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24070	9/8/2026 7:10:00 AM					1000																		AirTech Lab
CV-24070	9/8/2026 7:10:00 AM						82000																	AirTech Lab; [User entered 8.2%]
																								Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24070	9/9/2026 1:57:00 PM	32.2	67.7	0.1	0.0			0.5	0.0	119.1	119.1	0.69	-0.97	9.3	11.2	1.837	2.652	-4.35	-3.49	28.65	1344	34.4337403	-118.6486914	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24070	9/9/2026 1:57:46 PM	30.7	69.2	0.1	0.0			0.4	0.0	119.1	119.1	-1.05	-1.04	11.0	11.5	2.549	2.817	-3.46	-3.84	28.66	1340	34.4337333	-118.6487074	
CV-24070	9/10/2026 1:57:00 PM					1370																		AtmAA
CV-24070	9/10/2026 1:59:57 PM	33.6	66.4	0.0	0.0			0.5	0.0	150.7	150.7	-2.40	-2.47	24.5	25.7	4.084	4.495	-6.30	-6.78	28.49	1362	34.4337177	-118.6487056	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24070	9/16/2026 1:23:00 PM					1360																		AtmAA
CV-24070	9/16/2026 1:30:24 PM	42.9	57.1	0.0	0.0			0.8	0.0	144.7	144.7	-3.79	-4.01	19.2	18.8	2.470	2.384	-6.79	-6.88	28.57	1359	34.4337356	-118.6486836	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
																								Valve Adjustment:High Temp,Barely Open;Well Condition:Lorentz Pump Installed
CV-24071	9/2/2026 9:40:06 AM	24.9	68.0	0.0	7.1			0.4	0.0	138.4	138.3	-0.53	-0.72	12.1	13.5	0.955	1.201	-5.87	-7.02	28.62	1343	34.4340118	-118.6484862	Valve Adjustment:High Temp,Barely Open;Well Condition:Lorentz Pump Installed
CV-24071	9/8/2026 7:15:00 AM					550																		AirTech Lab
CV-24071	9/8/2026 7:15:00 AM						74000																	AirTech Lab; [User entered 7.4%]

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading	H2 Reading	CH4:CO2	BalO2	Init Temp	Adj Temp	Init Stat Press	Adj Stat Press	Init Flow	Adj Flow	Init Diff Press	Adj Diff Press	Sys Pressure	Adj Avail Press	Baro Press	Elev	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]	[ppmv]	[ppmv]		[%]	[°F]	[°F]	[\"H2O]	[\"H2O]	[scfm]	[scfm]	[\"H2O]	[\"H2O]	[\"H2O]	[\"H2O]	[\"Hg]	[ft]			
CV-24071	9/17/2026 2:19:48 PM	33.7	60.4	0.0	5.9			0.6	0.0	134.7	134.0	-3.15	-1.97	13.6	9.6	1.214	0.605	-9.94	-9.61	28.64	1345	34.4340007	-118.6484940	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open
CV-24072	9/2/2026 1:30:58 PM	42.9	57.1	0.0	0.0			0.8	0.0	111.0	110.0	-4.26	-3.50			4.283	3.491	-6.15	-6.00	28.58	1358	34.4341643	-118.6480443	Valve Adjustment:Decreased Flow/Vacuum
CV-24072	9/17/2026 2:25:11 PM	25.5	69.4	0.0	5.1			0.4	0.0	110.9	111.6	-0.27	-0.21			0.215	0.241	-9.18	-9.54	28.63	1359	34.4341910	-118.6480525	Valve Adjustment:Barely Open
CV-24073-TF	9/1/2026 2:25:19 PM	47.3	52.7	0.0	0.0			0.9	0.0	157.5	157.6	-1.98	-1.94			1.966	1.931	-5.96	-5.94	28.55	1367	34.4346323	-118.6477321	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24073-TF	9/1/2026 2:30:00 PM					1420																		AtmAA
CV-24073-TF	9/1/2026 2:30:00 PM						47600																	AtmAA; [User entered 4.76%]
CV-24073-TF	9/9/2026 1:21:38 PM	47.0	52.9	0.1	0.0			0.9	0.0	138.4	138.4	-2.02	-2.07			2.020	2.059	-5.22	-5.48	28.64	1366	34.4346204	-118.6476943	Valve Adjustment:No Flow Measurement;Well Condition:Lorentz Pump Installed
CV-24073-TF	9/21/2026 2:25:32 PM	24.1	71.1	0.2	4.6			0.3	23.0	153.9	154.4	-3.71	-3.70			3.712	3.722	-7.66	-7.45	28.48	1370	34.4346508	-118.6477230	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24073-TF	9/30/2026 9:00:28 AM	29.2	65.1	0.0	5.7			0.4	0.0	153.5	153.5	-6.11	-4.75			6.408	4.737	-10.46	-10.59	28.47	1365	34.4346349	-118.6477305	Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24073-TF	9/30/2026 9:01:24 AM	27.9	64.9	0.0	7.2			0.4	0.0	153.5	153.7	-4.46	-4.42			4.458	4.476	-10.37	-10.37	28.47	1365	34.4346352	-118.6477302	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24073-TF	9/30/2026 9:05:00 AM					1170																		AtmAA
CV-24074	9/2/2026 2:20:20 PM	1.5	83.5	0.1	14.9			0.0	149.0	118.3	118.8	-1.01	-0.91			1.036	0.973	-5.43	-5.70	28.55	1374	34.4347323	-118.6474223	Valve Adjustment:Barely Open
CV-24074	9/21/2026 2:20:48 PM	1.1	80.4	0.2	18.3			0.0	91.5	127.9	127.3	-1.49	-1.42			1.529	1.398	-7.05	-7.20	28.48	1366	34.4347475	-118.6474397	Valve Adjustment:Barely Open
CV-24075-TF	9/1/2026 1:27:41 PM	25.5	71.0	1.0	2.5			0.4	2.5	178.5	178.4	-10.56	-10.32			10.739	10.621	-13.20	-13.05	28.57	1377	34.4350212	-118.6471203	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TF	9/1/2026 1:34:00 PM					1740																		AtmAA
CV-24075-TF	9/1/2026 1:34:00 PM						67500																	AtmAA; [User entered 6.75%]
CV-24075-TF	9/9/2026 1:36:18 PM	31.9	66.8	1.3	0.0			0.5	0.0	181.5	181.6	-6.76	-6.40			6.858	6.349	-7.49	-7.66	28.57	1365	34.4350383	-118.6471025	Valve Adjustment:Other - See Daily Log,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TF	9/9/2026 1:41:00 PM					2030																		AtmAA
CV-24075-TF	9/16/2026 9:26:05 AM	10.8	82.6	0.0	6.6			0.1	0.0	182.3	182.3	-4.13	-4.11			4.123	4.088	-4.48	-4.36	28.6	1357	34.4350257	-118.6471345	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TF	9/16/2026 9:28:00 AM					2100																		AtmAA
CV-24075-TF	9/23/2026 9:31:50 AM	37.0	62.2	0.8	0.0			0.6	0.0	181.4	181.5	-11.74	-11.50			12.167	12.018	-12.52	-12.46	28.49	1373	34.4350254	-118.6471172	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TF	9/23/2026 9:35:00 AM					770																		AtmAA
CV-24075-TF	9/30/2026 8:50:15 AM	27.7	66.7	1.3	4.3			0.4	3.3	179.1	179.2	-10.45	-10.45			10.819	10.830	-11.24	-11.20	28.46				Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TF	9/30/2026 8:55:00 AM					1710																		AtmAA
CV-24076	9/1/2026 1:45:00 PM					1040																		AtmAA
CV-24076	9/1/2026 1:45:00 PM						41400																	AtmAA; [User entered 4.14%]
CV-24076	9/1/2026 1:45:11 PM	24.0	44.9	3.8	27.3			0.5	7.2	167.6	167.4	-4.21	-4.15			4.188	4.143	0.05	0.00	28.53	1389	34.4353069	-118.6468877	Valve Adjustment:High Temp
CV-24076	9/1/2026 1:49:10 PM	23.4	45.1	3.9	27.6			0.5	7.1	172.5	172.2	-4.17	-4.11			4.148	4.169	-5.94	-6.32	28.53	1388	34.4353041	-118.6468846	Valve Adjustment:High Temp
CV-24076	9/9/2026 1:57:00 PM					818																		AtmAA
CV-24076	9/9/2026 1:58:23 PM	24.4	43.2	4.1	28.3			0.6	6.9	172.5	174.2	-3.85	-3.62			3.902	3.634	-5.63	-4.76	28.55	1405	34.4353295	-118.6469041	Valve Adjustment:High Temp,Valve 100% Open
CV-24076	9/16/2026 9:59:57 AM	5.9	82.1	0.0	12.0			0.1	0.0	171.0	171.8	-4.41	-4.41			4.357	4.393	-6.32	-6.27	28.6	1369	34.4353454	-118.6468883	Valve Adjustment:High Temp
CV-24076	9/16/2026 10:02:00 AM					1010																		AtmAA
CV-24076	9/23/2026 9:57:00 AM	29.0	37.9	2.4	30.7			0.8	12.8	168.5	168.0	-7.83	-7.75			8.341	8.240	-11.19	-10.93	28.49	1377	34.4353274	-118.6468801	Valve Adjustment:High Temp
CV-24076	9/30/2026 9:00:43 AM	23.1	39.3	2.8	34.8			0.6	12.4	160.5	160.0	-7.51	-7.51			7.974	7.974	-10.38	-10.38	28.46	1372	34.4353301	-118.6468726	Valve Adjustment:High Temp
CV-24076	9/30/2026 9:05:00 AM					881																		AtmAA
CV-24077	9/1/2026 9:39:47 AM	22.7	57.4	0.0	19.9			0.4	0.0	143.9	140.9	-3.28	-3.34	0.0	0.0	3.410	3.507	-9.94		28.61	1312	34.4327360	-118.6493397	NSPS/EG CAI,High Temp
CV-24077	9/1/2026 11:02:58 AM	21.6	66.2	0.0	12.2			0.3	0.0	136.0	136.1	-3.57	-3.57	0.0	0.0	3.474	3.475	-9.56		28.62	1296	34.4326713	-118.6492630	NSPS/EG CAI,High Temp
CV-24077	9/1/2026 2:25:00 PM					1330																		AtmAA
CV-24077	9/1/2026 2:25:00 PM						40000																	AtmAA; [User entered 4%]
CV-24077	9/1/2026 2:29:54 PM	26.5	69.3	0.0	4.2			0.4	0.0	154.1	153.7	-3.11	-3.11			3.108	3.115	-8.98	-9.03	28.62	1329	34.4326822	-118.6493146	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	9/8/2026 10:33:07 AM	13.8	68.9	0.0	17.3			0.2	0.0	157.3	157.6	-1.79	-1.81	0.0	0.0	1.995	1.989	-6.89		28.63	1362	34.4326312	-118.6494683	NSPS/EG CAI,High Temp,Reduced System Vacuum

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [""H2O]	Adj Stat Press [""H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [""H2O]	Adj Diff Press [""H2O]	Sys Pressure [""H2O]	Adj Avail Press [""H2O]	Baro Press [""Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
CV-24077	9/8/2026 10:35:00 AM					1800																		AtmAA
CV-24077	9/14/2026 9:40:00 AM					1290																		AtmAA
CV-24077	9/14/2026 9:41:46 AM	15.5	60.1	0.0	24.4			0.3	0.0	157.7	157.8	-3.28	-3.34			3.289	3.350	-9.05	-8.95	28.53	1329	34.4326937	-118.6492783	Valve Adjustment:No Adjustments Made;Well Comment:lorentz pump installed
CV-24077	9/14/2026 10:22:00 AM	14.6	65.1	0.0	20.3			0.2	0.0	157.5	157.3	-3.03	-2.95			3.054	2.956	-8.15	-7.84	28.5	1324	34.4326883	-118.6493132	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	9/22/2026 12:59:33 PM	11.5	75.8	0.0	12.7			0.2	0.0	154.3	154.5	-3.37	-3.38	0.0	0.0	2.879	2.881	-9.16		28.51	1329	34.4326130	-118.6493027	NSPS/EG CAI,High Temp
CV-24077	9/22/2026 1:00:24 PM	12.5	78.5	0.0	9.0			0.2	0.0	155.1	155.1	-3.33	-3.33	0.0	0.0	2.874	2.669	-9.46		28.51	1312	34.4326507	-118.6492862	NSPS/EG CAI,High Temp
CV-24077	9/23/2026 1:52:00 PM					950																		AtmAA
CV-24077	9/23/2026 1:52:12 PM	25.8	60.5	0.0	13.7			0.4	0.0	156.0	156.2	-3.53	-3.53			3.526	3.516	-9.09	-8.99	28.49	1338	34.4326824	-118.6493065	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	9/30/2026 1:55:00 PM					1370																		AtmAA
CV-24077	9/30/2026 1:57:09 PM	24.7	63.6	0.0	11.7			0.4	0.0	156.0	156.0	-3.20	-3.15			3.202	3.182	-8.76	-8.76	28.42	1336	34.4326908	-118.6492945	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24078	9/1/2026 11:05:35 AM	7.9	63.9	3.2	25.0			0.1	7.8	108.7	108.8	-0.74	-0.75	5.8	7.0	0.010	0.015	-10.34		28.62	1398	34.4328607	-118.6494877	
CV-24078	9/22/2026 10:57:51 AM	15.2	62.6	3.2	19.0			0.2	5.9	113.9	113.9	-0.86	-0.88	13.8	12.7	0.056	0.048	-9.68		28.58	1329	34.4329245	-118.6494582	
CV-24079-TF	9/1/2026 10:56:25 AM	0.8	83.0	0.0	16.2			0.0	0.0	94.4	94.4	-0.50	-0.48	0.0	0.0	0.424	0.414	-7.39		28.42	1309	34.4330195	-118.6490892	
CV-24079-TF	9/21/2026 11:00:53 AM	18.8	68.1	0.1	13.0			0.3	130.0	170.4	169.1	-2.37	-1.20			2.320	1.175	-9.45	-9.04	28.64	1332	34.4329885	-118.6491078	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24079-TF	9/21/2026 11:03:19 AM	8.1	76.6	0.1	15.2			0.1	152.0	169.1	170.4	-1.08	-1.10			1.052	1.058	-9.31	-8.46	28.65	1320	34.4329590	-118.6491037	
CV-24079-TF	9/28/2026 10:34:01 AM	19.0	75.6	0.0	5.4			0.3	0.0	166.5	166.1	-1.73	-1.75			1.730	1.746	-7.68	-7.54	28.48	1335	34.4329805	-118.6491157	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24079-TF	9/30/2026 9:15:00 AM					1100																		AtmAA
CV-24079-TF	9/30/2026 9:17:09 AM	20.2	64.4	0.0	15.4			0.3	0.0	162.3	163.3	-2.12	-2.11			2.114	2.108	-7.41	-7.64	28.47	1343	34.4329769	-118.6491282	Valve Adjustment:No Flow Measurement,High Temp
CV-24080	9/1/2026 10:50:48 AM	18.9	68.8	0.0	12.3			0.3	0.0	123.5	123.6	-0.68	-0.68	1.5	3.0	0.002	0.007	-8.27		28.6	1335	34.4331360	-118.6489003	
CV-24080	9/9/2026 2:19:31 PM	31.2	48.7	0.0	20.1			0.6	0.0	128.3	128.4	-1.81	-1.83	16.1	22.7	0.176	0.350	-6.17		28.57	1329	34.4321602	-118.6487012	NSPS/EG CAC,
CV-24080	9/17/2026 10:09:09 AM	41.2	56.1	0.0	2.7			0.7	0.0	119.7	119.5	-1.96	-1.93	4.6	4.3	0.058	0.050	-8.86	-7.96	28.7	1344	34.4331267	-118.6488392	Valve Adjustment:Barely Open
CV-24081-TF	9/2/2026 9:06:17 AM	25.0	73.7	0.1	1.2			0.3	12.0	104.7	104.7	-0.13	-0.12			0.133	0.124	-11.78	-11.78	28.6	1349	34.4334087	-118.6485977	Valve Adjustment:Barely Open
CV-24081-TF	9/17/2026 1:48:26 PM	27.7	71.4	0.0	0.9			0.4	0.0	107.8	107.9	-1.10	-1.07			1.085	1.056	-9.84	-9.32	28.64	1356	34.4334192	-118.6486353	Valve Adjustment:Barely Open
CV-24082	9/2/2026 9:30:43 AM	43.2	54.8	0.0	2.0			0.8	0.0	122.8	122.5	-6.42	-5.74			6.708	5.972	-11.09	-11.49	28.6	1364	34.4334072	-118.6483257	Valve Adjustment:decreased Flow/Vacuum
CV-24082	9/17/2026 1:53:48 PM	43.3	53.8	0.0	2.9			0.8	0.0	126.1	125.2	-4.92	-3.79			4.127	3.805	-7.84	-10.15	28.63	1357	34.4334343	-118.6483500	Valve Adjustment:decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24083	9/2/2026 8:49:34 AM	30.6	66.2	0.0	3.2			0.5	0.0	157.9	158.8	-2.59	-2.56			2.569	2.570	-2.84	-2.54	28.64	1365	34.4337136	-118.6483451	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24083	9/2/2026 8:50:00 AM					1430																		AtmAA
CV-24083	9/2/2026 8:50:00 AM						76700																	AtmAA; [User entered 7.67%]
CV-24083	9/8/2026 10:18:45 AM	19.3	68.8	0.1	11.8			0.3	118.0	152.8	153.8	-0.46	-0.44	0.0	0.0	0.777	0.385	-0.93		28.6	1391	34.4337317	-118.6483928	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24083	9/8/2026 10:26:00 AM					1360																		AtmAA
CV-24083	9/17/2026 1:55:13 PM	40.8	59.2	0.0	0.0			0.7	0.0	154.0	152.8	-2.29	-2.23			2.342	2.194	-2.38	-2.11	28.68	1364	34.4337039	-118.6483548	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24083	9/17/2026 1:57:00 PM					703.5																		AtmAA
CV-24083	9/23/2026 1:21:00 PM					1060																		AtmAA
CV-24083	9/23/2026 1:23:41 PM	7.6	74.2	0.0	18.2			0.1	0.0	149.5	148.0	-7.12	-7.08			7.426	7.329	-7.78	-7.71	28.47	1363	34.4337095	-118.6483465	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24083	9/30/2026 10:01:53 AM	39.9	60.1	0.0	0.0			0.7	0.0	137.8	138.2	-9.44	-9.38			10.011	9.957	-10.21	-10.04	28.48	1352	34.4337238	-118.6483368	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TF	9/2/2026 8:41:51 AM	28.3	71.2	0.0	0.5			0.4	0.0	185.2	185.4	-7.28	-6.82			7.533	7.166	-10.91	-10.78	28.64	1370	34.4338541	-118.6480293	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TF	9/2/2026 8:45:00 AM					2215																		AtmAA
CV-24084-TF	9/2/2026 8:45:00 AM						106300																	AtmAA; [User entered 10.63%]
CV-24084-TF	9/8/2026 10:20:41 AM	2.3	80.9	0.0	16.8			0.0	0.0	187.2	187.4	-4.28	-3.40	54.1	47.2	4.085	3.135			28.6	1332	34.4338592	-118.6479802	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24084-TF	9/8/2026 10:25:00 AM					3620																		AtmAA
CV-24084-TF	9/17/2026 1:59:08 PM	39.8	60.2	0.0	0.0			0.7	0.0	186.2	186.0	-5.27	-4.79			5.550	4.942	-8.14	-8.54	28.68	1365	34.4338397	-118.6480644	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [\"H2O]	Adj Stat Press [\"H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [\"H2O]	Adj Diff Press [\"H2O]	Sys Pressure [\"H2O]	Adj Avail Press [\"H2O]	Baro Press [\"Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
CV-24084-TF	9/17/2026 2:02:00 PM					3220																		AtmAA
CV-24084-TF	9/23/2026 1:13:00 PM					2770																		AtmAA
CV-24084-TF	9/23/2026 1:16:20 PM	7.0	79.8	0.0	13.2			0.1	0.0	186.1	186.3	-4.81	-4.46			4.962	4.431	-8.14	-7.81	28.46	1373	34.4338474	-118.6480523	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TF	9/30/2026 9:55:00 AM					2810																		AtmAA
CV-24084-TF	9/30/2026 9:57:04 AM	8.2	79.0	0.0	12.8			0.1	0.0	185.3	185.2	-8.02	-7.08			8.553	7.438	-11.32	-11.16	28.47	1360	34.4338413	-118.6480469	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24085	9/1/2026 11:10:02 AM	40.6	51.9	0.0	7.5			0.8	0.0	93.7	93.6	0.23	0.23	0.0	0.0	0.028	0.025	0.23		28.6	1280	34.4323987	-118.6488777	NSPS/EG CAI,Positive Static Press.
CV-24085	9/1/2026 11:10:35 AM	41.7	51.9	0.0	6.4			0.8	0.0	93.6	93.6	0.25	0.26	0.0	0.0	0.012	0.013	0.26		28.6	1280	34.4323852	-118.6488888	NSPS/EG CAI,Positive Static Press.
CV-24085	9/9/2026 2:14:51 PM	27.6	40.0	0.0	32.4			0.7	0.0	133.8	132.8	-0.83	-0.49	0.0	0.0	0.898	-0.099	-0.46		28.57	1299	34.4323227	-118.6490213	NSPS/EG CAI,High Temp
CV-24085	9/9/2026 2:15:24 PM	27.8	39.9	0.0	32.3			0.7	0.0	132.6	132.6	-0.51	-0.49	0.0	0.0	-0.085	-0.088	-0.48		28.57	1322	34.4323160	-118.6490775	NSPS/EG CAI,High Temp
CV-24085	9/18/2026 4:38:39 PM	24.4	33.8	0.1	41.7			0.7	417.0	130.9	129.8	-1.87	-1.66	18.4	15.6	0.938	0.678	0.66	0.67	28.6	1344	34.4324113	-118.6490002	Valve Adjustment:Decreased Flow/Vacuum
CV-24086	9/1/2026 10:18:55 AM	39.1	48.2	0.0	12.7			0.8	0.0	126.2	126.9	-1.13	-1.18	49.5	15.5	1.602	0.156	-6.68		28.6	1322	34.4328010	-118.6486468	.
CV-24086	9/17/2026 9:56:01 AM	39.7	46.0	0.1	14.2			0.9	142.0	127.3	127.4	-1.94	-1.93	13.5	12.7	0.499	0.447	-12.53	-11.71	28.7	1358	34.4328898	-118.6486847	Valve Adjustment:Barely Open
CV-24087	9/14/2026 1:57:58 PM	49.2	43.1	0.0	7.7			1.1	0.0	121.5	121.3	-0.38	-0.38	12.3	12.3	0.413	0.414	-8.47	-8.54	28.37	1377	34.4330130	-118.6481458	Valve Adjustment:Barely Open
CV-24087	9/21/2026 9:41:26 AM	44.1	42.0	0.8	13.1			1.1	16.4	123.4	123.3	-2.49	-2.48	54.1	53.0	8.160	7.810	-9.17	-8.83	28.55	1373	34.4329927	-118.6481192	Valve Adjustment:Surging Liquid in Header
CV-24088	9/2/2026 1:21:22 PM	47.4	52.6	0.0	0.0			0.9	0.0	112.6	113.1	-2.03	-2.03			2.016	2.010	-9.24	-9.32	28.55	1378	34.4335760	-118.6476442	Valve Adjustment:Barely Open
CV-24088	9/17/2026 3:03:53 PM	44.8	51.9	0.1	3.2			0.9	32.0	104.5	104.8	-2.43	-2.40			2.432	2.397	-9.18	-8.51	28.6	1374	34.4335813	-118.6476792	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24089	9/1/2026 2:52:55 PM	44.6	46.2	0.0	9.2			1.0	0.0	129.3	129.5	-0.48	-0.47	15.4	15.4	0.660	0.661	-5.54		28.56	1348	34.4324250	-118.6481377	.
CV-24089	9/22/2026 2:06:04 PM	31.6	40.4	0.1	27.9			0.8	279.0	129.1	129.2	-0.81	-0.80	16.4	11.3	0.746	0.357	-9.71	-9.16	28.45	1363	34.4324632	-118.6480998	Valve Adjustment:Barely Open
CV-24090	9/3/2026 12:03:50 PM	44.6	51.4	0.0	4.0			0.9	0.0	113.4	113.3	-0.49	-0.65			0.451	0.626	-8.20	-8.07	28.54	1374	34.4326817	-118.6475420	Valve Adjustment:Increased Flow/Vacuum
CV-24090	9/14/2026 1:45:37 PM	42.7	49.3	0.0	8.0			0.9	0.0	117.0	116.6	-1.27	-1.20			1.117	1.083	-9.70	-9.11	28.37	1373	34.4326970	-118.6475555	Valve Adjustment:Barely Open
CV-24090	9/21/2026 9:16:50 AM	40.0	49.7	0.0	10.3			0.8	0.0	108.3	108.4	-1.47	-1.45			1.463	1.451	-11.13	-10.56	28.55	1371	34.4327005	-118.6475340	.
CV-24091	9/14/2026 1:37:49 PM	54.6	42.3	0.0	3.1			1.3	0.0	111.2	111.3	-6.38	-6.53	18.7	17.0	0.956	0.793	-10.71	-10.07	28.37	1393	34.4330008	-118.6469258	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24091	9/21/2026 8:59:41 AM	56.2	40.7	0.0	3.1			1.4	0.0	98.8	100.0	-10.84	-10.82	6.3	1.5	0.107	0.006	-11.24	-10.81	28.53	1381	34.4329872	-118.6468902	Valve Adjustment:Valve 100% Open
CV-24092	9/14/2026 1:27:47 PM	51.3	45.1	0.0	3.6			1.1	0.0	119.4	119.5	-3.65	-3.64	36.0	36.0	3.592	3.588	-9.53	-9.92	28.36	1395	34.4333165	-118.6461510	Valve Adjustment:Barely Open
CV-24092	9/24/2026 2:16:45 PM	50.9	46.7	0.0	2.4			1.1	0.0	119.9	119.8	-3.25	-3.26	34.2	34.4	3.234	3.260	-9.51	-9.58	28.44	1389	34.4333148	-118.6461470	.
CV-24093	9/13/2026 9:56:20 AM	29.5	22.6	10.3	37.6			1.3	3.6	99.4	98.3	-0.94	-0.94	1.5	1.8	0.005	0.008	-24.54	-24.33	28.47	1377	34.4340597	-118.6463428	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open;Well Comment:Pump is active;Well Condition:Poor,Lorentz Pump Installed
CV-24093	9/13/2026 9:58:10 AM	29.3	21.5	10.2	39.0			1.4	3.8	100.7	100.8	-0.95	-0.96	0.0	2.2	0.000	0.011	-24.77	-24.77	28.47	1380	34.4340730	-118.6463600	Valve Adjustment:Barely Open;Well Condition:Lorentz Pump Installed
CV-24093	9/28/2026 10:16:44 AM	0.2	3.9	20.0	75.9			0.1	3.8	80.1	80.4	-0.33	-0.34	2.9	2.6	0.019	0.015	0.40	0.38	28.41	1395	34.4340735	-118.6463412	.
CV-24094	9/14/2026 1:07:34 PM	19.3	70.0	3.0	7.7			0.3	2.6	102.9	102.9	-1.38	-1.37	0.3	0.3	0.009	0.009	-18.24		28.42	1411	34.4345155	-118.6460690	.
CV-24094	9/22/2026 10:05:46 AM	10.0	73.2	2.2	14.6			0.1	6.6	99.8	99.8	-0.62	-0.60	0.6	0.7	0.033	0.047	-11.58	-12.14	28.52	1372	34.4345660	-118.6460878	Valve Adjustment:Barely Open
CV-24095	9/1/2026 1:57:31 PM	5.3	71.6	0.0	23.1			0.1	0.0	186.0	186.2	-2.41	-2.42			2.420	2.413	-4.32	-4.44	28.72	1267	34.4333949	-118.6513113	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24095	9/1/2026 2:00:00 PM					2620																		AtmAA
CV-24095	9/1/2026 2:00:00 PM						159300																	AtmAA; [User entered 15.93%]
CV-24095	9/8/2026 1:30:00 PM					2940																		AtmAA
CV-24095	9/8/2026 1:31:41 PM	7.6	78.1	0.1	14.2			0.1	142.0	191.3	191.3	-1.91	-1.95	0.0	0.0	2.020	2.117	-1.96		28.69	1299	34.4331315	-118.6512473	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24095	9/10/2026 8:30:00 AM					2200																		AirTech Lab
CV-24095	9/10/2026 8:30:00 AM						180000																	AirTech Lab; [User entered 18%]
CV-24095	9/17/2026 9:42:47 AM	11.4	79.9	0.0	8.7			0.1	0.0	192.0	192.1	-5.15	-5.10			5.492	5.527	-8.35	-8.27	28.82	1260	34.4334194	-118.6512860	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24095	9/17/2026 9:47:00 AM					3210																		AtmAA
CV-24095	9/24/2026 9:52:08 AM	12.9	68.7	0.0	18.4			0.2	0.0	191.8	191.6	-7.41	-7.41			7.955	7.873	-10.74	-9.89	28.65	1254	34.4334084	-118.6512947	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24095	9/24/2026 10:00:00 AM					2670																		AtmAA
CV-24096	9/2/2026 8:14:01 AM	32.6	53.7	2.6	11.1			0.6	4.3	65.8	65.8	-2.39	-2.37	0.0	0.0	2.265	2.262	-2.31		28.71	1230	34.4332345	-118.6516627	.
CV-24096	9/23/2026 9:26:01 AM	30.5	40.7	4.5	24.3			0.7	5.4	87.7	88.4	-5.61	-5.44			5.875	5.718	-5.65	-5.53	28.6	1251	34.4332217	-118.6515660	Valve Adjustment:Decreased Flow/Vacuum
CV-24097	9/2/2026 8:18:03 AM	50.5	44.4	0.4	4.7			1.1	11.8	66.2	66.2	-3.21	-3.23	0.0	0.0	3.215	2.977	-3.40		28.71	1276	34.4327085	-118.6515597	Reduced System Vacuum,

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading	H2 Reading	CH4: CO2	BalO2	Init Temp	Adj Temp	Init Stat Press	Adj Stat Press	Init Flow	Adj Flow	Init Diff Press	Adj Diff Press	Sys Pressure	Adj Avail Press	Baro Press	Elev	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]	[ppmv]	[ppmv]		[%]	[°F]	[°F]	[°H2O]	[°H2O]	[scfm]	[scfm]	[°H2O]	[°H2O]	[°H2O]	[°H2O]	[°Hg]	[ft]			
CV-24097	9/30/2026 3:17:38 PM	41.6	40.3	0.0	18.1			1.0	0.0	99.3	99.4	2.75	0.67			0.000	0.000	2.87	0.52	28.45	1238	34.4328117	-118.6515068	Valve Adjustment:Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24098	9/2/2026 8:23:38 AM	43.7	51.6	0.3	4.4			0.8	14.7	72.3	72.3	-7.95	-7.38	0.0	0.0	7.929	7.186	-7.23		28.71	1257	34.4324882	-118.6512422	Reduced System Vacuum,
CV-24098	9/23/2026 9:16:20 AM	43.9	48.5	1.3	6.3			0.9	4.8	88.4	89.4	-11.66	-11.49			11.813	11.712	-11.54	-11.43	28.61	1247	34.4325072	-118.6512940	Well Comment:Valve stuck open
CV-24099	9/2/2026 8:32:12 AM	23.3	50.2	4.6	21.9			0.5	4.8	67.0	66.4	-7.76	-7.91	0.0	0.0	7.545	7.790	-7.47		28.71	1322	34.4323762	-118.6510242	Reduced System Vacuum,
CV-24099	9/23/2026 9:11:30 AM	0.0	4.8	19.5	75.7			0.0	3.9	79.8	80.5	-11.20	-11.53			11.426	11.646	-11.24	-11.48	28.6	1259	34.4323088	-118.6509557	Valve Adjustment: NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected;Well Comment:Valve stuck open
CV-24099	9/23/2026 9:13:00 AM	0.1	2.0	19.9	78.0			0.1	3.9	81.1	81.2	-10.68	-11.35			10.871	11.546	-10.75	-11.23	28.6	1257	34.4323130	-118.6509193	Valve Adjustment:High O2,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected;Well Comment:Valve stuck open
CV-24100	9/2/2026 8:50:27 AM	44.1	52.5	0.3	3.1			0.8	10.3	97.3	97.3	-8.85	-8.87	0.0	0.0	9.048	8.889	-8.71		28.7	1250	34.4318308	-118.6502663	.
CV-24100	9/2/2026 1:05:00 PM					144																		AtmAA
CV-24100	9/2/2026 1:05:00 PM						5600																	AtmAA; [User entered 0.56%]
CV-24100	9/2/2026 1:12:10 PM	33.8	66.2	0.0	0.0			0.5	0.0	151.7	153.7	0.52	-2.38			0.000	2.370	-8.44	-8.79	28.72	1261	34.4320575	-118.6505007	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24100	9/2/2026 1:16:31 PM	33.4	66.6	0.0	0.0			0.5	0.0	152.1	152.6	-2.41	-2.42			2.415	2.424	-8.81	-8.42	28.71	1262	34.4320563	-118.6505004	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	9/8/2026 7:35:00 AM					38																		AirTech Lab
CV-24100	9/8/2026 7:35:00 AM						6300																	AirTech Lab; [User entered 0.63%]
CV-24100	9/8/2026 2:53:01 PM	29.5	70.4	0.1	0.0			0.4	0.0	147.6	148.4	-1.51	-1.48	0.0	0.0	1.379	1.382	-6.92		28.7	1234	34.4320318	-118.6505738	NSPS/EG CAI,High Temp
CV-24100	9/8/2026 2:55:00 PM					192																		AtmAA
CV-24100	9/17/2026 2:15:00 PM					348																		AtmAA
CV-24100	9/17/2026 2:19:56 PM	35.9	64.1	0.0	0.0			0.6	0.0	148.6	148.5	-8.62	-8.47			8.916	8.943	-9.23	-10.86	28.75	1263	34.4320557	-118.6504980	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	9/17/2026 2:21:00 PM	35.6	64.4	0.0	0.0			0.6	0.0	148.7	149.0	-9.31	-8.93			9.615	9.179	-10.66	-9.18	28.75	1263	34.4320598	-118.6504961	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	9/24/2026 10:19:50 AM	29.3	70.3	0.3	0.1			0.4	0.3	142.1	133.8	-12.64	-12.13			13.209	12.517	-13.84	-13.18	28.65	1268	34.4320480	-118.6504950	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	9/24/2026 10:25:00 AM					137																		AtmAA
CV-24100	9/28/2026 1:58:23 PM	17.4	80.9	1.1	0.6			0.2	0.5	122.3	125.7	-12.00	-5.25			11.958	5.155	-12.19	-11.26	28.53	1243	34.4320353	-118.6504885	Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum
CV-24101	9/8/2026 7:30:00 AM					0																		AirTech Lab
CV-24101	9/8/2026 7:30:00 AM						1200																	AirTech Lab; [User entered 0.12%]
CV-24101	9/28/2026 1:59:13 PM	17.6	80.4	0.5	1.5			0.2	3.0	127.9	128.1	-6.06	-5.97			5.981	5.915	-11.97	-13.02	28.52	1249	34.4320435	-118.6504778	
CV-24102	9/2/2026 9:21:46 AM	43.1	47.1	0.0	9.8			0.9	0.0	101.0	101.1	-2.00	-1.95	0.0	0.0	1.759	1.755	-13.37		28.68	1316	34.4315287	-118.6498003	
CV-24102	9/22/2026 12:22:15 PM	40.3	52.4	0.0	7.3			0.8	0.0	101.9	101.7	-0.44	-0.40	0.0	0.0	0.832	0.573	-9.07		28.58	1263	34.4316202	-118.6499008	
CV-24103	9/1/2026 11:30:43 AM	41.2	42.6	0.0	16.2			1.0	0.0	111.6	111.7	-0.69	-0.68	5.7	5.7	0.676	0.675	-9.39		28.63	1309	34.4316838	-118.6489393	
CV-24103	9/21/2026 11:54:27 AM	42.1	41.4	0.0	16.5			1.0	0.0	110.5	110.6	-0.90	-0.90	5.3	5.3	0.587	0.583	-10.75	-11.06	28.67	1322	34.4316372	-118.6488253	Valve Adjustment:Audible Flow
CV-24104	9/1/2026 1:54:55 PM	44.1	49.9	0.0	6.0			0.9	0.0	101.7	101.8	-0.41	-0.24	3.1	3.0	1.072	0.973	-9.52		28.58	1339	34.4319182	-118.6479823	
CV-24104	9/3/2026 10:55:10 AM	40.5	53.8	0.0	5.7			0.8	0.0	101.4	101.6	-0.50	-0.65	3.7	3.7	1.428	1.430	-10.36	-10.18	28.58	1345	34.4318688	-118.6481022	Valve Adjustment:Increased Flow/Vacuum,Barely Open
CV-24104	9/21/2026 12:21:54 PM	41.8	52.5	0.0	5.7			0.8	0.0	102.3	102.2	-0.77	-0.76	3.0	2.0	0.932	0.437	-10.51	-10.83	28.67	1340	34.4318703	-118.6480883	Valve Adjustment:Audible Flow,Barely Open
CV-24105	9/1/2026 2:02:32 PM	45.1	40.6	0.0	14.3			1.1	0.0	118.3	118.3	-0.45	-0.44	12.1	12.1	0.892	0.894	-8.77		28.58	1280	34.4319265	-118.6477470	
CV-24105	9/22/2026 3:05:41 PM	41.1	41.4	0.0	17.5			1.0	0.0	118.2	118.3	-0.41	-0.41	13.5	13.1	1.168	1.101	-9.40	-9.06	28.42	1347	34.4319162	-118.6476585	Valve Adjustment:Barely Open
CV-24106	9/15/2026 12:21:17 PM	42.4	37.3	0.0	20.3			1.1	0.0	129.7	129.1	-1.37	-1.14	7.2	4.8	0.143	0.064	-19.46	-20.45	28.6	1342	34.4321198	-118.6467325	Valve Adjustment:Decreased Flow/Vacuum
CV-24106	9/15/2026 12:21:57 PM	41.7	37.7	0.0	20.6			1.1	0.0	129.1	128.8	-1.15	-1.15	4.3	4.9	0.051	0.067	-19.90	-20.64	28.58	1343	34.4321255	-118.6467260	
CV-24107	9/9/2026 1:53:59 PM	38.1	43.2	0.0	18.7			0.9	0.0	126.1	126.9	-3.96	-3.76	0.0	0.0	4.103	3.766	-5.54		28.61	1289	34.4327040	-118.6462592	
CV-24108	9/9/2026 1:16:23 PM	44.9	46.7	0.0	8.4			1.0	0.0	136.5	135.0	-2.96	-0.88	0.0	0.0	-0.067	-0.005	-19.93		28.59	1375	34.4332038	-118.6454417	NSPS/EG CAI,High Temp
CV-24108	9/9/2026 1:17:42 PM	45.8	45.8	0.0	8.4			1.0	0.0	135.0	135.0	-0.59	-0.56	0.0	0.0	0.013	0.010	-16.90		28.59	1302	34.4331657	-118.6455800	NSPS/EG CAI,High Temp
CV-24109	9/9/2026 12:50:32 PM	30.3	44.7	1.4	23.6			0.7	16.9	124.4	124.6	-3.66	-3.21	0.0	0.0	3.845	3.200	-19.13		28.59	1365	34.4340008	-118.6449610	
CV-24110	9/3/2026 1:03:31 PM	26.9	71.4	0.0	1.7			0.4	0.0	131.3	131.5	-0.10	-0.10	18.1	18.4	0.214	0.220	-16.49	-19.18	28.48	1381	34.4345965	-118.6446968	Valve Adjustment:High Temp,Barely Open
CV-24111	9/3/2026 1:42:51 PM	41.7	52.5	0.1	5.7			0.8	57.0	117.9	116.7	-10.08	-6.65			10.144	6.653	-16.42	-18.16	28.45	1393	34.4353150	-118.6449560	Valve Adjustment:Decreased Flow/Vacuum
CV-24112	9/3/2026 1:20:04 PM	46.7	39.5	0.0	13.8			1.2	0.0	130.2	130.2	-1.74	-1.73	38.0	37.1	0.942	0.898	-18.84	-18.72	28.48	1385	34.4352323	-118.6442025	Valve Adjustment:Barely Open

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [\"H2O]	Adj Stat Press [\"H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [\"H2O]	Adj Diff Press [\"H2O]	Sys Pressure [\"H2O]	Adj Avail Press [\"H2O]	Baro Press [\"Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
CV-24114	9/23/2026 9:58:47 AM	54.2	40.5	0.0	5.3			1.3	0.0	121.0	122.0	-12.19	-15.29	29.6	28.2	0.578	0.531	-12.87	-15.66	28.57	1277	34.4308057	-118.6485413	Valve Adjustment:Valve 100% Open
CV-24116	9/24/2026 1:00:00 PM					20.3																		AtmAA (24 TAT Request)
CV-24116	9/24/2026 1:00:00 PM						3200																	AtmAA (24 TAT Request); [User entered 0.32%]
CV-24116	9/24/2026 1:11:51 PM						58000																	[User entered 5.8%]
CV-24116	9/24/2026 1:12:29 PM	51.0	43.8	0.0	5.2			1.2	0.0	118.7	118.3	-1.10	-1.09			1.088	1.079	-7.61	-7.48	28.65	1239	34.4316483	-118.6457223	Valve Adjustment:Reduce Sys. Vac. - Flare Down:Well Condition:Lorentz Pump Installed
CV-24116	9/24/2026 3:03:05 PM					25																		
CV-24117	9/24/2026 10:47:16 AM	32.5	38.4	0.0	29.1			0.8	0.0	107.0	107.0	-0.76	-0.68			0.755	0.675	-13.54	-13.86	28.59	1301	34.4323488	-118.6449450	
CV-24118	9/1/2026 9:00:54 AM	8.2	79.8	0.0	12.0			0.1	0.0	150.9	150.9	-0.68	-0.68			0.664	0.671	-14.34	-16.65	28.65	1316	34.4332862	-118.6438527	
CV-24118	9/2/2026 2:19:21 PM	31.1	52.0	0.0	16.9			0.6	0.0	150.5	151.0	-0.37	-0.38			0.299	0.311	-15.66	-15.65	28.66	1302	34.4332987	-118.6438870	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24118	9/2/2026 2:25:00 PM					3750																		AtmAA
CV-24118	9/2/2026 2:25:00 PM						133800																	AtmAA; [User entered 13.38%]
CV-24118	9/10/2026 9:35:00 AM					3110																		AtmAA
CV-24118	9/10/2026 9:38:23 AM	16.2	73.1	0.0	10.7			0.2	0.0	151.4	151.6	-0.11	-0.10			0.095	0.096	-14.71	-14.72	28.64	1304	34.4332950	-118.6438345	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24118	9/17/2026 10:36:18 AM	32.1	62.7	0.0	5.2			0.5	0.0	144.2	144.5	-4.84	-4.84			4.816	4.820	-24.86	-25.05	28.79	1291	34.4332868	-118.6438448	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24118	9/17/2026 10:39:00 AM					2010																		AtmAA
CV-24119	9/28/2026 2:35:12 PM	44.0	46.2	0.0	9.8			1.0	0.0	137.1	136.0	-0.70	-0.66			0.633	0.547	-21.11	-21.60	28.41	1261	34.4337282	-118.6423448	Valve Adjustment:High Temp,Barely Open
CV-24120	9/9/2026 8:10:00 AM					680																		AirTech Lab
CV-24120	9/9/2026 8:10:00 AM						42000																	AirTech Lab; [User entered 4.2%]
CV-24120	9/14/2026 10:25:29 AM	3.3	39.8	10.8	46.1			0.1	4.3	97.7	97.7	-6.64	-3.05			6.984	3.010	-6.77	-6.57	28.59	1344	34.4368285	-118.6472872	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
CV-24120	9/14/2026 10:27:15 AM	2.5	29.5	12.9	55.1			0.1	4.3	97.7	97.7	-4.09	-4.04			4.017	3.980	-6.40	-6.51	28.59	1335	34.4368475	-118.6472788	
CV-24120	9/25/2026 10:26:04 AM	1.7	18.2	15.1	65.0			0.1	4.3	92.2	92.0	-4.70	-4.28			4.707	4.284	-8.33	-8.39	28.57	1333	34.4368447	-118.6472772	Valve Adjustment:Decreased Flow/Vacuum
CV-24120	9/28/2026 9:41:44 AM	7.8	92.2	0.0	0.0			0.1	0.0	89.4	84.7	4.93	-1.78			0.000	1.789	-9.49	-9.55	28.45	1352	34.4368405	-118.6472745	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-24120	9/28/2026 9:50:35 AM	6.9	89.6	0.9	2.6			0.1	2.9	91.6	91.5	-6.03	-6.00			6.389	6.331	-9.42	-9.20	28.47	1336	34.4368523	-118.6472812	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24121	9/3/2026 9:37:51 AM	23.6	52.8	2.6	21.1			0.4	8.0	99.9	125.5	120.52	-1.09			0.000	1.116	-6.33	-5.79	28.58	1333	34.4369440	-118.6470215	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-24121	9/3/2026 9:43:25 AM	31.6	51.2	3.6	13.7			0.6	3.8	125.7	125.5	-1.67	-1.70			1.654	1.759	-5.39	-4.96	28.57	1340	34.4369442	-118.6470290	Valve Adjustment:NSPS/EG CAC
CV-24121	9/10/2026 9:45:00 AM					25																		AirTech Lab
CV-24121	9/10/2026 9:45:00 AM						1600																	AirTech Lab; [User entered 0.16%]
CV-24121	9/25/2026 10:30:06 AM	31.7	67.5	0.0	0.8			0.5	0.0	127.2	127.4	-7.31	-5.47			7.693	5.899	-8.11	-8.11	28.58	1335	34.4369802	-118.6470150	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24122	9/8/2026 8:20:00 AM					200																		AirTech Lab
CV-24122	9/8/2026 8:20:00 AM						15000																	AirTech Lab; [User entered 1.5%]
CV-24122	9/15/2026 7:57:25 AM	27.9	24.0	10.3	37.8			1.2	3.7	67.3	67.4	-7.11	-7.11	47.9	47.9	5.818	5.809	-6.28	-6.27	28.58	1304	34.4371792	-118.6466323	Valve Adjustment:NSPS/EG CAI,High O2
CV-24122	9/15/2026 7:58:33 AM	27.9	24.0	10.3	37.8			1.2	3.7	67.5	67.5	-7.05	-7.39	47.6	48.1	5.742	5.872	-6.25	-6.42	28.58	1296	34.4371765	-118.6466377	
CV-24122	9/25/2026 10:38:50 AM	32.8	27.6	7.3	32.3			1.2	4.4	99.6	100.1	-4.96	-5.06	0.4	0.6	0.009	0.016	-4.97	-4.99	28.6	1313	34.4371658	-118.6466385	Valve Adjustment:High O2,Opened for Sample,Increased Flow/Vacuum,Plugged/Pinched Suspected
CV-24123	9/3/2026 9:17:50 AM	45.4	50.6	0.0	3.9			0.9	0.0	117.1	117.3	-3.49	-3.67	2.4	2.9	0.015	0.022	-6.89	-6.62	28.61	1284	34.4373050	-118.6462557	Valve Adjustment:Increased Flow/Vacuum
CV-24123	9/11/2026 3:37:45 PM	50.5	49.5	0.0	0.0			1.0	0.0	117.0		-3.32	-3.47			0.196	0.228	-6.30	-6.28	28.49	1300	34.4372933	-118.6462211	Valve Adjustment:Increased Flow/Vacuum
CV-24123	9/11/2026 3:38:20 PM	50.9	49.1	0.0	0.0			1.0	0.0	117.0		-3.52	-3.53			0.219	0.204	-6.14	-6.32	28.49	1301	34.4372888	-118.6462239	Valve Adjustment:Audible
CV-24123	9/23/2026 8:27:33 AM	46.6	49.4	0.0	4.0			0.9	0.0	117.0	116.6	-6.11	-5.29	4.3	3.8	0.051	0.040	-9.26	-9.58	28.59	1303	34.4372990	-118.6462398	Flow,Decreased Flow/Vacuum
CV-24124	9/15/2026 10:14:34 AM	6.4	67.4	1.3	24.9			0.1	19.2	135.9	136.0	-0.77	-0.77	0.0	0.0	0.729	0.725	-4.83		28.56	1309	34.4367153	-118.6469675	NSPS/EG CAI,High Temp
CV-24124	9/15/2026 10:15:20 AM	5.7	71.2	1.3	21.8			0.1	16.8	135.9	135.9	-0.74	-0.75	0.0	0.0	0.738	0.732	-4.88		28.56	1365	34.4366338	-118.6470908	NSPS/EG CAI,High Temp
CV-24124	9/29/2026 8:14:35 AM	6.2	60.8	2.3	30.7			0.1	13.1	134.1	133.9	-4.21	-4.20			4.239	4.234	-10.00	-9.90	28.35	1348	34.4366625	-118.6470088	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24124	9/29/2026 8:15:27 AM	6.2	61.0	2.3	30.6			0.1	13.2	133.4	133.9	-4.22	-4.21			4.287	4.246	-10.05	-9.82	28.36	1340	34.4366480	-118.6470102	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O"]	Adj Stat Press ["H2O"]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O"]	Adj Diff Press ["H2O"]	Sys Pressure ["H2O"]	Adj Avail Press ["H2O"]	Baro Press ["Hg"]	Elev [ft]	Latitude	Longitude	Comments
CV-24125-Tf	9/9/2026 8:20:00 AM					0																		AirTech Lab
CV-24125-Tf	9/9/2026 8:20:00 AM						1400																	AirTech Lab; [User entered 0.14%]
CV-24125-Tf	9/14/2026 9:25:49 AM	37.6	48.1	1.5	12.8			0.8	8.5	124.2	121.4	-8.02	-4.23			8.294	4.179	-10.16	-10.19	28.58	1325	34.4369652	-118.6463240	Valve Adjustment:Decreased Flow/Vacuum
CV-24125-Tf	9/29/2026 8:05:16 AM	44.1	51.3	0.0	4.6			0.9	0.0	90.0	89.9	-6.08	-6.08			6.357	6.348	-13.79	-13.88	28.38	1336	34.4369652	-118.6463265	Well Condition:Pnumatic Pump Installed
CV-24126	9/8/2026 2:01:24 PM	15.0	63.4	0.0	21.6			0.2	0.0	189.3	189.4	-2.35	-2.34			2.360	2.315	0.28	0.29	28.6	1386	34.4363679	-118.6471270	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24126	9/8/2026 2:04:00 PM					3490																	AtmAA	
CV-24126	9/14/2026 1:36:52 PM	16.3	40.1	2.3	41.3			0.4	18.0	177.6	177.7	-3.54	-3.14			3.504	3.172	0.18	0.29	28.42	1389	34.4363864	-118.6471412	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24126	9/14/2026 1:40:00 PM					1340																	AtmAA	
CV-24126	9/21/2026 1:17:00 PM					1360																	AtmAA	
CV-24126	9/21/2026 1:17:21 PM	19.1	34.2	3.2	43.5			0.6	13.6	174.2	174.1	-4.85	-4.87			5.079	5.075	-5.64	-5.61	28.51	1381	34.4363820	-118.6471044	Valve Adjustment:No Flow Measurement,High Temp
CV-24126	9/28/2026 1:36:03 PM	13.4	35.4	2.7	48.5			0.4	18.0	174.0	174.2	-5.83	-5.39			6.089	5.687	0.00	0.00	28.38	1375	34.4363779	-118.6471433	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24126	9/28/2026 1:45:00 PM					1370																	AtmAA	
CV-24127	9/8/2026 8:00:00 AM					2600																	AirTech Lab	
CV-24127	9/8/2026 8:00:00 AM						180000																AirTech Lab; [User entered 18%]	
CV-24127	9/8/2026 2:06:28 PM	8.9	69.4	0.0	21.7			0.1	0.0	177.2	177.2	-2.91	-2.77			2.901	2.783	-3.27	-3.07	28.59				Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24127	9/8/2026 2:09:00 PM					3930																	AtmAA	
CV-24127	9/14/2026 1:33:01 PM	28.2	67.5	0.0	4.3			0.4	0.0	160.3	160.3	-3.99	-3.92			3.941	3.902	-4.35	-4.21	28.42	1376	34.4364448	-118.6468262	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24127	9/14/2026 1:36:00 PM					1620																	AtmAA	
CV-24127	9/21/2026 1:12:42 PM	34.5	65.5	0.0	0.0			0.5	0.0	164.0	164.3	-4.83	-4.80			4.805	4.807	-6.15	-6.11	28.52	1384	34.4364483	-118.6468392	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24127	9/21/2026 1:13:00 PM					1780																	AtmAA	
CV-24127	9/28/2026 1:25:09 PM	26.7	40.6	0.5	32.2			0.7	64.4	151.6	151.4	-6.07	-6.07			6.351	6.385	-6.75	-6.74	28.38	1376	34.4364689	-118.6468414	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24127	9/28/2026 1:35:00 PM					1760																	AtmAA	
CV-24128	9/9/2026 12:13:22 PM	23.5	70.8	0.3	5.4			0.3	18.0	145.6	123.0	-0.61	-0.59			0.520	0.533	-9.30	-9.01	28.6	1362	34.4366942	-118.6464257	Valve Adjustment:NSPS/Eg CAC,High Temp,Barely Open
CV-24128	9/9/2026 12:14:49 PM	24.0	69.7	0.3	6.0			0.3	20.0	122.3	122.3	-0.50	-0.51			0.417	0.433	-6.44	-6.72	28.6	1358	34.4367017	-118.6464352	Valve Adjustment:NSPS/Eg CAC,Barely Open
CV-24128	9/10/2026 9:35:00 AM					2700																	AirTech Lab	
CV-24128	9/10/2026 9:35:00 AM						110000																AirTech Lab; [User entered 11%]	
CV-24128	9/25/2026 9:55:31 AM	23.1	58.8	0.3	17.8			0.4	59.3	127.8	127.8	-1.07	-1.10			1.058	1.094	-11.69	-11.68	28.53	1363	34.4367142	-118.6464303	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24129	9/9/2026 12:18:22 PM	43.9	55.4	0.7	0.0			0.8	0.0	130.8	130.8	-6.84	-6.09			7.350	6.513	-6.19	-6.02	28.61	1346	34.4366892	-118.6461563	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24129	9/25/2026 9:45:34 AM	45.6	54.4	0.0	0.0			0.8	0.0	130.6	130.0	-9.62	-9.32			9.944	9.542	-11.72	-11.70	28.56	1345	34.4367117	-118.6461688	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24130	9/30/2026 2:09:18 PM	18.7	72.0	0.0	9.3			0.3	0.0	126.1	125.6	-0.30	-0.29			0.314	0.297	-3.64	-4.00	28.43	1327	34.4368120	-118.6456965	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-24131	9/10/2026 1:47:00 PM	40.1	58.5	0.2	1.2			0.7	6.0	127.2	127.3	-0.12	-0.15	13.0	13.6	0.466	0.509	-10.31	-10.45	28.51	1325	34.4367267	-118.6450742	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24132	9/30/2026 10:16:29 AM	50.4	44.1	0.0	5.5			1.1	0.0	129.4	129.7	-8.73	-8.78	13.8	12.3	0.052	0.041	-12.67	-12.86	28.54	1286	34.4372418	-118.6440413	Valve Adjustment:High Temp,Barely Open
CV-24133	9/21/2026 8:33:25 AM	48.0	41.7	0.0	10.3			1.2	0.0	123.9	123.7	-7.50	-7.50	22.1	22.2	1.360	1.378	-13.36	-13.56	28.63	1283	34.4374257	-118.6427150	Valve Adjustment:High Temp,Barely Open
CV-24134-Tf	9/10/2026 1:06:47 PM	21.9	70.2	0.1	7.8			0.3	78.0	153.2	153.0	-1.75	-1.78			1.713	1.738	-1.68	-1.77	28.49	1370	34.4363520	-118.6465075	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24134-Tf	9/14/2026 1:29:38 PM	25.7	68.2	0.0	6.1			0.4	0.0	152.3	152.0	-2.57	-2.55			2.568	2.549	-3.03	-3.03	28.42	1369	34.4363697	-118.6464983	AtmAA
CV-24134-Tf	9/14/2026 1:32:00 PM					2890																	AtmAA	
CV-24134-Tf	9/21/2026 1:07:00 PM					3140																	AtmAA	
CV-24134-Tf	9/21/2026 1:09:25 PM	36.4	63.5	0.0	0.1			0.6	0.0	151.7	152.2	-2.66	-2.63			2.661	2.639	-3.07	-3.07	28.53	1372	34.4363611	-118.6464995	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24134-Tf	9/28/2026 1:06:51 PM	25.8	69.5	0.0	4.7			0.4	0.0	150.0	150.1	-0.91	-0.89			0.816	0.801	-1.35	-1.35	28.4	1368	34.4363582	-118.6465083	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24134-Tf	9/28/2026 1:25:00 PM					2760																	AtmAA	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [""H2O]	Adj Stat Press [""H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [""H2O]	Adj Diff Press [""H2O]	Sys Pressure [""H2O]	Adj Avail Press [""H2O]	Baro Press [""Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
CV-24135	9/3/2026 9:48:00 AM					4220																		AtmAA
CV-24135	9/3/2026 9:48:00 AM						141700																	AtmAA; [User entered 14.17%]
CV-24135	9/3/2026 10:26:41 AM	21.7	71.0	0.0	7.3			0.3	0.0	150.4	150.4	-0.79	-0.81			0.785	0.792	-2.69	-2.64	28.57	1355	34.4363871	-118.6459611	Valve Adjustment:No Flow Measurement,High Temp
CV-24135	9/10/2026 2:23:00 PM					3960																		AtmAA
CV-24135	9/10/2026 2:26:00 PM	18.0	73.9	0.0	8.1			0.2	0.0	149.4	149.2	0.48	-0.25			0.000	0.268	-1.69	-1.65	28.5	1374	34.4363958	-118.6459794	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24135	9/10/2026 2:27:03 PM	16.8	73.4	0.0	9.8			0.2	0.0	149.3	149.2	-0.28	-0.28			0.272	0.282	-1.68	-1.68	28.5	1377	34.4363965	-118.6459810	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24135	9/14/2026 1:23:45 PM	23.7	67.8	0.0	8.5			0.3	0.0	150.1	150.2	-1.75	-1.74			1.737	1.747	-3.03	-3.03	28.43	1362	34.4363989	-118.6459679	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24135	9/14/2026 1:27:00 PM					4270																		AtmAA
CV-24135	9/24/2026 1:53:54 PM	20.2	74.8	0.0	5.0			0.3	0.0	150.4	150.4	-1.16	-1.15			1.124	1.128	-2.15	-2.16	28.5	1370	34.4364099	-118.6459664	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24135	9/24/2026 1:55:00 PM					4070																		AtmAA
CV-24136	9/10/2026 1:43:56 PM	26.1	64.2	0.2	9.5			0.4	47.5	135.6	135.7	-1.32	-1.31			1.266	1.273	-5.92	-6.51	28.52	1329	34.4366128	-118.6442960	Valve Adjustment:Barely Open
CV-24137	9/28/2026 1:45:23 PM	43.7	44.1	0.0	12.2			1.0	0.0	105.6	104.2	-3.65	-3.65			3.667	3.662	-22.65	-22.31	28.37	1371	34.4361553	-118.6434965	Valve Adjustment:Barely Open
CV-24138	9/2/2026 7:35:00 AM					160																		AirTech Lab
CV-24138	9/2/2026 7:35:00 AM					25000																		AirTech Lab; [User entered 2.5%]
CV-24138	9/2/2026 7:58:13 AM	0.5	10.2	17.4	71.9			0.0	4.1	65.6	65.5	-3.91	-3.90	0.0	0.0	3.625	3.742	-3.85		28.7	1306	34.4342217	-118.6512640	NSPS/EG CAI,High O2
CV-24138	9/2/2026 7:59:07 AM	0.5	10.2	17.3	72.0			0.0	4.2	65.3	65.3	-4.08	-4.07	0.0	0.0	3.919	3.838	-3.96		28.7	1302	34.4342333	-118.6512605	NSPS/EG CAI,High O2
CV-24138	9/30/2026 2:54:56 PM	2.3	72.3	0.2	25.2			0.0	126.0	162.2	161.4	-4.34	-4.38			4.344	4.347	-4.39	-4.45	28.45	1267	34.4342628	-118.6512385	Valve Adjustment:High Temp,Barely Open
CV-24139	9/1/2026 1:45:00 PM					1070																		AtmAA
CV-24139	9/1/2026 1:45:00 PM						180100																	AtmAA; [User entered 18.01%]
CV-24139	9/1/2026 1:48:41 PM	5.5	70.8	0.4	23.3			0.1	58.3	145.4	145.4	-5.52	-5.53			5.666	5.590	-5.52	-5.54	28.7	1276	34.4344923	-118.6511560	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24139	9/2/2026 7:30:00 AM					720																		AirTech Lab
CV-24139	9/2/2026 7:30:00 AM						210000																	AirTech Lab; [User entered 21%]
CV-24139	9/8/2026 1:22:11 PM	8.7	58.3	4.3	28.7			0.1	6.7	110.5	110.5	-5.34	-4.90	0.0	0.0	5.220	5.065	-4.74		28.66	1220	34.4345005	-118.6511732	NSPS/EG CAC,Reduced System Vacuum
CV-24139	9/10/2026 2:55:48 PM	1.9	2.1	20.3	75.7			0.9	3.7	132.1	129.5	-4.74	-2.49			4.735	2.507	-4.88	-5.14	28.58	1280	34.4344994	-118.6511353	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24139	9/10/2026 3:13:23 PM	9.3	16.2	15.6	58.9			0.6	3.8	127.2	125.3	-1.12	-1.10			1.157	1.139	-4.86	-5.01	28.57	1280	34.4344991	-118.6511363	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24139	9/10/2026 3:15:24 PM	8.9	18.3	15.0	57.8			0.5	3.9	125.4	125.4	-0.67	-0.67			0.688	0.692	-4.94	-4.92	28.57	1280	34.4344991	-118.6511365	Valve Adjustment:No Flow Measurement;Well Condition:Pnumatic Pump Installed
CV-24139	9/30/2026 2:51:42 PM	4.2	53.0	7.8	35.0			0.1	4.5	128.4	129.2	-7.90	-7.71			8.057	7.886	-7.97	-7.89	28.45	1270	34.4345080	-118.6511198	Valve Adjustment:High O2,Barely Open
CV-24140	9/1/2026 1:40:00 PM					2160																		AtmAA
CV-24140	9/1/2026 1:40:00 PM						182800																	AtmAA; [User entered 18.28%]
CV-24140	9/1/2026 1:44:48 PM	3.8	74.8	0.0	21.4			0.1	0.0	164.0	164.0	-4.96	-4.94			5.000	5.075	-5.03	-5.12	28.69	1283	34.4346600	-118.6511438	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24140	9/2/2026 7:25:00 AM					1400																		AirTech Lab
CV-24140	9/2/2026 7:25:00 AM						210000																	AirTech Lab; [User entered 21%]
CV-24140	9/8/2026 1:16:52 PM	3.4	73.7	0.6	22.3			0.0	37.2	165.9	166.0	-4.55	-4.56	0.0	0.0	4.552	4.684	-4.58		28.53	1234	34.4347035	-118.6511152	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24140	9/8/2026 1:20:00 PM					2140																		AtmAA
CV-24140	9/17/2026 9:53:55 AM	7.1	72.3	0.3	20.3			0.1	67.7	154.7	153.3	-8.42	-8.13			8.789	8.635	-9.37	-9.09	28.8	1273	34.4346782	-118.6511147	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24140	9/17/2026 9:55:00 AM					2120																		AtmAA
CV-24140	9/24/2026 9:42:13 AM	7.8	72.8	0.3	19.1			0.1	63.7	145.3	145.5	-9.47	-9.32			9.937	9.784	-9.67	-9.46	28.61	1280	34.4346749	-118.6511171	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24140	9/24/2026 9:45:00 AM					1290																		AtmAA
CV-24141	9/2/2026 7:10:00 AM					26																		AirTech Lab
CV-24141	9/2/2026 7:10:00 AM						1900																	AirTech Lab; [User entered 0.19%]

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading	H2 Reading	CH4: CO2	BalO2	Init Temp	Adj Temp	Init Stat Press	Adj Stat Press	Init Flow	Adj Flow	Init Diff Press	Adj Diff Press	Sys Pressure	Adj Avail Press	Baro Press	Elev	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]	[ppmv]	[ppmv]		[%]	[°F]	[°F]	[\"H2O]	[\"H2O]	[scfm]	[scfm]	[\"H2O]	[\"H2O]	[\"H2O]	[\"H2O]	[\"Hg]	[ft]			
CV-24141	9/15/2026 9:57:58 AM	2.1	6.4	17.6	73.9			0.3	4.2	90.4	91.6	-4.95	-5.12			5.045	5.113	-4.99	-5.10	28.67	1295	34.4354872	-118.6513138	Valve Adjustment: NSPS/EG CAI, High O2, Barely Open, Surging Liquid in Well (Watered In)
CV-24141	9/15/2026 9:59:24 AM	2.1	5.6	17.7	74.6			0.4	4.2	92.2	92.1	-5.25	-5.27			5.226	5.262	-5.16	-5.10	28.67	1299	34.4354905	-118.6513135	
CV-24141	9/23/2026 9:57:06 AM	0.9	6.1	18.4	74.6			0.1	4.1	95.9	94.6	-7.13	-3.58			7.603	3.576	-7.14	-7.24	28.55	1304	34.4354748	-118.6513263	Valve Adjustment: High O2, Decreased Flow/Vacuum, Surging Liquid in Well (Watered In), Plugged/Pinched Suspected
CV-24142	9/1/2026 1:54:21 PM	4.0	65.9	2.7	27.4			0.1	10.1	128.0	128.2	-1.61	-1.61			1.601	1.596	-2.13	-2.18	28.73	1260	34.4339812	-118.6513562	Valve Adjustment: No Flow Measurement, Well Condition: Pneumatic Pump Installed
CV-24142	9/2/2026 7:40:00 AM					1200																		AirTech Lab
CV-24142	9/2/2026 7:40:00 AM						170000																	AirTech Lab; [User entered 17%]
CV-24142	9/30/2026 2:58:57 PM	1.6	52.9	7.2	38.3			0.0	5.3	130.5	130.5	-3.40	-3.42			3.391	3.421	-3.68	-3.91	28.45	1255	34.4339757	-118.6513368	Valve Adjustment: High O2
CV-24143	9/1/2026 7:40:00 AM					660																		Air Tech Lab
CV-24143	9/1/2026 7:40:00 AM						94000																	Air Tech Lab; [User entered 9.4%]
CV-24143	9/10/2026 12:19:01 PM	4.8	62.0	5.2	28.0			0.1	5.4	125.2	124.2	-1.95	-2.19			1.914	2.165	-1.86	-2.20	28.71	1286	34.4349895	-118.6512217	Valve Adjustment: NSPS/EG CAI, High O2, Decreased Flow/Vacuum, Surging Liquid in Header, Surging Liquid in Well (Watered In), Well Comment: No pump
CV-24143	9/10/2026 12:20:07 PM	3.9	61.0	5.3	29.8			0.1	5.6	123.9	124.1	-2.23	-1.93			2.169	1.893	-2.18	-1.86	28.71	1292	34.4350137	-118.6512360	
CV-24143	9/23/2026 9:50:14 AM	1.7	71.2	2.9	24.2			0.0	8.3	100.3	100.4	-7.99	-4.25			8.342	4.250	-8.18	-8.15	28.56	1285	34.4349848	-118.6512180	Valve Adjustment: Decreased Flow/Vacuum, Barely Open, Surging Liquid in Well (Watered In), Plugged/Pinched Suspected
CV-24144	9/2/2026 8:20:25 AM	55.9	41.0	0.0	3.1			1.4	0.0	68.7	68.8	-0.90	-0.86	28.9	28.9	0.667	0.665			28.72	1224	34.4325943	-118.6515392	Reduced System Vacuum,
CV-24145	9/9/2026 8:26:12 AM	14.9	59.4	0.0	25.7			0.3	0.0	187.7	188.0	-5.25	-5.06			0.111	0.001	-10.43	-10.35	28.64	1351	34.4362334	-118.6496453	Valve Adjustment: High Temp
CV-24145	9/9/2026 8:28:00 AM					1620																		AtmAA
CV-24145	9/15/2026 8:52:56 AM	14.4	58.4	0.0	27.2			0.2	0.0	187.1	187.2	-4.71	-4.73			0.000	0.000	-9.07	-9.09	28.57	1371	34.4362282	-118.6496228	Valve Adjustment: No Flow Measurement, High Temp
CV-24145	9/15/2026 8:55:00 AM					1770																		AtmAA
CV-24145	9/22/2026 8:48:58 AM	12.6	40.1	0.0	47.3			0.3	0.0	187.6	187.6	-3.76	-3.76			0.000	0.000	-10.15	-10.11	28.56	1356	34.4362284	-118.6496183	Valve Adjustment: No Flow Measurement, High Temp
CV-24145	9/22/2026 8:50:00 AM					1100																		AtmAA
CV-24145	9/29/2026 8:14:25 AM	8.7	72.8	0.0	18.5			0.1	0.0	187.9	187.6	-6.46	-6.44			0.000	0.000	-12.14	-12.22	28.35	1359	34.4362275	-118.6496108	Valve Adjustment: High Temp, Well Condition: Lorentz Pump Installed
CV-24145	9/29/2026 8:20:00 AM					2250																		AtmAA
CV-24146	9/11/2026 3:43:00 PM	54.5	45.5	0.0	0.0			1.2	0.0	115.0		-4.73	-4.92	16.0	18.4	0.334	0.442	-5.89	-6.15	28.49	1305	34.4374029	-118.6463693	Valve Adjustment: Increased Flow/Vacuum
CV-24146	9/11/2026 3:43:31 PM	58.8	41.2	0.0	0.0			1.4	0.0			-4.92	-4.93	16.7	20.0	0.329	0.476	-6.09	-6.18	28.49	1305	34.4374050	-118.6463694	
CV-24146	9/23/2026 8:23:00 AM	54.1	40.1	0.0	5.8			1.3	0.0	113.9	113.9	-7.63	-7.56	24.3	24.0	0.773	0.755	-9.13	-9.12	28.59	1313	34.4374017	-118.6463642	Valve Adjustment: Audible Flow
CV-24146	9/29/2026 7:46:29 AM	52.8	41.6	0.0	5.6			1.3	0.0	113.9	114.1	-7.09	-6.76	26.5	28.8	0.926	1.096	-8.82	-8.56	28.42	1312	34.4374220	-118.6463597	Valve Adjustment: Increased Flow/Vacuum
CV-24146	9/29/2026 7:48:05 AM	52.6	42.0	0.0	5.4			1.3	0.0	114.2	114.2	-7.17	-7.28	27.8	28.0	1.024	1.034	-8.92	-9.15	28.39	1305	34.4374292	-118.6463440	
CV-24147	9/14/2026 8:55:38 AM	52.0	42.3	0.0	5.7			1.2	0.0	115.3	115.3	-8.04	-8.08	21.2	24.7	0.117	0.159	-8.77	-8.51	28.62	1280	34.4375253	-118.6459207	Valve Adjustment: Audible Flow
CV-24147	9/29/2026 7:53:08 AM	49.6	41.1	0.0	9.3			1.2	0.0	113.1	113.2	-9.07	-9.11	5.1	25.1	0.007	0.168	-9.69	-10.07	28.42	1297	34.4375065	-118.6459440	Valve Adjustment: Valve 100% Open
CV-24148	9/1/2026 1:15:45 PM	32.5	61.0	0.0	6.5			0.5	0.0	167.1	167.2	-12.50	-12.32			12.640	12.476	-15.12	-14.51	28.57	1388	34.4350570	-118.6466701	Valve Adjustment: No Flow Measurement, High Temp, Well Condition: Lorentz Pump Installed
CV-24148	9/1/2026 1:21:00 PM					983																		AtmAA
CV-24148	9/1/2026 1:21:00 PM						49050																	AtmAA; [User entered 4.905%]
CV-24148	9/9/2026 1:24:00 PM					1250																		AtmAA
CV-24148	9/9/2026 1:25:02 PM	47.4	52.6	0.0	0.0			0.9	0.0	172.7	172.6	-7.07	-6.74			7.146	6.871	-8.73	-8.29	28.57	1389	34.4350486	-118.6466625	Valve Adjustment: No Flow Measurement, High Temp, Well Condition: Lorentz Pump Installed
CV-24148	9/16/2026 9:01:24 AM	31.5	67.5	0.0	1.0			0.5	0.0	176.9	177.4	-4.09	-4.05			4.094	4.040	-4.66	-4.56	28.57	1374	34.4350767	-118.6466515	Valve Adjustment: No Flow Measurement, High Temp, Well Condition: Lorentz Pump Installed
CV-24148	9/16/2026 9:06:00 AM					1580																		AtmAA
CV-24148	9/23/2026 9:17:16 AM	42.1	57.9	0.0	0.0			0.7	0.0	174.7	174.6	-11.53	-11.46			11.925	11.896	-13.29	-13.35	28.49	1373	34.4350471	-118.6466506	Valve Adjustment: No Flow Measurement, High Temp, Well Condition: Lorentz Pump Installed
CV-24148	9/23/2026 9:21:00 AM					861																		AtmAA
CV-24148	9/30/2026 8:20:00 AM					1060																		AtmAA
CV-24148	9/30/2026 8:33:02 AM	32.0	61.7	0.0	6.3			0.5	0.0	166.2	166.4	-10.27	-10.27			10.492	10.492	-11.87	-11.87	28.45	1376	34.4350587	-118.6466532	Valve Adjustment: No Flow Measurement, High Temp, Well Condition: Lorentz Pump Installed
CV-24149	9/2/2026 2:26:43 PM	35.9	54.8	0.0	9.3			0.7	0.0	128.5	128.4	-0.19	-0.22	11.4	14.8	0.034	0.057	-6.19	-6.57	28.55	1377	34.4348108	-118.6470007	Valve Adjustment: Barely Open
CV-24149	9/28/2026 10:08:01 AM	31.9	63.3	0.0	4.8			0.5	0.0	129.0	129.2	-1.78	-1.78	13.4	14.3	0.047	0.054	-12.36	-12.55	28.41	1374	34.4347757	-118.6469842	Valve Adjustment: Barely Open

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
CV-24150	9/14/2026 1:00:56 PM	41.8	57.7	0.4	0.1			0.7	0.2	96.0	96.0	-1.29	-1.29	38.1	38.0	1.388	1.384			28.41	1375	34.4346792	-118.6458260	
CV-24150	9/22/2026 10:00:08 AM	42.7	57.2	0.1	0.0			0.7	0.0	111.8	111.7	-0.92	-0.91			0.903	0.903	-12.67	-12.77	28.52	1386	34.4345958	-118.6457500	Valve Adjustment:Barely Open
CV-24151	9/2/2026 1:38:48 PM	45.9	46.4	0.3	7.4			1.0	24.7	116.4	116.9	-3.72	-3.10			3.676	3.030	-5.54	-5.73	28.56	1366	34.4344155	-118.6476508	Valve Adjustment:Decreased Flow/Vacuum
CV-24151	9/28/2026 10:24:52 AM	39.9	55.5	0.0	4.6			0.7	0.0	121.9	122.9	-6.75	-5.32			6.965	5.598	-10.94	-10.85	28.41	1372	34.4344018	-118.6476223	Valve Adjustment:Decreased Flow/Vacuum
CV-24152	9/2/2026 2:13:03 PM	19.3	76.5	0.0	4.2			0.3	0.0	142.5	142.6	0.06	-0.09	27.9	28.4	1.886	1.963	-3.52	-3.54	28.53	1371	34.4344700	-118.6471673	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-24152	9/2/2026 2:14:21 PM	19.5	76.3	0.0	4.2			0.3	0.0	142.7	142.7	-0.15	-0.15	28.5	27.9	1.975	1.888	-3.56	-3.60	28.56	1370	34.4344550	-118.6471763	Valve Adjustment:NSPS/EG CAC,High Temp,Barely Open
CV-24152	9/21/2026 2:17:53 PM	18.6	72.6	0.2	8.6			0.3	43.0	144.3	144.3	-1.01	-0.87	31.0	31.3	2.349	2.401	-5.39	-5.11	28.48	1367	34.4344860	-118.6471603	Valve Adjustment:High Temp,Barely Open
CV-24153	9/2/2026 2:35:08 PM	38.0	61.9	0.0	0.1			0.6	0.0	116.9	116.7	-0.47	-0.46			0.463	0.439	-14.03	-14.06	28.52	1389	34.4343767	-118.6464272	
CV-24153	9/28/2026 10:19:05 AM	36.3	63.7	0.0	0.0			0.6	0.0	129.6	129.7	-0.73	-0.72			0.722	0.706	-12.91	-13.71	28.41	1373	34.4343738	-118.6463667	Valve Adjustment:Barely Open
CV-24154	9/3/2026 12:57:36 PM	44.2	52.3	0.0	3.4			0.8	0.0	108.8	109.0	-4.74	-4.99			5.131	5.307	-13.73	-14.80	28.53	1374	34.4342658	-118.6460745	Valve Adjustment:Increased Flow/Vacuum
CV-24154	9/24/2026 1:45:55 PM	40.3	58.9	0.0	0.8			0.7	0.0	113.7	113.2	-2.06	-1.92			2.016	1.941	0.31	0.31	28.45	1394	34.4342520	-118.6460977	Valve Adjustment:Barely Open
CV-24155	9/2/2026 2:32:05 PM	33.5	61.8	0.0	4.7			0.5	0.0	123.9	124.4	-1.02	-1.03			1.001	1.008	-5.95	-6.02	28.52	1402	34.4342888	-118.6467388	Valve Adjustment:Barely Open
CV-24155	9/28/2026 10:12:48 AM	37.7	56.9	0.0	5.4			0.7	0.0	128.5	128.6	-2.25	-2.24			2.246	2.215	-11.61	-11.46	28.41	1388	34.4342855	-118.6466958	Valve Adjustment:Barely Open
CV-24156	9/2/2026 8:34:18 AM	25.8	69.6	0.0	4.6			0.4	0.0	137.1	137.2	0.15	-0.45	43.1	50.3	0.491	0.670	-9.76	-9.72	28.61	1373	34.4340631	-118.6477078	Valve Adjustment:High Temp,Increased Flow/Vacuum,Well Condition:Lorentz Pump Installed
CV-24156	9/2/2026 8:35:16 AM	27.2	71.7	0.0	1.1			0.4	0.0	136.9	137.0	-0.60	-0.58	49.9	52.9	0.659	0.740	-9.86	-9.79	28.6	1373	34.4340622	-118.6477081	Valve Adjustment:High Temp,Well Condition:Lorentz Pump Installed
CV-24156	9/17/2026 2:44:43 PM	22.3	70.0	1.1	6.6			0.3	6.0	137.1	137.1	-0.44	-0.39	50.0	46.8	0.662	0.579	-8.91	-7.82	28.6	1360	34.4340402	-118.6477392	
CV-24157	9/2/2026 1:17:03 PM	45.6	54.0	0.4	0.0			0.8	0.0	108.1	108.4	-0.95	-0.96			0.924	0.959	-9.30	-9.45	28.53	1383	34.4338150	-118.6473410	Valve Adjustment:Barely Open
CV-24157	9/17/2026 2:54:47 PM	47.9	51.1	0.0	1.0			0.9	0.0	103.0	103.3	-1.35	-1.31			1.315	1.303	-8.90	-9.20	28.6	1374	34.4338202	-118.6473437	Valve Adjustment:Barely Open
CV-24158	9/2/2026 1:50:00 PM	44.0	56.0	0.0	0.0			0.8	0.0	127.9	127.9	-0.36	-0.34	13.0	12.9	0.463	0.462	-9.69	-9.77	28.52	1383	34.4339030	-118.6470790	Valve Adjustment:Barely Open
CV-24158	9/18/2026 9:48:59 AM	41.7	58.3	0.0	0.0			0.7	0.0	126.2	126.1	-1.20	-1.17	6.7	6.9	0.123	0.130	-4.98	-4.70	28.63	1386	34.4339055	-118.6470555	Valve Adjustment:Barely Open
CV-24159	9/13/2026 10:18:12 AM	46.6	49.3	0.0	4.0			0.9	0.0	128.6	128.5	-1.37	-1.24	17.2	14.5	0.706	0.503	-19.76	-20.74	28.47	1391	34.4338023	-118.6466167	Valve Adjustment:Decreased Flow/Vacuum
CV-24159	9/13/2026 10:19:02 AM	46.0	49.2	0.0	4.8			0.9	0.0	128.2	128.3	-1.18	-1.17	14.8	15.1	0.518	0.543	-21.88	-22.23	28.49	1394	34.4338112	-118.6466227	
CV-24159	9/25/2026 11:34:39 AM	28.9	68.1	0.0	3.0			0.4	0.0	126.8	130.8	0.32	-0.05	4.9	12.2	0.057	0.353	-1.59	-0.89	28.59	1397	34.4337948	-118.6466287	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Reduce Sys. Vac. - Flare Down;Well Comment:Parnell down at time of read;Well Condition:Lorentz Pump Installed
CV-24159	9/25/2026 11:37:32 AM	30.6	66.7	0.0	2.7			0.5	0.0	136.5	135.7	-1.14	-0.44	29.7	13.9	2.121	0.461	-6.66	-7.40	28.6	1407	34.4337783	-118.6466275	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header
CV-24159	9/25/2026 11:38:14 AM	31.1	65.6	0.0	3.3			0.5	0.0	135.7	135.4	-0.46	-0.42	16.5	16.1	0.651	0.617	-10.43	-9.52	28.61	1402	34.4337793	-118.6466275	
CV-24160	9/13/2026 10:07:13 AM	49.0	47.9	0.0	3.1			1.0	0.0	127.3	127.3	-2.22	-2.33	11.5	13.1	0.869	1.122	-24.35	-24.62	28.48	1383	34.4337957	-118.6462740	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24160	9/13/2026 10:08:00 AM	48.7	47.3	0.0	4.0			1.0	0.0	127.4	127.4	-2.38	-2.38	13.3	13.3	1.149	1.161	-24.43	-24.73	28.48	1400	34.4338042	-118.6462428	
CV-24160	9/24/2026 2:00:04 PM	47.8	52.2	0.0	0.0			0.9	0.0	127.3	127.2	-0.22	-0.14	12.5	15.3	0.370	0.555	-9.53	-11.49	28.45	1382	34.4337915	-118.6462653	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24161	9/14/2026 1:18:54 PM	37.6	49.9	0.0	12.5			0.8	0.0	128.8	128.2	-14.85	-7.77			14.871	7.967	0.21	0.21	28.37	1398	34.4338633	-118.6456153	Valve Adjustment:Decreased Flow/Vacuum
CV-24162	9/9/2026 1:08:06 PM	36.5	38.9	0.3	24.3			0.9	81.0	120.5	120.5	-0.91	-0.84	0.0	0.0	0.778	0.771	-20.29		28.58	1296	34.4336587	-118.6451240	
CV-24162	9/14/2026 1:22:08 PM	48.6	48.2	0.0	3.2			1.0	0.0	105.2	105.6	-2.42	-2.40			2.401	2.380	-17.24	-20.61	28.37	1396	34.4339360	-118.6460018	Valve Comment:Valve stuck
CV-24163	9/1/2026 9:47:08 AM	27.6	69.9	0.0	2.5			0.4	0.0	136.1	136.5	-0.29	-0.29			0.281	0.281	-16.54	-15.59	28.6	1334	34.4334860	-118.6444818	Valve Adjustment:High Temp,Barely Open
CV-24164	9/2/2026 9:23:46 AM	32.4	67.6	0.0	0.0			0.5	0.0	127.1	126.6	-0.87	-0.87	19.3	19.2	0.877	0.871	-11.01	-11.36	28.6	1365	34.4334837	-118.6479817	
CV-24164	9/2/2026 9:26:17 AM	33.6	66.4	0.0	0.0			0.5	0.0	127.6	83.7	-0.17	-0.17	23.7	24.6	1.325	1.315	-10.86	-11.15	28.6	1348	34.4336052	-118.6481718	
CV-24164	9/17/2026 2:06:22 PM	32.1	67.9	0.0	0.0			0.5	0.0	132.0	132.4	-0.76	-0.77	17.6	17.7	0.738	0.741	-10.59	-10.81	28.63	1378	34.4334953	-118.6480047	Valve Adjustment:Barely Open
CV-24164	9/17/2026 2:07:38 PM	34.2	64.2	0.0	1.6			0.5	0.0	132.0	131.3	-0.72	-0.73	16.7	16.9	0.660	0.679	-9.89	-10.32	28.63	1375	34.4335048	-118.6480008	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24165	9/15/2026 1:44:17 PM	26.1	69.3	0.1	4.5			0.4	45.0	122.1	122.1	-7.49	-6.77	0.0	0.0	7.480	6.808	-8.32		28.5	1378	34.4335865	-118.6472948	
CV-24165	9/30/2026 1:54:12 PM	21.2	68.0	0.0	10.8			0.3	0.0	130.2	131.3	-0.50	-0.53			0.433	0.466	-0.10	-0.10	28.43	1391	34.4335258	-118.6472634	Valve Adjustment:No Flow Measurement;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [\"H2O]	Adj Stat Press [\"H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [\"H2O]	Adj Diff Press [\"H2O]	Sys Pressure [\"H2O]	Adj Avail Press [\"H2O]	Baro Press [\"Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24165	9/30/2026 2:18:26 PM	40.9	52.0	0.1	7.0			0.8	70.0	122.7	123.1	-5.74	-5.77			6.105	6.030	-7.38	-7.43	28.47	1347	34.4340783	-118.6497226	Valve Adjustment:No Flow Measurement;Well Condition:Lorentz Pump Installed
CV-24166	9/13/2026 10:25:03 AM	52.8	43.4	0.0	3.8			1.2	0.0	113.2	111.9	-5.71	-6.34			5.675	6.269	-7.74	-8.78	28.45	1399	34.4336058	-118.6468815	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24166	9/13/2026 10:25:58 AM	52.1	43.6	0.0	4.3			1.2	0.0	112.0	112.1	-6.13	-5.71			6.153	5.672	-7.84	-7.30	28.48	1398	34.4336128	-118.6468483	Well Condition:Lorentz Pump Installed
CV-24166	9/21/2026 8:17:14 AM	57.3	39.8	0.1	2.8			1.4	28.0	107.1	107.4	-5.51	-5.74			5.649	5.806	-7.90	-8.16	28.52	1404	34.4335947	-118.6468810	Valve Adjustment:Surging Liquid in Header
CV-24167	9/15/2026 9:35:57 AM	38.5	45.4	0.0	16.1			0.8	0.0	113.1	113.1	-4.54	-4.54	0.0	0.0	4.304	4.503	-9.19		28.5	1385	34.4335018	-118.6465045	
CV-24167	9/30/2026 1:45:26 PM	53.4	42.6	0.0	4.0			1.3	0.0	120.8	121.4	-0.05	-0.51			0.050	0.488	-0.94	-0.69	28.4	1400	34.4334452	-118.6464944	Valve Adjustment:No Flow Measurement;Increased Flow/Vacuum;Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-24167	9/30/2026 1:46:57 PM	52.1	43.2	0.0	4.7			1.2	0.0	122.2	122.0	-0.97	-1.25			0.962	1.164	-1.36	-1.30	28.4	1401	34.4334461	-118.6464909	Valve Adjustment:No Flow Measurement;Valve 100% Open
CV-24168	9/14/2026 2:05:52 PM	32.5	62.4	0.0	5.1			0.5	0.0	135.0	89.3	-1.78	-1.67			1.723	1.661	-6.61	-4.21	28.37	1404	34.4333278	-118.6473092	Valve Adjustment:Barely Open
CV-24168	9/21/2026 9:52:58 AM	37.2	60.1	0.0	2.7			0.6	0.0	131.2	133.4	-2.61	-1.00			2.627	0.988	-5.53	-7.50	28.52	1393	34.4333117	-118.6473277	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open
CV-24169	9/14/2026 2:01:29 PM	41.0	42.0	0.0	17.0			1.0	0.0	119.5	119.2	-2.16	-1.65			2.147	1.625	-7.54	-7.73	28.38	1378	34.4332180	-118.6477258	Valve Adjustment:Decreased Flow/Vacuum
CV-24169	9/28/2026 10:50:36 AM	33.9	42.5	0.0	23.6			0.8	0.0	119.4	119.4	-2.02	-2.02			2.018	1.994	-10.87	-11.08	28.41	1385	34.4332050	-118.6476922	Valve Adjustment:Barely Open
CV-24170	9/2/2026 9:09:47 AM	6.7	87.4	0.0	5.9			0.1	0.0	125.9	125.9	-0.15	-0.13	10.4	11.2	0.070	0.080	-7.92	-8.08	28.6	1369	34.4331175	-118.6485170	Valve Adjustment:Barely Open
CV-24170	9/17/2026 1:45:21 PM	7.5	82.5	0.1	9.9			0.1	99.0	129.8	129.8	-1.04	-1.03	11.6	11.2	0.086	0.081	-10.66	-9.52	28.64	1361	34.4331173	-118.6485125	Valve Adjustment:Barely Open
CV-24171	9/14/2026 1:31:04 PM	53.3	42.5	0.0	4.2			1.3	0.0	125.4	125.5	-1.30	-1.31	23.6	23.7	0.739	0.749	-8.86	-9.23	28.37	1397	34.4331873	-118.6466473	Valve Adjustment:Barely Open
CV-24171	9/21/2026 8:30:41 AM	53.4	45.4	0.0	1.2			1.2	0.0	123.8	124.4	-1.62	-2.00	23.4	31.1	0.724	1.277	-9.63	-9.37	28.52	1412	34.4331668	-118.6466512	Valve Adjustment:Increased Flow/Vacuum
CV-24172	9/14/2026 1:41:43 PM	50.9	41.7	0.2	7.2			1.2	36.0	127.2	127.2	-0.11	-0.10	3.0	3.1	0.026	0.027	-9.83	-9.87	28.37	1381	34.4329850	-118.6473162	Valve Adjustment:Barely Open
CV-24172	9/21/2026 9:04:18 AM	49.4	39.7	0.8	10.1			1.2	12.6	125.9	125.8	-0.15	-0.16	7.3	7.3	0.146	0.147	-11.61	-12.32	28.52	1379	34.4329933	-118.6472900	
CV-24173	9/14/2026 1:49:58 PM	9.4	84.7	0.0	5.9			0.1	0.0	136.2	136.1	-0.12	-0.12	13.6	13.9	0.448	0.465	-10.72	-10.82	28.37	1385	34.4329037	-118.6476818	Valve Adjustment:High Temp,Barely Open;Well Condition:Lorentz Pump Installed
CV-24173	9/21/2026 9:21:07 AM	8.2	90.2	0.0	1.6			0.1	0.0	134.6	134.7	-0.35	-0.35	14.1	15.2	0.473	0.555	-12.17	-11.86	28.54	1379	34.4329252	-118.6476558	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24174	9/15/2026 1:52:08 PM	32.5	56.0	0.0	11.5			0.6	0.0	111.5	111.5	-0.78	-0.77	0.0	0.0	0.709	0.712	-0.75		28.5	1365	34.4326532	-118.6480363	
CV-24174	9/24/2026 8:32:37 AM	32.4	41.9	0.0	25.7			0.8	0.0	128.2	125.5	-2.03	-1.16			2.005	1.146	-12.41	-9.39	28.55	1387	34.4327130	-118.6480365	Valve Adjustment:Decreased Flow/Vacuum
CV-24175	9/15/2026 9:24:45 AM	41.3	51.1	0.0	7.6			0.8	0.0	110.9	111.0	-1.23	-1.24	12.2	13.1	0.107	0.124	-12.28	-13.39	28.52	1368	34.4326248	-118.6485050	
CV-24175	9/30/2026 8:57:29 AM	14.8	80.4	0.0	4.8			0.2	0.0	114.4	77.5	-0.30	-0.30	6.3	10.7	0.025	0.067	-4.58	-4.53	28.52	1368	34.4326472	-118.6484672	Valve Adjustment:Audible Flow,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24176	9/1/2026 11:15:56 AM	28.1	65.0	0.0	6.9			0.4	0.0	94.8	95.6	0.22	0.20	0.0	0.0	-0.015	-0.017	0.12		28.6	1355	34.4325073	-118.6488945	NSPS/EG CAI,Positive Static Press.
CV-24176	9/1/2026 11:16:38 AM	28.0	65.9	0.0	6.1			0.4	0.0	95.9	95.9	0.06	0.14	0.0	0.0	-0.022	-0.012	0.16		28.6	1381	34.4324382	-118.6488618	NSPS/EG CAI,Positive Static Press.
CV-24176	9/3/2026 10:17:38 AM	30.3	62.8	0.0	7.0			0.5	0.0	89.4	90.3	0.20	0.21	5.3	4.7	0.017	0.013	0.25	0.31	28.59	1334	34.4326087	-118.6488848	Valve Adjustment:Positive Static Press,Valve 100% Open
CV-24176	9/30/2026 9:16:05 AM	19.0	33.6	2.5	44.9			0.6	18.0	79.0	79.0	-0.28	-0.28	1.6	1.8	0.007	0.008	0.02	0.02	28.54	1347	34.4326030	-118.6488967	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24177	9/2/2026 7:09:30 AM	9.2	76.9	0.7	13.2			0.1	18.9	100.1	100.3	-0.25	-0.25	0.0	0.0	0.076	0.075	-11.70		28.73	1355	34.4321960	-118.6495027	
CV-24177	9/22/2026 12:56:38 PM	7.7	87.8	1.0	3.5			0.1	3.5	110.4	110.4	-0.60	-0.56	0.0	0.0	-0.060	0.047	-9.38		28.54	1283	34.4327772	-118.6494463	
CV-24178	9/1/2026 2:59:57 PM	23.4	72.8	0.0	3.8			0.3	0.0	94.2	94.1	1.00	1.00	0.0	0.0	-0.034	-0.033	1.00		28.55	1322	34.4324093	-118.6486228	NSPS/EG CAI,Positive Static Press.
CV-24178	9/1/2026 3:02:27 PM	26.6	72.4	0.0	1.0			0.4	0.0	94.5	94.5	0.97	0.97	0.0	0.0	-0.049	-0.046	0.97		28.55	1319	34.4322302	-118.6489377	NSPS/EG CAI,Positive Static Press.
CV-24178	9/3/2026 10:29:19 AM	26.6	66.5	0.0	6.9			0.4	0.0	92.0	93.0	0.71	0.70	4.1	4.1	0.044	0.044	0.03	0.03	28.58	1361	34.4323703	-118.6485925	Valve Adjustment:Positive Static Press,Valve 100% Open
CV-24178	9/9/2026 2:38:51 PM	28.2	56.4	0.0	15.4			0.5	0.0	134.4	134.4	-3.03	-2.81	32.3	27.1	3.291	2.313	-6.44		28.57	1260	34.4324900	-118.6485782	NSPS/EG CAI,High Temp
CV-24178	9/9/2026 2:41:36 PM	28.3	57.0	0.0	14.7			0.5	0.0	134.4	134.5	-2.68	-2.69	32.9	28.7	3.417	2.599	-6.33		28.57	1345	34.4324700	-118.6485798	NSPS/EG CAI,High Temp
CV-24178	9/22/2026 1:58:45 PM	27.2	47.8	0.2	24.8			0.6	124.0	134.0	133.6	-3.98	-3.20	44.9	24.3	5.741	1.658	-9.26	-9.43	28.45	1374	34.4324362	-118.6485943	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24179	9/1/2026 11:22:17 AM	13.5	76.5	0.0	10.0			0.2	0.0	117.2	117.6	-0.15	-0.16	4.4	4.4	0.067	0.067	-10.35		28.63	1263	34.4321268	-118.6492020	
CV-24179	9/30/2026 11:41:43 AM	12.0	70.8	1.9	15.3			0.2	8.1	100.3	100.6	0.13	0.13	1.5	1.5	0.006	0.006	0.14	0.14	28.56	1325	34.4320955	-118.6492285	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Reduce Sys. Vac. - Flare Down;Well Comment:Well too tall to adjust
CV-24179	9/30/2026 11:42:38 AM	11.8	72.8	1.8	13.6			0.2	7.6	101.8	102.0	0.13	0.13	0.8	0.5	0.002	0.001	0.00	0.00	28.56	1340	34.4320860	-118.6492267	
CV-24180	9/1/2026 3:04:20 PM	23.8	76.2	0.0	0.0			0.3	0.0	91.6	91.6	0.47	0.45	0.0	0.0	-0.035	-0.032	0.05		28.56	1283	34.4321597	-118.6488385	NSPS/EG CAI,Positive Static Press.
CV-24180	9/1/2026 3:05:55 PM	17.2	79.9	0.0	2.9			0.2	0.0	91.8	91.8	0.46	0.45	0.0	0.0	-0.109	-0.038	0.44		28.56	1286	34.4320942	-118.6488652	NSPS/EG CAI,Positive Static Press.
CV-24180	9/18/2026 4:27:56 PM	26.9	43.3	0.0	29.8			0.6	0.0	129.4	128.5	-7.48	-5.96	22.0	14.2	1.362	0.562	-9.89	-10.55	28.58	1348	34.4321503	-118.6487858	Valve Adjustment:Decreased Flow/Vacuum

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-24180	9/22/2026 3:35:15 PM	28.6	48.8	0.0	22.6			0.6	0.0	126.2	126.2	-4.35	-3.97	23.8	12.3	1.588	0.422	-9.23	-8.90	28.44	1346	34.4321258	-118.6488007	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24181	9/1/2026 2:56:29 PM	18.4	78.9	0.0	2.7			0.2	0.0	97.8	97.7	0.26	0.30	0.0	0.0	-0.150	-0.141	0.30		28.56	1322	34.4320537	-118.6484773	NSPS/EG CAI,Positive Static Press.
CV-24181	9/1/2026 2:57:27 PM	17.1	78.3	0.0	4.6			0.2	0.0	97.4	97.4	0.25	0.26	0.0	0.0	-0.148	-0.147	0.27		28.56	1306	34.4321240	-118.6484930	NSPS/EG CAI,Positive Static Press.
CV-24181	9/9/2026 2:02:35 PM	32.6	55.6	0.0	11.8			0.6	0.0	123.6	123.6	-1.40	-1.39	7.1	7.0	6.116	5.924	-6.86		28.58	1421	34.4321305	-118.6483708	NSPS/EG CAC,
CV-24181	9/22/2026 3:27:56 PM	39.9	51.3	0.0	8.8			0.8	0.0	119.2	119.3	-1.05	-1.08			0.000	0.000	-6.57	-6.91	28.44	1342	34.4321670	-118.6483968	Valve Adjustment:Barely Open
CV-24182	9/1/2026 2:49:50 PM	42.7	42.4	0.0	14.9			1.0	0.0	101.6	101.6	-2.46	-2.42	0.0	0.0	2.294	2.290	-5.13		28.55	1398	34.4322618	-118.6481947	
CV-24182	9/22/2026 3:17:59 PM	33.4	38.7	1.2	26.7			0.9	22.3	113.5	113.7	-2.95	-2.98			2.891	2.857	-8.07	-7.98	28.43	1351	34.4322292	-118.6480608	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24183	9/1/2026 2:44:48 PM	45.4	40.5	0.0	14.1			1.1	0.0	98.2	98.2	-0.07	-0.11	0.0	0.0	0.339	0.345	-5.28		28.56	1306	34.4322535	-118.6477808	
CV-24183	9/22/2026 2:15:06 PM	31.4	25.5	0.4	42.7			1.2	106.8	96.2	95.0	-0.09	-0.05			0.065	0.092	-9.23	-9.28	28.45	1354	34.4323915	-118.6476695	Valve Adjustment:Barely Open
CV-24184	9/1/2026 2:29:37 PM	50.0	41.1	0.0	8.9			1.2	0.0	131.1	131.3	-0.10	-0.10	1.9	2.7	0.072	0.147	-5.65		28.56	1322	34.4325837	-118.6472167	NSPS/EG CAI,High Temp
CV-24184	9/1/2026 2:34:21 PM	51.8	42.2	0.0	6.0			1.2	0.0	136.3	136.5	-0.01	-0.01	8.2	8.2	1.382	1.380	-5.58		28.56	1358	34.4321850	-118.6474008	NSPS/EG CAI,High Temp
CV-24184	9/3/2026 12:22:14 PM	47.8	44.0	1.0	7.3			1.1	7.6	137.6	138.3	-0.14	-0.24	7.6	9.6	1.272	2.041	-8.41	-8.37	28.57	1348	34.4325148	-118.6472710	Valve Adjustment:High Temp,Increased Flow/Vacuum
CV-24184	9/3/2026 12:23:03 PM	47.4	43.8	1.1	7.7			1.1	7.1	138.4	138.3	-0.24	-0.23	9.2	9.3	1.855	1.902	-7.87	-8.10	28.57	1350	34.4325265	-118.6472592	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24184	9/22/2026 2:21:19 PM	30.8	28.5	4.9	35.8			1.1	7.3	129.7	130.0	-0.15	-0.13	5.7	6.0	0.712	0.776	-9.05	-9.52	28.45	1368	34.4325403	-118.6472523	Valve Adjustment:Barely Open
CV-24185	9/1/2026 2:19:32 PM	51.2	45.6	0.0	3.2			1.1	0.0	125.9	127.5	0.17	-0.03	16.7	20.4	0.747	1.118	-5.37		28.56	1299	34.4327203	-118.6470285	NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-24185	9/1/2026 2:20:58 PM	48.4	51.6	0.0	0.0			0.9	0.0	127.6	127.6	-0.16	-0.15	19.5	19.6	1.069	1.075	-5.37		28.56	1306	34.4326737	-118.6470057	NSPS/EG CAC,
CV-24185	9/3/2026 12:38:20 PM	49.0	48.5	0.0	2.5			1.0	0.0	125.4	125.3	-0.56	-0.59	24.2	24.6	1.613	1.667	-7.52	-7.72	28.57	1355	34.4326762	-118.6469485	Valve Adjustment:Increased Flow/Vacuum
CV-24185	9/22/2026 2:34:09 PM	30.2	27.8	7.9	34.1			1.1	4.3	124.2	124.1	-0.79	-0.78	26.3	26.3	1.917	1.912	-9.88	-9.50	28.42	1366	34.4326730	-118.6469535	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open
CV-24185	9/22/2026 2:35:54 PM	48.4	42.6	0.1	8.9			1.1	89.0	124.1	124.1	-0.79	-0.81	26.2	26.4	1.890	1.918	0.00	-0.01	28.45	1362	34.4326875	-118.6469315	Valve Adjustment:NSPS/EG CAC,Barely Open,Surging Liquid in Header
CV-24186	9/15/2026 10:32:27 AM	45.1	34.9	1.7	18.3			1.3	10.8	125.0	124.9	-1.34	-1.35	17.1	16.9	0.804	0.783	-8.43	-8.80	28.63	1374	34.4328470	-118.6465443	Valve Adjustment:Audible Flow
CV-24186	9/22/2026 2:42:35 PM	49.9	39.4	0.5	10.2			1.3	20.4	125.5	126.2	-0.70	-0.69	37.8	38.2	0.927	0.943	-9.08	-9.29	28.41	1366	34.4328407	-118.6465432	Valve Adjustment:Barely Open
CV-24187	9/22/2026 9:24:10 AM	50.2	45.5	0.0	4.3			1.1	0.0	124.3	124.4	-0.61	-0.55	8.1	8.2	0.174	0.181	-13.51		28.66	1260	34.4318558	-118.6495158	
CV-24187	9/22/2026 12:48:46 PM	45.0	53.1	0.0	1.9			0.8	0.0	126.5	126.6	-0.07	-0.07	0.0	0.0	-3.112	-3.024	-8.43		28.55	1266	34.4319670	-118.6495042	
CV-24187	9/22/2026 2:45:38 PM	50.2	40.7	0.1	9.0			1.2	90.0	107.3	107.5	-1.05	-1.04	19.7	20.0	1.039	1.070	-9.42	-9.14	28.42	1348	34.4324220	-118.6469768	Valve Adjustment:Barely Open
CV-24188	9/2/2026 8:53:02 AM	49.3	45.6	0.0	5.1			1.1	0.0	117.4	117.5	-2.57	-2.55	11.0	11.0	0.323	0.329	-13.15		28.7	1230	34.4315455	-118.6501003	
CV-24188	9/22/2026 10:14:23 AM	51.4	44.0	0.0	4.6			1.2	0.0	117.1	117.9	-0.50	-0.97	6.6	10.1	0.116	0.275	-11.84	-11.74	28.67	1273	34.4315062	-118.6501235	Valve Adjustment:Increased Flow/Vacuum
CV-24189	9/2/2026 8:58:47 AM	43.5	34.4	3.5	18.6			1.3	5.3	108.9	108.2	-0.46	-0.31	5.0	0.7	0.499	0.009	-13.60		28.7	1263	34.4313372	-118.6500550	
CV-24189	9/22/2026 10:07:55 AM	54.3	41.7	0.0	4.0			1.3	0.0	100.0	104.3	0.22	-0.11	0.5	3.4	0.004	0.233	-12.64	-12.60	28.69	1275	34.4313030	-118.6500181	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-24189	9/22/2026 10:08:53 AM	53.0	41.3	0.3	5.4			1.3	18.0	105.0	105.6	-0.18	-0.17	3.3	3.2	0.222	0.215	-12.57	-11.98	28.66	1274	34.4313025	-118.6500153	Valve Adjustment:NSPS/EG CAC
CV-24190	9/2/2026 9:15:42 AM	52.9	42.9	0.0	4.2			1.2	0.0	123.1	123.6	-4.35	-4.31	38.8	45.5	0.902	1.242	-12.92		28.65	1312	34.4315488	-118.6494625	
CV-24190	9/22/2026 12:45:58 PM	46.2	53.3	0.5	0.0			0.9	0.0	122.3	119.9	-1.80	-1.26	0.0	0.0	-4.481	-3.938	-8.99		28.57	1371	34.4315985	-118.6495228	
CV-24192	9/2/2026 9:12:33 AM	54.5	41.4	0.0	4.1			1.3	0.0	119.7	119.8	-11.72	-11.70	21.6	21.5	0.560	0.557	-12.50		28.66	1299	34.4313500	-118.6495168	
CV-24192	9/4/2026 1:39:12 PM	52.3	41.0	0.0	6.7			1.3	0.0	121.5	121.4	-7.94	-8.06	17.4	17.0	0.401	0.383	-8.64	-8.63	28.61	1303	34.4313397	-118.6494930	
CV-24192	9/22/2026 12:39:10 PM	54.4	44.1	1.5	0.0			1.2	0.0	118.9	119.7	-8.34	-8.35	0.0	0.0	-10.037	-10.037	-9.12		28.58	1276	34.4313383	-118.6495360	
CV-24193	9/1/2026 11:28:13 AM	44.2	42.8	0.0	13.0			1.0	0.0	117.6	117.7	-8.16	-8.17	15.8	15.8	0.310	0.311	-9.80		28.62	1306	34.4314840	-118.6492110	
CV-24193	9/21/2026 11:49:20 AM	50.8	42.7	0.0	6.5			1.2	0.0	119.3	119.3	-9.03	-9.03	14.6	15.4	0.367	0.411	-11.09	-11.30	28.67	1312	34.4315017	-118.6490660	Valve Adjustment:Audible Flow
CV-24194	9/1/2026 1:49:41 PM	53.0	38.0	0.3	8.7			1.4	29.0	106.3	106.3	-4.31	-4.31	3.6	3.6	1.313	1.322	-9.42		28.6	1296	34.4318220	-118.6484657	
CV-24194	9/3/2026 10:43:30 AM	49.6	47.6	0.0	2.9			1.0	0.0	107.5	107.6	-4.77	-4.94	3.6	3.9	1.378	1.627	-9.87	-9.98	28.58	1345	34.4318613	-118.6485208	Valve Adjustment:Increased Flow/Vacuum
CV-24194	9/21/2026 12:40:02 PM	50.4	44.9	0.0	4.7			1.1	0.0	106.0	106.1	-1.45	-2.03	5.4	3.3	3.076	1.145	-10.48	-10.35	28.63	1338	34.4318595	-118.6485112	Valve Adjustment:Unice Plate Changed (See OP Log),Audible Flow,Increased Flow/Vacuum,Well Comment:Changed OP from 0.50 to 0.75
CV-24194	9/21/2026 12:42:15 PM	51.6	44.6	0.0	3.8			1.2	0.0	106.6	106.5	-2.20	-2.22	7.0	7.4	1.031	1.154	-9.73	-10.75	28.63	1345	34.4318652	-118.6485092	
CV-24195	9/1/2026 1:57:58 PM	51.7	44.9	0.0	3.4			1.2	0.0	118.6	118.7	-0.25	-0.24	7.1	7.1	1.018	1.018	-9.56		28.58	1273	34.4317900	-118.6479335	
CV-24195	9/3/2026 11:04:13 AM	41.2	42.6	0.1	16.1			1.0	179.3	118.1	118.1	-0.53	-0.54	12.4	12.9	0.982	1.057	-8.69	-8.73	28.6	1342	34.4319197	-118.6476668	Valve Adjustment:Increased Flow/Vacuum
CV-24195	9/21/2026 12:26:17 PM	49.5	46.2	0.0	4.3			1.1	0.0	119.7	119.8	-0.58	-0.58	7.1	7.7	1.078	1.260	-10.64	-11.89	28.66	1345	34.4318237	-118.6478848	Valve Adjustment:Audible Flow
CV-24195	9/22/2026 3:15:01 PM	51.2	44.8	0.0	4.0			1.1	0.0	117.6	118.1	-0.31	-0.32	6.3	5.9	0.840	0.751	-8.59	-8.28	28.45	1343	34.4318195	-118.6478692	Valve Adjustment:Barely Open
CV-24196	9/1/2026 2:06:39 PM	46.4	48.4	0.2	5.0			1.0	25.0	123.6	123.6	-0.73	-0.69	11.6	11.6	0.171	0.171	-8.94		28.58	1316	34.4320417	-118.6471583	
CV-24196	9/22/2026 3:03:17 PM	46.2	52.6	0.0	1.2			0.9	0.0	123.9	123.7	-0.14	-0.21			0.000	0.000	-9.27	-9.50	28.45	1344	34.4320508	-118.6471755	Valve Adjustment:Barely Open
CV-24197	9/1/2026 2:10:01 PM	44.9	42.7	0.0	12.4			1.1	0.0	124.4	124.4	-0.46	-0.46	14.2	14.2	0.542	0.543	-5.69		28.58	1217	34.4324498	-118.6466075	

All LFG Extraction Wells - Setemember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading	H2 Reading	CH4: CO2	BalO2	Init Temp	Adj Temp	Init Stat Press	Adj Stat Press	Init Flow	Adj Flow	Init Diff Press	Adj Diff Press	Sys Pressure	Adj Avail Press	Baro Press	Elev	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]	[ppmv]	[ppmv]		[%]	[°F]	[°F]	["H2O]	["H2O]	[scfm]	[scfm]	["H2O]	["H2O]	["H2O]	["H2O]	["Hg]	[ft]			
CV-24197	9/22/2026 2:56:45 PM	47.1	45.3	0.0	7.6			1.0	0.0	128.4	126.6	-0.82	-0.84	17.8	18.5	0.876	0.946	-9.52	-9.50	28.45	1334	34.4323683	-118.6465750	Valve Adjustment:Barely Open
CV-24198	9/15/2026 12:38:31 PM	35.4	36.4	0.0	28.2			1.0	0.0	128.2	128.0	-3.30	-1.92	29.4	8.9	5.692	0.514	-21.08	-19.95	28.58	1326	34.4315760	-118.6475880	Valve Adjustment:Decreased Flow/Vacuum
CV-24198	9/15/2026 12:40:21 PM	34.8	36.6	0.0	28.6			1.0	0.0	127.9	127.7	-1.29	-1.28	8.9	9.4	0.514	0.570	-19.61	-19.67	28.57	1330	34.4315603	-118.6475888	Valve Adjustment:Surging Liquid in Header, Surging Liquid in Well (Watered In)
CV-24198	9/30/2026 1:17:46 PM	47.5	41.0	0.0	11.5			1.2	0.0	125.8	126.1	-0.08	-0.14	5.5	6.3	0.654	0.850	-7.23	-10.10	28.41	1346	34.4316255	-118.6476403	Valve Adjustment:Surging Liquid in Header, Surging Liquid in Well (Watered In)
CV-24199	9/15/2026 12:27:13 PM	46.5	39.6	0.0	13.9			1.2	0.0	128.5	128.4	-0.63	-0.61	15.0	15.7	0.296	0.325	-19.71	-19.20	28.58	1338	34.4318142	-118.6473160	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-24199	9/15/2026 12:29:31 PM	46.4	40.6	0.0	13.0			1.1	0.0	128.4	128.4	-0.47	-0.48	14.8	15.4	1.411	1.536	-18.71	-19.55	28.57	1341	34.4318080	-118.6473063	Valve Adjustment:Surging Liquid in Header, Surging Liquid in Well (Watered In)
CV-24199	9/30/2026 1:27:46 PM	51.6	44.8	0.0	3.6			1.2	0.0	127.9	128.8	-0.17	-0.12	50.5	48.8	3.401	3.178	0.04	0.04	28.41	1348	34.4318227	-118.6473313	Valve Adjustment:Decreased Flow/Vacuum
CV-24200	9/15/2026 9:58:46 AM	45.0	39.2	0.0	15.8			1.1	0.0	120.9	120.9	-2.67	-1.92	26.2	17.7	4.446	2.004	-21.82	-21.01	28.64	1292	34.4314395	-118.6472363	Valve Adjustment:Decreased Flow/Vacuum
CV-24200	9/15/2026 9:59:38 AM	45.1	38.6	0.0	16.3			1.2	0.0	120.9	120.9	-1.90	-1.90	18.2	17.8	2.118	2.040	-21.85	-21.77	28.64	1294	34.4314277	-118.6472468	Valve Adjustment:Decreased Flow/Vacuum
CV-24200	9/30/2026 1:33:17 PM	51.3	40.6	0.0	8.1			1.3	0.0	121.7	121.8	-0.03	-0.01	19.8	19.8	0.917	0.919	-8.27	-8.20	28.44	1302	34.4314577	-118.6472310	Valve Adjustment:Barely Open
CV-24201	9/15/2026 10:10:20 AM	48.3	46.4	0.1	5.2			1.0	52.0	109.5	124.0	0.97	-0.07	3.8	9.6	0.037	0.252	-22.09	-21.19	28.64	1266	34.4317253	-118.6466435	Valve Adjustment:NSPS/EG CAI, NSPS/EG CAC, Positive Static Press., Increased Flow/Vacuum; Well Condition: Pnumatic Pump Installed
CV-24201	9/15/2026 10:11:55 AM	49.0	46.3	0.0	4.7			1.1	0.0	125.4	125.4	-0.17	-0.13	9.4	9.0	0.242	0.222	-22.85	-23.30	28.64	1280	34.4317500	-118.6466223	Valve Adjustment:Decreased Flow/Vacuum, Barely Open
CV-24201	9/15/2026 10:14:30 AM	48.6	46.7	0.0	4.7			1.0	0.0	126.6	125.0	-0.03	-0.07	2.8	3.3	0.022	0.029	-24.24	-24.17	28.64	1280	34.4317480	-118.6466220	Well Condition: Pnumatic Pump Installed
CV-24201	9/24/2026 1:50:00 PM					24.3																		AtmAA (24 TAT Request)
CV-24201	9/24/2026 1:50:00 PM																							AtmAA (24 TAT Request) <0.10; [User entered 0.10%]
CV-24201	9/24/2026 1:50:04 PM						23000																	[User entered 2.3%]
CV-24201	9/24/2026 1:50:55 PM	48.7	47.3	0.0	4.0			1.0	0.0	119.2	119.0	1.11	1.11	2.2	2.0	0.013	0.011	-14.15	-14.43	28.63	1275	34.4317503	-118.6466507	Valve Adjustment:Reduce Sys. Vac. - Flare Down; Well Condition: Pnumatic Pump Installed
CV-24201	9/24/2026 2:48:38 PM					20																		
CV-24201	9/28/2026 8:40:33 AM	47.4	47.2	0.0	5.5			1.0	0.0	93.1	124.2	1.49	-0.19	2.4	14.2	0.015	0.551	-12.01	-12.63	28.53	1275	34.4317528	-118.6466283	Valve Adjustment:NSPS/EG CAI, NSPS/EG CAC, Positive Static Press., Increased Flow/Vacuum
CV-24201	9/28/2026 8:44:14 AM	47.9	47.5	0.0	4.6			1.0	0.0	127.9	128.6	-0.44	-0.44	14.5	14.4	0.578	0.573	-13.46	-14.11	28.52	1274	34.4317513	-118.6466318	Valve Adjustment:Decreased Flow/Vacuum
CV-24202	9/15/2026 4:15:49 PM	26.8	32.7	0.0	40.5			0.8	0.0	125.4	121.0	-13.62	-2.86			13.592	2.879	-19.41	-19.87	28.54	1266	34.4319677	-118.6462730	Valve Adjustment:Decreased Flow/Vacuum
CV-24202	9/15/2026 4:17:09 PM	26.1	32.5	0.0	41.4			0.8	0.0	119.7	119.9	-2.50	-2.48			2.522	2.486	-20.96	-20.81	28.56	1270	34.4319193	-118.6462603	Valve Adjustment:Increased Flow/Vacuum
CV-24202	9/23/2026 10:59:35 AM	35.4	39.2	0.0	25.4			0.9	0.0	127.1	127.2	-0.96	-1.00			0.957	0.988	-14.98	-16.96	28.62	1279	34.4319198	-118.6462808	Valve Adjustment:Increased Flow/Vacuum
CV-24202	9/24/2026 1:32:57 PM						16000																	[User entered 1.6%]
CV-24202	9/24/2026 1:35:00 PM						11.8																	AtmAA (24 TAT Request)
CV-24202	9/24/2026 1:35:00 PM																							AtmAA (24 TAT Request) <0.10; [User entered 0.10%]
CV-24202	9/24/2026 1:35:03 PM	36.3	38.6	0.0	25.0			0.9	0.0	118.2	118.4	-1.15	-1.15			1.143	1.099	-6.71	-6.71	28.6	1291	34.4319222	-118.6462708	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24202	9/24/2026 3:14:01 PM					10																		
CV-24203	9/15/2026 9:25:44 AM	53.3	42.4	0.0	4.3			1.3	0.0	122.8	123.0	-0.47	-0.57	6.1	9.1	0.239	0.534	-10.23	-10.15	28.68	1238	34.4315260	-118.6460085	Valve Adjustment:Increased Flow/Vacuum; Well Condition: Lorentz Pump Installed
CV-24203	9/15/2026 9:28:02 AM	53.1	42.4	0.0	4.5			1.3	0.0	123.3	123.8	-1.21	-1.23	10.4	10.7	0.693	0.731	-20.16	-20.22	28.69	1244	34.4315300	-118.6460148	Valve Adjustment:Surging Liquid in Header; Well Condition: Lorentz Pump Installed
CV-24203	9/24/2026 12:50:00 PM					11.9																		AtmAA (24 TAT Request)
CV-24203	9/24/2026 12:50:00 PM						1400																	AtmAA (24 TAT Request); [User entered 0.14%]
CV-24203	9/24/2026 12:53:25 PM						39000																	[User entered 3.9%]
CV-24203	9/24/2026 12:54:25 PM	51.8	43.9	0.0	4.3			1.2	0.0	124.1	124.2	-0.33	-0.35	7.6	7.9	0.370	0.403	-8.06	-8.02	28.66	1234	34.4315647	-118.6459937	Valve Adjustment:Reduce Sys. Vac. - Flare Down; Well Condition: Lorentz Pump Installed
CV-24203	9/24/2026 2:54:50 PM					25																		
CV-24204	9/15/2026 9:12:51 AM	51.7	44.0	0.0	4.3			1.2	0.0	126.9	126.9	-3.43	-3.32	19.2	18.1	0.871	0.773	-14.43	-10.23	28.67	1245	34.4314145	-118.6462598	Well Condition: Lorentz Pump Installed
CV-24204	9/15/2026 9:15:00 AM	50.7	44.6	0.0	4.7			1.1	0.0	127.0	127.2	-3.92	-4.02	21.3	20.7	0.600	0.569	-14.47	-13.58	28.68	1240	34.4314125	-118.6462587	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-24204	9/15/2026 9:15:53 AM	50.2	45.7	0.0	4.1			1.1	0.0	127.2	127.2	-3.96	-3.86	22.2	19.9	0.653	0.526	-13.05	-11.74	28.67	1239	34.4314237	-118.6462580	Well Condition: Lorentz Pump Installed
CV-24204	9/25/2026 9:17:43 AM	49.5	45.4	0.0	5.1			1.1	0.0	127.3	127.3	-5.51	-5.48	15.2	14.8	0.550	0.523	-15.93	-15.44	28.68	1227	34.4314310	-118.6462535	Valve Adjustment:Increased Flow/Vacuum; Well Condition: Lorentz Pump Installed
CV-24205	9/15/2026 9:07:09 AM	54.0	41.1	0.0	4.9			1.3	0.0	124.0	124.1	-2.75	-2.85	21.6	24.4	0.616	0.783	-10.28	-12.16	28.68	1234	34.4312307	-118.6464740	Valve Adjustment:Increased Flow/Vacuum; Well Condition: Lorentz Pump Installed

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [""H2O]	Adj Stat Press [""H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [""H2O]	Adj Diff Press [""H2O]	Sys Pressure [""H2O]	Adj Avail Press [""H2O]	Baro Press [""Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
CV-24205	9/15/2026 9:08:01 AM	52.9	41.7	0.0	5.4			1.3	0.0	124.2	124.1	-2.96	-2.98	24.6	25.5	0.795	0.859	-12.04	-13.33	28.68	1233	34.4312232	-118.6464747	
CV-24205	9/30/2026 4:14:08 PM	50.3	44.5	0.0	5.2			1.1	0.0	125.0	125.0	-3.72	-3.62	29.9	28.6	1.187	1.085	-15.30	-14.86	28.56	1223	34.4312302	-118.6464650	
CV-24206	9/15/2026 9:41:41 AM	36.4	41.1	3.9	18.6			0.9	4.8	82.1	81.9	0.10	-0.05			0.000	0.052	-13.90	-14.07	28.64	1293	34.4315140	-118.6467670	Valve Adjustment: NSPS/EG CAI, NSPS/EG CAC, Positive Static Press., Increased Flow/Vacuum; Well Condition: Pneumatic Pump Installed
CV-24206	9/15/2026 9:45:15 AM	44.2	48.1	0.2	7.5			0.9	37.5	82.3	82.3	-1.14	-1.14			1.167	1.158	-13.72	-13.13	28.64	1279	34.4315107	-118.6467832	Well Condition: Pneumatic Pump Installed
CV-24206	9/23/2026 10:43:02 AM	46.1	46.6	0.9	6.4			1.0	7.1	106.7	107.9	0.19	-0.60			0.000	0.587	-6.91	-5.77	28.61	1284	34.4315375	-118.6467783	Valve Adjustment: NSPS/EG CAI, Positive Static Press., Increased Flow/Vacuum, Barely Open
CV-24206	9/23/2026 10:44:23 AM	49.0	50.1	0.0	0.9			1.0	0.0	108.9	109.1	-0.74	-0.74			0.734	0.734	-5.72	-5.84	28.62	1287	34.4315385	-118.6467843	Valve Adjustment: NSPS/EG CAC, Barely Open
CV-24206	9/24/2026 12:30:00 PM					11.1																		AtmAA [24 TAT Request]
CV-24206	9/24/2026 12:30:00 PM						3700																	AtmAX [24 TAT Request]; [User entered 0.37%]
CV-24206	9/24/2026 12:33:26 PM						35000																	[User entered 3.5%]
CV-24206	9/24/2026 12:37:06 PM	46.1	41.2	0.0	12.7			1.1	0.0	92.7	93.5	-0.88	-0.84			0.019	0.019	-5.71	-5.47	28.64	1270	34.4315065	-118.6467857	Valve Adjustment: Reduce Sys. Vac. - Flare Down; Well Condition: Pneumatic Pump Installed
CV-24206	9/24/2026 12:39:33 PM	46.4	39.9	0.0	13.6			1.2	0.0	101.6	101.8	-1.06	-1.05			1.033	1.045	-7.90	-8.02	28.61	1271	34.4315013	-118.6467637	Valve Adjustment: Reduce Sys. Vac. - Flare Down; Well Condition: Pneumatic Pump Installed
CV-24206	9/24/2026 3:07:10 PM					40																		
CV-24207	9/3/2026 12:47:00 PM	40.1	56.1	0.0	3.8			0.7	0.0	127.3	136.1	9.06	-0.43	3.8	33.9	0.019	1.546	-6.71	-6.49	28.52	1390	34.4332975	-118.6469485	Valve Adjustment: NSPS/EG CAI, High Temp, Positive Static Press., Increased Flow/Vacuum
CV-24207	9/3/2026 12:48:27 PM	39.0	57.9	0.0	3.1			0.7	0.0	136.4	136.5	-0.69	-0.62	30.1	29.1	1.215	1.141	-7.52	-7.22	28.53	1387	34.4332798	-118.6469378	Valve Adjustment: NSPS/EG CAI, High Temp
CV-24207	9/13/2026 1:29:48 PM	47.7	47.2	0.0	5.0			1.0	0.0	135.8	135.7	-5.71	-4.89	25.7	19.3	0.905	0.509	-9.65	-9.24	28.44	1375	34.4332857	-118.6469355	Valve Adjustment: NSPS/EG CAI, High Temp, Decreased Flow/Vacuum; Well Comment: pump is active; Well Condition: Lorentz Pump Installed
CV-24207	9/13/2026 1:32:35 PM	48.0	47.2	0.0	4.8			1.0	0.0	135.5	135.3	-3.81	-2.69	20.8	15.9	2.884	1.680	-9.59	-9.32	28.45	1386	34.4332708	-118.6469427	Valve Adjustment: NSPS/EG CAI, Orifice Plate Changed (See OP Log), High Temp, Decreased Flow/Vacuum; Well Condition: Lorentz Pump Installed
CV-24207	9/13/2026 1:35:07 PM	48.1	46.8	0.0	5.1			1.0	0.0	135.2	134.6	-2.07	-2.13	16.8	17.0	1.858	1.911	-8.58	-8.79	28.45	1392	34.4332733	-118.6469483	Valve Adjustment: High Temp, Increased Flow/Vacuum
CV-24207	9/13/2026 1:35:54 PM	47.9	47.2	0.0	4.9			1.0	0.0	133.9	133.8	-2.03	-2.14	16.4	18.1	1.779	2.157	-8.32	-9.65	28.45	1396	34.4332788	-118.6469503	Valve Adjustment: High Temp
CV-24207	9/21/2026 8:26:11 AM	46.1	53.5	0.0	0.4			0.9	0.0	126.8	130.2	-1.22	-0.77	41.6	35.0	2.300	1.635	-9.10	-8.67	28.52	1393	34.4332750	-118.6469535	Valve Adjustment: Decreased Flow/Vacuum, Barely Open
CV-24208	9/24/2026 10:14:51 AM	41.7	57.4	0.0	0.9			0.7	0.0	131.8	131.8	-0.51	-0.48	13.1	13.4	1.118	1.169	-11.52	-10.81	28.62	1255	34.4318913	-118.6451020	Valve Adjustment: Barely Open, Surging Liquid in Header, Surging Liquid in Well (Watered In)
CV-24208	9/24/2026 10:16:08 AM	41.4	57.6	0.0	1.0			0.7	0.0	128.4	128.6	-0.52	-0.42	22.9	23.2	1.210	1.248	-11.73	-12.14	28.63	1256	34.4319008	-118.6450930	Valve Adjustment: NSPS/EG CAC, Decreased Flow/Vacuum, Surging Liquid in Header, Surging Liquid in Well (Watered In)
CV-24209	9/30/2026 2:11:34 PM	10.0	73.8	0.0	16.2			0.1	0.0	131.6	131.9	-0.02	-0.04			0.064	0.066	-11.17	-11.13	28.56	1294	34.4321832	-118.6456147	Valve Adjustment: NSPS/EG CAI, High Temp, Reduce Sys. Vac. - Flare Down
CV-24210	9/9/2026 1:42:55 PM	29.9	35.8	0.0	34.3			0.8	0.0	123.7	124.2	-5.12	-4.71	0.0	0.0	5.402	4.651	-5.44		28.61	1312	34.4326083	-118.6456548	
CV-24211	9/28/2026 2:53:00 PM	15.8	76.6	0.3	7.3			0.2	24.3	114.4	99.5	-19.56	-13.50			19.712	13.520	-19.84	-20.12	28.45	1253	34.4327265	-118.6438603	Valve Adjustment: Decreased Flow/Vacuum
CV-24212	9/28/2026 2:46:21 PM	9.3	70.2	0.8	19.7			0.1	24.6	118.1	110.9	-8.73	-5.06			8.849	5.092	-18.73	-19.44	28.45	1252	34.4331540	-118.6430773	Valve Adjustment: Decreased Flow/Vacuum
CV-24213	9/4/2026 9:21:22 AM	43.1	47.2	0.0	9.8			0.9	0.0	111.4	112.8	-0.03	-0.15			0.029	0.144	-12.00	-11.23	28.6	1322	34.4366015	-118.6429617	Valve Adjustment: Increased Flow/Vacuum
CV-24214	9/30/2026 1:49:40 PM	13.7	58.1	0.0	28.2			0.2	0.0	115.4	115.6	0.52	0.51			0.000	0.000	-5.50	-5.53	28.44	1321	34.4367497	-118.6435122	
CV-24215	9/30/2026 1:28:04 PM	44.4	50.1	0.0	5.5			0.9	0.0	119.7	119.7	-2.08	-2.22	14.0	16.3	0.126	0.169	-11.20	-11.37	28.47	1307	34.4369473	-118.6448165	
CV-24216	9/16/2026 11:46:26 AM	39.1	40.2	0.0	20.7			1.0	0.0	124.0	121.6	-7.38	-5.52			7.421	5.466	-18.92	-19.47	28.74	1306	34.4368255	-118.6422970	Valve Adjustment: Decreased Flow/Vacuum
CV-24217	9/3/2026 1:30:59 PM	41.0	58.2	0.0	0.8			0.7	0.0	109.0	109.0	-0.12	-0.13			0.049	0.034	-16.64	-16.61	28.46	1380	34.4359225	-118.6443843	Valve Adjustment: Barely Open
CV-24218	9/14/2026 1:37:55 PM	44.4	50.1	0.0	5.5			0.9	0.0	124.9	124.7	-0.12	-0.11	0.0	0.0	0.161	0.066			28.41	1266	34.4357750	-118.6459403	
CV-24219	9/1/2026 9:17:40 AM	13.9	82.1	0.0	4.0			0.2	0.0	183.9	183.8	-13.03	-13.08			13.459	13.451	-14.59	-14.71	28.57	1395	34.4350964	-118.6462255	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed
CV-24219	9/1/2026 9:23:00 AM					3280																		AtmAA
CV-24219	9/1/2026 9:23:00 AM						110300																	AtmAA; [User entered 11.03%]

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading	H2 Reading	CH4: CO2	BalO2	Init Temp	Adj Temp	Init Stat Press	Adj Stat Press	Init Flow	Adj Flow	Init Diff Press	Adj Diff Press	Sys Pressure	Adj Avail Press	Baro Press	Elev	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]	[ppmv]	[ppmv]		[%]	[°F]	[°F]	[\"H2O]	[\"H2O]	[scfm]	[scfm]	[\"H2O]	[\"H2O]	[\"H2O]	[\"H2O]	[\"Hg]	[ft]			
CV-24219	9/9/2026 10:37:30 AM	17.7	74.4	0.0	7.9			0.2	0.0	185.1	185.2	-12.33	-2.52			12.615	2.514	-12.89	-14.74	28.65	1398	34.4350904	-118.6462286	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24219	9/9/2026 10:37:57 AM	24.9	75.1	0.0	0.0			0.3	0.0	185.3	185.2	-2.89	-2.21			2.904	2.221	-14.68	-15.50	28.64	1399	34.4350896	-118.6462289	
CV-24219	9/9/2026 10:42:00 AM					2315																		AtmAA
CV-24219	9/15/2026 1:45:00 PM					3440																		AtmAA
CV-24219	9/15/2026 1:50:49 PM	12.3	76.9	0.0	10.8			0.2	0.0	189.6	189.5	5.71	-1.34			0.000	1.378	-3.32	-2.80	28.5	1393	34.4350933	-118.6462376	Valve Adjustment:NSPS/EG CAI,Decom Well (Temporary),No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24219	9/15/2026 1:52:47 PM	15.5	80.2	0.0	4.3			0.2	0.0	189.5	189.5	-1.37	-1.63			1.396	1.672	-2.82	-2.82	28.5	1395	34.4350976	-118.6462375	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24219	9/22/2026 2:24:19 PM	16.2	83.1	0.0	0.7			0.2	0.0	187.8	187.7	-7.73	-7.53			8.093	7.843	-8.93	-8.80	28.46	1379	34.4350910	-118.6462265	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24219	9/22/2026 2:26:00 PM					1340																		AtmAA
CV-24219	9/29/2026 1:44:55 PM	22.6	77.1	0.2	0.1			0.3	0.5	185.6	186.1	-4.86	-4.56			4.789	4.525	-9.23	-9.05	28.3	1393	34.4350993	-118.6462309	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24219	9/29/2026 1:45:41 PM	22.4	76.6	0.0	1.0			0.3	0.0	187.0	187.5	-4.85	-4.71			4.790	4.743	-9.32	-8.29	28.31	1388	34.4350982	-118.6462408	Well Condition:Lorentz Pump Installed
CV-24219	9/29/2026 1:50:00 PM					2530																		AtmAA
CV-24220	9/1/2026 9:58:34 AM	21.7	50.7	1.2	26.4			0.4	22.0	147.3	147.7	-14.47	-14.14			14.802	14.609	-14.83	-14.51	28.6	1339	34.4339702	-118.6439713	Valve Adjustment:Barely Open,Surging Liquid in Header,Plugged/Pinched Suspected
CV-24220	9/8/2026 9:02:20 AM	18.5	43.8	2.2	35.5			0.4	16.1	140.2	130.5	-14.17	-2.47			14.605	2.443	-15.10	-15.92	28.6	1379	34.4339354	-118.6439285	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24220	9/8/2026 9:07:51 AM	13.9	58.9	0.8	26.4			0.2	33.0	129.9	129.5	-2.32	-2.32			2.301	2.296	-16.05	-16.15	28.61				Valve Adjustment:No Flow Measurement;Well Condition:Lorentz Pump Installed
CV-24221	9/28/2026 2:25:52 PM	30.3	35.9	0.1	33.7			0.8	337.0	129.3	125.8	-15.36	-12.48	22.2	38.9	1.428	4.334	-16.57	-17.31	28.42	1250	34.4341298	-118.6421518	Valve Adjustment:Decreased Flow/Vacuum
CV-24222	9/30/2026 8:21:47 AM	50.0	40.5	0.0	9.5			1.2	0.0	121.8	121.8	-18.74	-18.80	29.7	28.3	2.536	2.306	-21.24	-20.99	28.53	1257	34.4336020	-118.6420043	Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24223	9/28/2026 2:38:35 PM	35.3	54.7	0.2	9.8			0.6	49.0	125.0	125.0	-1.08	-1.05			1.042	1.034	-18.97	-19.10	28.43	1244	34.4334207	-118.6425758	Valve Adjustment:Barely Open
CV-24224	9/30/2026 9:30:13 AM	47.9	47.9	0.0	4.2			1.0	0.0	80.5	81.0	0.26	-0.47			0.000	0.461	-23.43	-22.82	28.52	1321	34.4331493	-118.6448345	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24224	9/30/2026 9:30:54 AM	48.8	47.6	0.0	3.6			1.0	0.0	81.5	81.5	-0.56	-0.56			0.549	0.553	-22.93	-23.49	28.49	1325	34.4331415	-118.6448350	Valve Adjustment:Barely Open,Reduce Sys. Vac. - Flare Down
CV-24224	9/30/2026 2:00:06 PM	52.2	42.9	0.0	4.9			1.2	0.0	111.3	111.4	-0.10	-0.10			0.081	0.080	-19.04	-17.91	28.41	1331	34.4331565	-118.6448268	Valve Adjustment:Barely Open
CV-24225	9/1/2026 9:07:25 AM	48.4	49.1	0.5	2.0			1.0	4.0	120.5	120.6	-0.21	-0.21			0.194	0.196	-17.14	-17.25	28.65	1295	34.4327197	-118.6444303	Valve Adjustment:Barely Open
CV-24226	9/28/2026 2:56:01 PM	50.5	48.6	0.2	0.7			1.0	3.5	111.7	111.6	-5.30	-5.32	7.6	7.9	0.037	0.040	-21.53	-21.33	28.42	1249	34.4325337	-118.6442788	Valve Adjustment:Barely Open
CV-24227	9/2/2026 9:09:03 AM	55.9	42.0	0.0	2.1			1.3	0.0	117.4	117.6	-3.39	-3.52	22.0	28.6	1.026	1.738			28.7	1240	34.4309270	-118.6498232	Increased Flow/Vacuum,
CV-24227	9/4/2026 1:33:49 PM	52.9	40.8	0.0	6.3			1.3	0.0	118.8	118.7	-3.12	-3.38	22.6	26.5	1.194	1.643	-9.16	-11.65	28.64	1274	34.4309582	-118.6497832	Valve Adjustment:Increased Flow/Vacuum
CV-24227	9/22/2026 12:30:13 PM	51.2	48.8	0.0	0.0			1.0	0.0	118.0	118.0	-3.22	-3.24	18.9	19.2	0.800	0.827			28.6	1257	34.4309208	-118.6498442	
CV-24231	9/30/2026 12:42:54 PM	44.0	44.0	0.0	12.0			1.0	0.0	127.6	127.5	-0.54	-0.54	22.6	24.8	0.330	0.397	0.00	0.00	28.6	1273	34.4302777	-118.6496547	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24236	9/2/2026 1:22:24 PM	54.2	37.6	0.0	8.2			1.4	0.0	107.3	107.3	-2.38	-2.36	10.3	11.7	0.611	0.786	-11.59		28.75	1168	34.4300885	-118.6504988	
CV-24237	9/2/2026 1:11:47 PM	59.2	35.9	1.4	3.5			1.6	2.5	112.1	112.3	-0.95	-1.05	19.3	24.0	0.743	1.151	-11.43		28.75	1191	34.4306342	-118.6502053	Increased Flow/Vacuum,
CV-24237	9/4/2026 2:04:02 PM	39.0	40.2	1.3	19.5			1.0	14.8	112.8	112.9	-1.26	-1.37	29.3	32.0	1.102	1.318	-10.86	-11.84	28.68	1213	34.4306128	-118.6502200	Valve Adjustment:Increased Flow/Vacuum
CV-24243	9/17/2026 12:16:52 PM	48.3	37.6	1.6	12.5			1.3	7.8	117.9	120.9	0.01	-0.04	1.3	11.8	0.005	0.375	-18.26	-16.48	28.87	1205	34.4287647	-118.6506745	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum
CV-24243	9/17/2026 12:30:09 PM	27.2	23.9	8.6	40.4			1.1	4.7	121.2	120.8	-0.07	-0.04	11.5	8.7	0.357	0.205	-18.98	-17.30	28.86	1190	34.4287782	-118.6506690	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24243	9/17/2026 12:37:43 PM	28.8	25.7	8.5	37.1			1.1	4.4	120.5	120.6	-0.06	-0.05	5.2	2.6	0.073	0.018	-19.34	-17.40	28.87	1201	34.4287717	-118.6506562	Valve Adjustment:High O2
CV-24243	9/22/2026 1:52:57 PM	43.0	34.7	3.6	18.7			1.2	5.2	115.7	115.8	-0.01	-0.01	5.6	5.3	0.084	0.076	-11.81	-10.85	28.66	1206	34.4287828	-118.6506487	Valve Adjustment:NSPS/EG CAC
CV-24244	9/16/2026 8:41:03 AM	49.0	38.8	0.3	11.8			1.3	35.8	112.8	112.7	-1.63	-1.68	13.9	14.5	0.516	0.565	-18.26	-17.59	28.74	1207	34.4289962	-118.6513460	Valve Adjustment:Increased Flow/Vacuum
CV-24244	9/16/2026 8:43:19 AM	48.5	39.0	0.5	12.0			1.2	23.9	112.7	112.6	-1.68	-1.75	15.0	15.3	0.600	0.631	-18.10	-18.95	28.76	1193	34.4290265	-118.6513248	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments	
CV-24245	9/28/2026 10:15:21 AM	48.2	40.5	0.0	11.3			1.2	0.0	117.2	117.7	-0.75	-1.15	9.7	15.0	0.592	1.422	-15.65	-15.04	28.67	1163	34.4284875	-118.6500863	Valve Adjustment:Increased Flow/Vacuum	
CV-24245	9/28/2026 10:17:16 AM	47.7	40.9	0.0	11.4			1.2	0.0	117.8	117.7	-1.18	-1.17	14.6	14.7	1.350	1.368	-14.28	-14.27	28.65	1163	34.4284883	-118.6500860		
CV-24246	9/4/2026 9:59:35 AM	52.5	44.0	0.0	3.5			1.2	0.0	117.9	121.5	0.22	-0.07	4.0	16.3	0.043	0.715	-1.24	-0.96	28.76	1177	34.4286630	-118.6494528	Valve Adjustment:Positive Static Press.,Increased Flow/Vacuum	
CV-24246	9/4/2026 10:00:29 AM	52.0	43.9	0.0	4.1			1.2	0.0	121.7	121.8	-0.08	-0.13	15.6	20.6	0.655	1.147	-0.83	-1.73	28.76	1181	34.4286648	-118.6494527		
CV-24253	9/28/2026 9:37:51 AM	50.0	41.3	0.0	8.7			1.2	0.0	105.9	107.2	-1.20	-1.30	20.0	21.9	0.906	1.091	-14.99	-14.52	28.68	1153	34.4284638	-118.6498265	Valve Adjustment:Increased Flow/Vacuum	
CV-24253	9/28/2026 9:39:46 AM	49.4	41.7	0.0	9.0			1.2	0.0	105.9	107.5	-1.29	-1.28	22.6	21.9	1.156	1.096	-14.40	-14.07	28.68	1150	34.4284662	-118.6498218		
CV-25	9/21/2026 8:45:49 AM	54.9	42.2	0.0	2.9			1.3	0.0	89.9	90.2	-17.97	-17.95	4.0	5.3	0.021	0.036	-18.33	-18.62	28.66	1260	34.4370123	-118.6420942		
CV-2501	9/4/2026 1:08:58 PM	51.7	43.0	0.0	5.3			1.2	131.5	128.7	128.6	-1.13	-1.25	65.3	68.2	1.117	1.230	-6.69	-6.68	28.6	1310	34.4313455	-118.6484332	Valve Adjustment:Increased Flow/Vacuum	
																									Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Valve 100% Closed
CV-2502	9/11/2026 10:11:06 AM	56.8	35.9	0.0	7.3			1.6	0.0	114.6	120.3	0.22	-0.28			0.063	0.000	-15.62	-16.44	28.55	1316	34.4308813	-118.6491094	Valve Adjustment:NSPS/EG CAC,Barely Open	
CV-2502	9/11/2026 10:12:18 AM	56.5	39.0	0.0	4.5			1.4	0.0	122.0	122.0	-0.43	-0.43			0.000	0.000	-16.12	-16.07	28.55	1316	34.4308814	-118.6491091	Valve Adjustment:increased Flow/Vacuum	
CV-2503	9/11/2026 10:21:39 AM	45.5	32.1	0.0	22.4			1.4	0.0	130.3	130.4	-1.79	-1.91	53.0	57.8	0.718	0.855	-13.08	-13.31	28.57	1303	34.4312184	-118.6477578	Valve Adjustment:increased Flow/Vacuum	
CV-2503	9/23/2026 12:40:37 PM	43.5	37.7	0.0	18.8			1.2	0.0	130.2	130.2	-1.35	-1.43	39.8	46.0	0.416	0.556	-9.09	-10.51	28.62	1302	34.4312297	-118.6477603	Valve Adjustment:increased Flow/Vacuum	
CV-2504	9/23/2026 10:20:47 AM	48.4	40.8	0.0	10.9			1.2	0.0	129.9	130.1	-1.06	-1.21	37.3	42.5	3.868	5.045	-15.42	-15.94	28.6	1272	34.4303778	-118.6489542	Valve Adjustment:increased Flow/Vacuum	
CV-2504	9/23/2026 10:23:26 AM	47.3	41.2	0.0	11.5			1.1	0.0	130.2	130.1	-1.19	-1.23	41.0	40.6	4.695	4.602	-14.83	-14.61	28.61	1274	34.4303848	-118.6489475		
																									Valve Adjustment:increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2505	9/23/2026 12:39:50 PM	50.7	42.5	0.0	6.9			1.2	0.0	127.2	127.3	-1.84	-2.02	33.1	35.5	0.708	0.816	-13.13	-13.71	28.61	1242	34.4308168	-118.6471838	Well Condition:Lorentz Pump Installed	
CV-2506	9/23/2026 12:41:42 PM	49.9	42.3	0.0	7.8			1.2	0.0	127.2	127.2	-2.03	-2.04	36.3	34.7	0.853	0.779	-14.60	-13.32	28.61	1245	34.4308110	-118.6471653		
CV-2506	9/23/2026 1:16:38 PM	46.3	41.5	0.0	12.2			1.1	0.0	123.2	123.2	-1.11	-1.15	31.7	35.1	0.649	0.795	-11.29	-13.56	28.63	1237	34.4304637	-118.6475620		
																									Valve Adjustment:Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-2507	9/23/2026 1:33:01 PM	52.1	42.8	0.0	5.1			1.2	0.0	126.7	126.6	-0.74	-1.04	34.6	38.9	1.581	1.997	-13.48	-13.90	28.64	1212	34.4301367	-118.6481625		
CV-2507	9/23/2026 1:36:04 PM	52.4	42.6	0.0	5.1			1.2	0.0	126.6	126.6	-1.14	-1.17	39.4	38.8	2.054	1.985	-13.60	-13.61	28.64	1214	34.4301413	-118.6481570		
CV-2508	9/23/2026 2:08:04 PM	49.7	41.7	0.0	8.6			1.2	0.0	121.7	121.7	-10.89	-11.32	80.3	85.6	1.736	1.978	-13.94	-14.81	28.65	1189	34.4297225	-118.6487580		
CV-2509	9/4/2026 10:15:57 AM	49.3	42.7	0.0	8.0			1.2	0.0	117.0	117.0	-11.75	-11.91	80.5	80.1	4.258	4.214	-19.44	-18.98	28.75	1181	34.4292533	-118.6491843	Valve Adjustment:increased Flow/Vacuum	
CV-2510	9/4/2026 10:06:27 AM	52.7	43.2	0.0	4.1			1.2	0.0	116.1	116.1	-10.74	-10.80	45.5	46.5	5.752	6.020	-18.87	-19.41	28.76	1193	34.4290505	-118.6498313	Valve Adjustment:increased Flow/Vacuum	
																									Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-25100D	9/3/2026 10:05:34 AM	12.4	64.9	0.1	22.6			0.2	226.0	147.9	149.5	-3.40	-3.43			3.391	3.438	-5.22	-5.60	28.53	1365	34.4361387	-118.6471250	Flow/Vacuum, Barely Open	
CV-25100D	9/3/2026 10:06:21 AM	12.4	64.9	0.3	22.4			0.2	74.7	148.9	151.1	-3.35	-2.60			3.341	2.579	-5.28	-5.33	28.52	1371	34.4361427	-118.6471307	Valve Adjustment:High Temp,Decreased Flow/Vacuum	
CV-25100D	9/3/2026 10:34:00 AM					771																			AtmAA
CV-25100D	9/3/2026 10:34:00 AM						63000																		AtmAA; [User entered 6.3%]
CV-25100D	9/8/2026 1:58:00 PM					798																			AtmAA
																									Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-25100D	9/8/2026 1:58:37 PM	13.7	62.5	0.5	23.3			0.2	46.6	159.4	157.5	-1.86	-1.85			1.848	1.848	-4.87	-4.55	28.6	1385	34.4361739	-118.6471388	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed	
CV-25100D	9/14/2026 1:43:20 PM	30.1	47.6	0.1	22.2			0.6	222.0	123.5	123.2	-3.86	-3.84			3.876	3.853	-5.83	-5.92	28.42	1383	34.4361723	-118.6471456	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed	
CV-25100D	9/25/2026 2:09:25 PM	11.9	42.0	0.2	45.9			0.3	229.5	120.2	120.4	-5.56	-5.36			5.507	5.449	-10.08	-10.10	28.45	1371	34.4362112	-118.6471577	Valve Adjustment:Barely Open	
CV-25100S	9/8/2026 1:54:00 PM					2660																			AtmAA
CV-25100S	9/8/2026 1:54:17 PM	3.6	76.2	0.0	20.2			0.0	0.0	189.0	188.5	-2.16	-2.04			2.188	1.907	-5.09	-5.01	28.58	1382	34.4361660	-118.6471288	Valve Adjustment:No Flow Measurement,High Temp	
CV-25100S	9/14/2026 1:46:48 PM	19.1	63.9	0.0	17.0			0.3	0.0	176.4	176.4	-5.40	-5.05			5.702	5.234	-6.16	-5.89	28.42	1383	34.4361652	-118.6471451	Valve Adjustment:No Flow Measurement,High Temp	
CV-25100S	9/14/2026 1:47:00 PM					3330																			AtmAA
CV-25100S	9/21/2026 1:22:46 PM	11.6	72.0	0.0	16.4			0.2	0.0	178.4	178.6	-7.15	-7.08			7.370	7.370	-9.33	-9.26	28.53	1371	34.4361619	-118.6471508	Valve Adjustment:No Flow Measurement,High Temp	
CV-25100S	9/21/2026 1:24:00 PM					2790																			AtmAA
CV-25100S	9/28/2026 1:43:54 PM	8.7	79.9	0.0	11.4			0.1	0.0	164.0	164.2	-8.66	-8.42			8.951	8.717	-10.17	-10.11	28.38	1381	34.4361663	-118.6471300	Valve Adjustment:No Flow Measurement,High Temp	
CV-25100S	9/28/2026 1:55:00 PM					1910																			AtmAA
CV-25101D	9/3/2026 9:32:55 AM	23.2	46.3	0.0	30.5			0.5	0.0	128.9	128.8	-2.35	-2.33			2.330	2.319	-6.15	-6.06	28.52	1377	34.4359590	-118.6467967	Valve Adjustment:Barely Open	
CV-25101D	9/22/2026 10:51:18 AM	18.2	37.7	0.1	44.0			0.5	440.0	127.5	127.5	-3.65	-3.65			3.644	3.645	-9.61	-9.50	28.49	1385	34.4359605	-118.6467978	Valve Adjustment:Barely Open	
CV-25101S	9/3/2026 9:34:39 AM	5.9	27.5	0.1	66.5			0.2	665.0	108.8	109.1	-2.00	-1.98			2.000	1.969	-5.93	-5.60	28.52	1377	34.4359747	-118.6467778	Valve Adjustment:Barely Open	
CV-25101S	9/22/2026 10:53:04 AM	4.5	21.1	1.0	73.4			0.2	73.4	115.4	115.7	-3.02	-3.01			3.015	3.002	-9.54	-9.48	28.5	1385	34.4359565	-118.6468050	Valve Adjustment:Barely Open	
CV-25102	9/14/2026 9:45:37 AM	1.6	81.6	0.0	16.8			0.0	0.0	198.1	200.1	4.34	-0.10		15.5	-4.377	0.361			28.47	1339	34.4358030	-118.6473307		
CV-25102	9/14/2026 9:46:33 AM	1.6	81.6	0.0	16.8			0.0	0.0	200.4	200.4	-0.94	-0.49	41.4	37.9	2.463	2.069			28.47	1299	34.4359130	-118.6471542		

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [\"H2O]	Adj Stat Press [\"H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [\"H2O]	Adj Diff Press [\"H2O]	Sys Pressure [\"H2O]	Adj Avail Press [\"H2O]	Baro Press [\"Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
CV-25102	9/14/2026 1:20:00 PM					1660																		AtmAA
CV-25102	9/21/2026 9:40:00 AM					1260																		AtmAA
CV-25102	9/21/2026 9:46:14 AM	1.7	77.4	0.3	20.6			0.0	68.7	179.6	179.4	-3.90	-3.91			3.920	3.924	-13.02	-13.06	28.58	1375	34.4357959	-118.6471970	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-25102	9/21/2026 9:48:39 AM	2.1	76.8	0.3	20.8			0.0	69.3	174.0	174.6	-3.86	-3.84			3.854	3.873	-13.16	-13.27	28.57	1375	34.4357955	-118.6471971	Valve Adjustment:Audible Flow,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-25102	9/28/2026 10:49:11 AM	15.7	71.1	0.0	13.2			0.2	0.0	185.8	185.9	-2.30	-2.30			2.285	2.284	-10.61	-10.60	28.45	1372	34.4357783	-118.6471935	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-25102	9/28/2026 1:05:00 PM					1810																		AtmAA
CV-25102	9/30/2026 8:30:50 AM	1.9	78.6	0.4	19.1			0.0	47.8	196.3	196.4	-3.80	-1.16			3.725	1.141	-12.41	-12.22	28.48	1374	34.4357825	-118.6471932	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-25102	9/30/2026 8:32:19 AM	1.8	78.5	0.1	19.6			0.0	196.0	196.5	196.4	-1.23	-1.25			1.226	1.227	-12.23	-12.23	28.49	1374	34.4357815	-118.6471928	
CV-25103	9/3/2026 9:09:00 AM	21.7	32.9	2.7	42.7			0.7	15.8	116.8	117.3	-0.29	-0.30			0.287	0.302	-8.02	-8.14	28.52	1374	34.4356168	-118.6467338	Valve Adjustment:Barely Open
CV-25103	9/22/2026 10:46:56 AM	19.1	25.9	4.4	50.6			0.7	11.5	112.5	111.9	-0.61	-0.60			0.611	0.566	-11.13	-11.00	28.49	1381	34.4356483	-118.6467095	Valve Adjustment:Barely Open
CV-25104D	9/15/2026 9:02:09 AM	3.7	79.7	0.0	16.6			0.0	0.0	135.0	129.5	40.95	-0.20		5.7		0.045			28.53	1339	34.4354213	-118.6472855	
CV-25104D	9/15/2026 9:02:43 AM	3.6	82.7	0.0	13.7			0.0	0.0	128.8	128.7	-0.36	-0.36	13.4	13.4	0.241	0.241			28.53	1378	34.4353730	-118.6472162	
CV-25104D	9/23/2026 1:35:53 PM	3.6	80.1	0.2	16.1			0.0	80.5	152.5	155.2	-2.97	-0.23			2.965	0.224	-8.17	-8.26	28.41	1368	34.4353770	-118.6472283	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open;Well Condition:Lorentz Pump Installed
CV-25104S	9/14/2026 9:28:09 AM	12.0	71.6	0.0	16.4			0.2	0.0	174.0	174.2	-5.89	-5.88	67.9	67.9	5.887	5.882			28.47	1329	34.4354580	-118.6471855	
CV-25104S	9/14/2026 9:28:26 AM	11.9	72.7	0.0	15.4			0.2	0.0	174.0	174.2	-5.73	-5.73	67.4	67.3	5.819	5.816			28.47	1362	34.4354128	-118.6471958	
CV-25104S	9/21/2026 10:03:05 AM	13.6	65.3	0.0	21.1			0.2	0.0	118.0	118.0	-8.12	-8.13			8.465	8.449	-10.75	-10.83	28.58	1378	34.4353661	-118.6472328	Valve Adjustment:Audible Flow,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-25104S	9/30/2026 9:51:41 AM	9.5	71.3	0.0	19.2			0.1	0.0	118.4	118.0	-8.08	-7.91			8.222	8.221	-11.98	-12.17	28.47	1379	34.4353421	-118.6472406	Valve Adjustment:No Flow Measurement
CV-25105D	9/3/2026 8:36:30 AM	0.4	2.0	20.3	77.3			0.2	3.8	70.0	70.0	-15.70	-15.31			15.712	15.393	-15.35	-16.20	28.52	1386	34.4353675	-118.6467145	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-25105D	9/3/2026 8:39:20 AM	4.6	19.5	14.7	61.2			0.2	4.2	69.4	68.9	-13.84	-13.84			13.984	13.927	-15.79	-15.80	28.49	1397	34.4353710	-118.6466988	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-25105D	9/25/2026 11:09:43 AM	12.0	78.2	0.1	9.7			0.2	97.0	134.0	134.0	-3.07	-1.57			3.000	1.510	-12.40	-12.35	28.6	1383	34.4353582	-118.6466908	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-25105D	9/25/2026 11:12:40 AM	11.4	78.3	0.0	10.3			0.1	0.0	134.0	134.0	-1.24	-1.33			1.265	1.341	-11.61	-11.15	28.63	1379	34.4353510	-118.6466997	
CV-25105S	9/3/2026 8:42:42 AM	0.0	2.5	20.3	77.2			0.0	3.8	83.1	83.1	-0.30	-0.30			0.297	0.295	-9.61	-16.06	28.52	1394	34.4353628	-118.6467072	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25105S	9/3/2026 8:43:52 AM	0.0	1.7	20.4	77.9			0.0	3.8	67.3	67.1	-0.30	-0.30			0.301	0.301	-15.72	-16.29	28.52	1396	34.4353677	-118.6467120	Valve Adjustment:High O2,Barely Open
CV-25105S	9/25/2026 10:57:59 AM	2.1	2.9	16.9	78.1			0.7	4.6	98.5	98.3	-0.64	-0.64			0.630	0.632	-10.81	-10.48	28.61	1396	34.4353772	-118.6467088	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump
CV-25105S	9/25/2026 10:59:33 AM	2.1	3.0	17.1	77.8			0.7	4.5	98.6	98.6	-0.64	-0.64			0.629	0.628	-12.26	-12.24	28.59	1394	34.4353805	-118.6467123	
CV-25106D	9/14/2026 9:16:26 AM	40.0	58.6	0.3	1.1			0.7	3.7	81.3	81.3	-8.63	-8.58	95.8	95.1	8.512	8.393			28.48	1371	34.4350583	-118.6474012	
CV-25106D	9/21/2026 2:39:29 PM	20.7	62.2	2.8	14.3			0.3	5.1	108.1	108.3	-8.64	-8.86			8.746	9.002	-8.55	-8.38	28.48	1355	34.4350822	-118.6473845	Valve Adjustment:Barely Open;Well Condition:Pumatic Pump Installed
CV-25106S	9/15/2026 9:01:26 AM	19.4	34.1	5.8	40.7			0.6	7.0	77.3	77.3	-9.68	-9.66			9.791	9.883	-9.69	-9.82	28.6	1366	34.4350408	-118.6473680	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In)
CV-25106S	9/15/2026 9:02:41 AM	19.1	34.8	5.5	40.6			0.5	7.4	77.3	77.1	-9.67	-9.66			9.741	9.810	-9.59	-9.56	28.6	1366	34.4350378	-118.6473498	
CV-25106S	9/21/2026 2:36:58 PM	7.5	14.0	15.8	62.7			0.5	4.0	96.1	96.1	-8.44	-8.52			8.578	8.668	-8.23	-8.67	28.48	1362	34.4350632	-118.6473828	Valve Adjustment:High O2,Barely Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
CV-25107D	9/1/2026 9:37:00 AM					4190																		AtmAA
CV-25107D	9/1/2026 9:37:00 AM						110100																	AtmAA; [User entered 11.01%]
CV-25107D	9/1/2026 9:41:08 AM	2.6	0.0	19.7	77.7				3.9	169.5	168.9	-12.49	-3.48			12.951	3.488	-15.73	-15.78	28.57	1394	34.4350678	-118.6459510	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [\"H2O]	Adj Stat Press [\"H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [\"H2O]	Adj Diff Press [\"H2O]	Sys Pressure [\"H2O]	Adj Avail Press [\"H2O]	Baro Press [\"Hg]	Elev [ft]	Latitude	Longitude	Comments	
CV-25107D	9/1/2026 9:49:48 AM	10.8	53.7	7.0	28.5			0.2	4.1	168.5	167.7	-3.39	-2.44			3.346	2.366	-16.31	-15.71	28.57	1390	34.4350571	-118.6459631	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum	
CV-25107D	9/1/2026 9:52:33 AM	15.3	76.3	1.4	7.0			0.2	5.0	167.4	167.5	-1.37	-1.39			1.342	1.324	-16.18	-14.44	28.57	1391	34.4350530	-118.6459614	Valve Adjustment:No Flow Measurement,High Temp	
CV-25107D	9/1/2026 10:04:00 AM						110100																		AtmAA; [User entered 11.01%]
CV-25107D	9/9/2026 10:27:10 AM	12.6	80.1	0.0	7.3			0.2	0.0	172.9	172.7	9.76	-4.59			0.000	4.514	-9.45	-9.48	28.66	1404	34.4350433	-118.6459781	Valve Adjustment:No Flow Measurement,High Temp	
CV-25107D	9/9/2026 10:32:44 AM	12.1	59.9	4.2	23.8			0.2	5.7	173.4	173.3	-4.16	-1.42			4.160	1.423	-5.90	-6.70	28.65	1404	34.4350493	-118.6459781	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum	
CV-25107D	9/9/2026 10:33:42 AM	12.2	63.9	0.8	23.1			0.2	28.9	173.5	173.8	-2.70	-2.35			2.753	2.169	-6.24	-9.53	28.65	1404	34.4350494	-118.6459779		
CV-25107D	9/9/2026 10:35:00 AM					3410																			AtmAA
CV-25107D	9/15/2026 1:35:00 PM					4090																			AtmAA
CV-25107D	9/15/2026 1:35:50 PM	12.2	79.1	0.0	8.7			0.2	0.0	173.5	173.2	2.29	2.51			0.000	0.000	1.49	1.28	28.49	1402	34.4350638	-118.6459660	Valve Adjustment:No Flow Measurement,High Temp	
CV-25107D	9/15/2026 1:39:57 PM	10.4	76.2	0.0	13.4			0.1	0.0	175.4	175.9	2.11	2.71			0.000	0.000	-0.23	1.45	28.49	1401	34.4350641	-118.6459709	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Surging Liquid in Header	
CV-25107D	9/22/2026 2:13:00 PM					108																			AtmAA
CV-25107D	9/22/2026 2:20:08 PM	11.8	49.7	2.8	35.7			0.2	12.8	164.9	165.1	-3.12	-2.57			3.071	2.427	-3.12	-2.65	28.46	1403	34.4350618	-118.6459605	Valve Adjustment:No Flow Measurement,High Temp,Well Condition:Lorentz Pump Installed	
CV-25107D	9/29/2026 1:39:25 PM	11.1	38.8	7.9	42.2			0.3	5.3	163.8	167.1	-4.27	-5.45			3.948	4.939	-4.77	-5.85	28.31	1394	34.4350416	-118.6459700	Valve Adjustment:No Flow Measurement,High Temp,Surging Liquid in Header,Well Condition:Lorentz Pump Installed	
CV-25107D	9/29/2026 1:40:00 PM					3530																			AtmAA
CV-25107S	9/3/2026 12:53:12 PM	2.4	87.1	0.0	10.5			0.0	0.0	103.2	103.2	-0.06	-0.06			0.077	0.070	-12.55	-12.58	28.46	1380	34.4350475	-118.6459542	Valve Adjustment:Barely Open	
CV-25107S	9/22/2026 10:17:17 AM	46.2	50.8	0.1	2.9			0.9	29.0	143.9	142.6	-5.45	-3.22			5.743	3.210	-5.40	-7.15	28.49	1373	34.4350365	-118.6459687	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header	
CV-25107S	9/22/2026 10:19:04 AM	49.2	47.0	0.1	3.7			1.0	37.0	144.0	143.0	-2.64	-2.66			2.643	2.656	-9.61	-9.34	28.51	1378	34.4350417	-118.6459593	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)	
CV-2511	9/30/2026 1:02:49 PM	51.1	43.8	0.0	5.1			1.2	0.0	127.4	127.3	-0.38	-0.42	30.0	33.8	0.237	0.302	-8.87	-9.88	28.62	1247	34.4296585	-118.6501777	Valve Adjustment:Audible Flow,Surging Liquid in Header,Reduce Sys. Vac. - Flare Down	
CV-2512	9/4/2026 10:31:39 AM	44.0	42.6	0.0	13.4			1.0	0.0	125.3	125.4	-0.90	-0.92	22.2	24.8	0.130	0.162	-18.14	-17.92	28.7	1247	34.4292485	-118.6506277	Valve Adjustment:Increased Flow/Vacuum	
CV-2513	9/17/2026 1:56:08 PM	53.7	42.1	0.0	4.2			1.3	0.0	121.8	121.7	-2.27	-2.25	31.3	31.2	2.286	2.271	-14.17	-13.67	28.87	1156	34.4288257	-118.6488242		
CV-2513	9/17/2026 1:59:17 PM	52.8	42.0	0.0	5.2			1.3	0.0	121.7	121.7	-2.29	-2.28	30.3	30.4	1.193	1.202	-13.72	-13.04	28.88	1154	34.4288262	-118.6488200	Valve Adjustment:Orifice Plate Changed (See OP Log)	
CV-2514	9/21/2026 10:01:35 AM	53.7	42.0	0.0	4.3			1.3	0.0	127.4	127.5	-0.19	-0.26	16.5	18.4	0.638	0.790	-3.90	-3.97	28.78	1151	34.4296145	-118.6477938	Valve Adjustment:Increased Flow/Vacuum,Surging Liquid in Header	
CV-2514	9/21/2026 10:07:35 AM	53.4	41.8	0.0	4.8			1.3	0.0	127.8	127.8	-0.28	-0.34	17.2	18.3	0.692	0.787	-3.61	-3.88	28.79	1155	34.4296012	-118.6477977		
CV-2515	9/29/2026 10:32:00 AM	43.7	37.5	0.0	18.9			1.2	0.0	115.7	115.1	-2.03	-1.28	31.3	25.4	1.276	0.840	-16.05	-12.86	28.44	1253	34.4378905	-118.6432107	Valve Adjustment:Decreased Flow/Vacuum	
CV-2515	9/29/2026 10:36:37 AM	43.4	38.0	0.0	18.6			1.1	0.0	114.8	115.2	-1.21	-1.21	34.0	34.5	2.697	2.783	-15.76	-15.72	28.45	1255	34.4378745	-118.6432197	Valve Adjustment:Orifice Plate Changed (See OP Log)	
CV-2515	9/29/2026 10:37:18 AM	43.5	38.2	0.0	18.4			1.1	0.0	115.2	115.2	-1.26	-1.26	28.8	29.0	1.935	1.955	-15.90	-16.07	28.45	1264	34.4379030	-118.6432222	Valve Adjustment:Reduce Sys. Vac. - Flare Down	
CV-2515	9/29/2026 10:40:01 AM	43.5	38.2	0.0	18.4			1.1	0.0	115.2	115.3	-1.39	-1.40	15.6	15.4	0.565	0.552	-15.89	-15.88	28.43	1264	34.4378942	-118.6432200	Valve Comment:Removed differential port blockage	
CV-2516	9/16/2026 11:55:45 AM	50.1	42.2	0.0	7.7			1.2	0.0	128.0	127.9	-7.35	-7.35	20.4	21.0	2.737	2.909	-15.46	-15.70	28.75	1297	34.4374025	-118.6431808	Valve Adjustment:Audible Flow	
CV-2517	9/21/2026 9:13:49 AM	40.0	35.3	0.0	24.7			1.1	0.0	115.5	116.0	-3.28	-3.47	6.7	9.3	0.121	0.236	-19.36	-19.23	28.66	1267	34.4369505	-118.6420208		
CV-2518	9/21/2026 9:35:14 AM	52.5	38.3	0.0	9.2			1.4	0.0	109.8	110.3	-5.08	-5.08	27.2	27.7	0.189	0.195	-0.34	-0.30	28.7	1247	34.4364008	-118.6414373		
CV-2519	9/22/2026 2:34:58 PM	46.4	41.4	0.1	12.1			1.1	121.0	122.8	122.7	-1.01	-0.90	18.4	16.4	0.901	0.718	-18.60		28.49	1381	34.4361342	-118.6419822		
CV-2520	9/22/2026 2:46:22 PM	34.1	50.4	0.0	15.5			0.7	0.0	135.9	134.9	-1.60	-1.45	0.0	0.0	0.123	0.165	-19.20		28.49	1339	34.4358263	-118.6427397		
CV-2520	9/22/2026 2:48:41 PM	34.2	51.3	0.0	14.5			0.7	0.0	134.0	134.0	-1.12	-1.12	0.0	0.0	0.026	0.032	-19.21		28.49	1293	34.4358582	-118.6427438		
CV-2521	9/30/2026 8:54:33 AM	45.7	43.6	0.0	10.7			1.0	0.0	105.5	105.4	-19.50	-19.47			19.745	19.705	-19.75	-19.74	28.48	1331	34.4354747	-118.6430567	Valve Adjustment:Valve 100% Open,Reduce Sys. Vac. - Flare Down	
CV-2521	9/30/2026 12:10:46 PM	44.0	46.6	0.0	9.4			0.9	0.0	138.9	138.1	-12.72	-11.07			12.942	11.303	-12.78	-12.39	28.56	1329	34.4354790	-118.6430585	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down;Well Comment:No pump	
CV-2521	9/30/2026 12:11:47 PM	45.0	44.6	0.0	10.4			1.0	0.0	137.8	138.0	-10.78	-10.87			11.011	11.038	-12.35	-12.23	28.56	1329	34.4354862	-118.6430565		
CV-2522	9/22/2026 3:06:29 PM	41.8	45.5	0.0	12.7			0.9	0.0	132.8	131.3	-6.58	-4.60	0.0	0.0	-1.054	0.071	-19.09		28.52	1263	34.4355943	-118.6423742		

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [""H2O]	Adj Stat Press [""H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [""H2O]	Adj Diff Press [""H2O]	Sys Pressure [""H2O]	Adj Avail Press [""H2O]	Baro Press [""Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
CV-2522	9/22/2026 3:07:55 PM	43.6	44.3	0.0	12.1			1.0	0.0	129.3	129.4	-3.66	-3.62	0.0	0.0	0.021	-0.057	-19.22		28.52	1257	34.4355928	-118.6424520	
CV-2523	9/25/2026 11:36:15 AM	47.8	41.7	0.0	10.5			1.1	0.0	126.8	126.8	-5.94	-5.97	30.4	30.4	6.061	6.050	-19.38	-18.58	28.66	1286	34.4356635	-118.6416667	
CV-2524	9/22/2026 3:14:40 PM	32.2	40.5	1.0	26.3			0.8	26.3	138.1	126.7	-4.29	-1.46	0.0	0.0	-0.752	0.928	-16.91		28.52	1332	34.4348030	-118.6424923	NSPS/EG CAI,High Temp
CV-2524	9/22/2026 3:18:41 PM	33.0	37.6	0.9	28.5			0.9	31.7	122.1	121.8	-1.18	-1.14	0.0	0.0	1.078	1.071	-17.01		28.52	1260	34.4346678	-118.6425243	NSPS/EG CAI,
CV-2525	9/25/2026 11:17:14 AM	32.3	32.4	0.1	35.2			1.0	352.0	119.3	119.2	-12.87	-12.35	61.1	59.9	10.897	10.418	-19.50	-19.46	28.66	1276	34.4349688	-118.6417315	Valve Adjustment:Decreased Flow/Vacuum
CV-2526	9/29/2026 9:14:52 AM	47.4	39.0	0.0	13.5			1.2	0.0	122.5	122.7	-1.57	-1.60	13.3	12.9	0.114	0.108	-20.70	-20.74	28.46	1270	34.4345157	-118.6415813	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-2527	9/14/2026 8:36:25 AM	46.4	43.6	0.1	9.9			1.1	99.0	132.5	132.5	-5.65	-5.67			5.696	5.695	-20.31	-18.71	28.59	1304	34.4340957	-118.6428678	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-2527	9/14/2026 8:37:20 AM	45.8	44.0	0.0	10.2			1.0	0.0	132.6	132.2	-5.44	-5.42			5.697	5.695	-20.75	-19.64	28.59	1307	34.4340973	-118.6428842	
CV-2527	9/30/2026 9:05:03 AM	5.7	50.4	0.0	44.0			0.1	0.0	86.7	86.4	0.67	-0.24			0.000	0.249	-20.30	-19.56	28.53	1318	34.4340880	-118.6428660	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
CV-2527	9/30/2026 9:07:01 AM	5.4	52.2	0.0	42.4			0.1	0.0	86.1	86.1	-1.20	-1.21			1.203	1.213	-20.18	-19.97	28.5	1305	34.4341018	-118.6428687	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-2527	9/30/2026 9:11:36 AM	5.0	52.6	0.0	42.4			0.1	0.0	86.4	84.6	-1.23	-0.18			1.229	0.176	-20.41	-19.99	28.53	1319	34.4340958	-118.6428758	Valve Adjustment:Decreased Flow/Vacuum
CV-2527	9/30/2026 9:12:30 AM	5.1	52.9	0.0	42.1			0.1	0.0	84.6	84.5	-0.08	-0.08			0.076	0.075	-19.38	-20.78	28.53	1319	34.4340957	-118.6428798	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-2527	9/30/2026 12:24:57 PM	10.0	54.3	0.0	35.7			0.2	0.0	110.5	113.7	-3.12	-3.18			3.075	3.133	-12.80	-12.48	28.56	1309	34.4340902	-118.6428787	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open,Reduce Sys. Vac. - Flare Down
CV-2527	9/30/2026 12:26:17 PM	12.2	54.5	0.0	33.3			0.2	0.0	114.6	114.6	-3.63	-3.64			3.584	3.594	-12.30	-13.92	28.59	1307	34.4340925	-118.6428720	Valve Adjustment:NSPS/EG CAC
CV-2528	9/21/2026 10:33:20 AM	43.4	35.8	0.0	20.8			1.2	0.0	110.6	110.5	-5.40	-5.41	21.1	22.3	0.282	0.315	-25.30	-25.22	28.7	1241	34.4337997	-118.6412453	
CV-2529	9/4/2026 8:05:25 AM	55.1	39.4	0.7	4.7			1.4	6.3	77.4	80.4	13.31	-0.88	2.7	2.9	0.696	0.870	-16.78	-10.95	28.65	1229	34.4331448	-118.6423483	Valve Adjustment:Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-2529	9/4/2026 8:07:06 AM	51.6	39.1	1.3	8.0			1.3	6.1	80.6	80.6	-1.61	-1.67	2.7	2.7	0.746	0.750	-10.83	-10.97	28.65	1226	34.4331263	-118.6423528	
CV-2530	9/28/2026 3:53:58 PM	45.3	47.4	0.2	7.1			1.0	35.5	107.9	109.9	-21.37	-21.24			21.549	21.367	-21.59	-21.41	28.48	1223	34.4327540	-118.6429517	Valve Comment:Valve stuck open
CV-2531	9/28/2026 3:43:12 PM	35.2	53.1	0.2	11.5			0.7	57.5	113.6	113.3	-9.72	-3.38			9.743	3.377	-21.60	-21.67	28.48	1225	34.4325842	-118.6433368	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-2532	9/30/2026 8:40:47 AM	51.5	42.4	0.2	5.9			1.2	34.8	97.1	97.6	-22.46	-22.61			22.665	22.816	-23.52	-23.65	28.57	1214	34.4322510	-118.6437185	Well Condition:Pnumatic Pump Installed;Well Repairs:Sample Port
CV-2533	9/28/2026 3:24:49 PM	43.0	36.2	3.6	17.2			1.2	4.8	128.2	127.4	-5.77	-3.85	18.5	15.6	0.956	0.680	-21.91	-22.09	28.48	1194	34.4319202	-118.6440960	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-2534	9/1/2026 11:25:42 AM	33.8	46.3	0.0	19.9			0.7	0.0	110.6	110.6	-1.04	-1.04	0.0	0.0	-1.022	-1.022	-10.62		28.63	1302	34.4317317	-118.6491760	
CV-2534	9/28/2026 3:16:57 PM	51.6	48.3	0.0	0.1			1.1	0.0	100.4	100.7	-6.71	-3.34	43.6	29.2	2.456	1.086	-15.05	-14.42	28.46	1215	34.4316987	-118.6445058	Valve Adjustment:Decreased Flow/Vacuum
CV-2535	9/23/2026 12:53:43 PM	45.5	39.3	0.0	15.3			1.2	0.0	115.5	115.2	-0.53	-0.33	12.0	9.7	3.058	1.971	-2.96	-2.67	28.61	1249	34.4309728	-118.6469200	Valve Adjustment:Decreased Flow/Vacuum
CV-2536	9/25/2026 9:51:12 AM	48.1	43.1	1.3	7.5			1.1	5.6	98.2	98.2	-5.79	-5.73	5.5	5.2	0.628	0.553	-8.04	-7.79	28.76	1182	34.4309900	-118.6458555	
CV-2537	9/25/2026 9:09:18 AM	47.0	39.2	0.0	13.8			1.2	0.0	118.6	118.7	-3.10	-3.10			3.125	3.125	-8.98	-9.17	28.7	1223	34.4310497	-118.6466448	
CV-2538	9/25/2026 8:54:18 AM	50.2	40.9	0.0	9.0			1.2	0.0	114.5	114.4	-1.21	-1.21	31.4	31.4	2.281	2.268	-9.30	-9.22	28.71	1216	34.4308187	-118.6467205	
CV-2539	9/15/2026 10:51:41 AM	44.0	42.3	0.0	13.7			1.0	0.0	120.5	120.3	-1.41	-1.39			1.382	1.365	-9.43	-9.18	28.67	1322	34.4317167	-118.6492018	Valve Adjustment:Barely Open
CV-2539	9/21/2026 12:01:09 PM	41.3	43.2	0.0	15.5			1.0	0.0	122.6	122.3	-1.23	-1.23			1.210	1.210	-11.25	-11.22	28.67	1320	34.4317142	-118.6491973	Valve Adjustment:Barely Open
CV-2540	9/2/2026 9:19:21 AM	15.9	80.1	0.0	4.0			0.2	0.0	138.4	138.6	-10.01	-3.32			10.241	3.332	-11.57	-11.59	28.6	1367	34.4332697	-118.6480940	Valve Adjustment:Decreased Flow/Vacuum
CV-2540	9/17/2026 1:58:14 PM	7.6	81.6	0.0	10.8			0.1	0.0	138.7	138.9	-1.23	-1.31			1.219	1.280	-10.11	-10.45	28.63	1373	34.4332718	-118.6481188	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2541	9/1/2026 10:53:11 AM	21.9	63.8	0.0	14.3			0.3	0.0	108.4	108.9	-1.13	-1.14	0.0	0.0	1.169	1.168	-7.01		28.61	1309	34.4332297	-118.6491375	
CV-2541	9/17/2026 10:16:55 AM	22.7	63.9	0.1	13.3			0.4	133.0	127.5	128.6	-2.34	-2.01			2.336	2.000	-11.10	-10.75	28.7	1340	34.4332678	-118.6490583	Valve Adjustment:Decreased Flow/Vacuum
CV-2542	9/2/2026 1:13:18 PM	44.3	54.0	0.6	1.1			0.8	1.8	130.1	130.1	-9.73	-9.63			9.763	9.716	0.33	0.32	28.56	1389	34.4337235	-118.6471813	Valve Adjustment:Valve 100% Open
CV-2542	9/17/2026 3:00:18 PM	39.4	56.6	0.4	3.6			0.7	0.9	130.0	130.4	-9.73	-10.82			9.496	10.868	0.28	0.28	28.6	1383	34.4337205	-118.6472078	Valve Comment:Hard pipped;Valve Adjustment:Increased Flow/Vacuum
CV-2543-PLF	9/2/2026 9:36:06 AM	6.2	55.2	7.1	31.5			0.1	4.4	95.9	97.9	-1.92	-1.80			1.929	1.803	-1.48	-1.57	28.63	1343	34.4338343	-118.6484718	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-2543-PLF	9/17/2026 2:16:09 PM	13.5	60.1	4.1	22.3			0.2	5.4	99.7	101.0	-4.56	-3.40			4.536	3.398	-4.43	-3.30	28.64	1348	34.4338625	-118.6485018	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-2544	9/15/2026 9:11:52 AM	6.9	84.9	0.0	8.2			0.1	0.0	89.8	89.8	-2.09	-2.09	0.0	0.0	1.844	2.191	-6.81		28.51	1348	34.4339618	-118.6471392	
CV-2544	9/15/2026 9:14:07 AM	7.0	84.7	0.0	8.3			0.1	0.0	145.2	145.3	-1.43	-1.45	0.0	0.0	1.383	1.388	-6.55		28.51	1388	34.4339843	-118.6472425	NSPS/EG CAI,High Temp
CV-2544	9/15/2026 9:33:39 AM	6.8	82.3	0.0	10.9			0.1	0.0	145.4	145.4	-1.66	-1.63	0.0	0.0	1.483	1.401	-6.54		28.51	1401	34.4333795	-118.6465553	NSPS/EG CAI,High Temp

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading	H2 Reading	CH4: CO2	Bal/O2	Init Temp	Adj Temp	Init Stat Press	Adj Stat Press	Init Flow	Adj Flow	Init Diff Press	Adj Diff Press	Sys Pressure	Adj Avail Press	Baro Press	Elev	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]	[ppmv]	[ppmv]		[%]	[°F]	[°F]	[\"H2O]	[\"H2O]	[scfm]	[scfm]	[\"H2O]	[\"H2O]	[\"H2O]	[\"H2O]	[\"Hg]	[ft]			
CV-2544	9/21/2026 10:26:52 AM	10.7	82.2	0.0	7.1			0.1	0.0	150.1	150.0	-4.48	-4.33			4.477	4.338	-9.75	-9.28	28.58	1386	34.4340300	-118.6472290	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2544	9/21/2026 10:35:00 AM					2090												0.000	0.064	-3.90	-3.42	28.52		AtmAA
CV-2545	9/2/2026 1:57:34 PM	27.2	71.1	0.0	1.7			0.4	0.0	126.5	129.4	0.39	-0.07			0.000	0.064	-3.90	-3.42	28.52	1385	34.4340253	-118.6467365	Valve Adjustment:Barely Open
CV-2545	9/2/2026 2:00:03 PM	29.1	70.9	0.0	0.0			0.4	0.0	129.3	129.7	-0.12	-0.13			0.106	0.114	-3.34	-3.08	28.53	1392	34.4340200	-118.6467337	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-2545	9/21/2026 1:45:21 PM	33.1	61.0	0.1	5.8			0.5	58.0	127.9	127.5	-1.20	-1.19			1.175	1.164	-5.24	-4.92	28.47	1403	34.4340103	-118.6467513	Valve Adjustment:Barely Open
CV-2546	9/2/2026 2:02:59 PM	22.8	73.0	0.0	4.2			0.3	0.0	129.8	129.6	0.04	-0.05			0.000	0.059	-3.37	-2.78	28.53	1375	34.4341267	-118.6469773	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum,Barely Open
CV-2546	9/2/2026 2:03:29 PM	22.6	75.0	0.1	2.3			0.3	23.0	129.1	130.6	-0.21	-0.20			0.160	0.157	-3.16	-3.16	28.53	1385	34.4341332	-118.6469887	Valve Adjustment:Barely Open
CV-2546	9/21/2026 2:15:18 PM	18.6	73.6	3.5	4.3			0.3	1.2	124.4	124.5	-0.78	-0.78			0.775	0.815	-4.44	-4.36	28.48	1381	34.4341222	-118.6469958	Valve Adjustment:Barely Open
CV-2547	9/24/2026 1:41:35 PM	51.7	46.6	0.0	1.7			1.1	0.0	99.9	99.7	-0.05	-0.02			0.000	0.000	-2.31	-3.71	28.45	1389	34.4339323	-118.6459912	Valve Adjustment:Barely Open
CV-2548	9/1/2026 12:26:39 PM	6.6	80.2	0.0	13.2			0.1	0.0	139.7	139.7	-0.33	-0.38	44.1	46.2	2.624	2.879	-15.14	-16.55	28.66	1393	34.4343298	-118.6455988	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-2548	9/1/2026 12:27:39 PM	6.3	81.7	0.0	12.0			0.1	0.0	139.6	139.6	-0.45	-0.48	44.7	46.3	2.697	2.887	-15.69	-16.59	28.67	1388	34.4343440	-118.6456083	Valve Adjustment:Increased Flow/Vacuum
CV-2548	9/3/2026 1:03:06 PM	7.0	75.8	0.0	17.2			0.1	0.0	86.3	85.5	-1.22	-1.34	51.7	54.6	3.307	3.696	-19.04	-21.86	28.53	1388	34.4343420	-118.6455865	Valve Adjustment:Increased Flow/Vacuum
CV-2548	9/18/2026 2:00:15 PM	7.0	85.6	0.0	7.4			0.1	0.0	137.8	137.9	-0.99	-0.35	53.4	47.2	19.272	14.932	-21.05	-20.07	28.56	1421	34.4343682	-118.6455775	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open;Well Condition:Lorentz Pump Installed
CV-2548	9/18/2026 2:02:16 PM	6.9	85.9	0.0	7.2			0.1	0.0	137.9	137.8	-0.34	-0.20	51.8	48.4	18.065	15.715	-21.53	-18.48	28.56	1426	34.4343600	-118.6455920	Valve Adjustment:Orifice Plate Changed (See OP Log),High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2548	9/22/2026 9:25:43 AM	6.0	82.2	0.0	11.8			0.1	0.0	139.0	139.0	-0.08	-0.15			0.000	0.000	-20.23	-17.01	28.55	1392	34.4343344	-118.6455764	Valve Adjustment:Increased Flow/Vacuum
CV-2549	9/1/2026																							

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [”H2O]	Adj Stat Press [”H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [”H2O]	Adj Diff Press [”H2O]	Sys Pressure [”H2O]	Adj Avail Press [”H2O]	Baro Press [”Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
CV-2551	9/15/2026 1:29:53 PM	35.0	65.0	0.0	0.0			0.5	0.0	166.6	167.9	-5.40	-5.05			5.671	5.234	-8.13	-7.41	28.49	1408	34.4349401	-118.6458381	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2551	9/15/2026 1:30:00 PM					1540																		AtmAA
CV-2551	9/22/2026 2:05:45 PM	34.9	64.9	0.1	0.1			0.5	1.0	164.3	163.1	-4.43	-4.33			4.360	4.390	-6.30	-6.23	28.44	1405	34.4349389	-118.6458271	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2551	9/22/2026 2:07:00 PM					2190																		AtmAA
CV-2551	9/29/2026 1:30:00 PM					2660																		AtmAA
CV-2551	9/29/2026 1:30:09 PM	32.1	67.9	0.0	0.0			0.5	0.0	155.0	155.7	-4.57	-4.49			4.665	4.453	-6.15	-7.00	28.28	1398	34.4349211	-118.6458237	Valve Adjustment:High Temp,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-2552	9/1/2026 1:12:06 PM	8.3	81.6	0.0	10.1			0.1	0.0	171.3	171.3	-14.89	-14.20			15.020	14.372	0.00	0.00	28.57	1392	34.4348684	-118.6465507	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2552	9/1/2026 1:16:00 PM					1800																		AtmAA
CV-2552	9/1/2026 1:16:00 PM						74500																	AtmAA; [User entered 7.45%]
CV-2552	9/9/2026 1:16:00 PM					372																		AtmAA
CV-2552	9/9/2026 1:17:03 PM	40.3	59.4	0.3	0.0			0.7	0.0	165.1	165.1	-8.21	-8.42			8.227	8.580	0.00	0.00	28.57	1385	34.4348737	-118.6465371	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2552	9/16/2026 8:55:00 AM					1080																		AtmAA
CV-2552	9/16/2026 8:55:21 AM	24.8	75.2	0.0	0.0			0.3	0.0	168.3	168.5	-4.84	-4.77			4.845	4.790	0.00	0.00	28.57	1378	34.4348783	-118.6465171	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2552	9/23/2026 9:14:44 AM	32.3	67.2	0.5	0.0			0.5	0.0	167.1	167.1	-13.42	-13.14			13.773	13.624	0.04	0.04	28.49	1376	34.4348846	-118.6465267	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2552	9/23/2026 9:15:00 AM					1290																		AtmAA
CV-2552	9/30/2026 8:15:00 AM					1460																		AtmAA
CV-2552	9/30/2026 8:27:07 AM	23.4	76.2	0.3	0.1			0.3	0.3	167.7	167.7	-11.80	-11.79			12.086	12.068	0.08	0.08	28.42	1374	34.4348794	-118.6465258	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2553	9/2/2026 9:50:00 AM	34.8	60.4	0.0	4.8			0.6	0.0	110.0	110.0	-3.02	-2.47			3.027	2.471	-11.09	-10.76	28.64	1339	34.4341628	-118.6489138	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-2553	9/17/2026 10:55:57 AM	36.0	57.8	0.1	6.1			0.6	61.0	89.8	76.5	-3.03	-1.84			3.030	1.822	-10.97	-11.31	28.71	1342	34.4341562	-118.6489118	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-2554	9/1/2026 2:17:21 PM	35.4	64.6	0.0	0.0			0.5	0.0	160.4	160.5	-6.31	-6.23			0.335	0.262	0.00	0.00	28.58	1360	34.4344608	-118.6482734	Valve Adjustment:No Flow Measurement,High Temp
CV-2554	9/1/2026 2:20:00 PM					779																		AtmAA
CV-2554	9/1/2026 2:20:00 PM						59700																	AtmAA; [User entered 5.97%]
CV-2554	9/10/2026 8:49:04 AM	36.1	62.6	1.3	0.0			0.6	0.0	168.2	168.6	-6.55	-6.45			6.812	6.768	-6.74	-6.76	28.57	1358	34.4344607	-118.6482651	Valve Adjustment:No Flow Measurement,High Temp
CV-2554	9/10/2026 8:51:00 AM					816																		AtmAA
CV-2554	9/16/2026 10:15:07 AM	32.3	65.8	0.0	1.9			0.5	0.0	164.5	165.1	-4.73	-4.63			5.146	5.016	-5.06	-4.84	28.64	1354	34.4344641	-118.6482674	Valve Adjustment:No Flow Measurement,High Temp
CV-2554	9/16/2026 10:17:00 AM					669																		AtmAA
CV-2554	9/23/2026 10:20:05 AM	42.0	57.9	0.0	0.1			0.7	0.0	169.0	169.0	-10.78	-10.78			11.262	11.311	-10.93	-11.07	28.51	1353	34.4344504	-118.6482660	Valve Adjustment:No Flow Measurement,High Temp
CV-2554	9/23/2026 10:25:00 AM					671																		AtmAA
CV-2554	9/30/2026 9:20:33 AM	33.5	66.5	0.0	0.0			0.5	0.0	164.0	164.4	-10.37	-10.13			10.745	10.694	-10.37	-10.36	28.47	1356	34.4344741	-118.6482482	Valve Adjustment:No Flow Measurement,High Temp
CV-2554	9/30/2026 9:30:00 AM					582																		AtmAA
CV-2555	9/14/2026 10:19:23 AM	51.2	47.4	0.0	1.4			1.1	0.0	119.4	118.3	-3.92	-3.88	64.8	64.8	3.798	3.791			28.48	1339	34.4347467	-118.6477035	
																								Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2555	9/21/2026 2:31:09 PM	44.1	55.3	0.1	0.5			0.8	5.0	127.3	128.8	-3.41	-2.69			0.000	0.000	-7.80	-7.69	28.48	1355	34.4348352	-118.6477542	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2556-PLR	9/1/2026 1:23:16 PM	21.4	68.0	1.1	9.5			0.3	8.6	183.7	183.7	-0.29	-0.25			0.300	0.269	0.17	0.17	28.58	1371	34.4351565	-118.6472239	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2556-PLR	9/1/2026 1:29:00 PM					2270																		AtmAA
CV-2556-PLR	9/1/2026 1:29:00 PM						84900																	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [\"H2O]	Adj Stat Press [\"H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [\"H2O]	Adj Diff Press [\"H2O]	Sys Pressure [\"H2O]	Adj Avail Press [\"H2O]	Baro Press [\"Hg]	Elev [ft]	Latitude	Longitude	Comments	
CV-2556-PLR	9/16/2026 9:20:48 AM	10.7	80.8	0.0	8.5			0.1	0.0	186.8	187.7	0.31	-1.40			0.000	1.380	-4.55	-4.51	28.6	1360	34.4351579	-118.6471987	Valve Adjustment: NSPS/EG CAI; No Flow Measurement, High Temp; Increased Flow/Vacuum; Well Condition: Lorentz Pump Installed	
CV-2556-PLR	9/16/2026 9:21:53 AM	11.6	81.4	0.0	7.0			0.1	0.0	187.6	187.6	-1.53	-1.53			1.519	1.537	-4.58	-4.63	28.6	1359	34.4351558	-118.6472029	Valve Adjustment: NSPS/EG CAI; No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed	
CV-2556-PLR	9/23/2026 9:27:28 AM	41.2	46.9	2.3	9.6			0.9	4.2	174.8	174.3	-5.76	-5.76			6.258	6.258	-12.63	-12.63	28.49	1366	34.4351569	-118.6471918	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed	
CV-2556-PLR	9/23/2026 9:30:00 AM					687																			AtmAA
CV-2556-PLR	9/30/2026 8:45:00 AM					927																			AtmAA
CV-2556-PLR	9/30/2026 8:45:01 AM	23.6	45.9	2.8	27.7			0.5	9.9	171.8	171.8	-5.44	-5.43			5.872	5.878	-11.09	-11.16	28.46	1362	34.4351535	-118.6471946	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed	
CV-2557	9/15/2026 8:51:14 AM	16.8	43.1	0.0	40.1			0.4	0.0	140.6	140.8	-6.73	-6.66	0.0	0.0	6.647	6.574	-10.59		28.51	1352	34.4355248	-118.6465558	NSPS/EG CAI; High Temp	
CV-2557	9/15/2026 8:52:00 AM	16.8	43.1	0.0	40.1			0.4	0.0	139.6	140.0	-6.55	-6.55	0.0	0.0	6.545	6.549	-10.56		28.51	1348	34.4355342	-118.6464980	NSPS/EG CAI; High Temp	
CV-2557	9/22/2026 10:25:41 AM	15.6	39.1	2.9	42.4			0.4	14.6	139.7	139.1	-7.09	-5.41			7.429	5.761	-9.47	-10.02	28.52	1390	34.4354872	-118.6464842	Valve Adjustment: High Temp, Decreased Flow/Vacuum	
CV-2558-PLR	9/1/2026 10:13:00 AM					1150																			AtmAA
CV-2558-PLR	9/1/2026 10:13:00 AM						70000																		AtmAA; [User entered 7%]
CV-2558-PLR	9/1/2026 10:28:32 AM	17.3	75.1	0.3	7.3			0.2	24.3	192.6	193.3	1.35	1.32			0.000	0.000	0.67	0.59	28.58					Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Pneumatic Pump Installed
CV-2558-PLR	9/9/2026 1:00:56 PM	14.5	69.1	0.1	16.3			0.2	163.0	189.3	189.3	4.91	5.43			0.000	0.000	8.04	6.49	28.62	1388	34.4352914	-118.6463292	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Pneumatic Pump Installed	
CV-2558-PLR	9/9/2026 1:10:00 PM					2150																			AtmAA
CV-2558-PLR	9/15/2026 2:10:00 PM					600																			AtmAA
CV-2558-PLR	9/15/2026 2:11:15 PM	15.3	79.8	0.0	4.9			0.2	0.0	191.8	191.4	3.61	3.00			0.000	0.000	0.13	0.21	28.49	1391	34.4352955	-118.6463191	Valve Adjustment: High Temp, Positive Static Press., Valve 100% Open, Surging Liquid in Header, Surging Liquid in Well (Watered In)	
CV-2558-PLR	9/23/2026 8:35:00 AM					452.5																			AtmAA
CV-2558-PLR	9/23/2026 8:42:47 AM	13.3	81.9	0.0	4.8			0.2	0.0	186.0	186.0	1.80	1.79			0.000	0.000	-0.03	-0.15	28.46	1386	34.4352957	-118.6463184	Valve Adjustment: No Flow Measurement, High Temp, Positive Static Press., Valve 100% Open; Well Condition: Pneumatic Pump Installed	
CV-2558-PLR	9/29/2026 2:05:00 PM					1700																			AtmAA
CV-2558-PLR	9/29/2026 2:07:13 PM	17.2	78.5	0.0	4.3			0.2	0.0	201.2	201.2	1.00	1.05			0.000	0.000	-0.15	-0.15	28.27	1390	34.4352908	-118.6463089	Valve Adjustment: No Flow Measurement, High Temp, Valve 100% Open, Surging Liquid in Header; Well Condition: Lorentz Pump Installed	
CV-2559	9/14/2026 1:31:45 PM	10.3	89.7	0.0	0.0			0.1	0.0	120.2	120.2	-1.02	-0.79	0.0	0.0	-0.889	-0.591	-4.34		28.4	1355	34.4357713	-118.6455095		
CV-2559	9/22/2026 9:49:02 AM	12.3	77.9	0.1	9.7			0.2	97.0	131.4	131.8	-1.39	-1.34			1.391	1.336	-4.63	-4.48	28.51	1388	34.4357428	-118.6454868	Valve Adjustment: High Temp, Barely Open	
CV-2560	9/3/2026 9:21:28 AM	9.1	85.3	0.0	5.6			0.1	0.0	135.0	134.2	-0.24	-0.21			0.237	0.194	-6.40	-6.34	28.52	1391	34.4358958	-118.6466598	Valve Adjustment: High Temp, Barely Open	
CV-2560	9/22/2026 10:49:07 AM	14.0	70.0	0.2	15.8			0.2	79.0	137.3	137.3	-1.05	-1.05			1.023	1.037	-9.82	-9.57	28.49	1394	34.4359138	-118.6466578	Valve Adjustment: High Temp, Barely Open	
CV-2561	9/3/2026 9:41:08 AM	12.9	42.3	0.6	44.2			0.3	73.7	118.0	118.0	-0.49	-0.48			0.474	0.462	-3.49	-3.51	28.52	1376	34.4360748	-118.6466135	Valve Adjustment: Barely Open	
CV-2561	9/25/2026 2:14:35 PM	12.9	46.8	0.3	40.0			0.3	133.3	110.0	110.0	-0.22	-0.22			0.215	0.195	-2.12	-2.10	28.44	1394	34.4360888	-118.6466068	Valve Adjustment: Barely Open	
CV-2562	9/14/2026 1:42:18 PM	30.2	69.8	0.0	0.0			0.4	0.0	129.2	129.3	-0.17	-0.19	7.7	7.8	0.089	0.090	-3.07		28.4	1306	34.4361413	-118.6459982		
CV-2563	9/23/2026 8:42:14 AM	38.8	53.8	0.2	7.2			0.7	36.0	116.3	113.2	-4.76	-4.11			0.183	0.076	-9.54	-9.74	28.6	1313	34.4373045	-118.6457717	Valve Adjustment: Audible Flow, Decreased Flow/Vacuum; Well Comment: No OP	
CV-2564	9/1/2026 10:33:16 AM	30.6	58.0	0.0	11.4			0.5	0.0	103.9	103.9	-1.59	-1.00	0.0	0.0	1.561	0.962	-10.05		28.6	1289	34.4331910	-118.6487370		
CV-2564	9/17/2026 10:06:15 AM	39.7	54.3	0.1	5.9			0.7	59.0	120.1	120.0	-4.47	-4.28			4.462	4.283	-11.41	-9.61	28.71	1347	34.4331303	-118.6487315	Valve Adjustment: Decreased Flow/Vacuum, Barely Open	
CV-2565	9/1/2026 11:35:08 AM	38.3	42.2	0.0	19.5			0.9	0.0	101.4	101.4	-0.20	-0.20	0.0	0.0	0.228	0.223	-10.53		28.62	1293	34.4320288	-118.6489437		
CV-2565	9/4/2026 1:22:35 PM	43.9	41.2	0.0	14.9			1.1	0.0	103.7	103.4	-0.15	-0.28			0.141	0.267	-8.70	-8.70	28.57	1326	34.4319940	-118.6489847	Valve Adjustment: Increased Flow/Vacuum	
CV-2565	9/30/2026 11:33:22 AM	41.8	43.0	0.0	15.2			1.0	0.0	120.4	120.3	-0.18	-0.18			0.174	0.174	-3.29	-3.31	28.55	1338	34.4319660	-118.6489923	Valve Adjustment: Reduce Sys. Vac. - Flare Down	
CV-2566	9/1/2026 11:33:06 AM	43.7	43.6	0.0	12.7			1.0	0.0	102.1	102.3	-2.56	-2.56	0.0	0.0	2.656	2.647	-9.58		28.62	1342	34.4318257	-118.6487872		
CV-2566	9/21/2026 11:57:56 AM	48.5	44.8	0.0	6.7			1.1	0.0	117.0	117.4	-3.25	-3.04			3.191	2.988	-10.81	-10.81	28.67	1331	34.4317940	-118.6487693	Valve Adjustment: Decreased Flow/Vacuum	
CV-2567	9/1/2026 1:52:22 PM	51.1	41.0	0.1	7.8			1.2	78.0	104.3	104.4	-1.52	-1.52	0.0	0.0	1.548	1.545	-9.22		28.58	1319	34.4319495	-118.6479698		
CV-2567	9/21/2026 12:33:36 PM	50.0	44.3	0.0	5.7			1.1	0.0	115.9	116.3	-2.42	-2.41			2.377	2.364	-10.81	-10.60	28.65	1350	34.4319712	-118.6481002	Valve Adjustment: Audible Flow	
CV-2568	9/1/2026 2:47:30 PM	41.4	39.9	0.0	18.7			1.0	0.0	97.3	97.3	-2.83	-2.84	0.0	0.0	2.876	2.777	-5.30		28.56	1371	34.4322285	-118.6477988		

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [\"H2O]	Adj Stat Press [\"H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [\"H2O]	Adj Diff Press [\"H2O]	Sys Pressure [\"H2O]	Adj Avail Press [\"H2O]	Baro Press [\"Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2568	9/3/2026 11:10:53 AM	42.5	45.7	0.0	11.8			0.9	0.0	107.7	107.8	-2.16	-2.36			2.184	2.363	-6.01	-5.97	28.58	1358	34.4321577	-118.6477598	Valve Adjustment:Increased Flow/Vacuum,Barely Open
CV-2568	9/22/2026 3:09:14 PM	38.7	43.3	0.0	18.0			0.9	0.0	101.7	101.7	-0.50	-0.51			0.506	0.511	-9.01	-8.88	28.44	1348	34.4321603	-118.6477297	Valve Adjustment:Barely Open
CV-2569	9/1/2026 2:37:13 PM	45.7	45.7	0.0	8.6			1.0	0.0	97.2	97.3	-0.16	-0.16	0.0	0.0	0.227	0.211	-5.30		28.57	1322	34.4322047	-118.6474113	
CV-2569	9/24/2026 12:16:37 PM	41.5	45.6	0.0	12.9			0.9	0.0	116.7	116.8	-1.64	-1.64			1.610	1.611	-10.08	-10.07	28.63	1344	34.4322192	-118.6473983	Valve Adjustment:Audible Flow
CV-2570	9/1/2026 2:13:36 PM	52.1	42.4	0.0	5.5			1.2	0.0	97.1	97.3	-0.71	-0.69	0.0	0.0	0.618	0.613	-5.46		28.58	1296	34.4326718	-118.6471275	
CV-2570	9/30/2026 1:55:05 PM	52.7	42.8	0.0	4.5			1.2	0.0	119.5	119.5	-0.16	-0.15			0.155	0.152	-3.61	-3.24	28.52	1357	34.4324270	-118.6469898	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-2571	9/2/2026 10:53:10 AM	54.1	38.5	0.0	7.4			1.4	0.0	97.3	97.3	-9.07	-9.31	27.8	29.6	2.037	2.320	-14.26	-14.11	28.93	1140	34.4299500	-118.6457250	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-2572	9/30/2026 10:38:28 AM	54.6	43.3	0.0	2.1			1.3	0.0	123.0	122.9	-0.31	-0.30	27.6	27.1	0.992	0.961	-1.23	-1.14	28.67	1135	34.4297853	-118.6470640	Valve Adjustment:Barely Open
CV-2602	9/28/2026 9:13:58 AM	48.4	40.7	0.0	10.9			1.2	0.0	112.1	112.3	-4.86	-4.73	57.7	55.2	4.339	3.980	-10.40	-9.74	28.67	1148	34.4284570	-118.6497975	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-2603	9/17/2026 1:31:00 PM	49.0	41.4	0.0	9.6			1.2	0.0	122.3	122.3	-1.43	-1.38	19.7	19.5	8.291	8.139	-13.26	-13.06	28.91	1128	34.4283382	-118.6487775	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-2603	9/17/2026 1:35:30 PM	48.4	41.3	0.0	10.3			1.2	0.0	123.0	122.9	-1.99	-1.69	29.0	23.1	1.956	1.238	-13.61	-13.32	28.91	1130	34.4283543	-118.6487698	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
CV-2603	9/17/2026 1:37:32 PM	48.4	41.9	0.0	9.7			1.2	0.0	122.9	122.8	-1.63	-1.60	22.6	22.1	1.190	1.138	-12.51	-12.51	28.9	1123	34.4283613	-118.6487997	
CV-2605	9/30/2026 9:04:23 AM	46.1	42.0	0.0	11.9			1.1	0.0	129.1	129.4	-0.28	-0.28	5.9	6.2	0.753	0.816	-1.36	-1.36	28.71	1103	34.4275312	-118.6489412	Valve Adjustment:Barely Open
CV-2606	9/17/2026 1:17:22 PM	53.3	41.4	0.0	5.4			1.3	0.0	123.9	123.9	-0.94	-0.92	14.1	14.1	4.252	4.239	-15.62	-15.39	28.91	1143	34.4288927	-118.6484607	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-2606	9/17/2026 1:22:30 PM	53.2	41.6	0.0	5.2			1.3	0.0	124.3	124.3	-1.05	-1.10	15.3	16.1	0.545	0.605	-15.48	-15.53	28.91	1150	34.4289073	-118.6484578	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
CV-2606	9/17/2026 1:24:50 PM	52.2	42.2	0.0	5.6			1.2	0.0	124.3	124.3	-1.13	-1.13	15.7	15.9	0.570	0.585	-15.18	-16.15	28.91	1145	34.4289225	-118.6484590	
CV-2608	9/21/2026 9:33:42 AM	53.6	41.2	0.0	5.2			1.3	0.0	88.4	114.7	1.08	0.41	1.0	9.0	0.018	1.695	-6.55	-6.59	28.79	1146	34.4293738	-118.6480595	Valve Adjustment:NSPS/EG CAI,Increased Flow/Vacuum
CV-2608	9/21/2026 9:44:28 AM	53.3	41.9	0.0	4.8			1.3	0.0	120.2	123.1	0.25	-0.10	9.1	14.8	0.190	0.509	-6.05	-6.19	28.79	1141	34.4293493	-118.6480658	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Orifice Plate Changed (See OP Log),Positive Static Press.,Increased Flow/Vacuum
CV-2610	9/9/2026 10:26:51 AM	56.0	40.7	0.0	3.3			1.4	0.0	116.6	116.6	-0.79	-0.94	16.6	20.5	1.732	2.652	-13.13	-12.99	28.87	1132	34.4298355	-118.6465565	Valve Adjustment:increased Flow/Vacuum
CV-2610	9/9/2026 10:27:56 AM	54.9	40.6	0.0	4.4			1.4	0.0	116.7	116.7	-1.02	-1.02	20.0	20.3	2.525	2.611	-10.93	-12.33	28.86	1133	34.4298245	-118.6465593	
CV-2611	9/25/2026 8:33:59 AM	58.6	39.4	0.0	2.0			1.5	0.0	99.7	101.4	0.82	-0.25	4.3	10.2	0.376	2.128	-13.83	-12.67	28.76	1154	34.4303475	-118.6459120	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Surging Liquid in Header
CV-2611	9/25/2026 8:35:07 AM	57.0	39.5	0.0	3.4			1.4	0.0	101.8	101.9	-0.50	-0.51	10.1	10.3	2.094	2.158	-13.24	-13.34	28.79	1163	34.4303600	-118.6459287	Valve Adjustment:NSPS/EG CAC
CV-2612	9/23/2026 10:24:54 AM	56.0	42.9	0.0	1.1			1.3	0.0	105.9	106.6	0.86	0.88	2.9	2.6	0.023	0.018	1.00	1.00	28.62	1258	34.4311688	-118.6470948	
CV-2613	9/23/2026 9:13:04 AM	53.0	41.1	0.0	5.9			1.3	0.0	105.4		0.05		7.5		1.150		-16.74		28.6	1266	34.4306163	-118.6480082	Valve Adjustment:NSPS/EG CAI,Increased Flow/Vacuum
CV-2613	9/23/2026 9:20:54 AM	52.9	41.1	0.0	6.1			1.3	0.0	106.4	108.7	0.03	-0.16	7.2	14.8	0.117	0.501	-14.92	-11.74	28.6	1265	34.4306058	-118.6479975	Valve Adjustment:NSPS/EG CAC,Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
CV-2613	9/23/2026 9:28:02 AM	55.1	40.4	0.0	4.5			1.4	0.0	109.1	109.2	-0.19	-0.19	15.4	15.1	0.541	0.521	-11.95	-11.41	28.6	1270	34.4306265	-118.6480000	
CV-2613	9/23/2026 9:45:38 AM	54.6	40.3	0.0	5.1			1.4	0.0	108.6	109.3	-0.17	-0.16	15.6	15.4	0.553	0.538	-13.27	-12.92	28.61	1264	34.4306175	-118.6480067	
CV-2614	9/21/2026 12:45:34 PM	53.2	42.1	0.0	4.7			1.3	0.0	124.7	124.6	0.57	0.54	9.7	10.8	2.026	2.467	-17.54	-16.66	28.65	1267	34.4305132	-118.6484738	Valve Adjustment:NSPS/EG CAI,Orifice Plate Changed (See OP Log),Reconnected this Date,Positive Static Press.,Increased Flow/Vacuum
CV-2614	9/21/2026 12:51:30 PM	54.1	41.1	0.0	4.8			1.3	0.0	125.0	125.7	0.51	-0.43	3.2	8.7	0.222	1.608	-15.28	-16.87	28.68	1269	34.4305338	-118.6484800	Valve Adjustment:NSPS/EG CAC,Orifice Plate Changed (See OP Log),Positive Static Press.,Increased Flow/Vacuum
CV-2614	9/21/2026 12:53:19 PM	52.8	42.4	0.0	4.8			1.2	0.0	125.8	125.9	-0.54	-0.57	8.6	8.7	1.577	1.635	-16.72	-17.33	28.67	1262	34.4305240	-118.6484760	
CV-2615	9/21/2026 12:14:18 PM	46.8	44.2	0.0	9.0			1.1	0.0	108.6	108.6	-0.51	-0.51	27.4	27.5	0.962	0.964	-10.71	-10.51	28.61	1300	34.4312343	-118.6492985	Valve Adjustment:Orifice Plate Changed (See OP Log),Reconnected this Date
CV-2615	9/21/2026 12:17:00 PM	45.8	45.7	0.0	8.5			1.0	0.0	109.1	108.5	-0.51	-0.43	27.5	20.4	0.965	0.531	-10.74	-10.97	28.61	1307	34.4312255	-118.6492823	Valve Adjustment:Decreased Flow/Vacuum
CV-2615	9/21/2026 12:18:55 PM	45.4	45.9	0.0	8.7			1.0	0.0	108.1	108.0	-0.41	-0.40	19.7	20.0	0.493	0.507	-10.47	-10.68	28.62	1312	34.4312255	-118.6492940	
CV-2627	9/11/2026 8:23:45 AM	58.8	38.6	0.0	2.6			1.5	0.0	113.0	113.2	-0.41	-0.85	7.5	9.5	0.350	0.568	-4.52	-4.06	28.69	1188	34.4310297	-118.6461986	Valve Adjustment:Increased Flow/Vacuum
CV-2634	9/4/2026 7:30:48 AM	1.0	2.3	20.8	76.0			0.5	3.7	68.2	68.3	-1.74	-1.80	13.9	14.3	3.753	3.965	-1.64	-1.74	28.64	1215	34.4313887	-118.6454587	Valve Adjustment:Increased Flow/Vacuum
CV-2634	9/11/2026 8:16:30 AM	1.1	5.1	20.5	73.3			0.2	3.6	88.8	89.5	-3.70	-3.78	16.3	16.4	5.380	5.469	-3.86	-3.92	28.67	1209	34.4313936	-118.6454759	Valve Adjustment:NSPS/EG CAI,High O2,Increased Flow/Vacuum,Valve 100% Open
CV-2634	9/23/2026 1:07:00 PM	2.1	7.1	20.4	70.4			0.3	3.5	106.1	107.1	0.33	0.21	3.5	4.4	0.258	0.405	0.64	0.50	28.7	1212	34.4313947	-118.6454755	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Valve 100% Open

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [″H2O]	Adj Stat Press [″H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [″H2O]	Adj Diff Press [″H2O]	Sys Pressure [″H2O]	Adj Avail Press [″H2O]	Baro Press [″Hg]	Elev [ft]	Latitude	Longitude	Comments
CV-2634	9/24/2026 2:13:35 PM						1000																	[User entered 0.1%]
CV-2634	9/24/2026 2:14:26 PM	1.1	2.7	20.1	76.1			0.4	3.8	102.0	102.1	-6.61	-6.36	0.8	0.8	0.014	0.014	-6.79	-6.56	28.68	1205	34.4313813	-118.6454902	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-2634	9/24/2026 2:25:00 PM					15.8																		AtmAA [24 TAT Request]
CV-2634	9/24/2026 2:25:00 PM						1000																	AtmAA [24 TAT Request]
CV-2634	9/24/2026 2:58:48 PM					30																		<0.10; [User entered 0.10%]
CV-2634	9/24/2026 2:58:48 PM					30																		
CV-2634	9/24/2026 2:58:48 PM					30																		
																								valve Adjustment:Orifice Plate Changed (See OP Log),Reconnecte this Date,Surging Liquid in Well (Watered In);Well Comment:Wellhead remoted up slope
CV-2638	9/27/2026 11:47:09 AM	18.0	52.3	0.0	29.7			0.3	0.0	104.4	104.5	-12.40	-12.76	1.7	1.3	0.059	0.034	-13.45	-13.33	28.53	1361	34.4363957	-118.6436468	Valve Adjustment:Barely Open
CV-2663	9/28/2026 1:50:21 PM	25.6	55.1	0.1	19.2			0.5	192.0	143.1	143.2	-0.26	-0.27	8.0	11.4	0.086	0.178	-13.37	-16.86	28.37	1323	34.4350605	-118.6433293	Valve Adjustment:Barely Open
CV-2676	9/1/2026 8:50:09 AM	15.0	74.6	0.0	10.4			0.2	0.0	128.4	130.6	-0.17	-0.17			0.157	0.162	-16.48	-16.80	28.63	1319	34.4336153	-118.6434693	Valve Adjustment:Barely Open
																								Valve Adjustment:NSPS/EG CAC,Orifice Plate Changed (See OP Log),High Temp,Decreased Flow/Vacuum,Barely Open;Well Comment:Changed OP from 0.75 to 0.50;Well Condition:Pnumatic Pump Installed
CV-2680	9/16/2026 11:27:44 AM	41.8	40.6	0.1	17.5			1.0	175.0	132.4	122.6	-6.00	-4.59	26.3	34.7	4.571	7.828	-24.33	-24.14	28.78	1288	34.4353972	-118.6421087	Valve Adjustment:NSPS/EG CAC
CV-2680	9/16/2026 11:30:13 AM	38.5	40.6	0.5	20.4			0.9	40.8	125.8	125.9	-4.63	-4.63	8.5	8.4	8.106	7.987	-24.10	-24.04	28.78	1282	34.4353872	-118.6421277	Valve Adjustment:NSPS/EG CAC
CV-2680	9/22/2026 2:55:28 PM	39.9	44.0	0.0	16.1			0.9	0.0	129.1	128.7	-2.22	-2.02	17.4	16.2	6.627	5.686	-19.10		28.52	1257	34.4354220	-118.6420105	
CV-2681	9/22/2026 3:00:45 PM	14.0	42.9	0.0	43.1			0.3	0.0	94.2	94.5	1.01	-0.46		19.6	-0.697	0.391			28.52	1253	34.4353228	-118.6426775	
CV-2681	9/22/2026 3:01:29 PM	13.0	44.8	0.0	42.2			0.3	0.0	94.6	94.6	-0.37	-0.36	20.8	20.8	0.443	0.444			28.52	1289	34.4352577	-118.6426147	
CV-2683	9/22/2026 3:21:53 PM	24.6	44.1	0.0	31.3			0.6	0.0	96.9	96.9	-6.45	-5.76	5.4	4.7	0.032	0.024			28.52	1332	34.4346575	-118.6423535	
CV-2684	9/28/2026 2:31:31 PM	28.8	36.1	0.1	35.0			0.8	350.0	125.7	116.6	-13.86	-8.97	69.0	56.9	13.930	9.115	-19.07	-20.96	28.42	1256	34.4342220	-118.6422342	Valve Adjustment:Decreased Flow/Vacuum
CV-2687	9/9/2026 1:20:38 PM	49.4	40.2	0.0	10.4			1.2	0.0	124.6	124.6	-2.23	-2.23	0.9	0.9	0.019	0.018	-18.36	-19.13	28.75	1251	34.4335957	-118.6415808	
CV-2688	9/4/2026 8:25:47 AM	55.7	41.3	0.0	3.0			1.3	0.0	121.1	122.8	1.22	-0.71	5.6	12.7	0.196	1.030	-13.01	-18.08	28.68	1217	34.4327100	-118.6424180	Valve Adjustment:Increased Flow/Vacuum
CV-2688	9/18/2026 3:17:08 PM	55.3	44.7	0.0	0.0			1.2	0.0	124.3	123.3	-4.37	-2.37	13.1	8.2	1.110	0.433	-20.35	-20.61	28.71	1229	34.4327417	-118.6423970	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum
CV-2689	9/28/2026 3:05:38 PM	0.9	60.7	1.4	37.0			0.0	26.4	104.8	104.9	-9.39	-9.38			9.479	9.479	-13.72	-13.80	28.45	1223	34.4328413	-118.6433908	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2689	9/30/2026 11:55:35 AM						282000																	[User entered 28.2%]
CV-2689	9/30/2026 11:59:55 AM	0.8	61.1	0.0	38.1			0.0	0.0	121.3	122.7	-4.98	-9.18			5.093	9.278	-9.56	-9.14	28.56	1218	34.4328272	-118.6433742	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-2689	9/30/2026 12:01:28 PM	0.9	60.8	0.0	38.4			0.0	0.0	122.2	122.2	-9.55	-9.58			9.630	9.708	-9.54	-9.64	28.57	1249	34.4328153	-118.6433878	
CV-2690	9/4/2026 8:32:48 AM	54.4	41.4	0.0	4.2			1.3	0.0	120.8	121.0	-16.79	-17.12	3.6	3.6	0.286	0.292	-21.32	-21.12	28.68	1257	34.4323567	-118.6428787	Valve Adjustment:Increased Flow/Vacuum
CV-2691	9/28/2026 7:44:15 AM	55.8	40.2	0.0	4.0			1.4	0.0	125.7	125.8	-3.50	-3.65	17.5	19.1	1.997	2.379	-20.67	-20.81	28.63	1214	34.4321097	-118.6431822	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-2692	9/4/2026 7:43:29 AM	55.9	41.0	0.0	3.2			1.4	315.0	127.0	127.0	1.05	-0.39	26.7	36.1	0.935	1.715	-16.09	-13.52	28.67	1213	34.4316470	-118.6444830	Valve Adjustment:Increased Flow/Vacuum
CV-2692	9/18/2026 3:35:46 PM	54.9	42.2	0.0	2.9			1.3	0.0	127.2	127.3	-2.75	-2.72	35.3	35.5	1.648	1.673	-13.36	-13.59	28.71	1218	34.4316240	-118.6444675	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2695	9/16/2026 1:56:22 PM	54.5	41.8	0.0	3.7			1.3	0.0	114.4	114.5	-0.71	-0.72	11.9	12.8	0.897	1.028	-20.75	-19.37	28.77	1181	34.4288608	-118.6501575	Valve Adjustment:Increased Flow/Vacuum
CV-2695	9/16/2026 2:05:21 PM	53.9	42.1	0.0	4.0			1.3	0.0	114.4	114.9	-0.87	-1.44	6.3	9.3	0.247	0.542	-21.48	-19.94	28.76	1170	34.4288637	-118.6501745	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
CV-2695	9/16/2026 2:07:07 PM	53.3	42.9	0.0	3.8			1.2	0.0	114.9	114.9	-1.53	-1.49	9.6	9.0	0.575	0.507	-21.66	-19.08	28.77	1196	34.4288828	-118.6501817	
CV-48R	9/23/2026 8:32:14 AM	52.1	43.7	0.0	4.2			1.2	0.0	120.9	121.4	-7.38	-8.04	4.8	4.5	0.148	0.133	-9.72	-9.61	28.59	1307	34.4373335	-118.6458563	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-52D	9/22/2026 2:41:30 PM	31.1	51.8	0.0	17.1			0.6	0.0	102.6	99.2	-6.74	-6.73	1.2	1.2	0.435	0.434	-18.63		28.5	1270	34.4359503	-118.6424648	
CV-55R	9/2/2026 2:12:41 PM	29.9	55.0	0.0	15.1			0.5	0.0	151.6	151.4	-4.85	-4.87	4.2	2.9	0.120	0.057	-11.93	-12.04	28.64	1320	34.4343831	-118.6427878	Valve Adjustment:High Temp,Well Condition:Lorentz Pump Installed
CV-55R	9/2/2026 2:15:00 PM					425																		AtmAA
CV-55R	9/2/2026 2:15:00 PM					169000																		AtmAA; [User entered 16.9%]
CV-55R	9/10/2026 9:19:10 AM	37.5	49.3	0.1	13.1			0.8	131.0	152.4	152.5	-5.23	-5.21	4.5	3.8	0.140	0.100	-12.73	-12.97	28.64	1317	34.4343693	-118.6427642	Valve Adjustment:High Temp,Well Condition:Lorentz Pump Installed
CV-55R	9/10/2026 9:21:00 AM					207																		AtmAA
CV-55R	9/11/2026 9:33:09 AM	30.2	46.9	0.0	22.9			0.6	0.0	152.9	152.8	-5.63	-5.60	9.7	9.8	0.647	0.662	-14.41	-14.65	28.57	1302	34.4343857	-118.6427807	
CV-55R	9/17/2026 10:30:20 AM	35.1	43.8	0.0	21.1			0.8	0.0	150.8	151.0	-7.45	-7.41	1.7	3.6	0.019	0.089	-19.71	-18.40	28.78	1302	34.4343810	-118.6427784	Valve Adjustment:High O2,Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [\"H2O]	Adj Stat Press [\"H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [\"H2O]	Adj Diff Press [\"H2O]	Sys Pressure [\"H2O]	Adj Avail Press [\"H2O]	Baro Press [\"Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
CV-55R	9/17/2026 10:33:00 AM					440																		AtmAA
CV-55R	9/24/2026 2:26:00 PM	37.9	50.0	0.0	12.1			0.8	0.0	151.8	151.4	-5.73	-5.73	5.5	4.8	0.209	0.158	-15.44	-15.26	28.54	1322	34.4343653	-118.6427891	Valve Adjustment:No Flow Measurement,High Temp,Well Condition:Lorentz Pump Installed
CV-55R	9/24/2026 2:30:00 PM					249																		AtmAA
CV-56D	9/1/2026 8:36:44 AM	36.7	36.0	0.9	26.4			1.0	29.3	117.8	117.7	-3.10	-2.92	22.6	21.1	10.985	9.546	-16.72	-16.73	28.63	1311	34.4337917	-118.6431812	Valve Adjustment:Decreased Flow/Vacuum
CV-56S	9/1/2026 8:31:46 AM	26.4	17.3	4.5	51.8			1.5	11.5	110.9	110.8	-3.53	-3.11	1.7	1.1	0.728	0.302	-16.84	-16.84	28.63	1320	34.4337888	-118.6431718	Valve Adjustment:Decreased Flow/Vacuum
CV-57R	9/1/2026 10:13:04 AM	47.3	38.5	0.0	14.2			1.2	0.0	105.2	105.4	-0.58	-0.59	0.4	1.3	0.003	0.032	-12.78	-12.85	28.6	1336	34.4343207	-118.6435575	Valve Adjustment:Barely Open
CV-79R	9/1/2026 9:35:58 AM	51.3	45.7	0.0	3.0			1.1	0.0	136.8	136.5	-8.88	-7.05	7.4	5.6	0.134	0.075	-16.74	-16.91	28.63	1336	34.4332422	-118.6448520	Valve Adjustment:Decreased Flow/Vacuum
CV-79R	9/1/2026 9:37:09 AM	51.0	45.5	0.0	3.5			1.1	0.0	135.8	135.9	-5.28	-5.11	0.8	3.1	0.002	0.023	-16.78	-16.92	28.61	1341	34.4332420	-118.6448542	Temp,Decreased Flow/Vacuum
CV-94	9/22/2026 10:04:47 AM	50.1	40.5	0.0	9.4			1.2	0.0	112.3	112.5	-7.74	-7.74	1.3	1.5	0.011	0.013	-17.85		28.57	1322	34.4348150	-118.6437323	
CV-95	9/1/2026 10:09:59 AM	35.7	29.3	2.0	33.0			1.2	16.5	91.6	91.7	-0.19	-0.18	1.0	0.7	0.018	0.011	-15.01	-15.15	28.6	1344	34.4343058	-118.6436020	Valve Adjustment:Barely Open
CV-99	9/4/2026 7:05:00 AM					900																		AirTech Lab
CV-99	9/4/2026 7:05:00 AM						64000																	AirTech Lab; [User entered 6.4%]
CV-99	9/14/2026 9:15:48 AM	3.0	6.5	17.8	72.7			0.5	4.1	85.9	86.7	-9.69	-10.08	4.2	1.7	0.366	0.062	-9.91	-10.14	28.59	1323	34.4370603	-118.6463192	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
CV-99	9/14/2026 9:19:46 AM	31.6	48.3	3.5	16.6			0.7	4.7	88.0	88.3	-2.53	-2.53	2.6	2.7	0.139	0.144	-10.25	-10.45	28.58	1304	34.4370568	-118.6463197	Valve Adjustment:NSPS/EG CAC
CV-99	9/25/2026 10:42:18 AM	40.9	54.1	0.3	4.7			0.8	15.7	105.0	98.8	-0.47	-0.67	5.4	5.3	0.592	0.582	-12.91	-12.90	28.58	1311	34.4370470	-118.6463417	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
D-02	9/25/2026 9:39:15 AM	60.3	38.0	0.0	1.7			1.6	0.0	88.8	89.1	3.09	3.09	5.5	6.3	0.037	0.047	3.31	3.26	28.75	1175	34.4311670	-118.6442888	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Header
D-02	9/28/2026 12:45:58 PM	58.7	38.4	0.0	2.9			1.5	0.0	92.8	92.6	3.69	-15.39	3.7	2.9	0.016	0.011	3.78	-15.44	28.61	1174	34.4311728	-118.6442900	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
D-02	9/28/2026 12:48:09 PM	56.6	40.4	0.0	3.1			1.4	0.0	92.3	92.3	-15.36	-15.37	4.2	5.6	0.023	0.040	-15.41	-15.42	28.61	1175	34.4311653	-118.6443002	Valve Adjustment:Valve 100% Open,Reduce Sys. Vac. - Flare Down
D-03	9/2/2026 10:11:51 AM	51.6	36.6	1.7	10.1			1.4	5.8	99.5	99.6	-0.76	-0.75	3.0	2.5	0.011	0.008	-0.78	-0.83	28.82	1164	34.4311717	-118.6442877	Valve Adjustment:NSPS/EG CAC
D-04	9/25/2026 9:43:51 AM	50.4	38.0	0.7	10.8			1.3	14.6	89.4	89.5	-21.01	-20.65	7.1	6.3	0.064	0.051	-20.28	-20.89	28.76	1173	34.4311817	-118.6442882	
D-09	9/25/2026 8:39:40 AM	55.8	40.0	0.0	4.2			1.4	0.0	115.5	115.6	-10.91	-11.08	26.2	28.1	0.910	1.043	-12.04	-11.93	28.78	1147	34.4301047	-118.6463198	Valve Adjustment:Increased Flow/Vacuum
D-10	9/2/2026 10:47:58 AM	54.5	40.0	0.3	5.2			1.4	17.3	102.9	103.0	-13.15	-13.13	1.7	1.3	0.018	0.011	-14.52	-14.47	28.91	1144	34.4302038	-118.6458290	Valve Adjustment:Audible Flow
FP-001	9/9/2026 11:56:26 AM	27.2	24.2	3.6	45.0			1.1	12.5	114.6	114.6	-0.21	-0.19	8.0	8.0	0.401	0.405	-11.73	-11.30	28.63	1348	34.4365950	-118.6458458	
FP-002	9/9/2026 11:59:58 AM	26.5	24.5	4.4	44.6			1.1	10.1	114.6	114.6	-0.14	-0.13	16.7	14.7	5.891	4.564	-6.78	-5.15	28.6	1343	34.4366248	-118.6462108	
FP-003	9/9/2026 12:04:20 PM	45.5	44.9	1.5	8.1			1.0	5.4	114.6	114.6	-0.10	-0.09	2.3	2.3	0.572	0.571	-7.68	-7.46	28.63	1348	34.4366082	-118.6465073	
FP-005	9/25/2026 10:01:13 AM	0.1	2.7	18.5	78.7			0.0	4.3	89.1	89.2	-0.91	-0.86	5.5	5.4	3.140	3.081	-9.87	-9.43	28.52	1354	34.4364653	-118.6472745	
FP-006	9/9/2026 10:42:38 AM	21.8	65.9	0.4	11.9			0.3	29.8	107.1	107.4	-1.08	-1.07	0.6	1.0	0.008	0.019	-3.70	-4.06	28.64	1360	34.4363740	-118.6476428	
FP-008	9/9/2026 10:51:01 AM	4.6	33.3	9.9	52.2			0.1	5.3	108.4	108.3	-2.08	-2.04	0.2	0.2	0.012	0.006	-5.55	-5.05	28.64	1351	34.4363288	-118.6481510	
FP-009	9/9/2026 10:56:29 AM	15.4	66.8	1.6	16.2			0.2	10.1	114.2	114.2	-0.81	-0.81	3.6	3.4	0.278	0.249	-5.47	-5.51	28.62	1363	34.4366898	-118.6489068	Valve Adjustment:Barely Open
FP-010	9/9/2026 11:00:51 AM	19.9	76.3	0.6	3.2			0.3	5.3	120.9	120.9	-0.57	-0.65	10.5	10.7	2.349	2.422	-5.36	-5.56	28.63	1370	34.4366332	-118.6492395	Valve Adjustment:Barely Open
FP-011	9/9/2026 11:03:30 AM	24.9	35.6	6.9	32.6			0.7	4.7	96.1	96.4	-0.60	-0.67	2.3	2.6	0.107	0.141	-4.04	-5.43	28.63	1360	34.4365443	-118.6494752	Valve Adjustment:Barely Open
FP-012	9/1/2026 11:45:24 AM	0.7	4.7	19.0	75.6			0.1	4.0	95.6	95.8	-0.17	-0.17	0.3	0.3	0.002	0.002	-11.02	-10.66	28.67	1375	34.4366542	-118.6498983	
FP-013	9/1/2026 11:33:24 AM	2.4	6.0	17.1	74.5			0.4	4.4	95.5	95.5	-0.38	-0.38	13.5	13.5	3.700	3.698	-10.71	-10.72	28.67	1376	34.4365747	-118.6502460	
FP-014	9/25/2026 10:20:20 AM	4.5	35.5	10.1	49.9			0.1	4.9	112.4	112.5	-3.28	-3.23	6.6	6.6	4.697	4.712	-7.83	-7.87	28.56	1358	34.4364813	-118.6482293	Valve Adjustment:Barely Open
FP-015	9/9/2026 10:36:14 AM	0.3	0.7	19.3	79.7			0.4	4.1	114.6	114.7	-1.96	-1.97	0.6	0.7	0.008	0.009	-4.07	-4.38	28.64	1358	34.4363940	-118.6479208	Valve Adjustment:Barely Open
FP-016	9/9/2026 10:39:37 AM	0.3	0.4	19.3	80.0			0.8	4.1	108.9	109.5	-1.03	-1.04	0.2	0.2	0.006	0.011	-4.14	-4.38	28.64	1350	34.4364775	-118.6476588	
FP-017	9/14/2026 11:00:20 AM	54.4	35.0	2.4	8.2			1.6	3.4	98.8	98.6	-0.28	-0.27	0.4	0.4	0.003	0.003	-0.23		28.51	1339	34.4343250	-118.6486857	Increased Flow/Vacuum,
FP-018	9/1/2026 2:40:24 PM	50.4	38.9	0.6	10.1			1.3	16.8	96.1	96.1	-3.53	-3.37	7.4	6.7	1.135	0.928	-6.29	-6.30	28.56	1324	34.4344613	-118.6491045	
FP-019	9/1/2026 2:44:17 PM	54.4	43.5	0.1	2.0			1.3	20.0	95.1	95.2	-0.33	-0.28	2.4	2.6	0.117	0.133	-6.46	-6.24	28.56	1332	34.4346722	-118.6491785	
FP-020	9/14/2026 11:24:45 AM	5.1	10.6	13.8	70.5			0.5	5.1	96.0	96.0	-4.77	-4.77	2.7	2.7	0.145	0.145	-4.62		28.5	1309	34.4350263	-118.6491820	
FP-021	9/14/2026 11:16:23 AM	14.0	28.1	8.7	49.2			0.5	5.7	106.1	106.1	-3.52	-3.54	6.1	6.0	0.790	0.788	-4.49		28.5	1345	34.4352887	-118.6491603	
FP-022	9/14/2026 11:21:00 AM	6.1	26.8	1.1	66.0			0.2	60.0	104.5	104.5	-2.76	-2.76	0.8	0.8	0.014	0.014	-4.99		28.5	1362	34.4352097	-118.6491552	
FP-023	9/3/2026 8:54:48 AM	18.4	45.5	5.2	30.9			0.4	5.9	82.0	82.1	-0.69	-0.69	5.7	5.7	0.654	0.653	-7.18	-7.15	28.63	1346	34.4359968	-118.6496160	
FP-024	9/9/2026 11:18:04 AM	18.9	40.3	6.1	34.7			0.5	5.7	103.4	103.7	-0.32	-0.37	1.3	1.7	0.035	0.057	-4.84	-6.57	28.63	1337	34.4350883	-118.6477695	
FP-025	9/14/2026 10:07:38 AM	6.9	14.1	14.5	64.5			0.5	4.4	95.2	95.3	-1.82	-1.81	0.0	0.0	-0.224	-0.224	-7.26		28.49	1388	34.4353428	-118.6477610	
FP-026	9/14/2026 10:10:15 AM	11.5	23.0	10.7	54.8			0.5	5.1	92.6	92.6	-6.49	-6.49	0.0	0.0	-6.532	-6.536	-6.49		28.49	1348	34.4350197	-118.6480687	
FP-027	9/14/2026 10:53:07 AM	11.9	26.7	8.6	52.8			0.4	6.1	98.7	98.8	-7.18	-7.16	0.0	0.0	-6.995	-7.134	-7.16		28.5	1283	34.4349642	-118.6480655	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [\"H2O]	Adj Stat Press [\"H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [\"H2O]	Adj Diff Press [\"H2O]	Sys Pressure [\"H2O]	Adj Avail Press [\"H2O]	Baro Press [\"Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
FP-027	9/14/2026 2:20:08 PM	13.0	24.9	9.5	52.6			0.5	5.5	97.0	96.9	-0.50	-0.50	5.0	5.0	6.377	6.496	-6.80	-6.84	28.47	1364	34.4348765	-118.6482155	Valve Comment:Riser modified to adapt the well head
FP-027	9/15/2026 10:17:45 AM	1.0	18.6	15.1	65.3			0.1	4.3	93.6	93.7	-0.64	-0.64	4.4	4.4	4.998	4.974	-5.02	-5.29	28.58	1357	34.4348620	-118.6482127	
FP-028	9/14/2026 10:55:24 AM	9.2	10.1	15.7	65.0			0.9	4.1	101.0	101.1	-0.81	-0.79	2.5	2.5	0.122	0.122	-7.72		28.5	1319	34.4346473	-118.6483827	
FP-028	9/15/2026 10:30:36 AM	0.1	2.1	19.7	78.1			0.0	4.0	89.1	89.1	-0.43	-0.35	7.0	2.1	5.033	0.471	-5.60	-5.17	28.58	1357	34.4346723	-118.6482621	Valve Adjustment: NSPS/EG CAI, Reconnected this Date, Decreased Flow/Vacuum
FP-028	9/15/2026 10:31:51 AM	0.0	0.9	20.6	78.5			0.0	3.8	89.5	89.5	-0.34	-0.33	2.1	2.2	0.462	0.482	-5.13	-4.91	28.58	1357	34.4346753	-118.6482583	Valve Adjustment: NSPS/EG CAC
FP-029	9/14/2026 11:04:54 AM	52.2	41.3	0.0	6.5			1.3	0.0	110.3	110.9	-0.03	-0.06	0.0	0.0	-0.458	-0.648	-0.08		28.51	1345	34.4342698	-118.6489275	
FP-029	9/15/2026 10:38:34 AM	13.5	15.2	11.3	60.0			0.9	5.3	91.1	90.9	-0.62	-0.52	12.5	11.1	3.155	2.497	-4.51	-5.26	28.58	1361	34.4345653	-118.6482952	Valve Adjustment: NSPS/EG CAI, Reconnected this Date, Decreased Flow/Vacuum
FP-030	9/1/2026 2:31:04 PM	50.4	40.1	1.2	8.3			1.3	6.9	94.3	94.3	-0.47	-0.45	10.2	10.4	2.126	2.182	-6.36	-6.50	28.56	1336	34.4345195	-118.6497283	
FP-031	9/1/2026 2:28:03 PM	3.9	18.3	17.7	60.1			0.2	3.4	91.9	92.4	-1.14	-1.30	0.2	0.6	0.012	0.089	-6.57	-6.24	28.56	1341	34.4348335	-118.6497830	
FP-031	9/15/2026 2:13:37 AM	13.0	14.3	11.6	61.1			0.9	5.3	90.6	90.6	-0.50	-0.50	10.7	11.1	2.310	2.489	-4.95	-5.08	28.58	1361	34.4345654	-118.6482961	Valve Adjustment: NSPS/EG CAC
FP-032	9/1/2026 2:20:55 PM	6.5	13.6	11.2	68.7			0.5	6.1	94.6	94.9	-1.97	-1.60	3.9	2.1	1.604	0.476	-6.75	-6.50	28.56	1340	34.4350925	-118.6498458	Valve Adjustment: Decreased Flow/Vacuum
FP-033	9/1/2026 2:17:52 PM	0.0	1.5	19.5	79.0			0.0	4.1	95.1	95.1	-0.57	-0.55	0.7	0.8	0.010	0.014	-3.47	-3.24	28.54	1355	34.4353645	-118.6499232	
FP-034	9/1/2026 2:13:58 PM	0.4	7.7	11.7	80.2			0.1	6.9	99.7	99.7	-0.07	-0.06	4.6	4.6	0.436	0.441	-6.50	-6.10	28.53	1352	34.4356143	-118.6500065	Valve Adjustment: Barely Open
FP-035	9/1/2026 1:47:39 PM	19.4	39.8	4.9	35.9			0.5	7.3	91.8	91.8	-1.38	-1.36	4.2	5.1	0.365	0.519	-6.52	-6.64	28.53	1347	34.4358578	-118.6501190	Valve Adjustment: Barely Open
FP-036	9/14/2026 9:56:48 AM	9.7	15.8	12.5	62.0			0.6	5.0	93.2	93.3	-1.05	-1.06	2.0	2.1	1.052	1.115	-6.66	-6.81	28.45	1366	34.4361263	-118.6502075	
FP-037	9/1/2026 1:35:51 PM	1.1	1.1	19.3	78.5			1.0	4.1	92.9	93.6	-0.36	-0.36			0.000	0.000	-6.76	-6.66	28.53	1362	34.4362712	-118.6502867	
FP-038	9/14/2026 1:57:24 PM	25.4	17.9	6.6	50.1			1.4	7.6	98.2	98.7	-0.59	-0.59	41.7	41.7	1.953	1.957	-5.97		28.46	1339	34.4341347	-118.6497993	
FP-038	9/23/2026 10:03:41 AM	3.4	20.9	16.4	59.3			0.2	3.6	87.4	87.4	-1.96	-1.73	1.2	2.7	0.029	0.151	-7.74	-8.52	28.56	1284	34.4348375	-118.6509298	
FP-039	9/14/2026 1:59:50 PM	51.1	32.9	2.0	14.0			1.6	7.0	101.6	101.7	-0.63	-0.61	18.6	19.0	6.412	6.751	-5.67		28.47	1312	34.4341353	-118.6498533	
FP-040	9/23/2026 10:00:51 AM	12.0	43.2	6.4	38.4			0.3	6.0	103.2	103.2	-1.54	-1.49			0.000	0.000	-7.16	-7.50	28.54	1307	34.4352800	-118.6510477	
FP-041	9/2/2026 7:45:38 AM	13.4	33.2	4.3	49.1			0.4	11.4	64.9	65.0	-0.30	-0.29	7.1	7.4	1.022	1.114	-4.78		28.69	1273	34.4340772	-118.6507097	Reduced System Vacuum,
FP-042	9/2/2026 8:11:34 AM	6.2	28.7	12.1	53.0			0.2	4.4	70.4	70.5	-0.17	-0.17	11.5	11.1	2.764	2.557	-3.32		28.71	1230	34.4333060	-118.6512125	Reduced System Vacuum,
FP-043	9/2/2026 7:48:43 AM	8.0	26.0	7.6	58.4			0.3	7.7	82.4	82.5	-0.34	-0.33	26.0	26.0	4.205	4.203	-5.82		28.68	1247	34.4342878	-118.6507950	Reduced System Vacuum,
FP-044	9/2/2026 7:51:27 AM	0.5	6.7	19.2	73.6			0.1	3.8	67.4	67.5	-0.21	-0.21	5.6	5.6	0.590	0.590	-6.15		28.68	1250	34.4346070	-118.6508722	Reduced System Vacuum,
FP-045	9/2/2026 1:12:15 PM	0.0	0.1	21.0	78.9			0.2	3.8	94.1	105.4	-0.37	-0.05	13.4	0.3	3.645	0.001	-8.36	-8.48	28.67	1321	34.4334673	-118.6496613	Valve Adjustment: Decreased Flow/Vacuum, Barely Open
FP-046	9/25/2026 10:05:05 AM	9.3	36.2	9.1	45.4			0.3	5.0	93.5	93.4	-1.35	-1.34	16.5	16.6	5.589	5.667	-8.96	-9.07	28.54	1353	34.4365698	-118.6473025	
FP-047	9/29/2026 8:20:44 AM	3.3	6.5	15.4	74.8			0.5	4.9	73.0	73.0	-0.11	-0.11	1.4	1.5	0.040	0.044	-0.21	-0.21	28.35	1351	34.4367228	-118.6469347	
FP-050	9/2/2026 2:22:59 PM	25.8	60.0	0.1	14.1			0.4	141.0	99.9	99.9	-0.03	-0.02	6.2	6.3	0.235	0.242	-6.16	-6.89	28.55	1362	34.4349092	-118.6472822	
FP-051	9/2/2026 2:17:15 PM	35.9	63.4	0.2	0.5			0.6	2.5	98.4	98.4	-0.09	-0.10	25.3	25.8	0.802	0.834	-4.55	-4.66	28.56	1372	34.4345688	-118.6473497	
FP-052	9/2/2026 1:33:27 PM	9.3	14.1	10.5	66.1			0.7	6.3	94.0	94.0	-0.04	-0.04	14.0	14.1	1.192	1.220	-6.32	-6.38	28.59	1321	34.4342273	-118.6481287	Valve Adjustment: Barely Open
FP-053	9/2/2026 1:27:21 PM	17.1	19.4	8.6	54.9			0.9	6.4	100.3	100.6	-0.15	-0.14	2.5	2.4	0.123	0.118	-9.34	-8.94	28.56	1372	34.4340435	-118.6477683	
FP-054	9/1/2026 9:06:16 AM	27.3	72.6	0.1	0.0			0.4	0.0	164.9	165.1	-4.34	-4.34			4.310	4.314	-11.08	-11.22	28.57	1397	34.4349500	-118.6458056	Valve Adjustment: High Temp, Well Condition: Prumatic Pump Installed
FP-054	9/2/2026 2:06:03 PM	37.3	55.0	0.0	7.7			0.7	0.0	98.1	98.1	-0.09	-0.05			0.000	0.000	-3.55	-3.48	28.53	1370	34.4343572	-118.6471028	
FP-055	9/28/2026 10:39:01 AM	1.3	14.8	13.4	70.5			0.1	5.3	94.1	94.2	-0.25	-0.25	8.8	8.6	1.594	1.523	-12.12	-11.82	28.43	1365	34.4336285	-118.6481653	
FP-056	9/2/2026 9:03:40 AM	13.5	17.2	10.9	58.4			0.8	5.4	82.2	82.2	-0.14	-0.14	3.5	3.5	3.029	3.078	-11.89	-11.83	28.61	1359	34.4334652	-118.6486602	
FP-057	9/3/2026 12:59:26 PM	40.1	35.9	0.8	23.2			1.1	29.0	100.0	100.1	-0.97	-0.89	21.6	20.0	9.728	8.307	-19.92	-17.23	28.46	1382	34.4347557	-118.6455632	
FP-058	9/3/2026 12:56:21 PM	24.4	35.3	3.1	37.2			0.7	12.0	97.5	97.6	-0.60	-0.57	9.1	8.4	1.683	1.441	-18.79	-16.02	28.46	1403	34.4349677	-118.6458427	Valve Adjustment: Barely Open
FP-059	9/14/2026 1:04:23 PM	35.5	24.2	8.7	31.6			1.5	3.6	108.2	108.2	-0.75	-0.75	13.2	13.2	3.387	3.387	-21.45		28.42	1322	34.4346710	-118.6459353	
FP-060	9/28/2026 10:03:13 AM	0.0	0.0	20.8	79.2				3.8	86.5	86.4	-0.24	-0.25	4.8	4.8	0.465	0.459	-13.90	-13.92	28.41	1366	34.4348340	-118.6461072	
FP-061	9/9/2026 10:33:21 AM	1.0	14.4	16.0	68.6			0.1	4.3	112.1			-2.08		1.1	0.023		-4.40		28.64	1354	34.4364122	-118.6479115	
FP-062	9/10/2026 12:04:52 PM	9.7	74.0	0.0	15.9			0.1	0.0	151.0	151.1	-3.32	-3.16	6.8	4.6	0.063	0.028	-3.30	-3.09	28.71	1287	34.4349482	-118.6512123	
FP-063	9/10/2026 12:09:15 PM	0.5	3.2	19.4	76.9			0.2	4.0	112.6	112.8	-3.85	-3.78	1.9	1.5	0.024	0.015	-3.77	-3.85	28.71	1290	34.4349755	-118.6511665	
FP-064	9/14/2026 12:54:05 PM	52.9	40.5	0.0	6.6			1.3	0.0	100.8	101.7	0.00	-0.08	2.8	7.5	0.010	0.071	-18.32	-18.16	28.44	1368	34.4352088	-118.6442336	Valve Adjustment: NSPS/EG CAI, Reconnected this Date, Positive Static Press., Increased Flow/Vacuum, Barely Open
FP-064	9/14/2026 12:58:32 PM	51.3	39.0	0.0	9.7			1.3	0.0	101.6	101.4	-0.07	-0.07	6.2	6.3	0.048	0.049	-18.29	-18.20	28.44	1376	34.4351995	-118.6442335	Valve Adjustment: NSPS/EG CAC
FP-064	9/15/2026 9:47:50 AM	28.4	27.1	2.3	42.2			1.0	18.3	92.0	91.9	-0.43	-0.44	18.6	18.3	0.428	0.415	-20.38	-20.30	28.55	1386	34.4351913	-118.6442349	
FP-065	9/14/2026 1:10:28 PM	54.6	40.6	0.1	4.7			1.3	47.0	101.8	103.6	-0.01	-0.08	1.5	9.0	0.015	0.506	-17.75	-17.45	28.46	1383	34.4354977	-118.6441162	Valve Adjustment: NSPS/EG CAI, Reconnected this Date, Increased Flow/Vacuum, Barely Open
FP-065	9/15/2026 9:51:40 AM	32.6	29.9	2.2	35.3			1.1	16.0	93.0	92.8	-0.32	-0.32	7.2	7.1	0.314	0.310	-19.06	-18.87	28.55	1384	34.4354990	-118.6441080	
FP-066	9/14/2026 1:20:35 PM	39.5	30.5	2.2	27.8			1.3	12.6	103.8	103.8	-0.06	-0.07	8.2	8.2	1.289	1.291	-15.94		28.41	1345	34.4357498	-118.6441913	
FP-066	9/15/2026 9:55:34 AM	8.1	15.9	9.9	66.1			0.5	6.7	92.9	92.8	-0.40	-0.41	4.4	4.4	0.394	0.384</							

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [\"H2O]	Adj Stat Press [\"H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [\"H2O]	Adj Diff Press [\"H2O]	Sys Pressure [\"H2O]	Adj Avail Press [\"H2O]	Baro Press [\"Hg]	Elev [ft]	Latitude	Longitude	Comments	
H-01 (EXP-0)	9/30/2026 2:26:54 PM	10.2	47.0	0.0	42.9			0.2	0.0	110.0	110.3	-3.14	-3.13			3.207	3.234	-14.32	-13.88	28.53	1236	34.4377082	-118.6441205	Valve Adjustment:Reduce Sys. Vac. - Flare Down	
H-02 (EXP-0)	9/3/2026 12:33:02 PM	18.1	49.0	0.0	32.9			0.4	0.0	117.2	117.0	-5.04	-5.04			5.211	5.199	-14.80	-14.98	28.74	1239	34.4376965	-118.6446027	Valve Adjustment:Surging Liquid in Header	
H-02 (EXP-0)	9/30/2026 2:29:31 PM	20.5	46.6	0.0	33.0			0.4	0.0	115.0	115.2	-5.79	-5.62			5.834	5.807	-14.20	-14.26	28.53	1232	34.4376975	-118.6445695	Valve Adjustment:Reduce Sys. Vac. - Flare Down	
H-03 (EXP-0)	9/3/2026 12:29:22 PM	47.9	49.6	0.0	2.5			1.0	0.0	119.2	117.0	-13.87	-11.75			14.070	11.859	-14.22	-14.88	28.74	1249	34.4377235	-118.6446417	Valve Adjustment:Decreased Flow/Vacuum	
H-03 (EXP-0)	9/30/2026 2:35:08 PM	53.2	42.3	0.0	4.6			1.3	0.0	115.2	115.2	-11.33	-11.33			11.407	11.398	-13.62	-13.80	28.53	1240	34.4377113	-118.6446432	Valve Adjustment:Reduce Sys. Vac. - Flare Down	
H-04 (EXP-04)	9/3/2026 12:23:09 PM	3.4	56.9	0.0	39.7			0.1	0.0	135.4	131.8	-11.81	-5.71			12.043	5.809	-14.70	-14.68	28.74	1256	34.4377615	-118.6447062	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum	
H-04 (EXP-04)	9/3/2026 12:24:20 PM	2.5	57.9	0.0	39.6			0.0	0.0	131.5	131.5	-4.80	-4.79			4.952	4.937	-14.93	-14.77	28.74	1259	34.4377445	-118.6447087		
H-04 (EXP-04)	9/30/2026 2:38:36 PM	1.6	52.7	0.0	45.7			0.0	0.0	130.6	132.1	1.37	-0.04			0.000	0.022	-13.23	-13.04	28.53	1249	34.4377160	-118.6447213	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Positive Static Press.,Increased Flow/Vacuum	
H-04 (EXP-04)	9/30/2026 2:40:29 PM	1.5	55.3	0.0	43.2			0.0	0.0	136.6	136.8	-8.75	-8.98			8.881	9.017	-11.97	-12.08	28.53	1237	34.4377133	-118.6446953	Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down	
H-08 (EXP-08)	9/14/2026 8:50:48 AM	50.4	45.3	0.0	4.3			1.1	0.0	123.3	123.3	-13.52	-13.46			13.828	13.800	-16.01	-15.87	28.6	1259	34.4378665	-118.6465762	Valve Adjustment:Audible Flow	
H-08 (EXP-08)	9/29/2026 8:40:38 AM	51.1	45.8	0.0	3.1			1.1	0.0	123.3	123.5	-15.14	-15.48			15.290	15.683	-18.22	-18.23	28.45	1278	34.4378133	-118.6465330	Valve Adjustment:Increased Flow/Vacuum	
H-08 (EXP-08)	9/29/2026 8:42:05 AM	50.0	46.8	0.0	3.2			1.1	0.0	123.5	123.5	-15.69	-15.48			15.840	15.798	-18.26	-18.16	28.44	1283	34.4378187	-118.6465455		
H-10 (EXP-10)	9/15/2026 8:07:00 AM	11.5	70.4	0.0	18.1			0.2	0.0	131.2	131.2	-16.45	-16.49			16.378	16.420	-13.70	-13.73	28.59	1307	34.4374417	-118.6471038	Valve Adjustment:NSPS/EG CAI,High Temp	
H-10 (EXP-10)	9/15/2026 8:11:28 AM	10.9	69.6	0.0	19.5			0.2	0.0	131.3	131.3	-16.28	-16.27			16.313	16.296	-14.50	-14.51	28.59	1322	34.4374557	-118.6470822	Valve Adjustment:High Temp	
H-10 (EXP-10)	9/29/2026 8:30:20 AM	11.1	65.7	0.2	23.0			0.2	95.6	131.0	130.9	-16.22	-15.15			16.419	15.280	-15.98	-15.98	28.42	1312	34.4374495	-118.6471103	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Decreased Flow/Vacuum	
H-10 (EXP-10)	9/29/2026 8:32:34 AM	11.0	66.3	0.2	22.6			0.2	141.5	130.8	130.8	-14.47	-14.31			14.558	14.427	-15.78	-15.65	28.42	1312	34.4374272	-118.6470828		
H-1404C	9/15/2026 9:34:05 AM	12.8	30.3	0.6	56.3			0.4	93.8	153.8	153.6	-1.72	-1.76	3.1	3.1	1.105	1.089	-10.62	-11.82	28.54	1357	34.4324138	-118.6483060	Valve Adjustment:NSPS/EG CAI,High Temp	
H-1404C	9/15/2026 9:38:51 AM	12.7	29.9	0.6	56.8			0.4	94.7	153.4	153.9	-1.69	-1.68	4.1	3.2	1.956	1.155	-10.80	-10.77	28.56	1354	34.4323960	-118.6483453	Valve Adjustment:High Temp	
H-1404C	9/16/2026 10:35:00 AM					201																			AtmAA
H-1404C	9/16/2026 12:54:05 PM	13.9	31.9	0.5	53.7			0.4	116.7	151.7	150.8	-1.26	-1.24	7.7	6.0	1.315	0.814	-11.40	-11.82	28.6	1340	34.4324263	-118.6483047	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum	
H-1404C	9/16/2026 1:34:20 PM	10.5	26.3	0.5	62.7			0.4	118.4	151.1	122.2	-0.95	-0.59	4.5	0.2	2.307	0.003	-10.22	-10.22	28.61	1357	34.4324153	-118.6482913	Valve Adjustment:NSPS/EG CAC,Orifice Plate Changed (See OP Log),High Temp,Decreased Flow/Vacuum	
H-1404C	9/16/2026 1:40:19 PM	10.5	26.9	0.5	62.1			0.4	124.3	106.2	104.6	-0.56	-0.56	0.6	0.7	0.041	0.048	-11.07	-11.36	28.61	1348	34.4324238	-118.6482973		
H-1405C	9/1/2026 9:32:25 AM	16.0	49.7	2.9	31.4			0.3	10.8	90.9	91.2	-0.16	-0.16	1.2	1.0	0.010	0.007	-0.04		28.64	1224	34.4326442	-118.6498927		
H-1405C	9/22/2026 11:58:24 AM	0.0	0.2	22.8	77.0			0.0	3.4	101.0	101.0	-0.11	-0.10	0.0	0.0	-0.189	-0.189	-0.08		28.58	1345	34.4325665	-118.6496640	NSPS/EG CAI	
H-1405C	9/22/2026 11:59:05 AM	0.0	0.2	22.8	77.0			0.0	3.4	100.9	100.8	-0.11	-0.10	0.0	0.0	-0.179	-0.179	-0.09		28.58	1316	34.4325772	-118.6496620	NSPS/EG CAI,High O2	
H-1406W	9/2/2026 8:36:20 AM	28.4	59.3	1.9	10.4			0.5	5.5	71.9	70.8	-9.94	-3.86	1.8	2.3	0.022	0.036	-10.45		28.71	1227	34.4321592	-118.6507752	Reduced System Vacuum,	
H-1406W	9/4/2026 1:49:40 PM	31.7	55.6	0.6	12.0			0.6	19.4	93.1	93.5	-8.18	-8.33	0.1	0.4	0.000	0.001	-8.40	-8.33	28.64	1263	34.4321802	-118.6508002	Valve Adjustment:Increased Flow/Vacuum	
H-1406W	9/10/2026 10:32:49 AM	29.3	63.1	0.3	7.3			0.5	24.3	93.1	93.2	-1.56	-1.94	0.5	0.7	0.002	0.003	-1.45	-1.69	28.7	1244	34.4321732	-118.6507816	Valve Adjustment:Increased Flow/Vacuum	
H-1406W	9/23/2026 8:53:49 AM	0.2	7.4	19.4	73.0			0.0	3.8	83.1	83.1	-5.40	-5.40	2.2	2.5	0.029	0.038	-5.52	-5.71	28.6	1260	34.4321605	-118.6507730	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected	
H-1408CR	9/23/2026 12:53:30 PM	42.7	43.2	0.0	14.1			1.0	0.0	126.1	126.1	-0.22	-0.27	6.9	8.3	0.304	0.442	-9.57	-11.95	28.59	1326	34.4315698	-118.6475928	Valve Adjustment:Increased Flow/Vacuum,Barely Open	
H-1408E	9/14/2026 2:12:45 PM	54.4	42.0	0.0	3.6			1.3	0.0	98.1	103.0	-0.30	-0.30	7.0	7.0	0.305	0.308	-7.49	-7.83	28.37	1394	34.4333870	-118.6471932	Valve Adjustment:Barely Open	
H-1408E	9/21/2026 10:04:50 AM	55.3	43.0	0.0	1.7			1.3	0.0	117.6	118.5	-0.59	-1.25	7.0	5.8	0.312	0.218	-9.59	-9.11	28.52	1381	34.4333585	-118.6471537	Valve Adjustment:Increased Flow/Vacuum	
H-1408W	9/2/2026 9:01:18 AM	36.9	30.5	4.8	27.8			1.2	5.8	81.6	81.6	-0.24	-0.21	0.6	1.1	0.000	0.001	-12.71		28.71	1220	34.4311535	-118.6499650		
H-1409N	9/1/2026 2:27:54 PM	42.2	34.8	0.0	23.0			1.2	0.0	116.8	116.9	-0.41	-0.41	0.7	0.7	0.111	0.111	-3.83		28.55	1325	34.4324990	-118.6472582		
H-1409N	9/21/2026 9:11:22 AM	57.1	41.2	0.0	1.7			1.4	0.0	103.6	106.0	-1.22	-1.31	1.3	1.2	0.432	0.400	-9.97	-9.36	28.55	1354	34.4328685	-118.6469350	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)	
H-1410S	9/25/2026 9:05:52 AM	50.4	40.9	0.6	8.1			1.2	14.5	93.3	94.0	-8.70	-8.69	2.0	2.5	0.005	0.008	-9.29	-9.20	28.7	1220	34.4310030	-118.6466878		
H-1563N	9/14/2026 2:12:22 PM	48.5	36.8	0.3	14.4			1.3	48.0	126.0	126.0	-2.51	-2.51	6.6	6.7	0.263	0.267	-6.05		28.46	1332	34.4338745	-118.6498027		
H-1563N	9/17/2026 10:33:10 AM	32.6	37.8	0.5	29.1			0.9	58.2	126.1	124.6	-3.61	-2.51	3.5	5.0	0.078	0.161	-8.47	-8.32	28.71	1322	34.4338623	-118.6497998	Valve Adjustment:Decreased Flow/Vacuum	
H-1563S	9/1/2026 9:35:22 AM	13.8	27.5	0.4	58.3			0.5	145.8	90.1	90.1	-0.45	-0.44	0.4	0.4	0.016	0.019	-0.44		28.63	1270	34.4323257	-118.6496260		
H-1563S	9/22/2026 12:03:36 PM	10.9	23.5	0.3	65.3			0.5	217.7	94.4	94.4	-0.24	-0.21	0.9	0.3	0.090	0.013	-9.63		28.55	1286	34.4323790	-118.6495912		

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [”H2O]	Adj Stat Press [”H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [”H2O]	Adj Diff Press [”H2O]	Sys Pressure [”H2O]	Adj Avail Press [”H2O]	Baro Press [”Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
H-1565E	9/14/2026 2:16:08 PM	51.5	39.6	0.0	8.9			1.3	0.0	104.6	104.6	-0.07	-0.07	2.3	2.4	0.032	0.036	-3.03	-2.96	28.37	1408	34.4335807	-118.6472417	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1565E	9/21/2026 10:11:59 AM	38.7	36.0	0.0	25.3			1.1	0.0	91.1	91.2	-0.23	-0.24	0.7	1.3	0.003	0.011	-4.00	-4.28	28.52	1380	34.4335487	-118.6472173	Valve Adjustment:Barely Open
H-1568N	9/14/2026 2:10:12 PM	41.7	38.9	1.2	18.2			1.1	15.2	116.5	116.4	-0.90	-0.86	17.4	18.0	6.525	6.939	-8.35	-7.89	28.37	1387	34.433623	-118.6471542	Valve Adjustment:Barely Open
H-1568N	9/21/2026 9:57:33 AM	34.2	38.7	1.5	25.6			0.9	17.1	116.0	116.0	-1.29	-1.28	19.5	19.4	8.181	8.045	-9.71	-9.50	28.52	1381	34.4333530	-118.6471417	Valve Adjustment:Barely Open
H-1571S	9/24/2026 10:55:12 AM	52.9	42.0	0.0	5.1			1.3	0.0	94.1	100.2	-2.35	-2.37	5.0	4.3	0.055	0.042	-13.67	-13.38	28.59	1285	34.4321542	-118.6452327	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1572N	9/22/2026 10:24:00 AM	50.5	42.9	0.0	6.6			1.2	0.0	108.1	107.3	-0.22	-0.21	0.7	0.7	0.010	0.009	-22.00		28.55	1362	34.4338670	-118.6447982	
H-1572S	9/24/2026 10:40:13 AM	39.8	35.3	4.2	20.7			1.1	4.9	94.1	97.2	-0.03	-0.04	2.2	2.1	0.011	0.010	-13.67	-13.65	28.62	1275	34.4321608	-118.6447210	Valve Adjustment:Barely Open
H-1753N	9/1/2026 2:48:08 PM	38.5	30.1	4.8	26.6			1.3	5.5	96.3	96.3	-1.32	-1.30	2.0	2.0	0.009	0.009	-6.45	-6.37	28.56	1338	34.4347308	-118.6493502	
H-1753N	9/24/2026 11:34:35 AM	41.2	33.6	5.3	19.9			1.2	3.8	94.9	94.7	-1.25	-1.06	6.0	11.4	0.079	0.289	-11.98	-11.00	28.63	1346	34.4347177	-118.6493162	Valve Adjustment:NSPS/EG CAC,Orifice Plate Changed (See OP Log),High O2,Decreased Flow/Vacuum;Well Comment:Changed OP from 1.25 to 0.40
H-1753N	9/24/2026 11:36:18 AM	41.7	33.2	4.9	20.2			1.3	4.1	94.8	94.7	-1.03	-1.04	1.0	1.1	0.272	0.281	-10.78	-10.83	28.63	1341	34.4347147	-118.6493143	Valve Adjustment:NSPS/EG CAC
H-1753S	9/14/2026 1:54:43 PM	54.6	41.4	0.0	4.0			1.3	0.0	108.8	108.9	-1.25	-1.23	8.3	8.3	0.143	0.143	-5.86		28.45	1332	34.4339740	-118.6496573	
H-1753S	9/17/2026 10:36:17 AM	43.6	39.2	0.0	17.2			1.1	0.0	106.9	105.5	-2.04	-1.30	2.2	1.0	0.098	0.019	-8.80	-8.31	28.71	1336	34.4339248	-118.6495635	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-1756S	9/2/2026 7:25:00 AM	10.8	25.7	3.5	60.0			0.4	17.1	68.9	71.3	-0.60	-0.46	11.5	5.7	0.155	0.039	-7.97		28.66	1289	34.4324973	-118.6502938	Reduced System Vacuum,
H-1756S	9/22/2026 11:27:30 AM	30.9	41.6	1.9	25.6			0.7	13.5	111.0	109.4	-1.76	-0.56	43.8	19.0	2.444	0.456	-8.40		28.61	1293	34.4325735	-118.6502503	
H-1757S	9/1/2026 9:27:22 AM	38.4	46.9	0.0	14.7			0.8	0.0	93.9	94.1	-0.64	-0.66	5.8	5.8	0.075	0.074	-10.65		28.63	1348	34.4327692	-118.6497163	
H-1757S	9/22/2026 11:41:50 AM	31.4	42.3	0.0	26.3			0.7	0.0	109.8	110.1	-1.66	-1.45	5.3	0.0	0.066	-0.202	-9.30		28.58	1253	34.4327528	-118.6497990	
H-1760S	9/14/2026 1:52:17 PM	40.2	58.6	0.0	1.2			0.7	0.0	122.1	122.1	-1.47	-1.42	5.3	4.9	0.179	0.156	-11.15	-10.23	28.38	1384	34.4327338	-118.6479463	
H-1760S	9/21/2026 9:25:24 AM	39.0	55.9	0.0	5.1			0.7	0.0	117.9	117.9	-1.84	-1.87	5.2	5.4	0.174	0.184	-11.06	-11.76	28.55	1357	34.4327312	-118.6478820	Valve Adjustment:Surging Liquid in Header
H-1762N	9/13/2026 1:22:53 PM	51.5	39.8	0.0	8.6			1.3	0.0	115.5	116.1	-0.25	-0.31	5.7	6.9	0.685	1.006	-7.42	-7.85	28.46	1381	34.4334488	-118.6468737	Valve Adjustment:Increased Flow/Vacuum;Well Repairs:Flex Hose
H-1762N	9/13/2026 1:24:07 PM	50.4	39.8	0.0	9.8			1.3	0.0	116.4	116.5	-0.34	-0.31	6.8	6.8	0.992	0.966	-7.88	-7.52	28.45	1385	34.4334498	-118.6468985	
H-1762N	9/21/2026 8:20:33 AM	49.3	38.1	0.0	12.6			1.3	0.0	113.2	113.4	-0.40	-0.39	6.6	7.2	0.926	1.077	-8.87	-8.69	28.51	1393	34.4334683	-118.6468832	Valve Adjustment:Surging Liquid in Header
H-1763N	9/14/2026 1:09:46 PM	29.5	29.6	3.1	37.8			1.0	12.2	121.7	121.5	-1.46	-1.47	28.7	28.9	5.380	5.449	-22.89	-23.34	28.37	1400	34.4335408	-118.6462090	Valve Adjustment:Barely Open
H-1763N	9/24/2026 2:03:05 PM	29.7	41.8	2.3	26.2			0.7	11.4	124.3	124.3	-0.82	-0.75	20.4	20.3	2.693	2.680	-11.22	-10.82	28.45	1385	34.4335343	-118.6461888	Valve Adjustment:Barely Open
H-1763S	9/9/2026 1:49:39 PM	18.7	27.9	0.0	53.4			0.7	0.0	127.1	127.1	-1.62	-1.54	32.1	30.9	1.310	1.567	-7.16		28.62	1322	34.4323707	-118.6462738	
H-1764N	9/9/2026 1:21:26 PM	44.1	39.6	0.0	16.3			1.1	0.0	122.3	122.1	-3.89	-2.67	13.4	6.5	1.114	0.261	-22.61		28.58	1339	34.4331267	-118.6455518	
H-1764S	9/24/2026 11:03:44 AM	40.8	47.1	0.0	12.1			0.9	0.0	124.3	123.7	-9.00	-8.75	1.6	1.1	0.017	0.008	-13.77	-13.84	28.57	1302	34.4321818	-118.6454058	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-1767N	9/28/2026 3:02:56 PM	39.6	57.4	0.1	2.9			0.7	29.0	106.3	106.3	-1.19	-1.20	20.3	21.3	0.944	1.041	-19.62	-20.48	28.45	1233	34.4326733	-118.6436082	Valve Adjustment:Barely Open
H-1769N	9/1/2026 11:23:33 AM	9.7	28.4	3.8	58.1			0.3	15.3	124.7	123.6	-0.39	-0.37	1.9	1.8	0.386	0.349	-6.95	-6.92	28.67	1358	34.4370417	-118.6494878	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-1769N	9/16/2026 12:33:55 PM	4.7	17.8	7.6	69.9			0.3	9.2	118.5	117.7	-0.39	-0.37	2.4	1.9	0.650	0.383	-7.50	-7.24	28.67	1377	34.4370138	-118.6494922	Valve Adjustment:NSPS/EG CAC,High O2,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In)
H-1769N	9/16/2026 12:34:48 PM	4.6	17.1	7.7	70.6			0.3	9.2	117.1	117.0	-0.38	-0.38	1.9	1.8	0.375	0.356	-7.38	-7.66	28.68	1378	34.4370137	-118.6494940	
H-1770N	9/1/2026 11:22:05 AM	29.2	63.7	0.0	7.1			0.5	0.0	105.0	105.2	-1.01	-0.93	3.5	3.2	1.314	1.079	-10.45	-10.47	28.69	1357	34.4368300	-118.6500212	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-1770N	9/10/2026 9:10:00 AM					320																		AirTech Lab
H-1770N	9/10/2026 9:10:00 AM						23000																	AirTech Lab; [User entered 2.3%]
H-1770N	9/16/2026 2:50:15 PM	27.2	65.6	0.2	7.0			0.4	35.0	97.3	97.4	-1.43	-1.44	10.4	12.6	2.239	3.289	-11.97	-12.21	28.53	1330	34.4367707	-118.6500187	Valve Adjustment:Barely Open
H-1770S	9/1/2026 9:20:12 AM	40.1	52.8	0.0	7.1			0.8	0.0	103.4	103.6	-0.40	-0.40	0.2	0.3	0.006	0.007	-9.52		28.63	1283	34.4331502	-118.6501687	
H-1770S	9/24/2026 2:40:13 PM	27.1	48.3	1.7	22.9			0.6	13.5	105.7	106.3	-0.68	-0.58	0.3	1.5	0.002	0.045	-9.06	-8.80	28.49	1307	34.4331515	-118.6501883	Valve Adjustment:Barely Open
H-1771A	9/10/2026 1:09:59 PM	33.0	67.0	0.0	0.0			0.5	0.0	106.7	106.7	-0.01	-0.03	9.0	9.4	0.511	0.556	-1.46	-1.34	28.49	1368	34.4363303	-118.6464000	Valve Adjustment:Barely Open
H-1771B	9/3/2026 8:52:45 AM	13.6	70.2	0.0	16.2			0.2	0.0	98.8	98.6	-0.42	-0.42	1.3	1.5	0.036	0.047	-8.11	-7.91	28.52	1380	34.4355145	-118.6466442	Valve Adjustment:Barely Open
H-1771B	9/22/2026 10:31:17 AM	25.0	33.2	1.3	40.5			0.8	31.2	104.0	104.0	-1.03	-1.04	1.4	1.5	0.040	0.044	-11.00	-10.66	28.49	1389	34.4355065	-118.6466522	Valve Adjustment:Barely Open
H-1774N	9/10/2026 8:58:19 AM	38.4	58.6	0.0	3.0			0.7	0.0	118.9	118.5	-1.57	-1.09	40.8	29.4	2.174	1.125	-11.23	-11.24	28.67	1356	34.4367360	-118.6508087	Valve Adjustment:Decreased Flow/Vacuum
H-1774N	9/16/2026 2:40:28 PM	37.4	62.4	0.2	0.0			0.6	0.0	118.5	118.4	-0.95	-0.94	8.1	8.1	1.380	1.392	-12.02	-12.12	28.56	1292	34.4366750	-118.6507832	Valve Adjustment:Barely Open
H-1801S	9/1/2026 9:53:29 AM	0.1	2.6	19.6	77.7			0.0	4.0	90.5	90.7	-0.15	-0.17	1.0	0.8	0.022	0.012	-15.13	-15.17	28.6	1334	34.4337665	-118.6440815	Valve Adjustment:High O2,Barely Open
H-1801S	9/1/2026 9:53:57 AM	0.1	2.3	19.6	78.0			0.0	4.0	91.6	91.8	-0.18	-0.17	0.5	0.5	0.005	0.005	-14.60	-14.85	28.6	1334	34.4337655	-118.6440868	Valve Adjustment:High O2,Barely Open
H-1802S	9/22/2026 10:27:44 AM	53.6	43.7	0.0	2.7			1.2	0.0	108.4	112.1	-0.08	-0.21	6.8	20.5	0.054	0.490	-21.86		28.55	1358	34.4334885	-118.6447217	
H-1803N-PLS	9/8/2026 10:07:00 AM					1740																		AtmAA

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [\"H2O]	Adj Stat Press [\"H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [\"H2O]	Adj Diff Press [\"H2O]	Sys Pressure [\"H2O]	Adj Avail Press [\"H2O]	Baro Press [\"Hg]	Elev [ft]	Latitude	Longitude	Comments	
H-1803N-PL	9/8/2026 10:10:29 AM	1.7	77.3	0.0	21.0			0.0	0.0	198.6	198.5	-3.89	-3.65	50.5	48.8	3.828	3.563	0.24	0.25	28.61	1351	34.4370384	-118.6485862	Valve Adjustment:No Flow Measurement,High Temp	
H-1803N-PL	9/14/2026 9:29:28 AM	11.9	72.8	0.0	15.3			0.2	0.0	198.3	198.2	-5.11	-5.10	60.5	57.4	5.547	4.990	0.33	0.34	28.49	1339	34.4370404	-118.6486030	Valve Adjustment:No Flow Measurement,High Temp	
H-1803N-PL	9/14/2026 9:32:00 AM					1700																			AtmAA
H-1803N-PL	9/21/2026 9:40:35 AM	10.6	74.6	0.0	14.8			0.1	0.0	198.4	198.4	-7.19	-6.92	70.5	68.9	7.570	7.226	0.29	0.29	28.6	1346	34.4370364	-118.6486014	Valve Adjustment:No Flow Measurement,High Temp	
H-1803N-PL	9/21/2026 9:41:00 AM					1490																			AtmAA
H-1803N-PL	9/28/2026 9:10:00 AM					1290																			AtmAA
H-1803N-PL	9/28/2026 9:16:43 AM	10.7	74.1	0.0	15.2			0.1	0.0	198.5	198.7	-8.14	-7.98	74.1	73.6	8.456	8.330	0.13	0.13	28.46					Valve Adjustment:No Flow Measurement,High Temp
H-1804B	9/14/2026 1:13:24 PM	45.5	54.5	0.0	0.0			0.8	0.0	112.3	112.3	-17.18	-13.00	17.0	6.9	1.953	0.319	-19.67		28.41	1306	34.4342583	-118.6457412	.	
H-1804N	9/25/2026 2:27:02 PM	26.4	70.1	0.1	3.4			0.4	34.0	130.4	130.4	-0.99	-0.66	10.5	10.8	2.394	2.547	-3.03	-3.41	28.47	1344	34.4363942	-118.6457030	Valve Adjustment:Barely Open	
H-1804S	9/9/2026 1:23:01 PM	44.0	39.2	0.0	16.8			1.1	0.0	120.5	120.5	-18.66	-14.27	17.9	13.2	2.056	1.112	-16.77		28.58	1325	34.4331813	-118.6457637	.	
H-1805A	9/3/2026 1:50:46 PM	45.9	42.9	0.2	11.0			1.1	55.0	90.6		-2.14		2.0		0.005		-19.47		28.45	1389	34.4351325	-118.6450940	Valve Adjustment:Barely Open	
H-1805B	9/9/2026 1:05:06 PM	24.0	29.0	0.7	46.3			0.8	66.1	111.1	111.5	-0.65	-0.66	0.0	0.0	-0.009	-0.008	-20.25		28.58	1355	34.4337667	-118.6451923	.	
H-1805S	9/9/2026 1:38:46 PM	44.9	40.8	0.0	14.3			1.1	0.0	130.6	128.9	-2.57	-1.89	8.4	1.2	0.159	0.003	-21.53		28.61	1335	34.4328877	-118.6451552	NSPS/EG CAI,High Temp	
H-1805S	9/9/2026 1:39:27 PM	45.7	42.3	0.0	12.0			1.1	0.0	127.9	128.0	-1.54	-1.54	2.2	1.9	0.011	0.008	-21.21		28.61	1358	34.4328317	-118.6450868	NSPS/EG CAC,	
H-1806A	9/3/2026 1:23:27 PM	49.3	39.0	0.0	11.7			1.3	0.0	118.2	118.3	-0.92	-0.84	23.8	18.1	1.326	0.766	-18.43	-18.65	28.48	1384	34.4354598	-118.6442113	Valve Adjustment:Barely Open	
H-1806B	9/22/2026 10:17:41 AM	41.9	37.6	2.2	18.3			1.1	8.3	89.6	89.6	-0.94	-0.93	1.2	1.2	0.028	0.027	-21.27		28.55	1368	34.4338525	-118.6444215	.	
H-1806B	9/22/2026 10:19:58 AM	46.2	38.6	0.7	14.5			1.2	20.7	90.6	90.4	-0.92	-0.92	0.7	0.6	0.008	0.008	-21.73		28.55	1339	34.4339752	-118.6444817	.	
H-1806N	9/10/2026 1:30:41 PM	42.2	57.7	0.1	0.0			0.7	0.0	126.2	125.9	-1.02	-1.03	12.5	12.3	0.205	0.200	-9.67	-9.19	28.5	1356	34.4363658	-118.6443012	Valve Adjustment:Barely Open	
H-1806S	9/1/2026 9:12:20 AM	17.6	77.3	0.0	5.1			0.2	0.0	123.3	127.4	-0.15	-0.15	12.8	12.3	0.382	0.357	-17.38	-17.04	28.67	1285	34.4328808	-118.6444572	Valve Adjustment:Barely Open	
H-1807A	9/22/2026 10:02:24 AM	52.7	41.7	0.0	5.6			1.3	0.0	113.7	114.1	-16.50	-16.50	0.0	0.0	-3.806	-2.827	-19.39		28.57	1309	34.4352938	-118.6436250	.	
H-1807N	9/4/2026 9:28:29 AM	29.2	34.3	0.6	35.9			0.9	56.1	93.9	94.4	-1.07	-1.16	2.5	5.3	0.037	0.172	-11.28	-12.02	28.57	1350	34.4364542	-118.6435158	Valve Adjustment:Increased Flow/Vacuum	
H-1807N	9/10/2026 1:36:04 PM	47.8	37.2	0.1	14.9			1.3	149.0	113.3	113.9	-0.46	-0.45	2.6	2.6	0.042	0.044	-9.27	-8.35	28.52	1352	34.4364475	-118.6435195	Valve Adjustment:Barely Open	
H-1807S	9/1/2026 10:29:44 AM	45.4	32.9	0.2	21.5			1.4	107.5	98.0	98.5	-4.52	-4.51	3.8	2.4	0.018	0.008	-14.95	-15.17	28.64	1297	34.4338257	-118.6434557	.	
H-1952S	9/2/2026 1:24:38 PM	52.7	46.5	0.0	0.8			1.1	0.0	119.2	119.2	-1.66	-1.63	14.0	14.0	4.168	4.172	-9.38	-9.22	28.56	1358	34.4338043	-118.6476345	Valve Adjustment:Barely Open	
H-1952S	9/17/2026 2:50:32 PM	53.4	45.1	0.0	1.5			1.2	0.0	118.3	118.3	-1.68	-1.47	14.1	13.2	4.243	3.683	-9.63	-8.25	28.6	1329	34.4337640	-118.6476647	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)	
H-1955C	9/3/2026 1:54:00 PM	24.6	27.2	2.5	45.7			0.9	18.3	91.7	91.7	-0.61	-0.58	8.4	8.4	1.441	1.439	-22.84	-22.53	28.45	1380	34.4350433	-118.6454357	Valve Adjustment:Barely Open	
H-1955N	9/10/2026 1:18:23 PM	40.3	48.4	0.5	10.8			0.8	21.6	103.1	103.4	-0.38	-0.37	4.0	3.7	0.100	0.083	-2.11	-1.99	28.51	1346	34.4364757	-118.6455270	Valve Adjustment:Barely Open	
H-1956B	9/9/2026 12:56:13 PM	14.6	68.6	0.0	16.8			0.2	0.0	126.4	125.1	0.05	-0.57	0.0	8.4	-0.017	0.198	-1.18		28.59	1430	34.4342482	-118.6447508	NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum	
H-1956B	9/9/2026 12:57:13 PM	17.1	68.7	0.0	14.2			0.2	0.0	128.5	128.6	-0.73	-0.73	7.1	7.3	0.144	0.150	-1.11		28.59	1365	34.4342145	-118.6447100	NSPS/EG CAC,	
H-1956N	9/10/2026 1:26:20 PM	54.5	45.4	0.1	0.0			1.2	0.0	115.3	115.3	-1.99	-2.02	21.6	21.7	2.983	3.012	-4.53	-4.63	28.51	1320	34.4364623	-118.6448830	.	
H-1956S	9/1/2026 9:27:26 AM	44.7	41.2	0.0	14.1			1.1	0.0	104.1	103.9	-16.18	-16.16	0.5	0.5	0.027	0.025	-16.94	-16.98	28.6	1335	34.4331990	-118.6448652	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected	
H-1957B	9/3/2026 1:15:00 PM	57.6	40.4	0.0	2.0			1.4	0.0	97.3	97.4	-0.31	-0.32	22.2	23.0	3.049	3.268	-19.62	-20.91	28.48	1377	34.4345480	-118.6441168	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)	
H-1957N	9/10/2026 1:33:26 PM	52.5	47.4	0.1	0.0			1.1	0.0	121.9	122.0	-0.47	-0.45	5.6	4.9	0.203	0.153	-9.65	-9.70	28.52	1342	34.4364512	-118.6441942	Valve Adjustment:Barely Open	
H-1957S	9/30/2026 9:45:11 AM	45.0	45.2	0.6	9.2			1.0	16.7	142.6	127.3	-22.12	-3.68	3.0	0.2	0.216	0.001	-22.84	-22.16	28.48	1327	34.4337623	-118.6441242	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down	
H-1957S	9/30/2026 9:54:00 AM	44.0	46.0	0.5	9.5			1.0	18.3	130.5	129.5	-0.24	-0.24	0.8	0.9	0.015	0.016	-21.14	-21.02	28.49	1327	34.4337590	-118.6441348	Valve Adjustment:Barely Open,Reduce Sys. Vac. - Flare Down	
H-1957S	9/30/2026 2:08:10 PM	41.1	48.6	0.6	9.7			0.8	16.2	107.8	107.6	-0.73	-0.92	7.1	7.7	1.058	1.255	-18.27	-17.34	28.4	1326	34.4337655	-118.6441103	Valve Adjustment:Barely Open	
H-1958C	9/22/2026 9:58:48 AM	41.5	37.7	0.0	20.8			1.1	0.0	116.2	116.2	-1.10	-1.08	3.6	3.7	0.081	0.086	-20.18		28.59	1375	34.4352407	-118.6434030	.	
H-1958N	9/10/2026 1:37:51 PM	48.1	38.1	0.4	13.4			1.3	33.5	114.2	114.6	-0.61	-0.58	22.0	21.7	0.628	0.608	-9.51	-9.07	28.52	1354	34.4364260	-118.6434973	Valve Adjustment:Barely Open	
H-1958S	9/1/2026 10:27:20 AM	11.9	16.6	12.1	59.4			0.7	4.9	96.7	97.5	-0.16	-0.25	4.8	2.9	0.138	0.051	-15.09	-15.15	28.63	1301	34.4340163	-118.6433158	Valve Adjustment:High O2,Barely Open	
H-1962N	9/1/2026 11:28:27 AM	18.4	33.4	0.9	47.3			0.6	52.6	134.7	134.7	-4.07	-3.19			3.984	3.116	-10.18	-10.79	28.68	1361	34.4366952	-118.6501143	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum	
H-1962N	9/1/2026 11:29:39 AM	14.6	27.4	1.7	56.3			0.5	33.1	134.8	134.8	-3.15	-3.14			3.068	3.062	-10.73	-10.62	28.69	1371	34.4366880	-118.6501150	.	
H-1962N	9/16/2026 2:56:18 PM	17.2	36.2	0.9	45.7			0.5	50.8	136.1	136.9	-1.67	-1.51			1.641	1.445	-11.74	-11.84	28.52	1349	34.4366487	-118.6501228	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open	
H-1962N	9/16/2026 2:56:46 PM	17.6	33.8	1.5	47.1			0.5	31.4	136.9	136.7	-1.45	-1.45			1.437	1.438	-11.81	-11.81	28.52	1349	34.4366513	-118.6501238	Valve Adjustment:High Temp	
H-1963N	9/1/2026 10:58:20 AM	17.2	60.5	0.8	21.5			0.3	26.9	145.8	144.1	-0.54	-0.24	3.1	3.6	0.013	0.018	-6.98	-6.91	28.65	1371	34.4369235	-118.6495610	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum	
H-1963N	9/1/2026 10:59:34 AM																								

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading	H2 Reading	CH4: CO2	BalO2	Init Temp	Adj Temp	Init Stat Press	Adj Stat Press	Init Flow	Adj Flow	Init Diff Press	Adj Diff Press	Sys Pressure	Adj Avail Press	Baro Press	Elev	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]	[ppmv]	[ppmv]		[%]	[°F]	[°F]	[°H2O]	[°H2O]	[scfm]	[scfm]	[°H2O]	[°H2O]	[°H2O]	[°H2O]	[°Hg]	[ft]			
H-1963N	9/16/2026 12:20:55 PM	16.6	65.4	0.9	17.1			0.3	19.0	143.7	143.5	-0.33	-0.34	2.3	2.8	0.007	0.010	-10.20	-10.16	28.67	1373	34.4369177	-118.6495743	Valve Adjustment: NSPS/EG CAI, High Temp, Barely Open
H-1963N	9/16/2026 12:21:46 PM	16.4	66.5	0.9	16.2			0.2	18.0	143.7	143.7	-0.34	-0.34	2.3	2.4	0.007	0.008	-10.33	-10.35	28.68	1372	34.4369202	-118.6495612	
H-1966N	9/10/2026 9:06:20 AM	36.7	41.0	0.0	22.3			0.9	0.0	110.1	110.2	-0.46	-0.45	9.0	8.7	1.689	1.572	-5.07	-4.74	28.67	1349	34.4365540	-118.6508080	Valve Adjustment: Audible Flow
H-1966N	9/16/2026 2:32:58 PM	36.7	43.4	0.1	19.8			0.8	198.0	110.2	110.1	-0.36	-0.38	4.4	4.4	2.113	2.096	-5.04	-5.39	28.53	1305	34.4365103	-118.6507695	Valve Adjustment: Barely Open
H-1967E	9/2/2026 10:44:57 AM	42.0	35.5	2.0	20.5			1.2	10.3	101.9	101.6	-1.84	-0.93	6.0	4.7	0.046	0.027	-13.82	-13.68	28.89	1144	34.4302150	-118.6458270	Valve Adjustment: Audible Flow, Decreased Flow/Vacuum
H-1967W	9/2/2026 1:39:12 PM	55.5	37.2	0.0	7.3			1.5	0.0	102.8	102.8	-5.36	-5.36	57.2	58.6	3.641	3.819	-10.20		28.75	1194	34.4300793	-118.6509698	
H-2050E	9/30/2026 9:51:30 AM	55.3	42.8	0.2	1.7			1.3	8.5	101.1	101.2	-1.45	-1.50	3.3	3.7	0.218	0.286	-1.32	-1.52	28.71	1095	34.4291283	-118.6475085	Valve Adjustment: Barely Open
H-2050W	9/21/2026 2:03:14 PM	37.6	37.7	0.0	24.7			1.0	0.0	98.7	98.6	-0.76	-0.73	2.2	1.9	0.522	0.379	-4.76	-3.61	28.73	1184	34.4291275	-118.6491238	
H-2050W	9/21/2026 2:07:51 PM	37.7	37.5	0.0	24.8			1.0	0.0	98.3	99.8	-0.90	-1.22	2.4	5.4	0.115	0.597	-4.87	-4.76	28.73	1182	34.4291217	-118.6491375	Valve Adjustment: Orifice Plate Changed (See OP Log), Increased Flow/Vacuum
H-2050W	9/21/2026 2:09:57 PM	33.5	36.3	0.0	30.2			0.9	0.0	100.2	100.2	-1.20	-1.19	5.0	5.0	0.511	0.512	-4.25	-4.36	28.73	1194	34.4291248	-118.6491200	
H-2051W	9/2/2026 1:36:38 PM	55.9	39.4	0.0	4.7			1.4	0.0	103.7	103.8	-11.25	-11.26	6.2	6.1	0.044	0.042	-11.32		28.76	1201	34.4298638	-118.6508128	
H-2053E	9/2/2026 10:36:42 AM	54.7	39.9	0.0	5.4			1.4	0.0	119.3	119.4	-0.82	-1.05	12.3	13.9	0.194	0.250	-14.73	-14.87	28.9	1142	34.4302028	-118.6458253	Valve Adjustment: Audible Flow, Increased Flow/Vacuum
H-2055E	9/15/2026 10:19:32 AM	23.8	33.3	0.0	42.9			0.7	0.0	92.3	92.6	-0.58	-0.55	1.8	0.8	0.020	0.004	-23.64	-23.35	28.64	1282	34.4317688	-118.6465997	Valve Adjustment: Barely Open
H-2055E	9/24/2026 1:41:22 PM						28000																	[User entered 2.8%]
H-2055E	9/24/2026 1:42:43 PM	45.1	41.8	0.0	13.1			1.1	0.0	104.7	104.7	0.07	0.08	0.2	0.3	0.014	0.017	-13.09	-13.22	28.61	1283	34.4317447	-118.6466117	Valve Adjustment: Reduce Sys. Vac. - Flare Down
H-2055E	9/24/2026 1:45:00 PM					14.1																		AtmAA (24 TAT Request)
H-2055E	9/24/2026 1:45:00 PM						3300																	AtmAA (24 TAT Request); [User entered 0.33%]
H-2055E	9/24/2026 2:52:19 PM					20																		
H-2055E	9/28/2026 8:24:51 AM	39.2	36.4	0.0	24.3			1.1	0.0	71.0	84.3	-0.01	-0.75	0.2	1.5	0.015	0.535	-15.18	-14.70	28.52	1289	34.4317570	-118.6466127	Valve Adjustment: NSPS/EG CAI, NSPS/EG CAC, Increased Flow/Vacuum
H-2055E	9/28/2026 8:27:27 AM	30.7	34.3	0.0	35.0			0.9	0.0	86.3	86.4	-0.68	-0.68	1.4	1.4	0.513	0.506	-14.01	-13.36	28.53	1269	34.4317760	-118.6466288	
H-2056B	9/30/2026 10:41:17 AM	52.5	42.1	0.0	5.4			1.2	0.0	113.3	113.3	-0.09	-0.11	4.6	2.2	0.450	0.098	-0.66	-1.56	28.67	1145	34.4297317	-118.6474723	Valve Adjustment: Barely Open
H-2056W	9/2/2026 1:33:36 PM	58.0	38.6	0.0	3.4			1.5	0.0	106.7	106.7	-4.09	-4.67	81.1	76.9	7.330	6.611	-9.91		28.76	1122	34.4299845	-118.6507983	Increased Flow/Vacuum,
H-2057E	9/2/2026 10:33:09 AM	53.5	38.5	1.0	7.0			1.4	7.0	127.8	127.8	-9.61	-9.75	8.4	8.4	1.543	1.532	-13.87	-13.91	28.89	1151	34.4302000	-118.6458073	Valve Adjustment: Audible Flow, Surging Liquid in Header
H-2058E	9/25/2026 8:43:12 AM	53.5	40.0	0.0	6.5			1.3	0.0	113.6	113.6	-6.02	-6.16	45.2	46.6	2.666	2.829	-9.56	-9.82	28.79	1144	34.4300565	-118.6464293	Valve Adjustment: Increased Flow/Vacuum
H-2058W	9/2/2026 1:31:18 PM	58.3	35.3	0.0	6.4			1.7	0.0	100.3	100.4	-2.90	-3.34	14.4	24.3	0.222	0.638	-10.62		28.77	1237	34.4299820	-118.6506997	Increased Flow/Vacuum,
H-2059E	9/25/2026 8:48:49 AM	54.6	41.5	0.0	3.9			1.3	0.0	117.6	117.8	-13.66	-13.81	4.8	5.6	0.491	0.691	-14.47	-14.84	28.74	1180	34.4306673	-118.6462665	Valve Adjustment: Increased Flow/Vacuum
H-2059W	9/2/2026 1:18:59 PM	57.5	41.1	0.0	1.4			1.4	0.0	123.2	123.4	-2.98	-3.50	55.9	57.0	3.637	3.793	-7.80		28.74	1211	34.4311237	-118.6503147	Increased Flow/Vacuum,
H-2161E	9/30/2026 4:18:18 PM	51.4	44.4	0.0	4.2			1.2	0.0	126.1	126.2	-4.48	-4.46	50.7	51.0	3.446	3.480	-14.70	-14.05	28.57	1189	34.4308518	-118.6464575	
H-2161W	9/2/2026 1:15:54 PM	56.7	35.7	0.0	7.6			1.6	0.0	106.0	106.2	-4.88	-5.00	51.2	49.1	2.859	2.663	-6.70		28.75	1207	34.4310272	-118.6501297	Increased Flow/Vacuum,
H-2163C	9/15/2026 10:57:08 AM	47.1	40.4	0.2	12.3			1.2	61.5	83.9	83.9	-0.81	-0.81	1.1	1.1	0.124	0.134	-13.99	-14.22	28.67	1320	34.4310977	-118.6486693	Valve Adjustment: Audible Flow
H-2163C	9/21/2026 11:35:30 AM	37.7	41.5	0.0	20.8			0.9	0.0	87.9	87.9	-0.92	-0.92	0.5	0.5	0.071	0.070	-16.62	-16.82	28.67	1322	34.4310947	-118.6486623	Valve Adjustment: Audible Flow
H-2163W	9/2/2026 9:04:51 AM	28.7	23.0	9.2	39.1			1.2	4.3	90.0	92.8	-0.29	-0.16	8.3	8.2	0.393	0.392	-13.09		28.7	1220	34.4311025	-118.6498775	NSPS/EG CAI, High O2
H-2163W	9/2/2026 9:05:57 AM	56.5	40.9	0.0	2.6			1.4	0.0	98.9	99.0	-0.38	-0.36	7.7	7.7	0.339	0.339	-14.04		28.7	1266	34.4311833	-118.6498500	NSPS/EG CAC,
H-2163W	9/22/2026 12:25:17 PM	41.6	56.0	0.0	2.4			0.7	0.0	121.0	121.0	-0.27	-0.27	16.8	17.8	1.905	2.148	-8.99		28.6	1276	34.4312177	-118.6499042	
H-2164E	9/16/2026 3:11:14 PM	25.3	35.8	0.0	38.9			0.7	0.0	127.4	127.4	-2.49	-2.37	26.3	26.0	4.526	4.418	-19.17	-18.41	28.66	1271	34.4318938	-118.6460627	
H-2164E	9/24/2026 1:20:04 PM						6000																	[User entered 0.6%]
H-2164E	9/24/2026 1:23:09 PM	25.6	33.7	0.0	40.8			0.8	0.0	122.0	122.1	-0.34	-0.34	1.9	0.9	0.022	0.006	-13.72	-13.48	28.63	1268	34.4318975	-118.6460642	Valve Adjustment: Reduce Sys. Vac. - Flare Down
H-2164E	9/24/2026 1:25:00 PM					15																		AtmAA (24 TAT Request)
H-2164E	9/24/2026 1:25:00 PM																							AtmAA (24 TAT Request); [User entered 0.13%]
H-2164E	9/24/2026 3:05:04 PM					28																		
H-2165E	9/25/2026 9:23:57 AM	47.5	47.6	0.0	4.9			1.0	0.0	125.4	125.4	-3.38	-3.21	14.1	13.2	4.319	3.761	-8.61	-8.32	28.68	1251	34.4319015	-118.6451075	Valve Adjustment: Decreased Flow/Vacuum
H-2165W	9/2/2026 8:43:14 AM	31.1	65.0	0.1	3.8			0.5	38.0	139.4	136.6	-0.88	-0.31	4.4	0.0	2.592	-0.116	-11.41		28.7	1112	34.4322225	-118.6505600	Reduced System Vacuum,
H-2165W	9/2/2026 8:45:08 AM	14.3	76.0	0.0	9.7			0.2	0.0	135.9	137.6	-0.10	-0.09	0.8	0.8	0.101	0.105	-10.85		28.7	1309	34.4320863	-118.6504058	NSPS/EG CAI, High Temp, Reduced System Vacuum
H-2165W	9/9/2026 7:00:00 AM					680																		AirTech Lab
H-2165W	9/9/2026 7:00:00 AM						51000																	AirTech Lab; [User entered 5.1%]
H-2165W	9/23/2026 8:49:44 AM	8.9	88.0	0.0	3.1			0.1	0.0	147.2	147.2	-0.90	-0.92	6.4	6.3	0.272	0.265	-13.69	-14.55	28.59	1275	34.4321350	-118.6504333	Valve Adjustment: High Temp, Barely Open, Surging Liquid in Header, Surging Liquid in Well (Watered In)
H-2165W	9/30/2026 10:38:31 AM	10.1	73.5	0.0	16.4			0.1	0.0	148.0	146.0	-0.25	-1.32	7.8	40.2	0.407	10.981	-12.05	-13.26	28.58	1274	34.4321374	-118.65041	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [""H2O]	Adj Stat Press [""H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [""H2O]	Adj Diff Press [""H2O]	Sys Pressure [""H2O]	Adj Avail Press [""H2O]	Baro Press [""Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
H-2165W	9/30/2026 11:35:00 AM					218																		AtmAA
H-2166E	9/22/2026 10:33:01 AM	50.1	40.4	0.2	9.3			1.2	46.5	118.0	118.0	-0.73	-0.73	10.3	12.2	0.643	0.893	-13.80		28.54	1348	34.4355840	-118.6438355	
H-2168C	9/1/2026 12:08:00 PM	54.9	39.4	0.5	5.2			1.4	10.4	92.8	93.2	-16.12	-15.55	25.8	24.1	0.857	0.747	-16.06	-15.74	28.67	1386	34.4344342	-118.6448075	Valve Adjustment: Audible Flow, Surging Liquid in Header
H-2168E	9/22/2026 10:07:45 AM	48.1	39.1	0.1	12.7			1.2	127.0	114.3	114.3	-0.29	-0.29	4.4	4.4	0.113	0.113	-17.36		28.54	1381	34.4345267	-118.6438742	
H-2169C	9/9/2026 1:00:48 PM	37.0	37.6	1.2	24.2			1.0	20.2	120.5	120.7	-15.93	-12.29	32.7	17.7	1.370	0.396	-19.61		28.58	1398	34.4340938	-118.6451000	
H-2169E	9/22/2026 9:11:45 AM	47.9	48.6	0.0	3.5			1.0	0.0	77.7	90.1	0.07	-0.03	11.1	7.4	0.149	0.068	-21.81	-21.34	28.55	1370	34.4342221	-118.6442052	Valve Adjustment: NSPS/EG CAI, Positive Static Press., Barely Open
H-2169E	9/22/2026 9:12:40 AM	47.6	47.9	0.0	4.5			1.0	0.0	92.8	92.9	-0.05	-0.06	6.0	5.9	0.045	0.043	-20.67	-21.63	28.55	1374	34.4342334	-118.6442060	Valve Adjustment: NSPS/EG CAC, Barely Open
H-2169E	9/22/2026 10:14:12 AM	34.9	60.5	0.0	4.6			0.6	0.0	110.8	110.9	-0.11	-0.11	10.7	10.7	0.157	0.157	-21.57		28.54	1385	34.4341422	-118.6442120	
H-2170N	9/25/2026 11:43:20 AM	30.9	35.5	0.0	33.6			0.9	0.0	121.5	121.5	-3.46	-3.28	27.6	25.2	4.942	4.121	-16.41	-16.39	28.67	1265	34.4357882	-118.6414450	Valve Adjustment: Decreased Flow/Vacuum
H-2170S	9/21/2026 12:50:35 PM	43.6	38.7	0.1	17.6			1.1	176.0	106.8	110.6	-1.01	-1.65	0.6	2.8	0.003	0.049	-20.92	-20.97	28.67	1240	34.4335887	-118.6414913	
H-2171A	9/29/2026 10:23:57 AM	33.0	35.1	0.0	31.9			0.9	0.0	100.3	100.3	-0.67	-0.68	3.1	3.2	0.996	1.115	-2.24	-2.29	28.46	1256	34.4374322	-118.6425240	
H-2171B	9/21/2026 9:19:40 AM	38.8	34.4	0.0	26.8			1.1	0.0	119.9	120.0	-3.39	-3.40	15.4	15.3	1.532	1.502	-10.93	-11.27	28.67	1259	34.4365148	-118.6416428	
H-2171N	9/29/2026 10:44:58 AM	20.4	31.5	0.0	48.1			0.6	0.0	113.1	113.1	-0.73	-0.76	7.6	6.9	0.363	0.305	-15.04	-14.89	28.45	1252	34.4379790	-118.6432537	
H-2171S	9/25/2026 11:49:39 AM	25.8	33.4	0.0	40.8			0.8	0.0	121.5	121.7	-4.77	-4.74	48.0	47.0	15.243	14.601	-16.55	-16.66	28.69	1275	34.4357843	-118.6414638	Valve Adjustment: Decreased Flow/Vacuum
H-2272W	9/2/2026 9:18:52 AM	29.7	35.1	0.0	35.2			0.8	0.0	123.3	123.3	-0.64	-0.63	24.0	25.9	3.672	4.308	-13.13		28.67	1283	34.4318203	-118.6497095	
H-2272W	9/22/2026 12:19:10 PM	31.4	35.0	0.0	33.6			0.9	0.0	122.3	122.1	-0.41	-0.40	4.5	4.6	2.249	2.365	-9.93		28.57	1247	34.4317167	-118.6497675	
H-2273W	9/2/2026 7:21:33 AM	21.3	40.8	0.0	37.9			0.5	0.0	120.7	120.7	-0.91	-0.70	5.6	5.5	0.209	0.204	-9.36		28.66	1309	34.4322882	-118.6499358	Reduced System Vacuum,
H-2273W	9/4/2026 8:32:00 AM					160																		AirTech Lab
H-2273W	9/4/2026 8:32:00 AM						18000																	AirTech Lab; [User entered 1.8%]
H-2273W	9/9/2026 7:10:00 AM					78																		AirTech Lab
H-2273W	9/9/2026 7:10:00 AM						10000																	AirTech Lab; [User entered 1.0%]
H-2273W	9/22/2026 12:09:18 PM	31.8	42.0	0.0	26.2			0.8	0.0	123.2	123.0	-0.30	-0.26	4.9	4.9	0.160	0.158	-9.85		28.56	1270	34.4321787	-118.6498992	
H-2274B	9/1/2026 2:15:59 PM	54.6	42.3	0.0	3.1			1.3	0.0	103.9	104.1	-2.06	-2.15	4.7	6.9	0.055	0.119	-5.31		28.56	1365	34.4325842	-118.6470083	Increased Flow/Vacuum,
H-2274B	9/22/2026 2:38:09 PM	53.3	43.6	0.0	3.1			1.2	0.0	107.5	107.6	-3.97	-3.97	9.3	9.4	0.233	0.239	-9.02	-9.22	28.45	1352	34.4326725	-118.6469342	Valve Adjustment: Surging Liquid in Header, Surging Liquid in Well (Watered In)
H-2274W	9/2/2026 7:28:33 AM	19.9	36.3	0.1	43.7			0.5	437.0	62.0	62.0	-0.58	-0.58	1.0	1.0	0.005	0.005	-7.73		28.66	1312	34.4327643	-118.6504502	Reduced System Vacuum,
H-2274W	9/22/2026 11:23:46 AM	13.4	30.2	1.0	55.4			0.4	55.4	99.8	99.7	-0.44	-0.44	0.0	0.0	-0.135	-0.134	-8.18		28.6	1335	34.4327530	-118.6503850	
H-2275E	9/9/2026 1:51:36 PM	46.8	40.9	0.0	12.3			1.1	0.0	116.4	116.4	-0.28	-0.28	0.0	0.0	-0.015	-0.016	-4.39		28.61	1312	34.4324457	-118.6463502	
H-2275W	9/1/2026 11:38:16 AM	10.0	19.6	6.9	63.5			0.5	9.2	122.3	125.3	-0.68	-0.63	30.1	30.0	5.825	5.801	-10.56		28.63	1257	34.4321895	-118.6494103	NSPS/EG CAI, High O2
H-2275W	9/1/2026 11:39:55 AM	27.9	31.8	0.7	39.6			0.9	56.6	128.3	127.1	-0.64	-0.63	29.7	29.7	5.629	5.633	-10.55		28.63	1266	34.4321568	-118.6493250	NSPS/EG CAC,
H-2275W	9/1/2026 11:41:12 AM	34.7	37.5	0.4	27.4			0.9	68.5	124.5	124.5	-0.82	-0.78	28.9	28.9	5.330	5.335	-10.77		28.63	1312	34.4321390	-118.6493208	
H-2275W	9/22/2026 12:53:21 PM	8.2	25.1	2.9	63.8			0.3	22.0	131.8	127.9	-0.59	-0.54	9.6	3.4	0.637	0.077	-9.28		28.54	1306	34.4322370	-118.6493817	NSPS/EG CAI, High Temp
H-2275W	9/22/2026 12:53:59 PM	8.8	25.7	3.0	62.5			0.3	20.8	122.6	122.3	-0.47	-0.48	5.5	5.6	0.204	0.205	-9.19		28.54	1306	34.4323017	-118.6493957	NSPS/EG CAC,
H-2276A	9/14/2026 1:55:11 PM	48.9	42.1	0.2	8.8			1.2	44.0	113.6	113.7	-1.39	-1.44	6.3	6.4	0.093	0.095	-7.74	-8.07	28.38	1376	34.4328953	-118.6483110	
H-2276A	9/21/2026 9:31:10 AM	47.3	41.4	0.2	11.1			1.1	55.5	112.5	112.3	-1.79	-1.67	5.4	4.8	0.067	0.053	-9.87	-8.64	28.53	1358	34.4328922	-118.6482798	Valve Adjustment: Surging Liquid in Header
H-2276B	9/1/2026 2:23:18 PM	53.8	44.3	0.0	1.9			1.2	0.0	116.6	116.9	-4.02	-4.01	16.8	15.3	0.615	0.510	-5.44		28.55	1335	34.4329073	-118.6469532	
H-2276B	9/21/2026 9:13:01 AM	56.6	41.5	0.0	1.9			1.4	0.0	119.3	119.4	-6.93	-7.00	28.0	30.5	1.866	2.212	-9.99	-10.26	28.55	1371	34.4329035	-118.6469237	Valve Adjustment: Surging Liquid in Header
H-2276E	9/9/2026 1:36:12 PM	35.2	34.7	0.0	30.1			1.0	0.0	120.9	121.0	-0.44	-0.43	1.2	1.1	0.002	0.001	-19.66		28.6	1329	34.4328458	-118.6454408	
H-2276W	9/1/2026 9:23:11 AM	24.0	44.6	0.0	31.4			0.5	0.0	101.4	101.6	-5.67	-5.69	0.6	0.6	0.002	0.002	-10.72		28.64	1293	34.4326493	-118.6499660	
H-2276W	9/22/2026 11:39:01 AM	20.6	41.0	0.0	38.4			0.5	0.0	100.4	97.7	-3.07	-2.62	12.0	9.8	0.950	0.637	-9.80		28.58	1266	34.4326307	-118.6499450	
H-2277A	9/1/2026 10:22:08 AM	32.5	37.0	3.6	26.9			0.9	7.5	91.9	91.9	-0.36	-0.35	0.6	0.6	0.002	0.002	-7.34		28.59	1358	34.4330067	-118.6487560	
H-2277A	9/17/2026 10:03:32 AM	42.5	42.3	1.8	13.4			1.0	7.4	79.7	79.9	-3.20	-3.13	2.0	1.3	0.023	0.009	-11.34	-11.33	28.67	1344	34.4330428	-118.6487440	Valve Adjustment: Barely Open
H-2277B	9/14/2026 1:34:55 PM	53.7	42.8	0.0	3.5			1.3	0.0	95.0	109.9	-4.19	-2.26	1.7	1.1	0.780	0.320	-9.01	-9.42	28.37	1392	34.4330985	-118.6469388	Valve Adjustment: Decreased Flow/Vacuum
H-2277B	9/21/2026 8:52:57 AM	53.4	40.8	0.0	5.8			1.3	0.0	110.6	111.4	-2.22	-3.17	1.2	0.6	0.400	0.103	-10.25	-10.99	28.53	1378	34.4330735	-118.6469053	Valve Adjustment: Increased Flow/Vacuum
H-23 [EXP-2]	9/21/2026 8:51:57 AM	2.7	80.6	0.0	16.7			0.0	0.0	75.7	75.8	-18.76	-18.86	3.1	2.3	0.021	0.012	-18.82	-18.82	28.66	1262	34.4370247	-118.6420965	
H-2301E	9/24/2026 1:01:31 PM	54.2	40.3	0.0	5.5			1.3	0.0	102.7	102.7	-0.87	-0.87	5.3	7.0	0.063	0.108	-4.89	-4.89	28.87	1007	34.4270662	-118.6479868	
H-2301N	9/16/2026 7:52:01 AM	54.0	35.6	0.0	10.4			1.5	0.0	89.6	91.2	-2.49	-4.84	31.9	38.8	1.257	1.884	-11.54	-12.06	28.74	1199	34.4296310	-118.6512658	
H-2301N	9/23/2026 1:05:15 PM	35.9	32.0	0.0	32.1			1.1	0.0	98.6	98.6	-5.39	-5.38	30.3	29.2	1.165	1.079	-8.83	-8.61	28.66	1197	34.4296325	-118.6512267	
H-2301W	9/28/2026 2:15:49 PM	0.1	0.4	20.8	78.7			0.4	3.8	92.1	92.4	-3.52	-3.52	0.2	0.2	0.003	0.005	-5.86	-6.17	28.63	1127	34.4274735	-118.6506552	Valve Adjustment: NSPS/EG CAI, High O2, Decreased Flow/Vacuum, Plugged/Pinched Suspected
H-2301W	9/28/2026 2:16:39 PM	0.2	0.3	20.8	78.7			0.8	3.8	94.7	94.8	-3.82	-3.81	0.2	0.2	0.002	0.002	-6.26	-6.21	28.64	1118	34.4274762	-118.6506483	Valve Adjustment: High O2, Plugged/Pinched Suspected
H-2302C	9/17/2026 1:44:50 PM	50.0	39.9	0.0	10.1			1.3	0.0	122.8	122.8	-0.52	-1.83	8.6	10.3	0.470	0.669	-11.44	-11.49	28.91	1123	34.4283940	-118.6490058	Valve Adjustment: Increased Flow/Vacuum

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [""H2O]	Adj Stat Press [""H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [""H2O]	Adj Diff Press [""H2O]	Sys Pressure [""H2O]	Adj Avail Press [""H2O]	Baro Press [""Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
H-2302C	9/17/2026 1:47:40 PM	49.7	39.9	0.0	10.4			1.2	0.0	122.8	122.8	-1.94	-2.12	11.7	12.5	0.866	0.991	-11.49	-11.08	28.91	1133	34.4283882	-118.6490128	
H-2302E	9/24/2026 1:21:07 PM	54.4	42.0	0.0	3.6			1.3	0.0	110.8	110.9	-5.58	-5.67	13.1	13.3	0.220	0.228	-5.67	-5.62	28.83	1057	34.4275162	-118.6472432	
H-2303E	9/24/2026 1:28:29 PM	56.3	39.7	0.0	4.0			1.4	0.0	101.5	101.8	-0.86	-0.82	5.2	5.9	0.034	0.043	-0.52	-0.54	28.83	1071	34.4279082	-118.6471928	Valve Adjustment:Valve 100% Open
H-2303N	9/21/2026 1:25:13 PM	37.3	33.5	3.5	25.8			1.1	7.5	107.7	107.9	-0.82	-0.81	14.4	14.1	4.298	4.139	-11.74	-11.29	28.77	1132	34.4290423	-118.6484448	
H-2303N	9/21/2026 1:31:23 PM	38.4	34.2	3.3	24.1			1.1	7.4	108.2	108.2	-0.92	-1.01	8.6	9.7	1.519	1.951	-10.94	-10.64	28.78	1139	34.4290435	-118.6484375	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
H-2303N	9/21/2026 1:36:02 PM	40.6	35.4	2.7	21.3			1.1	8.0	108.1	108.0	-1.58	-1.72	14.6	15.3	4.420	4.854	-11.07	-10.50	28.77	1140	34.4290385	-118.6484447	Valve Adjustment:Increased Flow/Vacuum
H-2303N	9/21/2026 1:42:20 PM	41.8	35.9	2.6	19.7			1.2	7.6	107.9	107.9	-3.50	-3.51	46.5	46.5	4.985	4.974	-10.25	-10.85	28.76	1140	34.4290545	-118.6484497	Valve Adjustment:Orifice Plate Changed (See OP Log)
H-2303N	9/21/2026 1:46:07 PM	41.7	35.9	2.7	19.8			1.2	7.5	108.1	108.3	-3.98	-4.05	46.9	48.3	2.829	2.997	-10.03	-10.84	28.76	1142	34.4290322	-118.6484323	Valve Adjustment:Orifice Plate Changed (See OP Log)
H-2303S	9/30/2026 9:07:20 AM	50.2	41.2	0.0	8.6			1.2	0.0	107.2	108.2	-0.50	-0.47	0.3	3.4	0.002	0.242	-1.60	-1.43	28.71	1123	34.4272932	-118.6495713	Valve Adjustment:Barely Open
H-2303S	9/30/2026 3:11:43 PM	49.0	38.4	0.0	12.6			1.3	0.0	110.8	110.8	-1.92	-1.92	29.5	28.6	1.121	1.054	-8.18	-8.17	28.66	1125	34.4272693	-118.6495643	
H-2304E	9/24/2026 1:38:49 PM	54.4	41.0	0.0	4.6			1.3	0.0	98.9	98.8	-0.17	-0.19	78.8	79.0	3.794	3.817	-3.70	-3.70	28.82	1088	34.4282307	-118.6468948	
H-2304S	9/30/2026 8:57:47 AM	48.5	40.5	0.0	11.0			1.2	0.0	112.7	112.7	-0.10	-0.20	8.4	8.2	1.470	1.406	-1.67	-1.47	28.72	1090	34.4274785	-118.6489233	Valve Adjustment:Barely Open
H-2305N	9/21/2026 1:56:13 PM	36.5	36.1	0.0	27.5			1.0	0.0	101.1	101.2	-4.57	-4.47	2.8	3.9	0.017	0.035	-8.91	-8.82	28.77	1155	34.4289977	-118.6486237	
H-2305S	9/30/2026 8:54:12 AM	53.6	43.5	0.0	2.9			1.2	0.0	127.3	127.2	-0.87	-0.86	4.3	4.8	0.118	0.147	-1.75	-1.66	28.75	1064	34.4274495	-118.6485145	Valve Adjustment:Barely Open
H-2306N	9/30/2026 10:03:45 AM	49.7	44.3	0.0	6.0			1.1	0.0	119.2	119.2	-0.15	-0.16	10.0	10.5	0.230	0.255	-1.22	-1.14	28.67	1121	34.4294033	-118.6475793	Valve Adjustment:Barely Open
H-2307S	9/28/2026 9:57:33 AM	49.1	41.1	0.2	9.6			1.2	48.1	108.0	106.9	-0.80	-0.81	21.3	22.0	1.032	1.099	-14.85	-14.50	28.67	1147	34.4284633	-118.6498320	Valve Adjustment:Increased Flow/Vacuum
H-2307S	9/28/2026 9:59:24 AM	49.2	40.7	0.2	9.9			1.2	52.1	108.5	109.0	-0.83	-0.83	22.6	22.4	1.160	1.144	-15.30	-15.06	28.68	1143	34.4284515	-118.6498218	
H-2308S	9/28/2026 9:25:41 AM	46.3	40.8	0.0	12.8			1.1	0.0	98.0	98.6	-1.31	-1.31	14.7	15.7	0.269	0.309	-10.89	-9.97	28.68	1146	34.4284533	-118.6498070	
H-2309N	9/23/2026 10:09:11 AM	46.9	39.5	0.0	13.6			1.2	0.0	103.0	103.5	-8.08	-8.73	1.4	0.9	0.013	0.005	-12.63	-17.06	28.57	1293	34.4308103	-118.6489333	Valve Adjustment:Plugged/Pinched Suspected
H-2309S	9/28/2026 1:47:35 PM	50.4	41.7	0.0	7.8			1.2	0.0	120.4	120.4	-3.16	-3.26	33.3	35.5	1.456	1.656	-7.76	-7.94	28.65	1102	34.4281662	-118.6487472	Valve Adjustment:Increased Flow/Vacuum
H-2309S	9/28/2026 1:50:05 PM	50.1	42.5	0.0	7.5			1.2	0.0	120.5	120.5	-3.38	-3.34	37.0	37.0	1.795	1.801	-8.03	-7.93	28.65	1109	34.4281502	-118.6487540	
H-2310N	9/21/2026 10:17:15 AM	55.4	41.5	0.0	3.2			1.3	0.0	110.4	110.5	-0.02	-0.03	5.7	6.1	0.669	0.762	-3.48	-3.13	28.76	1197	34.4298735	-118.6478407	
H-2310N	9/21/2026 10:23:24 AM	54.9	41.4	0.0	3.8			1.3	0.0	111.4	113.5	-0.05	-0.24	4.0	9.1	0.098	0.518	-3.32	-3.03	28.76	1172	34.4298905	-118.6478558	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
H-2310N	9/21/2026 10:25:58 AM	52.0	43.2	0.0	4.8			1.2	0.0	113.6	113.7	-0.33	-0.32	9.6	9.9	0.574	0.609	-2.84	-2.95	28.76	1183	34.4298712	-118.6478453	
H-2310S	9/30/2026 9:54:34 AM	51.8	43.0	0.0	5.2			1.2	0.0	99.6	99.6	-0.05	-0.04	5.3	4.0	0.035	0.020	-1.33	-1.22	28.71	1105	34.4291867	-118.6475135	Valve Adjustment:Barely Open
H-2401S	9/17/2026 12:53:46 PM	54.0	40.8	0.0	5.1			1.3	0.0	112.3	112.3	-13.75	-14.41	46.4	47.6	2.853	3.010	-19.11	-18.85	28.84	1187	34.4288763	-118.6512315	Valve Adjustment:Increased Flow/Vacuum,Well Comment:Recommend bigger wellhead
H-2401S	9/17/2026 12:55:27 PM	54.0	40.9	0.0	5.1			1.3	0.0	112.2	112.3	-13.68	-13.74	44.9	45.3	2.671	2.716	-17.89	-18.15	28.84	1195	34.4288703	-118.6512107	
H-2402N	9/16/2026 9:29:50 AM	35.7	36.8	0.0	27.5			1.0	0.0	111.0	110.4	-0.80	-0.29	4.0	3.1	1.688	1.048	-19.97	-21.40	28.76	1218	34.4291228	-118.6502807	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-2402N	9/16/2026 9:38:17 AM	31.8	35.6	0.0	32.6			0.9	0.0	109.6	109.8	-0.32	-0.33	0.7	0.8	0.058	0.060	-20.82	-21.19	28.76	1209	34.4291292	-118.6502657	
H-2402S	9/17/2026 10:29:36 AM	44.0	40.5	0.0	15.6			1.1	0.0	112.8	112.8	-0.43	-0.36	16.3	15.0	0.604	0.514	-20.82	-20.74	28.87	1203	34.4287675	-118.6504800	Valve Adjustment:Decreased Flow/Vacuum
H-2402S	9/17/2026 10:36:31 AM	44.2	40.1	0.0	15.8			1.1	0.0	112.8	112.8	-0.38	-0.36	15.1	15.1	0.522	0.516	-22.14	-20.69	28.87	1209	34.4287543	-118.6504988	
H-2403N	9/16/2026 9:07:19 AM	24.1	28.3	4.2	43.5			0.8	10.4	118.4	117.3	-4.48	-0.57	17.6	5.5	6.658	0.624	-20.19	-20.32	28.74	1216	34.4293012	-118.6501653	Valve Adjustment:Decreased Flow/Vacuum
H-2403N	9/16/2026 9:15:02 AM	32.5	33.3	3.2	31.1			1.0	9.8	116.6	116.5	-0.56	-0.52	5.1	5.7	0.541	0.671	-21.31	-19.67	28.75	1228	34.4292928	-118.6501797	
H-2403S	9/17/2026 9:46:50 AM	48.6	41.3	0.5	9.6			1.2	18.5	77.4	84.4	-1.32	-1.73	0.3	3.3	0.006	1.142	-19.27	-20.72	28.87	1186	34.4287493	-118.6498800	Valve Adjustment:Increased Flow/Vacuum,Barely Open
H-2403S	9/17/2026 9:55:54 AM	53.1	43.0	0.0	3.9			1.2	0.0	88.4	91.0	-1.67	-1.97	3.2	5.2	0.208	0.550	-19.38	-18.17	28.87	1182	34.4287562	-118.6498785	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
H-2403S	9/17/2026 10:14:23 AM	53.1	42.7	0.0	4.2			1.2	0.0	95.4	95.8	-2.04	-2.11	5.1	5.1	0.517	0.523	-20.13	-18.81	28.87	1185	34.4287595	-118.6498838	Valve Adjustment:Increased Flow/Vacuum
H-2404N	9/4/2026 10:12:11 AM	50.2	43.7	0.0	6.1			1.1	0.0	116.6	116.6	-4.64	-4.80	14.3	16.2	4.368	5.588	-17.58	-18.99	28.72	1214	34.4293013	-118.6495623	Valve Adjustment:Increased Flow/Vacuum
H-2404N	9/17/2026 10:16:28 AM	53.4	42.5	0.0	4.1			1.3	0.0	96.1	96.2	-2.25	-2.14	4.9	5.2	0.481	0.546	-19.16	-17.75	28.88	1178	34.4287662	-118.6498930	
H-2404S	9/17/2026 9:29:43 AM	53.9	41.4	0.0	4.7			1.3	0.0	114.9	115.0	-11.78	-11.76	26.1	25.8	0.899	0.874	-12.80	-12.67	28.9	1170	34.4287540	-118.6493110	Valve Adjustment:Valve 100% Open
H-2405N	9/30/2026 12:52:28 PM	26.8	35.9	0.0	37.3			0.7	0.0	125.6	125.5	-0.06	-0.06	3.1	2.9	0.206	0.174	-10.05	-9.18	28.63	1260	34.4300043	-118.6495265	Valve Adjustment:Audible Flow,Barely Open,Reduce Sys. Vac. - Flare Down
H-29	9/25/2026 11:24:23 AM	18.4	44.5	1.8	35.3			0.4	19.6	104.8	103.6	-0.76	-0.70	0.1	0.1	0.002	0.001	-18.75	-18.67	28.66	1273	34.4354158	-118.6417870	Valve Adjustment:Decreased Flow/Vacuum,Valve 100% Closed
H-72	9/30/2026 1:21:04 PM	41.5	55.7	0.0	2.8			0.7	0.0	101.4	101.6	-1.35	-1.35	3.6	2.7	0.017	0.009	-11.97	-12.07	28.45	1331	34.4369380	-118.6448205	
H-74	9/16/2026 11:51:01 AM	49.7	42.2	0.0	8.1			1.2	0.0	113.4	113.4	-10.85	-11.05	15.2	15.0	4.994	4.866	-15.34	-15.19	28.75	1306	34.4371967	-118.6433037	Valve Adjustment:Audible Flow
H-75	9/22/2026 2:37:52 PM	37.6	39.7	0.0	22.7			0.9	0.0	96.3	96.5	-3.14	-2.72	4.0	4.0	4.183	4.201	-18.70		28.51	1348	34.4364338	-118.6419792	
H-79	9/4/2026 9:06:09 AM	47.5	44.1	0.0	8.4			1.1	0.0	123.7	123.6	-1.14	-1.13	4.3	5.4	0.025	0.038	-17.47	-17.30	28.58	1304	34.4339352	-118.6427842	
P-02R	9/14/2026 10:11:10 AM	26.5	30.3	0.0	43.2			0.9	0.0	89.7	89.8	-0.21	-0.20	12.5	12.5	0.938	0.938	-17.86	-18.05	28.67	1161	34.4297070	-118.6439315	

All LFG Extraction Wells - Setem্বর 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Adj Avail Press ["H2O]	Baro Press ["Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
P-03R	9/14/2026 1:32:02 PM	40.3	30.0	0.0	29.7			1.3	0.0	102.9	102.8	-0.70	-0.70	2.9	3.0	0.899	0.926	-17.70	-17.61	28.63	1165	34.4298962	-118.6441943	
P-04	9/14/2026 1:26:28 PM	50.2	36.2	0.0	13.6			1.4	0.0	103.6	103.6	-0.77	-0.75			0.762	0.740	-14.84	-14.69	28.66	1175	34.4295005	-118.6445293	
P-05	9/14/2026 1:22:06 PM	39.7	33.0	0.0	27.3			1.2	0.0	106.0	106.0	-0.02	-0.01			0.030	0.034	-13.70	-13.71	28.67	1152	34.4291833	-118.6447825	
P-06R	9/14/2026 1:14:43 PM	40.7	32.4	0.0	26.9			1.3	0.0	113.9	114.9	-0.45	-0.89	1.0	2.5	0.102	0.689	-13.06	-12.90	28.67	1148	34.4288800	-118.6450652	
P-07R	9/14/2026 9:55:22 AM	30.1	26.8	0.0	43.1			1.1	0.0	89.9	89.8	-27.69	-12.16	6.6	6.7	4.814	4.814	-17.52	-17.54	28.67	1182	34.4298193	-118.6433152	
P-08R	9/14/2026 10:17:08 AM	53.1	37.7	0.0	9.2			1.4	0.0	100.4	100.4	-13.10	-12.93	12.2	11.9	0.943	0.895	-14.49	-14.13	28.68	1165	34.4294058	-118.6437460	
P-09	9/14/2026 10:29:35 AM	48.2	36.0	0.0	15.8			1.3	0.0	98.1	98.2	-0.32	-0.34			0.000	0.000	-8.82	-9.28	28.7	1159	34.4289947	-118.6443200	
P-10	9/14/2026 10:34:17 AM	41.5	33.6	0.0	24.9			1.2	0.0	96.1	96.1	-0.10	-0.09	4.3	4.3	1.888	1.911	-9.32	-9.94	28.7	1143	34.4287177	-118.6446367	
P-11	9/14/2026 10:41:27 AM	45.5	35.8	0.0	18.7			1.3	0.0	106.8	107.1	-0.31	-0.31	7.3	7.1	5.639	5.418	-9.06	-9.11	28.71	1127	34.4284882	-118.6449703	
P-12	9/14/2026 1:08:27 PM	57.2	38.9	0.0	3.9			1.5	0.0	90.1	89.9	-10.76	-10.78	1.2	1.2	0.029	0.029	-10.91	-10.79	28.69	1118	34.4288657	-118.6456145	
P-13	9/14/2026 1:02:12 PM	51.6	35.3	0.0	13.1			1.5	0.0	91.5	91.2	-0.20	-0.20	4.6	4.6	0.417	0.424	-10.83	-10.85	28.7	1105	34.4285188	-118.6458233	
P-14	9/14/2026 10:49:55 AM	27.0	27.7	0.4	44.9			1.0	112.3	87.8	88.0	-0.06	-0.06			0.000	0.000	-10.23	-10.28	28.74	1092	34.4280243	-118.6460637	
P-15R	9/11/2026 9:23:55 AM	50.1	34.4	0.0	15.5			1.5	0.0	93.3	93.6	-1.24	-1.23	1.9	1.9	0.364	0.378	-10.83	-10.38	28.78	1100	34.4277942	-118.6459262	
P-16	9/11/2026 9:31:08 AM	52.9	35.6	0.0	11.5			1.5	0.0	99.1	99.0	-2.39	-2.39	5.3	5.3	2.963	2.936	-9.93	-9.84	28.78	1092	34.4275302	-118.6455993	
P-17	9/11/2026 1:40:34 PM	37.7	29.5	0.0	32.8			1.3	0.0	114.1	114.1	-0.49	-0.49			0.426	0.381	-8.12	-8.04	28.74	1099	34.4273787	-118.6453100	
P-18RD	9/11/2026 1:30:44 PM	50.6	32.8	0.0	16.6			1.5	0.0	100.3	100.7	-7.98	-7.78	2.8	3.2	0.868	1.103	-7.83	-7.69	28.74	1110	34.4271017	-118.6449838	
P-18RS	9/11/2026 1:34:14 PM	39.2	32.8	0.0	28.0			1.2	0.0	99.8	99.8	-0.73	-0.74	5.0	5.0	2.617	2.603	-7.96	-7.64	28.74	1096	34.4271037	-118.6450097	
P-19	9/11/2026 1:55:29 PM	29.6	27.6	0.0	42.8			1.1	0.0	96.5	96.4	-0.37	-0.35	2.4	4.2	0.035	0.109	-7.35	-7.33	28.75	1070	34.4268768	-118.6451973	
P-20R	9/11/2026 1:23:45 PM	46.0	32.8	0.0	21.2			1.4	0.0	101.6	101.7	-0.89	-1.02	2.1	2.9	0.445	0.887	-7.65	-7.51	28.74	1101	34.4268375	-118.6448275	
P-21	9/11/2026 1:17:27 PM	33.6	29.2	0.0	37.2			1.2	0.0	98.9	98.5	-0.16	-0.22			0.273	0.208	-7.63	-7.72	28.74	1111	34.4264870	-118.6448013	
P-21RD	9/11/2026 1:06:36 PM	41.4	32.0	0.0	26.6			1.3	0.0	105.3	105.4	-2.91	-2.94	9.8	10.1	2.013	2.130	-6.69	-6.95	28.71	1116	34.4263808	-118.6443692	
P-21RS	9/11/2026 1:09:45 PM	44.4	35.6	0.0	20.0			1.2	0.0	110.0	110.1	-2.88	-2.89	12.3	13.4	0.346	0.408	-6.76	-6.99	28.74	1119	34.4263870	-118.6443767	
P-22RD	9/11/2026 8:08:10 AM	53.5	40.5	0.0	6.0			1.3	0.0	120.4	120.4	-3.84	-3.84	4.4	4.4	5.289	5.295	-8.34	-8.32	28.69	1175	34.4269042	-118.6437940	
P-22RS	9/11/2026 8:04:52 AM	31.5	29.8	0.0	38.7			1.1	0.0	121.9	122.0	-1.20	-1.19	26.8	27.2	1.682	1.727	-8.50	-8.41	28.68	1180	34.4269258	-118.6438105	
P-23	9/11/2026 1:01:52 PM	4.9	19.7	0.1	75.3			0.2	753.0	103.2	106.6	-0.96	-0.63	0.9	1.6	0.005	0.016	-6.85	-6.78	28.74	1087	34.4261307	-118.6446950	
P-24	9/13/2026 1:20:31 PM	20.0	27.3	0.0	52.7			0.7	0.0	101.1	101.2	-1.34	-1.32	8.5	8.3	1.470	1.414	-6.42	-6.24	28.73	1101	34.4260803	-118.6443095	
P-26	9/13/2026 1:35:13 PM	44.9	31.8	0.0	23.3			1.4	0.0	90.7	89.4	-4.52	-4.48			4.466	4.438	-6.00	-5.83	28.71	1129	34.4265215	-118.6432322	
P-27	9/13/2026 1:42:38 PM	11.1	20.9	0.0	68.0			0.5	0.0	96.8	96.9	-0.78	-0.78	1.9	2.0	0.954	1.017	-5.50	-5.81	28.71	1134	34.4268305	-118.6427857	
P-28	9/13/2026 1:49:04 PM	36.7	30.9	0.0	32.4			1.2	0.0	98.6	98.6	-3.27	-3.26			3.237	3.216	-5.57	-5.26	28.68	1149	34.4270482	-118.6422927	
P-28	9/25/2026 2:03:37 PM	37.9	25.5	1.8	34.8			1.5	19.3			-1.00	-0.29			0.090	0.011	-4.91	-4.93	28.74	1151	34.4270463	-118.6422782	Valve Adjustment:Barely Open
P-29R	9/14/2026 8:03:35 AM	28.6	29.6	0.0	41.8			1.0	0.0	87.8	87.7	-0.82	-0.82	10.9	10.9	0.710	0.717	-7.97	-8.45	28.67	1142	34.4271838	-118.6418537	
P-30R	9/14/2026 8:11:45 AM	24.2	28.5	0.0	47.3			0.8	0.0	86.7	86.7	-4.67	-4.75	11.0	11.2	2.426	2.541	-7.68	-7.65	28.67	1163	34.4274317	-118.6416140	
P-32R1	9/14/2026 8:36:49 AM	27.5	30.8	0.6	41.1			0.9	68.5	113.4	113.4	-1.47	-1.47	4.9	4.8	6.518	6.199	-7.08	-6.88	28.66	1184	34.4282325	-118.6410458	
P-32R2	9/14/2026 8:45:03 AM	32.4	32.8	0.1	34.7			1.0	347.0	110.0	110.0	-1.77	-1.77	25.5	25.4	0.834	0.828	-7.19	-7.26	28.65	1181	34.4284388	-118.6409368	
P-33	9/14/2026 8:50:19 AM	46.3	37.1	0.0	16.6			1.2	0.0	93.2	93.4	-1.09	-1.12			0.479	0.510	-1.05	-1.05	28.63	1185	34.4288372	-118.6408297	
P-36	9/14/2026 9:06:39 AM	24.9	30.3	0.0	44.8			0.8	0.0	85.6	99.7	-0.27	-2.17			0.000	1.558	-4.37	-4.14	28.63	1215	34.4301798	-118.6400528	
P-36	9/14/2026 9:07:30 AM	24.6	30.6	0.0	44.8			0.8	0.0	100.0	101.6	-2.14	-2.11			1.516	1.487	-4.43	-4.65	28.63	1223	34.4301893	-118.6400587	
P-37	9/14/2026 9:26:35 AM	11.3	25.4	0.4	62.9			0.4	157.3	93.5	93.8	-0.18	-0.27	1.7	1.7	0.704	0.715	-4.18	-4.15	28.61	1225	34.4305073	-118.6403603	
P-38RD	9/9/2026 1:02:10 PM	41.9	35.5	0.0	22.6			1.2	0.0	109.1	109.1	-2.87	-2.91	11.0	11.4	0.752	0.819	-3.40	-3.38	28.73	1222	34.4299695	-118.6406322	
P-38RS	9/9/2026 12:58:14 PM	30.6	30.1	0.0	39.3			1.0	0.0	107.9	107.9	-0.71	-0.85	10.0	13.6	0.618	1.153	-3.15	-3.31	28.74	1231	34.4299758	-118.6406440	
P-39	9/9/2026 1:09:03 PM	4.6	5.0	18.3	72.1			0.9	3.9	114.9	115.1	-4.87	-4.83	0.9	1.1	0.018	0.026	-4.64	-4.61	28.74	1222	34.4294767	-118.6409795	Valve Adjustment: NSPS/EG CAI/High O2
P-39	9/9/2026 1:12:07 PM	5.0	4.6	18.1	72.3			1.1	4.0	116.8	116.7	-4.94	-4.90	1.2	2.4	0.028	0.122	-4.69	-4.85	28.74	1221	34.4294888	-118.6409893	Valve Adjustment: NSPS/EG CAI/High O2
P-41	9/9/2026 1:35:32 PM	35.3	29.7	2.8	32.2			1.2	11.5	118.7	118.8	-5.08	-5.05			0.000	0.000	-5.43	-5.40	28.74	1221	34.4289868	-118.6414145	
P-42R	9/9/2026 1:46:37 PM	48.1	35.2	0.0	16.7			1.4	0.0	117.9	118.0	-4.76	-4.84	2.6	3.2	0.754	1.117	-5.38	-5.88	28.74	1217	34.4284240	-118.6416973	
P-43	9/9/2026 1:51:47 PM	22.7	28.4	0.4	48.5			0.8	121.3	119.1	119.1	-2.52	-2.52			2.508	2.502	-5.57	-5.50	28.74	1222	34.4282688	-118.6418300	
P-44RD	9/9/2026 1:59:38 PM	48.3	34.6	0.0	17.1			1.4	0.0	114.8	115.3	-5.26	-5.16	0.1	0.9	0.001	0.092	-5.20	-5.24	28.74	1219	34.4281448	-118.6419440	
P-44RS	9/9/2026 1:56:43 PM	20.7	25.9	0.0	53.4			0.8	0.0	123.8	123.8	-3.54	-3.52	3.2	3.2	1.136	1.107	-5.29	-5.35	28.74	1219	34.4281342	-118.6419397	
P-45RD	9/11/2026 7:34:35 AM	45.5	35.5	0.0	19.0			1.3	0.0	117.2	117.2	-7.07	-6.94	6.5	6.8	0.270	0.297	-7.80	-7.76	28.64	1224	34.4277337	-118.6424752	
P-45RS	9/11/2026 7:38:47 AM	2.6	21.3	0.0	76.1			0.1	0.0	114.0	114.0	-0.75	-0.74	3.9	3.9	4.008	4.020	0.37	0.37	28.63	1218	34.4277402	-118.6424682	
P-46RD	9/11/2026 7:48:05 AM	52.4	36.5	0.0	11.1			1.4	0.0	107.4	107.6	-7.73	-7.76	2.1	3.7	0.028	0.086	-7.49	-7.50	28.64	1			

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading [ppmv]	H2 Reading [ppmv]	CH4: CO2	BalO2	Init Temp [°F]	Adj Temp [°F]	Init Stat Press [\"H2O]	Adj Stat Press [\"H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press [\"H2O]	Adj Diff Press [\"H2O]	Sys Pressure [\"H2O]	Adj Avail Press [\"H2O]	Baro Press [\"Hg]	Elev [ft]	Latitude	Longitude	Comments
		[%]	[%]	[%]	[%]				[%]															
P-55	9/2/2026 1:11:35 PM	36.3	31.8	0.0	31.9			1.1	0.0	101.6	101.6	-0.35	-0.34			0.329	0.324	-0.33	-0.34	28.74	1228	34.4297295	-118.6427393	
P-56	9/2/2026 1:26:56 PM	19.9	26.7	0.0	53.4			0.7	0.0	104.5	104.5	-0.30	-0.20			0.240	0.235	-17.69	-17.49	28.74	1241	34.4301117	-118.6428300	
P-57	9/2/2026 1:19:29 PM	32.3	28.9	1.3	37.5			1.1	28.8	89.5	89.5	-0.19	-0.18	2.5	2.2	0.008	0.006	-16.96	-16.56	28.72	1232	34.4299682	-118.6424433	
P-60R	9/2/2026 1:44:59 PM	60.5	38.4	0.0	1.1			1.6	0.0	96.1	95.7	-2.44	-2.86	0.6	2.1	0.007	0.087	-4.25	-4.43	28.72	1240	34.4307882	-118.6415505	
P-61	9/3/2026 10:41:33 AM	42.8	35.8	0.0	21.4			1.2	0.0	88.6	88.7	-0.45	-0.43	6.7	6.3	4.669	4.070	-4.15	-3.56	28.67	1243	34.4311500	-118.6411538	
P-65	9/3/2026 10:49:34 AM	29.7	29.3	0.0	41.0			1.0	0.0	87.2	87.1	-0.92	-1.12	7.5	8.8	1.122	1.537	-4.50	-3.46	28.67	1260	34.4304112	-118.6409530	
P-71	9/11/2026 8:24:58 AM	39.5	32.8	0.0	27.7			1.2	0.0	82.4	82.7	-1.60	-1.58			0.030	0.027	-8.22	-7.77	28.66	1216	34.4279690	-118.6432200	
P-75	9/2/2026 1:35:58 PM	55.9	36.6	0.0	7.5			1.5	0.0	94.5	94.8	-3.36	-3.47	13.4	14.9	1.092	1.352	-4.09	-4.46	28.71	1259	34.4302885	-118.6415238	
P-76	9/9/2026 12:51:44 PM	19.2	27.9	0.0	52.9			0.7	0.0	120.2	120.5	-1.06	-1.08			1.058	1.023	-3.17	-3.15	28.74	1232	34.4302210	-118.6404325	
P-79	9/11/2026 1:48:37 PM	24.1	27.0	0.0	48.9			0.9	0.0	100.0	99.6	0.03	-0.11			0.014	0.113	-7.38	-7.60	28.78	1053	34.4270263	-118.6460497	
P-79	9/14/2026 7:34:29 AM	19.1	25.5	1.3	54.1			0.7	41.6	89.2	89.7	-0.52	-0.59			0.000	0.000	-10.98	-10.97	28.78	1039	34.4270218	-118.6460565	
SC-2000E	9/25/2026 8:57:52 AM	45.9	39.7	0.0	14.4			1.2	0.0	120.7	120.7	-3.66	-3.40	5.8	5.3	0.726	0.598	-10.12	-9.73	28.72	1208	34.4307137	-118.6467738	Valve Adjustment:Decreased Flow/Vacuum
SC-2501E	9/8/2026 9:59:28 AM	2.6	71.6	0.4	25.4			0.0	63.5	189.2	189.3	-2.54	-2.55			2.539	2.529	-5.07	-5.15	28.61				Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open
SC-2501E	9/8/2026 10:01:00 AM					1240																		AtmAA
SC-2501E	9/14/2026 9:17:00 AM					1190																		AtmAA
SC-2501E	9/14/2026 9:21:21 AM	10.6	69.6	1.3	18.5			0.2	14.2	188.8	189.1	-4.34	-3.20			4.331	3.188	-7.38	-8.09	28.49	1334	34.4366658	-118.6479245	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum
SC-2501E	9/14/2026 9:23:51 AM	14.0	68.9	0.9	16.2			0.2	18.0	189.2	189.1	-3.07	-3.05			3.060	3.043	-8.09	-7.71	28.49	1338	34.4366885	-118.6479270	Valve Adjustment:No Flow Measurement,High Temp
SC-2501E	9/21/2026 9:24:00 AM					1120																		AtmAA
SC-2501E	9/21/2026 9:24:06 AM	12.2	72.7	0.9	14.2			0.2	15.8	189.9	189.9	-3.30	-3.30			3.296	3.300	-10.46	-10.78	28.59	1338	34.4367003	-118.6479188	Valve Adjustment:No Flow Measurement,High Temp
SC-2501E	9/28/2026 8:44:16 AM	9.2	72.4	0.9	17.5			0.1	19.4	189.9	189.8	-3.19	-3.18			3.195	3.188	-10.74	-10.61	28.46	1345	34.4366886	-118.6478967	Valve Adjustment:No Flow Measurement,High Temp
SC-2501E	9/28/2026 8:50:00 AM					1140																		AtmAA
SC-2501W	9/14/2026 1:14:36 PM	2.2	73.5	0.5	23.8			0.0	47.6	190.3	190.3	-3.26	-2.66			3.210	2.562	-3.78	-4.65	28.55	1363	34.4367787	-118.6485455	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
SC-2501W	9/14/2026 1:16:00 PM	2.5	73.3	0.4	23.8			0.0	59.5	190.3	190.3	-2.81	-2.83			2.756	2.754	-4.29	-4.15	28.56	1356	34.4367882	-118.6485310	Valve Adjustment:No Flow Measurement,High Temp
SC-2501W	9/21/2026 9:47:01 AM	13.5	67.7	2.1	16.7			0.2	8.0	189.2	189.2	-2.41	-2.46	18.2	18.4	2.395	2.442	-7.55	-7.52	28.58	1353	34.4367967	-118.6485404	Valve Adjustment:No Flow Measurement,High Temp
SC-2501W	9/21/2026 9:50:00 AM					722																		AtmAA
SC-2501W	9/28/2026 9:27:48 AM	16.8	64.8	1.8	16.6			0.3	9.2	188.8	188.9	-3.30	-3.29	21.2	21.2	3.271	3.259	-6.81	-6.99	28.46	1350	34.4367775	-118.6485433	Valve Adjustment:No Flow Measurement,High Temp
SC-2501W	9/28/2026 9:30:00 AM					741.5																		AtmAA
SW-10	9/28/2026 10:08:23 AM	19.5	35.0	2.2	43.3			0.6	19.7	89.7	89.9	-14.78	-14.78	13.7	12.6	0.242	0.204	-17.42	-17.60	28.55	1330	34.4370338	-118.6503715	
SW-115	9/17/2026 1:39:25 PM	41.5	34.0	1.0	23.5			1.2	23.5	90.2	90.2	-16.91	-16.96	24.9	24.6	3.907	3.812	-20.62	-20.51	28.81	1202	34.4348293	-118.6412152	
SW-1445	9/29/2026 12:27:40 PM	39.0	31.6	0.1	29.3			1.2	293.0	92.5	92.2	-4.39	-5.04	0.9	3.9	0.001	0.019	-5.13	-5.08	28.55	1228	34.4324977	-118.6520037	Valve Adjustment:Reconnected this Date
SW-1455	9/30/2026 4:06:16 PM	48.4	39.4	0.0	12.2			1.2	0.0	113.7	114.9	-3.56	-5.01	2.9	4.8	0.011	0.030	-5.44	-5.22	28.55	1217	34.4325137	-118.6519597	Valve Adjustment:Reconnected this Date,Increased Flow/Vacuum
SW-154	9/30/2026 2:17:21 PM	0.0	2.9	19.5	77.6			0.0	4.0	105.2	105.4	-13.68	-13.68			13.760	13.751	-13.59	-13.67	28.53	1267	34.4379645	-118.6456497	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-17-135	9/30/2026 4:01:25 PM	38.3	27.5	0.0	34.2			1.4	0.0	111.1	111.9	-4.08	-5.46	3.2	0.8	0.013	0.001	-5.43	-5.34	28.55	1216	34.4325153	-118.6519583	Valve Adjustment:Reconnected this Date,Increased Flow/Vacuum
SW-187	9/23/2026 9:03:24 AM	19.3	40.9	1.9	37.9			0.5	19.9	83.6	83.9	-15.87	-15.86	9.7	9.7	0.023	0.023	-15.98	-15.96	28.59	1310	34.4372337	-118.6473478	
SW-20	9/14/2026 10:03:19 AM	0.0	4.7	15.9	79.4			0.0	5.0	93.7	94.2	-4.02	-3.98	23.8	23.8	0.706	0.709	-17.52	-17.52	28.67	1170	34.4302225	-118.6436447	Valve Adjustment:NSPS/EG CAI,High O2
SW-20	9/14/2026 10:04:06 AM	0.0	4.8	16.0	79.2			0.0	5.0	94.7	94.6	-5.34	-5.35	23.9	23.8	0.718	0.715	-17.66	-17.75	28.67	1170	34.4302227	-118.6436470	Valve Adjustment:NSPS/EG CAI,High O2
SW-2501D	9/28/2026 8:51:48 AM	0.5	5.8	19.5	74.2			0.1	3.8	74.7	74.7	-14.44	-14.27	20.0	20.7	0.500	0.531	-14.40	-14.22	28.63	1236	34.4335223	-118.6519685	
SW-2501M	9/28/2026 8:37:05 AM	14.7	24.8	12.2	48.3			0.6	4.0	67.5	67.5	-14.18	-14.17	20.0	20.1	0.493	0.496	-14.22	-14.22	28.62	1234	34.4335150	-118.6520013	
SW-2501MB	9/28/2026 8:48:27 AM	21.0	52.3	3.5	23.2			0.4	6.6	72.4	72.5	-12.14	-12.09	6.1	5.6	0.225	0.192	-14.27	-14.22	28.63	1240	34.4335137	-118.6519903	
SW-2501S	9/28/2026 8:34:18 AM	4.2	11.6	11.1	73.1			0.4	6.6	65.9	65.9	-14.11	-14.11	18.0	18.0	0.395	0.396	-14.26	-14.26	28.63	1237	34.4335185	-118.6519930	
SW-2502D	9/28/2026 1:31:44 PM	7.0	79.2	0.1	13.7			0.1	137.0	93.8	93.9	-14.53	-14.53	1.5	1.5	0.230	0.254	-14.56	-14.52	28.62	1233	34.4337208	-118.6519175	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-2502M	9/28/2026 1:35:12 PM	0.0	3.5	19.6	76.9			0.0	3.9	94.5	94.5	-7.14	-7.14	0.3	0.3	0.010	0.010	-14.63	-14.62	28.63	1223	34.4337085	-118.6519090	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-2502MD	9/28/2026 9:07:21 AM	6.6	49.6	9.8	34.0			0.1	3.5	82.3	82.3	-14.15	-14.16	1.7	1.7	0.302	0.308	-14.22	-14.23	28.63	1232	34.4337310	-118.6519317	
SW-2502S	9/28/2026 9:04:57 AM	5.2	23.9	10.4	60.5			0.2	5.8	82.5	82.5	-14.11	-14.11	1.7	1.7	0.315	0.315	-14.27	-14.27	28.63	1236	34.4337335	-118.6519282	
SW-2503D	9/28/2026 9:31:14 AM	2.9	11.7	17.2	68.2			0.2	4.0	81.0	81.1	-14.11	-14.11	4.8	4.8	0.140	0.140	-14.21	-14.21	28.6	1267	34.4351315	-118.6516038	
SW-2503M	9/28/2026 9:36:56 AM	0.0	1.5	20.0	78.5			0.0	3.9	85.9	86.6	-10.41	-10.41	3.8	3.7	0.091	0.086	-14.17	-14.22	28.61	1280	34.4351258	-118.6515968	
SW-2503MD	9/28/2026 9:43:35 AM	5.2	21.3	12.5	61.0			0.2	4.9	86.2	86.2	-14.11	-14.11	5.7	5.6	0.202	0.192	-14.31	-14.56	28.62	1264	34.4351190	-118.6515960	
SW-2503S	9/28/2026 9:40:46 AM	12.3	22.7	12.3	52.7			0.5	4.3	82.0	82.1	-14.15	-14.20	6.0	6.0	0.221	0.225	-14.35	-14.37	28.6	1276	34.4351215	-118.6515818	
SW-2504D	9/28/2026 9:56:00 AM	0.2	1.6	19.5	78.7			0.1	4.0	81.4	81.5	-14.26	-14.11	3.8	2.5	0.087	0.038	-14.36	-14.56	28.61	1274	34.4353063	-118.6516703	

All LFG Extraction Wells - Setember 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4	CO2	O2	Bal Gas	CO Reading	H2 Reading	CH4:CO2	BalO2	Init Temp	Adj Temp	Init Stat Press	Adj Stat Press	Init Flow	Adj Flow	Init Diff Press	Adj Diff Press	Sys Pressure	Adj Avail Press	Baro Press	Elev	Latitude	Longitude	Comments	
		[%]	[%]	[%]	[%]	[ppmv]	[ppmv]		[%]	[°F]	[°F]	[\"H2O]	[\"H2O]	[scfm]	[scfm]	[\"H2O]	[\"H2O]	[\"H2O]	[\"H2O]	[\"Hg]	[ft]				
SW-2504M	9/28/2026 9:49:08 AM	0.1	2.4	19.6	77.9				0.0	4.0	85.0	85.2	-7.05	-7.05	4.3	4.2	0.111	0.108	-14.32	-14.47	28.63	1271	34.4353008	-118.6516693	
SW-2504MC	9/28/2026 9:59:28 AM	12.5	28.8	7.7	51.0				0.4	6.6	82.7	82.9	-16.48	-16.57	6.6	6.4	0.272	0.252	-16.62	-16.73	28.63	1272	34.4353142	-118.6516715	
SW-2504S	9/28/2026 9:52:36 AM	14.4	14.4	10.9	60.3				1.0	5.5	85.6	85.7	-14.21	-14.11	4.1	4.9	0.103	0.149	-14.27	-14.18	28.6	1264	34.4353082	-118.6516607	
SW-30	9/28/2026 8:56:46 AM	5.1	27.6	11.2	56.1				0.2	5.0	73.2	73.5	-13.98	-13.90	5.8	5.6	0.206	0.191	-14.22	-14.22	28.63	1233	34.4336635	-118.6519505	
SW-32	9/28/2026 8:26:06 AM	14.0	53.1	7.6	25.3				0.3	3.3	71.2	71.6	-14.11	-14.11	10.1	10.2	0.613	0.629	-14.44	-14.56	28.63	1234	34.4335182	-118.6520110	
SW-64	9/28/2026 8:59:49 AM	13.0	76.2	1.2	9.6				0.2	8.0	77.6	77.4	-14.11	-14.11	6.7	6.8	0.275	0.281	-14.22	-14.22	28.63	1232	34.4336715	-118.6519532	
SW-65	9/17/2026 10:54:03 AM	36.4	33.5	0.9	29.2				1.1	32.4	87.8	87.8	-17.60	-17.75	4.6	5.3	0.129	0.173	-23.34	-23.26	28.85	1208	34.4348230	-118.6412032	
SW-65	9/17/2026 11:10:21 AM	43.3	55.0	0.0	1.7				0.8	0.0	110.6	110.4	-7.25	-7.24			7.419	7.425	-23.61	-23.63	28.85	1213	34.4348453	-118.6412638	
SW-66	9/30/2026 2:19:22 PM	6.0	6.1	13.9	74.0				1.0	5.3	91.8	91.8	-12.34	-12.26			12.402	12.317	-12.36	-12.32	28.53	1280	34.4379620	-118.6456293	Valve Adjustment:Reduce Sys. Vac. - Flare Down
SW-68	9/28/2026 8:30:14 AM	13.1	34.5	1.8	50.6				0.4	28.1	66.4	66.4	-14.11	-14.23	13.8	7.6	1.141	0.345	-14.35	-14.47	28.62	1238	34.4335178	-118.6519883	
SW-70	9/23/2026 9:06:01 AM	14.5	66.2	0.9	18.4				0.2	20.4	89.1	89.1	-15.79	-15.83	7.5	0.0	0.013	0.000	-16.00	-16.25	28.62	1320	34.4372307	-118.6473725	
SW-71	9/13/2026 1:27:50 PM	13.5	17.5	7.2	61.8				0.8	8.6	95.2	95.1	-6.12	-6.08	2.6	2.4	0.715	0.597	-6.25	-6.08	28.71	1126	34.4259810	-118.6438412	Valve Adjustment: NSPS/EG CAI,High O2
SW-71	9/13/2026 1:29:03 PM	13.4	17.6	7.1	61.9				0.8	8.7	95.1	95.1	-6.13	-6.12	2.3	2.4	0.566	0.632	-6.07	-6.16	28.71	1123	34.4259863	-118.6438483	Valve Adjustment: NSPS/EG CAI,High O2
SW-72	9/14/2026 8:57:13 AM	22.8	22.4	5.0	49.8				1.0	10.0	76.6	76.4	-4.82	-4.26	2.7	2.7	0.758	0.760	-4.89	-5.08	28.63	1207	34.4296373	-118.6401932	
SW-80	9/3/2026 12:03:20 PM	27.1	28.6	1.8	42.5				0.9	23.6	92.6	93.3	-9.08	-9.08	6.2	6.2	0.234	0.234	-15.23	-15.23	28.75	1231	34.4383017	-118.6433473	
SW-9	9/23/2026 9:09:10 AM	0.9	20.8	13.2	65.1				0.0	4.9	86.4	86.4	-15.79	-15.79	31.5	29.8	0.241	0.215	-16.14	-16.21	28.62	1317	34.4372213	-118.6473733	
TC-1961C	9/24/2026 11:07:18 AM	6.0	24.0	0.0	70.0				0.3	0.0	118.5	118.5	-1.84	-1.80	5.9	7.1	0.082	0.117	-13.74	-13.83	28.58	1302	34.4321850	-118.6454320	Valve Adjustment:Surging Liquid in Header
TC-1961E	9/1/2026 9:15:54 AM	45.2	48.9	0.0	5.9				0.9	0.0	125.0	124.8	-3.54	-2.87	5.9	13.6	0.082	0.433	-17.37	-17.52	28.65	1296	34.4328613	-118.6444795	Valve Adjustment:Decreased Flow/Vacuum
TC-2174	9/8/2026 9:41:41 AM	1.4	78.8	0.0	19.8				0.0	0.0	185.6	185.6	-1.97	-1.94			1.980	1.959	0.04	0.04	28.63	1348	34.4367493	-118.6476344	Valve Adjustment:No Flow Measurement,High Temp
TC-2174	9/8/2026 9:44:00 AM					1880																		AtmAA	
TC-2174	9/14/2026 8:44:26 AM	3.3	78.6	0.0	18.1				0.0	0.0	185.7	185.7	-3.95	-3.94			3.923	3.911	0.00	0.00	28.49	1337	34.4367498	-118.6476372	Valve Adjustment:No Flow Measurement,High Temp
TC-2174	9/14/2026 8:47:00 AM					2370																		AtmAA	
TC-2174	9/21/2026 9:00:00 AM					2080																		AtmAA	
TC-2174	9/21/2026 9:00:43 AM	6.3	77.1	0.0	16.6				0.1	0.0	185.7	185.6	-3.90	-3.94			3.884	3.941	0.29	0.29	28.57	1338	34.4367669	-118.6476533	Valve Adjustment:No Flow Measurement,High Temp
TC-2174	9/28/2026 8:20:43 AM	2.0	77.9	0.0	20.1				0.0	0.0	185.8	185.9	-4.78	-4.76			4.752	4.750	0.00	0.00	28.46	1348	34.4367395	-118.6476302	Valve Adjustment:No Flow Measurement,High Temp
TC-2174	9/28/2026 8:25:00 AM					1710																		AtmAA	
VL-02	9/30/2026 10:59:45 AM	59.1	34.6	0.2	6.1				1.7	30.5	99.8	100.2	-2.01	-2.05	40.5	40.7	2.004	2.023	0.67	0.67	28.69	1167	34.4311722	-118.6443214	Valve Adjustment:Valve 100% Open