

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-108-52	9/1/2026 7:25:00 AM					450						Air Tech Lab
CV-108-52	9/1/2026 7:25:00 AM						130000					Air Tech Lab; [User entered 13%]
CV-108-52	9/2/2026 7:35:40 AM	15.6	69.0	0.0	15.4			61.0	60.7	10.57	12.65	NSPS/EG CAI,Positive Static Press.,Reduced System Vacuum
CV-108-52	9/2/2026 7:36:35 AM	15.6	71.2	0.0	13.2			59.0	59.0	11.01	11.01	NSPS/EG CAI,Positive Static Press.,Reduced System Vacuum
CV-108-52	9/10/2026 3:44:09 PM	48.6	51.3	0.0	0.1			107.3	108.9	1.07	-1.86	Valve Adjustment:NSPS/EG CAC,Increased Flow/Vacuum,Barely Open
CV-108-52	9/10/2026 3:44:53 PM	49.6	50.4	0.0	0.0			108.7	108.6	-2.85	-2.89	
CV-108-52	9/22/2026 11:11:22 AM	40.7	35.6	4.5	19.2			97.8	97.9	-9.72	-9.17	
CV-113	9/4/2026 7:00:00 AM					37						AirTech Lab
CV-113	9/4/2026 7:00:00 AM						0					AirTech Lab; [User entered 0%]
CV-113	9/14/2026 9:34:21 AM	0.3	1.6	18.7	79.4			97.6	97.8	-0.02	-0.02	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In)
CV-113	9/14/2026 9:35:35 AM	2.4	1.9	18.0	77.7			98.9	98.9	-0.03	-0.02	
CV-113	9/25/2026 10:33:54 AM	12.8	19.1	13.0	55.1			106.0	106.1	-0.01	-0.01	Valve Adjustment:High O2,Barely Open
CV-114	9/4/2026 8:22:00 AM					2200						AirTech Lab
CV-114	9/4/2026 8:22:00 AM						180000					AirTech Lab; [User entered 18%]
CV-114	9/8/2026 9:33:48 AM	0.8	81.3	0.0	17.9			189.9	189.8	-4.74	-4.61	Valve Adjustment:No Flow Measurement,High Temp
CV-114	9/8/2026 9:39:00 AM					3460						AtmAA
CV-114	9/14/2026 8:28:09 AM	1.5	82.9	0.0	15.6			188.9	189.0	-7.52	-7.31	Valve Adjustment:No Flow Measurement,High Temp
CV-114	9/14/2026 8:30:00 AM					3730						AtmAA
CV-114	9/21/2026 8:22:00 AM	3.0	79.4	0.0	17.6			189.0	189.0	-4.77	-4.56	Valve Adjustment:No Flow Measurement,High Temp
CV-114	9/28/2026 8:16:00 AM	2.6	0.0	0.0	97.4			188.8	188.8	-8.17	-8.17	Valve Adjustment:No Flow Measurement,High Temp
CV-1532A	9/1/2026 7:30:00 AM					1400						Air Tech Lab
CV-1532A	9/1/2026 7:30:00 AM						230000					AirTech Lab; [User entered 23%]
CV-1532A	9/1/2026 1:33:46 PM	1.2	70.8	1.1	26.9			101.4	102.1	-3.50	-3.64	Valve Adjustment:No Flow Measurement
CV-1532A	9/30/2026 3:06:52 PM	0.7	75.5	0.9	22.9			167.0	167.2	-7.59	-7.76	

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-1535	9/1/2026 9:18:24 AM	45.5	48.3	0.0	6.2			105.4	105.5	-0.58	-0.53	,
CV-1535	9/4/2026 7:22:00 AM					2800						AirTech Lab
CV-1535	9/4/2026 7:22:00 AM						180000					AirTech Lab; [User entered 18%]
CV-1535	9/22/2026 11:06:11 AM	28.1	36.2	0.0	35.7			125.6	125.5	-6.94	-5.60	,
CV-1535	9/24/2026 2:43:07 PM	29.6	40.2	0.0	30.2			126.1	125.8	-5.40	-4.58	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header
CV-1902A	9/1/2026 7:35:00 AM					310						Air Tech Lab
CV-1902A	9/1/2026 7:35:00 AM						43000					Air Tech Lab; [User entered 4.3%]
CV-1902A	9/8/2026 10:47:01 AM	2.5	75.0	0.2	22.3			158.4	159.4	-5.70	-5.63	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-1902A	9/8/2026 10:50:00 AM					1290						AtmAA
CV-1902A	9/16/2026 2:32:50 PM	12.4	72.3	1.3	14.0			157.7	157.8	-6.63	-6.42	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-1902A	9/23/2026 2:32:08 PM	10.3	77.5	0.0	12.2			182.5	181.6	-7.43	-7.12	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-1902A	9/30/2026 2:40:44 PM	9.6	64.4	2.6	23.4			154.5	155.0	-6.05	-6.02	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2001	9/2/2026 8:39:57 AM	9.5	69.9	2.0	18.6			79.4	79.5	-8.38	-8.03	Reduced System Vacuum,
CV-2001	9/9/2026 7:20:00 AM					1100						AirTech Lab
CV-2001	9/9/2026 7:20:00 AM						100000					AirTech Lab; [User entered 10%]
CV-2001	9/23/2026 8:47:00 AM	4.6	54.5	7.5	33.4			85.7	86.5	-11.67	-11.60	Valve Comment:Well too tall
CV-2002	9/1/2026 2:10:00 PM					3900						AtmAA
CV-2002	9/1/2026 2:10:00 PM						117100					AtmAA; [User entered 11.71%]
CV-2002	9/1/2026 2:10:13 PM	12.4	71.4	0.3	15.9			185.8	185.8	-6.92	-6.94	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2002	9/8/2026 1:42:58 PM	15.2	73.0	0.6	11.2			185.6	185.6	-5.92	-5.00	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2002	9/8/2026 1:45:00 PM					4130						AtmAA
CV-2002	9/9/2026 7:25:00 AM					2900						AirTech Lab
CV-2002	9/9/2026 7:25:00 AM						140000					AirTech Lab; [User entered 14%]

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2002	9/17/2026 8:11:35 AM	24.9	67.9	0.4	6.8			183.5	183.4	-6.40	-6.23	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	9/24/2026 9:58:49 AM	9.8	72.3	0.0	17.9			184.2	184.3	-10.65	-10.45	Valve Adjustment:No Flow Measurement,High Temp
CV-2007	9/3/2026 10:00:55 AM	16.8	76.7	0.0	6.5			126.2	126.3	-1.12	-1.15	Valve Adjustment:Barely Open
CV-2007	9/4/2026 7:48:00 AM					470						AirTech Lab
CV-2007	9/4/2026 7:48:00 AM						62000					AirTech Lab; [User entered 6.2%]
CV-2007	9/25/2026 2:05:13 PM	9.6	40.3	2.3	47.8			147.0	147.2	-1.11	-1.15	Valve Adjustment:High Temp,Barely Open
CV-2007	9/28/2026 10:15:15 AM	8.3	37.5	2.7	51.5			152.5	152.5	-2.02	-2.02	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2007	9/30/2026 10:12:39 AM	8.3	36.1	3.0	52.6			150.5	148.3	-1.88	-1.23	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-2007	9/30/2026 10:14:47 AM	8.0	36.4	3.3	52.3			146.5	146.4	-1.14	-1.13	Valve Adjustment:High Temp;Well Comment:Bad valve on well head;Well Condition:Fair;Well Repairs:Valve
CV-2301	9/2/2026 9:11:34 AM	20.2	64.6	0.0	15.2			179.1	179.0	-9.44	-9.27	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	9/2/2026 9:13:00 AM					775						AtmAA
CV-2301	9/2/2026 9:13:00 AM						55700					AtmAA; [User entered 5.57%]
CV-2301	9/3/2026 6:40:00 AM					470						AirTech Lab
CV-2301	9/3/2026 6:40:00 AM						55000					AirTech Lab; [User entered 5.5%]
CV-2301	9/8/2026 9:59:02 AM	22.0	48.9	3.9	25.2			167.1	167.3	-6.41	-6.37	NSPS/EG CAI,High Temp
CV-2301	9/8/2026 10:00:00 AM					1170						AtmAA
CV-2301	9/16/2026 1:46:53 PM	25.4	69.6	0.0	5.0			179.6	177.6	-5.55	-5.05	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	9/23/2026 1:27:45 PM	44.1	55.9	0.0	0.0			175.3	174.9	-6.56	-6.44	Valve Adjustment:No Flow Measurement,High Temp
CV-2301	9/30/2026 10:14:35 AM	43.3	46.5	10.2	0.0			174.4	174.6	-9.58	-8.80	Valve Adjustment:No Flow Measurement,High Temp
CV-2302	9/2/2026 8:56:46 AM	43.0	45.2	1.1	10.7			125.8	125.7	-12.16	-12.16	Valve Comment:Valve stuck open;Valve Adjustment:Valve 100% Open
CV-2302	9/3/2026 6:45:00 AM					0						AirTech Lab
CV-2302	9/3/2026 6:45:00 AM						35000					AirTech Lab; [User entered 3.5%]
CV-2302	9/17/2026 10:41:57 AM	44.5	45.0	1.1	9.4			113.0	113.3	-11.03	-12.03	
CV-2303	9/3/2026 6:50:00 AM					1700						AirTech Lab

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2303	9/3/2026 6:50:00 AM						190000					AirTech Lab; [User entered 19%]
CV-2303	9/3/2026 7:49:00 AM					2165						AtmAA
CV-2303	9/3/2026 7:49:00 AM						187500					AtmAA; [User entered 18.75%]
CV-2303	9/3/2026 7:52:16 AM	2.1	73.6	0.0	24.3			190.5		0.45		Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2303	9/3/2026 7:53:05 AM	3.2	79.0	0.0	17.8			188.1	189.1	0.46	0.41	Valve Adjustment:No Flow Measurement,High O2;Well Condition:Lorentz Pump Installed
CV-2303	9/9/2026 8:46:47 AM	8.8	39.4	0.2	51.6			188.7	188.8	-0.25	-0.23	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2303	9/9/2026 8:50:00 AM					2470						AtmAA
CV-2303	9/15/2026 9:24:00 AM	9.7	61.8	0.0	28.5			188.5	189.6	0.43	0.44	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2303	9/15/2026 9:25:00 AM					2620						AtmAA
CV-2303	9/22/2026 9:19:07 AM	6.4	78.9	0.0	14.7			192.6	193.1	0.26	0.22	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2305	9/1/2026 10:04:00 AM					2310						AtmAA
CV-2305	9/1/2026 10:04:00 AM						50300					AtmAA; [User entered 5.03%]
CV-2305	9/1/2026 10:04:41 AM	36.5	59.2	0.0	4.3			158.7	158.8	-4.76	-4.73	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	9/9/2026 8:05:00 AM					1200						AirTech Lab
CV-2305	9/9/2026 8:05:00 AM						47000					AirTech Lab; [User entered 4.7%]
CV-2305	9/9/2026 10:42:39 AM	27.0	71.2	0.0	1.8			155.5	155.6	-4.99	-3.44	Valve Adjustment:High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2305	9/9/2026 10:43:11 AM	35.9	57.4	0.0	6.7			155.7	155.7	-2.38	-2.34	
CV-2305	9/9/2026 11:00:00 AM					2760						AtmAA
CV-2305	9/15/2026 2:00:00 PM					2740						AtmAA
CV-2305	9/15/2026 2:02:20 PM	26.5	73.5	0.0	0.0			163.4	163.8	0.86	-1.38	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2305	9/15/2026 2:04:55 PM	26.3	73.7	0.0	0.0			163.6	163.7	-1.56	-1.51	Valve Adjustment: NSPS/EG CAC, High Temp; Well Condition: Lorentz Pump Installed
CV-2305	9/22/2026 2:28:38 PM	16.0	81.6	0.0	2.4			157.9	157.9	-5.10	-5.10	Valve Adjustment: High Temp; Well Condition: Lorentz Pump Installed
CV-2305	9/29/2026 1:49:58 PM	35.5	60.1	0.0	4.4			158.9	159.0	-6.52	-6.61	Valve Adjustment: High Temp; Well Condition: Lorentz Pump Installed
CV-2305	9/30/2026 10:01:12 AM	20.9	51.5	0.0	27.6			157.5	157.6	-8.45	-8.56	Valve Adjustment: High Temp; Well Condition: Lorentz Pump Installed
CV-2312-PLR	9/2/2026 8:09:16 AM	3.5	83.0	0.0	13.5			168.3	168.3	-3.87	-3.44	Valve Adjustment: No Flow Measurement, High Temp
CV-2312-PLR	9/3/2026 7:00:00 AM					2600						AirTech Lab
CV-2312-PLR	9/3/2026 7:00:00 AM						160000					AirTech Lab; [User entered 16%]
CV-2312-PLR	9/9/2026 1:24:41 PM	17.4	71.0	0.1	11.5			169.7	169.6	-3.71	-3.72	Valve Adjustment: No Flow Measurement, High Temp
CV-2312-PLR	9/9/2026 1:35:00 PM					3410						AtmAA
CV-2312-PLR	9/16/2026 10:44:19 AM	5.0	79.9	0.0	15.1			169.6	169.5	-2.65	-2.15	Valve Adjustment: No Flow Measurement, High Temp
CV-2312-PLR	9/23/2026 10:29:16 AM	43.9	53.5	2.6	0.0			170.0	170.1	-34.37	-34.04	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed
CV-2312-PLR	9/23/2026 1:10:56 PM	6.8	79.1	0.0	14.1			169.8	169.8	-4.53	-4.39	Valve Adjustment: No Flow Measurement, High Temp
CV-2312-PLR	9/30/2026 9:44:29 AM	6.4	79.0	0.0	14.6			169.9	170.0	-9.62	-9.44	Valve Adjustment: No Flow Measurement, High Temp
CV-2314-PLR	9/1/2026 1:32:37 PM	11.3	76.9	0.0	11.8			187.2	187.3	-13.88	-13.98	Valve Adjustment: No Flow Measurement, High Temp
CV-2314-PLR	9/1/2026 1:38:00 PM					4010						AtmAA
CV-2314-PLR	9/1/2026 1:38:00 PM						120100					AtmAA; [User entered 12.01%]
CV-2314-PLR	9/4/2026 7:56:00 AM					2700						AirTech Lab
CV-2314-PLR	9/4/2026 7:56:00 AM						130000					AirTech Lab; [User entered 13%]
CV-2314-PLR	9/9/2026 1:40:13 PM	23.0	76.3	0.0	0.7			188.1	188.1	-7.74	-7.41	Valve Adjustment: No Flow Measurement, High Temp
CV-2314-PLR	9/9/2026 1:46:00 PM					2810						AtmAA
CV-2314-PLR	9/16/2026 9:39:58 AM	6.1	84.0	0.1	9.8			187.9	187.8	-4.97	-5.18	Valve Adjustment: No Flow Measurement, High Temp
CV-2314-PLR	9/23/2026 9:37:50 AM	9.3	79.1	0.6	11.0			186.3	186.2	-12.90	-12.87	Valve Adjustment: No Flow Measurement, High Temp

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2314-PLR	9/30/2026 8:54:14 AM	5.1	82.0	0.2	12.7			185.5	185.5	-11.15	-11.08	Valve Adjustment:No Flow Measurement,High Temp
CV-2315	9/3/2026 9:13:05 AM	14.8	74.0	0.1	11.1			184.9	185.1	-2.07	-2.39	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	9/3/2026 9:17:00 AM					2450						AtmAA
CV-2315	9/3/2026 9:17:00 AM						123800					AtmAA; [User entered 12.38%]
CV-2315	9/4/2026 8:04:00 AM					2200						AirTech Lab
CV-2315	9/4/2026 8:04:00 AM						170000					AirTech Lab; [User entered 17%]
CV-2315	9/8/2026 1:48:37 PM	4.4	79.7	0.0	15.9			179.1	180.6	-0.43	-0.46	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	9/8/2026 1:51:00 PM					2730						AtmAA
CV-2315	9/14/2026 10:40:35 AM	17.7	69.7	0.0	12.6			191.7	191.8	-1.77	-1.67	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	9/14/2026 10:44:00 AM					1710						AtmAA
CV-2315	9/21/2026 10:37:20 AM	29.6	64.3	0.0	6.1			187.2	187.3	-4.79	-4.52	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	9/28/2026 10:36:48 AM	23.8	66.4	0.0	9.8			187.5	187.5	-5.20	-4.66	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2328	9/1/2026 2:21:10 PM	43.1	56.9	0.0	0.0			152.5	152.9	-3.85	-3.75	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2328	9/1/2026 2:25:00 PM					1690						AtmAA
CV-2328	9/1/2026 2:25:00 PM						2600					AtmAA; [User entered 0.26%]
CV-2328	9/9/2026 7:45:00 AM					630						AirTech Lab
CV-2328	9/9/2026 7:45:00 AM						62000					AirTech Lab; [User entered 6.2%]
CV-2328	9/9/2026 1:45:59 PM	50.5	49.5	0.0	0.0			119.1	119.1	-2.47	-2.38	Well Condition:Lorentz Pump Installed
CV-2328	9/24/2026 10:56:47 AM	37.6	56.8	0.1	5.5			151.3	151.3	-7.73	-7.05	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2328	9/24/2026 10:58:35 AM	36.2	57.1	0.0	6.7			151.1	151.3	-7.05	-7.05	
CV-2328	9/28/2026 2:24:07 PM	35.2	63.1	0.0	1.7			148.1	148.4	-7.55	-7.56	Valve Adjustment:High Temp
CV-2328	9/30/2026 8:52:17 AM	38.1	55.8	0.0	6.1			145.4	145.4	-8.94	-8.94	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2333	9/3/2026 7:45:00 AM					2700						AirTech Lab

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2333	9/3/2026 7:45:00 AM						190000					AirTech Lab; [User entered 19%]
CV-2333	9/8/2026 9:30:41 AM	1.2	65.8	0.0	33.0			184.2	184.4	-5.48	-5.22	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2333	9/8/2026 9:35:00 AM					4040						AtmAA
CV-2333	9/14/2026 8:23:05 AM	1.9	84.2	0.0	13.9			186.5	186.6	-7.65	-7.58	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2333	9/14/2026 8:25:00 AM					5050						AtmAA
CV-2333	9/21/2026 8:18:24 AM	2.4	80.9	0.0	16.7			187.9	187.9	-5.73	-5.73	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2333	9/28/2026 8:08:07 AM	1.0	78.3	0.0	20.7			189.0	189.0	-9.52	-9.10	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2334	9/3/2026 7:50:00 AM					2600						AirTech Lab
CV-2334	9/3/2026 7:50:00 AM						140000					AirTech Lab; [User entered 14%]
CV-2334	9/9/2026 12:10:26 PM	9.0	77.9	0.2	12.9			145.6	145.6	-1.32	-1.44	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2334	9/9/2026 12:10:43 PM	8.5	79.4	0.3	11.8			145.6	145.6	-1.49	-1.49	Valve Adjustment:High Temp,Barely Open
CV-2334	9/17/2026 12:59:56 PM	13.2	73.2	0.0	13.6			147.7	147.7	-3.43	-3.44	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2334	9/24/2026 1:44:17 PM	13.3	77.9	0.0	8.8			154.5	154.5	0.96	-0.98	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2334	9/24/2026 1:45:33 PM	11.5	74.4	0.0	14.1			154.7	154.7	-1.01	-1.00	Valve Adjustment:NSPS/EG CAC,High Temp;Well Condition:Lorentz Pump Installed
CV-2337	9/8/2026 10:57:52 AM	4.7	79.0	0.1	16.2			153.3	153.4	-1.73	-1.72	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2337	9/8/2026 11:00:00 AM					4780						AtmAA
CV-2337	9/10/2026 9:00:00 AM					2000						AirTech Lab
CV-2337	9/10/2026 9:00:00 AM						100000					AirTech Lab; [User entered 10%]
CV-2337	9/16/2026 2:19:44 PM	15.3	0.0	0.0	84.7			153.7	153.8	-1.09	-1.06	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2337	9/23/2026 2:21:55 PM	13.4	75.9	0.0	10.7			144.7	144.6	-7.37	-7.16	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2337	9/30/2026 2:20:16 PM	7.9	76.1	0.0	16.0			138.8	138.7	-7.92	-7.71	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2341	9/10/2026 8:29:15 AM	1.5	75.0	0.1	23.4			87.3	87.7	4.01	-1.90	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-2341	9/10/2026 8:30:27 AM	1.4	75.5	0.0	23.1			88.0	88.0	-2.28	-2.26	Valve Adjustment:NSPS/EG CAC
CV-2341	9/10/2026 8:45:00 AM					1500						AirTech Lab
CV-2341	9/10/2026 8:45:00 AM						220000					AirTech Lab; [User entered 22.%]
CV-2341	9/24/2026 2:48:06 PM	5.5	69.3	0.4	24.8			102.0	102.0	-8.55	-8.44	Valve Adjustment:Decreased Flow/Vacuum
CV-2344	9/1/2026 7:15:00 AM					1500						Air Tech Lab
CV-2344	9/1/2026 12:55:13 PM	10.7	76.2	0.0	13.1			141.6	142.2	-3.39	-3.41	Valve Adjustment:No Flow Measurement;Well Condition:Lorentz Pump Installed
CV-2344	9/1/2026 7:15:00 PM						110000					Air Tech Lab; [User entered 11%]
CV-2344	9/8/2026 1:49:02 PM	12.4	80.3	0.0	7.3			150.4	150.5	-1.60	-1.56	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2344	9/8/2026 1:50:00 PM					2700						AtmAA
CV-2344	9/8/2026 1:50:10 PM	12.1	80.1	0.0	7.8			150.8	150.8	-1.50	-1.50	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2344	9/14/2026 10:26:52 AM	12.3	67.3	0.0	20.4			147.1	147.4	-5.64	-5.66	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2344	9/14/2026 10:32:00 AM					2050						AtmAA
CV-2344	9/24/2026 9:12:30 AM	11.1	69.4	0.0	19.5			158.7	158.9	-6.09	-6.07	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2345	9/1/2026 7:10:00 AM					450						Air Tech Lab
CV-2345	9/1/2026 7:10:00 AM						33000					Air Tech Lab; [User entered 3.3%]
CV-2345	9/2/2026 7:32:38 AM	19.8	65.4	0.0	14.8			93.5	93.6	-3.62	-3.60	Reduced System Vacuum,
CV-2345	9/22/2026 11:32:10 AM	17.6	65.8	0.3	16.3			109.5	109.5	-3.85	-3.85	,
CV-2346	9/1/2026 7:05:00 AM					540						Air Tech Lab
CV-2346	9/1/2026 7:05:00 AM						53000					Air Tech Lab; [User entered 5.3%]
CV-2346	9/1/2026 10:35:00 AM					532						AtmAA
CV-2346	9/1/2026 10:35:00 AM						16600					AtmAA; [User entered 1.66%]

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2346	9/1/2026 10:36:56 AM	2.2	78.3	0.0	19.5			180.8	180.2	-7.84	-7.85	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	9/8/2026 2:30:00 PM					2740						AtmAA
CV-2346	9/8/2026 2:32:55 PM	11.4	81.2	0.1	7.3			179.4	179.6	-4.99	-4.97	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-2346	9/14/2026 10:07:15 AM	2.2	74.4	0.0	23.5			184.5	184.6	-6.55	-6.54	Valve Adjustment:No Adjustments Made
CV-2346	9/14/2026 10:09:25 AM	1.6	76.0	0.0	22.4			184.7	184.6	-7.13	-6.89	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2346	9/14/2026 10:10:00 AM					1720						AtmAA
CV-2346	9/24/2026 9:07:33 AM	4.5	81.8	0.0	13.7			187.3	187.2	-6.30	-6.14	Valve Adjustment:No Flow Measurement,High Temp
CV-2347	9/1/2026 6:55:00 AM					610						Air Tech Lab
CV-2347	9/1/2026 6:55:00 AM						46000					Air Tech Lab; [User entered 4.6%]
CV-2347	9/2/2026 7:17:45 AM	14.4	48.6	0.2	36.8			91.2	91.0	-3.87	-3.88	,
CV-2347	9/22/2026 12:05:58 PM	14.6	47.0	1.1	37.3			117.6	117.7	-3.52	-3.53	,
CV-2348	9/1/2026 6:50:00 AM						28000					Air Tech Lab; [User entered 2.8%]
CV-2348	9/1/2026 6:50:00 PM					380						Air Tech Lab
CV-2348	9/2/2026 7:12:27 AM	19.9	51.5	0.1	28.5			131.4	131.4	-9.05	-9.02	NSPS/EG CAI,High Temp
CV-2348	9/2/2026 7:13:13 AM	19.9	51.7	0.1	28.3			131.4	131.5	-9.18	-9.11	NSPS/EG CAI,High Temp
CV-2348	9/22/2026 12:12:09 PM	19.0	51.4	0.0	29.6			137.6	137.6	-8.62	-8.65	NSPS/EG CAI,High Temp
CV-2348	9/22/2026 12:13:11 PM	18.8	53.3	0.0	27.9			137.9	137.9	-8.79	-8.76	NSPS/EG CAI,High Temp
CV-2349	9/1/2026 2:05:00 AM						151900					AtmAA; [User entered 15.19%]
CV-2349	9/1/2026 2:02:58 PM	3.1	71.2	0.7	25.0			162.2	161.7	-2.58	-2.59	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2349	9/1/2026 2:05:00 PM					2770						AtmAA
CV-2349	9/2/2026 7:50:00 AM					2900						AirTech Lab
CV-2349	9/2/2026 7:50:00 AM						200000					AirTech Lab; [User entered 20%]
CV-2349	9/8/2026 1:35:00 PM					3020						AtmAA
CV-2349	9/8/2026 1:37:23 PM	9.1	77.3	0.7	12.9			164.0	163.8	2.35	1.83	NSPS/EG CAI,High Temp,Positive Static Press.,Reduced System Vacuum
CV-2349	9/8/2026 1:38:01 PM	9.5	80.8	0.3	9.4			163.4	163.5	1.50	1.56	NSPS/EG CAI,High Temp,Positive Static Press.,Reduced System Vacuum

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2349	9/17/2026 9:37:56 AM	10.3	75.6	0.0	14.1			176.9	178.0	1.36	0.12	Valve Adjustment: NSPS/EG CAI, Positive Static Press., Increased Flow/Vacuum, Valve 100% Open, Surging Liquid in Header; Well Condition: Lorentz Pump Installed
CV-2349	9/24/2026 9:55:30 AM	10.2	72.1	0.0	17.7			181.6	181.7	-1.34	-1.31	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed
CV-2350	9/1/2026 7:20:00 AM					3400						Air Tech Lab
CV-2350	9/1/2026 7:20:00 AM						170000					Air Tech Lab; [User entered 17%]
CV-2350	9/2/2026 8:27:52 AM	6.2	69.6	1.0	23.2			75.8	75.6	-8.15	-7.24	Reduced System Vacuum,
CV-2350	9/23/2026 9:06:15 AM	5.1	79.7	0.3	14.9			117.3	117.4	-11.21	-11.98	Well Comment: valve stuck open
CV-2351	9/2/2026 7:15:00 AM					220						AirTech Lab
CV-2351	9/2/2026 7:15:00 AM						27000					AirTech Lab; [User entered 2.7%]
CV-2351	9/10/2026 12:26:23 PM	19.0	47.9	5.4	27.7			118.4	118.2	-4.07	-3.88	Valve Adjustment: NSPS/EG CAI, High O2, Surging Liquid in Well (Watered In)
CV-2351	9/10/2026 12:27:25 PM	18.2	45.7	5.5	30.6			118.0	117.9	-3.76	-4.02	
CV-2351	9/23/2026 9:53:22 AM	0.0	9.2	19.0	71.8			96.7	96.6	-7.22	-7.02	Valve Adjustment: High O2, Surging Liquid in Header, Surging Liquid in Well (Watered In), Plugged/Pinched Suspected; Well Comment: valve stuck open
CV-2352	9/2/2026 7:20:00 AM					820						AirTech Lab
CV-2352	9/2/2026 7:20:00 AM						190000					AirTech Lab; [User entered 19%]
CV-2352	9/10/2026 11:57:24 AM	3.8	73.5	0.6	22.1			146.1	144.6	-3.85	-2.44	Valve Adjustment: NSPS/EG CAI, High Temp, Decreased Flow/Vacuum, Surging Liquid in Well (Watered In); Well Condition: Pneumatic Pump Installed
CV-2352	9/10/2026 11:59:11 AM	3.7	74.6	0.2	21.5			144.6	144.6	-2.47	-2.61	
CV-2352	9/30/2026 3:26:31 PM	18.1	68.1	0.1	13.7			189.3	190.5	-2.82	-2.85	Valve Adjustment: High Temp
CV-2353-PLR	9/2/2026 7:54:07 AM	4.1	68.4	1.0	26.5			90.4	91.2	-5.78	-5.73	Reduced System Vacuum,
CV-2353-PLR	9/10/2026 8:40:00 AM					560						AirTech Lab
CV-2353-PLR	9/10/2026 8:40:00 AM						230000					AirTech Lab; [User entered 23%]
CV-2353-PLR	9/30/2026 4:20:22 PM	1.9	39.9	8.9	49.3			140.6	142.2	-9.79	-9.79	Valve Adjustment: High Temp, High O2

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2354	9/2/2026 7:45:00 AM					1400						AirTech Lab
CV-2354	9/2/2026 7:45:00 AM						150000					AirTech Lab; [User entered 15%]
CV-2354	9/2/2026 8:05:50 AM	7.2	73.8	0.0	19.0			163.2	163.4	5.27	4.47	NSPS/EG CAI,High Temp,Positive Static Press.
CV-2354	9/2/2026 8:06:24 AM	7.4	74.5	0.1	18.0			162.5	162.2	2.07	4.58	NSPS/EG CAI,High Temp,Positive Static Press.
CV-2354	9/8/2026 8:08:52 AM	5.4	74.5	0.0	20.1			187.3	188.2	1.40	-0.48	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2354	9/8/2026 8:10:05 AM	5.3	70.3	0.0	24.4			188.7	188.0	-0.13	-0.10	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2354	9/8/2026 9:08:00 AM					1530						AtmAA
CV-2354	9/17/2026 9:46:30 AM	11.4	75.6	0.0	13.0			187.6	188.0	-4.82	-4.72	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2354	9/24/2026 9:34:17 AM	9.4	72.7	0.0	17.9			182.2	182.3	-9.36	-8.93	Valve Adjustment:No Flow Measurement,High Temp
CV-2354	9/24/2026 9:47:15 AM	7.7	71.3	0.3	20.7			110.3	110.5	-10.53	-10.30	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24002	9/10/2026 8:53:47 AM	35.4	49.0	0.0	15.6			112.6	111.9	-4.31	-3.21	Valve Adjustment:Decreased Flow/Vacuum
CV-24002	9/16/2026 2:44:36 PM	35.4	49.1	0.1	15.4			111.0	110.3	-3.19	-3.18	Valve Adjustment:Barely Open
CV-24003	9/14/2026 9:33:43 AM	26.1	40.5	0.6	32.8			104.8	105.0	-2.27	-2.27	Valve Adjustment:Barely Open
CV-24003	9/16/2026 2:48:11 PM	30.2	54.6	0.2	15.0			106.5	106.6	-1.52	-1.53	Valve Adjustment:Barely Open
CV-24007	9/1/2026 1:41:17 PM	26.5	46.2	0.1	27.2			145.5	145.7	-3.05	-2.88	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24007	9/3/2026 7:10:00 AM					400						AirTech Lab
CV-24007	9/3/2026 7:10:00 AM						51000					AirTech Lab; [User entered 5.1%]
CV-24007	9/8/2026 3:13:15 PM	16.2	67.7	0.0	16.1			166.8	166.8	-1.82	-1.79	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24007	9/8/2026 3:15:00 PM					1040						AtmAA
CV-24007	9/15/2026 8:10:00 AM					283						AtmAA
CV-24007	9/15/2026 8:12:16 AM	28.1	41.7	0.0	30.2			144.4	144.3	-3.30	-3.30	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24007	9/29/2026 9:01:50 AM	20.3	40.7	0.1	38.9			145.4	145.5	-4.55	-2.04	Valve Adjustment: NSPS/EG CAI, High Temp, Decreased Flow/Vacuum, Reduce Sys. Vac. - Flare Down; Well Condition: Pneumatic Pump Installed
CV-24007	9/29/2026 9:03:57 AM	13.4	65.5	0.0	21.1			146.3	146.5	-1.74	-1.75	
CV-24017	9/9/2026 7:35:00 AM					1400						AirTech Lab
CV-24017	9/9/2026 7:35:00 AM						160000					AirTech Lab; [User entered 16%]
CV-24017	9/9/2026 8:19:35 AM	20.9	71.3	0.4	7.4			176.0	176.4	-5.05	-4.88	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed
CV-24017	9/9/2026 8:21:00 AM					1095						AtmAA
CV-24017	9/15/2026 8:47:21 AM	17.7	52.5	0.0	29.8			186.7	186.8	-4.81	-4.72	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed
CV-24017	9/15/2026 8:51:00 AM					1110						AtmAA
CV-24017	9/22/2026 8:31:48 AM	19.7	69.8	0.7	9.8			174.5	174.0	-4.46	-4.45	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed
CV-24017	9/29/2026 8:02:00 AM	19.2	66.5	0.9	13.4			167.3	167.1	-7.79	-7.85	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed
CV-24049	9/10/2026 9:20:00 AM					1700						AirTech Lab
CV-24049	9/10/2026 9:20:00 AM						150000					AirTech Lab; [User entered 15%]
CV-24049	9/14/2026 9:39:50 AM	4.0	77.2	0.0	18.8			183.4	183.4	-5.97	-5.97	NSPS/EG CAI, High Temp
CV-24049	9/14/2026 9:40:16 AM	4.2	78.7	0.0	17.1			183.8	183.8	-5.71	-5.78	NSPS/EG CAI, High Temp
CV-24049	9/14/2026 10:45:00 AM					2200						AtmAA
CV-24049	9/21/2026 9:40:32 AM	4.5	71.0	0.0	24.5			187.6	188.7	-10.06	-4.11	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed
CV-24049	9/21/2026 9:41:36 AM	4.5	74.2	0.0	21.3			189.2	189.3	-5.33	-5.26	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed
CV-24049	9/28/2026 2:11:38 PM	8.0	78.8	0.0	13.2			187.9	187.8	-4.47	-4.46	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed
CV-24053	9/8/2026 7:40:00 AM					58						AirTech Lab
CV-24053	9/8/2026 7:40:00 AM						8800					AirTech Lab; [User entered 0.88%]

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24053	9/14/2026 10:03:36 AM	31.7	46.1	0.0	22.2			106.3	106.7	-7.56	-6.96	
CV-24053	9/23/2026 1:26:37 PM	28.6	49.0	0.2	22.2			118.6	119.2	-8.20	-7.30	Valve Adjustment:Decreased Flow/Vacuum
CV-24055	9/10/2026 9:25:00 AM					1400						AirTech Lab
CV-24055	9/10/2026 9:25:00 AM						85000					AirTech Lab; [User entered 8.5%]
CV-24055	9/14/2026 9:36:06 AM	4.9	55.9	3.0	36.2			122.0	122.3	-0.89	-0.88	
CV-24055	9/30/2026 8:16:47 AM	4.6	41.3	5.3	48.8			151.0	151.0	-1.29	-1.28	Valve Adjustment:NSPS/EG CAI,High Temp,High O2;Well Condition:Lorentz Pump Installed
CV-24055	9/30/2026 8:17:55 AM	4.5	41.9	5.1	48.5			151.0	151.0	-1.27	-1.27	
CV-24062	9/1/2026 2:14:11 PM	35.7	64.2	0.0	0.1			175.4	175.7	-4.89	-4.89	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	9/1/2026 2:15:00 PM					942.5						AtmAA
CV-24062	9/1/2026 2:15:00 PM						102100					AtmAA; [User entered 10.21%]
CV-24062	9/3/2026 7:20:00 AM					840						AirTech Lab
CV-24062	9/3/2026 7:20:00 AM						110000					AirTech Lab; [User entered 11%]
CV-24062	9/10/2026 8:48:00 AM					1200						AtmAA
CV-24062	9/16/2026 10:09:38 AM	29.5	65.0	0.0	5.5			173.3	173.7	-3.86	-3.78	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	9/23/2026 10:16:47 AM	40.6	59.4	0.0	0.0			178.3	178.8	-9.64	-9.56	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	9/30/2026 9:17:26 AM	19.7	75.5	0.0	4.8			170.1	170.4	-9.06	-9.06	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	9/1/2026 2:00:39 PM	8.4	79.6	0.0	12.0			186.3	186.3	-4.86	-4.53	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	9/1/2026 2:05:00 PM					1970						AtmAA
CV-24063	9/1/2026 2:05:00 PM						96900					AtmAA; [User entered 9.69%]
CV-24063	9/3/2026 7:20:00 AM					1400						AirTech Lab
CV-24063	9/3/2026 7:20:00 AM						110000					AirTech Lab; [User entered 11%]
CV-24063	9/10/2026 8:38:00 AM					1230						AtmAA

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24063	9/10/2026 8:38:14 AM	17.9	79.7	0.0	2.4			188.1	185.2	9.05	-3.06	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24063	9/10/2026 8:39:09 AM	17.9	76.6	0.0	5.5			184.9	184.7	-3.25	-3.27	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	9/14/2026 2:32:38 PM	11.5	76.5	0.0	12.0			183.6	183.7	-1.34	-1.21	Valve Comment:Installed new flow device well head;Valve Adjustment:Orifice Plate Changed (See OP Log),Valve 100% Open
CV-24063	9/15/2026 10:47:20 AM	11.5	74.0	0.0	14.5			183.9	184.0	-3.66	-3.66	
CV-24063	9/17/2026 12:22:16 PM	9.6	75.9	0.0	14.5					-4.20	-4.22	
CV-24063	9/17/2026 1:33:24 PM	21.7	70.2	0.0	8.1			167.8	167.7	-3.30	-3.27	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	9/23/2026 10:11:45 AM	32.2	67.7	0.0	0.1			167.4	167.5	-6.71	-6.44	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	9/30/2026 9:08:35 AM	24.7	75.3	0.0	0.0			133.5	133.1	-5.16	-5.14	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24064-PLR	9/1/2026 1:18:43 PM	37.6	58.3	0.0	4.1			191.4	191.5	-12.71	-12.97	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-PLR	9/1/2026 1:25:00 PM					2350						AtmAA
CV-24064-PLR	9/1/2026 1:25:00 PM						121100					AtmAA; [User entered 12.11%]
CV-24064-PLR	9/3/2026 7:30:00 AM					1600						AirTech Lab
CV-24064-PLR	9/3/2026 7:30:00 AM						140000					AirTech Lab; [User entered 14%]
CV-24064-PLR	9/9/2026 1:28:11 PM	47.8	52.2	0.0	0.0			191.7	192.6	-6.37	-5.83	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-PLR	9/9/2026 1:32:00 PM					1940						AtmAA
CV-24064-PLR	9/10/2026 8:45:01 AM	18.7	75.7	0.0	5.6			175.2	175.6	-5.39	-5.10	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24064-PLR	9/16/2026 9:05:32 AM	35.8	64.2	0.0	0.0			190.2	191.1	-3.71	-3.34	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-PLR	9/23/2026 9:22:59 AM	46.5	53.5	0.0	0.0			188.2	189.7	-11.55	-11.46	Valve Adjustment:No Flow Measurement,High Temp

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24064-PLR	9/30/2026 8:38:49 AM	37.9	56.7	0.0	5.4			188.1	188.5	-9.75	-9.65	Valve Adjustment:No Flow Measurement,High Temp
CV-24065-TP17	9/3/2026 8:57:02 AM	12.8	53.4	2.0	31.8			113.3	113.3	-4.29	-3.61	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24065-TP17	9/8/2026 7:50:00 AM					290						AirTech Lab
CV-24065-TP17	9/8/2026 7:50:00 AM						15000					AirTech Lab; [User entered 1.5%]
CV-24065-TP17	9/22/2026 10:39:59 AM	14.0	42.9	0.9	42.2			126.3	126.5	-5.40	-4.94	Valve Adjustment:Decreased Flow/Vacuum
CV-24066	9/1/2026 9:11:21 AM	21.0	41.6	0.1	37.3			89.1	89.3	-1.60	-1.58	,
CV-24066	9/10/2026 8:15:00 AM					250						AirTech Lab
CV-24066	9/10/2026 8:15:00 AM						23000					AirTech Lab; [User entered 2.3%]
CV-24066	9/22/2026 11:00:28 AM	16.9	44.9	0.0	38.2			102.6	103.9	-1.50	-1.52	,
CV-24066	9/24/2026 2:36:50 PM	18.0	42.6	0.0	39.4			123.0	122.8	-1.48	-1.48	Valve Adjustment:Barely Open
CV-24069	9/2/2026 8:53:53 AM	21.7	49.7	0.1	28.5			117.5	116.7	-1.22	-1.22	Valve Adjustment:Barely Open
CV-24069	9/8/2026 7:00:00 AM					580						AirTech Lab
CV-24069	9/8/2026 7:00:00 AM						64000					AirTech Lab; [User entered 6.4%]
CV-24069	9/28/2026 10:46:59 AM	11.9	44.8	0.2	43.1			126.3	126.4	-1.48	-1.49	Valve Adjustment:Barely Open
CV-24070	9/2/2026 8:55:00 AM					1590						AtmAA
CV-24070	9/2/2026 8:55:00 AM						64200					AtmAA; [User entered 6.42%]
CV-24070	9/2/2026 8:55:24 AM	29.3	64.5	0.0	6.2			149.4	149.4	-2.30	-2.33	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24070	9/8/2026 7:10:00 AM					1000						AirTech Lab
CV-24070	9/8/2026 7:10:00 AM						82000					AirTech Lab; [User entered 8.2%]
CV-24070	9/9/2026 1:57:00 PM	32.2	67.7	0.1	0.0			119.1	119.1	0.69	-0.97	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24070	9/9/2026 1:57:46 PM	30.7	69.2	0.1	0.0			119.1	119.1	-1.05	-1.04	
CV-24070	9/10/2026 1:57:00 PM					1370						AtmAA
CV-24070	9/10/2026 1:59:57 PM	33.6	66.4	0.0	0.0			150.7	150.7	-2.40	-2.47	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24070	9/16/2026 1:30:24 PM	42.9	57.1	0.0	0.0			144.7	144.7	-3.79	-4.01	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24071	9/2/2026 9:40:06 AM	24.9	68.0	0.0	7.1			138.4	138.3	-0.53	-0.72	Valve Adjustment:High Temp,Barely Open;Well Condition:Lorentz Pump Installed

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24071	9/8/2026 7:15:00 AM					550						AirTech Lab
CV-24071	9/8/2026 7:15:00 AM						74000					AirTech Lab; [User entered 7.4%]
CV-24071	9/17/2026 2:19:48 PM	33.7	60.4	0.0	5.9			134.7	134.0	-3.15	-1.97	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open
CV-24075-TP15	9/1/2026 1:27:41 PM	25.5	71.0	1.0	2.5			178.5	178.4	-10.56	-10.32	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TP15	9/1/2026 1:34:00 PM					1740						AtmAA
CV-24075-TP15	9/1/2026 1:34:00 PM						67500					AtmAA; [User entered 6.75%]
CV-24075-TP15	9/9/2026 1:36:18 PM	31.9	66.8	1.3	0.0			181.5	181.6	-6.76	-6.40	Valve Adjustment:Other - See Daily Log,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TP15	9/9/2026 1:41:00 PM					2030						AtmAA
CV-24075-TP15	9/16/2026 9:26:05 AM	10.8	82.6	0.0	6.6			182.3	182.3	-4.13	-4.11	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TP15	9/23/2026 9:31:50 AM	37.0	62.2	0.8	0.0			181.4	181.5	-11.74	-11.50	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TP15	9/30/2026 8:50:15 AM	27.7	66.7	1.3	4.3			179.1	179.2	-10.45	-10.45	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	9/1/2026 9:39:47 AM	22.7	57.4	0.0	19.9			143.9	140.9	-3.28	-3.34	NSPS/EG CAI,High Temp
CV-24077	9/1/2026 11:02:58 AM	21.6	66.2	0.0	12.2			136.0	136.1	-3.57	-3.57	NSPS/EG CAI,High Temp
CV-24077	9/1/2026 2:25:00 PM					1330						AtmAA
CV-24077	9/1/2026 2:25:00 PM						40000					AtmAA; [User entered 4%]
CV-24077	9/1/2026 2:29:54 PM	26.5	69.3	0.0	4.2			154.1	153.7	-3.11	-3.11	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	9/8/2026 10:33:07 AM	13.8	68.9	0.0	17.3			157.3	157.6	-1.79	-1.81	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24077	9/8/2026 10:35:00 AM					1800						AtmAA
CV-24077	9/14/2026 9:40:00 AM					1290						AtmAA
CV-24077	9/14/2026 9:41:46 AM	15.5	60.1	0.0	24.4			157.7	157.8	-3.28	-3.34	Valve Adjustment:No Adjustments Made;Well Comment:lortenz pump installed

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24077	9/14/2026 10:22:00 AM	14.6	65.1	0.0	20.3			157.5	157.3	-3.03	-2.95	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	9/22/2026 12:59:33 PM	11.5	75.8	0.0	12.7			154.3	154.5	-3.37	-3.38	NSPS/EG CAI,High Temp
CV-24077	9/22/2026 1:00:24 PM	12.5	78.5	0.0	9.0			155.1	155.1	-3.33	-3.33	NSPS/EG CAI,High Temp
CV-24077	9/23/2026 1:52:12 PM	25.8	60.5	0.0	13.7			156.0	156.2	-3.53	-3.53	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	9/30/2026 1:57:09 PM	24.7	63.6	0.0	11.7			156.0	156.0	-3.20	-3.15	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24079-TP8	9/1/2026 10:56:25 AM	0.8	83.0	0.0	16.2			94.4	94.4	-0.50	-0.48	
CV-24079-TP8	9/21/2026 11:00:53 AM	18.8	68.1	0.1	13.0			170.4	169.1	-2.37	-1.20	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24079-TP8	9/21/2026 11:03:19 AM	8.1	76.6	0.1	15.2			169.1	170.4	-1.08	-1.10	
CV-24079-TP8	9/28/2026 10:34:01 AM	19.0	75.6	0.0	5.4			166.5	166.1	-1.73	-1.75	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24079-TP8	9/30/2026 9:17:09 AM	20.2	64.4	0.0	15.4			162.3	163.3	-2.12	-2.11	Valve Adjustment:No Flow Measurement,High Temp
CV-24082	9/2/2026 9:30:43 AM	43.2	54.8	0.0	2.0			122.8	122.5	-6.42	-5.74	Valve Adjustment:Decreased Flow/Vacuum
CV-24082	9/17/2026 1:53:48 PM	43.3	53.8	0.0	2.9			126.1	125.2	-4.92	-3.79	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24083	9/2/2026 8:49:34 AM	30.6	66.2	0.0	3.2			157.9	158.8	-2.59	-2.56	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24083	9/2/2026 8:50:00 AM					1430						AtmAA
CV-24083	9/2/2026 8:50:00 AM						76700					AtmAA; [User entered 7.67%]
CV-24083	9/8/2026 10:18:45 AM	19.3	68.8	0.1	11.8			152.8	153.8	-0.46	-0.44	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24083	9/8/2026 10:20:00 AM					1360						AtmAA
CV-24083	9/17/2026 1:55:13 PM	40.8	59.2	0.0	0.0			154.0	152.8	-2.29	-2.23	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24083	9/23/2026 1:23:41 PM	7.6	74.2	0.0	18.2			149.5	148.0	-7.12	-7.08	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24083	9/30/2026 10:01:53 AM	39.9	60.1	0.0	0.0			137.8	138.2	-9.44	-9.38	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP11	9/2/2026 8:41:51 AM	28.3	71.2	0.0	0.5			185.2	185.4	-7.28	-6.82	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP11	9/2/2026 8:45:00 AM					2215						AtmAA
CV-24084-TP11	9/2/2026 8:45:00 AM						106300					AtmAA; [User entered 10.63%]
CV-24084-TP11	9/8/2026 10:20:41 AM	2.3	80.9	0.0	16.8			187.2	187.4	-4.28	-3.40	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24084-TP11	9/8/2026 10:25:00 AM					3620						AtmAA
CV-24084-TP11	9/17/2026 1:59:08 PM	39.8	60.2	0.0	0.0			186.2	186.0	-5.27	-4.79	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP11	9/23/2026 1:16:20 PM	7.0	79.8	0.0	13.2			186.1	186.3	-4.81	-4.46	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP11	9/30/2026 9:57:04 AM	8.2	79.0	0.0	12.8			185.3	185.2	-8.02	-7.08	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24088	9/2/2026 1:21:22 PM	47.4	52.6	0.0	0.0			112.6	113.1	-2.03	-2.03	Valve Adjustment:Barely Open
CV-24088	9/17/2026 3:03:53 PM	44.8	51.9	0.1	3.2			104.5	104.8	-2.43	-2.40	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24095	9/1/2026 1:57:31 PM	5.3	71.6	0.0	23.1			186.0	186.2	-2.41	-2.42	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24095	9/1/2026 2:00:00 PM					2620						AtmAA
CV-24095	9/1/2026 2:00:00 PM						159300					AtmAA; [User entered 15.93%]
CV-24095	9/8/2026 1:30:00 PM					2940						AtmAA
CV-24095	9/8/2026 1:31:41 PM	7.6	78.1	0.1	14.2			191.3	191.3	-1.91	-1.95	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24095	9/10/2026 8:30:00 AM					2200						AirTech Lab
CV-24095	9/10/2026 8:30:00 AM						180000					AirTech Lab; [User entered 18%]

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24095	9/17/2026 9:42:47 AM	11.4	79.9	0.0	8.7			192.0	192.1	-5.15	-5.10	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24095	9/24/2026 9:52:08 AM	12.9	68.7	0.0	18.4			191.8	191.6	-7.41	-7.41	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24096	9/2/2026 8:14:01 AM	32.6	53.7	2.6	11.1			65.8	65.8	-2.39	-2.37	,
CV-24096	9/23/2026 9:26:01 AM	30.5	40.7	4.5	24.3			87.7	88.4	-5.61	-5.44	Valve Adjustment:Decreased Flow/Vacuum
CV-24097	9/2/2026 8:18:03 AM	50.5	44.4	0.4	4.7			66.2	66.2	-3.21	-3.23	Reduced System Vacuum,
CV-24097	9/30/2026 3:17:38 PM	41.6	40.3	0.0	18.1			99.3	99.4	2.75	0.67	Valve Adjustment:Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24098	9/2/2026 8:23:38 AM	43.7	51.6	0.3	4.4			72.3	72.3	-7.95	-7.38	Reduced System Vacuum,
CV-24098	9/23/2026 9:16:20 AM	43.9	48.5	1.3	6.3			88.4	89.4	-11.66	-11.49	Well Comment:Valve stuck open
CV-24099	9/2/2026 8:32:12 AM	23.3	50.2	4.6	21.9			67.0	66.4	-7.76	-7.91	Reduced System Vacuum,
CV-24099	9/23/2026 9:11:30 AM	0.0	4.8	19.5	75.7			79.8	80.5	-11.20	-11.53	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected;Well Comment:Valve stuck open
CV-24099	9/23/2026 9:13:00 AM	0.1	2.0	19.9	78.0			81.1	81.2	-10.68	-11.35	Valve Adjustment:High O2,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected;Well Comment:Valve stuck open
CV-24100	9/2/2026 8:50:27 AM	44.1	52.5	0.3	3.1			97.3	97.3	-8.85	-8.87	,
CV-24100	9/2/2026 1:05:00 PM					144						AtmAA
CV-24100	9/2/2026 1:05:00 PM						5600					AtmAA; [User entered 0.56%]
CV-24100	9/2/2026 1:12:10 PM	33.8	66.2	0.0	0.0			151.7	153.7	0.52	-2.38	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24100	9/2/2026 1:16:31 PM	33.4	66.6	0.0	0.0			152.1	152.6	-2.41	-2.42	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	9/8/2026 7:35:00 AM					38						AirTech Lab
CV-24100	9/8/2026 7:35:00 AM						6300					AirTech Lab; [User entered 0.63%]

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24100	9/8/2026 2:53:01 PM	29.5	70.4	0.1	0.0			147.6	148.4	-1.51	-1.48	NSPS/EG CAI,High Temp
CV-24100	9/8/2026 2:55:00 PM					192						AtmAA
CV-24100	9/17/2026 2:19:56 PM	35.9	64.1	0.0	0.0			148.6	148.5	-8.62	-8.47	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	9/17/2026 2:21:00 PM	35.6	64.4	0.0	0.0			148.7	149.0	-9.31	-8.93	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	9/24/2026 10:19:50 AM	29.3	70.3	0.3	0.1			142.1	133.8	-12.64	-12.13	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24100	9/28/2026 1:58:23 PM	17.4	80.9	1.1	0.6			122.3	125.7	-12.00	-5.25	Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum
CV-24101	9/8/2026 7:30:00 AM					0						AirTech Lab
CV-24101	9/8/2026 7:30:00 AM						1200					AirTech Lab; [User entered 0.12%]
CV-24101	9/8/2026 2:50:19 PM		47.9	1.9				109.7	109.9	-7.19	-7.18	Reduced System Vacuum,
CV-24101	9/28/2026 1:59:13 PM	17.6	80.4	0.5	1.5			127.9	128.1	-6.06	-5.97	
CV-24102	9/2/2026 9:21:46 AM	43.1	47.1	0.0	9.8			101.0	101.1	-2.00	-1.95	,
CV-24102	9/22/2026 12:22:15 PM	40.3	52.4	0.0	7.3			101.9	101.7	-0.44	-0.40	,
CV-24120	9/9/2026 8:10:00 AM					680						AirTech Lab
CV-24120	9/9/2026 8:10:00 AM						42000					AirTech Lab; [User entered 4.2%]
CV-24120	9/14/2026 10:25:29 AM	3.3	39.8	10.8	46.1			97.7	97.7	-6.64	-3.05	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
CV-24120	9/14/2026 10:27:15 AM	2.5	29.5	12.9	55.1			97.7	97.7	-4.09	-4.04	
CV-24120	9/25/2026 10:26:04 AM	1.7	18.2	15.1	65.0			92.2	92.0	-4.70	-4.28	Valve Adjustment:Decreased Flow/Vacuum
CV-24120	9/28/2026 9:41:44 AM	7.8	92.2	0.0	0.0			89.4	84.7	4.93	-1.78	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-24120	9/28/2026 9:50:35 AM	6.9	89.6	0.9	2.6			91.6	91.5	-6.03	-6.00	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24121	9/3/2026 9:37:51 AM	23.6	52.8	2.6	21.1			99.9	125.5	120.52	-1.09	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24121	9/3/2026 9:43:25 AM	31.6	51.2	3.6	13.7			125.7	125.5	-1.67	-1.70	Valve Adjustment: NSPS/EG CAC
CV-24121	9/10/2026 9:45:00 AM					25						AirTech Lab
CV-24121	9/10/2026 9:45:00 AM						1600					AirTech Lab; [User entered 0.16%]
CV-24121	9/25/2026 10:30:06 AM	31.7	67.5	0.0	0.8			127.2	127.4	-7.31	-5.47	Valve Adjustment: Decreased Flow/Vacuum, Surging Liquid in Header, Surging Liquid in Well (Watered In)
CV-24122	9/8/2026 8:20:00 AM					200						AirTech Lab
CV-24122	9/8/2026 8:20:00 AM						15000					AirTech Lab; [User entered 1.5%]
CV-24122	9/15/2026 7:57:25 AM	27.9	24.0	10.3	37.8			67.3	67.4	-7.11	-7.11	Valve Adjustment: NSPS/EG CAI, High O2
CV-24122	9/15/2026 7:58:33 AM	27.9	24.0	10.3	37.8			67.5	67.5	-7.05	-7.39	
CV-24122	9/25/2026 10:38:50 AM	32.8	27.6	7.3	32.3			99.6	100.1	-4.96	-5.06	Valve Adjustment: High O2, Opened for Sample, Increased Flow/Vacuum, Plugged/Pinched Suspected
CV-24123	9/3/2026 9:17:50 AM	45.4	50.6	0.0	3.9			117.1	117.3	-3.49	-3.67	Valve Adjustment: Increased Flow/Vacuum
CV-24123	9/11/2026 3:37:45 PM	50.5	49.5	0.0	0.0			117.0		-3.32	-3.47	Valve Adjustment: Increased Flow/Vacuum
CV-24123	9/11/2026 3:38:20 PM	50.9	49.1	0.0	0.0			117.0		-3.52	-3.53	
CV-24123	9/23/2026 8:27:33 AM	46.6	49.4	0.0	4.0			117.0	116.6	-6.11	-5.29	Valve Adjustment: Audible Flow, Decreased Flow/Vacuum
CV-24125-TP20	9/9/2026 8:20:00 AM					0						AirTech Lab
CV-24125-TP20	9/9/2026 8:20:00 AM						1400					AirTech Lab; [User entered 0.14%]
CV-24125-TP20	9/14/2026 9:25:49 AM	37.6	48.1	1.5	12.8			124.2	121.4	-8.02	-4.23	Valve Adjustment: Decreased Flow/Vacuum
CV-24125-TP20	9/29/2026 8:05:16 AM	44.1	51.3	0.0	4.6			90.0	89.9	-6.08	-6.08	Well Condition: Pneumatic Pump Installed
CV-24126	9/8/2026 2:01:24 PM	15.0	63.4	0.0	21.6			189.3	189.4	-2.35	-2.34	Valve Adjustment: No Flow Measurement, High Temp; Well Condition: Lorentz Pump Installed
CV-24126	9/8/2026 2:04:00 PM					3490						AtmAA
CV-24126	9/14/2026 1:36:52 PM	16.3	40.1	2.3	41.3			177.6	177.7	-3.54	-3.14	Valve Adjustment: High Temp; Well Condition: Lorentz Pump Installed
CV-24126	9/14/2026 1:40:00 PM					1340						AtmAA
CV-24126	9/21/2026 1:17:21 PM	19.1	34.2	3.2	43.5			174.2	174.1	-4.85	-4.87	Valve Adjustment: No Flow Measurement, High Temp

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24126	9/28/2026 1:36:03 PM	13.4	35.4	2.7	48.5			174.0	174.2	-5.83	-5.39	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24127	9/8/2026 8:00:00 AM					2600						AirTech Lab
CV-24127	9/8/2026 8:00:00 AM						180000					AirTech Lab; [User entered 18%]
CV-24127	9/8/2026 2:06:28 PM	8.9	69.4	0.0	21.7			177.2	177.2	-2.91	-2.77	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24127	9/8/2026 2:09:00 PM					3930						AtmAA
CV-24127	9/14/2026 1:33:01 PM	28.2	67.5	0.0	4.3			160.3	160.3	-3.99	-3.92	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24127	9/14/2026 1:36:00 PM					1620						AtmAA
CV-24127	9/21/2026 1:12:42 PM	34.5	65.5	0.0	0.0			164.0	164.3	-4.83	-4.80	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24127	9/28/2026 1:25:09 PM	26.7	40.6	0.5	32.2			151.6	151.4	-6.07	-6.07	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24128	9/9/2026 12:13:22 PM	23.5	70.8	0.3	5.4			145.6	123.0	-0.61	-0.59	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24128	9/9/2026 12:14:49 PM	24.0	69.7	0.3	6.0			122.3	122.3	-0.50	-0.51	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24128	9/10/2026 9:35:00 AM					2700						AirTech Lab
CV-24128	9/10/2026 9:35:00 AM						110000					AirTech Lab; [User entered 11%]
CV-24128	9/25/2026 9:55:31 AM	23.1	58.8	0.3	17.8			127.8	127.8	-1.07	-1.10	Valve Adjustment:Barely Open
CV-24134-TP19	9/10/2026 1:06:47 PM	21.9	70.2	0.1	7.8			153.2	153.0	-1.75	-1.78	Valve Adjustment:High Temp,Barely Open
CV-24134-TP19	9/14/2026 1:29:38 PM	25.7	68.2	0.0	6.1			152.3	152.0	-2.57	-2.55	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24134-TP19	9/14/2026 1:32:00 PM					2890						AtmAA
CV-24134-TP19	9/21/2026 1:09:25 PM	36.4	63.5	0.0	0.1			151.7	152.2	-2.66	-2.63	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24134-TP19	9/28/2026 1:06:51 PM	25.8	69.5	0.0	4.7			150.0	150.1	-0.91	-0.89	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24138	9/2/2026 7:35:00 AM					160						AirTech Lab
CV-24138	9/2/2026 7:35:00 AM						25000					AirTech Lab; [User entered 2.5%]
CV-24138	9/2/2026 7:58:13 AM	0.5	10.2	17.4	71.9			65.6	65.5	-3.91	-3.90	NSPS/EG CAI,High O2
CV-24138	9/2/2026 7:59:07 AM	0.5	10.2	17.3	72.0			65.3	65.3	-4.08	-4.07	NSPS/EG CAI,High O2
CV-24138	9/30/2026 2:54:56 PM	2.3	72.3	0.2	25.2			162.2	161.4	-4.34	-4.38	Valve Adjustment:High Temp,Barely Open
CV-24139	9/1/2026 1:45:00 PM					1070						AtmAA
CV-24139	9/1/2026 1:45:00 PM						180100					AtmAA; [User entered 18.01%]
CV-24139	9/1/2026 1:48:41 PM	5.5	70.8	0.4	23.3			145.4	145.4	-5.52	-5.53	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24139	9/2/2026 7:30:00 AM					720						AirTech Lab
CV-24139	9/2/2026 7:30:00 AM						210000					AirTech Lab; [User entered 21%]
CV-24139	9/8/2026 1:22:11 PM	8.7	58.3	4.3	28.7			110.5	110.5	-5.34	-4.90	NSPS/EG CAC,Reduced System Vacuum
CV-24139	9/10/2026 2:55:48 PM	1.9	2.1	20.3	75.7			132.1	129.5	-4.74	-2.49	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24139	9/10/2026 3:13:23 PM	9.3	16.2	15.6	58.9			127.2	125.3	-1.12	-1.10	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24139	9/10/2026 3:15:24 PM	8.9	18.3	15.0	57.8			125.4	125.4	-0.67	-0.67	Valve Adjustment:No Flow Measurement;Well Condition:Pnumatic Pump Installed
CV-24139	9/30/2026 2:51:42 PM	4.2	53.0	7.8	35.0			128.4	129.2	-7.90	-7.71	Valve Adjustment:High O2,Barely Open
CV-24140	9/1/2026 1:40:00 PM					2160						AtmAA
CV-24140	9/1/2026 1:40:00 PM						182800					AtmAA; [User entered 18.28%]
CV-24140	9/1/2026 1:44:48 PM	3.8	74.8	0.0	21.4			164.0	164.0	-4.96	-4.94	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24140	9/2/2026 7:25:00 AM					1400						AirTech Lab
CV-24140	9/2/2026 7:25:00 AM						210000					AirTech Lab; [User entered 21%]
CV-24140	9/8/2026 1:16:52 PM	3.4	73.7	0.6	22.3			165.9	166.0	-4.55	-4.56	NSPS/EG CAI,High Temp,Reduced System Vacuum

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24140	9/8/2026 1:20:00 PM					2140						AtmAA
CV-24140	9/17/2026 9:53:55 AM	7.1	72.3	0.3	20.3			154.7	153.3	-8.42	-8.13	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24140	9/24/2026 9:42:13 AM	7.8	72.8	0.3	19.1			145.3	145.5	-9.47	-9.32	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24141	9/2/2026 7:10:00 AM					26						AirTech Lab
CV-24141	9/2/2026 7:10:00 AM						1900					AirTech Lab; [User entered 0.19%]
CV-24141	9/15/2026 9:57:58 AM	2.1	6.4	17.6	73.9			90.4	91.6	-4.95	-5.12	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In)
CV-24141	9/15/2026 9:59:24 AM	2.1	5.6	17.7	74.6			92.2	92.1	-5.25	-5.27	
CV-24141	9/23/2026 9:57:06 AM	0.9	6.1	18.4	74.6			95.9	94.6	-7.13	-3.58	Valve Adjustment:High O2,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24142	9/1/2026 1:54:21 PM	4.0	65.9	2.7	27.4			128.0	128.2	-1.61	-1.61	Valve Adjustment:No Flow Measurement;Well Condition:Pnumatic Pump Installed
CV-24142	9/2/2026 7:40:00 AM					1200						AirTech Lab
CV-24142	9/2/2026 7:40:00 AM						170000					AirTech Lab; [User entered 17%]
CV-24142	9/30/2026 2:58:57 PM	1.6	52.9	7.2	38.3			130.5	130.5	-3.40	-3.42	Valve Adjustment:High O2
CV-24143	9/1/2026 7:40:00 AM					660						Air Tech Lab
CV-24143	9/1/2026 7:40:00 AM						94000					Air Tech Lab; [User entered 9.4%]
CV-24143	9/10/2026 12:19:01 PM	4.8	62.0	5.2	28.0			125.2	124.2	-1.95	-2.19	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:No pump
CV-24143	9/10/2026 12:20:07 PM	3.9	61.0	5.3	29.8			123.9	124.1	-2.23	-1.93	
CV-24143	9/23/2026 9:50:14 AM	1.7	71.2	2.9	24.2			100.3	100.4	-7.99	-4.25	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24144	9/2/2026 8:20:25 AM	55.9	41.0	0.0	3.1			68.7	68.8	-0.90	-0.86	Reduced System Vacuum,
CV-99	9/4/2026 7:05:00 AM					900						AirTech Lab
CV-99	9/4/2026 7:05:00 AM						64000					AirTech Lab; [User entered 6.4%]

Table 2. Monthly LEA Selected Wells - September 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-99	9/14/2026 9:15:48 AM	3.0	6.5	17.8	72.7			85.9	86.7	-9.69	-10.08	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
CV-99	9/14/2026 9:19:46 AM	31.6	48.3	3.5	16.6			88.0	88.3	-2.53	-2.53	Valve Adjustment:NSPS/EG CAC
CV-99	9/25/2026 10:42:18 AM	40.9	54.1	0.3	4.7			105.0	98.8	-0.47	-0.67	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1770N	9/1/2026 11:22:05 AM	29.2	63.7	0.0	7.1			105.0	105.2	-1.01	-0.93	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
H-1770N	9/10/2026 9:10:00 AM					320						AirTech Lab
H-1770N	9/10/2026 9:10:00 AM						23000					AirTech Lab; [User entered 2.3%]
H-1770N	9/16/2026 2:50:15 PM	27.2	65.6	0.2	7.0			97.3	97.4	-1.43	-1.44	Valve Adjustment:Barely Open
H-2165W	9/2/2026 8:43:14 AM	31.1	65.0	0.1	3.8			139.4	136.6	-0.88	-0.31	Reduced System Vacuum,
H-2165W	9/2/2026 8:45:08 AM	14.3	76.0	0.0	9.7			135.9	137.6	-0.10	-0.09	NSPS/EG CAI,High Temp,Reduced System Vacuum
H-2165W	9/9/2026 7:00:00 AM					680						AirTech Lab
H-2165W	9/9/2026 7:00:00 AM						51000					AirTech Lab; [User entered 5.1%]
H-2165W	9/23/2026 8:49:44 AM	8.9	88.0	0.0	3.1			147.2	147.2	-0.90	-0.92	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-2165W	9/30/2026 10:38:31 AM	10.1	73.5	0.0	16.4			148.0	146.0	-0.25	-1.32	Valve Adjustment:High Temp,Increased Flow/Vacuum
H-2165W	9/30/2026 10:39:18 AM	19.4	75.3	0.0	5.3			144.9	145.2	-1.47	-1.42	Valve Adjustment:High Temp
H-2273W	9/2/2026 7:21:33 AM	21.3	40.8	0.0	37.9			120.7	120.7	-0.91	-0.70	Reduced System Vacuum,
H-2273W	9/4/2026 8:32:00 AM					160						AirTech Lab
H-2273W	9/4/2026 8:32:00 AM						18000					AirTech Lab; [User entered 1.8%]
H-2273W	9/9/2026 7:10:00 AM					78						AirTech Lab
H-2273W	9/9/2026 7:10:00 AM						10000					AirTech Lab; [User entered 1.0%]
H-2273W	9/22/2026 12:09:18 PM	31.8	42.0	0.0	26.2			123.2	123.0	-0.30	-0.26	,