CHIQUITA CANYON
A Waste Connections Company

November 3, 2026

***Via E-Mail***

Baitong Chen, Air Quality Engineer, bchen@aqmd.gov
Nathaniel Dickel, Senior Air Quality Engineer, ndickel@aqmd.gov
Christina Ojeda, Air Quality Inspector, cojeda@aqmd.gov
South Coast Air Quality Management District
21865 East Copley Drive
Diamond Bar, California 91765-4182

**Re: Chiquita Canyon, LLC's Weekly Leachate Inspection Report for Stipulated Order for Abatement (Case No. 6177-4), Condition 27(c)**

All:

Pursuant to Condition 27(c) of the Stipulated Order for Abatement with the South Coast Air Quality Management District in Case No. 6177-4, as modified on October 28, 2026 (the "Order"), Chiquita Canyon, LLC ("Chiquita") hereby submits the enclosed compilation of the twice daily leachate seep inspection logs for the period of October 26, 2026 through November 1, 2026. No leachate seepage or pooling was observed at the Chiquita Canyon Landfill (the "Landfill") during the reporting period.

During this reporting period, Chiquita also conducted and documented an expanded leachate seep inspection of the entire Main Canyon area on the afternoon of October 29, 2026, in accordance with Condition 27(b)(ii) of the Order. No leachate seepage was observed during that inspection, as reflected in the enclosed inspection log for that afternoon. Consistent with modified Condition 27(c), this report also identifies any leachate seepage or pooling observed outside of the Condition 27(b) inspections during the reporting period. No leachate seepage or pooling was observed outside of those inspections during the reporting period.

Please contact me if you have any questions regarding this matter.

Regards,

Tessa Lenz

Tessa Lenz
Environmental Manager
Chiquita Canyon

Attachment: Leachate Seep/Pooling Inspection Logs from October 26 – November 1, 2026

# 4050 - Chiquita Leachate Seep/Pooling Inspection

26 Oct 2026 / Tom Roe

**Complete**

| | |
|---|---|
| **Conducted on** | 26 Oct 2026 9:18 AM PDT |
| **Prepared by** | Tom Roe |

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

| | |
|---|---|
| **Has a leachate seep/pooling been located?** | No |



Photo 1

| | |
|---|---|
| **Description of area in photo where there is no leachate seepage or pooling.** | Westside perimeter road. |

# 4050 - Chiquita Leachate Seep/Pooling Inspection

26 Oct 2026 / Tom Roe

**Complete**

| | |
|---|---|
| **Conducted on** | 26 Oct 2026 3:19 PM PDT |
| **Prepared by** | Tom Roe |

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

| | |
|---|---|
| **Has a leachate seep/pooling been located?** | No |




Photo 1

| | |
|---|---|
| **Description of area in photo where there is no leachate seepage or pooling.** | North perimeter road. |

# 4050 - Chiquita Leachate Seep/Pooling Inspection

27 Oct 2026 / John Boucher

**Complete**

| | |
|---|---|
| **Conducted on** | 27 Oct 2026 7:25 AM PDT |
| **Prepared by** | John Boucher |

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

| | |
|---|---|
| **Has a leachate seep/pooling been located?** | No |



Photo 1

| | |
|---|---|
| **Description of area in photo where there is no leachate seepage or pooling.** | Westside perimeter road |

# 4050 - Chiquita Leachate Seep/Pooling Inspection

27 Oct 2026 / John Boucher

**Complete**

| | |
|---|---|
| **Conducted on** | 27 Oct 2026 1:13 PM PDT |
| **Prepared by** | John Boucher |

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

| | |
|---|---|
| **Has a leachate seep/pooling been located?** | No |



Photo 1

| | |
|---|---|
| **Description of area in photo where there is no leachate seepage or pooling.** | North side perimeter road |

# 4050 - Chiquita Leachate Seep/Pooling Inspection

28 Oct 2026 / John Boucher

**Complete**

| | |
|---|---|
| **Conducted on** | 28 Oct 2026 7:18 AM PDT |
| **Prepared by** | John Boucher |

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

| | |
|---|---|
| **Has a leachate seep/pooling been located?** | No |



Photo 1

| | |
|---|---|
| **Description of area in photo where there is no leachate seepage or pooling.** | Westside perimeter road |

# 4050 - Chiquita Leachate Seep/Pooling Inspection

28 Oct 2026 / John Boucher

**Complete**

| | |
|---|---|
| **Conducted on** | 28 Oct 2026 2:29 PM PDT |
| **Prepared by** | John Boucher |

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

| | |
|---|---|
| **Has a leachate seep/pooling been located?** | No |



Photo 1

| | |
|---|---|
| **Description of area in photo where there is no leachate seepage or pooling.** | Northside perimeter road |

# 4050 - Chiquita Leachate Seep/Pooling Inspection

29 Oct 2026 / John Boucher

**Complete**

| | |
|---|---|
| **Conducted on** | 29 Oct 2026 9:07 AM PDT |
| **Prepared by** | John Boucher |

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

| | |
|---|---|
| **Has a leachate seep/pooling been located?** | No |



Photo 1

| | |
|---|---|
| **Description of area in photo where there is no leachate seepage or pooling.** | Westside perimeter road |

# 4050 - Chiquita Leachate Seep/Pooling Inspection

29 Oct 2026 / John Boucher

**Complete**

| | |
|---|---|
| **Conducted on** | 29 Oct 2026 1:47 PM PDT |

Entire main canyon inspected for 27(b)(ii)

| | |
|---|---|
| **Prepared by** | John Boucher |

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

| | |
|---|---|
| **Has a leachate seep/pooling been located?** | No |



Photo 1

| | |
|---|---|
| **Description of area in photo where there is no leachate seepage or pooling.** | Northside perimeter road |

# 4050 - Chiquita Leachate Seep/Pooling Inspection

30 Oct 2026 / John Boucher

**Complete**

| | |
|---|---|
| **Conducted on** | 30 Oct 2026 7:08 AM PDT |
| **Prepared by** | John Boucher |

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

| | |
|---|---|
| **Has a leachate seep/pooling been located?** | No |



Photo 1

| | |
|---|---|
| **Description of area in photo where there is no leachate seepage or pooling.** | Westside perimeter road |

# 4050 - Chiquita Leachate Seep/Pooling Inspection

30 Oct 2026 / Tom Roe

**Complete**

| | |
|---|---|
| **Conducted on** | 30 Oct 2026 2:01 PM PDT |
| **Prepared by** | Tom Roe |

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

| | |
|---|---|
| **Has a leachate seep/pooling been located?** | No |




Photo 1

| | |
|---|---|
| **Description of area in photo where there is no leachate seepage or pooling.** | North perimeter road. |

# 4050 - Chiquita Leachate Seep/Pooling Inspection

31 Oct 2026 / Edwin De Leon

**Complete**

| | |
|---|---|
| **Conducted on** | 31 Oct 2026 7:53 AM PDT |
| **Prepared by** | Edwin De Leon |

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

| | |
|---|---|
| **Has a leachate seep/pooling been located?** | No |



Photo 1

| | |
|---|---|
| **Description of area in photo where there is no leachate seepage or pooling.** | North Westside perimeter road |

# 4050 - Chiquita Leachate Seep/Pooling Inspection

31 Oct 2026 / Edwin De Leon

**Complete**

| | |
|---|---|
| **Conducted on** | 31 Oct 2026 2:00 PM PDT |
| **Prepared by** | Edwin De Leon |

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

| | |
|---|---|
| **Has a leachate seep/pooling been located?** | No |




Photo 1

| | |
|---|---|
| **Description of area in photo where there is no leachate seepage or pooling.** | Westside perimeter road |

# 4050 - Chiquita Leachate Seep/Pooling Inspection

1 Nov 2026 / Michael Alvarez

**Complete**

| | |
|---|---|
| **Conducted on** | 1 Nov 2026 6:53 AM PST |
| **Prepared by** | Michael Alvarez |

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

| | |
|---|---|
| **Has a leachate seep/pooling been located?** | No |



Photo 1

| | |
|---|---|
| **Description of area in photo where there is no leachate seepage or pooling.** | Westside perimeter road |

# 4050 - Chiquita Leachate Seep/Pooling Inspection

1 Nov 2026 / Michael Alvarez

**Complete**

| | |
|---|---|
| **Conducted on** | 1 Nov 2026 1:01 PM PST |
| **Prepared by** | Michael Alvarez |

## Leachate Seep Inspection

Leachate seep/pooling Inspection

Leachate seep/pooling Inspection 1

| | |
|---|---|
| **Has a leachate seep/pooling been located?** | No |




Photo 1

| | |
|---|---|
| **Description of area in photo where there is no leachate seepage or pooling.** | Westside perimeter road |