Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-108-52	10/5/2026 9:20:00 AM					64						AirTech Lab
CV-108-52	10/5/2026 9:20:00 AM						7000					AirTech Lab; [User entered 0.70%]
CV-108-52	10/15/2026 9:19:36 AM	45.2	36.7	2.4	15.7			82.1	82.0	-5.60	-4.39	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-108-52	10/15/2026 9:59:53 AM	52.4	43.9	0.0	3.8			88.1	88.7	-4.06	-5.39	
CV-108-52	10/27/2026 9:27:50 AM	39.5	34.3	3.8	22.4			71.4	72.3	-4.36	-4.16	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-113	10/8/2026 7:40:00 AM					19						Air Tech Lab
CV-113	10/8/2026 7:40:00 AM						4900					Air Tech Lab; [User entered 0.49%]
CV-113	10/13/2026 9:10:42 AM	1.9	3.0	20.5	74.6			65.1	64.7	-11.54	-11.54	Valve Adjustment:NSPS/EG CAI,High O2
CV-113	10/13/2026 9:12:18 AM	0.3	0.8	21.2	77.7			63.5	63.4	-11.49	-11.42	Valve Adjustment:NSPS/EG CAI,High O2
CV-113	10/26/2026 8:55:15 AM	0.0	1.9	20.8	77.3			62.8	63.2	-7.84	-7.84	Valve Adjustment:Barely Open,Surging Liquid in Header,Plugged/Pinched Suspected
CV-114	10/5/2026 9:10:28 AM	1.6	71.1	0.0	27.3			185.6	185.4	-7.92	-7.88	Valve Adjustment:No Flow Measurement,High Temp
CV-114	10/5/2026 9:15:00 AM					3590						AtmAA
CV-114	10/5/2026 9:15:00 AM						164700					AtmAA; [User entered 16.47%]
CV-114	10/8/2026 7:50:00 AM					2000						Air Tech Lab
CV-114	10/8/2026 7:50:00 AM						160000					Air Tech Lab; [User entered 16%]
CV-114	10/12/2026 8:20:24 AM	1.7	79.2	0.4	18.7			179.7	179.6	-8.97	-8.91	Valve Adjustment:No Flow Measurement,High Temp
CV-114	10/12/2026 8:25:00 AM					3630						AtmAA
CV-114	10/19/2026 8:03:05 AM	1.9	81.7	1.3	15.1			182.3	182.3	-8.96	-8.78	Valve Adjustment:No Flow Measurement,High Temp
CV-114	10/26/2026 7:50:00 AM					2750						AtmAA
CV-114	10/26/2026 7:56:07 AM	1.6	70.4	1.5	26.5			149.1	162.8	-8.42	-8.29	Valve Adjustment:No Flow Measurement,High Temp
CV-1532A	10/5/2026 10:20:24 AM	4.6	78.3	1.2	15.9			117.0	117.3	-9.23	-6.58	Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-1532A	10/5/2026 10:21:19 AM	3.8	73.0	2.6	20.6			117.5	117.6	-7.81	-7.86	Valve Adjustment:No Flow Measurement;Well Condition:Pnumatic Pump Installed
CV-1532A	10/6/2026 2:20:00 PM					1270						AtmAA
CV-1532A	10/6/2026 2:20:00 PM						105700					AtmAA; [User entered 10.57%]

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-1532A	10/6/2026 2:26:45 PM	11.4	68.1	1.6	18.9			152.9	153.1	-4.57	-4.10	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-1532A	10/12/2026 7:20:00 AM					1400						Air Tech Lab
CV-1532A	10/12/2026 7:20:00 AM						220000					Air Tech Lab; [User entered 22%]
CV-1532A	10/13/2026 1:38:14 PM	12.2	68.2	0.3	19.3			101.5	101.6	-9.61	-8.45	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-1532A	10/28/2026 1:57:18 PM	0.8	71.1	0.4	27.7			93.4	93.5	-10.53	-10.56	
CV-1535	10/1/2026 11:49:37 AM	33.3	37.4	0.0	29.3			123.5	123.0	-3.03	-2.15	,
CV-1535	10/12/2026 9:20:00 AM					19						Air Tech Lab
CV-1535	10/12/2026 9:20:00 AM						5000					Air Tech Lab; [User entered 0.50%]
CV-1535	10/27/2026 9:40:08 AM	43.8	43.0	0.0	13.2			121.4	121.4	-2.36	-2.25	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-1902A	10/6/2026 1:35:00 PM					928						AtmAA
CV-1902A	10/6/2026 1:35:00 PM						147500					AtmAA; [User entered 14.75%]
CV-1902A	10/6/2026 1:35:09 PM	24.8	60.5	2.9	11.8			173.0	171.1	-7.83	-7.58	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-1902A	10/8/2026 8:05:00 AM					680						Air Tech Lab
CV-1902A	10/8/2026 8:05:00 AM						160000					Air Tech Lab; [User entered 16%]
CV-1902A	10/12/2026 2:05:00 PM					897						AtmAA
CV-1902A	10/12/2026 2:10:10 PM	4.7	58.6	7.7	29.0			150.3	147.8	-12.40	-7.52	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-1902A	10/12/2026 2:15:05 PM	6.9	64.8	4.0	24.3			150.5	147.3	-9.81	-9.96	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,Barely Open;Well Condition:Pnumatic Pump Installed
CV-1902A	10/14/2026 8:47:31 AM	47.2	45.2	1.9	5.7			71.8	71.9	-4.53	-4.22	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-1902A	10/27/2026 8:58:44 AM	1.7	63.1	4.6	30.6			151.1	155.9	-11.18	-11.28	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-2001	10/7/2026 8:10:00 AM					900						Air Tech Lab
CV-2001	10/7/2026 8:10:00 AM						84000					Air Tech Lab; [User entered 8.4%]
CV-2001	10/13/2026 9:02:59 AM	0.0	0.0	19.9	80.1			79.2	79.5	-17.60	-17.59	Valve Adjustment:NSPS/EG CAI,High O2
CV-2001	10/28/2026 1:04:00 PM	4.8	56.5	6.7	32.0			94.6	94.1	-16.01	-16.43	Valve Adjustment:NSPS/EG CAI,High O2
CV-2001	10/28/2026 1:04:53 PM	5.0	58.9	5.0	31.1			95.6	95.6	-16.85	-16.68	Valve Adjustment:NSPS/EG CAC
CV-2002	10/1/2026 1:25:00 PM					3575						AtmAA

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2002	10/1/2026 1:26:06 PM	17.3	72.3	0.2	10.2			183.0	183.1	-6.72	-6.32	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	10/7/2026 7:58:33 AM	11.5	81.6	0.0	6.9			183.1	183.0	-8.35	-8.09	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	10/7/2026 8:00:00 AM					3120						AtmAA
CV-2002	10/7/2026 8:00:00 AM						112700					AtmAA; [User entered 11.27%]
CV-2002	10/12/2026 9:11:00 AM					38						Air Tech Lab
CV-2002	10/12/2026 9:11:00 AM						11000					Air Tech Lab; [User entered 1.1%]
CV-2002	10/14/2026 9:10:00 AM					2910						AtmAA
CV-2002	10/14/2026 9:10:01 AM	34.0	65.9	0.1	0.0			179.5	179.4	-19.06	-18.37	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	10/21/2026 9:09:45 AM	27.6	56.5	0.4	15.5			177.0	177.0	-10.45	-10.41	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	10/21/2026 9:35:00 AM					1970						AtmAA
CV-2002	10/26/2026 8:25:00 AM	3.9	0.0	0.0	96.1			183.3	183.7	-9.01	-9.01	Valve Adjustment:No Flow Measurement,High Temp
CV-2007	10/8/2026 8:00:00 AM					950						Air Tech Lab
CV-2007	10/8/2026 8:00:00 AM						66000					Air Tech Lab; [User entered 6.6%]
CV-2007	10/8/2026 4:07:26 PM	17.7	75.7	0.0	6.6			120.7	120.7	-0.06	-0.06	Valve Adjustment:High Temp
CV-2007	10/23/2026 8:27:51 AM	11.8	82.2	0.0	6.0			100.7	100.7	-1.21	-1.22	Valve Adjustment:Barely Open
CV-2301	10/6/2026 6:45:00 AM					530						Air Tech Lab
CV-2301	10/6/2026 6:45:00 AM						58000					Air Tech Lab; [User entered 5.8%]
CV-2301	10/8/2026 8:59:00 AM						40600					AtmAA; [User entered 4.06%]
CV-2301	10/8/2026 8:59:48 AM	19.2	24.3	11.4	45.1			178.1	177.0	-7.38	-6.93	Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open,Reduce Sys. Vac. - Flare Down
CV-2301	10/9/2026 8:59:00 AM					615						AtmAA
CV-2301	10/14/2026 2:31:57 PM	3.1	0.6	20.7	75.6			168.0	157.2	-16.74	-3.13	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,High O2,Decreased Flow/Vacuum
CV-2301	10/14/2026 2:37:51 PM	22.1	49.8	6.0	22.1			158.7	158.4	-2.43	-2.38	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-2301	10/14/2026 2:50:00 PM					1900						AtmAA
CV-2301	10/20/2026 10:21:00 AM					1380						AtmAA
CV-2301	10/20/2026 10:21:58 AM	1.0	81.4	0.0	17.6			173.4	175.0	1.66	-3.46	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,Positive Static Press.,Increased Flow/Vacuum
CV-2301	10/20/2026 10:22:29 AM	1.0	83.3	0.0	15.7			174.9	174.4	-3.47	-3.37	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-2301	10/28/2026 10:20:00 AM					817						AtmAA
CV-2301	10/28/2026 10:34:33 AM	15.3	15.6	14.5	54.6			174.2	171.0	-7.08	-4.30	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Decreased Flow/Vacuum

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2301	10/28/2026 10:44:22 AM	20.9	35.6	8.6	34.9			171.0	168.4	-1.80	-1.79	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2301	10/28/2026 10:53:27 AM	14.9	56.2	4.4	24.5			166.6	167.3	-1.14	-0.97	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-2302	10/5/2026 1:40:12 PM	43.5	47.2	0.7	8.6			130.1	130.3	-9.11	-9.11	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-2302	10/6/2026 6:50:00 AM					200						Air Tech Lab
CV-2302	10/6/2026 6:50:00 AM						38000					Air Tech Lab; [User entered 3.8%]
CV-2302	10/20/2026 10:18:40 AM	37.6	48.2	1.5	12.7			128.2	129.5	-13.36	-13.84	Valve Comment:Valve stuck open;Valve Adjustment:Valve 100% Open
CV-2303	10/1/2026 2:05:00 PM					2170						AtmAA
CV-2303	10/1/2026 2:06:56 PM	8.5	73.0	0.8	17.7			194.0	193.7	0.13	0.20	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.;Well Condition:Lorentz Pump Installed
CV-2303	10/1/2026 2:08:57 PM	7.5	78.8	0.0	13.7			193.6	193.5	2.64	2.63	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.;Well Condition:Lorentz Pump Installed
CV-2303	10/6/2026 7:00:00 AM					1700						Air Tech Lab
CV-2303	10/6/2026 7:00:00 AM						180000					Air Tech Lab; [User entered 18%]
CV-2303	10/6/2026 8:44:21 AM	5.7	73.0	0.0	21.3			191.3	191.5	-4.71	-4.63	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2303	10/6/2026 8:45:00 AM					2230						AtmAA
CV-2303	10/6/2026 8:45:00 AM						180700					AtmAA; [User entered 18.07%]
CV-2303	10/13/2026 9:39:42 AM	7.8	48.8	0.0	43.4			194.9	194.2	1.44	-3.17	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2303	10/13/2026 9:40:00 AM					2940						AtmAA
CV-2303	10/13/2026 9:41:09 AM	7.5	72.6	0.0	19.9			194.1	194.3	-3.55	-3.46	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2303	10/20/2026 9:12:16 AM	1.5	70.9	0.3	27.3			162.7	163.4	-6.47	-6.40	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2303	10/20/2026 9:15:00 AM					694						AtmAA
CV-2303	10/27/2026 9:39:12 AM	4.1	85.3	0.0	10.6			190.1	190.1	-4.20	-4.05	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2303	10/27/2026 9:45:00 AM					1880						AtmAA
CV-2305	10/7/2026 6:50:00 AM					1200						Air Tech Lab
CV-2305	10/7/2026 6:50:00 AM						48000					Air Tech Lab; [User entered 4.8%]
CV-2305	10/7/2026 10:00:10 AM	21.2	78.7	0.1	0.0			161.8	161.7	-3.58	-3.54	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	10/7/2026 10:10:00 AM					2040						AtmAA
CV-2305	10/7/2026 10:10:00 AM						52900					AtmAA; [User entered 5.29%]
CV-2305	10/14/2026 10:00:00 AM					1610						AtmAA
CV-2305	10/14/2026 10:00:14 AM	0.0	0.0	0.0	100.0			160.4	160.3	-7.75	-7.75	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	10/15/2026 2:25:00 PM					1900						AtmAA
CV-2305	10/19/2026 2:24:51 PM	39.4	55.7	0.0	4.9			164.6	164.7	-5.06	-5.05	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	10/19/2026 2:25:00 PM					1900						AtmAA
CV-2305	10/26/2026 1:42:00 PM					1790						AtmAA
CV-2305	10/26/2026 1:42:55 PM	33.6	51.7	0.0	14.7			164.2	164.2	-5.05	-5.05	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2312-PLR	10/7/2026 7:10:00 AM					2600						Air Tech Lab
CV-2312-PLR	10/7/2026 7:10:00 AM						150000					Air Tech Lab; [User entered 15%]
CV-2312-PLR	10/7/2026 12:50:00 PM					2840						AtmAA
CV-2312-PLR	10/7/2026 12:50:00 PM						122600					AtmAA; [User entered 12.26%]
CV-2312-PLR	10/7/2026 1:07:45 PM	8.3	79.1	0.1	12.5			170.5	170.4	-1.68	-1.38	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	10/14/2026 2:20:00 AM					3620						AtmAA
CV-2312-PLR	10/14/2026 1:46:53 PM	49.4	50.4	0.2	0.0			169.8	169.9	-21.10	-19.88	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	10/21/2026 7:40:00 AM					3440						AtmAA
CV-2312-PLR	10/21/2026 7:44:02 AM	1.4	82.6	0.0	16.0			169.9	169.8	-2.82	-2.58	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PLR	10/28/2026 9:25:00 AM					2385						AtmAA
CV-2312-PLR	10/28/2026 9:36:36 AM	4.0	0.0	0.0	96.0			169.7	169.7	-2.84	-2.78	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	10/1/2026 12:43:36 PM	6.9	81.9	0.1	11.1			185.9	185.8	-6.54	-6.07	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	10/1/2026 12:45:00 PM					2630						AtmAA
CV-2314-PLR	10/7/2026 1:10:00 PM					3640						AtmAA
CV-2314-PLR	10/7/2026 1:10:00 PM						111100					AtmAA; [User entered 11.11%]
CV-2314-PLR	10/7/2026 1:14:53 PM	7.9	80.8	0.0	11.3			186.1	186.1	-4.97	-4.59	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	10/13/2026 8:10:00 AM					2700						AirTech Lab
CV-2314-PLR	10/13/2026 8:10:00 AM						130000					AirTech Lab; [User entered 13%]

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [ºF]	Adj Temp [ºF]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2314-PLR	10/14/2026 10:43:05 AM	10.7	77.0	0.6	11.7			185.1	185.2	-12.03	-11.79	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	10/14/2026 10:45:00 AM					4850						AtmAA
CV-2314-PLR	10/20/2026 1:18:21 PM	1.0	84.5	0.3	14.2			184.9	185.0	-8.47	-8.42	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	10/20/2026 1:25:00 PM					4230						AtmAA
CV-2314-PLR	10/27/2026 9:46:52 AM	3.6	79.7	0.0	16.7			184.6	184.6	-7.29	-7.16	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PLR	10/27/2026 9:50:00 AM					2750						AtmAA
CV-2315	10/5/2026 10:37:05 AM	27.9	63.7	0.0	8.4			181.6	181.8	-3.79	-3.59	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	10/5/2026 10:40:00 AM					1660						AtmAA
CV-2315	10/5/2026 10:40:00 AM						114600					AtmAA; [User entered 11.46%]
CV-2315	10/7/2026 7:35:00 AM					1900						Air Tech Lab
CV-2315	10/7/2026 7:35:00 AM						160000					Air Tech Lab; [User entered 16%]
CV-2315	10/12/2026 9:36:43 AM	20.3	67.7	0.1	11.9			187.8	187.7	-6.84	-6.40	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	10/12/2026 9:40:00 AM					1610						AtmAA
CV-2315	10/19/2026 1:40:32 PM	7.4	75.3	1.1	16.2			182.9	188.9	-0.35	-0.33	Valve Adjustment:No Flow Measurement,High Temp,Barely Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-2315	10/26/2026 9:49:22 AM	3.7	75.2	0.4	20.7			167.2	165.3	-4.57	-4.29	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	10/26/2026 9:55:00 AM					2780						AtmAA
CV-2315	10/28/2026 1:23:00 PM					2680						AtmAA
CV-2315	10/28/2026 1:29:59 PM	12.1	78.0	0.0	9.9			181.5	181.6	-1.00	-0.88	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2328	10/7/2026 1:54:08 PM	20.6	79.4	0.0	0.0			182.2	182.2	5.62	5.60	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-2328	10/7/2026 1:55:00 PM					2540						AtmAA
CV-2328	10/7/2026 1:55:00 PM						107000					AtmAA; [User entered 10.7%]
CV-2328	10/13/2026 7:10:00 AM					1500						AirTech Lab
CV-2328	10/13/2026 7:10:00 AM						120000					AirTech Lab; [User entered 12%]
CV-2328	10/14/2026 2:00:00 AM					1920						AtmAA

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2328	10/14/2026 1:59:51 PM	30.6	69.4	0.0	0.0			177.0	117.3	-9.79	-9.35	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2328	10/21/2026 7:27:22 AM	12.6	79.1	0.0	8.3			177.0	72.9	-3.50	-3.45	Valve Adjustment:No Flow Measurement,High O2;Well Condition:Lorentz Pump Installed
CV-2328	10/21/2026 7:30:00 AM					1850						AtmAA
CV-2328	10/27/2026 1:45:00 PM					1030						AtmAA
CV-2328	10/27/2026 1:45:18 PM	22.2	74.1	0.0	3.7			175.0	77.5	-8.26	-8.09	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2333	10/5/2026 9:05:55 AM	2.1	69.9	0.1	27.9			189.5	189.5	-8.42	-8.09	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	10/5/2026 9:10:00 AM					3940						AtmAA
CV-2333	10/5/2026 9:10:00 AM						188100					AtmAA; [User entered 18.81%]
CV-2333	10/6/2026 7:20:00 AM					2900						Air Tech Lab
CV-2333	10/6/2026 7:20:00 AM						180000					Air Tech Lab; [User entered 18%]
CV-2333	10/12/2026 8:16:31 AM	1.4	75.5	0.1	23.0			189.9	189.9	-8.38	-8.37	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	10/12/2026 8:20:00 AM					4480						AtmAA
CV-2333	10/19/2026 7:47:41 AM	1.2	80.3	0.8	17.7			189.4	189.5	-9.54	-9.32	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	10/26/2026 7:31:30 AM	0.5	67.5	0.5	31.5			190.2	190.2	-8.67	-8.42	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	10/26/2026 7:35:00 AM					3385						AtmAA
CV-2334	10/1/2026 2:15:00 PM					3170						AtmAA
CV-2334	10/1/2026 2:17:12 PM	9.9	77.6	0.0	12.5			163.0	163.1	0.42	0.42	Valve Adjustment:High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-2334	10/6/2026 7:30:00 AM					3000						Air Tech Lab
CV-2334	10/6/2026 7:30:00 AM						170000					Air Tech Lab; [User entered 17%]
CV-2334	10/8/2026 9:22:00 AM					2755						AtmAA
CV-2334	10/8/2026 9:22:00 AM						118400					AtmAA; [User entered 11.84%]
CV-2334	10/8/2026 9:23:57 AM	8.3	75.4	0.0	16.3			167.5	167.6	1.78	1.79	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2334	10/9/2026 2:33:11 PM	5.0	79.2	0.3	15.5			167.4	166.9	-5.77	-5.76	Valve Comment:orifice plate insert is shot;Valve Adjustment:NSPS/EG CAC
CV-2334	10/15/2026 2:10:00 PM					116						AtmAA
CV-2334	10/15/2026 2:13:15 PM	9.5	75.8	0.1	14.6			167.2	167.1	-3.11	-2.90	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2334	10/20/2026 1:16:00 PM					3650						AtmAA

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2334	10/20/2026 1:18:18 PM	10.5	69.7	0.1	19.7			174.0	174.0	-3.80	-3.80	Valve Adjustment:High Temp
CV-2334	10/26/2026 10:25:00 AM					4230						AtmAA
CV-2334	10/26/2026 10:30:53 AM	6.4	70.1	0.3	23.2			174.4	174.4	-7.16	-7.07	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2337	10/8/2026 8:10:00 AM					3700						Air Tech Lab
CV-2337	10/8/2026 8:10:00 AM						170000					Air Tech Lab; [User entered 17%]
CV-2337	10/12/2026 1:06:18 PM	8.7	78.5	0.0	12.8			152.7	153.2	-9.05	-3.37	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2337	10/12/2026 1:07:36 PM	7.9	79.2	0.0	12.9			153.3	153.3	-3.65	-3.57	
CV-2337	10/12/2026 2:40:00 PM					2690						AtmAA
CV-2337	10/19/2026 8:50:56 AM	10.2	0.0	0.0	89.8			153.8	154.0	0.16	-3.26	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2337	10/19/2026 8:52:22 AM	11.7	0.0	0.0	88.3			154.0	154.0	-3.45	-3.44	Valve Adjustment:NSPS/EG CAC,High Temp;Well Condition:Lorentz Pump Installed
CV-2337	10/26/2026 10:02:00 AM					4270						AtmAA
CV-2337	10/26/2026 10:10:07 AM	14.6	73.3	0.0	12.1			153.9	153.9	-1.89	-1.87	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2341	10/1/2026 11:15:14 AM	22.7	51.3	0.7	25.3			122.1	122.2	-7.43	-6.17	,
CV-2341	10/12/2026 9:06:00 AM					1000						Air Tech Lab
CV-2341	10/12/2026 9:06:00 AM						160000					Air Tech Lab; [User entered 16%]
CV-2341	10/27/2026 10:14:44 AM	0.9	83.8	0.0	15.3			165.0	74.3	-1.19	-1.18	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2341	10/27/2026 10:15:18 AM	0.7	85.5	0.0	13.8			165.0	70.4	-1.20	-1.21	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed
CV-2344	10/1/2026 10:30:00 AM					1810						AtmAA
CV-2344	10/1/2026 10:30:08 AM	19.5	65.9	0.0	14.6			144.2	145.3	-5.73	-5.73	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2344	10/5/2026 9:10:00 AM					1200						AirTech Lab
CV-2344	10/5/2026 9:10:00 AM						93000					AirTech Lab; [User entered 9.3%]
CV-2344	10/5/2026 1:45:00 PM					3.96						AtmAA
CV-2344	10/5/2026 1:45:00 PM						0					<0.10 AtmAA; [User entered 0%]

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2344	10/5/2026 1:45:14 PM	29.7	70.3	0.0	0.0			154.5	154.7	-6.59	-6.35	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2344	10/14/2026 8:20:00 AM	24.6	61.5	0.1	13.8			151.3	151.9	-12.13	-11.88	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2344	10/19/2026 9:31:02 AM	23.9	65.3	0.0	10.8			154.5	154.9	-6.62	-6.49	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2344	10/26/2026 9:19:27 AM	14.8	0.0	0.0	85.2			146.1	146.3	-7.14	-7.08	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2344	10/26/2026 9:22:00 AM					2010						AtmAA
CV-2345	10/5/2026 9:05:00 AM					230						AirTech Lab
CV-2345	10/5/2026 9:05:00 AM						26000					AirTech Lab; [User entered 2.6%]
CV-2345	10/14/2026 2:16:01 PM	15.4	53.7	0.3	30.6			133.2	132.8	-8.05	-8.06	Valve Adjustment:NSPS/EG CAI,High Temp;Well Repairs:Valve
CV-2345	10/14/2026 2:17:33 PM	15.6	55.0	0.2	29.2			132.2	132.6	-8.06	-8.07	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2345	10/27/2026 9:50:50 AM	32.5	65.0	2.4	0.1			127.6	128.6	-5.40	-5.29	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2346	10/1/2026 10:21:20 AM	6.3	78.5	0.0	15.2			185.8	185.4	-7.33	-7.33	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	10/1/2026 10:25:00 AM					2210						AtmAA
CV-2346	10/5/2026 9:00:00 AM					380						AirTech Lab
CV-2346	10/5/2026 9:00:00 AM						38000					AirTech Lab; [User entered 3.8%]
CV-2346	10/5/2026 1:30:00 PM					105						AtmAA
CV-2346	10/5/2026 1:30:00 PM						5100					AtmAA; [User entered 0.51%]
CV-2346	10/5/2026 1:31:20 PM	16.0	82.2	0.0	1.8			188.5	188.7	-7.45	-7.28	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2346	10/13/2026 3:04:35 PM	14.2	72.7	0.0	13.1			186.6	186.8	-11.20	-11.12	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	10/19/2026 9:19:00 AM	7.5	79.3	0.0	13.2			190.1	189.7	-7.57	-7.75	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	10/26/2026 9:26:46 AM	21.3	0.0	0.0	78.7			187.6	188.3	-8.13	-7.55	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	10/26/2026 9:28:00 AM					2520						AtmAA
CV-2347	10/5/2026 8:55:00 AM					660						AirTech Lab
CV-2347	10/5/2026 8:55:00 AM						50000					AirTech Lab; [User entered 5.0%]

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2347	10/14/2026 2:22:29 PM	7.8	41.9	0.0	50.3			137.2	137.4	-6.34	-6.38	Valve Adjustment:NSPS/EG CAI,High Temp;Well Repairs:Valve
CV-2347	10/14/2026 2:23:22 PM	7.6	42.1	0.0	50.3			138.2	138.5	-6.40	-6.42	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2347	10/27/2026 9:55:17 AM	11.4	54.3	0.1	34.2			141.3	141.5	-4.15	-4.14	Valve Comment:well too tall for system adjustment
CV-2348	10/1/2026 12:08:04 PM	16.3	42.3	0.0	41.4			139.9	139.9	-7.46	-7.44	NSPS/EG CAI,High Temp
CV-2348	10/1/2026 12:08:31 PM	17.7	49.7	0.1	32.5			140.2	140.2	-7.43	-7.42	NSPS/EG CAI,High Temp
CV-2348	10/5/2026 8:50:00 AM					420						AirTech Lab
CV-2348	10/5/2026 8:50:00 AM						34000					AirTech Lab; [User entered 3.4%]
CV-2348	10/27/2026 10:00:49 AM	6.9	80.9	1.2	11.0			156.3	156.5	-11.87	-12.08	Valve Comment:hard piped
CV-2349	10/1/2026 1:30:00 PM					2780						AtmAA
CV-2349	10/1/2026 1:36:07 PM	17.3	76.1	0.0	6.6			159.2	158.7	-0.05	-0.07	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.;Well Condition:Lorentz Pump Installed
CV-2349	10/7/2026 7:53:34 AM	7.7	69.2	0.0	23.1			173.1	173.5	-1.25	-0.80	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2349	10/7/2026 7:55:00 AM					3360						AtmAA
CV-2349	10/7/2026 7:55:00 AM						177400					AtmAA; [User entered 17.74%]
CV-2349	10/12/2026 9:30:00 AM					2700						Air Tech Lab
CV-2349	10/12/2026 9:30:00 AM						190000					Air Tech Lab; [User entered 19%]
CV-2349	10/14/2026 9:03:12 AM	0.0	0.0	0.0	100.0			176.3	178.4	-2.39	-2.37	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2349	10/14/2026 9:05:00 AM					4140						AtmAA
CV-2349	10/19/2026 10:18:23 AM	18.4	68.9	0.0	12.7			186.7	186.0	-1.78	-1.69	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2349	10/26/2026 8:13:00 AM					4350						AtmAA
CV-2349	10/26/2026 8:20:52 AM	3.9	0.0	0.0	96.1			172.0	175.1	0.40	0.39	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2350	10/9/2026 7:20:00 AM					3200						AirTech Lab
CV-2350	10/9/2026 7:20:00 AM						160000					AirTech Lab; [User entered 16%]
CV-2350	10/9/2026 9:55:13 AM	5.2	71.7	0.8	22.3			128.2	128.3	-13.84	-13.86	Valve Comment:valve to tall
CV-2350	10/30/2026 8:45:43 AM	4.7	74.6	1.5	19.2			98.1	98.1	-13.16	-12.83	Valve Comment:Well stuck open
CV-2351	10/5/2026 9:22:00 AM					0						AirTech Lab
CV-2351	10/5/2026 9:22:00 AM						0					AirTech Lab; [User entered 0%]

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2351	10/13/2026 10:36:28 AM	1.8	3.9	17.4	76.9			85.8	85.9	-9.56	-9.61	Valve Adjustment:NSPS/EG CAI,High O2;Well Repairs:Valve
CV-2351	10/20/2026 11:30:58 AM	14.4	24.4	11.4	49.8			98.1	98.3	-6.09	-5.92	Valve Adjustment:NSPS/EG CAI,High O2
CV-2351	10/20/2026 11:31:30 AM	14.7	24.4	11.2	49.7			98.3	98.4	-5.54	-5.54	Valve Adjustment:NSPS/EG CAI,High O2
CV-2352	10/5/2026 10:27:07 AM	12.5	80.6	1.1	5.8			138.1	136.5	-7.47	-4.29	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-2352	10/5/2026 10:27:58 AM	12.7	76.7	1.9	8.7			139.1	139.2	-5.16	-5.12	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2352	10/6/2026 2:40:00 PM					920						AtmAA
CV-2352	10/6/2026 2:40:00 PM						181100					AtmAA; [User entered 18.11%]
CV-2352	10/6/2026 2:52:49 PM	34.6	65.4	0.0	0.0			187.9	192.7	71.93	-3.01	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Pnumatic Pump Installed
CV-2352	10/6/2026 2:54:54 PM	30.1	69.6	0.0	0.3			191.9	192.2	-3.80	-3.69	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2352	10/13/2026 1:26:37 PM	19.0	62.1	3.3	15.6			116.3	115.7	-8.48	-8.42	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2352	10/14/2026 7:45:00 AM					750						Air Tech Lab
CV-2352	10/14/2026 7:45:00 AM						210000					Air Tech Lab; [User entered 21%]
CV-2352	10/20/2026 11:24:50 AM	4.2	77.6	1.7	16.5			117.5	114.9	-5.69	-5.46	Valve Adjustment:Decreased Flow/Vacuum
CV-2353-PLR	10/12/2026 9:50:00 AM					510						Air Tech Lab
CV-2353-PLR	10/12/2026 9:50:00 AM						190000					Air Tech Lab; [User entered 19%]
CV-2353-PLR	10/13/2026 10:50:34 AM	3.8	64.1	3.1	29.0			122.9	122.8	-12.75	-12.61	Valve Adjustment:Decreased Flow/Vacuum
CV-2353-PLR	10/27/2026 9:09:06 AM	2.5	69.8	2.1	25.6			112.1	109.4	-11.28	-11.46	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-2354	10/12/2026 8:48:00 AM					1700						Air Tech Lab
CV-2354	10/12/2026 8:48:00 AM						190000					Air Tech Lab; [User entered 19%]
CV-2354	10/13/2026 2:05:00 PM					3700						AtmAA
CV-2354	10/13/2026 2:47:46 PM	21.3	71.8	0.1	6.8			183.1	182.9	2.18	1.64	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Positive Static Press.,Valve 100% Open

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-2354	10/13/2026 2:51:36 PM	22.0	74.0	0.0	4.0			183.2	185.2	1.50	1.58	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Positive Static Press.,Valve 100% Open
CV-2354	10/14/2026 8:09:06 AM	13.2	74.6	0.5	11.7			188.5	188.4	-5.28	-4.70	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2354	10/20/2026 9:24:58 AM	0.0	0.0	0.0	100.0			187.9	188.7	-3.19	-2.80	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2354	10/20/2026 9:35:00 AM					2620						AtmAA
CV-2354	10/26/2026 8:00:00 AM					2330						AtmAA
CV-2354	10/26/2026 8:01:14 AM	7.2	0.0	0.0	92.8			185.6	185.6	-2.45	-2.25	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24002	10/1/2026 10:28:47 AM	35.8	42.8	0.0	21.4			113.4	113.4	-3.39	-3.38	Valve Adjustment:Barely Open
CV-24002	10/16/2026 11:02:56 AM	32.5	48.2	2.0	17.3			107.9	106.7	-4.00	-3.96	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24003	10/1/2026 10:26:19 AM	30.1	46.3	0.4	23.2			108.6	109.0	-1.84	-1.87	Valve Adjustment:Barely Open
CV-24003	10/16/2026 10:53:24 AM	34.5	49.6	0.7	15.2			108.5	108.9	-2.26	-2.28	Valve Adjustment:Barely Open
CV-24007	10/1/2026 1:58:09 PM	6.5	75.9	0.2	17.4			162.0	162.2	-0.41	-0.40	Valve Adjustment:High Temp,Barely Open
CV-24007	10/5/2026 2:42:07 PM	33.7	62.9	0.2	3.2			163.1	162.8	-0.31	-0.30	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24007	10/5/2026 2:45:00 PM					1950						AtmAA
CV-24007	10/5/2026 2:45:00 PM						145200					AtmAA; [User entered 14.52%]
CV-24007	10/6/2026 7:05:00 AM					1600						Air Tech Lab
CV-24007	10/6/2026 7:05:00 AM						170000					Air Tech Lab; [User entered 17%]
CV-24007	10/13/2026 8:04:39 AM	15.0	71.4	0.0	13.6			160.8	161.1	-1.73	-1.71	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24007	10/13/2026 8:05:00 AM					1820						AtmAA
CV-24007	10/20/2026 7:59:27 AM	28.9	48.4	0.3	22.4			157.7	157.8	-2.74	-2.74	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24007	10/20/2026 8:05:00 AM					652.5						AtmAA
CV-24007	10/27/2026 7:23:00 AM					627						AtmAA
CV-24007	10/27/2026 7:26:10 AM	23.5	42.4	0.7	27.5		5.9	155.0	155.0	-15.52	-15.40	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24017	10/6/2026 8:15:00 AM					998						AtmAA
CV-24017	10/6/2026 8:15:00 AM						110250					AtmAA; [User entered 11.025%]
CV-24017	10/6/2026 8:18:44 AM	21.6	68.5	0.5	9.4			186.4	186.6	-5.45	-5.39	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	10/13/2026 7:35:00 AM					870						AirTech Lab

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24017	10/13/2026 7:35:00 AM						110000					AirTech Lab; [User entered 11%]
CV-24017	10/13/2026 9:00:00 AM					1440						AtmAA
CV-24017	10/13/2026 9:00:37 AM	28.1	62.3	0.9	8.7			184.0	183.9	-9.44	-9.22	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	10/20/2026 8:10:46 AM	11.9	65.1	2.6	20.4			144.2	144.5	-7.50	-7.39	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	10/20/2026 8:20:00 AM					546						AtmAA
CV-24049	10/5/2026 1:54:02 PM	12.2	71.5	0.0	16.3			191.8	191.8	-3.02	-2.98	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24049	10/6/2026 7:45:00 AM					1500						Air Tech Lab
CV-24049	10/6/2026 7:45:00 AM						130000					Air Tech Lab; [User entered 13%]
CV-24049	10/12/2026 9:50:41 AM	18.6	72.2	0.0	9.2			190.2	190.2	-6.95	-6.95	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24049	10/12/2026 9:55:00 AM					2350						AtmAA
CV-24049	10/19/2026 2:12:04 PM	8.2	82.5	0.1	9.2			165.7	174.9	-2.32	-2.26	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24049	10/21/2026 9:48:34 AM	1.0	88.8	0.6	9.6			86.6	88.0	-6.62	-6.92	Valve Adjustment:Barely Open,Plugged/Pinched Suspected;Well Condition:Lorentz Pump Installed
CV-24053	10/7/2026 7:45:00 AM					150						Air Tech Lab
CV-24053	10/7/2026 7:45:00 AM						18000					Air Tech Lab; [User entered 1.8%]
CV-24053	10/14/2026 10:00:56 AM	24.3	43.4	0.6	31.7			98.9	99.3	-9.98	-9.83	
CV-24053	10/21/2026 9:35:37 AM	29.0	44.5	0.4	26.1			95.8	78.1	-6.29	-5.60	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24055	10/7/2026 9:17:41 AM	4.3	54.3	2.1	39.3			147.2	147.4	-0.48	-0.49	Valve Adjustment:High Temp,Barely Open,Reduce Sys. Vac. - Flare Down
CV-24055	10/8/2026 1:04:27 PM	13.6	56.7	1.8	27.9			141.4	141.5	-0.32	-0.34	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24055	10/8/2026 1:05:00 PM					1730						AtmAA
CV-24055	10/13/2026 8:00:00 AM					1200						AirTech Lab
CV-24055	10/13/2026 8:00:00 AM						58000					AirTech Lab; [User entered 5.8%]
CV-24055	10/23/2026 8:01:24 AM	2.9	32.9	6.5	57.7			148.1	147.7	-2.47	-2.48	Valve Adjustment:High Temp,Barely Open
CV-24055	10/26/2026 1:50:00 PM					1120						AtmAA

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24055	10/26/2026 1:52:32 PM	7.1	33.0	5.4	54.5			140.5	140.5	-8.11	-7.03	Valve Adjustment:NSPS/EG CAl,No Flow Measurement,High Temp,High O2,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-24055	10/26/2026 1:57:36 PM	6.5	38.5	4.3	50.7			149.7	149.7	-7.12	-7.07	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-24062	10/7/2026 7:25:00 AM					720						Air Tech Lab
CV-24062	10/7/2026 7:25:00 AM						100000					Air Tech Lab; [User entered 10%]
CV-24062	10/7/2026 1:40:00 PM					1010						AtmAA
CV-24062	10/7/2026 1:40:00 PM						86900					AtmAA; [User entered 8.69%]
CV-24062	10/7/2026 1:46:54 PM	36.5	63.4	0.0	0.1			179.2	179.8	-3.83	-3.79	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	10/14/2026 1:50:00 PM					773.5						AtmAA
CV-24062	10/14/2026 1:54:36 PM	38.7	61.2	0.1	0.0			178.8	178.3	-9.98	-9.77	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	10/20/2026 1:50:00 PM					1210						AtmAA
CV-24062	10/20/2026 1:53:31 PM	26.7	64.8	0.0	8.5			171.9	171.8	-6.63	-6.60	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	10/27/2026 1:28:50 PM	24.4	71.6	0.0	4.0			173.0	173.2	-9.44	-9.44	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	10/27/2026 1:35:00 PM					418						AtmAA
CV-24063	10/7/2026 7:20:00 AM					1000						Air Tech Lab
CV-24063	10/7/2026 7:20:00 AM						84000					Air Tech Lab; [User entered 8.4%]
CV-24063	10/14/2026 11:04:24 AM	11.9	76.6	0.0	11.5			172.9	174.2	-10.41	-10.56	
CV-24063	10/15/2026 2:00:00 PM					2200						AtmAA
CV-24063	10/15/2026 2:00:03 PM	20.7	74.9	0.1	4.3			164.1	163.8	-3.53	-3.37	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	10/20/2026 8:25:00 AM					2170						AtmAA
CV-24063	10/20/2026 8:28:54 AM	8.4	68.0	3.5	20.1			160.1	160.1	-6.94	-6.91	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	10/29/2026 9:05:28 AM	14.4	78.5	0.0	7.0			180.9	180.9	-13.65	-13.52	Valve Adjustment:No Flow Measurement,High O2;Well Condition:Lorentz Pump Installed
CV-24063	10/29/2026 9:11:00 AM					1575						AtmAA
CV-24064-PLR	10/7/2026 7:30:00 AM					1600						Air Tech Lab
CV-24064-PLR	10/7/2026 7:30:00 AM						130000					Air Tech Lab; [User entered 13%]

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24064-PLR	10/7/2026 1:27:02 PM	16.4	81.5	0.1	2.0			191.2	191.1	-4.92	-4.54	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-PLR	10/7/2026 1:30:00 PM					1820						AtmAA
CV-24064-PLR	10/7/2026 1:30:00 PM						99100					AtmAA; [User entered 9.91%]
CV-24064-PLR	10/14/2026 10:31:46 AM	42.2	57.8	0.0	0.0			190.2	190.2	-10.53	-10.11	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-PLR	10/14/2026 10:35:00 AM					2400						AtmAA
CV-24064-PLR	10/20/2026 1:06:11 PM	15.9	70.4	0.0	13.7			189.8	190.6	-7.91	-7.58	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-PLR	10/20/2026 1:10:00 PM					2330						AtmAA
CV-24064-PLR	10/27/2026 9:32:00 AM					1370						AtmAA
CV-24064-PLR	10/27/2026 9:32:22 AM	6.5	82.2	0.0	11.3			191.7	191.4	-5.79	-5.73	Valve Adjustment:No Flow Measurement,High Temp
CV-24065-TP17	10/7/2026 9:03:42 AM	9.1	42.6	1.4	46.9			123.0	123.1	-3.46	-3.51	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24065-TP17	10/13/2026 8:20:00 AM					390						AirTech Lab
CV-24065-TP17	10/13/2026 8:20:00 AM						22000					AirTech Lab; [User entered 2.2%]
CV-24065-TP17	10/23/2026 7:50:35 AM	11.0	40.6	2.4	46.0			120.2	120.4	-6.26	-6.26	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24066	10/1/2026 11:46:06 AM	14.1	41.1	0.0	44.8			113.7	113.8	-1.21	-1.18	,
CV-24066	10/12/2026 8:58:00 AM					140						Air Tech Lab
CV-24066	10/12/2026 8:58:00 AM						18000					Air Tech Lab; [User entered 1.8%]
CV-24066	10/27/2026 10:07:03 AM	16.8	39.1	0.1	44.0			112.4	112.7	-1.61	-1.61	Valve Adjustment:Barely Open
CV-24066	10/27/2026 10:07:36 AM	18.8	42.5	0.2	38.5			113.8	114.0	-1.61	-1.61	Valve Adjustment:Barely Open
CV-24069	10/5/2026 10:11:52 AM	10.2	42.9	0.6	46.3			129.2	129.0	-1.48	-1.48	Valve Adjustment:Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-24069	10/13/2026 7:25:00 AM					540						AirTech Lab
CV-24069	10/13/2026 7:25:00 AM						43000					AirTech Lab; [User entered 4.3%]
CV-24069	10/20/2026 10:13:43 AM	9.7	46.6	0.6	43.1			121.6	120.6	-1.44	-1.45	Valve Adjustment:Barely Open
CV-24070	10/7/2026 7:55:00 AM					830						Air Tech Lab
CV-24070	10/7/2026 7:55:00 AM						63000					Air Tech Lab; [User entered 6.3%]
CV-24070	10/13/2026 8:28:43 AM	41.7	50.5	0.0	7.8			137.5	135.7	-14.47	-9.06	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24070	10/13/2026 8:31:35 AM	34.8	54.6	0.0	10.7			136.8	136.5	-11.75	-11.75	Valve Adjustment:High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24070	10/13/2026 8:32:52 AM	38.2	53.5	0.0	8.3			136.5	136.4	-11.67	-11.67	Valve Adjustment:High Temp

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24070	10/28/2026 3:30:21 PM	34.1	59.1	0.1	6.7			141.1	141.0	-9.93	-9.99	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24071	10/5/2026 1:31:44 PM	31.9	60.5	0.1	7.5			135.9	135.9	-0.72	-0.72	Valve Adjustment:High Temp,Barely Open
CV-24071	10/13/2026 7:30:00 AM					440						AirTech Lab
CV-24071	10/13/2026 7:30:00 AM						62000					AirTech Lab; [User entered 6.2%]
CV-24071	10/20/2026 1:36:52 PM	22.7	58.1	0.6	18.6			133.8	134.0	-0.60	-0.52	Valve Adjustment:High Temp,Barely Open
CV-24075-TP15	10/7/2026 1:15:00 PM					1970						AtmAA
CV-24075-TP15	10/7/2026 1:15:00 PM						102100					AtmAA; [User entered 10.21%]
CV-24075-TP15	10/7/2026 1:19:39 PM	8.1	81.3	0.0	10.6			184.0	183.8	-4.45	-4.43	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TP15	10/14/2026 10:38:34 AM	23.5	65.4	1.6	9.5			180.8	180.5	-11.37	-10.78	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-TP15	10/14/2026 10:43:00 AM					2600						AtmAA
CV-24075-TP15	10/20/2026 1:13:29 PM	4.4	77.9	1.0	16.7			182.7	182.8	-8.12	-8.12	Valve Adjustment:No Flow Measurement,High Temp
CV-24075-TP15	10/20/2026 1:20:00 PM					2240						AtmAA
CV-24075-TP15	10/27/2026 9:42:13 AM	10.8	79.0	0.2	10.0			185.0	184.8	-6.74	-6.74	Valve Adjustment:No Flow Measurement,High Temp
CV-24075-TP15	10/27/2026 9:45:00 AM					1850						AtmAA
CV-24077	10/1/2026 11:31:54 AM	12.3	60.9	0.0	26.8			154.6	154.6	-2.93	-2.92	NSPS/EG CAI,High Temp
CV-24077	10/1/2026 11:32:36 AM	12.2	61.4	0.0	26.4			155.0	155.0	-2.75	-2.78	NSPS/EG CAI,High Temp
CV-24077	10/5/2026 9:55:00 AM					1200						AtmAA
CV-24077	10/5/2026 9:55:00 AM						34800					AtmAA; [User entered 3.48%]
CV-24077	10/5/2026 9:57:24 AM	15.9	68.8	0.0	15.3			157.0	156.9	-4.66	-4.61	Valve Adjustment:No Flow Measurement,High Temp
CV-24077	10/12/2026 1:33:29 PM	15.7	59.0	0.0	25.3			154.3	153.9	-6.58	-3.01	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24077	10/12/2026 1:34:22 PM	15.5	62.9	0.0	21.6			154.3	154.6	-2.58	-2.51	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	10/12/2026 1:37:00 PM					1255						AtmAA
CV-24077	10/19/2026 8:06:13 AM	10.7	86.7	0.0	2.6			165.6	165.4	-0.29	-0.20	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	10/26/2026 10:33:00 AM					1680						AtmAA

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24077	10/26/2026 10:42:39 AM	19.7	76.7	0.0	3.6			167.0	167.9	0.29	-2.65	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24079-TP8	10/1/2026 10:44:33 AM	16.4	65.9	0.0	17.7			163.1	159.7	-1.19	-1.85	NSPS/EG CAI,High Temp
CV-24079-TP8	10/1/2026 10:45:49 AM	20.6	61.5	0.0	17.9			158.3	157.4	-1.52	-1.51	NSPS/EG CAI,High Temp
CV-24079-TP8	10/8/2026 1:29:25 PM	24.2	70.1	0.0	5.7			169.5	170.6	-0.61	-0.56	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24079-TP8	10/8/2026 1:30:00 PM					1460						AtmAA
CV-24079-TP8	10/8/2026 1:30:00 PM						89300					AtmAA; [User entered 8.93%]
CV-24079-TP8	10/15/2026 9:55:00 AM					943						AtmAA
CV-24079-TP8	10/15/2026 9:55:26 AM	36.7	49.4	0.3	13.6			153.1	153.5	-4.79	-4.76	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24079-TP8	10/21/2026 8:20:00 AM					845						AtmAA
CV-24079-TP8	10/21/2026 8:20:35 AM	24.4	53.8	0.0	21.8			160.5	161.0	-2.47	-2.41	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24079-TP8	10/29/2026 9:33:30 AM	36.5	53.4	0.0	10.1			148.7	149.5	-6.77	-6.76	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24079-TP8	10/29/2026 9:37:00 AM					618						AtmAA
CV-24082	10/13/2026 8:20:39 AM	41.0	46.8	0.0	12.2			91.3	91.3	-8.38	-8.37	Well Condition:Lorentz Pump Installed
CV-24082	10/20/2026 1:17:39 PM	11.0	77.8	0.1	11.1			110.4	112.9	-0.22	-0.22	Valve Adjustment:Barely Open
CV-24083	10/5/2026 1:27:20 PM	43.2	48.9	0.7	7.2			126.5	126.7	-6.41	-6.24	Valve Adjustment:Decreased Flow/Vacuum
CV-24083	10/20/2026 1:30:38 PM	43.7	53.7	0.4	2.2			122.4	122.3	-5.82	-5.82	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24084-TP11	10/8/2026 8:45:28 AM	6.6	83.6	0.0	9.8			187.3	187.1	-6.66	-6.07	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP11	10/8/2026 8:49:00 AM					2580						AtmAA
CV-24084-TP11	10/8/2026 8:49:00 AM						98400					AtmAA; [User entered 9.84%]
CV-24084-TP11	10/14/2026 2:08:09 PM	16.5	76.8	0.1	6.6			185.4	185.5	-13.52	-13.48	Valve Adjustment:No Flow Measurement,High Temp
CV-24084-TP11	10/14/2026 2:35:00 PM					3470						AtmAA
CV-24084-TP11	10/21/2026 7:58:02 AM	2.1	87.9	0.0	10.0			186.7	186.8	-4.87	-5.05	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-TP11	10/21/2026 8:00:00 AM					3570						AtmAA

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [ºF]	Adj Temp [ºF]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24084-TP11	10/28/2026 10:01:00 AM					3430						AtmAA
CV-24084-TP11	10/28/2026 10:09:28 AM	10.3	83.0	0.0	6.7			186.1	186.3	-7.75	-7.75	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24088	10/6/2026 8:57:17 AM	0.0	0.0	21.0	79.0			113.0	113.3	-0.01	-0.01	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24088	10/6/2026 8:57:43 AM	0.0	0.0	20.9	79.1			113.5	113.3	-0.01	-0.01	Valve Adjustment:High O2,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24088	10/20/2026 2:13:44 PM	42.2	55.7	0.2	1.9			111.1	111.7	-2.15	-2.11	Valve Adjustment:Barely Open
CV-24095	10/1/2026 1:39:15 PM	13.6	74.0	0.0	12.4			191.4	191.5	-4.30	-4.24	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24095	10/1/2026 1:40:00 PM					2820						AtmAA
CV-24095	10/7/2026 7:46:52 AM	7.9	76.2	0.0	15.9			192.4	192.4	-3.56	-3.12	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24095	10/7/2026 7:50:00 AM					2510						AtmAA
CV-24095	10/7/2026 7:50:00 AM						177850					AtmAA; [User entered 17.785%]
CV-24095	10/13/2026 8:55:00 AM					2600						AirTech Lab
CV-24095	10/13/2026 8:55:00 AM						220000					AirTech Lab; [User entered 22%]
CV-24095	10/14/2026 8:45:00 AM					4450						AtmAA
CV-24095	10/14/2026 8:54:32 AM	13.8	65.5	0.0	20.7			183.9	186.1	2.79	-1.43	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-24095	10/14/2026 8:57:33 AM	14.5	72.3	0.0	13.2			185.5	185.8	-0.55	-0.40	Valve Adjustment:NSPS/EG CAC,High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-24095	10/21/2026 9:05:00 AM					3490						AtmAA
CV-24095	10/21/2026 9:07:57 AM	3.3	72.8	0.0	23.9			183.5	182.8	8.44	8.49	Valve Adjustment:High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24095	10/28/2026 1:44:00 PM					3640						AtmAA
CV-24095	10/28/2026 1:49:19 PM	5.1	73.7	0.1	21.2			189.5	189.3	23.33	22.68	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24096	10/13/2026 9:34:28 AM	34.8	48.4	2.1	14.7			73.8	74.3	-5.31	-5.19	Valve Adjustment:Decreased Flow/Vacuum
CV-24096	10/20/2026 10:15:07 AM	43.1	56.2	0.7	0.0			86.9	87.0	-3.59	-3.46	Valve Adjustment:Decreased Flow/Vacuum
CV-24097	10/9/2026 9:52:16 AM	49.0	42.9	3.3	4.8			96.5	96.9	-5.04	-4.89	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24097	10/20/2026 10:23:00 AM	54.8	45.1	0.1	0.0			83.1	84.0	-3.70	-3.77	Valve Adjustment:Increased Flow/Vacuum
CV-24098	10/9/2026 9:47:06 AM	34.2	48.8	3.1	13.9			87.6	89.1	-13.90	-13.88	Valve Comment:valve stuck open
CV-24098	10/30/2026 9:03:31 AM	43.6	40.5	2.4	13.5			62.4	62.4	-16.55	-16.99	Valve Adjustment:Decreased Flow/Vacuum
CV-24099	10/9/2026 9:43:11 AM	17.5	76.3	1.2	5.0			89.3	89.5	-13.97	-13.97	Valve Comment:valve stuck open
CV-24099	10/30/2026 8:58:53 AM	0.3	3.0	20.0	76.7			59.8	60.0	-13.16	-13.88	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24100	10/9/2026 9:32:42 AM	17.6	72.6	1.1	8.7			127.4	127.2	-6.42	-3.40	Valve Adjustment:Decreased Flow/Vacuum
CV-24100	10/13/2026 8:40:00 AM					68						AirTech Lab
CV-24100	10/13/2026 8:40:00 AM						11000					AirTech Lab; [User entered 1.1%]
CV-24100	10/28/2026 1:11:35 PM	17.2	69.0	1.0	12.8			79.4	77.9	-9.34	-9.36	
CV-24101	10/7/2026 8:05:00 AM					43						Air Tech Lab
CV-24101	10/7/2026 8:05:00 AM						5700					Air Tech Lab; [User entered 0.57%]
CV-24101	10/9/2026 9:29:11 AM	45.0	50.3	0.5	4.2			106.7	108.8	-9.31	-8.10	Valve Adjustment:Decreased Flow/Vacuum
CV-24101	10/9/2026 9:35:13 AM	7.5	68.6	4.5	19.4			101.3	101.6	-13.84	-13.72	Valve Adjustment:Decreased Flow/Vacuum
CV-24101	10/30/2026 8:50:38 AM	38.9	58.0	1.1	2.0			118.8	113.3	-17.32	-17.06	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24102	10/5/2026 9:46:47 AM						17000					[User entered 1.7%]
CV-24102	10/5/2026 9:47:47 AM	45.4	50.0	0.0	4.6			113.3	113.5	-0.49	-0.49	Well Comment:Pump off upon arrival;Well Condition:Pnumatic Pump Installed
CV-24102	10/20/2026 7:43:14 AM	43.5	54.6	0.0	1.9			67.5	67.6	-0.86	-0.85	
CV-24120	10/11/2026 11:39:56 AM	1.4	15.5	17.5	65.7			80.2	80.4	-3.02	-2.56	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open;Well Comment:Pump is active;Well Condition:Lorentz Pump Installed
CV-24120	10/11/2026 11:41:48 AM	1.8	16.4	16.7	65.1			81.0	80.1	-1.37	-10.22	Valve Adjustment:High O2,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24120	10/11/2026 11:43:43 AM	2.2	25.3	15.6	57.0			80.0	79.3	-1.72	-1.72	Valve Adjustment:High O2;Well Comment:pump is active;Well Condition:Lorentz Pump Installed
CV-24120	10/13/2026 7:45:00 AM					330						AirTech Lab
CV-24120	10/13/2026 7:45:00 AM						22000					AirTech Lab; [User entered 2.2%]
CV-24120	10/26/2026 8:47:43 AM	1.8	22.0	16.6	59.6			64.2	64.2	-8.10	-8.14	Valve Adjustment:High O2,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24121	10/8/2026 7:45:00 AM					0						Air Tech Lab
CV-24121	10/8/2026 7:45:00 AM						0					Air Tech Lab; [User entered 0%]
CV-24121	10/11/2026 11:46:36 AM	34.7	60.0	0.0	5.2			123.1	123.1	-7.51	-7.39	Well Condition:Pnumatic Pump Installed
CV-24121	10/26/2026 8:43:18 AM	32.5	64.4	0.3	2.8			107.9	105.1	-5.94	-4.62	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24122	10/8/2026 8:15:00 AM					130						Air Tech Lab
CV-24122	10/8/2026 8:15:00 AM						8000					Air Tech Lab; [User entered 0.80%]
CV-24122	10/11/2026 11:03:13 AM	36.1	28.6	7.8	27.6			76.6	76.8	-6.50	-6.17	Valve Adjustment:NSPS/EG CAI,High O2,Valve 100% Open,Decreased Flow/Vacuum
CV-24122	10/11/2026 11:04:24 AM	36.3	29.3	7.7	26.8			77.2	77.3	-3.59	-3.56	Valve Adjustment:High O2
CV-24122	10/26/2026 9:00:07 AM	56.8	41.1	0.1	2.0			67.2	67.6	-3.50	-3.56	Valve Adjustment:Barely Open
CV-24123	10/13/2026 7:41:04 AM	44.7	52.1	0.0	3.2			115.5	115.5	-5.19	-5.15	Valve Adjustment:NSPS/EG CAI,No Flow Measurement;Well Comment:Needs o.p
CV-24125-TP20	10/11/2026 11:13:09 AM	43.4	51.5	0.0	5.1			93.4	92.2	-13.22	-6.14	Valve Adjustment:Decreased Flow/Vacuum;Well Comment:pump offline;Well Condition:Pnumatic Pump Installed
CV-24125-TP20	10/11/2026 11:14:42 AM	43.4	49.5	0.0	7.0			91.8	92.0	-3.24	-3.25	Well Comment:pump offline;Well Condition:Pnumatic Pump Installed
CV-24125-TP20	10/13/2026 7:50:00 AM					25						AirTech Lab
CV-24125-TP20	10/13/2026 7:50:00 AM						5200					AirTech Lab; [User entered 0.52%]
CV-24125-TP20	10/26/2026 9:10:30 AM	27.6	64.6	1.5	6.3			107.5	107.6	-8.44	-8.44	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down,Plugged/Pinched Suspected
CV-24126	10/5/2026 1:44:55 PM	21.6	40.1	2.1	36.2			176.6	176.6	-4.44	-4.33	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24126	10/5/2026 1:45:00 PM					1710						AtmAA
CV-24126	10/5/2026 1:45:00 PM						60600					AtmAA; [User entered 6.06%]
CV-24126	10/12/2026 10:30:00 AM					1750						AtmAA

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [ºF]	Adj Temp [ºF]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24126	10/12/2026 10:33:32 AM	12.8	40.8	2.7	43.7			176.7	176.7	-7.32	-6.95	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24126	10/21/2026 9:39:03 AM	6.3	53.5	0.8	39.4			181.5	181.9	-3.82	-3.69	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24126	10/21/2026 10:25:00 AM					2560						AtmAA
CV-24126	10/26/2026 10:06:44 AM	8.4	41.5	2.8	47.3			175.9	175.9	-6.06	-5.95	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24126	10/26/2026 10:10:00 AM					2260						AtmAA
CV-24127	10/5/2026 1:40:00 PM					3660						AtmAA
CV-24127	10/5/2026 1:40:00 PM						169300					AtmAA; [User entered 16.93%]
CV-24127	10/5/2026 1:40:34 PM	37.6	62.3	0.1	0.0			174.6	175.5	-5.40	-5.27	Valve Adjustment:No Flow Measurement,High Temp
CV-24127	10/8/2026 7:55:00 AM					1400						Air Tech Lab
CV-24127	10/8/2026 7:55:00 AM						87000					Air Tech Lab; [User entered 8.7%]
CV-24127	10/12/2026 2:03:41 PM	35.6	61.8	0.0	2.6			162.8	162.8	-9.15	-9.10	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24127	10/12/2026 2:05:00 PM					1320						AtmAA
CV-24127	10/20/2026 1:09:24 PM	16.5	40.5	0.9	42.1			145.5	145.5	-6.38	-6.17	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24127	10/20/2026 1:11:00 PM					1720						AtmAA
CV-24127	10/26/2026 10:12:05 AM	18.1	35.7	1.6	44.6			144.5	144.5	-5.93	-5.71	Valve Adjustment:No Flow Measurement,High Temp
CV-24127	10/26/2026 10:15:00 AM					1070						AtmAA
CV-24128	10/6/2026 7:35:00 AM					2100						Air Tech Lab
CV-24128	10/6/2026 7:35:00 AM						85000					Air Tech Lab; [User entered 8.5%]
CV-24128	10/11/2026 11:24:46 AM	21.2	57.1	0.3	21.4			93.5	93.8	-1.28	-0.81	Valve Adjustment:Decreased Flow/Vacuum;Well Comment:lorentz fittings need to be secured;Well Condition:Lorentz Pump Installed
CV-24128	10/11/2026 11:27:14 AM	15.2	63.7	0.0	21.1			92.9	92.8	-0.67	-0.67	Valve Adjustment:Barely Open;Well Comment:fittings secured;Well Condition:Lorentz Pump Installed
CV-24128	10/26/2026 9:21:22 AM	39.8	58.6	0.3	1.3			125.5	125.5	-0.28	-0.28	Valve Adjustment:Barely Open
CV-24134-TP19	10/5/2026 1:35:00 PM					3080						AtmAA
CV-24134-TP19	10/5/2026 1:35:00 PM						120200					AtmAA; [User entered 12.02%]
CV-24134-TP19	10/5/2026 1:37:24 PM	38.3	61.6	0.1	0.0			152.9	152.2	-1.66	-1.62	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24134-TP19	10/12/2026 1:55:00 PM					2690						AtmAA

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24134-TP19	10/12/2026 1:57:36 PM	32.6	67.4	0.0	0.0			134.5	135.1	-3.83	-3.81	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24134-TP19	10/26/2026 10:15:41 AM	15.5	71.2	0.0	13.3			150.2	150.1	-5.72	-5.41	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open
CV-24134-TP19	10/26/2026 10:20:00 AM					3350						AtmAA
CV-24138	10/5/2026 10:30:00 AM					1010						AtmAA
CV-24138	10/5/2026 10:30:00 AM						148300					AtmAA; [User entered 14.83%]
CV-24138	10/5/2026 10:33:11 AM	13.8	80.4	0.0	5.8			163.0	163.1	-4.61	-4.45	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24138	10/9/2026 8:35:00 AM					1700						AirTech Lab
CV-24138	10/9/2026 8:35:00 AM						340000					AirTech Lab; [User entered 34%]
CV-24138	10/14/2026 8:39:51 AM	31.0	46.3	2.0	20.7			71.2	71.0	-7.86	-7.71	Valve Adjustment:No Flow Measurement;Well Condition:Pnumatic Pump Installed
CV-24138	10/20/2026 9:45:06 AM	3.0	75.0	0.4	21.6			162.1	162.3	-5.51	-5.25	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24138	10/20/2026 9:45:39 AM	3.0	77.0	0.7	19.3			162.7	163.1	-5.04	-4.99	Valve Adjustment:Decreased Flow/Vacuum
CV-24138	10/20/2026 9:50:00 AM					1430						AtmAA
CV-24138	10/26/2026 8:54:48 AM	26.4	0.0	3.8	69.8			64.0	64.1	-4.55	-4.25	Valve Adjustment:No Flow Measurement;Well Condition:Pnumatic Pump Installed
CV-24138	10/28/2026 1:38:07 PM	18.9	46.1	4.9	30.2			89.6	89.6	-6.00	-5.96	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24139	10/5/2026 9:26:00 AM					490						AirTech Lab
CV-24139	10/5/2026 9:26:00 AM						160000					AirTech Lab; [User entered 16%]
CV-24139	10/13/2026 9:58:30 AM	5.1	43.1	6.8	45.0			86.1	87.2	-11.50	-11.34	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24139	10/13/2026 10:05:24 AM	5.4	44.3	6.9	43.4			87.8	88.7	-11.25	-11.25	Valve Adjustment:NSPS/EG CAI,High O2
CV-24139	10/20/2026 9:36:34 AM	5.7	59.3	4.8	30.2			86.8	86.9	-10.11	-9.92	Valve Adjustment:Decreased Flow/Vacuum
CV-24140	10/1/2026 1:48:19 PM	9.8	72.6	0.0	17.6			160.2	160.2	-2.37	-2.27	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24140	10/1/2026 1:50:00 PM					1640						AtmAA
CV-24140	10/5/2026 9:24:00 AM					1200						AirTech Lab
CV-24140	10/5/2026 9:24:00 AM						200000					AirTech Lab; [User entered 20%]
CV-24140	10/7/2026 7:35:17 AM	5.1	75.2	0.1	19.6			124.2	123.3	-2.86	-2.68	Valve Adjustment:No Flow Measurement;Well Condition:Pnumatic Pump Installed

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-24140	10/20/2026 9:32:41 AM	3.1	80.7	0.3	15.9			123.9	124.1	-9.10	-8.93	Valve Adjustment:Decreased Flow/Vacuum
CV-24141	10/9/2026 8:40:00 AM					110						AirTech Lab
CV-24141	10/9/2026 8:40:00 AM						28000					AirTech Lab; [User entered 2.8%]
CV-24141	10/13/2026 10:39:49 AM	2.6	6.2	17.1	74.1			82.9	82.8	-9.12	-9.00	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open
CV-24141	10/20/2026 11:37:36 AM	16.2	29.5	8.0	46.3			98.1	97.6	-0.09	-0.56	Valve Adjustment:NSPS/EG CAI,High O2,Increased Flow/Vacuum
CV-24141	10/20/2026 11:38:22 AM	15.8	28.7	8.3	47.2			98.4	98.4	-0.81	-0.81	Valve Adjustment:NSPS/EG CAI,High O2
CV-24142	10/9/2026 8:30:00 AM					1100						AirTech Lab
CV-24142	10/9/2026 8:30:00 AM						160000					AirTech Lab; [User entered 16%]
CV-24142	10/13/2026 9:50:57 AM	0.7	15.3	15.1	68.9			131.8	132.1	-5.63	-4.68	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Decreased Flow/Vacuum,Barely Open
CV-24142	10/13/2026 9:53:09 AM	0.4	11.5	16.2	71.9			133.1	133.3	-4.74	-4.72	Valve Adjustment:NSPS/EG CAI,High Temp,High O2
CV-24142	10/20/2026 9:49:21 AM	2.1	44.4	8.8	44.7			170.7	170.9	-4.19	-3.99	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Decreased Flow/Vacuum
CV-24142	10/20/2026 9:50:53 AM	2.3	46.1	8.6	43.0			170.8	171.1	-2.92	-2.92	Valve Adjustment:NSPS/EG CAI,High Temp,High O2
CV-24142	10/20/2026 9:55:00 AM					1500						AtmAA
CV-24142	10/26/2026 8:33:34 AM	4.6	0.0	2.3	93.1			162.2	162.2	-4.04	-3.95	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24142	10/26/2026 8:35:00 AM					2360						AtmAA
CV-24143	10/9/2026 8:25:00 AM					13						AirTech Lab
CV-24143	10/9/2026 8:25:00 AM						6000					AirTech Lab; [User entered 0.60%]
CV-24143	10/13/2026 10:32:36 AM	0.2	1.5	18.8	79.5			82.0	82.0	-10.38	-10.33	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Well (Watered In)
CV-24143	10/20/2026 10:07:52 AM	0.1	0.6	20.8	78.5				88.1		-0.01	
CV-24143	10/20/2026 11:27:21 AM	0.5	5.7	19.5	74.3			98.9	98.8	-3.86	-3.89	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Well (Watered In)
CV-24144	10/9/2026 9:50:12 AM	44.0	44.5	0.9	10.6			103.6	103.6	-4.82	-4.99	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24144	10/20/2026 10:27:56 AM	57.6	42.2	0.0	0.2			102.6	102.7	-3.18	-3.22	Valve Adjustment:Increased Flow/Vacuum
CV-99	10/8/2026 7:35:00 AM					110						Air Tech Lab
CV-99	10/8/2026 7:35:00 AM						11000					Air Tech Lab; [User entered 1.1%]
CV-99	10/13/2026 10:56:53 AM	30.3	59.4	1.7	8.6			81.9	82.0	-15.58	-15.34	

Table 2. Monthly LEA Selected Wells - October 2026
Chiquita Canyon Landill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Comments
CV-99	10/26/2026 9:07:28 AM	26.5	67.8	1.1	4.6			70.0	70.0	-11.31	-11.18	Valve Adjustment:High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1770N	10/6/2026 7:10:00 AM					130						Air Tech Lab
H-1770N	10/6/2026 7:10:00 AM						19000					Air Tech Lab; [User entered 1.9%]
H-1770N	10/12/2026 12:51:00 PM	30.2	59.8	0.0	10.0			89.2	87.5	-2.87	-2.79	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Barely Open
H-1770N	10/16/2026 10:56:15 AM	29.4	69.1	0.1	1.4			93.4	93.4	-2.08	-2.10	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-2165W	10/8/2026 2:39:54 PM	0.1	0.1	21.9	77.9			142.7	141.2	0.00	0.00	Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down
H-2165W	10/8/2026 2:42:00 PM					808						AtmAA
H-2165W	10/8/2026 2:42:00 PM						39500					AtmAA; [User entered 3.95%]
H-2165W	10/9/2026 8:20:00 AM					230						AirTech Lab
H-2165W	10/9/2026 8:20:00 AM						28000					AirTech Lab; [User entered 2.8%]
H-2165W	10/9/2026 1:56:27 PM	17.3	72.4	0.0	10.3			141.1	141.0	-2.47	-2.68	Valve Adjustment:NSPS/EG CAI,High Temp
H-2165W	10/9/2026 2:03:34 PM	19.5	70.2	0.0	10.3			141.7	140.6	-2.76	-2.74	Valve Adjustment:High Temp
H-2165W	10/14/2026 2:27:33 PM	20.2	19.0	10.3	50.5			113.3	113.2	-2.08	-1.55	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-2165W	10/28/2026 1:20:43 PM	19.0	65.9	0.2	14.9			140.2	139.6	-3.38	-3.39	Valve Adjustment:NSPS/EG CAI,High Temp
H-2165W	10/28/2026 1:32:37 PM	7.0	76.2	0.1	16.7			138.2	140.0	-1.22	-1.22	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-2273W	10/5/2026 9:15:00 AM					81						AirTech Lab
H-2273W	10/5/2026 9:15:00 AM						8400					AirTech Lab; [User entered 0.84%]
H-2273W	10/9/2026 9:24:29 AM	15.2	32.3	0.7	51.8			126.7	126.6	-0.95	-0.95	Valve Adjustment:Barely Open
H-2273W	10/18/2026 1:32:49 PM	19.2	31.3	0.0	49.5			124.9	122.6	-0.42	-0.34	Valve Adjustment:Decreased Flow/Vacuum
H-2273W	10/18/2026 1:34:40 PM	19.1	31.2	0.0	49.7			121.7	121.3	-0.32	-0.32	