All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
A-01	10/2/2026 9:54:34 AM	57.3	38.3	0.0	4.4			1.5	0.0	87.7	87.7	-20.48	-20.47			20.756	20.754	-20.16	0.31	1171	34.4312423	-118.6437358	
A-02	10/2/2026 10:19:40 AM	53.6	37.7	0.0	8.7			1.4	0.0	100.7	100.7	-11.52	-11.53			11.900	11.849	-11.24	0.29	1176	34.4316170	-118.6432943	
A-03	10/2/2026 10:24:38 AM	54.5	37.3	0.0	8.2			1.5	0.0	122.8	122.9	-19.86	-20.02			20.282	20.432	-19.07	0.95	1186	34.4320172	-118.6428395	
A-04	10/2/2026 10:30:21 AM	58.2	38.9	0.0	2.9			1.5	0.0	99.1	99.1	-19.62	-19.66			19.964	20.079	-18.69	0.97	1181	34.4321827	-118.6422298	
A-05	10/2/2026 11:00:13 AM	57.0	38.2	0.0	4.8			1.5	0.0	98.1	98.1	-18.87	-18.98			19.343	19.391	-18.61	0.37	1199	34.4325148	-118.6416465	
B-01	10/15/2026 9:42:03 AM	2.6	22.7	0.0	74.7			0.1	0.0	76.6	76.7	-2.93	-2.32	6.2	4.2	9.471	4.392	-20.98	-18.66	1228	34.4338327	-118.6396150	Valve Adjustment:Decreased Flow/Vacuum
B-01	10/15/2026 9:42:47 AM	2.5	18.1	0.0	79.4			0.1	0.0	76.8	76.8	-2.26	-2.27	4.3	4.2	4.534	4.467	-21.31	-19.04	1257	34.4338635	-118.6396228	
B-02R	10/15/2026 9:49:20 AM	23.6	28.4	0.0	48.0			0.8	0.0	76.3	76.3	-8.05	-8.06	6.0	6.0	3.658	3.721	-20.45	-12.39	1230	34.4335517	-118.6394978	
B-03R	10/15/2026 9:57:50 AM	15.9	26.4	0.0	57.7			0.6	0.0	84.3	84.1	-0.82	-0.90	1.5	1.9	0.549	0.855	-1.98	-1.08	1224	34.4337750	-118.6388302	
B-05	10/15/2026 10:15:11 AM	16.4	27.1	0.3	56.2			0.6	187.3	91.2	91.8	-0.32	-0.48	5.2	9.7	0.162	0.564	-1.51	-1.03	1229	34.4336478	-118.6382673	Valve Adjustment:Increased Flow/Vacuum
B-05	10/15/2026 10:16:16 AM	16.7	27.0	0.3	56.0			0.6	186.7	91.8	91.8	-0.51	-0.50	9.3	9.8	0.522	0.569	-1.10	-0.6	1225	34.4336350	-118.6382537	
B-06	10/15/2026 10:24:00 AM	20.3	27.5	0.0	52.2			0.7	0.0	83.7	82.2	-0.19	-0.29	1.0	5.4	0.006	0.175	-1.15	-0.86	1215	34.4340060	-118.6377523	Valve Adjustment:NSPS/EG CAI,Increased Flow/Vacuum
B-06	10/15/2026 10:25:28 AM	19.5	27.4	0.0	53.1			0.7	0.0	82.0	82.0	-0.29	-0.27	4.5	4.0	0.119	0.094	-0.64	-0.37	1223	34.4340005	-118.6377617	
B-07R	10/15/2026 8:40:24 AM	34.8	27.3	5.8	32.1			1.3	5.5	84.5	84.6	-0.14	-0.12	1.4	1.2	0.036	0.028	0.10	0.22	1209	34.4342683	-118.6374348	Valve Adjustment:NSPS/EG CAI,High O2
B-07R	10/15/2026 8:44:21 AM	38.8	29.9	4.2	27.1			1.3	6.5	84.1	84.3	-0.13	-0.13	0.5	1.1	0.005	0.022	0.14	0.27	1218	34.4342967	-118.6374173	Valve Adjustment:NSPS/EG CAI,Valve 100% Open
B-08	10/15/2026 10:31:17 AM	1.2	1.7	19.1	78.0			0.7	4.1	85.5	85.6	-2.57	-2.42	2.0	2.5	0.076	0.125	-2.03	0.39	1214	34.4337567	-118.6373473	Valve Adjustment:NSPS/EG CAI,High O2
B-08	10/15/2026 10:32:33 AM	1.4	2.1	18.7	77.8			0.7	4.2	85.7	85.8	-2.48	-2.56	2.5	2.2	0.121	0.099	-2.05	0.51	1219	34.4337597	-118.6373453	Valve Adjustment:NSPS/EG CAI,High O2,Valve 100% Open
B-09	10/15/2026 8:30:40 AM	32.4	32.1	0.0	35.5			1.0	0.0	91.6	91.8	-0.29	-0.26	4.6	4.6	2.180	2.167	-3.02	-2.76	1209	34.4342230	-118.6370422	
B-10	10/15/2026 8:20:43 AM	22.4	28.3	0.0	49.3			0.8	0.0	90.1	90.3	-0.28	-0.26	4.1	4.1	1.725	1.757	-2.75	-2.49	1215	34.4340177	-118.6365603	
B-11	10/15/2026 7:45:54 AM	33.8	30.9	0.0	35.3			1.1	0.0	93.9	92.9	-0.11	-0.16	4.0	3.9	0.036	0.034	-2.15	-1.99	1135	34.4348195	-118.6368992	
B-12	10/15/2026 10:04:07 AM	20.6	27.7	0.0	51.7			0.7	0.0	96.0	96.1	-0.47	-0.47	2.4	3.4	0.035	0.072	-1.95	-1.48	1234	34.4340307	-118.6385145	
B-13	10/15/2026 9:28:18 AM	28.3	30.3	0.0	41.4			0.9	0.0	92.6	93.0	-0.53	-0.58	11.9	12.8	0.853	0.993	-20.87	-20.29	1216	34.4344228	-118.6379017	
B-14	10/15/2026 7:36:56 AM	23.1	28.0	0.0	48.9			0.8	0.0	92.3	91.9	-0.35	-0.34	2.3	2.5	0.560	0.647	-2.18	-1.84	1126	34.4349272	-118.6370592	
C-03	10/2/2026 10:08:27 AM	31.4	30.4	6.5	31.7			1.0	4.9	97.7	97.7	-20.66	-20.73			20.965	21.033	-20.36	0.37	1181	34.4313988	-118.6435058	Valve Adjustment:NSPS/EG CAI,High O2
C-03	10/2/2026 10:14:05 AM	25.4	24.1	9.2	41.3			1.1	4.5	97.6	97.6	-20.59	-20.62			20.904	20.897	-20.33	0.29	1178	34.4314065	-118.6435102	
C-07	10/30/2026 7:45:07 AM	46.4	36.4	1.6	15.6			1.3	9.8	82.5	82.6	-23.68	-23.72			23.805	23.786	0.01	23.73	1180	34.4326502	-118.6414108	
C-08	10/7/2026 2:08:03 PM	1.4	1.3	20.3	77.0			1.1	3.8	112.3	112.5	-7.13	-7.16	0.6	0.6	0.007	0.009	-7.15	0.01	1214	34.4336443	-118.6408657	Valve Adjustment:NSPS/EG CAI,High O2,Reduce Sys. Vac. - Flare Down
C-08	10/7/2026 2:09:01 PM	1.2	1.2	20.3	77.3			1.0	3.8	112.8	112.8	-7.05	-7.13	0.6	1.1	0.008	0.023	-7.12	0.01	1202	34.4336578	-118.6408897	Valve Adjustment:NSPS/EG CAI,High O2
C-08	10/15/2026 10:36:17 AM	0.6	0.4	20.6	78.4			1.5	3.8	88.8	91.5	-21.24	-20.99			0.095	0.000	-21.08	-0.09	1206	34.4336378	-118.6408875	Valve Adjustment:NSPS/EG CAI,High O2
C-10	10/7/2026 1:33:34 PM	53.9	38.2	0.0	7.9			1.4	0.0	128.0	128.0	-7.99	-8.03			8.101	8.110	-8.12	-0.09	1217	34.4347155	-118.6411920	
C-10	10/15/2026 10:50:48 AM	58.4	41.6	0.0	0.0			1.4	0.0	99.1	99.4	-20.72	-20.72	56.1	56.1	20.984	20.981	0.31	21.03	1219	34.4347102	-118.6411980	Well Comment:no system port
C-11	10/30/2026 8:40:23 AM	57.7	41.2	0.0	1.1			1.4	0.0	83.3	84.2	-21.85	-21.73	3.1	3.2	0.204	0.220	-21.98	-0.25	1229	34.4352452	-118.6413125	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum,Barely Open
C-11	10/30/2026 8:42:04 AM	56.6	42.2	0.0	1.2			1.3	0.0	84.0	84.0	-21.63	-21.63	3.2	3.2	0.218	0.215	-21.86	-0.23	1225	34.4352543	-118.6413192	
C-12	10/12/2026 8:01:11 AM	58.8	38.6	0.0	2.6			1.5	0.0	60.7	60.6	-18.16	-18.18	2.1	2.1	0.026	0.025	-17.75	0.43	1229	34.4359790	-118.6408937	
C-15	10/12/2026 8:18:41 AM	11.0	7.6	17.4	64.0			1.4	3.7	59.5	59.5	-18.13	-18.17	1.5	1.2	0.005	0.003	-17.76	0.41	1222	34.4362605	-118.6410425	Valve Adjustment:NSPS/EG CAI,High O2
C-15	10/12/2026 8:19:51 AM	10.6	7.5	17.4	64.5			1.4	3.7	59.4	59.4	-18.10	-18.04	2.3	1.9	0.011	0.008	-17.76	0.28	1216	34.4362612	-118.6410545	Valve Adjustment:NSPS/EG CAI,High O2
C-19	10/30/2026 9:25:58 AM	57.2	42.8	0.0	0.0			1.3	0.0	62.9	62.9	106.98	-5.31			0.000	5.375	0.01	5.32	1225	34.4375628	-118.6421692	Valve Adjustment:NSPS/EG CAI,Increased Flow/Vacuum,Barely Open
C-19	10/30/2026 9:37:13 AM	56.7	42.5	0.0	0.8			1.3	0.0	96.9	97.1	-7.36	-4.89			7.412	4.986	0.01	4.9	1235	34.4375552	-118.6421372	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum
C-27	10/12/2026 8:10:27 AM	0.0	0.5	21.5	78.0			0.0	3.6	58.0	57.9	-18.13	-18.03	0.4	0.4	0.002	0.003	-17.76	0.27	1232	34.4361657	-118.6409727	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High O2
C-27	10/12/2026 8:11:56 AM	0.0	0.3	21.6	78.1			0.0	3.6	57.2	57.0	-17.87	-17.95	0.2	0.3	0.001	0.002	-17.72	0.23	1230	34.4361715	-118.6409765	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High O2
C-28	10/7/2026 10:34:56 AM	53.9	39.0	0.0	7.1			1.4	0.0	109.8	109.9	-5.42	-5.42	2.4	2.4	1.529	1.578	-8.10	-2.68	1225	34.4354315	-118.6413833	
C-29	10/7/2026 1:15:35 PM	28.8	61.0	0.0	10.2			0.5	0.0	117.2	117.5	-1.34	-1.34			1.344	1.337	-7.92	-6.58	1224	34.4348522	-118.6412445	Valve Adjustment:Reduce Sys. Vac. - Flare Down
C-30	10/11/2026 12:48:07 PM	54.6	40.7	0.0	4.7			1.3	0.0	122.4	122.8	-3.56	-3.55	4.4	4.4	0.125	0.123	-20.56	-17.01	1255	34.4342467	-118.6412777	
CV-02	10/15/2026 1:09:20 PM	13.0	23.2	0.0	63.8			0.6	0.0	123.1	122.9	-2.67	-1.99	0.9	1.1	0.086	0.140	-21.26	-19.27	1243	34.4335615	-118.6413793	
CV-03	10/15/2026 1:22:41 PM	37.7	34.2	0.0	28.1			1.1	0.0	118.9	119.1	-4.11	-4.08	10.3	10.4	0.683	0.696	-6.63	-2.55	1228	34.4333350	-118.6414513	
CV-04	10/15/2026 1:16:04 PM	41.5	34.5	0.2	23.8			1.2	119.0	115.1	114.8	-0.28	-0.32	11.5	12.2	0.028	0.031	-2.17	-1.85	1213	34.4330932	-118.6416653	
CV-05	10/29/2026 10:09:35 AM	57.7	37.6	0.0	4.7			1.5	0.0	106.8	106.9	-23.67	-23.86	4.1	4.7	0.373	0.490	-23.77	0.09	1228	34.4328008	-118.6422102	

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-06	10/1/2026 12:56:38 PM	49.8	46.8	0.0	3.4			1.1	0.0	105.0	105.1	-8.30	-8.31	4.0	4.0	0.102	0.103	-12.33	-4.02	1216	34.4326683	-118.6428417	Valve Adjustment:Audible Flow,Reduce Sys. Vac. - Flare Down
CV-108-52	10/5/2026 9:20:00 AM					64																	AirTech Lab
CV-108-52	10/5/2026 9:20:00 AM						7000																AirTech Lab; [User entered 0.70%]
CV-108-52	10/15/2026 9:19:36 AM	45.2	36.7	2.4	15.7			1.2	6.5	82.1	82.0	-5.60	-4.39			0.079	0.000	-5.44	-1.05	1281	34.4333927	-118.6506805	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-108-52	10/15/2026 9:59:53 AM	52.4	43.9	0.0	3.8			1.2	0.0	88.1	88.7	-4.06	-5.39			0.045	0.040	-3.92	1.47	1279	34.4333993	-118.6506800	
CV-108-52	10/27/2026 9:27:50 AM	39.5	34.3	3.8	22.4			1.2	5.9	71.4	72.3	-4.36	-4.16			0.000	0.000	-4.24	-0.08	1269	34.4334052	-118.6506810	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-113	10/8/2026 7:40:00 AM					19																	Air Tech Lab
CV-113	10/8/2026 7:40:00 AM						4900																Air Tech Lab; [User entered 0.49%]
CV-113	10/13/2026 9:10:42 AM	1.9	3.0	20.5	74.6			0.6	3.6	65.1	64.7	-11.54	-11.54	9.4	10.6	0.107	0.136	-11.36	0.18	1342	34.4369538	-118.6467380	Valve Adjustment:NSPS/EG CAI,High O2
CV-113	10/13/2026 9:12:18 AM	0.3	0.8	21.2	77.7			0.4	3.7	63.5	63.4	-11.49	-11.42	9.3	9.9	0.104	0.119	-11.23	0.19	1347	34.4369753	-118.6467238	Valve Adjustment:NSPS/EG CAI,High O2
CV-113	10/26/2026 8:55:15 AM	0.0	1.9	20.8	77.3			0.0	3.7	62.8	63.2	-7.84	-7.84	3.2	2.8	0.059	0.047	-7.81	0.03	1345	34.4369627	-118.6466888	Valve Adjustment:Barely Open,Surging Liquid in Header,Plugged/Pinched Suspected
CV-114	10/5/2026 9:10:28 AM	1.6	71.1	0.0	27.3			0.0	0.0	185.6	185.4	-7.92	-7.88			8.263	8.215	-8.84	-0.96	1327	34.4367214	-118.6476548	Valve Adjustment:No Flow Measurement,High Temp
CV-114	10/5/2026 9:15:00 AM					3590																	AtmAA
CV-114	10/5/2026 9:15:00 AM						164700																AtmAA; [User entered 16.47%]
CV-114	10/8/2026 7:50:00 AM					2000																	Air Tech Lab
CV-114	10/8/2026 7:50:00 AM						160000																Air Tech Lab; [User entered 16%]
CV-114	10/12/2026 8:20:24 AM	1.7	79.2	0.4	18.7			0.0	46.8	179.7	179.6	-8.97	-8.91			9.061	9.098	1.77	10.68	1346	34.4367139	-118.6476408	Valve Adjustment:No Flow Measurement,High Temp
CV-114	10/12/2026 8:25:00 AM					3630																	AtmAA
CV-114	10/19/2026 8:03:05 AM	1.9	81.7	1.3	15.1			0.0	11.6	182.3	182.3	-8.96	-8.78			8.900	8.804	-9.03	-0.25	1358	34.4367345	-118.6475930	Valve Adjustment:No Flow Measurement,High Temp
CV-114	10/26/2026 7:50:00 AM					2750																	AtmAA
CV-114	10/26/2026 7:56:07 AM	1.6	70.4	1.5	26.5			0.0	17.7	149.1	162.8	-8.42	-8.29	58.3	57.1	8.574	8.393	-7.81	0.48	1324	34.4367433	-118.6475920	Valve Adjustment:No Flow Measurement,High Temp
CV-1424	10/28/2026 9:01:47 AM	36.4	37.4	0.0	26.2			1.0	0.0	108.7	107.3	-3.62	-2.08	22.5	9.0	3.202	0.507	-17.80	-15.72	1390	34.4351240	-118.6450777	Valve Adjustment:Decreased Flow/Vacuum
CV-1532A	10/5/2026 10:20:24 AM	4.6	78.3	1.2	15.9			0.1	13.3	117.0	117.3	-9.23	-6.58			9.641	6.911	-9.22	-2.64	1288	34.4338692	-118.6508322	Valve Adjustment:No Flow Measurement,Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-1532A	10/5/2026 10:21:19 AM	3.8	73.0	2.6	20.6			0.1	7.9	117.5	117.6	-7.81	-7.86			8.169	8.227	-9.30	-1.44	1289	34.4338695	-118.6508305	Valve Adjustment:No Flow Measurement;Well Condition:Pnumatic Pump Installed
CV-1532A	10/6/2026 2:20:00 PM					1270																	AtmAA
CV-1532A	10/6/2026 2:20:00 PM						105700																AtmAA; [User entered 10.57%]
CV-1532A	10/6/2026 2:26:45 PM	11.4	68.1	1.6	18.9			0.2	11.8	152.9	153.1	-4.57	-4.10			4.638	4.024	-3.37	0.73	1289	34.4338809	-118.6508387	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-1532A	10/12/2026 7:20:00 AM					1400																	Air Tech Lab
CV-1532A	10/12/2026 7:20:00 AM						220000																Air Tech Lab; [User entered 22%]
CV-1532A	10/13/2026 1:38:14 PM	12.2	68.2	0.3	19.3			0.2	64.3	101.5	101.6	-9.61	-8.45			10.021	8.902	-10.71	-2.26	1281	34.4338696	-118.6508325	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-1532A	10/28/2026 1:57:18 PM	0.8	71.1	0.4	27.7			0.0	69.3	93.4	93.5	-10.53	-10.56			10.600	10.626	-10.42	0.14	1261	34.4338928	-118.6508632	
CV-1534A-F	10/14/2026 8:40:47 AM	1.4	82.0	0.7	15.9			0.0	22.7	97.0	96.8	-13.30	-11.27			13.485	11.341	0.00	11.27	1273	34.4336458	-118.6507752	Valve Comment:No system port;Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-1534A-F	10/14/2026 2:05:58 PM	3.0	80.2	0.0	16.8			0.0	0.0	122.1	120.3	-9.21	-9.16			9.281	9.179	0.00	9.16	1263	34.4336457	-118.6508092	Valve Adjustment:Surging Liquid in Header
CV-1534A-F	10/16/2026 2:37:47 PM	3.4	83.3	0.0	13.3			0.0	0.0	104.0	103.8	-13.02	-13.20			13.015	13.194	0.00	13.2	1275	34.4336390	-118.6507953	Valve Adjustment:Increased Flow/Vacuum
CV-1535	10/1/2026 11:49:37 AM	33.3	37.4	0.0	29.3			0.9	0.0	123.5	123.0	-3.03	-2.15	0.0	0.0	0.035	0.081	-8.07	-5.92	1237	34.4333467	-118.6504323	,
CV-1535	10/12/2026 9:20:00 AM					19																	Air Tech Lab
CV-1535	10/12/2026 9:20:00 AM						5000																Air Tech Lab; [User entered 0.50%]
CV-1535	10/27/2026 9:40:08 AM	43.8	43.0	0.0	13.2			1.0	0.0	121.4	121.4	-2.36	-2.25			0.186	0.184	-12.17	-9.92	1300	34.4332972	-118.6503385	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-1601D	10/6/2026 1:23:13 PM	48.2	43.7	0.0	8.1			1.1	0.0	116.7	116.6	-0.45	-0.45	7.7	7.7	1.264	1.250	-11.46	-11.01	1315	34.4310945	-118.6486722	Valve Adjustment:Audible Flow

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-1601D	10/19/2026 1:28:34 PM	51.3	42.4	0.1	6.2			1.2	62.0	112.3	113.6	-0.36	-0.68	6.0	12.8	0.762	3.461	-13.56	-12.88	1318	34.4311020	-118.6486638	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-1601S	10/6/2026 1:25:22 PM	46.2	43.6	0.0	10.2			1.1	0.0	118.9	118.9	-0.43	-0.44	5.3	5.5	0.590	0.630	-11.99	-11.55	1317	34.4311045	-118.6486698	Valve Adjustment:Audible Flow
CV-1601S	10/19/2026 1:31:41 PM	47.8	42.7	0.0	9.5			1.1	0.0	115.2	115.1	-0.77	-0.77	5.5	5.3	0.632	0.599	-13.61	-12.84	1319	34.4310898	-118.6486692	Valve Adjustment:Audible Flow
CV-1604	10/7/2026 11:06:06 AM	50.4	40.6	0.0	9.0			1.2	0.0	115.1	117.6	0.19	-0.31	0.0	2.5	-0.045	0.130	-5.85	-5.54	1224	34.4322208	-118.6450458	NSPS/EG CAI,Positive Static Press.,Reduced System Vacuum,Increased Flow/Vacuum
CV-1604	10/7/2026 11:06:43 AM	55.3	43.8	0.0	0.9			1.3	0.0	120.5	120.7	-0.50	-0.50	0.9	1.0	0.018	0.022	-5.62	-5.12	1237	34.4321707	-118.6450723	NSPS/EG CAC,Reduced System Vacuum
CV-1604	10/27/2026 9:19:46 AM						12000																[User entered 1.2%]
CV-1604	10/27/2026 9:21:23 AM	46.4	47.4	0.0	6.2			1.0	0.0	131.9	130.6	-3.80	-3.32	5.7	1.6	0.209	0.017	-15.46	-12.14	1276	34.4321658	-118.6450368	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Decreased Flow/Vacuum
CV-1604	10/27/2026 9:29:24 AM	43.8	48.1	0.0	8.1			0.9	0.0	126.0	126.0	-2.61	-2.60	2.3	2.3	0.585	0.571	-15.27	-12.67	1275	34.4321645	-118.6450343	
CV-1604	10/27/2026 9:35:00 AM					5.75																	AtmAA
CV-1604	10/27/2026 9:35:00 AM						3500																AtmAA; [User entered 0.35%]
CV-1701D	10/5/2026 12:18:15 PM						103000																[User entered 10.3%]
CV-1701D	10/5/2026 12:20:57 PM	16.4	49.2	3.2	31.3			0.3	9.9	131.9	126.4	-16.39	-0.39	1.2	0.3	0.405	0.017	-16.69	-16.3	1311	34.4335848	-118.6433357	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Decreased Flow/Vacuum,Plugged/Pinched Suspected
CV-1701D	10/5/2026 12:26:05 PM	19.3	54.0	0.2	26.5			0.4	132.7	126.0	129.4	-0.40	-0.31	0.5	0.5	0.064	0.067	-16.44	-16.13	1297	34.4335702	-118.6433157	Valve Adjustment:Barely Open,Plugged/Pinched Suspected
CV-1701D	10/22/2026 9:55:32 AM	3.7	80.6	0.0	15.7			0.0	0.0	79.4	79.6	-6.70	-6.80	6.2	6.3	9.872	10.027	3.41	10.21	1302	34.4335922	-118.6433443	Valve Adjustment:Increased Flow/Vacuum
CV-1701S	10/2/2026 1:15:58 PM	0.1	0.0	21.2	78.8			2.5	3.7	120.7	120.7	-1.80	-0.42	3.6	12.5	0.081	1.003	-16.30	-15.88	1284	34.4335842	-118.6433235	Valve Adjustment:NSPS/EG CAI,High O2,Valve 100% Closed
CV-1701S	10/5/2026 12:37:35 PM						132000																[User entered 13.2%]
CV-1701S	10/5/2026 12:43:02 PM	24.6	54.5	0.0	20.9			0.5	0.0	121.9	138.8	3.56	-0.32	3.7	5.2	0.086	0.178	-16.65	-16.33	1294	34.4336068	-118.6433237	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-1701S	10/5/2026 12:50:10 PM	20.3	58.6	0.0	21.2			0.3	0.0	142.1	142.2	-0.72	-0.72	4.2	4.2	4.975	4.963	-16.53	-15.81	1294	34.4335947	-118.6433128	Valve Adjustment:Orifice Plate Changed (See OP Log),High Temp,Barely Open
CV-1701S	10/5/2026 12:55:01 PM	20.5	60.6	0.0	18.9			0.3	0.0	144.4	144.4	-0.98	-0.98	4.5	4.4	0.439	0.431	-16.71	-15.73	1297	34.4335860	-118.6433388	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-1901	10/12/2026 1:12:08 PM	19.2	71.7	0.0	9.1			0.3	0.0	101.8	102.3	-0.56	-0.56	1.4	1.3	0.038	0.036	-12.42	-11.86	1320	34.4357073	-118.6508405	Valve Adjustment:Audible Flow,Barely Open
CV-1901	10/29/2026 9:49:57 AM	17.0	71.0	0.0	12.0			0.2	0.0	109.0	109.0	-2.01	-0.72	1.4	1.5	0.042	0.044	-12.90	-12.18	1340	34.4357018	-118.6507973	Valve Adjustment:Barely Open
CV-1902A	10/6/2026 1:35:00 PM					928																	AtmAA
CV-1902A	10/6/2026 1:35:00 PM						147500																AtmAA; [User entered 14.75%]
CV-1902A	10/6/2026 1:35:09 PM	24.8	60.5	2.9	11.8			0.4	4.1	173.0	171.1	-7.83	-7.58			7.922	7.719	-7.87	-0.29	1308	34.4346043	-118.6503060	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-1902A	10/8/2026 8:05:00 AM					680																	Air Tech Lab
CV-1902A	10/8/2026 8:05:00 AM						160000																Air Tech Lab; [User entered 16%]
CV-1902A	10/12/2026 2:05:00 PM					897																	AtmAA
CV-1902A	10/12/2026 2:10:10 PM	4.7	58.6	7.7	29.0			0.1	3.8	150.3	147.8	-12.40	-7.52			12.543	7.801	-12.21	-4.69	1314	34.4346093	-118.6502908	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-1902A	10/12/2026 2:15:05 PM	6.9	64.8	4.0	24.3			0.1	6.1	150.5	147.3	-9.81	-9.96			10.135	10.239	-11.63	-1.67	1323	34.4345917	-118.6502860	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,Barely Open;Well Condition:Pnumatic Pump Installed
CV-1902A	10/14/2026 8:47:31 AM	47.2	45.2	1.9	5.7			1.0	3.0	71.8	71.9	-4.53	-4.22			0.137	0.100	-5.49	-1.27	1272	34.4334097	-118.6506608	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-1902A	10/27/2026 8:58:44 AM	1.7	63.1	4.6	30.6			0.0	6.7	151.1	155.9	-11.18	-11.28			11.127	11.253	-11.11	0.17	1312	34.4346133	-118.6503133	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-1905	10/5/2026 10:16:44 AM	52.4	45.2	0.0	2.4			1.2	0.0	115.0	115.2	-3.55	-3.67	9.0	10.6	0.518	0.719	-11.05	-7.38	1409	34.4334913	-118.6459937	Valve Adjustment:Increased Flow/Vacuum
CV-2001	10/7/2026 8:10:00 AM					900																	Air Tech Lab
CV-2001	10/7/2026 8:10:00 AM						84000																Air Tech Lab; [User entered 8.4%]
CV-2001	10/13/2026 9:02:59 AM	0.0	0.0	19.9	80.1				4.0	79.2	79.5	-17.60	-17.59	0.5	1.4	0.002	0.012	-17.65	-0.06	1261	34.4322843	-118.6505782	Valve Adjustment:NSPS/EG CAI,High O2
CV-2001	10/28/2026 1:04:00 PM	4.8	56.5	6.7	32.0			0.1	4.8	94.6	94.1	-16.01	-16.43	2.7	2.4	0.045	0.036	-16.46	-0.03	1277	34.4322745	-118.6505570	Valve Adjustment:NSPS/EG CAI,High O2
CV-2001	10/28/2026 1:04:53 PM	5.0	58.9	5.0	31.1			0.1	6.2	95.6	95.6	-16.85	-16.68	2.0	4.1	0.025	0.108	-16.94	-0.26	1272	34.4322787	-118.6505497	Valve Adjustment:NSPS/EG CAC
CV-2002	10/1/2026 1:25:00 PM					3575																	AtmAA

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-2002	10/1/2026 1:26:06 PM	17.3	72.3	0.2	10.2			0.2	51.0	183.0	183.1	-6.72	-6.32			6.967	6.609	-7.42	-1.1	1266	34.4328060	-118.6511704	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	10/7/2026 7:58:33 AM	11.5	81.6	0.0	6.9			0.1	0.0	183.1	183.0	-8.35	-8.09			8.569	8.331	-9.42	-1.33	1272	34.4328125	-118.6511807	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	10/7/2026 8:00:00 AM					3120																	AtmAA
CV-2002	10/7/2026 8:00:00 AM						112700																AtmAA; [User entered 11.27%]
CV-2002	10/12/2026 9:11:00 AM					38																	Air Tech Lab
CV-2002	10/12/2026 9:11:00 AM						11000																Air Tech Lab; [User entered 1.1%]
CV-2002	10/14/2026 9:10:00 AM					2910																	AtmAA
CV-2002	10/14/2026 9:10:01 AM	34.0	65.9	0.1	0.0			0.5	0.0	179.5	179.4	-19.06	-18.37			19.319	18.706	-19.68	-1.31	1259	34.4328188	-118.6511890	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	10/21/2026 9:09:45 AM	27.6	56.5	0.4	15.5			0.5	38.8	177.0	177.0	-10.45	-10.41	189.1	188.5	10.508	10.442	-10.12	0.29	1267	34.4328043	-118.6511802	Valve Adjustment:No Flow Measurement,High Temp
CV-2002	10/21/2026 9:35:00 AM					1970																	AtmAA
CV-2002	10/26/2026 8:25:00 AM	3.9	0.0	0.0	96.1				0.0	183.3	183.7	-9.01	-9.01			9.374	9.361	-10.24	-1.23	1264	34.4328012	-118.6511712	Valve Adjustment:No Flow Measurement,High Temp
CV-2003	10/14/2026 8:51:20 AM	12.4	77.9	0.0	9.7			0.2	0.0	104.0	105.3	-6.61	-5.09	3.2	1.2	1.104	0.141	-10.40	-5.31	1271	34.4334112	-118.6507148	Valve Adjustment:Decreased Flow/Vacuum
CV-2003	10/27/2026 9:24:09 AM	12.4	77.0	0.0	10.6			0.2	0.0	99.3	99.0	-2.31	-2.03	1.1	2.1	0.134	0.449	-4.49	-2.46	1267	34.4333863	-118.6507220	Valve Adjustment:Decreased Flow/Vacuum
CV-2006	10/5/2026 2:00:00 PM					2730																	AtmAA
CV-2006	10/5/2026 2:00:00 PM						99100																AtmAA; [User entered 9.91%]
CV-2006	10/5/2026 2:01:20 PM	18.5	81.4	0.0	0.1			0.2	0.0	186.5	186.5	-5.88	-5.67	6.1	16.3	0.054	0.392	-8.26	-2.59	1319	34.4352112	-118.6506820	Valve Adjustment:High Temp
CV-2006	10/12/2026 2:22:55 PM	6.8	82.4	0.0	10.8			0.1	0.0	186.2	186.2	-11.10	-10.80	7.3	5.7	0.079	0.048	-12.66	-1.86	1315	34.4352008	-118.6506438	Valve Adjustment:High Temp
CV-2006	10/12/2026 2:30:00 PM					2200																	AtmAA
CV-2006	10/19/2026 8:43:05 AM	11.8	0.0	0.0	88.2				0.0	181.9	181.9	-6.51	-6.49	15.5	10.2	0.352	0.153	-10.67	-4.18	1318	34.4352068	-118.6506673	Valve Adjustment:High Temp
CV-2006	10/26/2026 10:13:00 AM					3940																	AtmAA
CV-2006	10/26/2026 10:13:24 AM	13.2	74.3	0.0	12.5			0.2	0.0	180.9	181.0	-5.29	-5.27	13.6	12.7	0.268	0.235	-8.18	-2.91	1331	34.4352198	-118.6506809	Valve Adjustment:High Temp
CV-2007	10/8/2026 8:00:00 AM					950																	Air Tech Lab
CV-2007	10/8/2026 8:00:00 AM						66000																Air Tech Lab; [User entered 6.6%]
CV-2007	10/8/2026 4:07:26 PM	17.7	75.7	0.0	6.6			0.2	0.0	120.7	120.7	-0.06	-0.06	1.1	1.8	0.004	0.009	-5.12	-5.06	1385	34.4361637	-118.6469770	Valve Adjustment:High Temp
CV-2007	10/23/2026 8:27:51 AM	11.8	82.2	0.0	6.0			0.1	0.0	100.7	100.7	-1.21	-1.22	1.5	1.7	0.006	0.008	-12.78	-11.56	1368	34.4361682	-118.6469857	Valve Adjustment:Barely Open
CV-2008	10/15/2026 10:22:38 AM	20.4	79.6	0.0	0.0			0.3	0.0	105.7	101.6	-2.65	-1.53	0.4	1.9	0.035	0.973	-2.48	-0.95	1377	34.4362155	-118.6462403	Valve Adjustment:Decreased Flow/Vacuum
CV-2008	10/26/2026 10:22:04 AM	19.1	80.9	0.0	0.0			0.2	0.0	109.1	109.7	-4.96	-4.97	0.1	0.3	0.005	0.018	-5.56	-0.59	1378	34.4362005	-118.6462415	Valve Adjustment:Barely Open
CV-2009	10/21/2026 10:35:02 AM	26.6	34.7	7.7	31.0			0.8	4.0	121.1	120.7	-2.51	-2.49	19.6	20.3	0.507	0.544	-4.09	-1.6	1369	34.4362573	-118.6452568	Valve Adjustment:NSPS/EG CAI,High O2
CV-2009	10/21/2026 10:48:28 AM	43.5	51.2	0.1	5.2			0.8	52.0	134.0	134.0	-3.16	-3.12	14.2	13.8	0.271	0.255	-4.08	-0.96	1368	34.4362643	-118.6452525	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2009	10/21/2026 10:50:36 AM	43.0	51.4	0.2	5.4			0.8	27.0	130.7	130.7	-2.38	-1.90	20.8	13.0	0.579	0.224	-4.51	-2.61	1377	34.4362610	-118.6452680	Valve Adjustment:NSPS/EG CAC
CV-2009A	10/1/2026 1:08:47 PM	26.7	72.0	0.0	1.3			0.4	0.0	155.9	155.9	0.20	0.18	4.8	4.7	0.153	0.150	-0.89	-1.07	1400	34.4359783	-118.6452544	Valve Adjustment:High Temp,Positive Static Press.;Well Condition:Lorentz Pump Installed
CV-2009A	10/1/2026 1:10:00 PM					1430																	AtmAA
CV-2009A	10/8/2026 10:27:00 AM					1400																	AtmAA
CV-2009A	10/8/2026 10:27:00 AM						88300																AtmAA; [User entered 8.83%]
CV-2009A	10/8/2026 10:29:30 AM	20.1	69.7	0.0	10.2			0.3	0.0	155.9	155.8	0.45	0.46	5.1	5.3	0.178	0.188	-0.02	-0.48	1393	34.4359750	-118.6452709	Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-2009A	10/12/2026 9:29:55 AM	39.8	57.0	0.0	3.2			0.7	0.0	125.8	125.8	-3.53	-3.51	16.6	16.8	1.797	1.838	-4.89	-1.38	1390	34.4359805	-118.6452727	Valve Adjustment:Audible Flow
CV-2009A	10/15/2026 1:43:38 PM	15.9	77.6	0.0	6.5			0.2	0.0	137.3	138.0	1.12	0.93	16.0	15.7	1.676	1.620	-0.35	-1.28	1397	34.4359773	-118.6452606	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Valve 100% Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-2009A	10/15/2026 1:44:31 PM	18.9	75.5	0.0	5.6			0.3	0.0	140.1	140.1	0.96	0.96	15.5	15.6	1.575	1.603	-0.34	-1.3	1393	34.4359731	-118.6452517	Valve Adjustment:Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-2010	10/7/2026 1:55:15 PM	39.9	51.2	0.0	8.9			0.8	0.0	108.8	108.9	-5.73	-5.35	0.0	16.3	-0.047	0.345	-5.46	-0.11	1365	34.4356557	-118.6435205	Reduced System Vacuum,
CV-2010	10/27/2026 9:18:52 AM	46.9	47.1	0.0	6.0			1.0	0.0	135.3	134.9	-18.26	-18.26	3.8	4.3	0.021	0.025	-20.13	-1.87	1342	34.4356400	-118.6435837	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2010	10/27/2026 9:22:29 AM	43.9	50.1	0.0	6.0			0.9	0.0	132.8	132.7	-15.50	-15.51	0.7	3.5	0.001	0.017	-20.43	-4.92	1346	34.4356433	-118.6435885	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-2010A	10/7/2026 1:45:33 PM	40.4	46.1	0.0	13.5			0.9	0.0	101.0	101.1	-5.23	-5.22	15.8	15.8	0.676	0.679	-5.71	-0.49	1365	34.4357785	-118.6436018	Reduced System Vacuum,
CV-2011	10/2/2026 1:35:35 PM	49.8	46.8	0.0	3.4			1.1	0.0	128.5	128.6	-3.85	-4.09	11.3	10.7	0.171	0.152	-15.45	-11.36	1344	34.4342072	-118.6434560	Valve Adjustment:Increased Flow/Vacuum
CV-2011A	10/1/2026 3:25:00 PM					1080																	AtmAA

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-2011A	10/1/2026 3:36:07 PM	36.8	50.2	0.1	12.9			0.7	129.0	152.4	152.4	-4.24	-4.25	64.3	60.9	1.157	1.037	-15.22	-10.97	1322	34.4345131	-118.6431851	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2011A	10/8/2026 2:15:00 PM						212300																AtmAA; [User entered 21.23%]
CV-2011A	10/8/2026 3:15:00 PM					1230																	AtmAA
CV-2011A	10/8/2026 3:16:07 PM	22.6	57.2	0.0	20.2			0.4	0.0	152.2	152.3	1.08	1.09	38.8	34.8	0.414	0.334	-2.62	-3.71	1333	34.4345334	-118.6431520	Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-2011A	10/9/2026 3:15:55 PM	27.6	53.5	0.6	18.3			0.5	30.5	153.0	152.8	-3.57	-3.57	73.1	79.4	1.499	1.771	-12.15	-8.58	1331	34.4345304	-118.6431785	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2011A	10/15/2026 12:00:36 PM	29.0	61.1	0.0	9.9			0.5	0.0	149.2	149.0	-5.78	-5.88	77.2	76.3	1.651	1.612	-14.46	-8.58	1339	34.4345523	-118.6431847	Valve Adjustment:Increased Flow/Vacuum
CV-2011A	10/15/2026 2:20:00 PM					950																	AtmAA
CV-2011A	10/15/2026 2:21:49 PM	30.6	0.0	0.3	69.1				230.3	150.7	150.7	-0.16	-0.14	48.2	48.2	0.638	0.635	-4.38	-4.24	1335	34.4345164	-118.6431640	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2011A	10/21/2026 7:38:06 AM	15.3	56.7	0.0	28.0			0.3	0.0	148.4	148.3	-0.98	-0.87	17.0	15.3	0.825	0.672	-4.90	-4.03	1350	34.4345180	-118.6431962	Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-2011A	10/21/2026 7:41:03 AM	14.8	57.7	0.0	27.5			0.3	0.0	148.5	148.3	-0.69	-0.71	15.1	19.0	0.656	1.038	-4.78	-4.07	1349	34.4345110	-118.6431857	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2011A	10/21/2026 7:56:00 AM					347																	AtmAA
CV-2011A	10/28/2026 10:13:00 AM					1360																	AtmAA
CV-2011A	10/28/2026 10:13:45 AM	28.3	52.5	0.0	19.1			0.5	0.0	150.9	150.8	-5.37	-5.15	22.9	24.3	1.524	1.708	-13.54	-8.39	1339	34.4345328	-118.6431708	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2012	10/28/2026 7:58:00 AM	46.1	47.5	0.0	6.4			1.0	0.0	125.7	125.7	-6.06	-6.08	6.4	6.2	0.055	0.052	-19.28	-13.2	1337	34.4350087	-118.6433150	
CV-2201-PL	10/12/2026 9:55:12 AM	3.1	77.8	0.3	18.8			0.0	62.7	122.7	122.5	-4.06	-4.17			3.944	4.059	-4.18	-0.01	1349	34.4355588	-118.6488377	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-2201-PL	10/19/2026 10:11:29 AM	3.2	77.9	0.2	18.7			0.0	93.5	129.8	129.8	-3.74	-3.63			3.654	3.552	-3.68	-0.05	1353	34.4355545	-118.6488307	Valve Adjustment:Barely Open
CV-2204-PL	10/5/2026 10:32:30 AM	29.3	68.6	0.0	2.1			0.4	0.0	186.0	122.2	-6.24	-5.39			6.812	5.900	-6.62	-1.23	1360	34.4357507	-118.6474848	Valve Adjustment:No Flow Measurement,High Temp
CV-2204-PL	10/5/2026 10:35:00 AM					1500																	AtmAA
CV-2204-PL	10/5/2026 10:35:00 AM						158900																AtmAA; [User entered 15.89%]
CV-2204-PL	10/12/2026 9:30:53 AM	20.9	62.7	0.0	16.4			0.3	0.0	188.0	85.1	-9.72	-9.34			10.081	9.714	-10.12	-0.78	1355	34.4357728	-118.6474637	Valve Adjustment:No Flow Measurement,High Temp
CV-2204-PL	10/12/2026 9:35:00 AM					1065																	AtmAA
CV-2204-PL	10/19/2026 1:29:48 PM	1.0	6.8	0.8	91.4			0.1	114.3	184.1	192.1	-1.71	-1.66			1.700	1.658	-4.64	-2.98	1339	34.4357665	-118.6474788	Valve Adjustment:No Flow Measurement,High Temp
CV-2204-PL	10/26/2026 9:38:08 AM	4.8	78.3	0.2	16.7			0.1	83.5	192.0	73.9	-5.87	-5.47			4.937	5.740	-5.85	-0.38	1367	34.4357645	-118.6474750	Valve Adjustment:No Flow Measurement,High Temp
CV-2204-PL	10/26/2026 9:45:00 AM					1040																	AtmAA
CV-2205	10/1/2026 3:20:00 PM					3130																	AtmAA
CV-2205	10/1/2026 3:22:01 PM	16.8	67.3	0.0	15.9			0.2	0.0	149.6	152.3	0.61	-4.43	33.2	14.5	0.298	0.058	-14.68	-10.25	1384	34.4342401	-118.6440823	Valve Adjustment:NSPS/EG CAC,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2205	10/1/2026 3:22:33 PM	16.9	68.7	0.0	14.4			0.2	0.0	152.5	152.5	-4.72	-4.72	9.3	11.3	0.024	0.035	-14.79	-10.07	1382	34.4342402	-118.6440817	
CV-2205	10/8/2026 3:00:58 PM	0.0	0.0	21.9	78.1				3.6	142.5	142.5	0.00	0.02	115.5	116.7	3.585	3.657	-6.19	-6.21	1383	34.4342398	-118.6440879	Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-2205	10/9/2026 2:26:07 PM	37.4	50.1	0.0	12.5			0.7	0.0	141.9	141.9	-9.38	-9.37	44.5	44.9	0.542	0.551	-17.06	-7.69	1367	34.4342666	-118.6441150	Valve Adjustment:High Temp
CV-2207	10/28/2026 9:16:37 AM	46.0	53.5	0.0	0.5			0.9	0.0	121.1	120.6	-2.15	-2.10	7.1	3.7	0.013	0.004	-15.84	-13.74	1380	34.4359750	-118.6442458	Valve Adjustment:Decreased Flow/Vacuum;Well Comment:valve stuck open
CV-2208A	10/1/2026 2:25:43 PM	34.2	64.0	0.0	1.8			0.5	0.0	157.1	157.1	-1.53	-1.53	13.5	12.1	0.051	0.041	-4.94	-3.41	1362	34.4365430	-118.6449451	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2208A	10/1/2026 2:30:00 PM					1050																	AtmAA
CV-2208A	10/8/2026 9:37:03 AM	15.0	70.7	0.0	14.3			0.2	0.0	154.8	155.0	0.71	0.71	45.3	45.7	0.567	0.576	-0.99	-1.7	1321	34.4365630	-118.6449713	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-2208A	10/8/2026 9:40:00 AM					1330																	AtmAA
CV-2208A	10/8/2026 9:40:00 AM						212400																AtmAA; [User entered 21.24%]
CV-2208A	10/9/2026 2:48:08 PM	12.8	60.8	0.1	26.3			0.2	263.0	147.4	146.8	-2.60	-2.60	23.1	23.2	0.148	0.148	-5.78	-3.18	1334	34.4365650	-118.6449620	Valve Adjustment:High Temp
CV-2208A	10/12/2026 1:41:53 PM	38.2	61.3	0.5	0.0			0.6	0.0	124.7	125.3	-6.74	-6.74	27.0	31.0	0.196	0.258	-7.92	-1.18	1330	34.4365416	-118.6449162	Well Condition:Lorentz Pump Installed
CV-2301	10/6/2026 6:45:00 AM					530																	Air Tech Lab
CV-2301	10/6/2026 6:45:00 AM						58000																Air Tech Lab; [User entered 5.8%]
CV-2301	10/8/2026 8:59:00 AM						40600																AtmAA; [User entered 4.06%]

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-2301	10/8/2026 8:59:48 AM	19.2	24.3	11.4	45.1			0.8	4.0	178.1	177.0	-7.38	-6.93			7.874	7.537	-7.67	-0.74	1339	34.4335322	-118.6492086	Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Open,Reduce Sys. Vac. - Flare Down
CV-2301	10/9/2026 8:59:00 AM					615																	AtmAA
CV-2301	10/14/2026 2:31:57 PM	3.1	0.6	20.7	75.6			5.2	3.7	168.0	157.2	-16.74	-3.13			17.063	3.125	-19.49	-16.36	1344	34.4335161	-118.6492138	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,High O2,Decreased Flow/Vacuum
CV-2301	10/14/2026 2:37:51 PM	22.1	49.8	6.0	22.1			0.4	3.7	158.7	158.4	-2.43	-2.38			2.423	2.383	-6.87	-4.49	1344	34.4335164	-118.6492196	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-2301	10/14/2026 2:50:00 PM					1900																	AtmAA
CV-2301	10/20/2026 10:21:00 AM					1380																	AtmAA
CV-2301	10/20/2026 10:21:58 AM	1.0	81.4	0.0	17.6			0.0	0.0	173.4	175.0	1.66	-3.46			0.000	3.410	-6.68	-3.22	1359	34.4335005	-118.6492372	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,Positive Static Press.,Increased Flow/Vacuum
CV-2301	10/20/2026 10:22:29 AM	1.0	83.3	0.0	15.7			0.0	0.0	174.9	174.4	-3.47	-3.37			3.405	3.330	-5.10	-1.73	1350	34.4335027	-118.6492465	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-2301	10/28/2026 10:20:00 AM					817																	AtmAA
CV-2301	10/28/2026 10:34:33 AM	15.3	15.6	14.5	54.6			1.0	3.8	174.2	171.0	-7.08	-4.30			7.256	4.287	-15.87	-11.57	1350	34.4335077	-118.6492471	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2301	10/28/2026 10:44:22 AM	20.9	35.6	8.6	34.9			0.6	4.1	171.0	168.4	-1.80	-1.79			1.796	1.784	-16.70	-14.91	1349	34.4335101	-118.6492470	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Decreased Flow/Vacuum
CV-2301	10/28/2026 10:53:27 AM	14.9	56.2	4.4	24.5			0.3	5.6	166.6	167.3	-1.14	-0.97			1.129	1.046	-16.35	-15.38	1350	34.4335130	-118.6492439	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
CV-2302	10/5/2026 1:40:12 PM	43.5	47.2	0.7	8.6			0.9	12.3	130.1	130.3	-9.11	-9.11			9.261	9.315	0.00	9.11	1362	34.4339972	-118.6492128	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-2302	10/6/2026 6:50:00 AM					200																	Air Tech Lab
CV-2302	10/6/2026 6:50:00 AM						38000																Air Tech Lab; [User entered 3.8%]
CV-2302	10/20/2026 10:18:40 AM	37.6	48.2	1.5	12.7			0.8	8.5	128.2	129.5	-13.36	-13.84			13.622	14.099	0.34	14.18	1355	34.4340363	-118.6492000	Valve Comment:Valve stuck open;Valve Adjustment:Valve 100% Open
CV-2303	10/1/2026 2:05:00 PM					2170																	AtmAA
CV-2303	10/1/2026 2:06:56 PM	8.5	73.0	0.8	17.7			0.1	22.1	194.0	193.7	0.13	0.20			0.000	0.000	-0.73	-0.93	1363	34.4353755	-118.6496889	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.;Well Condition:Lorentz Pump Installed
CV-2303	10/1/2026 2:08:57 PM	7.5	78.8	0.0	13.7			0.1	0.0	193.6	193.5	2.64	2.63			0.000	0.000	-0.88	-3.51	1363	34.4353762	-118.6496904	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.;Well Condition:Lorentz Pump Installed
CV-2303	10/6/2026 7:00:00 AM					1700																	Air Tech Lab
CV-2303	10/6/2026 7:00:00 AM						180000																Air Tech Lab; [User entered 18%]
CV-2303	10/6/2026 8:44:21 AM	5.7	73.0	0.0	21.3			0.1	0.0	191.3	191.5	-4.71	-4.63			4.687	4.955	-6.15	-1.52	1358	34.4353561	-118.6496917	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2303	10/6/2026 8:45:00 AM					2230																	AtmAA
CV-2303	10/6/2026 8:45:00 AM						180700																AtmAA; [User entered 18.07%]
CV-2303	10/13/2026 9:39:42 AM	7.8	48.8	0.0	43.4			0.2	0.0	194.9	194.2	1.44	-3.17			0.000	3.132	-4.71	-1.54	1348	34.4353741	-118.6496725	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2303	10/13/2026 9:40:00 AM					2940																	AtmAA
CV-2303	10/13/2026 9:41:09 AM	7.5	72.6	0.0	19.9			0.1	0.0	194.1	194.3	-3.55	-3.46			3.479	3.415	-4.51	-1.05	1350	34.4353792	-118.6496793	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2303	10/20/2026 9:12:16 AM	1.5	70.9	0.3	27.3			0.0	91.0	162.7	163.4	-6.47	-6.40			6.599	6.584	-6.59	-0.19	1361	34.4353637	-118.6496977	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2303	10/20/2026 9:15:00 AM					694																	AtmAA
CV-2303	10/27/2026 9:39:12 AM	4.1	85.3	0.0	10.6			0.0	0.0	190.1	190.1	-4.20	-4.05			4.236	4.033	-2.17	1.88	1354	34.4353652	-118.6496897	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2303	10/27/2026 9:45:00 AM					1880																	AtmAA
CV-2304-PL	10/2/2026 8:54:44 AM	1.7	74.1	0.0	24.3			0.0	0.0	172.3	172.5	-10.47	-10.41			0.027	0.000	-10.67	-0.26	1344	34.4345565	-118.6487427	Valve Adjustment:NSPS/EG CAI,High Temp,Surging Liquid in Well (Watered In)
CV-2304-PL	10/6/2026 9:55:00 AM					1920																	AtmAA
CV-2304-PL	10/6/2026 9:55:00 AM						182600																AtmAA; [User entered 18.26%]

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-2304-PL	10/6/2026 9:55:56 AM	6.9	63.9	0.0	29.2			0.1	0.0	177.1	177.3	-9.44	-9.39			10.014	9.850	-9.60	-0.21	1345	34.4345468	-118.6487563	Valve Adjustment:No Flow Measurement,High Temp
CV-2304-PL	10/13/2026 10:20:00 AM					2090																	AtmAA
CV-2304-PL	10/13/2026 10:25:01 AM	10.4	70.1	0.1	19.4			0.1	194.0	171.5	171.8	-12.24	-12.13			12.965	12.762	-13.12	-0.99	1344	34.4345807	-118.6487895	Valve Adjustment:No Flow Measurement,High Temp
CV-2304-PL	10/16/2026 2:27:02 PM	2.3	84.6	0.0	13.1			0.0	0.0	161.0	160.9	-11.47	-11.51			11.558	11.404	-0.04	11.47	1340	34.4345550	-118.6487268	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-2304-PL	10/20/2026 9:50:00 AM					1930																	AtmAA
CV-2304-PL	10/20/2026 9:52:32 AM	3.1	77.2	0.0	19.7			0.0	0.0	171.9	171.9	-5.04	-4.89			0.168	0.067	-4.78	0.11	1344	34.4345455	-118.6487437	Valve Adjustment:No Flow Measurement,High Temp
CV-2304-PL	10/28/2026 7:51:00 AM					2200																	AtmAA
CV-2304-PL	10/28/2026 7:51:44 AM	2.5	85.7	0.3	11.5			0.0	38.3	167.8	168.2	-10.71	-10.58			10.796	10.741	-11.02	-0.44	1335	34.4345607	-118.6487458	Valve Adjustment:No Flow Measurement,High Temp
CV-2305	10/7/2026 6:50:00 AM					1200																	Air Tech Lab
CV-2305	10/7/2026 6:50:00 AM						48000																Air Tech Lab; [User entered 4.8%]
CV-2305	10/7/2026 10:00:10 AM	21.2	78.7	0.1	0.0			0.3	0.0	161.8	161.7	-3.58	-3.54			0.072	0.044	-5.15	-1.61	1382	34.4352220	-118.6465280	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	10/7/2026 10:10:00 AM					2040																	AtmAA
CV-2305	10/7/2026 10:10:00 AM						52900																AtmAA; [User entered 5.29%]
CV-2305	10/14/2026 10:00:00 AM					1610																	AtmAA
CV-2305	10/14/2026 10:00:14 AM	0.0	0.0	0.0	100.0				0.0	160.4	160.3	-7.75	-7.75			0.697	0.588	-11.41	-3.66	1379	34.4352547	-118.6465750	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	10/15/2026 2:25:00 PM					1900																	AtmAA
CV-2305	10/19/2026 2:24:51 PM	39.4	55.7	0.0	4.9			0.7	0.0	164.6	164.7	-5.06	-5.05			0.457	0.458	-7.89	-2.84	1385	34.4352206	-118.6465402	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2305	10/19/2026 2:25:00 PM					1900																	AtmAA
CV-2305	10/26/2026 1:42:00 PM					1790																	AtmAA
CV-2305	10/26/2026 1:42:55 PM	33.6	51.7	0.0	14.7			0.6	0.0	164.2	164.2	-5.05	-5.05			0.248	0.245	-7.44	-2.39	1387	34.4352147	-118.6465097	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2306-PL	10/9/2026 2:58:09 PM	20.5	70.6	0.2	8.7			0.3	43.5	152.9	153.0	-1.58	-1.58			0.000	0.000	-2.74	-1.16	1381	34.4359712	-118.6452498	Valve Adjustment:NSPS/EG CAI,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2306-PL	10/12/2026 9:21:57 AM	11.8	74.6	0.6	13.0			0.2	21.7	179.0	64.7	-11.42	-10.99			11.834	11.356	-11.83	-0.84	1338	34.4360799	-118.6478273	Valve Adjustment:No Flow Measurement,High Temp
CV-2306-PL	10/12/2026 9:25:00 AM					1170																	AtmAA
CV-2306-PL	10/19/2026 1:14:17 PM	17.0	79.8	0.0	3.2			0.2	0.0	160.6	160.8	-0.25	-0.51			0.343	0.413	0.12	0.63	1361	34.4360843	-118.6478370	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Barely Open,Surging Liquid in Header;Well Comment:no system sample port installed
CV-2306-PL	10/26/2026 9:27:46 AM	3.0	76.7	0.0	20.3			0.0	0.0	181.1	182.3	-7.31	-7.15			7.557	7.397	-7.08	0.07	1354	34.4360833	-118.6478073	Valve Adjustment:No Flow Measurement,High Temp
CV-2306-PL	10/26/2026 9:40:00 AM					1200																	AtmAA
CV-2308-PL	10/12/2026 9:59:27 AM	3.0	77.0	0.4	19.6			0.0	49.0	105.5	104.1	-11.96	-11.74			11.839	11.701	-12.24	-0.5	1362	34.4358808	-118.6489167	Valve Adjustment:Barely Open
CV-2308-PL	10/19/2026 10:07:15 AM	3.3	77.5	0.5	18.7			0.0	37.4	120.5	121.8	-9.87	-9.87			9.932	9.946	-10.78	-0.91	1356	34.4358812	-118.6489032	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In)
CV-2310-PL	10/6/2026 9:01:50 AM	8.2	76.1	0.0	15.7			0.1	0.0	198.0	131.6	-6.47	-6.40			6.850	6.685	-7.12	-0.72	1350	34.4353270	-118.6491490	Valve Adjustment:No Flow Measurement,High Temp
CV-2310-PL	10/6/2026 9:05:00 AM					1840																	AtmAA
CV-2310-PL	10/6/2026 9:05:00 AM						166700																AtmAA; [User entered 16.67%]
CV-2310-PL	10/13/2026 9:48:45 AM	8.8	74.3	0.1	16.8			0.1	168.0	195.0	105.0	-11.13	-10.78			11.875	11.519	-12.51	-1.73	1352	34.4353264	-118.6491417	Valve Adjustment:No Flow Measurement,High Temp
CV-2310-PL	10/13/2026 9:50:00 AM					1210																	AtmAA
CV-2310-PL	10/20/2026 8:55:15 AM	1.9	84.1	0.1	13.9			0.0	139.0	194.0	67.5	-10.37	-10.28			10.586	10.481	-9.01	1.27	1364	34.4353198	-118.6491393	Valve Adjustment:No Flow Measurement,High Temp
CV-2310-PL	10/20/2026 9:03:00 AM					1460																	AtmAA
CV-2310-PL	10/27/2026 9:30:00 AM					1390																	AtmAA
CV-2310-PL	10/27/2026 9:30:14 AM	5.2	84.2	0.2	10.4			0.1	52.0	193.0	61.2	-10.18	-10.03			10.244	9.841	-10.02	0.01	1358	34.4353197	-118.6491362	Valve Adjustment:No Flow Measurement,High Temp
CV-2311	10/4/2026 2:50:00 PM						115250																AtmAA; [User entered 11.525%]
CV-2311	10/5/2026 2:47:20 PM	22.7	69.4	0.1	7.8			0.3	78.0	171.8	172.4	-4.11	-4.07			4.092	4.087	-7.60	-3.53	1374	34.4363029	-118.6498600	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2311	10/5/2026 2:50:00 PM					1050																	AtmAA
CV-2311	10/5/2026 2:50:00 PM						115250																AtmAA; [User entered 11.525%]
CV-2311	10/13/2026 8:10:00 AM					1630																	AtmAA

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-2311	10/13/2026 8:27:30 AM	24.1	44.6	5.3	26.0			0.5	4.9	153.0	158.5	-7.14	-2.12			7.405	2.124	-14.43	-12.31	1363	34.4363182	-118.6499245	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,High O2,Barely Open;Well Condition:Lorentz Pump Installed
CV-2311	10/13/2026 8:43:22 AM	8.2	61.6	3.3	26.9			0.1	8.2	163.1	162.5	-0.41	-0.41			0.409	0.423	-14.78	-14.37	1366	34.4363281	-118.6499057	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2311	10/20/2026 8:04:54 AM	10.7	66.8	0.2	22.3			0.2	111.5	145.6	144.5	-5.04	-5.04			4.932	4.932	-11.91	-6.87	1372	34.4362927	-118.6499013	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2311	10/20/2026 8:10:00 AM					1030																	AtmAA
CV-2311	10/27/2026 7:29:00 AM					1550																	AtmAA
CV-2311	10/27/2026 7:31:48 AM	40.7	50.4	0.2	3.7		5	0.8	18.5	134.2	134.8	-11.35	-11.11			11.251	11.186	-4.53	6.58	1368	34.4363073	-118.6498915	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2312-PL	10/7/2026 7:10:00 AM					2600																	Air Tech Lab
CV-2312-PL	10/7/2026 7:10:00 AM						150000																Air Tech Lab; [User entered 15%]
CV-2312-PL	10/7/2026 12:50:00 PM					2840																	AtmAA
CV-2312-PL	10/7/2026 12:50:00 PM						122600																AtmAA; [User entered 12.26%]
CV-2312-PL	10/7/2026 1:07:45 PM	8.3	79.1	0.1	12.5			0.1	125.0	170.5	170.4	-1.68	-1.38	23.2	21.0	1.605	1.313	-2.39	-1.01	1392	34.4342181	-118.6473752	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PL	10/14/2026 2:20:00 AM					3620																	AtmAA
CV-2312-PL	10/14/2026 1:46:53 PM	49.4	50.4	0.2	0.0			1.0	0.0	169.8	169.9	-21.10	-19.88	81.4	79.3	21.308	20.145	-8.45	11.43	1367	34.4342048	-118.6473710	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PL	10/21/2026 7:40:00 AM					3440																	AtmAA
CV-2312-PL	10/21/2026 7:44:02 AM	1.4	82.6	0.0	16.0			0.0	0.0	169.9	169.8	-2.82	-2.58	31.1	29.5	2.910	2.616	-3.92	-1.34	1368	34.4342236	-118.6473616	Valve Adjustment:No Flow Measurement,High Temp
CV-2312-PL	10/28/2026 9:25:00 AM					2385																	AtmAA
CV-2312-PL	10/28/2026 9:36:36 AM	4.0	0.0	0.0	96.0				0.0	169.7	169.7	-2.84	-2.78	28.8	30.4	2.466	2.754	-5.73	-2.95	1382	34.4342164	-118.6473681	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PL	10/1/2026 12:43:36 PM	6.9	81.9	0.1	11.1			0.1	111.0	185.9	185.8	-6.54	-6.07			6.792	6.249	-6.53	-0.46	1426	34.4346924	-118.6466941	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PL	10/1/2026 12:45:00 PM					2630																	AtmAA
CV-2314-PL	10/7/2026 1:10:00 PM					3640																	AtmAA
CV-2314-PL	10/7/2026 1:10:00 PM						111100																AtmAA; [User entered 11.11%]
CV-2314-PL	10/7/2026 1:14:53 PM	7.9	80.8	0.0	11.3			0.1	0.0	186.1	186.1	-4.97	-4.59			4.845	4.504	-4.91	-0.32	1391	34.4347083	-118.6467203	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PL	10/13/2026 8:10:00 AM					2700																	AirTech Lab
CV-2314-PL	10/13/2026 8:10:00 AM						130000																AirTech Lab; [User entered 13%]
CV-2314-PL	10/14/2026 10:43:05 AM	10.7	77.0	0.6	11.7			0.1	19.5	185.1	185.2	-12.03	-11.79			12.599	12.200	-12.29	-0.5	1378	34.4346860	-118.6467076	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PL	10/14/2026 10:45:00 AM					4850																	AtmAA
CV-2314-PL	10/20/2026 1:18:21 PM	1.0	84.5	0.3	14.2			0.0	47.3	184.9	185.0	-8.47	-8.42			8.781	8.798	-8.96	-0.54	1382	34.4346781	-118.6467092	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PL	10/20/2026 1:25:00 PM					4230																	AtmAA
CV-2314-PL	10/27/2026 9:46:52 AM	3.6	79.7	0.0	16.7			0.0	0.0	184.6	184.6	-7.29	-7.16			7.921	7.846	-12.55	-5.39	1363	34.4346988	-118.6467082	Valve Adjustment:No Flow Measurement,High Temp
CV-2314-PL	10/27/2026 9:50:00 AM					2750																	AtmAA
CV-2315	10/5/2026 10:37:05 AM	27.9	63.7	0.0	8.4			0.4	0.0	181.6	181.8	-3.79	-3.59			3.771	3.381	-3.97	-0.38	1380	34.4355043	-118.6471937	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	10/5/2026 10:40:00 AM					1660																	AtmAA
CV-2315	10/5/2026 10:40:00 AM						114600																AtmAA; [User entered 11.46%]
CV-2315	10/7/2026 7:35:00 AM					1900																	Air Tech Lab
CV-2315	10/7/2026 7:35:00 AM						160000																Air Tech Lab; [User entered 16%]
CV-2315	10/12/2026 9:36:43 AM	20.3	67.7	0.1	11.9			0.3	119.0	187.8	187.7	-6.84	-6.40			7.164	6.748	-7.89	-1.49	1373	34.4355208	-118.6472041	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	10/12/2026 9:40:00 AM					1610																	AtmAA
CV-2315	10/19/2026 1:40:32 PM	7.4	75.3	1.1	16.2			0.1	14.7	182.9	188.9	-0.35	-0.33			0.253	0.287	-5.84	-5.51	1399	34.4355100	-118.6471957	Valve Adjustment:No Flow Measurement,High Temp,Barely Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-2315	10/26/2026 9:49:22 AM	3.7	75.2	0.4	20.7			0.0	51.8	167.2	165.3	-4.57	-4.29			4.131	4.704	0.00	4.29	1393	34.4355050	-118.6471943	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2315	10/26/2026 9:55:00 AM					2780																	AtmAA
CV-2315	10/28/2026 1:23:00 PM					2680																	AtmAA

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-2315	10/28/2026 1:29:59 PM	12.1	78.0	0.0	9.9			0.2	0.0	181.5	181.6	-1.00	-0.88			0.970	0.858	-8.69	-7.81	1383	34.4354981	-118.6471915	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2316	10/1/2026 12:50:00 PM					2910																	AtmAA
CV-2316	10/1/2026 12:51:51 PM	15.6	76.8	0.0	7.6			0.2	0.0	152.0	152.1	0.22	0.21	19.0	19.1	0.244	0.245	-0.03	-0.24	1402	34.4360001	-118.6463641	Valve Adjustment:High Temp,Positive Static Press.;Well Condition:Lorentz Pump Installed
CV-2316	10/8/2026 10:16:00 AM					3450																	AtmAA
CV-2316	10/8/2026 10:16:00 AM						126600																AtmAA; [User entered 12.66%]
CV-2316	10/8/2026 10:18:06 AM	14.9	75.3	0.0	9.8			0.2	0.0	152.7	152.8	0.36	0.37	23.3	23.5	0.367	0.372	0.23	-0.14	1378	34.4360331	-118.6463725	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-2316	10/9/2026 2:55:26 PM	25.5	60.4	0.0	14.1			0.4	0.0	151.0	151.0	-1.34	-1.23	44.4	42.3	1.337	1.213	-1.95	-0.72	1399	34.4360364	-118.6463871	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2316	10/15/2026 10:10:00 AM					2530																	AtmAA
CV-2316	10/15/2026 10:29:41 AM	2.8	3.2	19.8	74.2			0.9	3.7	150.1	149.9	-2.39	-2.61	57.5	59.6	2.220	2.391	-3.01	-0.4	1398	34.4360349	-118.6463942	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Increased Flow/Vacuum,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2316	10/15/2026 10:36:21 AM	26.1	66.8	0.6	6.5			0.4	10.8	149.6	149.6	-2.14	-2.10	54.5	54.5	1.990	1.992	-2.26	-0.16	1399	34.4360340	-118.6463926	Valve Adjustment:NSPS/EG CAC,High Temp;Well Condition:Lorentz Pump Installed
CV-2316	10/21/2026 7:28:00 AM					874																	AtmAA
CV-2316	10/21/2026 7:28:37 AM	21.9	66.4	0.2	11.5			0.3	57.5	146.9	146.9	-2.37	-2.30			2.318	2.282	-1.67	0.63	1404	34.4360218	-118.6463982	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2319	10/7/2026 10:06:35 AM	27.0	66.8	0.0	6.2			0.4	0.0	181.8	181.8	1.44	1.43			0.000	0.000	-4.57	-6	1395	34.4353185	-118.6458024	Valve Adjustment:High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-2319	10/7/2026 10:35:00 AM					4740																	AtmAA
CV-2319	10/7/2026 10:35:00 AM						100900																AtmAA; [User entered 10.09%]
CV-2319	10/15/2026 8:30:00 AM					3370																	AtmAA
CV-2319	10/15/2026 8:32:16 AM	30.9	68.5	0.4	0.2			0.5	0.5	177.1	177.3	-5.37	-5.05			5.821	5.569	-10.64	-5.59	1390	34.4352942	-118.6457968	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2319	10/19/2026 2:34:50 PM	29.8	70.2	0.0	0.0			0.4	0.0	178.6	179.9	-4.23	-4.00			4.075	3.853	-8.04	-4.04	1389	34.4352891	-118.6458091	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2319	10/26/2026 1:49:54 PM	34.3	52.2	0.0	13.5			0.7	0.0	186.2	186.4	-9.79	-9.44			10.074	9.760	-11.52	-2.08	1406	34.4352978	-118.6457914	Valve Adjustment:High Temp
CV-2319	10/26/2026 1:52:00 PM					5340																	AtmAA
CV-2321	10/7/2026 8:30:00 AM					2880																	AtmAA
CV-2321	10/7/2026 8:30:00 AM						59500																AtmAA; [User entered 5.95%]
CV-2321	10/7/2026 8:55:42 AM	30.7	66.8	0.7	1.8			0.5	2.6	144.5	144.5	-4.07	-3.91			0.133	0.236	-11.01	-7.1	1386	34.4346615	-118.6453595	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2321	10/23/2026 12:49:29 PM	21.5	68.3	0.4	9.8			0.3	24.5	143.9	144.0	-4.79	-4.81	4.4	4.2	0.057	0.051	-12.22	-7.41	1398	34.4346375	-118.6453655	
CV-2322	10/14/2026 10:13:17 AM	18.0	62.7	0.1	19.2			0.3	192.0	98.8	99.4	-11.95	-11.78			11.961	11.817	-11.67	0.11	1375	34.4352762	-118.6475300	Valve Adjustment:Decreased Flow/Vacuum
CV-2322	10/28/2026 1:51:57 PM	3.3	78.0	0.7	18.0			0.0	25.7	125.4	125.9	-11.50	-11.70			11.438	11.570	-11.52	0.18	1375	34.4352513	-118.6475243	Valve Comment:Hard pipped
CV-2324	10/27/2026 10:25:50 AM	49.8	43.0	0.1	7.1			1.2	71.0	119.9	120.1	-1.65	-1.64	14.1	13.8	0.128	0.122	-14.22	-12.58	1366	34.4345013	-118.6442482	
CV-2326	10/6/2026 10:20:00 AM					3330																	AtmAA
CV-2326	10/6/2026 10:20:00 AM						168000																AtmAA; [User entered 16.8%]
CV-2326	10/6/2026 10:21:44 AM	14.5	71.2	0.0	14.3			0.2	0.0	183.6	183.5	-8.76	-8.53			9.349	9.143	-9.12	-0.59	1366	34.4361253	-118.6504630	Valve Adjustment:No Flow Measurement,High Temp
CV-2326	10/13/2026 8:50:00 AM					2340																	AtmAA
CV-2326	10/13/2026 8:51:37 AM	19.4	68.3	0.5	11.8			0.3	23.6	181.8	181.7	-11.12	-11.08			11.583	11.383	-13.94	-2.86	1360	34.4361211	-118.6504453	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2326	10/20/2026 8:19:12 AM	16.8	64.4	0.0	18.8			0.3	0.0	170.5	170.5	-11.18	-11.13			11.135	11.065	-11.20	-0.07	1364	34.4360953	-118.6504412	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2326	10/20/2026 8:27:00 AM					2730																	AtmAA
CV-2326	10/27/2026 7:35:00 AM					2290																	AtmAA
CV-2326	10/27/2026 7:35:28 AM	18.2	63.4	0.1	5.2		13.1	0.3	52.0	182.2	182.2	-10.53	-10.43			10.510	10.365	-10.51	-0.08	1377	34.4361160	-118.6504487	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2327	10/14/2026 10:15:08 AM	1.4	86.5	0.0	12.1			0.0	0.0	187.3	187.7	-6.40	-6.20			6.912	6.702	-10.39	-4.19	1358	34.4348855	-118.6479172	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Comment:hard pipped

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-2327	10/14/2026 10:17:15 AM	1.2	87.1	0.0	11.7			0.0	0.0	187.5	187.7	-6.39	-6.38			6.817	6.842	-10.50	-4.12	1361	34.4348778	-118.6478978	Valve Adjustment:High Temp,Barely Open
CV-2327	10/20/2026 8:14:16 AM	1.7	82.3	0.0	16.0			0.0	0.0	168.3	168.7	-5.71	-5.39			5.778	5.415	-10.86	-5.47				Valve Adjustment:No Flow Measurement,High Temp
CV-2327	10/20/2026 8:15:00 AM					2920																	AtmAA
CV-2327	10/27/2026 1:20:00 PM					1015																	AtmAA
CV-2327	10/27/2026 1:21:08 PM	8.8	82.0	0.0	9.2			0.1	0.0	170.9	171.1	-6.26	-6.07			6.363	6.077	-11.37	-5.3	1349	34.4348757	-118.6479237	Valve Adjustment:No Flow Measurement,High Temp
CV-2328	10/7/2026 1:54:08 PM	20.6	79.4	0.0	0.0			0.3	0.0	182.2	182.2	5.62	5.60	47.0	46.9	5.672	5.660	-5.79	-11.39	1355	34.4343377	-118.6483650	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-2328	10/7/2026 1:55:00 PM					2540																	AtmAA
CV-2328	10/7/2026 1:55:00 PM						107000																AtmAA; [User entered 10.7%]
CV-2328	10/13/2026 7:10:00 AM					1500																	AirTech Lab
CV-2328	10/13/2026 7:10:00 AM						120000																AirTech Lab; [User entered 12%]
CV-2328	10/14/2026 2:00:00 AM					1920																	AtmAA
CV-2328	10/14/2026 1:59:51 PM	30.6	69.4	0.0	0.0			0.4	0.0	177.0	117.3	-9.79	-9.35	61.5	62.9	10.026	9.509	-9.82	-0.47	1354	34.4342994	-118.6483576	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2328	10/21/2026 7:27:22 AM	12.6	79.1	0.0	8.3			0.2	0.0	177.0	72.9	-3.50	-3.45	36.8	39.9	3.529	3.465	-4.64	-1.19	1363	34.4343083	-118.6483360	Valve Adjustment:No Flow Measurement,High O2;Well Condition:Lorentz Pump Installed
CV-2328	10/21/2026 7:30:00 AM					1850																	AtmAA
CV-2328	10/27/2026 1:45:00 PM					1030																	AtmAA
CV-2328	10/27/2026 1:45:18 PM	22.2	74.1	0.0	3.7			0.3	0.0	175.0	77.5	-8.26	-8.09	56.7	61.0	8.472	8.317	-8.34	-0.25	1347	34.4343054	-118.6483361	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2333	10/5/2026 9:05:55 AM	2.1	69.9	0.1	27.9			0.0	279.0	189.5	189.5	-8.42	-8.09			8.789	8.407	-9.60	-1.51	1347	34.4365228	-118.6473614	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	10/5/2026 9:10:00 AM					3940																	AtmAA
CV-2333	10/5/2026 9:10:00 AM						188100																AtmAA; [User entered 18.81%]
CV-2333	10/6/2026 7:20:00 AM					2900																	Air Tech Lab
CV-2333	10/6/2026 7:20:00 AM						180000																Air Tech Lab; [User entered 18%]
CV-2333	10/12/2026 8:16:31 AM	1.4	75.5	0.1	23.0			0.0	230.0	189.9	189.9	-8.38	-8.37			8.403	8.378	-10.13	-1.76	1355	34.4365159	-118.6473711	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	10/12/2026 8:20:00 AM					4480																	AtmAA
CV-2333	10/19/2026 7:47:41 AM	1.2	80.3	0.8	17.7			0.0	22.1	189.4	189.5	-9.54	-9.32			9.409	9.237	-9.63	-0.31	1364	34.4365182	-118.6473652	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	10/26/2026 7:31:30 AM	0.5	67.5	0.5	31.5			0.0	63.0	190.2	190.2	-8.67	-8.42	52.9	52.4	8.793	8.610	-8.60	-0.18	1364	34.4365258	-118.6473663	Valve Adjustment:No Flow Measurement,High Temp
CV-2333	10/26/2026 7:35:00 AM					3385																	AtmAA
CV-2334	10/1/2026 2:15:00 PM					3170																	AtmAA
CV-2334	10/1/2026 2:17:12 PM	9.9	77.6	0.0	12.5			0.1	0.0	163.0	163.1	0.42	0.42	48.6	47.5	6.975	6.676	-5.59	-6.01	1357	34.4366637	-118.6467074	Valve Adjustment:High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-2334	10/6/2026 7:30:00 AM					3000																	Air Tech Lab
CV-2334	10/6/2026 7:30:00 AM						170000																Air Tech Lab; [User entered 17%]
CV-2334	10/8/2026 9:22:00 AM					2755																	AtmAA
CV-2334	10/8/2026 9:22:00 AM						118400																AtmAA; [User entered 11.84%]
CV-2334	10/8/2026 9:23:57 AM	8.3	75.4	0.0	16.3			0.1	0.0	167.5	167.6	1.78	1.79	48.0	48.2	6.818	6.880	-3.64	-5.43	1335	34.4366783	-118.6466932	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2334	10/9/2026 2:33:11 PM	5.0	79.2	0.3	15.5			0.1	51.7	167.4	166.9	-5.77	-5.76	2.1	1.8	0.013	0.010	-6.94	-1.18	1360	34.4366908	-118.6467072	Valve Comment:orifice plate insert is shot;Valve Adjustment:NSPS/EG CAC
CV-2334	10/15/2026 2:10:00 PM					116																	AtmAA
CV-2334	10/15/2026 2:13:15 PM	9.5	75.8	0.1	14.6			0.1	146.0	167.2	167.1	-3.11	-2.90	6.2	1.8	0.112	0.009	-3.89	-0.99	1373	34.4366719	-118.6467114	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2334	10/20/2026 1:16:00 PM					3650																	AtmAA
CV-2334	10/20/2026 1:18:18 PM	10.5	69.7	0.1	19.7			0.2	197.0	174.0	174.0	-3.80	-3.80	30.1	30.4	2.728	2.778	-7.38	-3.58	1378	34.4366895	-118.6466878	Valve Adjustment:High Temp
CV-2334	10/26/2026 10:25:00 AM					4230																	AtmAA
CV-2334	10/26/2026 10:30:53 AM	6.4	70.1	0.3	23.2			0.1	77.3	174.4	174.4	-7.16	-7.07	32.9	26.5	0.763	0.494	-3.42	3.65	1359	34.4366605	-118.6466982	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2335	10/12/2026 1:42:28 PM	58.2	41.8	0.0	0.0			1.4	0.0	84.7	88.5	-1.84	-3.17			1.812	3.105	-9.81	-6.64	1342	34.4363720	-118.6509800	Valve Adjustment:Increased Flow/Vacuum

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-2335	10/16/2026 11:13:19 AM	51.6	43.9	0.4	4.1			1.2	10.3	99.2	100.1	-2.82	-2.88			2.802	2.902	-6.34	-3.46	1344	34.4363773	-118.6509698	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2336	10/12/2026 1:35:29 PM	22.5	39.4	9.1	29.0			0.6	3.2	67.6	67.6	-11.71	-11.78			11.792	11.817	-11.76	0.02	1342	34.4359815	-118.6508910	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Comment:Pump not working;Well Condition:Pnumatic Pump Installed
CV-2336	10/12/2026 1:36:24 PM	21.5	37.6	9.3	31.6			0.6	3.4	67.6	67.6	-11.63	-11.61			11.628	11.552	-11.68	-0.07	1342	34.4359937	-118.6508828	
CV-2336	10/29/2026 9:46:44 AM	13.7	77.3	0.2	8.8			0.2	44.0	65.8	65.9	-1.29	-1.39			1.283	1.388	-12.12	-10.73	1338	34.4359770	-118.6508580	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-2337	10/8/2026 8:10:00 AM					3700																	Air Tech Lab
CV-2337	10/8/2026 8:10:00 AM						170000																Air Tech Lab; [User entered 17%]
CV-2337	10/12/2026 1:06:18 PM	8.7	78.5	0.0	12.8			0.1	0.0	152.7	153.2	-9.05	-3.37	24.3	23.3	1.743	1.570	-12.12	-8.75	1332	34.4354448	-118.6507618	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2337	10/12/2026 1:07:36 PM	7.9	79.2	0.0	12.9			0.1	0.0	153.3	153.3	-3.65	-3.57	23.3	23.2	1.576	1.566	-12.22	-8.65	1347	34.4354423	-118.6507533	
CV-2337	10/12/2026 2:40:00 PM					2690																	AtmAA
CV-2337	10/19/2026 8:50:56 AM	10.2	0.0	0.0	89.8				0.0	153.8	154.0	0.16	-3.26	22.1	19.7	1.406	1.129	-9.88	-6.62	1324	34.4354524	-118.6507670	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2337	10/19/2026 8:52:22 AM	11.7	0.0	0.0	88.3				0.0	154.0	154.0	-3.45	-3.44	18.9	19.2	1.030	1.072	-9.67	-6.23	1324	34.4354525	-118.6507673	Valve Adjustment:NSPS/EG CAC,High Temp;Well Condition:Lorentz Pump Installed
CV-2337	10/26/2026 10:02:00 AM					4270																	AtmAA
CV-2337	10/26/2026 10:10:07 AM	14.6	73.3	0.0	12.1			0.2	0.0	153.9	153.9	-1.89	-1.87	24.1	24.3	1.671	1.692	-7.84	-5.97	1336	34.4354587	-118.6507805	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2338	10/6/2026 1:30:00 PM					544																	AtmAA
CV-2338	10/6/2026 1:30:00 PM						170850																AtmAA; [User entered 17.085%]
CV-2338	10/6/2026 1:30:15 PM	23.5	69.1	1.2	6.2			0.3	5.2	181.8	182.5	-5.69	-5.52			5.714	5.515	-5.94	-0.42	1308	34.4348524	-118.6504625	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2338	10/12/2026 2:20:06 PM	9.4	72.7	2.6	15.3			0.1	5.9	182.4	183.5	-8.98	-8.40			9.170	8.629	-8.78	-0.38	1308	34.4348392	-118.6504742	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2338	10/12/2026 2:22:00 PM					791																	AtmAA
CV-2338	10/19/2026 8:35:13 AM	10.2	0.0	4.1	85.7				20.9	166.7	166.7	-6.67	-6.65			6.995	6.985	-8.01	-1.36	1310	34.4348776	-118.6504713	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2338	10/26/2026 10:17:35 AM	12.3	74.4	0.0	13.3			0.2	0.0	189.0	189.4	-5.48	-5.43			6.085	6.095	-5.82	-0.39	1317	34.4348429	-118.6504854	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2338	10/26/2026 10:20:00 AM					1760																	AtmAA
CV-2339	10/14/2026 8:32:38 AM	0.8	14.4	16.4	68.4			0.1	4.2	72.3	74.6	-12.77	-6.81			13.011	7.007	-13.27	-6.46	1316	34.4341978	-118.6502665	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-2339	10/27/2026 8:51:02 AM	0.6	23.0	15.2	61.2			0.0	4.0	64.9	67.1	-6.30	-1.66			6.295	1.660	-11.58	-9.92	1306	34.4341803	-118.6502798	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2341	10/1/2026 11:15:14 AM	22.7	51.3	0.7	25.3			0.4	36.1	122.1	122.2	-7.43	-6.17	0.0	0.0	7.417	6.133	-8.18	-2.01	1260	34.4335760	-118.6502675	,
CV-2341	10/12/2026 9:06:00 AM					1000																	Air Tech Lab
CV-2341	10/12/2026 9:06:00 AM						160000																Air Tech Lab; [User entered 16%]
CV-2341	10/27/2026 10:14:44 AM	0.9	83.8	0.0	15.3			0.0	0.0	165.0	74.3	-1.19	-1.18			1.190	1.211	-11.53	-10.35	1309	34.4336138	-118.6502072	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2341	10/27/2026 10:15:18 AM	0.7	85.5	0.0	13.8			0.0	0.0	165.0	70.4	-1.20	-1.21			1.207	1.205	-11.78	-10.57	1320	34.4336088	-118.6502003	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed
CV-2342A-F	10/1/2026 10:40:00 AM					644																	AtmAA
CV-2342A-F	10/1/2026 10:43:03 AM	9.7	65.4	0.0	24.9			0.1	0.0	150.4	150.5	-5.45	-5.43			5.943	6.122	-8.20	-2.77	1291	34.4342305	-118.6508517	Valve Adjustment:No Flow Measurement,High Temp
CV-2342A-F	10/6/2026 2:31:08 PM	16.9	67.1	0.0	16.0			0.3	0.0	185.4	185.5	-5.52	-5.35			5.563	5.488	-7.85	-2.5	1292	34.4342088	-118.6508299	Valve Adjustment:No Flow Measurement,High Temp
CV-2342A-F	10/6/2026 2:35:00 PM					781																	AtmAA
CV-2342A-F	10/6/2026 2:35:00 PM						196300																AtmAA; [User entered 19.63%]

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-2342A-F	10/13/2026 1:32:09 PM	18.2	69.5	0.1	12.2			0.3	122.0	186.1	185.9	-9.17	-9.10			9.556	9.451	-12.02	-2.92	1284	34.4341937	-118.6508305	Valve Adjustment:No Flow Measurement,High Temp
CV-2342A-F	10/13/2026 1:35:00 PM					986																	AtmAA
CV-2342A-F	10/19/2026 9:49:06 AM	14.0	71.6	0.0	14.4			0.2	0.0	179.0	178.8	-7.27	-6.78			0.000	0.000	0.04	6.82	1276	34.4342114	-118.6508477	Valve Adjustment:No Flow Measurement,High Temp
CV-2342A-F	10/26/2026 9:06:00 AM					1060																	AtmAA
CV-2342A-F	10/26/2026 9:06:09 AM	14.5	0.0	0.0	85.5				0.0	169.8	172.6	-7.12	-7.12			7.565	7.556	-9.09	-1.97	1286	34.4342277	-118.6508363	Valve Adjustment:No Flow Measurement,High Temp
CV-2343-PL	10/1/2026 10:35:00 AM					2990																	AtmAA
CV-2343-PL	10/1/2026 10:35:17 AM	17.2	62.1	0.0	20.7			0.3	0.0	189.6	189.8	-8.41	-8.13			8.935	8.735	-9.25	-1.12	1283	34.4332247	-118.6506852	Valve Adjustment:No Flow Measurement,High Temp
CV-2343-PL	10/6/2026 2:10:00 AM					3530																	AtmAA
CV-2343-PL	10/6/2026 2:10:00 PM						183200																AtmAA; [User entered 18.32%]
CV-2343-PL	10/6/2026 2:10:26 PM	12.5	73.2	0.3	14.0			0.2	46.7	191.1	190.5	-9.08	-8.72			9.256	8.889	-9.75	-1.03	1273	34.4332192	-118.6506725	Valve Adjustment:No Flow Measurement,High Temp
CV-2343-PL	10/13/2026 2:59:12 PM	15.5	72.7	0.0	11.8			0.2	0.0	186.1	186.4	-13.14	-12.81			13.669	13.351	-13.85	-1.04	1286	34.4332242	-118.6506667	Valve Adjustment:No Flow Measurement,High Temp
CV-2343-PL	10/13/2026 3:00:00 PM					4680																	AtmAA
CV-2343-PL	10/19/2026 9:38:06 AM	6.4	74.2	0.0	19.4			0.1	0.0	191.1	190.5	-8.30	-8.13			8.967	8.680	-9.67	-1.54	1276	34.4332329	-118.6506864	Valve Adjustment:No Flow Measurement,High Temp
CV-2343-PL	10/26/2026 9:14:56 AM	7.9	0.0	0.0	92.1				0.0	191.2	190.7	-9.39	-9.14			9.805	9.660	-10.11	-0.97	1280	34.4332343	-118.6506979	Valve Adjustment:No Flow Measurement,High Temp
CV-2343-PL	10/26/2026 9:17:00 AM					4380																	AtmAA
CV-2344	10/1/2026 10:30:00 AM					1810																	AtmAA
CV-2344	10/1/2026 10:30:08 AM	19.5	65.9	0.0	14.6			0.3	0.0	144.2	145.3	-5.73	-5.73			6.273	6.308	-8.35	-2.62	1296	34.4329702	-118.6504377	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2344	10/5/2026 9:10:00 AM					1200																	AirTech Lab
CV-2344	10/5/2026 9:10:00 AM						93000																AirTech Lab; [User entered 9.3%]
CV-2344	10/5/2026 1:45:00 PM					3.96																	AtmAA
CV-2344	10/5/2026 1:45:00 PM						0																<0.10 AtmAA; [User entered 0%]
CV-2344	10/5/2026 1:45:14 PM	29.7	70.3	0.0	0.0			0.4	0.0	154.5	154.7	-6.59	-6.35			6.494	6.361	-8.79	-2.44	1283	34.4329717	-118.6504578	Valve Adjustment:No Flow Measurement,High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2344	10/14/2026 8:20:00 AM	24.6	61.5	0.1	13.8			0.4	138.0	151.3	151.9	-12.13	-11.88			12.408	12.045	-14.82	-2.94	1278	34.4330002	-118.6504248	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2344	10/19/2026 9:31:02 AM	23.9	65.3	0.0	10.8			0.4	0.0	154.5	154.9	-6.62	-6.49			7.115	7.039	-9.59	-3.1	1285	34.4329718	-118.6504336	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2344	10/26/2026 9:19:27 AM	14.8	0.0	0.0	85.2				0.0	146.1	146.3	-7.14	-7.08			7.739	7.551	-9.84	-2.76	1288	34.4329881	-118.6504708	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2344	10/26/2026 9:22:00 AM					2010																	AtmAA
CV-2345	10/5/2026 9:05:00 AM					230																	AirTech Lab
CV-2345	10/5/2026 9:05:00 AM						26000																AirTech Lab; [User entered 2.6%]
CV-2345	10/14/2026 2:16:01 PM	15.4	53.7	0.3	30.6			0.3	102.0	133.2	132.8	-8.05	-8.06			8.064	8.019	-15.91	-7.85	1287	34.4327457	-118.6502047	Valve Adjustment:NSPS/EG CAI,High Temp;Well Repairs:Valve
CV-2345	10/14/2026 2:17:33 PM	15.6	55.0	0.2	29.2			0.3	146.0	132.2	132.6	-8.06	-8.07			8.039	8.087	-16.12	-8.05	1283	34.4327295	-118.6502045	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2345	10/27/2026 9:50:50 AM	32.5	65.0	2.4	0.1			0.5	0.0	127.6	128.6	-5.40	-5.29			5.519	5.502	-11.86	-6.57	1287	34.4327238	-118.6501897	Valve Adjustment:Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2346	10/1/2026 10:21:20 AM	6.3	78.5	0.0	15.2			0.1	0.0	185.8	185.4	-7.33	-7.33			7.728	7.728	-9.62	-2.29	1295	34.4325897	-118.6500658	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	10/1/2026 10:25:00 AM					2210																	AtmAA
CV-2346	10/5/2026 9:00:00 AM					380																	AirTech Lab
CV-2346	10/5/2026 9:00:00 AM						38000																AirTech Lab; [User entered 3.8%]
CV-2346	10/5/2026 1:30:00 PM					105																	AtmAA
CV-2346	10/5/2026 1:30:00 PM						5100																AtmAA; [User entered 0.51%]
CV-2346	10/5/2026 1:31:20 PM	16.0	82.2	0.0	1.8			0.2	0.0	188.5	188.7	-7.45	-7.28			7.393	7.203	-9.34	-2.06	1298	34.4325887	-118.6500532	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2346	10/13/2026 3:04:35 PM	14.2	72.7	0.0	13.1			0.2	0.0	186.6	186.8	-11.20	-11.12			11.710	11.546	-14.15	-3.03	1311	34.4325761	-118.6500531	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-2346	10/19/2026 9:19:00 AM	7.5	79.3	0.0	13.2				0.1	0.0	190.1	189.7	-7.57	-7.75			8.053	8.269	-11.97	-4.22	1284	34.4325953	-118.6500748	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	10/26/2026 9:26:46 AM	21.3	0.0	0.0	78.7				0.0	0.0	187.6	188.3	-8.13	-7.55			8.671	8.060	-10.27	-2.72	1300	34.4326132	-118.6500934	Valve Adjustment:No Flow Measurement,High Temp
CV-2346	10/26/2026 9:28:00 AM					2520																	AtmAA
CV-2347	10/5/2026 8:55:00 AM					660																	AirTech Lab
CV-2347	10/5/2026 8:55:00 AM						50000																AirTech Lab; [User entered 5.0%]
CV-2347	10/14/2026 2:22:29 PM	7.8	41.9	0.0	50.3				0.2	0.0	137.2	137.4	-6.34	-6.38			6.392	6.363	-16.07	-9.69	1299	34.4323547	-118.6498545	Valve Adjustment:NSPS/EG CAI,High Temp;Well Repairs:Valve
CV-2347	10/14/2026 2:23:22 PM	7.6	42.1	0.0	50.3				0.2	0.0	138.2	138.5	-6.40	-6.42			6.425	6.579	-15.24	-8.82	1302	34.4323488	-118.6498568	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2347	10/27/2026 9:55:17 AM	11.4	54.3	0.1	34.2				0.2	342.0	141.3	141.5	-4.15	-4.14			4.168	4.151	-11.49	-7.35	1302	34.4323595	-118.6498455	Valve Comment:well too tall for system adjustment
CV-2348	10/1/2026 12:08:04 PM	16.3	42.3	0.0	41.4				0.4	0.0	139.9	139.9	-7.46	-7.44	0.0	0.0	7.546	7.389	-7.42	0.02	1230	34.4321572	-118.6497275	NSPS/EG CAI,High Temp
CV-2348	10/1/2026 12:08:31 PM	17.7	49.7	0.1	32.5				0.4	325.0	140.2	140.2	-7.43	-7.42	0.0	0.0	7.531	7.527	-7.40	0.02	1243	34.4321698	-118.6496717	NSPS/EG CAI,High Temp
CV-2348	10/5/2026 8:50:00 AM					420																	AirTech Lab
CV-2348	10/5/2026 8:50:00 AM						34000																AirTech Lab; [User entered 3.4%]
CV-2348	10/27/2026 10:00:49 AM	6.9	80.9	1.2	11.0				0.1	9.2	156.3	156.5	-11.87	-12.08			12.025	12.152	0.34	12.42	1303	34.4321608	-118.6496330	Valve Comment:hard piped
CV-2349	10/1/2026 1:30:00 PM					2780																	AtmAA
CV-2349	10/1/2026 1:36:07 PM	17.3	76.1	0.0	6.6				0.2	0.0	159.2	158.7	-0.05	-0.07			0.050	0.048	-2.05	-1.98	1268	34.4331296	-118.6512426	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.;Well Condition:Lorentz Pump Installed
CV-2349	10/7/2026 7:53:34 AM	7.7	69.2	0.0	23.1				0.1	0.0	173.1	173.5	-1.25	-0.80			1.197	0.866	-2.02	-1.22	1266	34.4331766	-118.6512079	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2349	10/7/2026 7:55:00 AM					3360																	AtmAA
CV-2349	10/7/2026 7:55:00 AM						177400																AtmAA; [User entered 17.74%]
CV-2349	10/12/2026 9:30:00 AM					2700																	Air Tech Lab
CV-2349	10/12/2026 9:30:00 AM						190000																Air Tech Lab; [User entered 19%]
CV-2349	10/14/2026 9:03:12 AM	0.0	0.0	0.0	100.0				0.0	176.3	178.4	-2.39	-2.37			2.408	2.441	-2.57	-0.2	1252	34.4331575	-118.6512528	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2349	10/14/2026 9:05:00 AM					4140																	AtmAA
CV-2349	10/19/2026 10:18:23 AM	18.4	68.9	0.0	12.7				0.3	0.0	186.7	186.0	-1.78	-1.69			1.679	1.786	-1.79	-0.1	1256	34.4331389	-118.6512554	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2349	10/26/2026 8:13:00 AM					4350																	AtmAA
CV-2349	10/26/2026 8:20:52 AM	3.9	0.0	0.0	96.1				0.0	172.0	175.1	0.40	0.39			0.000	0.000	0.72	0.33	1259	34.4331426	-118.6512523	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2350	10/9/2026 7:20:00 AM					3200																	AirTech Lab
CV-2350	10/9/2026 7:20:00 AM						160000																AirTech Lab; [User entered 16%]
CV-2350	10/9/2026 9:55:13 AM	5.2	71.7	0.8	22.3				0.1	27.9	128.2	128.3	-13.84	-13.86			13.995	14.149	-13.70	0.16	1272	34.4327698	-118.6509062	Valve Comment:valve to tall
CV-2350	10/30/2026 8:45:43 AM	4.7	74.6	1.5	19.2				0.1	12.8	98.1	98.1	-13.16	-12.83			13.153	12.755	-14.51	-1.68	1287	34.4327715	-118.6508803	Valve Comment:Well stuck open
CV-2351	10/5/2026 9:22:00 AM					0																	AirTech Lab
CV-2351	10/5/2026 9:22:00 AM						0																AirTech Lab; [User entered 0%]
CV-2351	10/13/2026 10:36:28 AM	1.8	3.9	17.4	76.9				0.5	4.4	85.8	85.9	-9.56	-9.61			9.862	9.887	-9.63	-0.02	1290	34.4351478	-118.6511460	Valve Adjustment:NSPS/EG CAI,High O2;Well Repairs:Valve
CV-2351	10/20/2026 11:30:58 AM	14.4	24.4	11.4	49.8				0.6	4.4	98.1	98.3	-6.09	-5.92			6.224	6.020	-5.98	-0.06	1313	34.4351258	-118.6511558	Valve Adjustment:NSPS/EG CAI,High O2
CV-2351	10/20/2026 11:31:30 AM	14.7	24.4	11.2	49.7				0.6	4.4	98.3	98.4	-5.54	-5.54			5.649	5.649	-5.44	0.1	1316	34.4351255	-118.6511607	Valve Adjustment:NSPS/EG CAI,High O2
CV-2352	10/5/2026 10:27:07 AM	12.5	80.6	1.1	5.8				0.2	5.3	138.1	136.5	-7.47	-4.29			7.815	4.296	-7.44	-3.15	1289	34.4348720	-118.6510565	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-2352	10/5/2026 10:27:58 AM	12.7	76.7	1.9	8.7				0.2	4.6	139.1	139.2	-5.16	-5.12			5.625	5.643	-7.55	-2.43	1280	34.4348648	-118.6510460	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2352	10/6/2026 2:40:00 PM					920																	AtmAA
CV-2352	10/6/2026 2:40:00 PM						181100																AtmAA; [User entered 18.11%]
CV-2352	10/6/2026 2:52:49 PM	34.6	65.4	0.0	0.0				0.5	0.0	187.9	192.7	71.93	-3.01			0.000	2.895	-6.77	-3.76	1291	34.4348567	-118.6510447	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Pnumatic Pump Installed

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-2352	10/6/2026 2:54:54 PM	30.1	69.6	0.0	0.3			0.4	0.0	191.9	192.2	-3.80	-3.69			3.997	3.693	-5.98	-2.29	1294	34.4348615	-118.6510497	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2352	10/13/2026 1:26:37 PM	19.0	62.1	3.3	15.6			0.3	4.7	116.3	115.7	-8.48	-8.42			8.869	8.844	-9.82	-1.4	1290	34.4348819	-118.6510380	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2352	10/14/2026 7:45:00 AM					750																	Air Tech Lab
CV-2352	10/14/2026 7:45:00 AM						210000																Air Tech Lab; [User entered 21%]
CV-2352	10/20/2026 11:24:50 AM	4.2	77.6	1.7	16.5			0.1	9.7	117.5	114.9	-5.69	-5.46			5.878	5.607	-5.56	-0.1	1310	34.4348563	-118.6510607	Valve Adjustment:Decreased Flow/Vacuum
CV-2353-PL	10/12/2026 9:50:00 AM					510																	Air Tech Lab
CV-2353-PL	10/12/2026 9:50:00 AM						190000																Air Tech Lab; [User entered 19%]
CV-2353-PL	10/13/2026 10:50:34 AM	3.8	64.1	3.1	29.0			0.1	9.4	122.9	122.8	-12.75	-12.61			12.987	12.847	-12.70	-0.09	1300	34.4345223	-118.6508995	Valve Adjustment:Decreased Flow/Vacuum
CV-2353-PL	10/27/2026 9:09:06 AM	2.5	69.8	2.1	25.6			0.0	12.2	112.1	109.4	-11.28	-11.46			11.312	11.453	-11.37	0.09	1290	34.4345567	-118.6508875	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-2354	10/12/2026 8:48:00 AM					1700																	Air Tech Lab
CV-2354	10/12/2026 8:48:00 AM						190000																Air Tech Lab; [User entered 19%]
CV-2354	10/13/2026 2:05:00 PM					3700																	AtmAA
CV-2354	10/13/2026 2:47:46 PM	21.3	71.8	0.1	6.8			0.3	68.0	183.1	182.9	2.18	1.64			0.000	0.000	2.02	0.38	1256	34.4336680	-118.6513265	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Positive Static Press.,Valve 100% Open
CV-2354	10/13/2026 2:51:36 PM	22.0	74.0	0.0	4.0			0.3	0.0	183.2	185.2	1.50	1.58			0.000	0.000	1.35	-0.23	1258	34.4336942	-118.6513695	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Positive Static Press.,Valve 100% Open
CV-2354	10/14/2026 8:09:06 AM	13.2	74.6	0.5	11.7			0.2	23.4	188.5	188.4	-5.28	-4.70			5.200	4.709	-8.38	-3.68	1258	34.4336914	-118.6513433	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2354	10/20/2026 9:24:58 AM	0.0	0.0	0.0	100.0				0.0	187.9	188.7	-3.19	-2.80			3.082	2.727	-5.78	-2.98	1259	34.4336749	-118.6513728	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2354	10/20/2026 9:35:00 AM					2620																	AtmAA
CV-2354	10/26/2026 8:00:00 AM					2330																	AtmAA
CV-2354	10/26/2026 8:01:14 AM	7.2	0.0	0.0	92.8				0.0	185.6	185.6	-2.45	-2.25			2.446	2.111	-5.18	-2.93	1250	34.4336876	-118.6513269	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24001	10/1/2026 10:35:13 AM	55.8	44.2	0.0	0.0			1.3	0.0	111.6	111.5	-1.45	-1.46			1.443	1.441	-2.53	-1.07	1351	34.4366578	-118.6509298	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24001	10/16/2026 11:10:24 AM	53.6	46.3	0.1	0.0			1.2	0.0	99.7	99.6	-3.56	-3.63			3.591	3.624	-6.02	-2.39	1358	34.4366368	-118.6509238	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24002	10/1/2026 10:28:47 AM	35.8	42.8	0.0	21.4			0.8	0.0	113.4	113.4	-3.39	-3.38			3.394	3.378	-10.62	-7.24	1348	34.4367400	-118.6504680	Valve Adjustment:Barely Open
CV-24002	10/16/2026 11:02:56 AM	32.5	48.2	2.0	17.3			0.7	8.7	107.9	106.7	-4.00	-3.96			4.046	3.962	-12.52	-8.56	1360	34.4367310	-118.6504795	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24003	10/1/2026 10:26:19 AM	30.1	46.3	0.4	23.2			0.7	58.0	108.6	109.0	-1.84	-1.87	1.5	2.5	0.006	0.016	-10.99	-9.12	1366	34.4368710	-118.6500847	Valve Adjustment:Barely Open
CV-24003	10/16/2026 10:53:24 AM	34.5	49.6	0.7	15.2			0.7	21.7	108.5	108.9	-2.26	-2.28	0.8	1.5	0.002	0.006	-12.57	-10.29	1366	34.4368812	-118.6500950	Valve Adjustment:Barely Open
CV-24004	10/1/2026 10:22:35 AM	31.1	49.5	0.0	19.4			0.6	0.0	119.2	121.1	-2.52	-2.26	7.4	3.7	0.151	0.038	-8.74	-6.48	1356	34.4370343	-118.6496905	Valve Adjustment:Decreased Flow/Vacuum
CV-24004	10/16/2026 10:50:01 AM	34.7	54.6	0.2	10.5			0.6	52.5	117.0	117.0	-2.75	-2.90	4.9	2.6	0.065	0.018	-10.33	-7.43	1359	34.4370480	-118.6496915	Valve Adjustment:Barely Open
CV-24006	10/1/2026 2:07:02 PM	11.1	78.6	0.2	10.1			0.1	50.5	125.7	125.9	-0.04	-0.05	3.0	4.4	0.025	0.053	-4.09	-4.04	1365	34.4363578	-118.6504565	Valve Adjustment:Barely Open
CV-24006	10/16/2026 11:23:08 AM	16.6	71.1	1.6	10.7			0.2	6.7	109.7	109.8	-0.39	-0.46	1.2	1.5	0.004	0.006	-4.91	-4.45	1390	34.4363475	-118.6504615	Valve Adjustment:Barely Open
CV-24007	10/1/2026 1:58:09 PM	6.5	75.9	0.2	17.4			0.1	87.0	162.0	162.2	-0.41	-0.40	5.0	5.4	0.073	0.084	0.34	0.74	1370	34.4364853	-118.6501027	Valve Adjustment:High Temp,Barely Open
CV-24007	10/5/2026 2:42:07 PM	33.7	62.9	0.2	3.2			0.5	16.0	163.1	162.8	-0.31	-0.30	5.6	5.6	0.091	0.090	-12.00	-11.7	1382	34.4365029	-118.6501276	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24007	10/5/2026 2:45:00 PM					1950																	AtmAA
CV-24007	10/5/2026 2:45:00 PM						145200																AtmAA; [User entered 14.52%]
CV-24007	10/6/2026 7:05:00 AM					1600																	Air Tech Lab
CV-24007	10/6/2026 7:05:00 AM						170000																Air Tech Lab; [User entered 17%]
CV-24007	10/13/2026 8:04:39 AM	15.0	71.4	0.0	13.6			0.2	0.0	160.8	161.1	-1.73	-1.71	5.8	6.1	0.097	0.109	-16.17	-14.46	1348	34.4365156	-118.6501192	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24007	10/13/2026 8:05:00 AM					1820																	AtmAA
CV-24007	10/20/2026 7:59:27 AM	28.9	48.4	0.3	22.4			0.6	74.7	157.7	157.8	-2.74	-2.74	36.0	35.2	3.797	3.647	-14.69	-11.95	1375	34.4365000	-118.6501305	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24007	10/20/2026 8:05:00 AM					652.5																	AtmAA

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24007	10/27/2026 7:23:00 AM					627																	AtmAA
CV-24007	10/27/2026 7:26:10 AM	23.5	42.4	0.7	27.5		5.9	0.6	39.3	155.0	155.0	-15.52	-15.40	54.0	54.0	8.868	8.863	-3.08	12.32	1367	34.4365188	-118.6501122	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24008	10/5/2026 2:35:00 PM					1170																	AtmAA
CV-24008	10/5/2026 2:35:00 PM						93500																AtmAA; [User entered 9.35%]
CV-24008	10/5/2026 2:36:24 PM	34.4	64.3	0.2	1.1			0.5	5.5	180.8	180.9	-6.95	-6.94	99.1	98.6	7.120	7.048	-8.17	-1.23	1381	34.4366696	-118.6497049	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24008	10/13/2026 8:00:00 AM					674.5																	AtmAA
CV-24008	10/13/2026 8:00:07 AM	22.3	59.3	1.1	17.3			0.4	15.7	177.9	177.9	-13.59	-13.56	136.1	136.0	13.757	13.737	-15.42	-1.86	1343	34.4366744	-118.6497093	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24008	10/20/2026 1:33:04 PM	23.7	56.8	0.2	19.3			0.4	96.5	178.3	178.5	-8.42	-8.35	107.4	107.3	8.377	8.362	-9.93	-1.58	1381	34.4366687	-118.6496927	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24008	10/20/2026 1:35:00 PM					1340																	AtmAA
CV-24008	10/28/2026 1:43:00 PM					1270																	AtmAA
CV-24008	10/28/2026 1:45:56 PM	43.6	56.4	0.0	0.0			0.8	0.0	178.0	178.0	-7.41	-7.41	102.1	102.3	7.541	7.565	-11.25	-3.84	1371	34.4366602	-118.6496919	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24009	10/5/2026 2:29:57 PM	9.7	71.3	0.1	18.9			0.1	189.0	171.6	171.5	-4.93	-4.93			0.030	0.032	-8.23	-3.3	1396	34.4368281	-118.6493659	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-24009	10/5/2026 2:30:00 PM					1480																	AtmAA
CV-24009	10/5/2026 2:30:00 PM						161600																AtmAA; [User entered 16.16%]
CV-24009	10/12/2026 2:35:00 PM					1630																	AtmAA
CV-24009	10/12/2026 3:01:53 PM	1.6	1.2	19.7	77.5			1.3	3.9	162.4	162.1	-9.84	-2.56			0.940	0.281	-13.29	-10.73	1381	34.4368519	-118.6493547	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Barely Open;Well Condition:Pnumatic Pump Installed
CV-24009	10/12/2026 3:04:11 PM	12.1	75.6	0.3	12.0			0.2	40.0	161.8	161.9	-1.60	-1.57			0.143	0.136	-13.25	-11.68	1382	34.4368523	-118.6493550	Valve Adjustment:NSPS/EG CAC,High Temp;Well Condition:Pnumatic Pump Installed
CV-24009	10/20/2026 10:45:00 AM					1690																	AtmAA
CV-24009	10/20/2026 10:45:09 AM	0.0	0.0	0.2	99.8				499.0	167.1	167.1	-2.79	-2.76			0.095	0.084	-2.16	0.6	1407	34.4368397	-118.6493510	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24009	10/26/2026 9:10:27 AM	5.0	73.9	0.0	21.1			0.1	0.0	170.4	170.4	-9.97	-9.72			5.295	5.007	-4.70	5.02	1382	34.4368870	-118.6493395	Valve Adjustment:High Temp
CV-24009	10/26/2026 9:15:00 AM					1650																	AtmAA
CV-24010	10/13/2026 1:46:29 PM	4.3	31.3	9.2	55.2			0.1	6.0	84.4	84.4	-10.76	-10.54			10.647	10.464	-10.47	0.07	1370	34.4370803	-118.6489423	Valve Adjustment:NSPS/EG CAI,High O2
CV-24010	10/13/2026 1:48:32 PM	4.5	32.9	8.8	53.8			0.1	6.1	85.0	84.9	-10.63	-10.66			10.454	10.484	-10.55	0.11	1361	34.4370875	-118.6489487	Valve Adjustment:NSPS/EG CAI,High O2
CV-24010	10/29/2026 10:11:43 AM	2.5	20.5	13.9	63.1			0.1	4.5	74.8	75.0	-11.24	-11.15			11.662	11.618	-11.30	-0.15	1367	34.4370872	-118.6489228	Valve Adjustment:High O2,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24011	10/5/2026 2:51:36 PM	30.7	62.6	0.0	6.7			0.5	0.0	184.0	184.1	-2.22	-2.15	34.9	33.1	3.718	3.339	-6.47	-4.32	1376	34.4361656	-118.6501634	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24011	10/5/2026 3:05:00 PM					1680																	AtmAA
CV-24011	10/5/2026 3:05:00 PM						143000																AtmAA; [User entered 14.3%]
CV-24011	10/13/2026 8:55:00 AM					1350																	AtmAA
CV-24011	10/13/2026 8:56:51 AM	24.6	64.1	0.1	11.2			0.4	112.0	179.0	179.1	-4.96	-4.80	47.9	48.5	7.027	7.197	-12.85	-8.05	1373	34.4361846	-118.6501772	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24011	10/20/2026 8:14:22 AM	15.0	64.9	0.1	20.0			0.2	200.0	180.6	180.6	-4.72	-4.66	45.0	45.8	6.216	6.426	-10.44	-5.78	1367	34.4361803	-118.6501930	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24011	10/20/2026 8:21:00 AM					1010																	AtmAA
CV-24011	10/27/2026 7:38:35 AM	14.0	66.2	0.0	6.5		13.3	0.2	0.0	179.5	179.6	-9.76	-9.55	12.4	13.1	0.471	0.526	-4.97	4.58	1368	34.4361983	-118.6501825	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24011	10/27/2026 7:40:00 AM					1060																	AtmAA
CV-24012	10/6/2026 8:27:56 AM	6.9	77.3	0.0	15.8			0.1	0.0	184.5	184.5	-3.98	-3.92			3.983	3.900	-11.54	-7.62	1356	34.4361719	-118.6493699	Valve Adjustment:No Flow Measurement,High Temp
CV-24012	10/8/2026 12:47:00 PM					2200																	AtmAA
CV-24012	10/8/2026 12:47:00 PM						149100																AtmAA; [User entered 14.91%]
CV-24012	10/8/2026 12:49:01 PM	8.6	77.7	0.0	13.7			0.1	0.0	185.2	185.4	-0.43	-0.30			0.416	0.322	-7.43	-7.13	1364	34.4361889	-118.6493765	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24012	10/13/2026 9:09:34 AM	15.5	67.8	0.0	16.7			0.2	0.0	183.1	183.3	-8.45	-8.42			9.019	9.052	-14.93	-6.51	1347	34.4361937	-118.6493816	Valve Adjustment:No Flow Measurement,High Temp
CV-24012	10/13/2026 9:10:00 AM					1980																	AtmAA
CV-24012	10/20/2026 8:32:12 AM	7.2	74.7	0.0	18.1			0.1	0.0	161.5	161.5	-6.72	-6.72			6.768	6.670	-12.13	-5.41	1356	34.4361755	-118.6493702	Valve Adjustment:No Flow Measurement,High Temp
CV-24012	10/20/2026 8:42:00 AM					2030																	AtmAA
CV-24012	10/27/2026 7:56:22 AM	2.1	73.2	0.3	6.5		17.9	0.0	21.7	175.0	176.0	-11.19	-11.11			11.153	11.060	-6.32	4.79	1370	34.4361667	-118.6493672	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24012	10/27/2026 8:05:00 AM					1680																	AtmAA
CV-24013	10/5/2026 2:21:29 PM	9.4	71.6	0.2	18.8			0.1	94.0	194.1	193.2	1.24	-4.74			0.000	4.706	-7.96	-3.22	1389	34.4365862	-118.6492099	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24013	10/5/2026 2:23:25 PM	9.8	71.7	0.1	18.4			0.1	184.0	193.1	194.0	-4.70	-4.66			4.667	4.676	-7.97	-3.31	1384	34.4365849	-118.6492218	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24013	10/5/2026 2:25:00 PM					1240																	AtmAA
CV-24013	10/5/2026 2:25:00 PM						102200																AtmAA; [User entered 10.22%]
CV-24013	10/12/2026 2:28:38 PM	7.3	75.8	0.3	16.6			0.1	55.3	190.6	190.0	-9.89	-9.88			10.181	10.100	-13.38	-3.5	1384	34.4366003	-118.6492113	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24013	10/12/2026 2:30:00 PM					2160																	AtmAA
CV-24013	10/20/2026 10:26:00 AM					0																	AtmAA <50
CV-24013	10/20/2026 10:37:58 AM	2.1	76.6	0.2	21.1			0.0	105.5	192.1	191.5	-0.36	-2.03			0.363	2.012	-0.13	1.9	1387	34.4365990	-118.6492432	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24013	10/20/2026 10:39:00 AM	2.0	80.7	0.1	17.2			0.0	172.0	192.1	191.6	-2.27	-2.21			2.235	2.150	0.17	2.38	1389	34.4365873	-118.6492443	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24013	10/26/2026 8:40:00 AM					2690																	AtmAA
CV-24013	10/26/2026 9:04:28 AM	2.3	73.2	0.1	24.4			0.0	244.0	189.6	189.0	-9.76	-9.67			9.968	9.896	-8.81	0.86	1375	34.4366167	-118.6492220	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24014	10/5/2026 10:02:26 AM	14.3	64.5	0.0	21.2			0.2	0.0	184.8	185.3	-4.43	-4.31	38.3	37.3	4.494	4.282	-5.73	-1.42	1377	34.4367768	-118.6489462	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24014	10/5/2026 10:05:00 AM					1540																	AtmAA
CV-24014	10/12/2026 9:02:55 AM	5.3	72.3	0.1	22.3			0.1	223.0	184.1	184.2	-7.36	-7.18	49.5	49.0	7.637	7.478	-8.93	-1.75	1363	34.4367680	-118.6489501	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24014	10/12/2026 9:05:00 AM					1850																	AtmAA
CV-24014	10/19/2026 9:31:08 AM	15.7	57.9	5.9	20.5			0.3	3.5	178.5	171.4	-7.24	-2.79	49.2	30.6	7.464	2.800	-8.12	-5.33	1371	34.4367722	-118.6489468	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,High O2,Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24014	10/19/2026 9:51:45 AM	14.9	51.2	6.6	27.3			0.3	4.1	175.9	178.5	-4.52	-7.68	38.7	50.6	4.543	7.898	-8.30	-0.62	1361	34.4367312	-118.6489362	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,High O2,Valve 100% Open;Well Condition:Pnumatic Pump Installed
CV-24014	10/19/2026 9:53:51 AM	16.9	56.5	4.3	22.3			0.3	5.2	178.5	179.1	-6.41	-6.41	47.0	47.0	6.786	6.790	-6.90	-0.49	1362	34.4367470	-118.6489430	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed
CV-24014	10/26/2026 8:55:00 AM					1710																	AtmAA
CV-24014	10/26/2026 9:00:03 AM	2.4	73.3	0.1	24.2			0.0	242.0	185.3	185.4	-6.51	-6.40			6.721	6.564	-6.31	0.09	1375	34.4367802	-118.6489480	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24015	10/5/2026 9:05:00 AM					2050																	AtmAA
CV-24015	10/5/2026 9:47:53 AM	14.8	73.5	0.0	11.7			0.2	0.0	190.3	190.2	-6.06	-5.73			6.537	6.041	-7.92	-2.19	1362	34.4368707	-118.6486319	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24015	10/5/2026 9:50:00 AM						211500																AtmAA; [User entered 21.15%]
CV-24015	10/12/2026 8:49:21 AM	5.0	74.7	0.0	20.3			0.1	0.0	188.7	188.6	-7.00	-6.61			7.220	6.760	-8.01	-1.4	1358	34.4368663	-118.6486188	Valve Adjustment:No Flow Measurement,High Temp
CV-24015	10/12/2026 8:50:00 AM					1740																	AtmAA
CV-24015	10/19/2026 8:46:02 AM	6.8	71.6	2.5	19.1			0.1	7.6	188.5	188.4	-7.59	-7.43			7.731	7.494	-7.96	-0.53	1358	34.4368550	-118.6486105	Valve Adjustment:No Flow Measurement,High Temp
CV-24015	10/26/2026 8:42:12 AM	1.8	72.7	0.0	25.5			0.0	0.0	148.7	147.6	-7.83	-7.41			7.952	7.605	-7.41	0	1369	34.4368685	-118.6486118	Valve Adjustment:No Flow Measurement,High Temp
CV-24015	10/26/2026 9:10:00 AM					2060																	AtmAA
CV-24016	10/5/2026 3:10:00 PM					1270																	AtmAA
CV-24016	10/5/2026 3:10:00 PM						81000																AtmAA; [User entered 8.1%]
CV-24016	10/5/2026 3:10:01 PM	26.2	52.3	0.1	21.4			0.5	214.0	179.3	179.3	-4.57	-4.55			4.592	4.557	-5.56	-1.01	1369	34.4358753	-118.6502619	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24016	10/13/2026 9:22:57 AM	22.3	53.4	0.0	24.3			0.4	0.0	172.4	172.3	-7.50	-7.46			8.060	8.054	-10.37	-2.91	1356	34.4359100	-118.6502401	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24016	10/13/2026 9:25:00 AM					1280																	AtmAA
CV-24016	10/20/2026 8:25:16 AM	12.9	59.2	0.0	27.9			0.2	0.0	150.8	140.2	-7.39	-7.39			7.261	7.274	-8.51	-1.12	1359	34.4359088	-118.6502452	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24016	10/20/2026 8:32:00 AM					621																	AtmAA
CV-24016	10/28/2026 1:55:00 PM					1370																	AtmAA
CV-24016	10/28/2026 1:58:37 PM	23.5	48.5	0.0	28.0			0.5	0.0	173.8	173.7	-4.81	-4.76			5.068	5.043	-7.82	-3.06	1365	34.4358960	-118.6502289	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	10/6/2026 8:15:00 AM					998																	AtmAA
CV-24017	10/6/2026 8:15:00 AM						110250																AtmAA; [User entered 11.025%]
CV-24017	10/6/2026 8:18:44 AM	21.6	68.5	0.5	9.4			0.3	18.8	186.4	186.6	-5.45	-5.39			5.703	5.669	-10.42	-5.03	1359	34.4360966	-118.6498290	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	10/13/2026 7:35:00 AM					870																	AirTech Lab
CV-24017	10/13/2026 7:35:00 AM						110000																AirTech Lab; [User entered 11%]
CV-24017	10/13/2026 9:00:00 AM					1440																	AtmAA
CV-24017	10/13/2026 9:00:37 AM	28.1	62.3	0.9	8.7			0.5	9.7	184.0	183.9	-9.44	-9.22			10.005	9.773	-13.94	-4.72	1358	34.4360946	-118.6498110	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	10/20/2026 8:10:46 AM	11.9	65.1	2.6	20.4			0.2	7.8	144.2	144.5	-7.50	-7.39			7.542	7.536	-10.94	-3.55	1367	34.4360937	-118.6498095	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24017	10/20/2026 8:20:00 AM					546																	AtmAA
CV-24018	10/1/2026 2:24:27 PM	6.9	73.6	0.2	19.3			0.1	96.5	142.0	142.5	-0.42	-0.33			0.254	0.310	-7.85	-7.52	1364	34.4356030	-118.6500470	Valve Adjustment:High Temp,Barely Open
CV-24018	10/20/2026 8:43:20 AM	5.7	76.6	0.0	17.7			0.1	0.0	141.1	142.1	-0.71	-0.71			0.708	0.707	-11.23	-10.52	1366	34.4356048	-118.6500672	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24018	10/20/2026 8:52:00 AM					1340																	AtmAA
CV-24019	10/6/2026 8:38:03 AM	7.5	75.1	0.0	17.4			0.1	0.0	186.9	186.7	-4.99	-4.72			4.938	5.079	-10.06	-5.34	1357	34.4357802	-118.6497777	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24019	10/6/2026 8:40:00 AM					2040																	AtmAA
CV-24019	10/6/2026 8:40:00 AM						147100																AtmAA; [User entered 14.71%]
CV-24019	10/13/2026 9:19:02 AM	8.5	70.0	1.8	19.7			0.1	10.9	185.7	185.9	-8.09	-7.75			8.650	8.290	-13.80	-6.05	1343	34.4357677	-118.6497812	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24019	10/13/2026 9:20:00 AM					2090																	AtmAA
CV-24019	10/20/2026 8:38:10 AM	2.0	84.5	0.0	13.5			0.0	0.0	157.4	157.8	-5.77	-5.42			5.815	5.641	-11.12	-5.7	1359	34.4357703	-118.6497688	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24019	10/20/2026 8:47:00 AM					2150																	AtmAA
CV-24019	10/28/2026 2:00:00 PM					1310																	AtmAA
CV-24019	10/28/2026 2:19:39 PM	8.0	60.6	5.6	25.8			0.1	4.6	175.6	180.5	-2.57	-0.94			2.576	0.928	-9.16	-8.22	1362	34.4357594	-118.6497524	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24019	10/28/2026 2:23:25 PM	8.3	71.3	2.5	17.9			0.1	7.2	182.3	181.5	-0.69	-0.59			0.710	0.618	-9.76	-9.17	1362	34.4357650	-118.6497630	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24020	10/1/2026 10:18:21 AM	0.2	0.4	18.7	80.7			0.5	4.3	89.3	89.2	-9.07	-8.63			9.170	8.736	-9.14	-0.51	1354	34.4359782	-118.6493603	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In);Well Comment:Pump is not cycling;Well Condition:Pnumatic Pump Installed
CV-24020	10/1/2026 10:19:12 AM	0.2	0.5	18.6	80.7			0.4	4.3	89.6	89.5	-8.96	-9.07			8.947	9.025	-8.90	0.17	1353	34.4359988	-118.6493642	
CV-24020	10/27/2026 1:43:02 PM	3.3	11.1	19.0	66.6			0.3	3.5	80.9	82.0	-12.87	-11.48	69.6	65.7	12.966	11.511	-13.17	-1.69	1344	34.4359673	-118.6493675	Valve Adjustment:High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24021	10/12/2026 10:03:14 AM	0.0	4.3	18.6	77.1			0.0	4.1	77.1	77.6	-12.05	-11.80			11.888	11.778	-11.96	-0.16	1358	34.4361602	-118.6490508	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump
CV-24021	10/12/2026 10:04:11 AM	0.0	2.2	18.9	78.9			0.0	4.2	77.0	76.8	-11.91	-11.93			11.826	11.846	-11.88	0.05	1356	34.4361630	-118.6490522	

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24021	10/19/2026 10:03:05 AM	0.0	3.9	19.3	76.8			0.0	4.0	85.3	84.7	-10.68	-10.59			10.805	10.706	-10.64	-0.05	1358	34.4361407	-118.6490242	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In);Well Comment:No pump
CV-24021	10/19/2026 10:04:00 AM	0.0	2.0	19.5	78.5			0.0	4.0	85.0	85.1	-10.57	-10.57			10.736	10.728	-10.51	0.06	1353	34.4361538	-118.6490523	
CV-24022-F	10/5/2026 10:05:37 AM	14.5	70.3	0.0	15.2			0.2	0.0	195.0	195.3	-6.48	-6.28			7.005	6.806	-6.77	-0.49	1368	34.4365143	-118.6488160	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24022-F	10/5/2026 10:15:00 AM					1820																	AtmAA
CV-24022-F	10/5/2026 10:15:00 AM						204100																AtmAA; [User entered 20.41%]
CV-24022-F	10/12/2026 9:05:55 AM	6.7	72.5	0.0	20.8			0.1	0.0	194.6	194.6	-9.02	-8.64			9.275	8.916	-9.96	-1.32	1353	34.4365030	-118.6487995	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24022-F	10/12/2026 9:10:00 AM					1830																	AtmAA
CV-24022-F	10/19/2026 10:17:11 AM	8.6	20.1	11.8	59.5			0.4	5.0	193.6	193.0	-4.37	-8.30			4.376	8.610	-8.27	0.03	1367	34.4365070	-118.6488078	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24022-F	10/19/2026 10:20:24 AM	17.5	64.7	2.9	14.9			0.3	5.1	193.1	192.9	-7.49	-7.36			7.790	7.734	-8.00	-0.64	1377	34.4364918	-118.6487968	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24022-F	10/26/2026 9:15:47 AM	2.4	71.9	0.1	25.6			0.0	256.0	194.8	194.8	-5.39	-5.35			5.535	5.496	-5.35	0	1378	34.4365128	-118.6487942	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24022-F	10/26/2026 9:20:00 AM					2660																	AtmAA
CV-24023	10/5/2026 9:56:28 AM	17.3	65.3	0.0	17.4			0.3	0.0	196.0	100.4	-5.82	-5.73			6.302	6.177	-6.05	-0.32	1378	34.4365830	-118.6484418	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24023	10/5/2026 10:00:00 AM					1570																	AtmAA
CV-24023	10/5/2026 10:00:00 AM						219900																AtmAA; [User entered 21.99%]
CV-24023	10/12/2026 8:57:52 AM	6.3	72.5	0.0	21.2			0.1	0.0	196.0	84.9	-6.91	-6.66			7.102	6.993	-7.16	-0.5	1357	34.4365777	-118.6484385	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24023	10/12/2026 9:00:00 AM					1420																	AtmAA
CV-24023	10/19/2026 9:13:32 AM	13.1	75.4	0.3	11.2			0.2	37.3	73.4	70.5	-7.02	-7.00			7.209	7.151	-6.92	0.08	1358	34.4365767	-118.6484285	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24024-F	10/12/2026 8:40:20 AM	4.0	74.4	0.4	21.2			0.1	53.0	119.4	120.0	-6.86	-6.66			7.052	6.939	-8.35	-1.69	1352	34.4367917	-118.6481581	Valve Adjustment:No Flow Measurement
CV-24024-F	10/26/2026 9:52:59 AM	1.3	71.6	1.5	25.6			0.0	17.1	126.1	126.5	-6.82	-6.85			7.091	7.167	-7.45	-0.6	1348	34.4367897	-118.6481470	
CV-24025	10/6/2026 8:48:11 AM	4.9	73.0	0.1	22.0			0.1	220.0	175.0	175.3	-4.65	-4.59			4.602	4.551	-6.98	-2.39	1351	34.4352726	-118.6499583	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24025	10/6/2026 8:55:00 AM					1600																	AtmAA
CV-24025	10/6/2026 8:55:00 AM						95800																AtmAA; [User entered 9.58%]
CV-24025	10/13/2026 9:30:00 AM					1400																	AtmAA
CV-24025	10/13/2026 9:30:25 AM	9.9	38.9	0.8	50.4			0.3	63.0	171.3	171.3	-7.02	-6.82			7.563	7.537	-9.65	-2.83	1351	34.4352769	-118.6499522	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24025	10/20/2026 9:15:32 AM	2.3	56.1	0.4	41.2			0.0	103.0	166.9	150.1	-6.05	-5.95			6.112	6.017	-7.81	-1.86	1362	34.4352758	-118.6499472	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24025	10/20/2026 9:20:00 AM					1220																	AtmAA
CV-24025	10/27/2026 1:06:00 PM					1070																	AtmAA
CV-24025	10/27/2026 1:07:19 PM	7.6	39.7	1.0	51.7			0.2	51.7	159.9	161.1	-9.35	-9.31			9.164	9.087	1.34	10.65	1363	34.4352633	-118.6499468	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24025	10/27/2026 1:11:31 PM	6.3	41.3	0.4	52.0			0.2	130.0	164.1	164.1	-7.53	-7.32			7.344	7.279	-9.00	-1.68	1364	34.4352673	-118.6499348	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24026	10/6/2026 8:33:11 AM	3.2	69.4	0.0	27.4			0.0	0.0	185.6	184.9	-5.05	-4.72			5.297	5.043	-7.33	-2.61	1348	34.4356357	-118.6493168	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24026	10/6/2026 8:35:00 AM					1810																	AtmAA
CV-24026	10/6/2026 8:35:00 AM						185900																AtmAA; [User entered 18.59%]
CV-24026	10/13/2026 9:15:00 AM					1830																	AtmAA
CV-24026	10/13/2026 9:15:01 AM	4.5	72.4	0.1	23.0			0.1	230.0	183.1	184.3	-8.08	-7.86			8.658	8.429	-13.57	-5.71	1341	34.4356417	-118.6492942	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24026	10/14/2026 2:03:56 PM	1.1	84.4	0.0	14.5			0.0	0.0	179.4	179.7	-7.35	-7.31			7.406	7.344	-10.53	-3.22	1344	34.4356532	-118.6492787	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24026	10/14/2026 2:05:14 PM	0.9	84.7	0.0	14.4			0.0	0.0	180.0	179.2	-7.10	-7.12			7.122	7.140	-10.42	-3.3	1339	34.4356545	-118.6492977	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24026	10/20/2026 8:47:29 AM	3.5	74.9	0.0	21.6			0.0	0.0	169.0	169.5	-7.05	-6.91			7.157	7.071	-8.80	-1.89	1352	34.4356617	-118.6492728	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24026	10/20/2026 8:57:00 AM					2300																	AtmAA
CV-24026	10/27/2026 8:03:10 AM	1.0	70.7	1.3	7.1		19.9	0.0	5.5	183.7	183.6	-9.80	-9.47			9.852	9.725	-6.39	3.08	1347	34.4356590	-118.6492655	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24026	10/27/2026 8:10:00 AM					1730																	AtmAA
CV-24027	10/12/2026 10:23:27 AM	1.4	73.3	1.8	23.5			0.0	13.1	148.7	142.1	-12.10	-5.52			12.020	5.390	-12.08	-6.56	1355	34.4361162	-118.6487305	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Comment:Pump now working
CV-24027	10/12/2026 10:25:25 AM	1.4	78.9	0.0	19.7			0.0	0.0	142.6	142.9	-6.04	-6.00			6.030	5.975	-12.21	-6.21	1352	34.4361358	-118.6487270	
CV-24027	10/19/2026 9:53:44 AM	1.1	74.7	1.2	23.0			0.0	19.2	106.6	105.8	-10.20	-10.20			10.355	10.325	-10.85	-0.65	1346	34.4361013	-118.6487250	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In);Well Comment:Pneumatic pump not working;Well Condition:Pnumatic Pump Installed
CV-24028	10/5/2026 10:09:40 AM	15.3	69.7	0.0	15.0			0.2	0.0	196.0	196.2	-9.53	-9.44			10.171	10.050	-9.82	-0.38	1368	34.4363487	-118.6484808	Valve Adjustment:No Flow Measurement,High Temp
CV-24028	10/5/2026 10:20:00 AM					1060																	AtmAA
CV-24028	10/5/2026 10:20:00 AM						193900																AtmAA; [User entered 19.39%]
CV-24028	10/12/2026 9:10:41 AM	8.9	74.4	0.0	16.7			0.1	0.0	193.8	193.2	-11.71	-11.67			12.087	12.181	-12.37	-0.7	1352	34.4363445	-118.6484793	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24028	10/12/2026 9:15:00 AM					1090																	AtmAA
CV-24028	10/19/2026 10:27:10 AM	21.7	67.4	2.8	8.1			0.3	2.9	192.1	192.6	-9.17	-9.11			9.477	9.391	-9.91	-0.8	1359	34.4363425	-118.6484845	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24028	10/26/2026 9:19:05 AM	2.3	73.6	0.0	24.1			0.0	0.0	192.6	192.2	-9.83	-9.60			9.993	9.959	-9.73	-0.13	1365	34.4363485	-118.6484540	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24028	10/26/2026 9:30:00 AM					1010																	AtmAA
CV-24029	10/13/2026 1:30:27 PM	0.0	1.6	19.9	78.5			0.0	3.9	85.4	85.5	-12.30	-12.38	23.8	23.9	12.189	12.305	-12.11	0.27	1352	34.4364430	-118.6480605	Valve Adjustment:NSPS/EG CAI,High O2
CV-24029	10/13/2026 1:31:38 PM	0.0	1.7	19.9	78.4			0.0	3.9	85.6	85.7	-12.20	-12.28	23.8	23.8	12.125	12.167	-12.09	0.19	1357	34.4364432	-118.6480622	Valve Adjustment:NSPS/EG CAI,High O2
CV-24029	10/26/2026 8:42:58 AM	0.0	1.6	21.2	77.2			0.0	3.6	69.3	69.6	-8.96	-8.94			9.165	9.138	-8.85	0.09	1365	34.4364557	-118.6480623	Valve Adjustment:NSPS/EG CAI,High O2
CV-24029	10/26/2026 8:45:48 AM	0.0	1.0	21.2	77.8			0.0	3.7	71.7	70.4	-9.08	-9.08			9.272	9.300	-8.89	0.19	1371	34.4364472	-118.6479758	Valve Adjustment:NSPS/EG CAI,High O2
CV-24030	10/5/2026 9:25:00 AM					1700																	AtmAA
CV-24030	10/5/2026 9:25:00 AM						161900																AtmAA; [User entered 16.19%]
CV-24030	10/5/2026 9:28:07 AM	9.6	75.3	0.4	14.7			0.1	36.8	188.0	94.8	-0.56	-0.50			0.606	0.425	-8.06	-7.56	1334	34.4366529	-118.6479344	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24030	10/12/2026 8:30:38 AM	3.4	68.4	2.7	25.5			0.0	9.4	189.0	58.1	-3.55	-3.38			3.584	3.404	-9.21	-5.83	1357	34.4366337	-118.6478806	Valve Adjustment:No Flow Measurement,High Temp
CV-24030	10/12/2026 8:35:00 AM					1760																	AtmAA
CV-24030	10/19/2026 8:28:51 AM	5.8	74.5	2.6	17.1			0.1	6.6	184.0	64.9	-2.64	-2.20			2.593	1.871	-8.42	-6.22	1347	34.4366518	-118.6478630	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24030	10/26/2026 8:00:00 AM					1450																	AtmAA
CV-24030	10/26/2026 8:08:42 AM	0.2	7.9	16.9	75.0			0.0	4.4	184.0	67.3	-8.09	-8.04			8.273	8.212	-6.38	1.66	1346	34.4366688	-118.6478717	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,High O2;Well Condition:Lorentz Pump Installed
CV-24030	10/26/2026 8:26:38 AM	1.2	44.6	9.3	44.9			0.0	4.8	184.0	69.9	-5.81	-5.72			6.039	5.794	-5.80	-0.08	1348	34.4366353	-118.6478892	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-24031	10/6/2026 9:09:18 AM	30.9	60.2	0.0	8.9			0.5	0.0	160.9	161.0	-3.17	-3.17			3.166	3.157	-10.36	-7.19	1338	34.4348833	-118.6498161	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24031	10/6/2026 9:15:00 AM					748																	AtmAA
CV-24031	10/6/2026 9:15:00 AM						75500																AtmAA; [User entered 7.55%]
CV-24031	10/13/2026 9:55:09 AM	33.7	59.3	0.0	7.0			0.6	0.0	159.7	159.7	-4.19	-4.15			4.180	4.139	-12.29	-8.14	1348	34.4348800	-118.6498126	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24031	10/13/2026 10:00:00 AM					696																	AtmAA

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24031	10/20/2026 9:22:14 AM	20.3	61.0	0.0	18.7			0.3	0.0	159.5	159.4	-3.41	-3.34			3.347	3.281	-10.75	-7.41	1351	34.4348922	-118.6498493	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24031	10/20/2026 9:30:00 AM					828																	AtmAA
CV-24031	10/27/2026 1:21:37 PM	35.6	62.4	0.2	1.8			0.6	9.0	150.8	150.8	-3.87	-3.87			3.880	3.858	-11.94	-8.07	1355	34.4348732	-118.6498372	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24031	10/27/2026 1:23:00 PM					655																	AtmAA
CV-24032	10/6/2026 9:05:15 AM	19.6	67.3	0.0	13.1			0.3	0.0	187.8	188.0	-4.93	-4.87			4.939	4.850	-6.11	-1.24	1340	34.4351052	-118.6496157	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24032	10/6/2026 9:10:00 AM					656.5																	AtmAA
CV-24032	10/6/2026 9:10:00 AM						101800																AtmAA; [User entered 10.18%]
CV-24032	10/13/2026 9:52:02 AM	29.1	61.0	0.1	9.8			0.5	98.0	187.8	187.8	-4.72	-4.72			5.394	5.391	-6.45	-1.73	1348	34.4351177	-118.6496220	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24032	10/13/2026 9:55:00 AM					838																	AtmAA
CV-24032	10/20/2026 9:18:30 AM	7.2	52.7	0.1	40.0			0.1	400.0	157.8	158.2	-5.60	-5.37			5.717	5.596	-6.45	-1.08	1350	34.4350932	-118.6496392	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24032	10/20/2026 9:25:00 AM					913																	AtmAA
CV-24032	10/27/2026 1:17:28 PM	18.9	56.9	0.1	24.1			0.3	241.0	180.4	180.4	-4.50	-4.38			4.478	4.297	-4.95	-0.57	1346	34.4350978	-118.6496215	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24032	10/27/2026 1:18:00 PM					871																	AtmAA
CV-24033	10/6/2026 8:55:22 AM	6.2	74.0	0.0	19.8			0.1	0.0	196.0	196.0	-5.05	-4.99			5.243	5.247	-6.19	-1.2	1349	34.4353149	-118.6495093	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24033	10/6/2026 9:00:00 AM					1920																	AtmAA
CV-24033	10/6/2026 9:00:00 AM						174800																AtmAA; [User entered 17.48%]
CV-24033	10/13/2026 9:43:49 AM	7.4	72.4	0.0	20.2			0.1	0.0	195.4	194.9	-5.14	-5.10			5.787	5.787	-6.27	-1.17	1341	34.4353394	-118.6494553	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24033	10/13/2026 9:45:00 AM					2210																	AtmAA
CV-24033	10/20/2026 9:01:07 AM	1.6	83.8	0.2	14.4			0.0	72.0	178.3	179.5	-6.35	-6.21			6.397	6.318	-6.42	-0.21	1344	34.4353260	-118.6494727	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24033	10/20/2026 9:08:00 AM					1990																	AtmAA
CV-24033	10/27/2026 9:33:42 AM	3.3	79.5	0.6	16.6			0.0	27.7	191.2	191.4	-4.96	-4.95			4.972	4.979	-4.57	0.38	1340	34.4353325	-118.6494565	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24033	10/27/2026 9:36:00 AM					364																	AtmAA
CV-24034	10/5/2026 10:20:55 AM	22.9	73.3	0.5	3.3			0.3	6.6	192.3	192.4	-8.76	-8.64			9.224	9.252	-9.18	-0.54	1347	34.4361115	-118.6481385	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24034	10/5/2026 10:25:00 AM					1220																	AtmAA
CV-24034	10/5/2026 10:25:00 AM						160300																AtmAA; [User entered 16.03%]
CV-24034	10/12/2026 9:14:51 AM	9.1	77.4	0.5	13.0			0.1	26.0	178.8	176.7	-11.33	-11.20			11.680	11.604	-12.25	-1.05	1346	34.4360931	-118.6481343	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24034	10/12/2026 9:20:00 AM					1220																	AtmAA
CV-24034	10/19/2026 10:33:39 AM	23.1	75.5	0.7	0.7			0.3	1.0	158.3	158.2	-8.90	-8.90			9.237	9.192	-9.01	-0.11	1343	34.4361173	-118.6481330	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24034	10/26/2026 9:23:11 AM	2.7	76.7	0.2	20.4			0.0	102.0	163.6	163.2	-10.06	-9.76			10.204	9.932	-8.74	1.02	1355	34.4361138	-118.6481187	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24034	10/26/2026 9:35:00 AM					960																	AtmAA
CV-24035-F	10/5/2026 9:01:20 AM	3.0	79.9	0.1	17.0			0.0	170.0	190.7	189.8	-6.57	-6.60			6.818	6.848	-8.97	-2.37	1356	34.4363825	-118.6476899	Valve Adjustment:No Flow Measurement,High Temp
CV-24035-F	10/5/2026 9:05:00 AM					1780																	AtmAA
CV-24035-F	10/5/2026 9:05:00 AM						160250																AtmAA; [User entered 16.025%]
CV-24035-F	10/12/2026 8:12:51 AM	2.1	83.3	0.2	14.4			0.0	72.0	177.4	176.7	-8.04	-8.03			8.122	8.107	-9.66	-1.63	1334	34.4363888	-118.6477247	Valve Adjustment:No Flow Measurement,High Temp
CV-24035-F	10/12/2026 8:15:00 AM					1280																	AtmAA
CV-24035-F	10/19/2026 7:53:03 AM	1.9	86.8	0.5	10.8			0.0	21.6	154.2	154.2	-9.04	-8.78			8.856	8.659	-8.87	-0.09	1359	34.4363812	-118.6477022	Valve Adjustment:No Flow Measurement,High Temp
CV-24035-F	10/26/2026 7:34:51 AM	1.0	74.7	0.2	24.1			0.0	120.5	167.6	168.5	-7.72	-6.48			7.869	6.673	-5.37	1.11	1363	34.4363873	-118.6477213	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24035-F	10/26/2026 7:40:00 AM					2590																	AtmAA

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24036	10/1/2026 2:38:36 PM	43.7	31.3	2.9	22.1			1.4	7.6	95.4	95.4	-0.83	-0.81			0.000	0.000	-7.77	-6.96	1326	34.4344837	-118.6497002	
CV-24036	10/1/2026 2:41:30 PM	43.9	32.3	2.5	21.3			1.4	8.5	112.1	112.2	-7.93	-7.97			8.027	8.027	-7.74	0.23	1324	34.4344327	-118.6497067	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In)
CV-24036	10/13/2026 10:01:17 AM	64.1	33.3	2.6	0.0			1.9	0.0	90.9	90.7	-11.91	-11.69	15.5	15.4	12.709	12.435	-12.87	-1.18	1343	34.4344459	-118.6497195	Valve Adjustment:No Flow Measurement;Well Condition:Lorentz Pump Installed
CV-24036	10/27/2026 1:18:30 PM	52.8	38.9	1.5	6.8			1.4	4.5	96.2	97.3	-12.36	-12.15			12.319	12.226	-12.19	-0.04	1335	34.4344287	-118.6497123	Valve Adjustment:Valve 100% Open
CV-24037	10/14/2026 9:22:40 AM	27.7	62.4	0.5	9.4			0.4	18.8	140.4	139.3	-10.20	-5.04			10.494	5.448	-10.46	-5.42	1347	34.4347343	-118.6494167	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24037	10/14/2026 9:23:32 AM	25.1	63.8	0.3	10.8			0.4	36.0	139.9	140.5	-4.70	-4.99			5.111	4.984	-10.37	-5.38	1335	34.4347388	-118.6494270	Valve Adjustment:High Temp
CV-24037	10/27/2026 1:25:03 PM	22.5	67.1	0.1	10.3			0.3	103.0	142.5	143.1	-3.89	-1.50			3.878	1.484	-10.64	-9.14	1337	34.4347253	-118.6494467	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open
CV-24038	10/6/2026 9:21:55 AM	15.0	73.3	0.0	11.7			0.2	0.0	197.8	197.8	-4.20	-4.14			4.172	4.117	-10.25	-6.11	1341	34.4350108	-118.6488846	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24038	10/6/2026 9:45:00 AM					1800																	AtmAA
CV-24038	10/6/2026 9:45:00 AM						175200																AtmAA; [User entered 17.52%]
CV-24038	10/13/2026 10:25:00 AM					2310																	AtmAA
CV-24038	10/13/2026 10:30:34 AM	10.0	69.8	0.1	20.1			0.1	201.0	196.8	196.8	-6.40	-6.40			7.107	7.039	-12.68	-6.28	1345	34.4350161	-118.6488790	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24038	10/20/2026 9:40:09 AM	5.5	74.3	0.1	20.1			0.1	201.0	173.4	173.4	-5.11	-5.08			5.353	5.329	-11.51	-6.43	1346	34.4349932	-118.6488720	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24038	10/20/2026 9:45:00 AM					1720																	AtmAA
CV-24038	10/27/2026 1:34:48 PM	9.0	83.6	0.2	7.2			0.1	36.0	190.8	190.7	-9.16	-9.08			9.201	9.191	-14.74	-5.66	1340	34.4349813	-118.6488955	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24038	10/27/2026 1:35:00 PM					1270																	AtmAA
CV-24039	10/14/2026 10:03:24 AM	0.0	1.5	15.5	83.0			0.0	5.4	87.6	88.3	-12.53	-12.40			12.299	12.397	-12.30	0.1	1340	34.4352898	-118.6486623	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24039	10/29/2026 9:06:21 AM	0.2	76.6	0.5	22.7			0.0	45.4	145.2	161.0	-12.49	-12.19			12.738	12.554	-14.51	-2.32	1353	34.4352855	-118.6486837	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
CV-24039	10/29/2026 9:09:35 AM	0.2	59.6	0.1	40.1			0.0	401.0	168.8	170.9	-12.23	-9.08			12.589	9.432	-14.48	-5.4	1346	34.4352822	-118.6486853	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
CV-24039	10/29/2026 9:24:00 AM					1960																	AtmAA
CV-24040	10/12/2026 9:48:38 AM	0.4	10.9	17.1	71.6			0.0	4.2	77.6	78.1	-13.74	-13.59			13.869	13.777	-13.74	-0.15	1351	34.4356277	-118.6483878	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Comment:Pump not on
CV-24040	10/12/2026 9:49:30 AM	0.3	10.4	17.4	71.9			0.0	4.1	79.2	79.0	-13.53	-13.48			13.765	13.655	-13.81	-0.33	1351	34.4356298	-118.6483895	
CV-24040	10/19/2026 9:45:24 AM	0.0	12.9	16.7	70.4			0.0	4.2	81.5	82.6	-10.87	-10.84			10.999	10.906	-10.96	-0.12	1342	34.4356363	-118.6483980	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In);Well Comment:Lorentz not working:Well Condition:Lorentz Pump Installed
CV-24040	10/19/2026 9:46:19 AM	0.0	12.9	16.8	70.3			0.0	4.2	79.7	79.6	-11.00	-10.87			11.110	11.056	-11.17	-0.3	1350	34.4356317	-118.6483480	
CV-24041	10/12/2026 10:39:21 AM	2.3	69.5	1.4	26.8			0.0	19.1	104.1	103.1	-10.73	-10.37			10.738	10.406	-10.82	-0.45	1355	34.4358593	-118.6480405	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Well (Watered In);Well Comment:Pump is shut off
CV-24041	10/28/2026 2:08:25 PM	0.8	76.3	2.1	20.8			0.0	9.9	188.8	189.8	-9.23	-5.46			9.313	5.514	-11.73	-6.27	1351	34.4358580	-118.6480325	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In);Well Condition:Pnumatic Pump Installed
CV-24041	10/28/2026 2:11:24 PM	1.0	74.8	1.2	23.0			0.0	19.2	190.6	190.8	-6.75	-6.68			6.835	6.754	-11.61	-4.93	1348	34.4358708	-118.6480425	
CV-24042	10/5/2026 10:26:57 AM	26.7	69.2	0.0	4.1			0.4	0.0	179.4	178.7	-8.69	-8.50			9.334	9.054	-9.54	-1.04	1366	34.4362412	-118.6474735	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24042	10/5/2026 10:30:00 AM					1670																	AtmAA
CV-24042	10/5/2026 10:30:00 AM						127800																AtmAA; [User entered 12.78%]

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24042	10/12/2026 9:25:52 AM	16.4	73.7	0.1	9.8			0.2	98.0	176.5	182.4	-14.03	-13.52			14.413	13.964	-14.91	-1.39	1355	34.4362343	-118.6474632	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24042	10/12/2026 9:30:00 AM					1110																	AtmAA
CV-24042	10/21/2026 10:25:01 AM	11.2	70.5	0.3	18.0			0.2	60.0	179.7	178.5	-7.06	-6.91			7.133	7.017	-6.73	0.18	1379	34.4362488	-118.6474547	Valve Adjustment:No Flow Measurement,High Temp
CV-24042	10/21/2026 10:30:00 AM					1000																	AtmAA
CV-24042	10/29/2026 9:44:29 AM	27.3	42.8	0.0	29.9			0.6	0.0	173.9	179.2	-12.05	-11.83			12.220	11.926	-12.60	-0.77	1372	34.4362488	-118.6474630	Valve Adjustment:No Flow Measurement,High Temp
CV-24042	10/29/2026 9:47:00 AM					1540																	AtmAA
CV-24043	10/14/2026 1:47:12 PM	40.8	53.1	0.0	6.1			0.8	0.0	123.9	124.5	-6.05	-5.94			5.921	5.965	-6.47	-0.53	1334	34.4341020	-118.6497205	Valve Adjustment:Decreased Flow/Vacuum
CV-24043	10/23/2026 9:50:21 AM	42.1	56.5	0.0	1.4			0.7	0.0	99.7	100.2	-10.13	-10.10			10.593	10.507	-10.73	-0.63	1328	34.4340847	-118.6497070	Valve Adjustment:Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down,Plugged/Pinched Suspected
CV-24044	10/1/2026 2:44:15 PM	24.3	65.6	0.2	9.9			0.4	49.5	156.7	156.5	-2.94	-2.94			2.924	2.947	-7.20	-4.26	1325	34.4343717	-118.6493843	
CV-24044	10/6/2026 9:14:58 AM	35.8	64.2	0.0	0.0			0.6	0.0	160.8	161.0	-4.88	-4.72			5.311	5.224	-9.67	-4.95	1336	34.4343898	-118.6494009	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24044	10/6/2026 9:30:00 AM					559																	AtmAA
CV-24044	10/6/2026 9:30:00 AM						71100																AtmAA; [User entered 7.11%]
CV-24044	10/13/2026 10:07:48 AM	42.0	57.9	0.0	0.1			0.7	0.0	159.6	158.8	-8.15	-8.13			8.989	8.980	-13.26	-5.13	1340	34.4343752	-118.6494181	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24044	10/13/2026 10:10:00 AM					768																	AtmAA
CV-24044	10/20/2026 9:31:15 AM	20.3	69.2	0.0	10.5			0.3	0.0	156.2	155.7	-6.13	-6.05			6.288	6.241	-10.99	-4.94	1348	34.4343875	-118.6494082	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24044	10/20/2026 9:35:00 AM					590																	AtmAA
CV-24044	10/27/2026 1:27:37 PM	28.0	71.8	0.2	0.0			0.4	0.0	144.5	144.8	-8.05	-8.00			7.984	7.915	-11.63	-3.63	1342	34.4343812	-118.6494005	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24044	10/27/2026 1:29:00 PM					523																	AtmAA
CV-24045	10/6/2026 9:18:26 AM	32.4	67.6	0.0	0.0			0.5	0.0	192.5	192.0	-3.01	-3.00			3.003	2.985	-9.89	-6.89	1330	34.4347425	-118.6490522	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24045	10/6/2026 9:40:00 AM					1720																	AtmAA
CV-24045	10/6/2026 9:40:00 AM						165200																AtmAA; [User entered 16.52%]
CV-24045	10/13/2026 10:15:00 AM					1860																	AtmAA
CV-24045	10/13/2026 10:19:32 AM	13.7	70.8	0.5	15.0			0.2	30.0	190.1	188.9	-6.23	-6.09			6.933	6.898	-12.98	-6.89				Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24045	10/20/2026 9:36:52 AM	9.2	70.3	1.0	19.5			0.1	19.5	159.0	157.5	-11.29	-11.23			11.403	11.349	-11.18	0.05	1349	34.4347358	-118.6490812	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24045	10/20/2026 9:40:00 AM					1000																	AtmAA
CV-24045	10/28/2026 8:31:00 AM					2100																	AtmAA
CV-24045	10/28/2026 8:35:55 AM	5.8	82.9	0.4	10.9			0.1	27.3	182.8	182.2	-6.09	-6.09			6.099	6.124	-11.18	-5.09	1325	34.4347417	-118.6490777	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24046	10/6/2026 9:48:56 AM	11.0	73.7	0.0	15.3			0.1	0.0	160.6	163.5	0.50	-3.04			0.000	3.032	1.21	4.25	1338	34.4350683	-118.6483901	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-24046	10/6/2026 9:50:00 AM					2240																	AtmAA
CV-24046	10/6/2026 9:50:00 AM						238200																AtmAA; [User entered 23.82%]
CV-24046	10/6/2026 9:50:27 AM	6.4	68.7	0.0	24.9			0.1	0.0	163.7	164.1	-3.17	-3.13			3.132	3.133	-2.86	0.27	1345	34.4350811	-118.6483687	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24046	10/13/2026 10:36:36 AM	6.0	67.4	0.0	26.6			0.1	0.0	101.7	99.8	-3.93	-3.80			3.921	3.791	-3.71	0.09	1357	34.4350704	-118.6483756	Valve Adjustment:No Flow Measurement;Well Condition:Lorentz Pump Installed
CV-24046	10/28/2026 2:01:56 PM	4.0	62.6	2.5	30.9			0.1	12.4	188.7	189.6	-5.81	-2.39			5.890	2.400	-6.03	-3.64	1364	34.4350422	-118.6483772	
CV-24048	10/14/2026 10:07:06 AM	9.3	84.7	0.0	6.0			0.1	0.0	93.2	92.9	-10.62	-11.84			10.681	11.823	-12.77	-0.93	1357	34.4355578	-118.6477955	
CV-24048	10/21/2026 9:40:34 AM	9.4	73.3	1.6	15.7			0.1	9.8	74.4	75.3	-6.97	-6.79			7.095	7.088	-7.01	-0.22	1363	34.4355692	-118.6478120	Valve Adjustment:Barely Open,Plugged/Pinched Suspected
CV-24049	10/5/2026 1:54:02 PM	12.2	71.5	0.0	16.3			0.2	0.0	191.8	191.8	-3.02	-2.98			2.997	2.974	-7.74	-4.76	1380	34.4359354	-118.6471909	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24049	10/6/2026 7:45:00 AM					1500																	Air Tech Lab
CV-24049	10/6/2026 7:45:00 AM						130000																Air Tech Lab; [User entered 13%]
CV-24049	10/12/2026 9:50:41 AM	18.6	72.2	0.0	9.2			0.3	0.0	190.2	190.2	-6.95	-6.95			7.299	7.247	-13.00	-6.05	1373	34.4359270	-118.6472321	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24049	10/12/2026 9:55:00 AM					2350																	AtmAA
CV-24049	10/19/2026 2:12:04 PM	8.2	82.5	0.1	9.2			0.1	92.0	165.7	174.9	-2.32	-2.26			2.307	2.249	-8.18	-5.92	1366	34.4359557	-118.6472107	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24049	10/21/2026 9:48:34 AM	1.0	88.8	0.6	9.6			0.0	16.0	86.6	88.0	-6.62	-6.92			6.768	7.074	-6.62	0.3	1386	34.4353690	-118.6472333	Valve Adjustment:Barely Open,Plugged/Pinched Suspected;Well Condition:Lorentz Pump Installed
CV-24050	10/14/2026 1:56:37 PM	26.5	36.4	0.0	37.1			0.7	0.0	119.7	120.1	-10.78	-10.42			10.857	10.451	-11.05	-0.63	1325	34.4337228	-118.6499650	Valve Adjustment:Decreased Flow/Vacuum
CV-24050	10/23/2026 9:57:56 AM	28.8	39.4	0.0	31.8			0.7	0.0	119.2	118.9	-12.17	-12.15			12.618	12.599	-12.47	-0.32	1309	34.4337277	-118.6499713	Valve Adjustment:Valve 100% Open
CV-24051	10/14/2026 9:17:39 AM	25.4	61.5	1.4	11.7			0.4	8.4	84.3	84.0	-12.12	-11.90			12.384	12.144	-12.45	-0.55	1348	34.4344863	-118.6490048	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24051	10/28/2026 3:16:14 PM	23.0	59.5	2.7	14.8			0.4	5.5	93.1	92.9	-10.28	-9.90			10.341	10.029	-10.66	-0.76	1340	34.4344680	-118.6490077	Valve Adjustment:Decreased Flow/Vacuum
CV-24052	10/14/2026 9:55:08 AM	34.8	55.6	0.2	9.4			0.6	47.0	109.0	109.3	-5.87	-5.89			6.349	6.393	-10.28	-4.39	1361	34.4350670	-118.6480575	Valve Adjustment:Barely Open
CV-24052	10/21/2026 9:30:34 AM	36.7	53.9	0.8	8.6			0.7	10.8	90.2	90.4	-3.67	-3.69			3.736	3.704	-5.64	-1.95	1364	34.4350573	-118.6480560	Valve Adjustment:Barely Open
CV-24053	10/7/2026 7:45:00 AM					150																	Air Tech Lab
CV-24053	10/7/2026 7:45:00 AM						18000																Air Tech Lab; [User entered 1.8%]
CV-24053	10/14/2026 10:00:56 AM	24.3	43.4	0.6	31.7			0.6	52.8	98.9	99.3	-9.98	-9.83			10.399	10.324	-11.67	-1.84	1372	34.4352492	-118.6477860	
CV-24053	10/21/2026 9:35:37 AM	29.0	44.5	0.4	26.1			0.7	65.3	95.8	78.1	-6.29	-5.60			6.377	5.714	-6.97	-1.37	1362	34.4352495	-118.6477953	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24054	10/5/2026 10:39:53 AM	27.1	72.0	0.0	0.9			0.4	0.0	178.7	178.9	-9.08	-8.97			9.655	9.587	-9.66	-0.69	1381	34.4356377	-118.6471680	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24054	10/8/2026 10:49:29 AM	20.7	74.7	0.0	4.6			0.3	0.0	181.9	181.9	-5.67	-5.62			6.154	6.159	-5.98	-0.36	1389	34.4356378	-118.6471874	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24054	10/8/2026 10:50:00 AM					1690																	AtmAA
CV-24054	10/8/2026 10:50:00 AM						124300																AtmAA; [User entered 12.43%]
CV-24054	10/12/2026 9:39:55 AM	19.7	68.4	0.3	11.6			0.3	38.7	178.0	178.1	-13.69	-13.50			14.077	13.995	-14.40	-0.9	1376	34.4356301	-118.6471909	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24054	10/12/2026 9:45:00 AM					1610																	AtmAA
CV-24054	10/19/2026 1:52:27 PM	10.0	74.9	0.3	14.8			0.1	49.3	144.5	142.1	-2.33	-2.33			2.285	2.278	-9.43	-7.1	1387	34.4356423	-118.6471845	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24055	10/7/2026 9:17:41 AM	4.3	54.3	2.1	39.3			0.1	18.7	147.2	147.4	-0.48	-0.49			0.478	0.488	-7.10	-6.61	1397	34.4358747	-118.6469135	Valve Adjustment:High Temp,Barely Open,Reduce Sys. Vac. - Flare Down
CV-24055	10/8/2026 1:04:27 PM	13.6	56.7	1.8	27.9			0.2	15.5	141.4	141.5	-0.32	-0.34			0.303	0.304	-7.29	-6.95	1408	34.4358576	-118.6469167	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24055	10/8/2026 1:05:00 PM					1730																	AtmAA
CV-24055	10/13/2026 8:00:00 AM					1200																	AirTech Lab
CV-24055	10/13/2026 8:00:00 AM						58000																AirTech Lab; [User entered 5.8%]
CV-24055	10/23/2026 8:01:24 AM	2.9	32.9	6.5	57.7			0.1	8.9	148.1	147.7	-2.47	-2.48			2.466	2.481	-12.94	-10.46	1376	34.4358887	-118.6468980	Valve Adjustment:High Temp,Barely Open
CV-24055	10/26/2026 1:50:00 PM					1120																	AtmAA
CV-24055	10/26/2026 1:52:32 PM	7.1	33.0	5.4	54.5			0.2	10.1	140.5	140.5	-8.11	-7.03			8.091	7.043	-1.34	5.69	1403	34.4358885	-118.6469375	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,High O2,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-24055	10/26/2026 1:57:36 PM	6.5	38.5	4.3	50.7			0.2	11.8	149.7	149.7	-7.12	-7.07			7.095	7.017	-4.01	3.06	1407	34.4358640	-118.6469690	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-24056	10/1/2026 11:17:57 AM	21.3	40.1	0.2	38.4			0.5	192.0	126.8	127.3	-4.61	-3.71	0.0	0.0	4.537	3.660			1273	34.4332637	-118.6502377	,
CV-24056	10/27/2026 10:10:39 AM	9.9	66.5	1.1	22.5			0.1	20.5	142.2	142.1	-4.41	-4.41			4.413	4.413	-6.91	-2.5	1309	34.4332722	-118.6501570	Valve Adjustment:High Temp
CV-24057	10/1/2026 11:22:04 AM	17.8	62.3	0.0	19.9			0.3	0.0	149.1	147.9	-1.72	-0.93			0.657	0.178	-6.71	-5.78	1358	34.4334823	-118.6495673	NSPS/EG CAI,High Temp
CV-24057	10/1/2026 11:23:35 AM	18.4	62.6	0.0	19.0			0.3	0.0	144.7	144.6	-0.47	-0.46			0.199	0.200	-6.94	-6.48	1335	34.4334777	-118.6495710	NSPS/EG CAI,High Temp
CV-24057	10/20/2026 10:05:00 AM					1440																	AtmAA

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24057	10/20/2026 10:07:18 AM	14.2	70.5	0.1	15.2			0.2	152.0	149.0	149.4	-0.11	-0.11			0.000	0.000	-10.85	-10.74	1345	34.4334542	-118.6496723	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24057	10/29/2026 9:57:38 AM	15.4	53.7	0.0	30.8			0.3	0.0	147.1	147.2	-1.62	-1.60	8.4	6.1	0.203	0.105	-14.80	-13.2	1331	34.4334627	-118.6496378	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24057	10/29/2026 10:03:00 AM					1280																	AtmAA
CV-24058	10/1/2026 11:00:38 AM	23.0	34.3	0.0	42.7			0.7	0.0	115.5	116.5	-6.39	-5.71	0.0	0.0	6.504	5.742	-7.46	-1.75	1378	34.4337850	-118.6493668	,
CV-24058	10/23/2026 9:40:08 AM	17.4	31.6	0.2	50.8			0.6	254.0	109.7	110.6	-7.44	-7.43			8.026	8.001	-10.80	-3.37	1325	34.4337957	-118.6494525	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24059	10/8/2026 8:51:41 AM	6.1	79.1	0.0	14.8			0.1	0.0	160.9	160.7	-5.39	-5.39	7.6	7.2	0.172	0.153	-10.61	-5.22	1346	34.4337686	-118.6490478	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24059	10/8/2026 8:55:00 AM					906																	AtmAA
CV-24059	10/8/2026 8:55:00 AM						117900																AtmAA; [User entered 11.79%]
CV-24059	10/14/2026 2:50:51 PM	39.8	53.1	1.9	5.2			0.7	2.7	161.9	161.9	-9.77	-9.77	18.1	16.9	0.970	0.850	-17.88	-8.11				Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24059	10/14/2026 2:55:00 PM					382																	AtmAA
CV-24059	10/21/2026 8:09:59 AM	25.7	63.3	0.0	11.0			0.4	0.0	160.3	160.2	-3.31	-3.31	11.6	11.5	0.392	0.388	-10.68	-7.37	1348	34.4337456	-118.6490902	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24059	10/21/2026 8:10:00 AM					796																	AtmAA
CV-24059	10/28/2026 10:15:00 AM					514																	AtmAA
CV-24059	10/28/2026 10:15:01 AM	30.6	61.7	0.0	7.7			0.5	0.0	161.6	161.5	-5.45	-5.27	30.8	30.2	2.806	2.703	-17.05	-11.78	1352	34.4337644	-118.6490877	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24060	10/5/2026 1:35:04 PM	23.6	61.9	1.6	12.9			0.4	8.1	126.0	126.0	-4.14	-4.13			4.162	4.145	-9.48	-5.35	1366	34.4340277	-118.6487642	Valve Adjustment:Barely Open
CV-24060	10/28/2026 3:26:43 PM	23.4	55.3	2.1	19.2			0.4	9.1	122.0	122.0	-8.82	-1.35			8.975	1.341	-17.21	-15.86	1333	34.4340238	-118.6487863	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24061	10/5/2026 9:20:09 AM	29.9	70.1	0.0	0.0			0.4	0.0	138.6	138.6	-0.84	-1.44			0.837	1.448	-10.71	-9.27	1366	34.4343322	-118.6486125	Valve Adjustment:No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24061	10/5/2026 9:21:00 AM	29.7	70.3	0.0	0.0			0.4	0.0	138.5	138.6	-1.55	-1.56			1.555	1.536	-10.49	-8.93	1363	34.4343512	-118.6486278	Valve Adjustment:No Flow Measurement;Well Condition:Lorentz Pump Installed
CV-24061	10/8/2026 1:16:49 PM	32.4	65.9	0.0	1.7			0.5	0.0	145.0	144.2	0.13	0.13			0.000	0.000	-6.76	-6.89	1365	34.4343394	-118.6486369	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24061	10/8/2026 1:17:00 PM					644.5																	AtmAA
CV-24061	10/8/2026 1:17:00 PM						82400																AtmAA; [User entered 8.24%]
CV-24061	10/9/2026 2:29:59 PM	37.6	57.3	0.0	5.1			0.7	0.0	144.3	142.9	-0.81	-0.81			0.789	0.780	-8.91	-8.1	1348	34.4343300	-118.6486314	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24061	10/28/2026 3:10:53 PM	27.6	63.5	0.0	8.9			0.4	0.0	130.7	128.4	-2.33	-0.80			2.319	0.785	-10.93	-10.13	1344	34.4343515	-118.6486243	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24062	10/7/2026 7:25:00 AM					720																	Air Tech Lab
CV-24062	10/7/2026 7:25:00 AM						100000																Air Tech Lab; [User entered 10%]
CV-24062	10/7/2026 1:40:00 PM					1010																	AtmAA
CV-24062	10/7/2026 1:40:00 PM						86900																AtmAA; [User entered 8.69%]
CV-24062	10/7/2026 1:46:54 PM	36.5	63.4	0.0	0.1			0.6	0.0	179.2	179.8	-3.83	-3.79			3.829	3.779	-4.83	-1.04	1358	34.4345908	-118.6481121	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	10/14/2026 1:50:00 PM					773.5																	AtmAA
CV-24062	10/14/2026 1:54:36 PM	38.7	61.2	0.1	0.0			0.6	0.0	178.8	178.3	-9.98	-9.77			10.150	9.896	-11.75	-1.98	1392	34.4347840	-118.6474829	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	10/20/2026 1:50:00 PM					1210																	AtmAA
CV-24062	10/20/2026 1:53:31 PM	26.7	64.8	0.0	8.5			0.4	0.0	171.9	171.8	-6.63	-6.60			6.785	6.824	-7.71	-1.11	1361	34.4345402	-118.6480944	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	10/27/2026 1:28:50 PM	24.4	71.6	0.0	4.0			0.3	0.0	173.0	173.2	-9.44	-9.44			9.636	9.615	-11.64	-2.2	1354	34.4345748	-118.6480889	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24062	10/27/2026 1:35:00 PM					418																	AtmAA
CV-24063	10/7/2026 7:20:00 AM					1000																	Air Tech Lab
CV-24063	10/7/2026 7:20:00 AM						84000																Air Tech Lab; [User entered 8.4%]
CV-24063	10/14/2026 11:04:24 AM	11.9	76.6	0.0	11.5			0.2	0.0	172.9	174.2	-10.41	-10.56			10.525	10.651	-11.27	-0.71	1357	34.4349425	-118.6475325	
CV-24063	10/15/2026 2:00:00 PM					2200																	AtmAA
CV-24063	10/15/2026 2:00:03 PM	20.7	74.9	0.1	4.3			0.3	43.0	164.1	163.8	-3.53	-3.37			3.222	3.428	-4.00	-0.63	1371	34.4349290	-118.6475112	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24063	10/20/2026 8:25:00 AM					2170																	AtmAA
CV-24063	10/20/2026 8:28:54 AM	8.4	68.0	3.5	20.1			0.1	5.7	160.1	160.1	-6.94	-6.91			6.976	6.943	-9.45	-2.54	1338	34.4349407	-118.6475349	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24063	10/29/2026 9:05:28 AM	14.4	78.5	0.0	7.0			0.2	0.0	180.9	180.9	-13.65	-13.52			13.897	13.611	-12.77	0.75	1367	34.4349508	-118.6475065	Valve Adjustment:No Flow Measurement,High O2;Well Condition:Lorentz Pump Installed
CV-24063	10/29/2026 9:11:00 AM					1575																	AtmAA
CV-24064-F	10/7/2026 7:30:00 AM					1600																	Air Tech Lab
CV-24064-F	10/7/2026 7:30:00 AM						130000																Air Tech Lab; [User entered 13%]
CV-24064-F	10/7/2026 1:27:02 PM	16.4	81.5	0.1	2.0			0.2	20.0	191.2	191.1	-4.92	-4.54			4.749	4.570	-5.68	-1.14	1369	34.4352363	-118.6471818	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-F	10/7/2026 1:30:00 PM					1820																	AtmAA
CV-24064-F	10/7/2026 1:30:00 PM						99100																AtmAA; [User entered 9.91%]
CV-24064-F	10/14/2026 10:31:46 AM	42.2	57.8	0.0	0.0			0.7	0.0	190.2	190.2	-10.53	-10.11			10.986	10.594	-11.89	-1.78	1370	34.4352258	-118.6471772	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-F	10/14/2026 10:35:00 AM					2400																	AtmAA
CV-24064-F	10/20/2026 1:06:11 PM	15.9	70.4	0.0	13.7			0.2	0.0	189.8	190.6	-7.91	-7.58			8.071	7.637	-8.68	-1.1	1389	34.4352065	-118.6471550	Valve Adjustment:No Flow Measurement,High Temp
CV-24064-F	10/20/2026 1:10:00 PM					2330																	AtmAA
CV-24064-F	10/27/2026 9:32:00 AM					1370																	AtmAA
CV-24064-F	10/27/2026 9:32:22 AM	6.5	82.2	0.0	11.3			0.1	0.0	191.7	191.4	-5.79	-5.73			6.286	6.313	-12.40	-6.67	1365	34.4352240	-118.6471637	Valve Adjustment:No Flow Measurement,High Temp
CV-24065-T	10/7/2026 9:03:42 AM	9.1	42.6	1.4	46.9			0.2	33.5	123.0	123.1	-3.46	-3.51			3.454	3.493	-7.67	-4.16	1387	34.4356232	-118.6467870	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24065-T	10/13/2026 8:20:00 AM					390																	AirTech Lab
CV-24065-T	10/13/2026 8:20:00 AM						22000																AirTech Lab; [User entered 2.2%]
CV-24065-T	10/23/2026 7:50:35 AM	11.0	40.6	2.4	46.0			0.3	19.2	120.2	120.4	-6.26	-6.26			6.720	6.730	-13.22	-6.96	1389	34.4356337	-118.6468187	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24066	10/1/2026 11:46:06 AM	14.1	41.1	0.0	44.8			0.3	0.0	113.7	113.8	-1.21	-1.18	0.0	0.0	1.181	1.176	-7.95	-6.77	1345	34.4329975	-118.6497830	,
CV-24066	10/12/2026 8:58:00 AM					140																	Air Tech Lab
CV-24066	10/12/2026 8:58:00 AM						18000																Air Tech Lab; [User entered 1.8%]
CV-24066	10/27/2026 10:07:03 AM	16.8	39.1	0.1	44.0			0.4	440.0	112.4	112.7	-1.61	-1.61			1.606	1.628	-2.02	-0.41	1311	34.4329933	-118.6498095	Valve Adjustment:Barely Open
CV-24066	10/27/2026 10:07:36 AM	18.8	42.5	0.2	38.5			0.4	192.5	113.8	114.0	-1.61	-1.61			1.602	1.599	-11.87	-10.26	1316	34.4330003	-118.6498018	Valve Adjustment:Barely Open
CV-24067	10/5/2026 9:50:00 AM					1510																	AtmAA
CV-24067	10/5/2026 9:50:00 AM						37900																AtmAA; [User entered 3.79%]
CV-24067	10/5/2026 9:52:19 AM	18.2	37.3	0.0	44.5			0.5	0.0	154.8	154.1	-4.73	-3.30			0.000	0.000	-6.10	-2.8	1332	34.4331765	-118.6497242	Valve Adjustment:High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24067	10/5/2026 9:53:08 AM	19.3	45.4	0.0	35.3			0.4	0.0	153.9	153.8	-3.49	-3.27			0.000	0.000	-6.69	-3.42	1327	34.4331795	-118.6497305	Well Condition:Lorentz Pump Installed
CV-24067	10/12/2026 1:47:14 PM	17.6	60.6	0.0	21.8			0.3	0.0	162.2	162.1	-3.53	-3.49			0.159	0.089	-7.53	-4.04	1333	34.4331705	-118.6497558	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-24067	10/12/2026 1:48:00 PM					1890																	AtmAA
CV-24067	10/20/2026 10:37:20 AM	1.7	84.6	0.0	13.7			0.0	0.0	155.2	153.9	0.72	0.89	6.3	6.0	0.112	0.104	1.18	0.29	1318	34.4331943	-118.6497365	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.
CV-24067	10/20/2026 1:02:55 PM	0.1	79.5	0.1	20.3			0.0	203.0	124.3	123.9	0.77	0.78	2.9	3.0	0.022	0.025	-1.02	-1.8	1338	34.4331780	-118.6497257	Valve Adjustment:NSPS/EG CAI,Positive Static Press.
CV-24067	10/20/2026 1:10:22 PM	0.1	79.0	0.0	20.9			0.0	0.0	125.9	134.5	-0.67	-0.68	3.3	2.6	0.029	0.019	-1.57	-0.89	1328	34.4331892	-118.6497325	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24067	10/21/2026 10:08:23 AM	0.9	85.9	0.0	13.2			0.0	0.0	136.7	137.1	0.40	0.27			0.153	0.039	0.50	0.23	1339	34.4332014	-118.6497393	Valve Adjustment:Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24068	10/1/2026 10:49:56 AM	22.5	39.9	0.1	37.5			0.6	375.0	129.1	129.5	-4.57	-4.59	0.0	0.0	4.670	4.666	-5.97	-1.38	1332	34.4331862	-118.6488587	,
CV-24068	10/28/2026 3:36:18 PM	21.8	38.3	0.3	39.6			0.6	132.0	138.7	138.6	-8.21	-5.43			8.270	5.366	-12.37	-6.94	1331	34.4332332	-118.6493393	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24069	10/5/2026 10:11:52 AM	10.2	42.9	0.6	46.3			0.2	77.2	129.2	129.0	-1.48	-1.48			1.455	1.449	-11.45	-9.97	1343	34.4333995	-118.6489268	Valve Adjustment:Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-24069	10/13/2026 7:25:00 AM					540																	AirTech Lab
CV-24069	10/13/2026 7:25:00 AM						43000																AirTech Lab; [User entered 4.3%]
CV-24069	10/20/2026 10:13:43 AM	9.7	46.6	0.6	43.1			0.2	71.8	121.6	120.6	-1.44	-1.45			1.429	1.435	-12.92	-11.47	1355	34.4334203	-118.6489493	Valve Adjustment:Barely Open
CV-24070	10/7/2026 7:55:00 AM					830																	Air Tech Lab
CV-24070	10/7/2026 7:55:00 AM						63000																Air Tech Lab; [User entered 6.3%]

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24070	10/13/2026 8:28:43 AM	41.7	50.5	0.0	7.8			0.8	0.0	137.5	135.7	-14.47	-9.06	25.8	14.3	4.590	1.365	-18.36	-9.3	1349	34.4336972	-118.6487070	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24070	10/13/2026 8:31:35 AM	34.8	54.6	0.0	10.7			0.6	0.0	136.8	136.5	-11.75	-11.75	20.5	20.4	2.843	2.811	-18.72	-6.97	1351	34.4337005	-118.6487097	Valve Adjustment:High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24070	10/13/2026 8:32:52 AM	38.2	53.5	0.0	8.3			0.7	0.0	136.5	136.4	-11.67	-11.67	20.5	20.4	2.843	2.835	-18.90	-7.23	1355	34.4336922	-118.6487155	Valve Adjustment:High Temp
CV-24070	10/28/2026 3:30:21 PM	34.1	59.1	0.1	6.7			0.6	67.0	141.1	141.0	-9.93	-9.99	12.0	11.9	3.278	3.190	-17.82	-7.83	1341	34.4337172	-118.6486983	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24071	10/5/2026 1:31:44 PM	31.9	60.5	0.1	7.5			0.5	75.0	135.9	135.9	-0.72	-0.72	9.2	10.8	0.558	0.757	-8.37	-7.65	1364	34.4339772	-118.6484670	Valve Adjustment:High Temp,Barely Open
CV-24071	10/13/2026 7:30:00 AM					440																	AirTech Lab
CV-24071	10/13/2026 7:30:00 AM						62000																AirTech Lab; [User entered 6.2%]
CV-24071	10/20/2026 1:36:52 PM	22.7	58.1	0.6	18.6			0.4	31.0	133.8	134.0	-0.60	-0.52	9.1	8.6	0.540	0.483	-8.68	-8.16	1363	34.4339780	-118.6484802	Valve Adjustment:High Temp,Barely Open
CV-24072	10/6/2026 9:17:31 AM	43.9	55.2	0.0	0.9			0.8	0.0	115.6	117.1	-4.01	-2.31			4.014	2.304	-10.15	-7.84	1360	34.4341832	-118.6480333	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24072	10/20/2026 1:46:34 PM	38.9	58.7	0.1	2.3			0.7	23.0	113.1	114.8	0.39	-0.16			0.000	0.141	-8.22	-8.06	1373	34.4341603	-118.6480570	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open
CV-24072	10/20/2026 1:47:58 PM	42.4	57.3	0.1	0.2			0.7	2.0	114.8	115.0	-0.25	-0.39			0.259	0.403	-7.09	-6.7	1371	34.4341482	-118.6480473	Valve Adjustment:Barely Open
CV-24073-T	10/6/2026 10:40:13 AM	9.2	79.5	0.1	11.2			0.1	112.0	157.9	158.0	-2.40	-2.40			2.393	2.382	-8.61	-6.21	1373	34.4346458	-118.6476872	Valve Adjustment:High Temp
CV-24073-T	10/8/2026 8:29:21 AM	35.8	0.0	0.0	64.2				0.0	157.3	157.5	-0.72	-0.72			0.716	0.721	-7.04	-6.32	1368	34.4346280	-118.6476969	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24073-T	10/8/2026 8:30:00 AM					1620																	AtmAA
CV-24073-T	10/8/2026 8:30:00 AM						40600																AtmAA; [User entered 4.06%]
CV-24073-T	10/14/2026 2:15:00 AM					1230																	AtmAA
CV-24073-T	10/14/2026 1:40:58 PM	49.5	50.4	0.1	0.0			1.0	0.0	141.8	141.9	-7.03	-6.74			7.216	6.957	-9.53	-2.79	1361	34.4346204	-118.6477104	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24073-T	10/21/2026 9:20:23 AM	28.5	68.2	0.9	2.4			0.4	2.7	130.5	130.5	-4.92	-4.48			5.088	4.512	-6.05	-1.57	1373	34.4346302	-118.6477107	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open
CV-24074	10/6/2026 10:36:57 AM	1.5	81.7	0.1	16.7			0.0	167.0	143.8	143.8	-1.00	-1.00			1.067	1.067	-8.50	-7.5	1377	34.4347450	-118.6473783	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
CV-24074	10/6/2026 10:37:47 AM	0.9	84.4	0.1	14.6			0.0	146.0	144.1	143.7	-0.96	-0.80			0.987	0.336	-8.61	-7.81	1378	34.4347282	-118.6473973	Valve Adjustment:High Temp,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24074	10/21/2026 9:17:10 AM	11.9	78.1	0.6	9.4			0.2	15.7	147.7	149.5	-4.66	-4.64			4.676	4.749	-5.75	-1.11	1380	34.4347235	-118.6474133	Valve Adjustment:Barely Open
CV-24074	10/26/2026 2:19:33 PM	16.6	79.1	0.0	4.3			0.2	0.0	144.2	144.8	-7.92	-7.91			7.937	8.026	-6.03	1.88	1378	34.4347533	-118.6474125	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24074	10/26/2026 2:20:00 PM					4170																	AtmAA
CV-24075-T	10/7/2026 1:15:00 PM					1970																	AtmAA
CV-24075-T	10/7/2026 1:15:00 PM						102100																AtmAA; [User entered 10.21%]
CV-24075-T	10/7/2026 1:19:39 PM	8.1	81.3	0.0	10.6			0.1	0.0	184.0	183.8	-4.45	-4.43			4.434	4.411	-4.82	-0.39	1379	34.4350411	-118.6471380	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-T	10/14/2026 10:38:34 AM	23.5	65.4	1.6	9.5			0.4	5.9	180.8	180.5	-11.37	-10.78			11.823	11.347	-11.76	-0.98	1369	34.4350300	-118.6471145	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24075-T	10/14/2026 10:43:00 AM					2600																	AtmAA
CV-24075-T	10/20/2026 1:13:29 PM	4.4	77.9	1.0	16.7			0.1	16.7	182.7	182.8	-8.12	-8.12			8.382	8.382	-8.37	-0.25	1383	34.4350148	-118.6471352	Valve Adjustment:No Flow Measurement,High Temp
CV-24075-T	10/20/2026 1:20:00 PM					2240																	AtmAA
CV-24075-T	10/27/2026 9:42:13 AM	10.8	79.0	0.2	10.0			0.1	50.0	185.0	184.8	-6.74	-6.74			7.329	7.365	-11.54	-4.8	1358	34.4350190	-118.6471231	Valve Adjustment:No Flow Measurement,High Temp
CV-24075-T	10/27/2026 9:45:00 AM					1850																	AtmAA
CV-24076	10/8/2026 8:12:44 AM	34.7	59.4	0.0	5.9			0.6	0.0	169.6	169.2	-5.11	-5.05			5.471	5.383	-7.07	-2.02	1370	34.4353056	-118.6468911	Valve Adjustment:High Temp
CV-24076	10/8/2026 8:13:00 AM					897																	AtmAA
CV-24076	10/8/2026 8:13:00 AM						36600																AtmAA; [User entered 3.66%]
CV-24076	10/14/2026 1:20:00 PM					714																	AtmAA
CV-24076	10/14/2026 1:25:50 PM	21.1	34.3	4.1	40.5			0.6	9.9	169.8	169.6	-7.99	-7.79			8.076	8.082	-10.61	-2.82	1391	34.4353069	-118.6468365	Valve Adjustment:No Flow Measurement,High Temp
CV-24076	10/20/2026 1:26:41 PM	10.7	48.5	2.3	38.5			0.2	16.7	172.0	172.1	-5.95	-5.93			6.135	6.156	-8.05	-2.12	1387	34.4353046	-118.6468876	Valve Adjustment:High Temp
CV-24076	10/20/2026 1:35:00 PM					853																	AtmAA
CV-24076	10/27/2026 1:12:00 PM					306																	AtmAA
CV-24076	10/27/2026 1:15:12 PM	25.2	44.3	1.7	28.8			0.6	16.9	170.4	169.7	-8.20	-8.09			8.342	8.154	-11.51	-3.42	1381	34.4352981	-118.6468803	Valve Adjustment:High Temp

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24077	10/1/2026 11:31:54 AM	12.3	60.9	0.0	26.8			0.2	0.0	154.6	154.6	-2.93	-2.92	0.0	0.0	-2.934	-2.929	-7.87	-4.95	1309	34.4327422	-118.6493305	NSPS/EG CAI,High Temp
CV-24077	10/1/2026 11:32:36 AM	12.2	61.4	0.0	26.4			0.2	0.0	155.0	155.0	-2.75	-2.78	0.0	0.0	-2.868	-2.972	-7.76	-4.98	1276	34.4327537	-118.6493477	NSPS/EG CAI,High Temp
CV-24077	10/5/2026 9:55:00 AM					1200																	AtmAA
CV-24077	10/5/2026 9:55:00 AM						34800																AtmAA; [User entered 3.48%]
CV-24077	10/5/2026 9:57:24 AM	15.9	68.8	0.0	15.3			0.2	0.0	157.0	156.9	-4.66	-4.61			4.687	4.632	-10.73	-6.12	1345	34.4326825	-118.6493105	Valve Adjustment:No Flow Measurement,High Temp
CV-24077	10/12/2026 1:33:29 PM	15.7	59.0	0.0	25.3			0.3	0.0	154.3	153.9	-6.58	-3.01			6.771	2.922	-13.45	-10.44	1335	34.4326547	-118.6492958	Valve Adjustment:No Flow Measurement,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24077	10/12/2026 1:34:22 PM	15.5	62.9	0.0	21.6			0.2	0.0	154.3	154.6	-2.58	-2.51			2.547	2.454	-13.65	-11.14	1330	34.4326567	-118.6492973	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	10/12/2026 1:37:00 PM					1255																	AtmAA
CV-24077	10/19/2026 8:06:13 AM	10.7	86.7	0.0	2.6			0.1	0.0	165.6	165.4	-0.29	-0.20			0.283	0.222	-12.19	-11.99	1322	34.4326841	-118.6492981	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24077	10/26/2026 10:33:00 AM					1680																	AtmAA
CV-24077	10/26/2026 10:42:39 AM	19.7	76.7	0.0	3.6			0.3	0.0	167.0	167.9	0.29	-2.65			0.000	2.641	-9.87	-7.22	1342	34.4326750	-118.6493113	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24078	10/1/2026 11:35:52 AM	5.2	56.9	0.2	37.7			0.1	188.5	139.9	137.2	-1.77	-1.64	7.5	9.9	0.018	0.031	-8.17	-6.53	1325	34.4328482	-118.6494428	NSPS/EG CAI,High Temp
CV-24078	10/1/2026 11:38:13 AM	5.1	57.6	0.1	37.2			0.1	372.0	136.9	136.9	-1.68	-1.68	5.1	5.9	0.008	0.011	-8.23	-6.55	1316	34.4329320	-118.6494478	NSPS/EG CAI,High Temp
CV-24078	10/29/2026 2:33:32 PM	0.1	2.5	20.1	77.3			0.0	3.8	143.0	134.5	-5.40	-1.74	15.3	2.5	0.676	0.017	-13.14	-11.4	1335	34.4329038	-118.6494423	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Decreased Flow/Vacuum,Plugged/Pinched Suspected
CV-24078	10/29/2026 2:34:09 PM	0.3	2.7	19.9	77.1			0.1	3.9	135.2	134.8	-1.57	-1.55	1.9	2.6	0.010	0.020	-13.91	-12.36	1334	34.4329120	-118.6494465	Valve Adjustment:High Temp,High O2,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24079-T	10/1/2026 10:44:33 AM	16.4	65.9	0.0	17.7			0.2	0.0	163.1	159.7	-1.19	-1.85	0.0	0.0	1.153	1.579	-5.90	-4.05	1332	34.4331265	-118.6490283	NSPS/EG CAI,High Temp
CV-24079-T	10/1/2026 10:45:49 AM	20.6	61.5	0.0	17.9			0.3	0.0	158.3	157.4	-1.52	-1.51	0.0	0.0	1.518	1.511	-5.90	-4.39	1316	34.4330688	-118.6490750	NSPS/EG CAI,High Temp
CV-24079-T	10/8/2026 1:29:25 PM	24.2	70.1	0.0	5.7			0.3	0.0	169.5	170.6	-0.61	-0.56			0.610	0.563	-5.86	-5.3	1334	34.4329806	-118.6491200	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24079-T	10/8/2026 1:30:00 PM					1460																	AtmAA
CV-24079-T	10/8/2026 1:30:00 PM						89300																AtmAA; [User entered 8.93%]
CV-24079-T	10/15/2026 9:55:00 AM					943																	AtmAA
CV-24079-T	10/15/2026 9:55:26 AM	36.7	49.4	0.3	13.6			0.7	45.3	153.1	153.5	-4.79	-4.76			5.517	5.524	-11.45	-6.69	1341	34.4330031	-118.6491493	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24079-T	10/21/2026 8:20:00 AM					845																	AtmAA
CV-24079-T	10/21/2026 8:20:35 AM	24.4	53.8	0.0	21.8			0.5	0.0	160.5	161.0	-2.47	-2.41			2.461	2.425	-7.17	-4.76	1339	34.4329773	-118.6491478	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24079-T	10/29/2026 9:33:30 AM	36.5	53.4	0.0	10.1			0.7	0.0	148.7	149.5	-6.77	-6.76			6.936	6.932	-14.91	-8.15	1355	34.4329805	-118.6491170	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24079-T	10/29/2026 9:37:00 AM					618																	AtmAA
CV-24080	10/1/2026 10:37:25 AM	28.9	60.3	0.0	10.8			0.5	0.0	124.6	124.6	-1.11	-1.00	8.2	7.7	0.048	0.042	-6.79	-5.79	1319	34.4330903	-118.6489828	,
CV-24080	10/20/2026 10:01:50 AM	25.8	67.2	0.0	7.0			0.4	0.0	122.3	123.1	-1.23	-1.24	5.3	5.6	0.077	0.085	-11.32	-10.08	1352	34.4331302	-118.6488867	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24081-T	10/5/2026 10:20:22 AM	45.9	47.2	0.0	6.9			1.0	0.0	123.2	123.4	-2.66	-2.65			2.603	2.601	-11.03	-8.38	1361	34.4334095	-118.6485748	Valve Adjustment:Surging Liquid in Header
CV-24081-T	10/20/2026 10:34:15 AM	42.5	54.0	0.2	3.3			0.8	16.5	111.9	112.1	-1.99	-1.98			1.984	1.963	-9.43	-7.45	1356	34.4334027	-118.6486028	Valve Adjustment:Barely Open
CV-24082	10/13/2026 8:20:39 AM	41.0	46.8	0.0	12.2			0.9	0.0	91.3	91.3	-8.38	-8.37			8.433	8.427	-17.72	-9.35	1370	34.4334127	-118.6483465	Well Condition:Lorentz Pump Installed
CV-24082	10/20/2026 1:17:39 PM	11.0	77.8	0.1	11.1			0.1	111.0	110.4	112.9	-0.22	-0.22			0.126	0.113	-12.12	-11.9	1366	34.4334127	-118.6483330	Valve Adjustment:Barely Open
CV-24083	10/5/2026 1:27:20 PM	43.2	48.9	0.7	7.2			0.9	10.3	126.5	126.7	-6.41	-6.24			6.552	6.434	-6.76	-0.52	1360	34.4337050	-118.6483548	Valve Adjustment:Decreased Flow/Vacuum
CV-24083	10/20/2026 1:30:38 PM	43.7	53.7	0.4	2.2			0.8	5.5	122.4	122.3	-5.82	-5.82			5.779	5.779	-5.72	0.1	1350	34.4337117	-118.6483442	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24084-T	10/8/2026 8:45:28 AM	6.6	83.6	0.0	9.8			0.1	0.0	187.3	187.1	-6.66	-6.07			7.029	6.612	-9.47	-3.4	1359	34.4338557	-118.6480412	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24084-T	10/8/2026 8:49:00 AM					2580																	AtmAA
CV-24084-T	10/8/2026 8:49:00 AM						98400																AtmAA; [User entered 9.84%]
CV-24084-T	10/14/2026 2:08:09 PM	16.5	76.8	0.1	6.6			0.2	66.0	185.4	185.5	-13.52	-13.48			13.739	13.569	-16.92	-3.44	1361	34.4338344	-118.6480157	Valve Adjustment:No Flow Measurement,High Temp
CV-24084-T	10/14/2026 2:35:00 PM					3470																	AtmAA
CV-24084-T	10/21/2026 7:58:02 AM	2.1	87.9	0.0	10.0			0.0	0.0	186.7	186.8	-4.87	-5.05			4.786	5.088	-8.99	-3.94	1362	34.4338508	-118.6480398	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24084-T	10/21/2026 8:00:00 AM					3570																	AtmAA
CV-24084-T	10/28/2026 10:01:00 AM					3430																	AtmAA
CV-24084-T	10/28/2026 10:09:28 AM	10.3	83.0	0.0	6.7			0.1	0.0	186.1	186.3	-7.75	-7.75			7.927	7.909	-15.12	-7.37	1362	34.4338593	-118.6480405	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24085	10/13/2026 7:46:04 AM	13.8	24.0	0.0	62.3			0.6	0.0	126.3	126.6	-2.93	-2.93	18.3	18.3	0.925	0.928	-17.90	-14.97	1349	34.4324025	-118.6490128	
CV-24085	10/20/2026 8:58:14 AM	15.7	27.7	0.2	56.4			0.6	234.9	129.8	126.6	-1.95	-1.45	17.9	8.8	0.888	0.213	-15.85	-14.4	1334	34.4323912	-118.6490293	Valve Adjustment:Decreased Flow/Vacuum
CV-24085	10/20/2026 9:00:17 AM	16.4	28.7	0.0	54.9			0.6	0.0	126.4	126.0	-1.35	-1.35	7.0	6.7	0.135	0.124	-15.92	-14.57	1338	34.4323893	-118.6490205	Well Comment:Pump removed
CV-24086	10/1/2026 10:23:35 AM	35.8	46.3	0.0	17.9			0.8	0.0	126.5	128.1	0.08	-0.08	24.1	34.9	0.382	0.802	-5.92	-5.84	1306	34.4328508	-118.6486713	NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-24086	10/1/2026 10:26:49 AM	34.5	49.2	0.0	16.3			0.7	0.0	128.4	128.3	-0.11	-0.10	24.8	24.8	0.414	0.413	-4.88	-4.78	1289	34.4329258	-118.6487752	NSPS/EG CAC,
CV-24086	10/20/2026 9:52:55 AM	25.7	36.8	2.9	34.6			0.7	11.9	127.0	126.8	-1.07	-1.06	10.9	11.1	0.326	0.340	0.33	1.39	1381	34.4328897	-118.6487175	Valve Comment:Well to tall;Valve Adjustment:Barely Open
CV-24087	10/5/2026 9:29:12 AM	40.4	39.3	1.1	19.2			1.0	17.5	122.9	122.9	-2.71	-2.66	54.8	51.8	8.334	7.446	-9.13	-6.47	1379	34.4330035	-118.6481327	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24087	10/16/2026 2:21:06 PM	36.4	36.2	1.3	26.1			1.0	20.1	123.7	123.7	-2.87	-2.88	61.7	61.3	10.632	10.492	-11.72	-8.84	1375	34.4329922	-118.6481218	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24088	10/6/2026 8:57:17 AM	0.0	0.0	21.0	79.0				3.8	113.0	113.3	-0.01	-0.01			0.000	0.000	-11.01	-11	1365	34.4335740	-118.6476583	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24088	10/6/2026 8:57:43 AM	0.0	0.0	20.9	79.1				3.8	113.5	113.3	-0.01	-0.01			0.000	0.000	-10.96	-10.95	1370	34.4335828	-118.6476708	Valve Adjustment:High O2,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24088	10/20/2026 2:13:44 PM	42.2	55.7	0.2	1.9			0.8	9.5	111.1	111.7	-2.15	-2.11			2.154	2.106	-10.52	-8.41	1363	34.4335687	-118.6476607	Valve Adjustment:Barely Open
CV-24089	10/6/2026 1:52:18 PM	23.3	35.3	0.0	41.4			0.7	0.0	135.4	135.6	-2.10	-1.97	51.1	45.3	7.439	5.830	-11.46	-9.49	1340	34.4324398	-118.6481140	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open
CV-24089	10/6/2026 1:52:58 PM	23.6	35.7	0.0	40.7			0.7	0.0	135.5	135.5	-1.94	-1.94	45.2	44.5	5.785	5.628	-11.74	-9.8	1344	34.4324387	-118.6481118	Valve Adjustment:High Temp
CV-24089	10/21/2026 8:41:14 AM	21.3	35.9	0.0	42.8			0.6	0.0	131.6	128.2	-1.51	-0.86	15.1	5.2	4.990	0.595	-10.26	-9.4	1352	34.4324388	-118.6480933	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24089	10/21/2026 8:41:57 AM	21.0	35.3	0.0	43.8			0.6	0.0	127.9	127.9	-0.85	-0.84	5.2	4.9	0.588	0.526	-10.43	-9.59	1362	34.4324273	-118.6480972	Valve Adjustment:Barely Open,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24090	10/6/2026 2:20:58 PM	37.0	49.6	0.0	13.4			0.7	0.0	122.7	122.8	-1.24	-1.23			1.217	1.225	-11.53	-10.3	1361	34.4327115	-118.6475608	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24090	10/16/2026 1:07:33 PM	32.0	41.5	0.0	26.5			0.8	0.0	120.1	117.3	-1.95	-1.13			1.817	1.029	-16.19	-15.06	1380	34.4326705	-118.6475293	Valve Adjustment:Decreased Flow/Vacuum
CV-24090	10/16/2026 2:06:36 PM	34.7	42.7	0.0	22.6			0.8	0.0	108.7	108.4	-0.83	-0.83			0.730	0.683	-16.71	-15.88	1379	34.4326837	-118.6475283	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24091	10/5/2026 8:37:42 AM	55.7	42.2	0.0	2.1			1.3	0.0	103.1	102.9	-14.75	-14.89	5.1	3.7	0.070	0.038	-15.14	-0.25	1387	34.4329888	-118.6468927	Valve Adjustment:Valve 100% Open
CV-24091	10/16/2026 1:54:01 PM	56.6	41.1	0.0	2.3			1.4	0.0	114.8	114.9	-16.97	-16.88	4.2	5.0	0.050	0.069	-17.31	-0.43	1384	34.4329925	-118.6468858	Valve Adjustment:Valve 100% Open
CV-24092	10/5/2026 10:12:32 AM	50.5	41.1	0.1	8.3			1.2	83.0	120.5	120.5	-5.76	-5.74	47.0	47.0	6.140	6.158	-13.80	-8.06	1402	34.4332692	-118.6461317	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24093	10/5/2026 10:29:23 AM	8.3	17.6	18.1	56.0			0.5	3.1	93.0	93.2	-0.51	-0.51	4.2	3.9	0.039	0.033	0.62	1.13	1404	34.4340495	-118.6463532	Valve Adjustment:High O2
CV-24093	10/19/2026 1:03:14 PM	45.4	44.7	0.0	10.0			1.0	0.0	123.9	123.8	-3.51	-3.15	34.9	32.4	2.889	2.484	-5.64	-2.49	1391	34.4340448	-118.6463648	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24093	10/19/2026 1:04:36 PM	44.9	44.0	0.0	11.1			1.0	0.0	123.9	124.0	-2.82	-2.88	27.6	28.2	1.808	1.879	-5.88	-3	1389	34.4340480	-118.6463453	Well Condition:Lorentz Pump Installed
CV-24094	10/14/2026 9:41:42 AM	7.2	37.8	11.6	43.4			0.2	3.7	82.6	82.6	-13.70	-13.36	2.8	3.4	0.156	0.237	-14.09	-0.73	1385	34.4345953	-118.6460798	
CV-24094	10/14/2026 9:43:51 AM	7.9	37.1	11.9	43.1			0.2	3.6	82.8	82.9	-13.75	-13.86	3.4	3.2	0.237	0.210	-14.03	-0.17	1383	34.4345930	-118.6460808	Valve Adjustment:NSPS/EG CAI,High O2

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24094	10/27/2026 3:08:25 PM	15.9	29.9	11.3	42.9			0.5	3.8	90.7	90.2	-14.78	-9.42	1.5	1.0	0.254	0.113	-15.13	-5.71	1373	34.4345732	-118.6460877	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24095	10/1/2026 1:39:15 PM	13.6	74.0	0.0	12.4			0.2	0.0	191.4	191.5	-4.30	-4.24			4.263	4.242	-5.42	-1.18	1266	34.4333804	-118.6513103	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24095	10/1/2026 1:40:00 PM					2820																	AtmAA
CV-24095	10/7/2026 7:46:52 AM	7.9	76.2	0.0	15.9			0.1	0.0	192.4	192.4	-3.56	-3.12			3.575	3.098	-6.34	-3.22	1262	34.4333871	-118.6513499	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24095	10/7/2026 7:50:00 AM					2510																	AtmAA
CV-24095	10/7/2026 7:50:00 AM						177850																AtmAA; [User entered 17.785%]
CV-24095	10/13/2026 8:55:00 AM					2600																	AirTech Lab
CV-24095	10/13/2026 8:55:00 AM						220000																AirTech Lab; [User entered 22%]
CV-24095	10/14/2026 8:45:00 AM					4450																	AtmAA
CV-24095	10/14/2026 8:54:32 AM	13.8	65.5	0.0	20.7			0.2	0.0	183.9	186.1	2.79	-1.43			0.000	1.377	6.16	7.59	1249	34.4334090	-118.6513108	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-24095	10/14/2026 8:57:33 AM	14.5	72.3	0.0	13.2			0.2	0.0	185.5	185.8	-0.55	-0.40			0.558	0.471	0.77	1.17	1253	34.4334021	-118.6512909	Valve Adjustment:NSPS/EG CAC,High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-24095	10/21/2026 9:05:00 AM					3490																	AtmAA
CV-24095	10/21/2026 9:07:57 AM	3.3	72.8	0.0	23.9			0.0	0.0	183.5	182.8	8.44	8.49			0.000	0.000	17.92	9.43	1251	34.4333891	-118.6512906	Valve Adjustment:High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24095	10/28/2026 1:44:00 PM					3640																	AtmAA
CV-24095	10/28/2026 1:49:19 PM	5.1	73.7	0.1	21.2			0.1	302.3	189.5	189.3	23.33	22.68			0.000	0.000	23.60	0.92	1246	34.4333928	-118.6513045	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Valve 100% Open,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-24096	10/13/2026 9:34:28 AM	34.8	48.4	2.1	14.7			0.7	7.0	73.8	74.3	-5.31	-5.19			5.475	5.325	-7.73	-2.54	1259	34.4332163	-118.6515758	Valve Adjustment:Decreased Flow/Vacuum
CV-24096	10/20/2026 10:15:07 AM	43.1	56.2	0.7	0.0			0.8	0.0	86.9	87.0	-3.59	-3.46			3.589	3.466	-4.42	-0.96	1260	34.4332130	-118.6515765	Valve Adjustment:Decreased Flow/Vacuum
CV-24097	10/9/2026 9:52:16 AM	49.0	42.9	3.3	4.8			1.1	1.5	96.5	96.9	-5.04	-4.89			5.315	5.187	-5.09	-0.2	1258	34.4328030	-118.6515373	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24097	10/20/2026 10:23:00 AM	54.8	45.1	0.1	0.0			1.2	0.0	83.1	84.0	-3.70	-3.77			3.696	3.785	-3.61	0.16	1261	34.4327982	-118.6515418	Valve Adjustment:Increased Flow/Vacuum
CV-24098	10/9/2026 9:47:06 AM	34.2	48.8	3.1	13.9			0.7	4.5	87.6	89.1	-13.90	-13.88			14.163	14.230	-13.73	0.15	1254	34.4325168	-118.6513090	Valve Comment:valve stuck open
CV-24098	10/30/2026 9:03:31 AM	43.6	40.5	2.4	13.5			1.1	5.6	62.4	62.4	-16.55	-16.99			16.742	17.167	-16.64	0.35	1253	34.4325147	-118.6513247	Valve Adjustment:Decreased Flow/Vacuum
CV-24099	10/9/2026 9:43:11 AM	17.5	76.3	1.2	5.0			0.2	4.2	89.3	89.5	-13.97	-13.97			14.345	14.315	-14.08	-0.11	1262	34.4323290	-118.6509152	Valve Comment:valve stuck open
CV-24099	10/30/2026 8:58:53 AM	0.3	3.0	20.0	76.7			0.1	3.8	59.8	60.0	-13.16	-13.88			13.323	14.005	-12.86	1.02	1257	34.4323622	-118.6509288	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24100	10/9/2026 9:32:42 AM	17.6	72.6	1.1	8.7			0.2	7.9	127.4	127.2	-6.42	-3.40			6.838	3.409	-14.36	-10.96	1265	34.4320448	-118.6504815	Valve Adjustment:Decreased Flow/Vacuum
CV-24100	10/13/2026 8:40:00 AM					68																	AirTech Lab
CV-24100	10/13/2026 8:40:00 AM						11000																AirTech Lab; [User entered 1.1%]
CV-24100	10/28/2026 1:11:35 PM	17.2	69.0	1.0	12.8			0.2	12.8	79.4	77.9	-9.34	-9.36			0.064	0.009	-16.95	-7.59	1268	34.4320253	-118.6504672	
CV-24101	10/7/2026 8:05:00 AM					43																	Air Tech Lab
CV-24101	10/7/2026 8:05:00 AM						5700																Air Tech Lab; [User entered 0.57%]
CV-24101	10/9/2026 9:29:11 AM	45.0	50.3	0.5	4.2			0.9	8.4	106.7	108.8	-9.31	-8.10			9.628	8.326	-11.08	-2.98	1260	34.4318288	-118.6502790	Valve Adjustment:Decreased Flow/Vacuum
CV-24101	10/9/2026 9:35:13 AM	7.5	68.6	4.5	19.4			0.1	4.3	101.3	101.6	-13.84	-13.72			0.000	0.000	-13.85	-0.13	1266	34.4322790	-118.6505590	Valve Adjustment:Decreased Flow/Vacuum
CV-24101	10/30/2026 8:50:38 AM	38.9	58.0	1.1	2.0			0.7	1.8	118.8	113.3	-17.32	-17.06			17.439	17.147	-17.41	-0.35	1265	34.4318332	-118.6502830	Valve Adjustment:Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24102	10/5/2026 9:46:47 AM						17000																[User entered 1.7%]
CV-24102	10/5/2026 9:47:47 AM	45.4	50.0	0.0	4.6			0.9	0.0	113.3	113.5	-0.49	-0.49			0.485	0.485	-12.42	-11.93	1276	34.4316302	-118.6497823	Well Comment:Pump off upon arrival;Well Condition:Pnumatic Pump Installed

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24102	10/20/2026 7:43:14 AM	43.5	54.6	0.0	1.9			0.8	0.0	67.5	67.6	-0.86	-0.85			0.868	0.861	-16.04	-15.19	1291	34.4316243	-118.6497798	
CV-24103	10/7/2026 1:43:57 PM	47.0	44.1	0.0	9.0			1.1	0.0	118.1	118.2	-0.14	-0.14	5.1	5.3	0.552	0.584	-7.15	-7.01	1312	34.4316462	-118.6488533	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24103	10/20/2026 8:08:37 AM	32.9	36.9	0.0	30.2			0.9	0.0	96.6	89.3	-1.32	-1.21	2.7	1.0	0.147	0.020	-16.96	-15.75	1318	34.4316375	-118.6488277	Valve Adjustment:Decreased Flow/Vacuum
CV-24103	10/20/2026 8:09:28 AM	32.0	37.3	0.0	30.7			0.9	0.0	86.4	86.0	-1.20	-1.19	1.2	1.1	0.029	0.024	-10.78	-9.59	1320	34.4316458	-118.6488357	Valve Adjustment:Barely Open
CV-24104	10/6/2026 10:03:06 AM	43.0	51.0	0.0	6.0			0.8	0.0	106.8	106.9	-2.04	-1.52	6.5	3.8	4.540	1.581	-12.99	-11.47	1371	34.4318858	-118.6480622	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Surging Liquid in Header
CV-24104	10/16/2026 1:28:06 PM	41.9	52.3	0.0	5.8			0.8	0.0	102.7	101.9	-0.80	-0.21	3.6	3.1	1.393	1.016	-16.53	-16.32	1359	34.4318787	-118.6480740	Valve Adjustment:Decreased Flow/Vacuum
CV-24105	10/6/2026 10:12:00 AM	37.3	38.2	0.2	24.3			1.0	121.5	115.6	115.5	-1.12	-0.96	15.3	11.5	1.478	0.835	-12.60	-11.64	1338	34.4319223	-118.6476472	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24105	10/26/2026 11:52:29 AM	42.9	39.5	0.1	17.5			1.1	125.1	118.5	118.5	-0.25	-0.25	11.8	11.7	0.875	0.872	-14.22	-13.97	1342	34.4318972	-118.6476540	
CV-24105	10/26/2026 11:59:16 AM	43.8	40.5	0.1	15.6			1.1	312.4	118.2	118.2	-0.18	-0.18	11.3	11.3	2.692	2.716	-14.09	-13.91	1335	34.4318835	-118.6476368	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-24107	10/1/2026 9:49:11 AM	44.4	48.2	0.1	7.3			0.9	73.0	107.1	106.9	0.92	0.92			0.000	0.000	1.02	0.1	1332	34.4325475	-118.6461675	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Reduce Sys. Vac. - Flare Down,Plugged/Pinched Suspected;Well Condition:Lorentz Pump Installed
CV-24107	10/1/2026 9:49:55 AM	43.4	48.6	0.0	8.0			0.9	0.0	106.8	106.7	0.93	0.93			0.000	0.000	1.02	0.09	1321	34.4325503	-118.6461780	
CV-24107	10/5/2026 2:01:12 PM	40.1	39.5	0.2	20.2			1.0	101.0	133.4	131.8	-7.33	-2.90			7.377	2.837	-12.21	-9.31	1325	34.4325360	-118.6461660	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-24107	10/5/2026 2:02:11 PM	38.9	37.7	0.3	23.1			1.0	77.0	131.4	131.2	-2.65	-2.64			2.602	2.590	-12.92	-10.28	1331	34.4325088	-118.6461568	
CV-24108	10/29/2026 1:54:39 PM	44.9	52.3	0.3	2.5			0.9	8.3	132.7	132.9	-0.84	-0.84	4.9	4.4	0.066	0.054	-13.38	-12.54	1362	34.4331460	-118.6454373	Valve Adjustment:High Temp
CV-24109	10/27/2026 10:05:14 AM	32.2	43.1	0.2	24.5			0.7	122.5	99.2	99.1	-4.25	-4.25			4.207	4.205	-21.92	-17.67	1372	34.4339968	-118.6448790	
CV-24110	10/5/2026 12:49:56 PM	30.6	64.3	0.0	5.1			0.5	0.0	127.9	82.5	-0.30	-0.41	10.2	12.5	0.287	0.399	-9.56	-9.15	1401	34.4345940	-118.6446747	Valve Adjustment:Audible Flow,Barely Open,Surging Liquid in Header
CV-24110	10/5/2026 12:58:09 PM	29.9	65.0	0.0	5.1			0.5	0.0	127.9	127.9	-0.31	-0.18	10.2	8.0	0.285	0.174	-9.60	-9.42	1389	34.4346125	-118.6446795	Valve Adjustment:Barely Open,Surging Liquid in Header
CV-24111	10/28/2026 9:07:29 AM	42.2	53.8	0.0	4.0			0.8	0.0	115.8	115.4	-5.31	-4.80			5.593	4.823	-17.39	-12.59	1396	34.4353060	-118.6449755	Valve Adjustment:Decreased Flow/Vacuum
CV-24112	10/28/2026 9:51:49 AM	46.3	40.5	0.0	13.2			1.1	0.0	128.7	128.2	-2.47	-2.26	35.8	28.9	0.831	0.540	-17.37	-15.11	1394	34.4352108	-118.6442192	Valve Adjustment:Decreased Flow/Vacuum
CV-24114	10/30/2026 8:14:45 AM	56.7	41.7	0.0	1.6			1.4	0.0	66.1	65.5	5.06	4.99	4.3	3.6	0.045	0.031	5.05	0.06	1288	34.4308152	-118.6485402	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24114	10/30/2026 8:15:25 AM	56.4	41.9	0.0	1.7			1.3	0.0	65.2	65.2	5.06	5.06	3.9	3.9	0.038	0.037	5.09	0.03	1291	34.4308038	-118.6485343	Valve Adjustment:Positive Static Press.,Valve 100% Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24116	10/7/2026 1:15:47 PM	50.5	44.2	0.0	5.3			1.1	0.0	123.6	123.4	-2.84	-2.79	0.0	0.0	3.368	2.551	-7.94	-5.15	1302	34.4318295	-118.6456920	Reduced System Vacuum,
CV-24117	10/7/2026 11:12:31 AM	41.7	36.9	0.0	21.4			1.1	0.0	115.7	115.9	-0.23	-0.22	0.0	0.0	0.174	0.171	-4.90	-4.68	1220	34.4322765	-118.6449067	Reduced System Vacuum,
CV-24118	10/4/2026 1:56:57 PM	17.2	56.0	1.0	25.9			0.3	26.2	133.5	133.4	-6.71	-6.71			6.747	6.740	-16.74	-10.03	1305	34.4332800	-118.6438337	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24118	10/4/2026 2:02:35 PM	16.8	56.0	0.9	26.2			0.3	27.9	133.4	131.6	-6.34	-0.54			6.361	0.586	-16.37	-15.83	1313	34.4332835	-118.6437865	Valve Adjustment:NSPS/EG CAC,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24118	10/4/2026 2:05:50 PM	13.2	62.2	0.5	24.2			0.2	44.7	131.4	131.8	-0.33	-1.09			0.354	1.096	-16.93	-15.84	1300	34.4332840	-118.6438367	Valve Adjustment:High Temp,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24119	10/5/2026 1:54:25 PM						94000																[User entered 9.4%]
CV-24119	10/5/2026 1:56:15 PM	44.4	45.1	0.0	10.6			1.0	0.0	139.2	140.0	0.14	-0.80			0.000	0.764	-13.48	-12.68	1275	34.4337405	-118.6422982	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24119	10/5/2026 1:59:15 PM	43.8	45.5	0.0	10.7			1.0	0.0	142.0	142.4	-1.04	-1.05			1.037	1.041	-13.41	-12.36	1265	34.4337392	-118.6423163	Valve Adjustment:High Temp
CV-24119	10/16/2026 1:40:45 PM	36.6	49.3	0.0	14.1			0.7	0.0	139.8	140.4	-4.47	-5.05			4.272	4.934	-16.57	-11.52	1262	34.4337458	-118.6422997	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-24120	10/11/2026 11:39:56 AM	1.4	15.5	17.5	65.7			0.1	3.8	80.2	80.4	-3.02	-2.56			2.995	2.527	-10.10	-7.54	1327	34.4368333	-118.6472933	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open;Well Comment:Pump is active;Well Condition:Lorentz Pump Installed
CV-24120	10/11/2026 11:41:48 AM	1.8	16.4	16.7	65.1			0.1	3.9	81.0	80.1	-1.37	-10.22			1.315	10.180	-10.15	0.07	1337	34.4368582	-118.6473053	Valve Adjustment:High O2,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24120	10/11/2026 11:43:43 AM	2.2	25.3	15.6	57.0			0.1	3.6	80.0	79.3	-1.72	-1.72			1.633	1.671	-10.03	-8.31	1342	34.4368572	-118.6473058	Valve Adjustment:High O2;Well Comment:pump is active;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24120	10/13/2026 7:45:00 AM					330																	AirTech Lab
CV-24120	10/13/2026 7:45:00 AM						22000																AirTech Lab; [User entered 2.2%]
CV-24120	10/26/2026 8:47:43 AM	1.8	22.0	16.6	59.6			0.1	3.6	64.2	64.2	-8.10	-8.14			8.235	8.307	-8.19	-0.05	1343	34.4368492	-118.6472845	Valve Adjustment:High O2,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24121	10/8/2026 7:45:00 AM					0																	Air Tech Lab
CV-24121	10/8/2026 7:45:00 AM						0																Air Tech Lab; [User entered 0%]
CV-24121	10/11/2026 11:46:36 AM	34.7	60.0	0.0	5.2			0.6	0.0	123.1	123.1	-7.51	-7.39			7.499	7.344	-10.08	-2.69	1315	34.4369642	-118.6470602	Well Condition:Pnumatic Pump Installed
CV-24121	10/26/2026 8:43:18 AM	32.5	64.4	0.3	2.8			0.5	9.3	107.9	105.1	-5.94	-4.62			6.021	4.627	-8.27	-3.65	1332	34.4369440	-118.6470143	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24122	10/8/2026 8:15:00 AM					130																	Air Tech Lab
CV-24122	10/8/2026 8:15:00 AM						8000																Air Tech Lab; [User entered 0.80%]
CV-24122	10/11/2026 11:03:13 AM	36.1	28.6	7.8	27.6			1.3	3.5	76.6	76.8	-6.50	-6.17	0.9	0.8	0.015	0.012	-6.46	-0.29	1329	34.4371482	-118.6465982	Valve Adjustment:NSPS/EG CAI,High O2,Valve 100% Open,Decreased Flow/Vacuum
CV-24122	10/11/2026 11:04:24 AM	36.3	29.3	7.7	26.8			1.2	3.5	77.2	77.3	-3.59	-3.56	0.8	0.8	0.012	0.012	-6.77	-3.21	1331	34.4371513	-118.6466175	Valve Adjustment:High O2
CV-24122	10/26/2026 9:00:07 AM	56.8	41.1	0.1	2.0			1.4	20.0	67.2	67.6	-3.50	-3.56	0.6	0.4	0.018	0.006	-3.37	0.19	1325	34.4371835	-118.6466002	Valve Adjustment:Barely Open
CV-24123	10/13/2026 7:41:04 AM	44.7	52.1	0.0	3.2			0.9	0.0	115.5	115.5	-5.19	-5.15			0.056	0.044	-11.43	-6.28	1304	34.4373083	-118.6462545	Valve Adjustment:NSPS/EG CAI,No Flow Measurement;Well Comment:Needs o.p
CV-24124	10/11/2026 11:32:16 AM	6.4	61.2	3.0	29.4			0.1	9.7	134.4	134.0	-4.37	-4.36			4.365	4.364	-10.04	-5.68	1351	34.4366597	-118.6470652	Valve Adjustment:NSPS/EG CAI,High Temp;Well Condition:Lorentz Pump Installed
CV-24124	10/11/2026 11:33:07 AM	6.2	60.5	2.9	30.4			0.1	10.3	133.5	134.0	-4.41	-4.37			4.418	4.385	-10.23	-5.86	1347	34.4366562	-118.6470670	Valve Adjustment:High Temp
CV-24124	10/26/2026 8:29:17 AM	5.4	70.4	1.6	22.6			0.1	14.1	139.0	139.0	-2.87	-2.87			2.871	2.861	-7.93	-5.06	1360	34.4366192	-118.6470542	Valve Comment:well too tall for valve adjustment;Valve Adjustment:Barely Open
CV-24125-T	10/11/2026 11:13:09 AM	43.4	51.5	0.0	5.1			0.8	168.3	93.4	92.2	-13.22	-6.14			13.374	6.242	-13.52	-7.38	1327	34.4369640	-118.6463433	Valve Adjustment:Decreased Flow/Vacuum;Well Comment:pump offline;Well Condition:Pnumatic Pump Installed
CV-24125-T	10/11/2026 11:14:42 AM	43.4	49.5	0.0	7.0			0.9	0.0	91.8	92.0	-3.24	-3.25			3.271	3.278	-13.34	-10.09	1326	34.4369793	-118.6463447	Well Comment:pump offline;Well Condition:Pnumatic Pump Installed
CV-24125-T	10/13/2026 7:50:00 AM					25																	AirTech Lab
CV-24125-T	10/13/2026 7:50:00 AM						5200																AirTech Lab; [User entered 0.52%]
CV-24125-T	10/26/2026 9:10:30 AM	27.6	64.6	1.5	6.3			0.4	4.2	107.5	107.6	-8.44	-8.44			8.549	8.519	-11.07	-2.63	1329	34.4369813	-118.6463262	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down,Plugged/Pinched Suspected
CV-24126	10/5/2026 1:44:55 PM	21.6	40.1	2.1	36.2			0.5	17.2	176.6	176.6	-4.44	-4.33			4.415	4.289	-4.86	-0.53	1395	34.4363788	-118.6471306	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24126	10/5/2026 1:45:00 PM					1710																	AtmAA
CV-24126	10/5/2026 1:45:00 PM						60600																AtmAA; [User entered 6.06%]
CV-24126	10/12/2026 10:30:00 AM					1750																	AtmAA
CV-24126	10/12/2026 10:33:32 AM	12.8	40.8	2.7	43.7			0.3	16.2	176.7	176.7	-7.32	-6.95			7.635	7.329	-8.07	-1.12	1373	34.4363782	-118.6471488	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24126	10/21/2026 9:39:03 AM	6.3	53.5	0.8	39.4			0.1	49.3	181.5	181.9	-3.82	-3.69			3.918	3.856	0.00	3.69	1377	34.4363716	-118.6471400	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24126	10/21/2026 10:25:00 AM					2560																	AtmAA
CV-24126	10/26/2026 10:06:44 AM	8.4	41.5	2.8	47.3			0.2	16.9	175.9	175.9	-6.06	-5.95			6.356	6.244	-5.71	0.24	1384	34.4363908	-118.6471158	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24126	10/26/2026 10:10:00 AM					2260																	AtmAA
CV-24127	10/5/2026 1:40:00 PM					3660																	AtmAA
CV-24127	10/5/2026 1:40:00 PM						169300																AtmAA; [User entered 16.93%]
CV-24127	10/5/2026 1:40:34 PM	37.6	62.3	0.1	0.0			0.6	0.0	174.6	175.5	-5.40	-5.27			5.562	5.406	-5.67	-0.4	1389	34.4364620	-118.6468379	Valve Adjustment:No Flow Measurement,High Temp
CV-24127	10/8/2026 7:55:00 AM					1400																	Air Tech Lab
CV-24127	10/8/2026 7:55:00 AM						87000																Air Tech Lab; [User entered 8.7%]
CV-24127	10/12/2026 2:03:41 PM	35.6	61.8	0.0	2.6			0.6	0.0	162.8	162.8	-9.15	-9.10			9.347	9.279	-9.56	-0.46	1371	34.4364350	-118.6468297	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24127	10/12/2026 2:05:00 PM					1320																	AtmAA
CV-24127	10/20/2026 1:09:24 PM	16.5	40.5	0.9	42.1			0.4	46.8	145.5	145.5	-6.38	-6.17			6.291	6.137	-7.96	-1.79	1390	34.4364220	-118.6468258	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24127	10/20/2026 1:11:00 PM					1720																	AtmAA
CV-24127	10/26/2026 10:12:05 AM	18.1	35.7	1.6	44.6			0.5	27.9	144.5	144.5	-5.93	-5.71			6.157	5.948	-5.59	0.12	1380	34.4364655	-118.6468258	Valve Adjustment:No Flow Measurement,High Temp
CV-24127	10/26/2026 10:15:00 AM					1070																	AtmAA
CV-24128	10/6/2026 7:35:00 AM					2100																	Air Tech Lab
CV-24128	10/6/2026 7:35:00 AM						85000																Air Tech Lab; [User entered 8.5%]
CV-24128	10/11/2026 11:24:46 AM	21.2	57.1	0.3	21.4			0.4	73.6	93.5	93.8	-1.28	-0.81			1.214	0.786	-13.28	-12.47	1341	34.4367018	-118.6464375	Valve Adjustment:Decreased Flow/Vacuum;Well Comment:lorentz fittings need to be secured;Well Condition:Lorentz Pump Installed
CV-24128	10/11/2026 11:27:14 AM	15.2	63.7	0.0	21.1			0.2	526.8	92.9	92.8	-0.67	-0.67			0.657	0.672	-13.24	-12.57	1355	34.4367043	-118.6464543	Valve Adjustment:Barely Open;Well Comment:fittings secured;Well Condition:Lorentz Pump Installed
CV-24128	10/26/2026 9:21:22 AM	39.8	58.6	0.3	1.3			0.7	4.3	125.5	125.5	-0.28	-0.28			0.257	0.267	-10.02	-9.74	1351	34.4366997	-118.6464018	Valve Adjustment:Barely Open
CV-24129	10/11/2026 11:18:44 AM	47.1	49.5	0.0	3.5			1.0	0.0	125.4	125.5	-9.88	-9.90			10.201	10.216	-12.86	-2.96	1359	34.4367120	-118.6461722	Well Condition:Lorentz Pump Installed
CV-24129	10/26/2026 9:19:27 AM	37.9	62.1	0.0	0.0			0.6	0.0	129.7	129.6	-8.06	-7.78			8.119	7.928	-10.38	-2.6	1344	34.4366958	-118.6461875	Valve Adjustment:Decreased Flow/Vacuum
CV-24130	10/13/2026 10:45:08 AM	21.0	67.1	0.8	11.1			0.3	13.9	104.0	104.4	-5.01	-5.00			5.303	5.298	-8.99	-3.99	1334	34.4368048	-118.6457155	
CV-24130	10/26/2026 9:15:29 AM	18.5	69.8	0.0	11.7			0.3	0.0	115.9	117.7	-0.85	-0.85			0.843	0.845	-5.39	-4.54	1337	34.4368097	-118.6456940	Valve Adjustment:Barely Open
CV-24131	10/13/2026 8:05:37 AM	37.8	44.0	1.7	16.5			0.9	9.7	124.8	124.9	-5.73	-5.73	29.2	28.8	2.378	2.311	-15.58	-9.85	1347	34.4367155	-118.6450875	
CV-24132	10/21/2026 9:06:50 AM	56.8	40.9	0.0	2.3			1.4	0.0	127.0	127.1	-4.39	-4.41	2.1	3.9	0.012	0.043	-6.57	-2.16	1297	34.4372433	-118.6440277	
CV-24133	10/11/2026 1:33:58 PM	46.4	36.4	0.0	17.2			1.3	0.0	118.3	118.5	-4.46	-4.44	5.9	6.1	0.094	0.104	-4.77	-0.33	1269	34.4374272	-118.6427337	
CV-24134-T	10/5/2026 1:35:00 PM					3080																	AtmAA
CV-24134-T	10/5/2026 1:35:00 PM						120200																AtmAA; [User entered 12.02%]
CV-24134-T	10/5/2026 1:37:24 PM	38.3	61.6	0.1	0.0			0.6	0.0	152.9	152.2	-1.66	-1.62			1.651	1.620	-2.03	-0.41	1375	34.4363521	-118.6465107	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24134-T	10/12/2026 1:55:00 PM					2690																	AtmAA
CV-24134-T	10/12/2026 1:57:36 PM	32.6	67.4	0.0	0.0			0.5	0.0	134.5	135.1	-3.83	-3.81			3.827	3.825	-3.89	-0.08	1373	34.4363373	-118.6465005	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24134-T	10/26/2026 10:15:41 AM	15.5	71.2	0.0	13.3			0.2	0.0	150.2	150.1	-5.72	-5.41			5.893	5.654	-6.30	-0.89	1362	34.4363582	-118.6464838	Valve Adjustment:High Temp,Decreased Flow/Vacuum,Barely Open
CV-24134-T	10/26/2026 10:20:00 AM					3350																	AtmAA
CV-24135	10/1/2026 2:21:13 PM	22.2	76.8	0.0	1.0			0.3	0.0	149.2	149.1	-1.00	-1.01			0.955	0.955	-1.95	-0.94	1369	34.4363715	-118.6459641	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24135	10/1/2026 2:25:00 PM					4780																	AtmAA
CV-24135	10/8/2026 9:30:29 AM	9.1	75.8	0.0	15.1			0.1	0.0	150.2	150.3	0.65	0.65			0.000	0.000	0.54	-0.11	1334	34.4363929	-118.6459824	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24135	10/8/2026 9:33:00 AM					4380																	AtmAA
CV-24135	10/8/2026 9:33:00 AM						140300																AtmAA; [User entered 14.03%]
CV-24135	10/9/2026 2:21:33 PM	7.7	70.6	0.2	21.5			0.1	107.5	150.2	150.3	-1.22	-1.20			1.215	1.198	-1.86	-0.66	1337	34.4363655	-118.6459712	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24135	10/12/2026 1:48:07 PM	25.9	71.3	0.0	2.8			0.4	0.0	146.0	146.2	-3.30	-3.24			3.245	3.200	-4.27	-1.03	1356	34.4363670	-118.6459552	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24135	10/12/2026 1:50:00 PM					4640																	AtmAA
CV-24135	10/20/2026 1:01:34 PM	15.0	74.4	0.0	10.6			0.2	0.0	141.1	140.2	-6.23	-6.21			6.189	6.110	-7.81	-1.6	1372	34.4363608	-118.6459633	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24135	10/20/2026 1:04:00 PM					3660																	AtmAA
CV-24136	10/21/2026 9:59:57 AM	25.4	46.8	0.0	27.8			0.5	0.0	132.0	132.0	-2.66	-2.67			2.654	2.653	-5.16	-2.49	1338	34.4366477	-118.6442640	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24136	10/21/2026 10:00:59 AM	25.2	45.4	0.0	29.4			0.6	0.0	131.5	131.7	-2.65	-2.66			2.638	2.637	-5.16	-2.5	1346	34.4366308	-118.6442698	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24137	10/7/2026 10:16:57 AM	44.3	44.8	0.0	10.9			1.0	0.0	98.0	101.5	-1.79	-1.13	0.0	0.0	1.755	0.870	-9.35	-8.22	1362	34.4361498	-118.6434460	Reduced System Vacuum,
CV-24138	10/5/2026 10:30:00 AM					1010																	AtmAA
CV-24138	10/5/2026 10:30:00 AM						148300																AtmAA; [User entered 14.83%]
CV-24138	10/5/2026 10:33:11 AM	13.8	80.4	0.0	5.8			0.2	0.0	163.0	163.1	-4.61	-4.45			4.535	4.498	-4.43	0.02	1268	34.4342515	-118.6512367	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24138	10/9/2026 8:35:00 AM					1700																	AirTech Lab
CV-24138	10/9/2026 8:35:00 AM						340000																AirTech Lab; [User entered 34%]

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24138	10/14/2026 8:39:51 AM	31.0	46.3	2.0	20.7			0.7	10.4	71.2	71.0	-7.86	-7.71			7.986	7.837	-8.79	-1.08	1251	34.4342492	-118.6512454	Valve Adjustment:No Flow Measurement;Well Condition:Pnumatic Pump Installed
CV-24138	10/20/2026 9:45:06 AM	3.0	75.0	0.4	21.6			0.0	54.0	162.1	162.3	-5.51	-5.25			4.729	4.374	-5.64	-0.39	1273	34.4342702	-118.6512490	Valve Adjustment:NSPS/EG CAI,High Temp
CV-24138	10/20/2026 9:45:39 AM	3.0	77.0	0.7	19.3			0.0	27.6	162.7	163.1	-5.04	-4.99			4.819	4.380	-5.51	-0.52	1269	34.4342578	-118.6512550	Valve Adjustment:Decreased Flow/Vacuum
CV-24138	10/20/2026 9:50:00 AM					1430																	AtmAA
CV-24138	10/26/2026 8:54:48 AM	26.4	0.0	3.8	69.8				18.4	64.0	64.1	-4.55	-4.25			5.188	4.253	-3.79	0.46	1264	34.4342392	-118.6512476	Valve Adjustment:No Flow Measurement;Well Condition:Pnumatic Pump Installed
CV-24138	10/28/2026 1:38:07 PM	18.9	46.1	4.9	30.2			0.4	6.2	89.6	89.6	-6.00	-5.96			6.138	6.140	-5.94	0.02	1271	34.4342475	-118.6512448	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24139	10/5/2026 9:26:00 AM					490																	AirTech Lab
CV-24139	10/5/2026 9:26:00 AM						160000																AirTech Lab; [User entered 16%]
CV-24139	10/13/2026 9:58:30 AM	5.1	43.1	6.8	45.0			0.1	6.6	86.1	87.2	-11.50	-11.34			11.706	11.620	-11.57	-0.23	1270	34.4344962	-118.6511488	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24139	10/13/2026 10:05:24 AM	5.4	44.3	6.9	43.4			0.1	6.3	87.8	88.7	-11.25	-11.25			11.426	11.435	-12.36	-1.11	1282	34.4345010	-118.6511348	Valve Adjustment:NSPS/EG CAI,High O2
CV-24139	10/20/2026 9:36:34 AM	5.7	59.3	4.8	30.2			0.1	6.3	86.8	86.9	-10.11	-9.92			9.777	9.631	-10.22	-0.3	1280	34.4344932	-118.6511610	Valve Adjustment:Decreased Flow/Vacuum
CV-24140	10/1/2026 1:48:19 PM	9.8	72.6	0.0	17.6			0.1	0.0	160.2	160.2	-2.37	-2.27			2.426	2.232	-3.79	-1.52	1277	34.4346619	-118.6511102	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24140	10/1/2026 1:50:00 PM					1640																	AtmAA
CV-24140	10/5/2026 9:24:00 AM					1200																	AirTech Lab
CV-24140	10/5/2026 9:24:00 AM						200000																AirTech Lab; [User entered 20%]
CV-24140	10/7/2026 7:35:17 AM	5.1	75.2	0.1	19.6			0.1	196.0	124.2	123.3	-2.86	-2.68			2.847	2.685	-3.22	-0.54	1262	34.4347003	-118.6511350	Valve Adjustment:No Flow Measurement;Well Condition:Pnumatic Pump Installed
CV-24140	10/20/2026 9:32:41 AM	3.1	80.7	0.3	15.9			0.0	53.0	123.9	124.1	-9.10	-8.93			8.891	8.773	-8.94	-0.01	1289	34.4346620	-118.6511293	Valve Adjustment:Decreased Flow/Vacuum
CV-24141	10/9/2026 8:40:00 AM					110																	AirTech Lab
CV-24141	10/9/2026 8:40:00 AM						28000																AirTech Lab; [User entered 2.8%]
CV-24141	10/13/2026 10:39:49 AM	2.6	6.2	17.1	74.1			0.4	4.3	82.9	82.8	-9.12	-9.00			9.468	9.387	-9.86	-0.86	1309	34.4354888	-118.6513068	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open
CV-24141	10/20/2026 11:37:36 AM	16.2	29.5	8.0	46.3			0.5	5.8	98.1	97.6	-0.09	-0.56			0.094	0.558	-5.62	-5.06	1321	34.4355025	-118.6513060	Valve Adjustment:NSPS/EG CAI,High O2,Increased Flow/Vacuum
CV-24141	10/20/2026 11:38:22 AM	15.8	28.7	8.3	47.2			0.6	5.7	98.4	98.4	-0.81	-0.81			0.814	0.813	-6.02	-5.21	1322	34.4355042	-118.6513167	Valve Adjustment:NSPS/EG CAI,High O2
CV-24142	10/9/2026 8:30:00 AM					1100																	AirTech Lab
CV-24142	10/9/2026 8:30:00 AM						160000																AirTech Lab; [User entered 16%]
CV-24142	10/13/2026 9:50:57 AM	0.7	15.3	15.1	68.9			0.0	4.6	131.8	132.1	-5.63	-4.68			5.825	4.585	-7.76	-3.08	1263	34.4339872	-118.6513415	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Decreased Flow/Vacuum,Barely Open
CV-24142	10/13/2026 9:53:09 AM	0.4	11.5	16.2	71.9			0.0	4.4	133.1	133.3	-4.74	-4.72			4.673	4.607	-7.96	-3.24	1259	34.4339902	-118.6513427	Valve Adjustment:NSPS/EG CAI,High Temp,High O2
CV-24142	10/20/2026 9:49:21 AM	2.1	44.4	8.8	44.7			0.0	5.1	170.7	170.9	-4.19	-3.99			4.114	3.816	-4.11	-0.12	1263	34.4339808	-118.6513523	Valve Adjustment:NSPS/EG CAI,High Temp,High O2,Decreased Flow/Vacuum
CV-24142	10/20/2026 9:50:53 AM	2.3	46.1	8.6	43.0			0.0	5.0	170.8	171.1	-2.92	-2.92			2.956	3.525	-2.79	0.13	1265	34.4339877	-118.6513557	Valve Adjustment:NSPS/EG CAI,High Temp,High O2
CV-24142	10/20/2026 9:55:00 AM					1500																	AtmAA
CV-24142	10/26/2026 8:33:34 AM	4.6	0.0	2.3	93.1				40.5	162.2	162.2	-4.04	-3.95			3.915	4.255	-4.26	-0.31	1264	34.4339968	-118.6513323	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-24142	10/26/2026 8:35:00 AM					2360																	AtmAA
CV-24143	10/9/2026 8:25:00 AM					13																	AirTech Lab
CV-24143	10/9/2026 8:25:00 AM						6000																AirTech Lab; [User entered 0.60%]
CV-24143	10/13/2026 10:32:36 AM	0.2	1.5	18.8	79.5			0.1	4.2	82.0	82.0	-10.38	-10.33			10.760	10.718	-10.43	-0.1	1280	34.4349943	-118.6511975	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Well (Watered In)
CV-24143	10/20/2026 10:07:52 AM	0.1	0.6	20.8	78.5			0.2	3.8		88.1		-0.01				0.020			1265	34.4334068	-118.6513140	
CV-24143	10/20/2026 11:27:21 AM	0.5	5.7	19.5	74.3			0.1	3.8	98.9	98.8	-3.86	-3.89			3.864	3.908	-3.67	0.22	1305	34.4349920	-118.6512225	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Well (Watered In)
CV-24144	10/9/2026 9:50:12 AM	44.0	44.5	0.9	10.6			1.0	11.8	103.6	103.6	-4.82	-4.99	6.7	7.0	4.848	5.366	-4.52	0.47	1250	34.4325598	-118.6515443	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24144	10/20/2026 10:27:56 AM	57.6	42.2	0.0	0.2			1.4	0.0	102.6	102.7	-3.18	-3.22			3.228	3.219	-3.10	0.12	1242	34.4325768	-118.6516008	Valve Adjustment:Increased Flow/Vacuum

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24145	10/6/2026 8:24:47 AM	14.7	64.1	0.0	21.2			0.2	0.0	186.6	186.3	-4.96	-4.94			0.000	0.000	-11.23	-6.29	1358	34.4362166	-118.6496496	Valve Adjustment:High Temp
CV-24145	10/6/2026 8:30:00 AM					1890																	AtmAA
CV-24145	10/6/2026 8:30:00 AM						192300																AtmAA; [User entered 19.23%]
CV-24145	10/13/2026 9:05:00 AM					1810																	AtmAA
CV-24145	10/13/2026 9:05:57 AM	19.8	67.2	0.1	12.9			0.3	129.0	185.8	186.3	-7.36	-7.33			0.263	0.138	-14.74	-7.41	1352	34.4362332	-118.6496244	Valve Adjustment:High Temp
CV-24145	10/20/2026 8:29:22 AM	12.3	55.7	0.0	32.0			0.2	0.0	183.5	184.0	-6.23	-6.17			0.050	0.063	-11.84	-5.67	1358	34.4362300	-118.6496495	Valve Adjustment:High Temp
CV-24145	10/20/2026 8:37:00 AM					1450																	AtmAA
CV-24145	10/27/2026 7:48:00 AM					1480																	AtmAA
CV-24145	10/27/2026 7:48:16 AM	7.2	69.3	0.5	3.5		19.5	0.1	7.0	183.6	183.5	-11.00	-10.98	50.1	50.3	4.887	4.921	-6.31	4.67	1347	34.4362227	-118.6496248	Valve Adjustment:High Temp
CV-24146	10/11/2026 10:57:32 AM	53.8	42.0	0.0	4.3			1.3	0.0	114.0	114.1	-6.89	-7.03	26.0	26.2	0.896	0.912	-8.35	-1.32	1287	34.4374218	-118.6463783	Valve Adjustment:Increased Flow/Vacuum,Valve 100% Open
CV-24146	10/11/2026 10:58:21 AM	53.7	41.7	0.0	4.6			1.3	0.0	114.1	114.1	-6.99	-6.50	24.4	25.2	0.787	0.841	-7.86	-1.36	1295	34.4374145	-118.6463880	
CV-24146	10/26/2026 2:24:24 PM	53.2	39.9	0.1	6.8			1.3	68.0	115.0	115.0	-6.26	-6.29	25.5	27.1	0.853	0.959	-7.28	-0.99	1304	34.4374040	-118.6463803	Valve Adjustment:Valve 100% Open
CV-24147	10/11/2026 12:23:46 PM	51.7	41.8	0.0	6.5			1.2	0.0	114.0	114.0	-8.02	-8.35	8.6	11.4	0.020	0.035	-8.77	-0.42	1279	34.4375180	-118.6459748	
CV-24147	10/26/2026 2:32:01 PM	43.6	39.2	0.1	17.1			1.1	171.0	113.6	113.1	-7.36	-6.75	8.9	15.1	0.020	0.059	-7.90	-1.15	1269	34.4375210	-118.6459465	Valve Adjustment:Decreased Flow/Vacuum
CV-24148	10/8/2026 8:06:00 AM					1300																	AtmAA
CV-24148	10/8/2026 8:06:00 AM						45200																AtmAA; [User entered 4.52%]
CV-24148	10/8/2026 8:07:38 AM	25.2	74.8	0.0	0.0			0.3	0.0	170.4	170.5	-6.19	-6.18			6.533	6.525	-7.80	-1.62	1375	34.4350508	-118.6466810	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24148	10/14/2026 10:28:57 AM	33.0	66.9	0.0	0.1			0.5	0.0	170.2	170.7	-10.54	-10.45			11.009	10.907	-11.78	-1.33	1371	34.4350551	-118.6466685	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24148	10/14/2026 10:30:00 AM					931																	AtmAA
CV-24148	10/20/2026 1:01:45 PM	15.8	74.6	0.0	9.6			0.2	0.0	187.3	187.5	-4.25	-4.25			4.258	4.218	-8.25	-4	1396	34.4350322	-118.6466487	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24148	10/20/2026 1:05:00 PM					2190																	AtmAA
CV-24148	10/27/2026 9:25:00 AM					459																	AtmAA
CV-24148	10/27/2026 9:25:01 AM	25.3	61.2	0.0	13.5			0.4	0.0	178.9	178.9	-4.93	-4.72			4.925	5.279	-11.74	-7.02	1369	34.4350521	-118.6466708	Valve Adjustment:Other - See Daily Log,High Temp;Well Condition:Lorentz Pump Installed
CV-24149	10/6/2026 10:44:57 AM	29.3	62.9	0.1	7.7			0.5	77.0	130.7	130.8	-1.02	-1.03	17.0	14.8	0.076	0.058	-9.36	-8.33	1382	34.4347705	-118.6469770	Valve Adjustment:Barely Open
CV-24149	10/21/2026 10:11:53 AM	30.3	62.2	0.7	6.8			0.5	9.7	125.3	125.1	-1.00	-0.96	9.8	17.2	0.025	0.077	-6.86	-5.9	1391	34.4347792	-118.6469795	Valve Adjustment:Barely Open
CV-24150	10/14/2026 10:00:43 AM	52.0	44.5	0.4	3.1			1.2	7.8	98.0	99.1	-2.59	-2.59			2.565	2.558	-14.21	-11.62	1389	34.4346133	-118.6457270	
CV-24150	10/23/2026 12:57:21 PM	50.2	49.4	0.0	0.4			1.0	0.0	107.4	76.6	-1.38	-1.37			1.364	1.356	-11.04	-9.67	1383	34.4345897	-118.6457595	
CV-24151	10/6/2026 9:38:28 AM	44.0	53.9	0.0	2.1			0.8	0.0	119.0	119.2	-4.47	-3.73			4.480	3.733	-9.41	-5.68	1368	34.4344147	-118.6476165	Valve Adjustment:Decreased Flow/Vacuum
CV-24151	10/21/2026 8:48:45 AM	48.8	50.6	0.1	0.5			1.0	5.0	94.6	94.6	-0.85	-0.89			0.831	0.834	-5.37	-4.48	1382	34.4344072	-118.6476175	Valve Adjustment:Barely Open
CV-24152	10/6/2026 10:33:25 AM	20.9	69.6	0.1	9.4			0.3	94.0	145.3	145.5	-1.53	-1.21	31.7	28.4	2.458	1.978	-6.36	-5.15	1386	34.4344493	-118.6471642	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24152	10/12/2026 1:24:58 PM	24.1	75.9	0.0	0.0			0.3	0.0	143.5	143.5	-2.85	-2.82			0.000	0.000	-9.61	-6.79	1382	34.4344253	-118.6471452	Well Condition:Lorentz Pump Installed
CV-24152	10/21/2026 9:13:13 AM	19.6	75.7	0.3	4.4			0.3	14.7	143.0	143.0	-0.55	-0.50	25.8	24.8	1.628	1.495	-4.64	-4.14	1389	34.4344565	-118.6471782	Valve Adjustment:High Temp,Barely Open
CV-24153	10/14/2026 9:10:54 AM	48.4	49.4	0.0	2.2			1.0	0.0	101.3	101.4	-3.54	-3.54			3.481	3.476	-14.18	-10.64	1392	34.4343637	-118.6463988	
CV-24153	10/28/2026 10:35:24 AM	34.4	65.1	0.0	0.5			0.5	0.0	125.5	96.4	-2.56	-2.38			2.555	2.387	-11.86	-9.48	1391	34.4343745	-118.6464210	Valve Adjustment:Decreased Flow/Vacuum
CV-24154	10/5/2026 10:26:46 AM	49.9	44.9	2.0	3.2			1.1	1.6	108.3	110.8	-3.63	-3.25			3.587	3.223	0.59	3.84	1400	34.4342587	-118.6460838	
CV-24154	10/19/2026 1:25:47 PM	44.5	52.4	0.0	3.1			0.8	0.0	105.2	104.4	-2.75	-1.50			2.737	1.513	-3.76	-2.26	1396	34.4342617	-118.6460785	Valve Adjustment:Decreased Flow/Vacuum
CV-24154	10/19/2026 1:27:05 PM	44.0	52.4	0.0	3.6			0.8	0.0	104.8	104.6	-1.35	-1.35			1.353	1.361	-5.19	-3.84	1398	34.4342588	-118.6460848	Valve Adjustment:Barely Open,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-24154	10/27/2026 3:12:02 PM	37.3	60.1	0.1	2.5			0.6	25.0	111.1	111.2	-2.50	-2.48			2.518	2.504	-13.38	-10.9	1370	34.4343558	-118.6464210	Valve Adjustment:Barely Open
CV-24155	10/6/2026 10:50:19 AM	39.5	46.9	0.0	13.6			0.8	0.0	129.6	129.7	-1.89	-1.76			1.867	1.747	-8.99	-7.23	1387	34.4343055	-118.6466925	Valve Adjustment:Decreased Flow/Vacuum
CV-24155	10/21/2026 9:00:18 AM	31.3	50.0	0.2	18.5			0.6	92.5	113.8	113.2	-2.77	-2.45			2.759	2.459	-5.96	-3.51	1388	34.4342820	-118.6467182	Valve Adjustment:Decreased Flow/Vacuum
CV-24156	10/6/2026 9:07:16 AM	25.6	69.2	0.0	5.2			0.4	0.0	137.0	137.1	-2.31	-2.31	48.1	50.0	0.617	0.668	-10.55	-8.24	1362	34.4340580	-118.6476863	Well Condition:Lorentz Pump Installed
CV-24156	10/20/2026 2:00:07 PM	23.9	71.9	0.2	4.0			0.3	20.0	137.3	137.3	-0.91	-0.91	53.3	53.1	0.758	0.751	-10.10	-9.19	1370	34.4340773	-118.6477162	Valve Adjustment:High Temp,Barely Open
CV-24157	10/13/2026 9:54:23 AM	47.8	48.5	0.0	3.7			1.0	0.0	88.4	88.7	-3.59	-3.59			3.327	3.295	-15.75	-12.16	1391	34.4338025	-118.6473227	Well Condition:Lorentz Pump Installed
CV-24157	10/20/2026 2:16:38 PM	49.7	47.8	0.1	2.4			1.0	24.0	107.1	107.0	-1.52	-1.49			1.463	1.457	-10.84	-9.35	1381	34.4337802	-118.6473482	Valve Adjustment:Barely Open
CV-24158	10/6/2026 9:55:20 AM	34.5	65.5	0.0	0.0			0.5	0.0	129.7	129.7	-1.97	-1.96	12.1	11.7	0.404	0.378	-10.38	-8.42	1403	34.4339060	-118.6470513	

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24158	10/28/2026 10:57:48 AM	32.4	64.8	0.0	2.8			0.5	0.0	128.4	128.2	-3.98	-3.97	13.3	12.7	0.494	0.451	-14.93	-10.96	1406	34.4339228	-118.6470583	
CV-24159	10/5/2026 8:12:22 AM	29.3	70.7	0.0	0.0			0.4	0.0	94.5	95.5	-0.54	-0.56	3.4	2.4	0.026	0.013	-0.52	0.04	1400	34.4337778	-118.6466640	Valve Adjustment:Barely Open
CV-24159	10/16/2026 1:28:43 PM	37.0	55.0	0.0	8.0			0.7	0.0	128.8	129.2	-1.25	-1.30	10.9	13.2	0.281	0.414	-5.66	-4.36	1397	34.4337762	-118.6466325	Valve Adjustment:Barely Open
CV-24160	10/5/2026 10:21:24 AM	50.0	48.0	0.0	2.0			1.0	0.0	127.9	128.0	-1.28	-1.29	13.9	14.5	0.460	0.496	-8.18	-6.89	1429	34.4337700	-118.6463337	Valve Adjustment:Barely Open
CV-24160	10/19/2026 1:09:34 PM	50.4	43.6	0.0	6.0			1.2	0.0	126.8	127.4	-1.24	-1.22	7.1	7.3	0.322	0.345	-8.94	-7.72	1395	34.4337707	-118.6463065	
CV-24160	10/22/2026 9:23:28 AM	48.5	51.5	0.0	0.0			0.9	0.0	115.6	115.9	-0.70	-0.74	6.8	9.9	0.107	0.225	-3.00	-2.26	1400	34.4337973	-118.6462587	Valve Adjustment:Increased Flow/Vacuum
CV-24161	10/16/2026 2:08:44 PM	38.7	48.6	0.0	12.7			0.8	0.0	121.1	121.1	-4.04	-4.25			3.936	4.440	-0.04	4.21	1391	34.4338800	-118.6455790	Valve Adjustment:Increased Flow/Vacuum
CV-24162	10/2/2026 10:15:26 AM	42.7	40.5	0.2	16.6			1.1	75.5	102.9	103.6	-2.96	-3.10			2.984	3.112	-18.65	-15.55	1372	34.4335697	-118.6451063	Valve Adjustment:Increased Flow/Vacuum
CV-24163	10/2/2026 10:37:25 AM	39.6	55.7	0.0	4.7			0.7	0.0	129.0	129.1	-1.81	-2.22			1.808	2.214	-17.59	-15.37	1346	34.4334538	-118.6444853	Valve Adjustment:Increased Flow/Vacuum
CV-24164	10/5/2026 1:22:17 PM	21.1	70.5	0.2	8.2			0.3	41.0	137.4	137.5	-0.22	-0.22	9.6	9.5	0.222	0.216	-9.32	-9.1	1363	34.4334727	-118.6479822	Valve Adjustment:Barely Open
CV-24164	10/20/2026 1:23:41 PM	19.7	76.2	0.2	3.9			0.3	19.5	135.5	136.1	-0.13	-0.13	6.7	6.9	0.108	0.115	-11.19	-11.06	1350	34.4334595	-118.6479863	Valve Adjustment:Barely Open
CV-24165	10/13/2026 8:51:02 AM	29.9	55.4	0.0	14.7			0.5	0.0	97.2	103.9	-15.29	-7.72			15.345	7.923	-15.38	-7.66	1396	34.4335297	-118.6472665	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24165	10/13/2026 8:53:23 AM	32.8	54.8	0.0	12.5			0.6	0.0	103.4	103.3	-7.39	-7.39			7.481	7.484	-14.45	-7.06	1393	34.4335230	-118.6472758	Well Condition:Lorentz Pump Installed
CV-24165	10/28/2026 10:43:12 AM	26.8	70.6	0.0	2.6			0.4	0.0	130.2	130.2	-6.30	-6.10			6.844	6.798	-14.57	-8.47	1403	34.4335590	-118.6472620	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24166	10/5/2026 9:51:28 AM	50.1	44.8	0.0	5.1			1.1	0.0	120.5	120.5	-8.10	-8.10			8.473	8.473	-11.19	-3.09	1398	34.4335953	-118.6468950	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24166	10/28/2026 10:54:08 AM	45.1	46.3	0.0	8.6			1.0	0.0	118.1	114.9	-9.49	-7.50			10.157	8.099	-13.75	-6.25	1407	34.4335747	-118.6468822	Valve Adjustment:Decreased Flow/Vacuum
CV-24167	10/14/2026 7:34:51 AM	37.3	37.2	0.0	25.5			1.0	0.0	116.9	116.9	-14.87	-14.97			14.811	14.883	-16.16	-1.19	1425	34.4335150	-118.6464808	
CV-24167	10/16/2026 1:33:35 PM	36.3	39.5	0.0	24.2			0.9	0.0	119.4	119.6	-12.49	-12.47			12.537	12.447	-13.66	-1.19	1408	34.4334850	-118.6464742	Valve Adjustment:Valve 100% Open
CV-24168	10/5/2026 9:36:47 AM	20.0	78.5	0.0	1.5			0.3	0.0	132.0	131.7	0.46	-0.66			0.000	0.644	-6.02	-5.36	1403	34.4332787	-118.6473237	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum
CV-24168	10/5/2026 9:37:34 AM	21.4	77.1	0.0	1.5			0.3	0.0	132.4	132.7	-0.60	-0.60			0.579	0.579	-4.76	-4.16	1393	34.4332885	-118.6473277	Valve Adjustment:NSPS/EG CAC,High Temp,Barely Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
CV-24168	10/16/2026 2:27:21 PM	36.7	50.6	0.0	12.7			0.7	0.0	121.2	123.6	-3.92	-3.92			3.903	3.927	-11.73	-7.81	1398	34.4332898	-118.6473063	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24169	10/5/2026 1:19:32 PM	15.4	59.7	0.2	24.7			0.3	123.5	122.7	122.7	-1.63	-1.64			1.640	1.625	-9.38	-7.74	1387	34.4332047	-118.6477187	Valve Adjustment:Barely Open
CV-24169	10/16/2026 2:24:06 PM	27.0	37.0	0.1	35.9			0.7	359.0	118.1	118.1	-2.61	-2.59			2.599	2.609	-14.92	-12.33	1380	34.4331987	-118.6477078	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24170	10/5/2026 1:12:37 PM	4.8	83.4	0.1	11.7			0.1	117.0	133.0	133.0	-0.65	-0.64	12.0	10.1	0.093	0.066	-7.84	-7.2	1359	34.4331113	-118.6485112	Valve Adjustment:Barely Open
CV-24170	10/20/2026 9:44:45 AM	4.3	86.9	0.5	8.3			0.0	16.6	130.2	130.3	-1.40	-1.42	13.2	14.7	0.113	0.141	-13.18	-11.76	1363	34.4331138	-118.6485197	Valve Adjustment:Barely Open
CV-24171	10/5/2026 10:08:31 AM	2.2	1.0	19.9	76.9			2.2	3.9	126.7	126.5	-3.05	-2.76	24.4	19.3	0.791	0.495	-13.09	-10.33	1397	34.4331625	-118.6466415	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open
CV-24171	10/5/2026 10:10:10 AM	5.9	3.7	18.3	72.1			1.6	3.9	126.3	126.2	-2.57	-2.57	19.2	19.2	0.491	0.489	-12.93	-10.36	1397	34.4331585	-118.6466408	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24171	10/7/2026 1:11:13 PM	49.0	48.0	0.0	3.0			1.0	0.0	126.8	127.6	-0.02	-0.01	24.2	24.0	0.776	0.764	-6.49	-6.48	1385	34.4331618	-118.6466500	Valve Adjustment:NSPS/EG CAC,Barely Open
CV-24171	10/16/2026 1:46:59 PM	50.8	46.2	0.0	3.0			1.1	0.0	126.2	126.1	-3.70	-3.70	33.0	33.3	1.445	1.476	-16.30	-12.6	1405	34.4331755	-118.6466190	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24172	10/5/2026 8:42:40 AM	42.1	41.4	1.9	14.6			1.0	7.7	122.1	122.0	-0.25	-0.25	9.5	9.4	0.244	0.243	-13.99	-13.74	1388	34.4329647	-118.6473105	Valve Adjustment:Barely Open
CV-24172	10/16/2026 2:03:51 PM	44.2	40.6	0.9	14.3			1.1	15.9	124.3	124.2	-0.16	-0.15	3.3	6.4	0.030	0.111	-16.81	-16.66	1388	34.4329655	-118.6473010	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24173	10/5/2026 8:55:14 AM	9.9	86.5	0.0	3.6			0.1	0.0	134.8	134.8	-0.56	-0.57	14.7	15.2	0.518	0.552	-13.79	-13.22	1388	34.4328685	-118.6476800	Valve Adjustment:High Temp,Barely Open
CV-24173	10/16/2026 2:10:21 PM	17.8	74.2	0.0	8.0			0.2	0.0	133.5	133.2	-0.51	-0.46	16.5	15.6	0.648	0.580	-17.13	-16.67	1386	34.4328793	-118.6476612	Valve Adjustment:High Temp,Barely Open
CV-24174	10/5/2026 9:14:59 AM	27.6	39.6	0.0	32.8			0.7	0.0	114.3	112.8	-1.22	-1.22			1.204	1.208	-12.96	-11.74	1393	34.4327035	-118.6480697	Valve Adjustment:Barely Open
CV-24174	10/16/2026 12:56:19 PM	18.0	36.4	0.0	45.6			0.5	0.0	125.5	123.0	-2.46	-1.15			2.442	1.207	-16.20	-15.05	1380	34.4327208	-118.6480285	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24175	10/5/2026 9:19:51 AM	25.0	69.9	0.0	5.1			0.4	0.0	121.4	121.4	-1.00	-1.01	7.2	7.4	0.140	0.148	-12.60	-11.59	1388	34.4325927	-118.6484772	Valve Adjustment:Barely Open

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24175	10/16/2026 2:15:19 PM	21.7	59.9	0.0	18.4			0.4	0.0	120.3	120.2	-0.37	-0.84	12.9	7.2	0.452	0.142	-16.57	-15.73	1373	34.4326382	-118.6484562	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24176	10/13/2026 7:57:31 AM	21.5	34.8	0.0	43.7			0.6	0.0	123.0	119.4	-10.88	-5.85	77.8	17.6	4.029	0.202	-14.51	-8.66	1345	34.4326040	-118.6489007	Valve Comment:No smaller OP available;Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24176	10/13/2026 7:59:50 AM	15.4	30.8	0.0	53.8			0.5	0.0	118.3	118.7	-5.38	-5.67	24.3	28.3	0.382	0.517	-16.05	-10.38	1350	34.4326015	-118.6488982	Valve Adjustment:Increased Flow/Vacuum
CV-24176	10/13/2026 8:02:48 AM	18.2	33.3	0.0	48.6			0.5	0.0	120.4	120.7	-7.39	-7.39	56.6	59.8	2.094	2.347	-16.62	-9.23	1342	34.4325963	-118.6489020	Valve Adjustment:Increased Flow/Vacuum
CV-24176	10/13/2026 8:04:26 AM	19.6	34.6	0.0	45.9			0.6	0.0	121.2	121.2	-7.72	-7.72	58.5	56.9	2.247	2.124	-17.62	-9.9	1351	34.4326063	-118.6488838	Well Condition:Lorentz Pump Installed
CV-24176	10/20/2026 8:43:13 AM	22.1	34.6	0.0	43.3			0.6	0.0	123.9	122.1	-6.42	-4.14	51.4	21.6	1.740	0.303	-14.39	-10.25	1342	34.4325910	-118.6488907	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24176	10/20/2026 8:47:05 AM	20.9	32.3	0.0	46.8			0.6	0.0	121.8	121.9	-4.32	-4.32	27.9	28.8	0.505	0.538	-13.91	-9.59	1337	34.4325617	-118.6488920	Well Condition:Lorentz Pump Installed
CV-24177	10/1/2026 12:17:47 PM	10.1	70.0	0.0	19.9			0.1	0.0	112.7	112.6	0.04	-0.38	0.0	0.0	-0.075	0.466	-1.21	-0.83	1325	34.4321932	-118.6493842	NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
CV-24177	10/1/2026 12:18:53 PM	9.5	78.3	0.0	12.2			0.1	0.0	112.5	112.6	-0.47	-0.49	0.0	0.0	0.584	0.582	-1.05	-0.56	1319	34.4322452	-118.6493423	NSPS/EG CAC,
CV-24177	10/20/2026 9:10:56 AM	5.1	12.3	13.6	69.0			0.4	5.1	111.0	110.5	-10.48	-0.71			10.750	0.701	-15.13	-14.42	1296	34.4322325	-118.6494693	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open;Well Repairs:Sample Port
CV-24177	10/20/2026 9:12:54 AM	2.8	11.9	15.7	69.7			0.2	4.4	109.5	109.4	-0.40	-0.40			0.391	0.387	-15.62	-15.22	1317	34.4322455	-118.6494535	Valve Adjustment:High O2;Well Condition:Lorentz Pump Installed
CV-24178	10/6/2026 1:45:58 PM	27.4	47.2	0.3	25.1			0.6	83.7	134.4	134.4	-3.53	-3.05	38.6	30.1	4.227	2.558	-11.00	-7.95	1342	34.4323850	-118.6486078	Valve Adjustment:High Temp,Decreased Flow/Vacuum
CV-24178	10/20/2026 8:31:02 AM	24.5	39.3	0.1	36.0			0.6	277.2	122.2	111.8	-4.87	-2.50	36.4	5.9	3.689	0.094	-16.40	-13.9	1364	34.4323928	-118.6485902	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24178	10/20/2026 8:34:39 AM	20.0	31.7	0.0	48.3			0.6	0.0	108.0	106.7	-2.14	-2.12	4.8	5.3	0.062	0.074	-16.42	-14.3	1347	34.4323867	-118.6485990	Valve Adjustment:Barely Open
CV-24179	10/5/2026 1:22:35 PM	17.0	54.8	0.0	28.2			0.3	0.0	138.4	137.8	-1.26	-1.11	10.6	9.0	0.317	0.228	-10.69	-9.58	1314	34.4320982	-118.6491768	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open
CV-24179	10/5/2026 1:23:47 PM	16.5	55.8	0.0	27.7			0.3	0.0	137.8	137.8	-1.11	-1.11	9.0	9.8	0.224	0.267	-10.51	-9.4	1321	34.4321005	-118.6491990	
CV-24179	10/18/2026 1:40:49 PM	21.5	51.7	0.0	26.8			0.4	0.0	138.1	138.1	-0.62	-0.62	8.0	8.4	0.179	0.196	-13.41	-12.79	1310	34.4321143	-118.6492132	
CV-24180	10/6/2026 1:40:43 PM	1.9	8.9	17.7	71.5			0.2	4.0	107.2	107.2	-0.29	-0.28	2.3	2.3	0.014	0.014	-10.12	-9.84	1337	34.4321397	-118.6488213	Valve Adjustment:High O2,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24180	10/6/2026 1:41:19 PM	2.0	9.5	17.5	71.0			0.2	4.1	107.2	107.2	-0.29	-0.29	4.5	4.7	0.054	0.059	-10.12	-9.83	1335	34.4321342	-118.6488352	Valve Adjustment:Barely Open
CV-24180	10/7/2026 1:16:31 PM	16.2	65.1	0.0	18.7			0.2	0.0	127.8	127.7	-4.56	-4.25	16.0	15.9	0.717	0.709	-7.66	-3.41	1336	34.4321418	-118.6488257	Valve Adjustment:NSPS/EG CAC,Reduce Sys. Vac. - Flare Down;Well Condition:Pnumatic Pump Installed
CV-24180	10/7/2026 1:19:30 PM	16.5	64.3	0.0	19.2			0.3	0.0	127.7	127.6	-4.77	-4.04	15.0	15.9	0.631	0.707	-7.79	-3.75	1338	34.4321405	-118.6488257	Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Condition:Pnumatic Pump Installed
CV-24180	10/19/2026 10:25:42 AM	32.1	49.4	0.0	18.5			0.6	0.0	129.2	129.2	-7.53	-6.95	14.6	3.9	0.598	0.043	-13.82	-6.87	1348	34.4321262	-118.6488272	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum
CV-24181	10/6/2026 9:48:02 AM	41.8	43.1	0.0	15.1			1.0	0.0	125.4	123.0	-2.98	-2.20	89.2	25.1	7.138	0.552	-9.73	-7.53	1352	34.4321830	-118.6483805	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Surging Liquid in Header
CV-24181	10/16/2026 9:01:38 AM	27.8	44.1	0.0	28.1			0.6	0.0	109.6	107.5	-2.18	-2.06	36.5	27.3	1.139	0.634	-8.69	-6.63	1345	34.4321633	-118.6483903	Valve Adjustment:Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
CV-24182	10/11/2026 2:00:38 PM	28.9	38.1	0.6	32.4			0.8	54.9	82.7	85.0	-3.01	-3.01			3.038	3.036	-5.54	-2.53	1357	34.4322548	-118.6480742	
CV-24182	10/11/2026 2:01:09 PM	29.0	38.5	0.6	31.9			0.8	54.0	88.8	89.0	-3.00	-3.01			3.026	3.015	-5.44	-2.43	1357	34.4322617	-118.6480708	
CV-24182	10/21/2026 8:29:16 AM	30.0	40.0	0.6	29.4			0.8	47.3	111.7	106.2	-3.60	-1.10			3.610	1.094	-9.36	-8.26	1358	34.4322458	-118.6480657	Valve Adjustment:Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
CV-24182	10/21/2026 8:31:14 AM	29.3	38.3	0.2	32.2			0.8	139.9	104.2	103.4	-0.94	-0.96			0.940	0.965	-9.80	-8.84	1366	34.4322467	-118.6480708	Valve Adjustment:Barely Open,Reduce Sys. Vac. - Flare Down
CV-24183	10/6/2026 1:59:33 PM	47.5	46.7	0.0	5.8			1.0	0.0	114.6	114.7	-0.86	-0.86			0.837	0.837	-12.07	-11.21	1344	34.4323655	-118.6476707	Valve Adjustment:Barely Open
CV-24183	10/16/2026 9:19:49 AM	46.4	43.4	0.0	10.2			1.1	0.0	99.1	97.4	-2.17	-1.78			2.093	1.738	-15.42	-13.64	1358	34.4323370	-118.6476617	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Reduce Sys. Vac. - Flare Down
CV-24184	10/5/2026 1:48:34 PM	17.2	18.8	9.1	54.9			0.9	6.0	127.9	127.0	-0.82	-0.42	13.2	5.5	3.785	0.658	-11.36	-10.94	1372	34.4325085	-118.6472553	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-24184	10/5/2026 1:49:11 PM	16.7	17.7	9.5	56.1			0.9	5.9	127.1	127.1	-0.37	-0.37	5.6	5.6	0.674	0.678	-11.60	-11.23	1364	34.4325043	-118.6472537	

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24184	10/16/2026 9:52:16 AM	1.5	3.1	17.7	77.7			0.5	4.4	108.5	104.4	-0.42	-0.22	4.9	2.1	0.492	0.092	-15.26	-15.04	1352	34.4325262	-118.6472672	Valve Comment:Changed OP from 0.75 to 0.50;Valve Adjustment:NSPS/EG CAI,Orifice Plate Changed (See OP Log),High O2,Decreased Flow/Vacuum,Barely Open;Well Comment:No pump
CV-24184	10/16/2026 9:53:32 AM	1.5	3.1	17.7	77.7			0.5	4.4	102.1	102.0	-0.10	-0.12	2.2	2.1	0.094	0.090	-15.80	-15.68	1350	34.4325232	-118.6472752	
CV-24185	10/6/2026 2:05:47 PM	44.2	42.6	0.0	13.2			1.0	0.0	124.3	124.2	-1.16	-1.16	29.8	30.1	2.458	2.503	-12.05	-10.89	1360	34.4326693	-118.6469647	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-24185	10/20/2026 10:00:09 AM	46.4	41.9	0.0	11.7			1.1	0.0	121.6	121.3	-0.97	-0.70	27.0	20.9	1.994	1.193	-9.95	-9.25	1360	34.4326772	-118.6469565	Valve Adjustment:Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24185	10/20/2026 10:02:17 AM	44.8	45.4	0.0	9.8			1.0	0.0	121.5	121.0	-0.58	-0.58	16.9	16.8	0.782	0.770	-15.41	-14.83	1364	34.4326633	-118.6469430	Well Condition:Lorentz Pump Installed
CV-24186	10/6/2026 2:09:54 PM	41.6	38.6	1.5	18.3			1.1	12.2	128.5	128.4	-1.18	-1.17	47.3	46.0	1.459	1.375	-13.74	-12.57	1365	34.4328392	-118.6465602	Valve Adjustment:Barely Open
CV-24186	10/20/2026 9:51:14 AM	52.5	38.3	0.0	9.2			1.4	0.0	125.8	126.0	-2.23	-2.23	26.5	28.6	1.953	2.270	-20.08	-17.85	1372	34.4328193	-118.6465888	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24186	10/20/2026 9:52:40 AM	51.6	38.5	0.0	9.9			1.3	0.0	126.1	126.1	-2.25	-2.25	27.8	27.9	2.138	2.159	-6.36	-4.11	1359	34.4328258	-118.6465523	Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24187	10/5/2026 9:37:22 AM						17000																[User entered 1.7%]
CV-24187	10/5/2026 9:38:05 AM	43.9	45.9	0.0	10.2			1.0	0.0	128.3	128.4	-1.17	-1.15	13.5	13.8	0.505	0.528	-12.19	-11.04	1313	34.4318655	-118.6495982	
CV-24187	10/18/2026 1:18:23 PM	41.8	40.1	0.0	18.1			1.0	0.0	128.0	127.4	-0.83	-0.45	13.8	9.4	0.526	0.245	-12.69	-12.24	1289	34.4318828	-118.6495912	Valve Adjustment:Decreased Flow/Vacuum
CV-24187	10/18/2026 1:20:38 PM	42.6	43.1	0.0	14.3			1.0	0.0	126.9	127.0	-0.26	-0.28	6.8	7.0	0.128	0.133	-12.22	-11.94	1276	34.4319122	-118.6495835	
CV-24188	10/5/2026 9:52:49 AM						26000																[User entered 2.6%]
CV-24188	10/5/2026 9:54:37 AM	51.5	44.0	0.0	4.5			1.2	0.0	118.0	119.1	-1.22	-2.38	7.6	13.6	0.154	0.500	-12.89	-10.51	1267	34.4315343	-118.6501262	Valve Adjustment:Increased Flow/Vacuum
CV-24188	10/5/2026 9:56:38 AM	50.3	45.8	0.0	4.0			1.1	0.0	119.2	119.3	-2.89	-3.08	14.0	14.4	0.533	0.566	-12.44	-9.36	1270	34.4315012	-118.6501248	
CV-24188	10/21/2026 9:41:23 AM	51.4	45.6	0.0	3.0			1.1	0.0	115.9	115.8	-1.67	-1.68	6.4	6.3	0.110	0.106	-9.53	-7.85	1268	34.4315092	-118.6500997	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24189	10/5/2026 10:08:11 AM						35000																[User entered 3.5%]
CV-24189	10/5/2026 10:08:41 AM	46.7	41.5	0.0	11.8			1.1	0.0	120.4	120.6	-3.09	-3.08	11.8	12.0	2.960	3.095	-12.72	-9.64	1260	34.4313010	-118.6499988	
CV-24189	10/21/2026 9:31:02 AM	39.4	34.6	0.4	25.6			1.1	63.9	115.9	111.2	-2.70	-1.61	10.2	3.3	2.187	0.231	-9.26	-7.65	1270	34.4313108	-118.6499943	Valve Adjustment:Decreased Flow/Vacuum
CV-24189	10/21/2026 9:36:32 AM	41.6	36.4	0.7	21.3			1.1	30.5	106.2	104.1	-1.20	-0.97	3.3	2.2	1.177	0.518	-9.70	-8.73	1266	34.4312975	-118.6499825	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
CV-24189	10/21/2026 9:37:35 AM	43.3	36.7	0.8	19.2			1.2	24.6	103.6	103.1	-0.89	-0.89	2.3	2.4	0.551	0.593	-9.54	-8.65	1269	34.4313048	-118.6499802	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24190	10/5/2026 10:22:41 AM	50.9	45.0	0.0	4.1			1.1	0.0	123.8	125.5	-0.21	-1.31	2.6	14.1	0.018	0.544	-11.84	-10.53	1313	34.4315822	-118.6494813	Valve Adjustment:Increased Flow/Vacuum
CV-24190	10/5/2026 10:24:47 AM						38000																[User entered 3.8%]
CV-24190	10/5/2026 10:25:56 AM	50.7	45.3	0.0	4.1			1.1	0.0	126.0	125.7	-1.78	-1.36	18.3	15.0	0.922	0.621	-11.73	-10.37	1308	34.4316010	-118.6494755	Valve Adjustment:Decreased Flow/Vacuum
CV-24190	10/5/2026 10:27:25 AM	50.4	44.8	0.0	4.8			1.1	0.0	125.7	125.9	-1.66	-1.69	13.5	13.9	0.504	0.534	-11.78	-10.09	1313	34.4315833	-118.6494730	
CV-24190	10/20/2026 7:50:18 AM	52.7	44.3	0.0	3.1			1.2	0.0	122.8	122.9	-3.69	-3.97	9.5	15.2	0.247	0.638	-15.42	-11.45	1307	34.4315867	-118.6494920	Valve Adjustment:Increased Flow/Vacuum
CV-24190	10/20/2026 7:56:48 AM	50.0	45.8	0.0	4.2			1.1	0.0	122.7	123.1	-4.39	-4.45	13.6	14.7	0.514	0.600	-15.53	-11.08	1309	34.4315695	-118.6494952	Valve Adjustment:Plugged/Pinched Suspected
CV-24192	10/5/2026 10:14:19 AM						42000																[User entered 4.2%]
CV-24192	10/5/2026 10:14:47 AM	52.0	41.3	0.0	6.7			1.3	0.0	121.7	121.3	-11.29	-11.01	18.3	20.6	0.450	0.567	-11.99	-0.98	1294	34.4313203	-118.6495047	Valve Adjustment:Increased Flow/Vacuum
CV-24192	10/5/2026 10:15:42 AM	51.1	42.4	0.0	6.5			1.2	0.0	121.0	121.3	-11.31	-10.64	20.4	21.9	0.559	0.643	-12.11	-1.47	1295	34.4313195	-118.6494982	
CV-24192	10/20/2026 8:01:09 AM	51.1	41.1	0.0	7.8			1.2	0.0	120.0	120.1	-15.55	-15.54	22.4	23.7	0.679	0.765	-17.12	-1.58	1305	34.4313343	-118.6495118	Valve Adjustment:Increased Flow/Vacuum,Valve 100% Open
CV-24192	10/20/2026 8:02:14 AM	50.0	42.6	0.0	7.4			1.2	0.0	120.0	120.0	-15.73	-15.55	24.3	23.1	0.802	0.725	-17.01	-1.46	1305	34.4313302	-118.6495103	Valve Adjustment:Valve 100% Open
CV-24193	10/5/2026 10:35:49 AM						44000																[User entered 4.4%]
CV-24193	10/5/2026 10:37:19 AM	51.2	42.4	0.0	6.3			1.2	0.0	120.7	120.7	-10.31	-10.84	8.7	9.4	0.101	0.118	-12.23	-1.39	1325	34.4314955	-118.6490677	Valve Adjustment:Increased Flow/Vacuum,Plugged/Pinched Suspected
CV-24193	10/5/2026 10:38:01 AM	51.0	42.1	0.0	6.9			1.2	0.0	120.7	120.6	-11.11	-11.13	8.7	8.5	0.100	0.096	-12.30	-1.17	1334	34.4315075	-118.6490523	
CV-24193	10/19/2026 1:45:01 PM	52.9	42.6	0.0	4.5			1.2	0.0	117.8	117.8	-12.05	-12.05	9.9	9.9	0.172	0.172	-13.93	-1.88	1326	34.4315000	-118.6490687	Valve Adjustment:Audible Flow
CV-24194	10/6/2026 9:53:09 AM	50.7	43.5	0.0	5.8			1.2	0.0	108.7	109.0	-3.47	-4.23	7.8	9.5	1.283	1.884	-13.45	-9.22	1351	34.4318648	-118.6485003	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-24194	10/16/2026 1:23:17 PM	49.7	45.3	0.0	5.0			1.1	0.0	109.1	109.2	-4.96	-5.20	10.7	12.2	2.420	3.150	-16.61	-11.41	1353	34.4318547	-118.6485125	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
CV-24195	10/6/2026 10:06:39 AM	48.7	44.5	0.0	6.8			1.1	0.0	121.3	121.4	-1.17	-1.17	6.5	6.4	0.908	0.869	-13.07	-11.9	1355	34.4318503	-118.6478635	Valve Adjustment:Audible Flow

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24195	10/16/2026 1:36:19 PM	48.1	44.3	0.0	7.6			1.1	0.0	121.0	121.1	-0.16	-0.14	8.6	8.7	1.550	1.593	-16.83	-16.69	1352	34.4318360	-118.6478463	Valve Adjustment:Barely Open
CV-24196	10/7/2026 9:36:39 AM	45.3	49.2	0.0	5.6			0.9	0.0	125.6	125.7	-1.19	-1.19	4.0	5.4	0.021	0.038	-10.49	-9.3	1338	34.4320550	-118.6471742	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24196	10/16/2026 9:36:22 AM	44.5	49.1	0.0	6.4			0.9	0.0	124.4	122.8	-1.95	-1.40	12.4	5.1	0.201	0.034	-15.36	-13.96	1342	34.4320583	-118.6471862	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24197	10/7/2026 9:44:53 AM	45.9	44.6	0.0	9.5			1.0	0.0	129.5	129.3	-1.30	-1.30	18.3	18.5	0.930	0.945	-10.60	-9.3	1340	34.4323805	-118.6465672	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24197	10/20/2026 9:38:33 AM	43.7	42.0	0.0	14.3			1.0	0.0	127.3	126.1	-1.91	-1.48	23.9	13.5	1.582	0.506	-19.55	-18.07	1355	34.4323492	-118.6465955	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24197	10/20/2026 9:39:51 AM	42.9	42.0	0.0	15.2			1.0	0.0	125.9	125.8	-1.40	-1.40	13.5	13.8	0.503	0.527	-19.62	-18.22	1355	34.4323378	-118.6465795	
CV-24198	10/11/2026 1:47:56 PM	41.7	39.7	0.0	18.6			1.0	0.0	124.5	124.4	-1.08	-1.17	9.7	8.9	0.616	0.515	-6.97	-5.8	1333	34.4315613	-118.6475893	Valve Adjustment:Decreased Flow/Vacuum
CV-24198	10/11/2026 1:50:00 PM	41.4	40.5	0.0	18.1			1.0	0.0	123.2	123.4	-0.92	-0.94	8.0	7.6	1.371	1.235	-6.68	-5.74	1331	34.4315632	-118.6475907	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-24198	10/26/2026 11:24:40 AM	42.6	39.0	0.0	18.4			1.1	0.0	126.6	125.6	-0.69	-0.30	11.1	6.1	2.661	0.788	-12.66	-12.36	1321	34.4315423	-118.6475837	Valve Adjustment:Decreased Flow/Vacuum
CV-24198	10/26/2026 11:25:54 AM	42.6	39.6	0.0	17.8			1.1	0.0	125.4	125.3	-0.22	-0.21	5.7	5.9	0.698	0.733	-12.62	-12.41	1316	34.4315500	-118.6475990	Valve Adjustment:Barely Open
CV-24199	10/11/2026 1:43:42 PM	44.1	41.0	0.0	15.0			1.1	0.0	126.5	126.3	-1.42	-1.44	20.0	21.0	2.627	2.894	-6.52	-5.08	1332	34.4317798	-118.6473228	
CV-24199	10/21/2026 12:06:25 PM	40.6	39.3	0.0	20.1			1.0	0.0	127.2	124.6	-1.92	-0.52	31.9	8.8	6.679	0.501	-15.21	-14.69	1341	34.4317500	-118.6472990	Valve Adjustment:Decreased Flow/Vacuum
CV-24199	10/21/2026 12:07:22 PM	47.0	42.2	0.0	10.8			1.1	0.0	124.9	124.7	-0.31	-0.32	10.8	10.8	0.748	0.751	-15.70	-15.38	1327	34.4317660	-118.6473162	
CV-24200	10/12/2026 10:17:15 AM	49.1	41.8	0.0	9.2			1.2	0.0	120.2	120.4	-1.44	-1.53	12.1	12.9	1.670	1.889	-16.62	-15.09	1282	34.4314510	-118.6472310	Valve Adjustment:Increased Flow/Vacuum
CV-24200	10/12/2026 10:19:58 AM	48.5	41.6	0.0	9.9			1.2	0.0	120.4	120.3	-1.58	-1.58	13.1	12.9	1.903	1.842	-16.68	-15.1	1284	34.4314435	-118.6472347	
CV-24200	10/26/2026 11:16:36 AM	47.7	38.8	0.0	13.5			1.2	0.0	121.3	121.2	-0.89	-0.86	15.8	14.5	1.580	1.342	-12.81	-11.95	1280	34.4314282	-118.6472140	Valve Adjustment:Decreased Flow/Vacuum
CV-24200	10/26/2026 11:17:56 AM	46.4	39.8	0.0	13.8			1.2	0.0	121.3	121.1	-0.76	-0.76	12.5	12.4	1.000	0.984	-12.77	-12.01	1280	34.4314372	-118.6472218	
CV-24201	10/7/2026 12:30:34 PM	47.0	47.5	0.0	5.5			1.0	0.0	129.2	129.3	1.55	1.54	8.3	8.4	0.190	0.193	-8.12	-9.66	1282	34.4317565	-118.6466512	Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Condition:Pnumatic Pump Installed
CV-24201	10/12/2026 10:01:01 AM	49.2	47.3	0.0	3.5			1.0	0.0	136.7	136.6	-3.55	-3.43	23.9	22.8	1.618	1.469	-16.80	-13.37	1275	34.4317408	-118.6466577	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24201	10/12/2026 10:07:26 AM	48.9	48.0	0.0	3.1			1.0	0.0	134.4	135.5	-2.75	-2.78	15.4	15.4	1.173	1.189	-16.13	-13.35	1283	34.4317447	-118.6466565	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24201	10/12/2026 10:10:17 AM	49.0	47.7	0.0	3.3			1.0	0.0	135.7	135.6	-2.88	-2.89	20.2	20.3	1.142	1.161	-16.20	-13.31	1276	34.4317430	-118.6466400	
CV-24201	10/21/2026 11:44:39 AM	49.4	46.0	0.0	4.7			1.1	0.0	133.8	132.5	-2.63	-1.58	22.6	14.3	1.427	0.566	-16.81	-15.23	1272	34.4317518	-118.6466217	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24201	10/21/2026 11:46:35 AM	49.5	46.1	0.0	4.4			1.1	0.0	132.1	132.2	-1.40	-1.38	14.4	14.5	0.577	0.586	-16.91	-15.53	1280	34.4317397	-118.6466103	Valve Adjustment:High Temp
CV-24202	10/7/2026 12:52:32 PM	37.6	38.2	0.3	24.0			1.0	77.3	128.5	128.3	-1.19	-1.19			1.197	1.196	-8.03	-6.84	1277	34.4319498	-118.6462648	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24202	10/21/2026 11:31:05 AM	37.8	47.0	0.0	15.2			0.8	0.0	110.8	103.6	-1.67	-0.70			1.685	0.694	-11.62	-10.92	1299	34.4319163	-118.6462715	Valve Adjustment:Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
CV-24202	10/21/2026 11:33:16 AM	39.1	43.7	0.0	17.1			0.9	0.0	102.8	102.8	-0.63	-0.63			0.634	0.623	-15.26	-14.63	1291	34.4319105	-118.6462767	
CV-24203	10/7/2026 1:20:41 PM	53.8	44.6	0.0	1.6			1.2	0.0	124.6	125.3	0.32	-0.06	9.4	15.7	0.539	1.501	-5.58	-5.52	1247	34.4314840	-118.6458877	NSPS/EG CAI,Positive Static Press.,Reduced System Vacuum,Increased Flow/Vacuum
CV-24203	10/7/2026 1:22:01 PM	53.8	44.6	0.0	1.6			1.2	0.0	125.7	125.7	-0.25	-0.24	18.5	10.9	2.097	0.722	-4.58	-4.34	1276	34.4315870	-118.6459542	NSPS/EG CAC,
CV-24203	10/21/2026 11:11:12 AM	47.6	45.4	0.0	7.0			1.0	0.0	126.3	125.8	-1.51	-1.03	14.1	12.0	1.281	0.924	-7.58	-6.55	1252	34.4315353	-118.6459930	Valve Adjustment:Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24203	10/21/2026 11:13:17 AM	46.9	46.0	0.0	7.1			1.0	0.0	125.8	125.8	-1.00	-0.98	10.0	10.2	0.646	0.671	-8.72	-7.74	1250	34.4315388	-118.6459905	Well Condition:Lorentz Pump Installed
CV-24204	10/7/2026 1:24:28 PM	50.7	46.2	0.0	3.1			1.1	0.0	127.0	127.0	-2.82	-2.81	11.7	11.6	0.308	0.305	-8.41	-5.6	1243	34.4313332	-118.6461417	Reduced System Vacuum,
CV-24204	10/21/2026 11:04:31 AM	50.6	45.0	0.0	4.4			1.1	0.0	124.8	124.7	-3.94	-3.94	11.5	10.6	0.313	0.264	-9.11	-5.17	1235	34.4314163	-118.6462510	Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-24204	10/23/2026 2:53:18 PM	51.6	42.6	0.0	5.8			1.2	0.0	126.0	126.2	-5.71	-5.99	14.7	16.4	0.515	0.641	-14.88	-8.89	1242	34.4314307	-118.6462728	Valve Adjustment:Increased Flow/Vacuum
CV-24205	10/12/2026 10:29:39 AM	49.9	42.6	0.0	7.5			1.2	0.0	121.8	122.0	-6.38	-6.56	19.5	21.6	0.501	0.619	-16.85	-10.29	1232	34.4312333	-118.6464707	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24205	10/12/2026 10:33:06 AM	49.3	42.8	0.0	7.9			1.2	0.0	122.0	122.0	-6.52	-6.53	21.8	21.5	0.631	0.616	-16.41	-9.88	1232	34.4312257	-118.6464703	
CV-24205	10/21/2026 11:01:12 AM	48.0	38.7	0.0	13.3			1.2	0.0	121.3	121.2	-3.57	-3.62	22.7	23.6	0.675	0.730	-9.29	-5.67	1243	34.4312177	-118.6464755	Valve Adjustment:Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24206	10/7/2026 12:20:18 PM	48.1	44.6	0.0	7.3			1.1	0.0	114.2	114.7	-0.47	-0.47			0.459	0.463	-4.40	-3.93	1275	34.4315277	-118.6467975	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24206	10/21/2026 11:53:14 AM	37.9	40.2	0.0	21.9			0.9	0.0	83.5	84.8	-1.95	-0.85			1.954	0.849	-11.86	-11.01	1279	34.4314998	-118.6467502	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24206	10/21/2026 11:55:56 AM	37.8	40.2	0.0	22.0			0.9	0.0	84.8	84.7	-0.95	-0.95			0.957	0.958	-12.26	-11.31	1281	34.4315088	-118.6467700	Well Condition:Pnumatic Pump Installed
CV-24207	10/13/2026 9:17:29 AM	46.0	50.0	0.0	4.1			0.9	0.0	134.1	130.3	-11.08	-5.71	29.2	14.0	5.792	1.286	-16.46	-10.75	1391	34.4332648	-118.6469367	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24207	10/13/2026 9:21:58 AM	48.0	47.9	0.0	4.0			1.0	0.0	129.2	128.9	-5.37	-6.05	14.0	19.9	1.294	2.619	-16.21	-10.16	1398	34.4332830	-118.6469443	Valve Adjustment:Increased Flow/Vacuum
CV-24207	10/16/2026 1:42:03 PM	46.1	52.8	0.0	1.1			0.9	0.0	136.6	135.7	-1.68	-0.20	38.4	30.5	1.988	1.248	-15.02	-14.82	1399	34.4332727	-118.6469487	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Header
CV-24207	10/16/2026 1:43:12 PM	46.8	52.2	0.0	1.0			0.9	0.0	135.6	135.6	-0.27	-0.20	30.6	30.7	1.253	1.264	-15.00	-14.8	1391	34.4332818	-118.6469353	Valve Adjustment:High Temp,Barely Open
CV-24208	10/7/2026 1:10:45 PM	39.1	49.9	0.0	11.0			0.8	0.0	130.4	129.8	-1.32	-0.48	29.0	20.8	2.028	1.034	-7.40	-6.92	1234	34.4319692	-118.6451693	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-24208	10/7/2026 1:11:55 PM	40.2	52.3	0.0	7.5			0.8	0.0	129.8	129.8	-0.38	-0.38	20.8	20.8	1.043	1.043	-7.38	-7	1224	34.4319732	-118.6452162	NSPS/EG CAC,Reduced System Vacuum
CV-24209	10/7/2026 10:53:50 AM	8.0	66.6	0.0	25.4			0.1	0.0	122.1	122.4	-0.25	-0.22	0.0	0.0	0.085	0.087	-8.07	-7.85	1280	34.4321392	-118.6455367	Reduced System Vacuum,
CV-24209	10/27/2026 7:50:00 AM					196																	AtmAA
CV-24209	10/27/2026 7:50:00 AM						12500																AtmAA; [User entered 1.25%]
CV-24209	10/27/2026 7:57:22 AM						0																[User entered 0%]
CV-24209	10/27/2026 8:02:43 AM	17.4	40.8	0.2	41.6			0.4	244.8	105.9	104.6	-10.98	-1.93			11.042	1.932	-12.93	-11	1301	34.4321965	-118.6456122	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-24209	10/27/2026 8:05:32 AM	10.4	35.4	0.0	54.2			0.3	0.0	102.6	102.6	-2.01	-2.01			2.023	2.021	-13.54	-11.53	1293	34.4321852	-118.6456072	Well Condition:Pnumatic Pump Installed
CV-24210	10/7/2026 10:23:50 AM	34.3	37.7	0.0	28.0			0.9	0.0	115.8	117.1	-7.17	-6.86	0.0	0.0	7.142	6.789	-7.87	-1.01	1293	34.4326153	-118.6456165	Reduced System Vacuum,
CV-24211	10/5/2026 9:09:21 AM						0																
CV-24211	10/5/2026 9:11:47 AM	17.5	69.1	0.0	13.4			0.3	0.0	125.9	126.6	-12.08	-2.48			12.297	2.492	-19.90	-17.42	1284	34.4326920	-118.6438595	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed;Well Repairs:Sample Port
CV-24211	10/5/2026 9:13:45 AM	15.7	67.4	0.0	16.9			0.2	0.0	126.7	126.6	-1.82	-1.83			1.820	1.836	-19.90	-18.07	1263	34.4327110	-118.6438488	
CV-24211	10/16/2026 1:20:04 PM	14.9	85.1	0.0	0.0			0.2	0.0	119.6	119.9	-5.23	-5.31			5.273	5.240	-21.11	-15.8	1259	34.4327057	-118.6438438	Valve Adjustment:Increased Flow/Vacuum
CV-24212	10/16/2026 1:35:57 PM	7.1	74.6	2.1	16.2			0.1	7.7	120.9	123.6	-3.96	-4.00			3.845	3.810	-17.90	-13.9	1245	34.4331677	-118.6430517	Valve Adjustment:Increased Flow/Vacuum
CV-24213	10/7/2026 1:38:07 PM	42.2	45.7	0.0	12.1			0.9	0.0	120.7	121.5	0.76	-0.06	0.0	0.0	-0.757	0.169	-3.55	-3.49	1312	34.4364662	-118.6428582	NSPS/EG CAI,Positive Static Press.,Reduced System Vacuum,Increased Flow/Vacuum
CV-24213	10/7/2026 1:39:26 PM	43.3	47.1	0.0	9.6			0.9	0.0	120.8	120.7	-0.51	-0.51	0.0	0.0	0.493	0.497	-3.23	-2.72	1293	34.4365572	-118.6428947	NSPS/EG CAC,Reduced System Vacuum
CV-24214	10/12/2026 9:10:49 AM	6.7	40.6	4.4	48.3			0.2	11.0	125.4	124.1	-3.51	-3.50			3.451	3.445	-9.60	-6.1	1303	34.4367293	-118.6435282	Valve Adjustment:Surging Liquid in Well (Watered In);Well Comment:No pump
CV-24215	10/13/2026 10:18:39 AM	44.6	46.1	0.1	9.2			1.0	92.0	94.7	94.7	-3.22	-3.45	9.4	8.7	0.143	0.124	-16.07	-12.62	1305	34.4369377	-118.6448080	
CV-24216	10/26/2026 12:35:04 PM	28.9	30.8	0.0	40.3			0.9	0.0	98.5	99.7	-12.84	-11.69			12.904	11.813	-14.21	-2.52	1288	34.4368510	-118.6423502	Valve Adjustment:Decreased Flow/Vacuum
CV-24216	10/26/2026 12:38:32 PM	28.9	31.6	0.0	39.5			0.9	0.0	97.8	98.5	-12.51	-12.51			12.509	12.509	-14.33	-1.82	1310	34.4367905	-118.6423563	Valve Adjustment:Barely Open,Plugged/Pinched Suspected
CV-24217	10/28/2026 9:22:44 AM	41.5	53.3	0.0	5.2			0.8	0.0	99.4	99.4	-1.19	-1.19			1.196	1.198	-16.25	-15.06	1394	34.4359348	-118.6443728	Valve Adjustment:Barely Open
CV-24218	10/26/2026 10:31:44 AM	40.1	58.5	0.0	1.4			0.7	0.0	127.7	127.0	-3.24	-3.02			3.241	3.021	-9.18	-6.16	1387	34.4357990	-118.6457917	Valve Adjustment:Decreased Flow/Vacuum
CV-24218	10/28/2026 9:29:05 AM	8.5	12.2	12.0	67.3			0.7	5.6	71.0	71.0	-0.45	-0.44			0.000	0.000	-16.69	-16.25	1401	34.4357792	-118.6442213	Valve Adjustment:High O2,Barely Open
CV-24219	10/7/2026 9:55:01 AM	11.1	77.4	0.0	11.5			0.1	0.0	182.9	182.4	-4.06	-3.79			4.025	3.746	-6.26	-2.47	1377	34.4350948	-118.6462297	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24219	10/7/2026 10:05:00 AM					2760																	AtmAA
CV-24219	10/7/2026 10:05:00 AM						112300																AtmAA; [User entered 11.23%]
CV-24219	10/14/2026 9:51:23 AM	13.8	76.5	0.0	9.7			0.2	0.0	190.2	189.9	-8.08	-7.92			8.317	8.240	-11.53	-3.61	1381	34.4350898	-118.6462272	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24219	10/14/2026 9:55:00 AM					3800																	AtmAA
CV-24219	10/19/2026 2:14:33 PM	12.9	77.8	0.0	9.3			0.2	0.0	190.6	190.4	-4.52	-4.36			4.483	4.071	-7.67	-3.31	1387	34.4350971	-118.6462281	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-24219	10/29/2026 2:53:17 PM	11.7	82.3	0.0	6.0			0.1	0.0	190.9	191.0	-5.75	-5.75			5.655	5.763	-8.12	-2.37	1370	34.4351000	-118.6462330	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-24219	10/29/2026 2:54:00 PM					2600																	AtmAA
CV-24220	10/29/2026 10:44:45 AM	8.6	52.7	1.2	37.5			0.2	31.3	125.2	125.4	-3.57	-3.56			3.544	3.531	-18.94	-15.38	1346	34.4339457	-118.6439592	
CV-24220	10/29/2026 1:41:39 PM	8.2	52.9	1.5	37.4			0.2	24.9	130.0	129.7	-6.97	-4.78			6.960	4.816	-19.51	-14.73	1343	34.4339545	-118.6439797	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-24221	10/12/2026 1:06:47 PM	37.3	35.7	0.0	27.0			1.0	0.0	126.4	126.3	-9.95	-9.95	17.7	18.0	0.884	0.913	-18.06	-8.11	1296	34.4341100	-118.6421472	
CV-24222	10/5/2026 2:04:17 PM						37000																[User entered 3.7%]
CV-24222	10/5/2026 2:05:26 PM	48.3	41.0	0.0	10.7			1.2	0.0	124.1	124.1	-12.34	-12.42	21.7	22.8	1.332	1.473	-13.33	-0.91	1262	34.4335902	-118.6419962	Valve Adjustment:Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-24222	10/5/2026 2:06:10 PM	48.1	41.0	0.0	10.9			1.2	0.0	124.0	124.1	-12.22	-12.25	23.1	23.4	1.509	1.548	-13.36	-1.11	1255	34.4335897	-118.6419962	
CV-24223	10/5/2026 2:17:03 PM	30.1	50.8	1.8	17.4			0.6	9.9	129.7	127.8	-9.41	-2.58			9.506	2.598	-11.07	-8.49	1266	34.4334255	-118.6425155	Valve Adjustment:Decreased Flow/Vacuum;Well Comment:pump offline upon arrival;Well Condition:Pnumatic Pump Installed;Well Repairs:Sample Port
CV-24223	10/5/2026 2:22:54 PM	32.8	52.6	0.6	14.0			0.6	24.1	124.0	124.0	-2.74	-2.72			2.760	2.713	-14.44	-11.72	1261	34.4334112	-118.6425438	Well Condition:Pnumatic Pump Installed;Well Repairs:Sample Port
CV-24224	10/7/2026 10:32:22 AM	55.9	44.1	0.0	0.0			1.3	0.0	105.5	105.6	-0.10	-0.14	0.0	0.0	-0.026	0.155			1293	34.4331410	-118.6448115	Reduced System Vacuum,
CV-24225	10/16/2026 1:28:49 PM	49.7	45.8	1.2	3.3			1.1	2.8	105.0	107.1	-0.86	-1.13			0.432	0.914	-22.01	-20.88	1300	34.4326973	-118.6444408	Valve Adjustment:Increased Flow/Vacuum
CV-24226	10/16/2026 1:07:08 PM	56.5	43.2	0.1	0.2			1.3	2.0	124.8	125.2	-4.97	-4.95			5.083	5.061	0.03	4.98	1253	34.4321127	-118.6443178	Valve Adjustment:Valve 100% Open
CV-24227	10/14/2026 2:02:56 PM	47.5	40.5	0.0	12.0			1.2	0.0	119.2	119.2	-6.65	-4.95	33.9	24.0	2.715	1.347	-18.69	-13.74	1249	34.4309447	-118.6498163	Valve Adjustment:Decreased Flow/Vacuum
CV-24231	10/27/2026 1:22:51 PM	41.8	39.7	0.0	18.5			1.1	0.0	126.9	126.9	-0.98	-0.96	29.7	30.0	0.569	0.581	-17.91	-16.95	1283	34.4302694	-118.6496755	
CV-24236	10/26/2026 8:08:05 AM	43.2	35.8	0.0	21.0			1.2	0.0	107.3	106.8	-3.69	-3.41	11.9	9.0	0.883	0.507	-14.79	-11.38	1203	34.4301312	-118.6504890	Valve Adjustment:Decreased Flow/Vacuum
CV-24236	10/26/2026 8:11:12 AM	38.1	35.8	0.0	26.1			1.1	0.0	105.3	104.4	-2.72	-2.71	5.3	5.2	0.571	0.558	-8.64	-5.93	1214	34.4301208	-118.6504913	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-24237	10/14/2026 2:30:08 PM	26.7	24.5	7.2	41.6			1.1	5.8	113.1	113.1	-1.34	-1.34	24.0	24.0	0.740	0.736	-21.89	-20.55	1221	34.4306227	-118.6502245	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-24243	10/6/2026 9:14:38 AM	50.9	39.6	0.9	8.6			1.3	10.1	118.7	120.3	-0.02	-0.04	2.6	5.3	0.018	0.077	-14.63	-14.59	1206	34.4287570	-118.6506538	Valve Adjustment:Increased Flow/Vacuum
CV-24243	10/6/2026 9:19:33 AM	48.2	39.5	1.4	11.0			1.2	7.9	120.6	121.1	-0.04	-0.04	5.2	4.7	0.073	0.059	-14.76	-14.72	1213	34.4287717	-118.6506657	
CV-24244	10/26/2026 8:25:10 AM	48.4	37.7	0.5	13.5			1.3	29.3	111.1	111.3	-1.28	-1.28	10.9	11.1	0.318	0.328	-12.53	-11.25	1186	34.4290277	-118.6513230	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-24245	10/6/2026 11:03:32 AM	39.7	36.4	0.0	23.9			1.1	0.0	117.5	117.5	-1.28	-1.27	24.1	24.1	1.274	1.272	-12.88	-11.61	1161	34.4284413	-118.6501377	,
CV-24246	10/6/2026 10:59:06 AM	31.4	30.0	4.3	34.3			1.0	8.0	114.0	114.1	-1.49	-1.30	39.6	33.7	4.115	2.978	-7.10	-5.8	1201	34.4286718	-118.6493993	,
CV-24253	10/12/2026 1:53:54 PM	47.9	40.5	0.0	11.5			1.2	0.0	95.6	95.6	-2.08	-2.09	25.7	25.8	1.471	1.487	-19.92	-17.83	1157	34.4284465	-118.6498328	
CV-25	10/11/2026 1:40:27 PM	52.1	39.4	0.0	8.5			1.3	0.0	81.8	82.4	-4.87	-4.86	6.3	4.6	0.048	0.026	-4.71	0.15	1247	34.4370023	-118.6421308	
CV-2501	10/5/2026 10:32:57 AM	49.8	43.2	0.0	7.0			1.2	0.0	130.1	130.2	-1.56	-1.55	23.3	22.9	0.142	0.137	-9.53	-7.98	1320	34.4313148	-118.6484903	Valve Adjustment:Audible Flow,Surging Liquid in Header;Well Condition:Lorentz Pump Installed
CV-2502	10/6/2026 12:54:40 PM	53.2	41.9	0.1	4.8			1.3	48.0	122.0	125.0	0.43	-0.56	6.6	42.4	0.012	0.473	-12.08	-11.52	1307	34.4308707	-118.6490878	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2502	10/6/2026 12:55:42 PM	52.5	41.5	0.0	6.0			1.3	0.0	125.3	125.3	-0.72	-0.72	40.0	40.0	0.421	0.421	-11.82	-11.1	1314	34.4308795	-118.6490958	Valve Adjustment:NSPS/EG CAC
CV-2503	10/26/2026 11:09:55 AM	44.0	39.2	0.0	16.8			1.1	0.0	130.2	130.3	-1.63	-0.87	43.5	28.3	0.501	0.212	-10.76	-9.89	1289	34.4312207	-118.6477547	Valve Adjustment:Decreased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2503	10/26/2026 11:10:59 AM	46.8	40.6	0.0	12.6			1.2	0.0	130.3	130.2	-0.78	-0.78	28.2	28.8	0.210	0.220	-11.64	-10.86	1300	34.4312122	-118.6477593	Well Condition:Lorentz Pump Installed
CV-2504	10/15/2026 1:11:52 PM	43.1	39.9	0.0	17.0			1.1	0.0	130.5	130.4	-0.83	-0.76	100.7	97.8	2.660	2.507	-8.84	-8.08	1273	34.4303835	-118.6489443	Valve Adjustment:Barely Open
CV-2505	10/6/2026 10:01:28 AM	48.9	42.0	0.1	9.0			1.2	90.0	126.0	126.1	-2.93	-2.92	36.9	34.6	0.825	0.729	-13.41	-10.49	1224	34.4307778	-118.6471457	,
CV-2506	10/6/2026 10:23:28 AM	40.8	38.8	0.0	20.4			1.1	0.0	122.3	122.4	-1.77	-1.59	34.6	33.3	0.732	0.679	-12.65	-11.06	1234	34.4304395	-118.6476043	,
CV-2507	10/6/2026 10:26:09 AM	50.1	42.6	0.0	7.3			1.2	0.0	125.5	125.5	-2.07	-2.06	39.7	37.5	1.915	1.704	-12.55	-10.49	1168	34.4301053	-118.6482213	,
CV-2508	10/6/2026 10:30:02 AM	47.4	40.8	0.0	11.8			1.2	0.0	121.3	121.4	-10.82	-10.79	69.5	73.2	1.175	1.304	-12.60	-1.81	1207	34.4292617	-118.6491455	,
CV-2509	10/6/2026 10:33:39 AM	44.3	39.6	0.0	16.1			1.1	0.0	117.3	117.4	-9.42	-9.25	60.6	58.3	2.248	2.080	-13.68	-4.43	1129	34.4291430	-118.6491612	,
CV-2510	10/6/2026 10:51:16 AM	51.8	42.2	0.0	6.0			1.2	0.0	116.8	116.8	-8.07	-8.08	36.6	35.0	3.518	3.222	-14.28	-6.2	1184	34.4291785	-118.6497915	,
CV-25100D	10/15/2026 9:55:22 AM	9.7	32.7	0.3	57.3			0.3	191.0	114.8	115.5	-6.41	-4.45			6.623	4.457	-10.80	-6.35	1368	34.4361415	-118.6471372	Valve Adjustment:Decreased Flow/Vacuum
CV-25100D	10/23/2026 8:31:22 AM	7.6	30.8	2.7	58.9			0.2	21.8	109.9	109.3	-4.73	-4.73			5.186	5.183	-12.69	-7.96	1367	34.4361850	-118.6471267	Valve Adjustment:Barely Open
CV-25100S	10/5/2026 1:50:00 PM					3260																	AtmAA
CV-25100S	10/5/2026 1:50:00 PM						171900																AtmAA; [User entered 17.19%]

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-25100S	10/5/2026 1:50:36 PM	14.3	72.4	0.0	13.3			0.2	0.0	187.3	188.1	-6.91	-6.85			7.100	7.048	-7.61	-0.76	1383	34.4361422	-118.6471523	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-25100S	10/12/2026 10:12:19 AM	6.4	74.8	0.1	18.7			0.1	187.0	182.4	182.9	-10.16	-10.12			10.572	10.528	-11.07	-0.95	1350	34.4361680	-118.6471477	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-25100S	10/12/2026 10:20:00 AM					3540																	AtmAA
CV-25100S	10/19/2026 2:20:05 PM	5.5	66.5	0.2	27.8			0.1	139.0	160.2	164.4	-2.26	-2.23			2.232	2.219	-8.37	-6.14	1369	34.4361552	-118.6471430	Valve Adjustment:No Flow Measurement,High Temp
CV-25100S	10/26/2026 10:02:04 AM	4.1	73.4	0.2	22.3			0.1	111.5	171.4	171.4	-9.71	-9.70			9.889	9.863	-6.78	2.92	1372	34.4361600	-118.6471295	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-25100S	10/26/2026 10:05:00 AM					3360																	AtmAA
CV-25101D	10/7/2026 9:21:07 AM	10.1	21.7	11.6	56.6			0.5	4.9	115.2	114.4	-1.18	-1.16			1.163	1.135	-8.33	-7.17	1396	34.4359755	-118.6467747	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Reduce Sys. Vac. - Flare Down
CV-25101D	10/7/2026 9:21:30 AM	10.3	21.6	11.5	56.6			0.5	4.9	115.0	115.2	-1.20	-1.20			1.192	1.186	-8.31	-7.11	1398	34.4359808	-118.6467843	Valve Adjustment:High O2,Reduce Sys. Vac. - Flare Down
CV-25101D	10/14/2026 10:36:27 AM	6.6	11.8	15.9	65.7			0.6	4.1	93.4	93.2	-2.02	-2.00			2.037	2.016	-11.41	-9.41	1388	34.4359902	-118.6467833	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High O2,Valve 100% Open
CV-25101D	10/14/2026 10:37:54 AM	6.6	11.8	15.9	65.7			0.6	4.1	93.6	93.7	-2.04	-2.03			2.051	2.036	-11.67	-9.64	1393	34.4359893	-118.6467908	Valve Adjustment:NSPS/EG CAI,High O2,Valve 100% Open
CV-25101D	10/23/2026 8:08:10 AM	4.5	13.1	16.7	65.7			0.3	3.9	88.5	88.4	-3.34	-3.34			3.355	3.355	-12.29	-8.95	1399	34.4359780	-118.6467872	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25101S	10/7/2026 9:28:22 AM	0.0	0.1	20.4	79.5			0.0	3.9	94.9	95.0	-0.69	-0.70			0.682	0.680	-8.23	-7.53	1394	34.4359682	-118.6467760	Valve Adjustment:High O2,Barely Open
CV-25101S	10/23/2026 8:12:41 AM	0.0	0.3	21.5	78.2			0.0	3.6	56.2	56.3	-1.33	-1.33			1.333	1.331	-12.55	-11.22	1403	34.4359870	-118.6467840	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-25102	10/5/2026 10:44:01 AM	29.4	67.7	0.0	2.9			0.4	0.0	196.5	196.8	0.66	0.66			0.000	0.000	-9.60	-10.26	1377	34.4357771	-118.6471901	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press.;Well Condition:Lorentz Pump Installed
CV-25102	10/5/2026 10:47:04 AM	21.0	71.4	0.0	7.6			0.3	0.0	196.6	197.3	0.57	-5.40			0.000	5.939	-9.49	-4.09	1377	34.4357796	-118.6471901	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-25102	10/5/2026 10:50:00 AM					1760																	AtmAA
CV-25102	10/5/2026 10:50:00 AM						171500																AtmAA; [User entered 17.15%]
CV-25102	10/12/2026 9:47:40 AM	15.6	72.2	0.8	11.4			0.2	14.3	188.6	188.3	-10.50	-10.49	5.9	5.9	10.953	10.884	-13.91	-3.42	1370	34.4357802	-118.6472005	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-25102	10/12/2026 9:50:00 AM					1460																	AtmAA
CV-25102	10/19/2026 1:59:47 PM	4.5	45.8	0.7	49.0			0.1	70.0	153.3	151.9	-2.55	-2.53			2.541	2.538	-9.26	-6.73	1385	34.4357797	-118.6471997	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-25102	10/26/2026 9:57:52 AM	3.8	74.3	0.2	21.7			0.1	108.5	159.4	159.9	-9.92	-9.76			10.108	10.122	-5.73	4.03	1367	34.4357883	-118.6471948	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-25102	10/26/2026 10:00:00 AM					1510																	AtmAA
CV-25103	10/7/2026 9:10:42 AM	22.3	39.4	2.6	35.7			0.6	13.7	111.3	111.3	-0.11	-0.11			0.093	0.092	-9.76	-9.65	1399	34.4356608	-118.6466507	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-25103	10/23/2026 7:54:23 AM	12.0	31.5	8.2	48.3			0.4	5.9	65.5	65.5	-0.98	-0.98			0.983	0.980	-13.66	-12.68	1371	34.4356725	-118.6467003	Valve Adjustment:Barely Open
CV-25104D	10/7/2026 1:41:02 PM	15.5	57.7	6.6	20.2			0.3	3.1	114.4	114.4	-5.53	-5.43			5.634	5.515	-5.65	-0.22	1364	34.4353708	-118.6472599	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High O2;Well Condition:Lorentz Pump Installed
CV-25104D	10/21/2026 9:57:54 AM	4.3	83.1	0.1	12.5			0.1	125.0	80.0	80.0	-1.29	-1.54			1.324	1.574	-6.80	-5.26	1373	34.4353657	-118.6472412	Valve Adjustment:Barely Open
CV-25104S	10/14/2026 10:19:36 AM	4.6	86.0	0.0	9.4			0.1	0.0	101.3	101.3	-5.00	-5.04			5.006	5.038	-11.50	-6.46	1365	34.4353700	-118.6472473	Valve Adjustment:No Flow Measurement
CV-25104S	10/28/2026 1:48:59 PM	10.5	69.8	0.0	19.7			0.2	0.0	81.9	83.6	-8.28	-7.88			8.325	7.936	-10.73	-2.85	1361	34.4353623	-118.6472335	Valve Adjustment:Decreased Flow/Vacuum
CV-25105D	10/7/2026 8:45:38 AM	16.2	77.7	0.0	6.1			0.2	0.0	129.0	83.0	-1.41	-1.42			1.396	1.415	-9.01	-7.59	1382	34.4353875	-118.6466865	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-25105D	10/23/2026 7:34:58 AM	14.0	83.7	0.0	2.3			0.2	0.0	130.0	130.0	-4.80	-4.80			5.201	5.194	-11.55	-6.75	1379	34.4353988	-118.6466928	Valve Adjustment:Barely Open
CV-25105S	10/7/2026 8:43:07 AM	5.2	9.1	11.9	73.8			0.6	6.2	89.1	89.0	-0.17	-0.17			0.165	0.170	-8.98	-8.81	1392	34.4353807	-118.6466953	Valve Adjustment:Barely Open,Reduce Sys. Vac. - Flare Down
CV-25105S	10/23/2026 7:37:14 AM	6.3	22.6	8.8	62.3			0.3	7.1	122.9	122.9	-6.85	-6.79			7.246	7.120	-11.55	-4.76	1378	34.4353883	-118.6467082	Valve Adjustment:High O2,Barely Open
CV-25106D	10/14/2026 8:32:23 AM	0.0	0.0	21.5	78.5				3.7	69.2	68.7	-13.41	-13.49			13.499	13.599	-13.26	0.23	1365	34.4350433	-118.6473722	Valve Adjustment:NSPS/EG CAI,High O2

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-25106D	10/14/2026 8:33:16 AM	0.0	0.0	21.4	78.6				3.7	68.5	68.4	-13.65	-13.81			13.708	13.837	-13.50	0.31	1356	34.4350525	-118.6473722	Valve Adjustment:NSPS/EG CAI,High O2
CV-25106D	10/14/2026 10:26:29 AM	0.1	3.3	19.7	76.9			0.0	3.9	80.7	81.7	-11.98	-11.68			12.088	11.723	-11.92	-0.24	1360	34.4350447	-118.6473540	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum
CV-25106D	10/14/2026 10:29:13 AM	0.0	0.4	20.2	79.4			0.0	3.9	82.0	82.0	-11.46	-11.48			11.527	11.537	-12.02	-0.54	1356	34.4350603	-118.6473747	Valve Adjustment:NSPS/EG CAI,High O2
CV-25106D	10/21/2026 10:04:19 AM	4.1	12.0	13.6	70.3			0.3	5.2	65.4	65.1	-7.09	-7.09			7.307	7.251	-7.07	0.02	1373	34.4350533	-118.6473637	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25106D	10/21/2026 10:05:25 AM	4.2	11.8	13.6	70.4			0.4	5.2	65.5	65.5	-7.09	-7.09			7.332	7.332	-7.18	-0.09	1378	34.4350557	-118.6473632	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-25106S	10/14/2026 8:11:49 AM	0.0	0.0	21.8	78.2				3.6	73.0	73.1	-14.37	-14.25			14.342	14.244	-14.18	0.07	1368	34.4350452	-118.6473740	Valve Adjustment:NSPS/EG CAI,High O2
CV-25106S	10/14/2026 8:16:58 AM	0.0	0.0	21.7	78.3				3.6	74.0	74.2	-14.37	-14.25			14.381	14.256	-14.20	0.05	1361	34.4350482	-118.6473697	Valve Adjustment:NSPS/EG CAI,High O2
CV-25106S	10/14/2026 10:40:17 AM	0.0	0.0	20.2	79.8				4.0	88.5	88.8	-12.17	-11.99			12.226	12.080	-12.00	-0.01	1361	34.4350345	-118.6473707	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Well (Watered In);Well Repairs:Valve
CV-25106S	10/14/2026 10:41:40 AM	0.0	0.0	20.1	79.9				4.0	88.9	88.9	-12.30	-12.30			12.410	12.491	-12.21	0.09	1371	34.4350325	-118.6473682	Valve Adjustment:NSPS/EG CAI,High O2
CV-25106S	10/21/2026 10:08:18 AM	5.0	10.2	16.1	68.7			0.5	4.3	67.9	68.1	-6.96	-7.03			7.188	7.223	-6.97	0.06	1377	34.4350210	-118.6473675	
CV-25107D	10/7/2026 9:35:00 AM					607																	AtmAA
CV-25107D	10/7/2026 9:35:00 AM						17100																AtmAA; [User entered 1.71%]
CV-25107D	10/7/2026 9:49:36 AM	5.5	74.5	0.0	20.0			0.1	0.0	183.7	183.3	1.46	1.34			0.000	0.000	4.37	3.03	1392	34.4350601	-118.6459750	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down;Well Condition:Pnumatic Pump Installed
CV-25107D	10/14/2026 9:47:26 AM	12.1	77.2	0.1	10.6			0.2	106.0	175.4	175.9	-11.42	-11.33			11.742	11.635	-12.12	-0.79	1381	34.4350461	-118.6459656	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-25107D	10/14/2026 9:50:00 AM					4790																	AtmAA
CV-25107D	10/19/2026 2:06:52 PM	12.1	78.2	0.0	9.7			0.2	0.0	174.4	175.0	-7.67	-7.58			7.974	7.927	-8.08	-0.5	1388	34.4350328	-118.6459703	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-25107D	10/26/2026 1:33:46 PM	35.2	64.8	0.0	0.0			0.5	0.0	177.3	177.7	-4.97	-4.93			5.113	4.851	-6.07	-1.14	1381	34.4350529	-118.6459471	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-25107D	10/26/2026 1:37:00 PM					4850																	AtmAA
CV-25107S	10/14/2026 1:03:00 PM	32.1	57.2	0.0	10.7			0.6	0.0	138.7	139.3	-3.56	-3.86			3.538	3.823	-10.98	-7.12	1378	34.4350513	-118.6459590	Valve Adjustment:NSPS/EG CAI,High Temp
CV-25107S	10/14/2026 1:04:46 PM	31.2	60.4	0.0	8.4			0.5	0.0	140.2	140.2	-2.64	-2.58			2.605	2.544	-11.75	-9.17	1383	34.4350523	-118.6459548	Valve Adjustment:NSPS/EG CAI,High Temp
CV-25107S	10/23/2026 12:37:31 PM	48.7	45.6	0.0	5.7			1.1	0.0	130.1	130.0	-4.96	-4.41			4.983	4.428	-10.18	-5.77	1380	34.4350573	-118.6459630	Valve Adjustment:Decreased Flow/Vacuum
CV-2511	10/25/2026 1:41:37 PM	50.8	42.4	0.0	6.8			1.2	0.0	127.9	128.3	-0.50	-0.77	7.8	20.9	0.016	0.115	-13.51	-12.74	1249	34.4296802	-118.6501445	Valve Adjustment:Increased Flow/Vacuum
CV-2511	10/25/2026 1:43:46 PM	49.6	42.8	0.0	7.6			1.2	0.0	128.5	128.9	-0.88	-0.86	22.3	21.1	0.131	0.117	-13.69	-12.83	1246	34.4296480	-118.6501708	
CV-2512	10/26/2026 8:37:27 AM	43.9	41.1	0.0	15.1			1.1	0.0	124.0	119.1	-0.46	-0.14	17.1	14.6	0.076	0.055	-14.23	-14.09	1242	34.4292342	-118.6506203	Valve Adjustment:Decreased Flow/Vacuum
CV-2512	10/26/2026 8:39:05 AM	43.4	41.4	0.0	15.2			1.0	0.0	115.9	115.6	-0.07	-0.07	22.5	23.4	0.129	0.140	-14.11	-14.04	1260	34.4292550	-118.6506097	
CV-2513	10/6/2026 11:08:13 AM	45.5	39.8	0.0	14.7			1.1	0.0	122.1	122.2	-2.21	-1.94	20.4	17.5	0.912	0.673	-10.58	-8.64	1079	34.4288960	-118.6488625	,
CV-2514	10/25/2026 1:56:15 PM	52.5	41.8	0.0	5.8			1.3	0.0	126.0	126.0	-1.76	-2.33	27.0	29.8	1.705	2.091	-7.79	-5.46	1137	34.4296072	-118.6478092	Valve Adjustment:Increased Flow/Vacuum
CV-2514	10/25/2026 1:58:13 PM	52.6	41.7	0.0	5.7			1.3	0.0	125.9	125.8	-2.22	-2.20	32.3	32.1	1.372	1.352	-7.49	-5.29	1136	34.4296163	-118.6478098	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-2515	10/11/2026 1:09:51 PM	46.9	32.7	0.0	20.4			1.4	0.0	106.8	108.5	-2.11	-2.08	1.4	4.3	0.004	0.043	-4.27	-2.19	1277	34.4378590	-118.6431908	
CV-2515	10/19/2026 12:45:02 PM	33.4	27.7	0.0	38.9			1.2	0.0	115.3	115.4	-0.70	-0.70	3.6	3.8	0.029	0.034	-14.05	-13.35	1285	34.4378808	-118.6432105	
CV-2516	10/21/2026 9:24:53 AM	52.1	41.8	0.0	6.1			1.2	0.0	125.2	125.0	-4.07	-4.08	15.5	15.4	1.571	1.554	-7.40	-3.32	1315	34.4374012	-118.6431863	
CV-2517	10/11/2026 1:56:15 PM	27.6	30.3	0.0	42.1			0.9	0.0	104.5	107.2	-3.67	-3.79	2.6	5.2	0.019	0.073	-4.77	-0.98	1264	34.4369707	-118.6420463	Valve Adjustment:Increased Flow/Vacuum
CV-2518	10/11/2026 2:09:07 PM	53.1	36.4	0.0	10.5			1.5	0.0	108.8	108.9	-2.14	-2.11	7.7	5.7	0.015	0.008	-0.37	1.74	1257	34.4363818	-118.6414603	
CV-2519	10/26/2026 12:20:49 PM	44.6	39.9	0.0	15.5			1.1	0.0	121.0	120.6	-1.18	-1.00	15.4	6.6	0.647	0.119	-16.42	-15.42	1289	34.4361325	-118.6420513	Valve Adjustment:Decreased Flow/Vacuum
CV-2519	10/26/2026 12:21:35 PM	44.1	40.2	0.0	15.7			1.1	0.0	120.4	120.4	-0.94	-0.93	7.6	7.2	0.156	0.142	-16.43	-15.5	1299	34.4361188	-118.6420465	
CV-2520	10/12/2026 1:33:46 PM	32.9	46.7	0.0	20.4			0.7	0.0	132.7	132.8	-1.58	-1.51	0.7	1.8	0.002	0.009	-17.08	-15.57	1316	34.4358692	-118.6427840	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2520	10/12/2026 1:36:33 PM	31.4	48.8	0.0	19.8			0.6	0.0	134.0	133.5	-1.64	-1.76	2.7	6.0	0.021	0.101	-17.57	-15.81	1325	34.4358668	-118.6427887	Valve Adjustment:NSPS/EG CAI,High Temp,Valve 100% Closed

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-2520	10/15/2026 11:00:02 AM	34.3	55.2	0.0	10.5			0.6	0.0	129.1	130.2	-1.74	-1.78	4.4	4.8	0.045	0.055	-16.61	-14.83	1313	34.4358873	-118.6428093	Valve Adjustment:Increased Flow/Vacuum
CV-2520	10/26/2026 12:46:13 PM	41.7	49.3	0.0	9.1			0.8	0.0	122.3	122.3	-13.88	-13.86	3.0	2.7	2.452	1.970	-16.77	-2.91	1309	34.4359822	-118.6425053	
CV-2521	10/21/2026 8:05:25 AM	41.8	44.2	0.0	14.1			0.9	0.0	106.6	105.2	-7.39	-2.00			7.164	2.013	-8.46	-6.46	1327	34.4354770	-118.6430615	Valve Adjustment:Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
CV-2521	10/21/2026 8:08:50 AM	39.8	45.5	0.0	14.8			0.9	0.0	103.2	102.2	-1.38	-1.36			1.390	1.371	-8.74	-7.38	1335	34.4354788	-118.6430518	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-2522	10/12/2026 10:09:46 AM	47.1	41.2	0.0	11.7			1.1	0.0	126.6	127.3	-4.28	-4.27	2.8	3.6	0.021	0.036	-18.42	-14.15	1283	34.4355295	-118.6423718	
CV-2523	10/7/2026 9:04:26 AM	52.7	36.9	0.0	10.4			1.4	0.0	126.3	126.3	-3.01	-2.99	31.8	31.8	2.802	2.809	-9.24	-6.25	1269	34.4356787	-118.6416522	
CV-2524	10/12/2026 10:26:15 AM	36.6	41.3	0.5	21.6			0.9	43.2	136.9	137.9	-2.99	-3.10	8.8	9.8	0.220	0.268	-17.05	-13.95	1294	34.4347888	-118.6424972	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2524	10/12/2026 10:32:01 AM	37.2	39.6	1.7	21.5			0.9	12.6	117.1	115.5	-1.23	-1.22	3.1	3.0	0.026	0.025	-17.52	-16.3	1297	34.4347853	-118.6425123	Valve Adjustment:NSPS/EG CAC,Valve 100% Closed
CV-2524	10/15/2026 12:40:07 PM	34.4	48.6	0.0	17.0			0.7	0.0	90.0	106.5	0.28	-0.57			0.071	0.000	-16.83	-16.26	1284	34.4347998	-118.6425260	Valve Adjustment:NSPS/EG CAI,Positive Static Press.
CV-2524	10/15/2026 12:41:42 PM	10.3	50.1	0.0	39.6			0.2	0.0	109.5	109.5	-0.84	-0.84			0.000	0.000	-15.81	-14.97	1284	34.4347990	-118.6425210	Valve Adjustment:NSPS/EG CAC
CV-2525	10/7/2026 9:33:19 AM	43.5	30.8	0.0	25.7			1.4	0.0	118.8	118.7	-11.38	-12.39	61.1	64.0	10.569	11.626	-9.05	3.34	1273	34.4349932	-118.6417192	Valve Adjustment:NSPS/EG CAI
CV-2526	10/7/2026 10:22:15 AM	49.8	39.3	0.0	10.9			1.3	0.0	122.5	122.8	-0.57	-0.72	4.9	7.4	0.066	0.150	-8.56	-7.84	1255	34.4345093	-118.6415827	
CV-2526	10/25/2026 3:01:05 PM	45.9	36.7	0.0	17.4			1.2	0.0	121.2	120.5	-2.40	-1.82	18.8	9.6	0.226	0.059	-19.37	-17.55	1266	34.4345138	-118.6415868	Valve Adjustment:Decreased Flow/Vacuum
CV-2526	10/25/2026 3:02:03 PM	44.9	37.9	0.0	17.3			1.2	0.0	120.0	119.9	-1.71	-1.69	7.3	6.7	0.034	0.029	-19.28	-17.59	1264	34.4345120	-118.6415925	
CV-2527	10/15/2026 9:13:34 AM	46.9	45.3	0.0	7.8			1.0	0.0	122.7	122.3	-5.48	-5.46			5.753	5.743	-16.55	-11.09	1310	34.4341023	-118.6428637	
CV-2527	10/21/2026 7:44:28 AM	44.6	44.4	0.0	11.0			1.0	0.0	114.2	114.4	-2.46	-1.80			2.473	1.814	-6.87	-5.07	1316	34.4340958	-118.6428763	Valve Adjustment:Decreased Flow/Vacuum
CV-2528	10/15/2026 10:52:46 AM	44.1	34.2	0.0	21.7			1.3	0.0	110.9	111.0	-4.99	-4.99	18.7	20.2	0.220	0.256	-20.96	-15.97	1243	34.4337760	-118.6412690	
CV-2529	10/1/2026 2:11:34 PM	53.0	41.3	0.0	5.7			1.3	0.0	113.6	116.1	15.86	-0.10	1.2	4.0	0.154	1.777	-18.17	-18.07	1224	34.4331145	-118.6423493	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Positive Static Press.,Increased Flow/Vacuum
CV-2529	10/1/2026 2:22:39 PM	50.6	40.2	1.2	8.0			1.3	6.5	116.3	116.2	-7.01	-3.37	2.0	3.7	0.009	0.032	-17.44	-14.07	1229	34.4331200	-118.6423433	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum,Plugged/Pinched Suspected
CV-2530	10/1/2026 12:52:54 PM	46.8	42.8	1.0	9.4			1.1	9.4	113.7	113.4	-12.29	-11.73			12.132	11.638	-12.24	-0.51	1229	34.4327895	-118.6429522	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-2531	10/1/2026 1:05:05 PM	33.8	50.7	0.0	15.5			0.7	0.0	135.8	139.2	7.81	-0.73			0.000	0.684	-12.42	-11.69	1219	34.4325418	-118.6433428	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.,Increased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
CV-2531	10/1/2026 1:06:22 PM	35.7	50.1	0.0	14.2			0.7	0.0	139.7	139.8	-1.36	-1.38			1.317	1.329	-14.18	-12.8	1216	34.4325318	-118.6433167	Valve Adjustment:NSPS/EG CAC,High Temp,Reduce Sys. Vac. - Flare Down
CV-2531	10/19/2026 9:33:35 AM	34.7	55.5	0.0	9.8			0.6	0.0	125.3	125.4	-6.39	-6.82			6.496	6.959	-16.81	-9.99	1225	34.4325342	-118.6433478	Valve Adjustment:Increased Flow/Vacuum
CV-2532	10/1/2026 1:10:46 PM	52.9	42.5	0.2	4.4			1.2	22.0	124.3	124.3	-14.83	-14.83			14.724	14.730	-15.20	-0.37	1209	34.4322257	-118.6437093	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-2533	10/1/2026 1:15:51 PM	51.4	40.2	1.4	7.0			1.3	5.0	131.9	130.0	-1.00	-0.04	11.8	12.3	0.386	0.418	-15.33	-15.29	1206	34.4318977	-118.6441093	Valve Adjustment:NSPS/EG CAI,Audible Flow,High Temp,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
CV-2533	10/1/2026 1:18:14 PM	54.0	42.3	2.2	1.5			1.3	0.7	130.8	130.2	-0.23	-0.18	11.5	10.4	0.364	0.300	-15.36	-15.18	1213	34.4318990	-118.6441013	Valve Adjustment:NSPS/EG CAC,Reduce Sys. Vac. - Flare Down
CV-2534	10/1/2026 1:28:03 PM	53.0	44.2	0.0	2.8			1.2	0.0	108.5	108.4	-0.64	-1.02	25.4	27.0	0.823	0.930	-9.75	-8.73	1220	34.4316793	-118.6444603	Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
CV-2535	10/6/2026 10:05:13 AM	32.4	35.3	0.0	32.3			0.9	0.0	113.8	113.7	-1.67	-1.37	8.1	5.0	7.143	2.729	-10.15	-8.78	1234	34.4311742	-118.6469100	,
CV-2536	10/7/2026 2:12:34 PM	46.9	44.9	1.1	7.1			1.0	6.2	120.9	123.2	-4.64	-4.44	2.1	2.2	0.507	0.515	-6.85	-2.41	1174	34.4310158	-118.6458708	Valve Adjustment:Reduce Sys. Vac. - Flare Down,Plugged/Pinched Suspected
CV-2537	10/6/2026 10:18:52 AM	39.8	38.0	0.0	22.2			1.0	0.0	118.1	118.5	-3.57	-1.09	62.3	43.4	3.486	1.712			1234	34.4310395	-118.6465747	,
CV-2538	10/6/2026 10:13:04 AM	46.8	40.7	0.0	12.5			1.1	0.0	124.7	124.6	-1.52	-1.12	11.2	4.5	2.612	0.421	-11.63	-10.51	1214	34.4308343	-118.6467192	,
CV-2539	10/5/2026 10:31:03 AM						19000																[User entered 1.9%]
CV-2539	10/5/2026 10:31:24 AM	41.4	42.9	0.0	15.7			1.0	0.0	120.8	121.0	-1.37	-1.37			1.379	1.379	-11.48	-10.11	1331	34.4316992	-118.6491918	
CV-2539	10/19/2026 1:48:21 PM	40.4	41.3	0.0	18.3			1.0	0.0	122.9	122.9	-1.02	-1.01			0.981	0.987	-13.14	-12.13	1330	34.4317282	-118.6492102	Valve Adjustment:Barely Open
CV-2540	10/5/2026 1:17:02 PM	7.2	79.1	0.1	13.6			0.1	136.0	140.4	140.5	-1.63	-1.66			1.621	1.647	-9.59	-7.93	1374	34.4332595	-118.6481043	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-2540	10/20/2026 1:07:16 PM	16.2	72.0	0.4	11.4			0.2	28.5	128.7	129.2	-6.66	-5.96			6.584	5.908	-11.56	-5.6	1379	34.4332583	-118.6480993	Valve Adjustment:Decreased Flow/Vacuum
CV-2541	10/1/2026 10:39:57 AM	20.0	63.4	0.0	16.6			0.3	0.0	140.5	141.0	-0.81	-0.77	0.0	0.0	0.708	0.708	-6.42	-5.65	1378	34.4331362	-118.6490738	NSPS/EG CAI,High Temp
CV-2541	10/1/2026 10:41:27 AM	18.9	66.3	0.0	14.8			0.3	0.0	141.2	141.1	-0.75	-0.64	0.0	0.0	0.596	0.494	-6.22	-5.58	1329	34.4329943	-118.6491577	NSPS/EG CAI,High Temp
CV-2541	10/20/2026 10:05:18 AM	20.0	70.0	0.0	10.0			0.3	0.0	137.6	137.2	-1.01	-0.99			0.999	0.991	-10.38	-9.39	1348	34.4332672	-118.6490708	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-2541	10/20/2026 10:09:25 AM	19.8	70.9	0.0	9.3			0.3	0.0	139.0	139.9	-0.91	-0.91			0.899	0.903	-9.60	-8.69	1311	34.4332497	-118.6490627	Valve Adjustment:High Temp,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In);Well Condition:Lorentz Pump Installed
CV-2542	10/13/2026 9:45:50 AM	38.9	55.1	0.0	6.0			0.7	0.0	131.5	131.5	-15.99	-16.00			15.706	15.808	-15.92	0.08	1399	34.4337248	-118.6471695	Valve Comment:No sample port located on well-head;Valve Adjustment:High Temp,Valve 100% Open
CV-2542	10/13/2026 9:49:39 AM	39.0	55.4	0.0	5.6			0.7	0.0	131.1	131.1	-16.51	-16.13			16.673	16.257	-16.43	-0.3	1394	34.4337205	-118.6471817	Valve Adjustment:High Temp,Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2542	10/20/2026 2:21:44 PM	37.2	57.5	0.5	4.8			0.6	9.6	131.0	130.9	-11.32	-11.26			11.158	11.081	0.08	11.34	1369	34.4337093	-118.6471860	Valve Comment:hard pipped
CV-2543-PL	10/5/2026 1:29:34 PM	19.2	54.2	3.4	23.2			0.4	6.8	124.9	125.6	-6.54	-6.60			6.760	6.727	-6.56	0.04	1363	34.4338122	-118.6484650	Valve Adjustment:Barely Open,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down,Plugged/Pinched Suspected
CV-2543-PL	10/20/2026 1:33:56 PM	21.4	63.9	1.5	13.2			0.3	8.8	108.9	108.6	-6.37	-6.87			6.323	6.816	-6.33	0.54	1353	34.4338097	-118.6484690	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2544	10/1/2026 3:05:00 PM					1485																	AtmAA
CV-2544	10/1/2026 3:09:28 PM	19.5	79.0	0.0	1.5			0.2	0.0	148.0	98.8	-1.75	-1.82	24.8	26.1	1.765	1.797	-5.38	-3.56	1383	34.4340318	-118.6472159	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2544	10/6/2026 9:47:15 AM	5.3	85.4	0.0	9.3			0.1	0.0	100.0		-3.63				3.656		-7.38	-3.75	1396	34.4340487	-118.6472173	Valve Adjustment:Barely Open
CV-2544	10/8/2026 1:42:00 PM					1830																	AtmAA
CV-2544	10/8/2026 1:42:00 PM						80200																AtmAA; [User entered 8.02%]
CV-2544	10/8/2026 1:50:01 PM	14.5	80.0	0.2	5.3			0.2	26.5	147.0	95.1	0.03	0.02			0.000	0.000	-3.24	-3.26	1373	34.4340232	-118.6472355	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Reduce Sys. Vac. - Flare Down;Well Condition:Lorentz Pump Installed
CV-2544	10/9/2026 3:03:49 PM	5.0	82.3	0.0	12.7			0.1	0.0	149.0	95.1	-7.58	-7.51			7.638	7.554	0.13	7.64	1378	34.4340355	-118.6472097	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2544	10/15/2026 8:57:55 AM	14.2	0.0	0.2	85.6				428.0	146.0	75.8	-4.58	-4.55			4.528	4.530	-8.53	-3.98	1385	34.4340433	-118.6472414	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2544	10/15/2026 9:00:00 AM					2620																	AtmAA
CV-2544	10/21/2026 8:44:50 AM	9.7	83.7	0.3	6.3			0.1	21.0	115.0	115.0	-3.04	-3.19			2.959	3.144	-3.21	-0.02	1395	34.4340440	-118.6472322	Valve Adjustment:Valve 100% Open;Well Condition:Lorentz Pump Installed
CV-2544	10/21/2026 10:25:00 AM					1810																	AtmAA
CV-2544	10/21/2026 10:30:51 AM	10.9	77.8	0.0	11.3			0.1	0.0	147.0	66.6	-3.33	-3.29	34.0	35.8	3.338	3.220	-4.27	-0.98	1394	34.4340212	-118.6472496	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2544	10/28/2026 9:53:00 AM					2120																	AtmAA
CV-2544	10/28/2026 10:00:15 AM	18.2	81.7	0.0	0.1			0.2	0.0	149.0	69.7	-2.78	-2.70			2.756	2.635	-5.37	-2.67	1387	34.4340332	-118.6472341	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2545	10/6/2026 10:25:38 AM	33.3	58.3	0.3	8.1			0.6	27.0	127.1	127.0	-1.63	-1.61			1.597	1.608	-5.56	-3.95	1392	34.4340462	-118.6467247	Valve Adjustment:Barely Open
CV-2545	10/21/2026 9:02:56 AM	28.9	62.4	0.1	8.6			0.5	86.0	114.0	114.2	-1.47	-1.45			1.516	1.465	-4.01	-2.56	1390	34.4340417	-118.6467352	Valve Adjustment:Barely Open
CV-2546	10/6/2026 10:27:52 AM	16.5	74.5	0.0	9.0			0.2	0.0	140.5	139.5	-1.54	-1.41			1.512	1.412	-5.32	-3.91	1389	34.4341368	-118.6469617	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2546	10/6/2026 10:28:18 AM	15.7	76.8	0.0	7.5			0.2	0.0	139.5	139.6	-1.40	-1.42			1.407	1.384	-5.68	-4.26	1380	34.4341262	-118.6469700	
CV-2546	10/21/2026 9:06:15 AM	13.2	81.6	0.2	5.0			0.2	25.0	127.8	127.7	-1.22	-1.23			1.239	1.219	-4.05	-2.82	1392	34.4341322	-118.6469787	Valve Adjustment:Barely Open
CV-2547	10/5/2026 10:23:50 AM	49.3	48.2	1.1	1.4			1.0	1.3	112.6	112.9	-1.24	-1.25	30.6	30.6	1.212	1.208	-3.11	-1.86	1404	34.4339400	-118.6459860	Valve Adjustment:Barely Open
CV-2548	10/14/2026 10:22:00 AM	14.7	76.8	0.0	8.5			0.2	0.0	139.4	139.5	-9.31	-7.81	78.4	66.6	8.574	6.131	-16.30	-8.49	1390	34.4343468	-118.6455753	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2548	10/14/2026 10:24:34 AM	13.6	78.2	0.0	8.2			0.2	0.0	139.0	138.9	-8.70	-9.06	75.2	79.7	7.871	8.865	-14.99	-5.93	1394	34.4343398	-118.6455845	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2548	10/27/2026 2:50:53 PM	17.3	76.5	0.0	6.2			0.2	0.0	82.5	138.9	-10.81	-10.11	43.0	39.2	11.511	10.501	-20.00	-9.89	1397	34.4343442	-118.6455782	Valve Adjustment:Decreased Flow/Vacuum
CV-2549	10/14/2026 10:34:53 AM	28.1	68.3	0.0	3.6			0.4	0.0	132.3	132.4	-3.37	-3.44	40.1	41.2	2.158	2.278	-18.19	-14.75	1390	34.4343763	-118.6452617	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2549	10/14/2026 10:37:44 AM	36.4	60.6	0.0	3.0			0.6	0.0	125.9	126.1	-2.01	-2.00	2.8	2.9	0.010	0.011	-19.20	-17.2	1394	34.4343790	-118.6452622	Valve Adjustment:NSPS/EG CAC,Valve 100% Closed
CV-2549	10/14/2026 10:40:50 AM	36.8	59.4	0.0	3.8			0.6	0.0	122.9	130.3	-2.28	-2.27	20.2	18.4	0.533	0.449	-17.74	-15.47	1401	34.4343637	-118.6452703	Valve Adjustment:Increased Flow/Vacuum
CV-2549	10/27/2026 2:37:39 PM	11.9	81.9	0.0	6.2			0.1	0.0	135.5	134.6	-1.45	-1.34	4.8	3.7	0.504	0.300	-21.48	-20.14	1395	34.4343777	-118.6452767	Valve Adjustment:Barely Open

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-2550	10/8/2026 7:45:44 AM	4.1	87.6	0.0	8.3			0.0	0.0	178.5	178.6	-6.68	-6.40			6.796	6.340	-8.18	-1.78	1358	34.4348322	-118.6461769	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2550	10/8/2026 7:47:00 AM					2135																	AtmAA
CV-2550	10/8/2026 7:47:00 AM						94550																AtmAA; [User entered 9.455%]
CV-2550	10/14/2026 10:12:38 AM	9.2	78.7	0.1	12.0			0.1	120.0	188.3	188.2	-13.02	-12.81			13.388	13.297	-13.89	-1.08	1363	34.4348179	-118.6461638	Valve Adjustment:No Flow Measurement,High Temp
CV-2550	10/14/2026 10:15:00 AM					3465																	AtmAA
CV-2550	10/20/2026 10:25:00 AM					2330																	AtmAA
CV-2550	10/20/2026 10:25:09 AM	1.8	77.4	0.0	20.8			0.0	0.0	193.8	193.5	-7.58	-7.46			8.067	8.063	-8.38	-0.92	1418	34.4347793	-118.6462079	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2550	10/27/2026 8:28:00 AM					2040																	AtmAA
CV-2550	10/27/2026 9:05:33 AM	8.3	84.1	0.0	7.6			0.1	0.0	190.2	190.0	-6.97	-6.91			7.361	7.302	-13.05	-6.14	1371	34.4348092	-118.6461587	Valve Adjustment:No Flow Measurement,High Temp
CV-2551	10/7/2026 9:02:15 AM	26.8	67.7	0.0	5.5			0.4	0.0	174.6	174.9	-3.68	-3.35			3.631	3.355	-5.24	-1.89	1388	34.4349314	-118.6458139	Valve Adjustment:No Flow Measurement,High Temp
CV-2551	10/7/2026 9:05:00 AM					2900																	AtmAA
CV-2551	10/7/2026 9:05:00 AM						88000																AtmAA; [User entered 8.8%]
CV-2551	10/14/2026 9:44:23 AM	12.5	78.1	0.1	9.3			0.2	93.0	174.7	176.0	-0.88	-0.74			0.929	0.739	-12.93	-12.19	1384	34.4349461	-118.6458280	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2551	10/14/2026 9:45:00 AM					4260																	AtmAA
CV-2551	10/19/2026 1:59:11 PM	13.7	80.0	0.0	6.3			0.2	0.0	175.5	176.5	0.76	-2.20			0.000	2.152	-8.26	-6.06	1391	34.4349370	-118.6458087	Valve Adjustment:NSPS/EG CAI,High Temp,Positive Static Press.;Well Condition:Pnumatic Pump Installed
CV-2551	10/19/2026 2:00:43 PM	12.0	78.0	0.0	10.0			0.2	0.0	178.4	177.8	-2.28	-2.11			2.263	2.100	-7.82	-5.71	1391	34.4349221	-118.6458140	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2551	10/26/2026 1:30:43 PM	36.5	63.4	0.0	0.1			0.6	0.0	169.7	169.2	-4.98	-4.68			4.909	4.900	-6.28	-1.6	1384	34.4349314	-118.6458134	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Pnumatic Pump Installed
CV-2551	10/26/2026 1:31:00 PM					2620																	AtmAA
CV-2552	10/8/2026 7:56:00 AM					1800																	AtmAA
CV-2552	10/8/2026 7:56:00 AM						73900																AtmAA; [User entered 7.39%]
CV-2552	10/8/2026 7:57:49 AM	22.3	76.9	0.2	0.6			0.3	3.0	167.0	166.9	-7.22	-7.08			7.410	7.283	0.10	7.18	1365	34.4348867	-118.6465251	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2552	10/14/2026 10:20:00 AM					1310																	AtmAA
CV-2552	10/14/2026 10:24:31 AM	9.2	78.1	0.0	12.7			0.1	0.0	164.0	165.4	0.53	-3.90			0.000	3.897	-12.49	-8.59	1372	34.4348700	-118.6465292	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Positive Static Press.,Increased Flow/Vacuum;Well Condition:Lorentz Pump Installed
CV-2552	10/14/2026 10:25:20 AM	29.6	68.6	0.0	1.8			0.4	0.0	165.4	165.4	-3.85	-3.74			3.861	3.749	-12.40	-8.66	1371	34.4348711	-118.6465274	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2552	10/20/2026 12:55:00 PM					1390																	AtmAA
CV-2552	10/20/2026 12:56:48 PM	19.3	73.7	0.3	6.7			0.3	22.3	162.4	162.4	-8.66	-8.65			8.889	8.865	0.15	8.8	1403	34.4348935	-118.6464941	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2552	10/27/2026 9:20:00 AM					790																	AtmAA
CV-2552	10/27/2026 9:20:28 AM	32.5	67.5	0.0	0.0			0.5	0.0	163.8	163.8	-7.75	-7.50			8.272	8.009	0.04	7.54	1386	34.4348682	-118.6465187	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2553	10/5/2026 1:37:17 PM	28.4	62.1	0.1	9.4			0.5	94.0	101.5	100.3	-0.16	-0.17			0.144	0.164	-9.66	-9.49	1352	34.4341418	-118.6489052	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2553	10/20/2026 10:27:54 AM	28.8	63.6	0.0	7.6			0.5	0.0	121.4	121.5	-0.01	-0.02			0.000	0.008	-11.38	-11.36	1358	34.4341523	-118.6489277	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2554	10/7/2026 1:49:48 PM	39.9	60.1	0.0	0.0			0.7	0.0	137.7	138.5	-4.93	-4.87			4.927	4.864	-4.80	0.07	1349	34.4344776	-118.6482824	Valve Adjustment:No Flow Measurement,High Temp
CV-2554	10/20/2026 1:56:58 PM	25.3	67.8	0.1	6.8			0.4	68.0	111.3	111.6	-8.02	-8.09			8.250	8.268	-8.03	0.06	1352	34.4344463	-118.6482719	Valve Adjustment:No Flow Measurement,High Temp
CV-2555	10/6/2026 9:31:28 AM	40.9	58.2	0.0	0.9			0.7	0.0	124.2	123.5	-3.52	-2.12	31.5	4.8	6.493	0.150	-3.47	-1.35	1358	34.4348280	-118.6476827	Valve Adjustment:Decreased Flow/Vacuum
CV-2555	10/21/2026 9:25:00 AM	28.6	68.9	0.2	2.3			0.4	11.5	126.5	127.2	-0.13	-0.13	12.2	10.8	0.957	0.758	-6.57	-6.44	1364	34.4347980	-118.6477015	Valve Adjustment:Barely Open;Well Condition:Lorentz Pump Installed
CV-2556-PL	10/7/2026 1:24:09 PM	8.0	81.9	0.0	10.1			0.1	0.0	177.0	116.0	-2.12	-2.11			2.120	2.115	-2.13	-0.02	1372	34.4351567	-118.6472305	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-2556-PL	10/7/2026 1:25:00 PM					1580																	AtmAA
CV-2556-PL	10/7/2026 1:25:00 PM						62100																AtmAA; [User entered 6.21%]
CV-2556-PL	10/14/2026 10:35:34 AM	26.4	43.2	3.2	27.2			0.6	8.5	168.0	77.1	-6.40	-6.11			6.836	6.649	-6.64	-0.53	1368	34.4351441	-118.6472111	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2556-PL	10/14/2026 10:40:00 AM					1130																	AtmAA
CV-2556-PL	10/20/2026 1:09:50 PM	12.5	54.7	1.5	31.3			0.2	20.9	174.5	174.5	-4.54	-4.53			4.505	4.505	-8.46	-3.93	1385	34.4351523	-118.6471843	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2556-PL	10/20/2026 1:15:00 PM					1250																	AtmAA
CV-2556-PL	10/27/2026 9:37:37 AM	18.5	43.6	2.4	35.5			0.4	14.8	169.9	169.9	-4.25	-4.19			4.290	4.267	-11.87	-7.68	1358	34.4351474	-118.6472073	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2556-PL	10/27/2026 9:40:00 AM					614																	AtmAA
CV-2557	10/1/2026 9:59:43 AM	12.7	81.4	0.0	5.9			0.2	0.0	138.9	142.6	-2.82	-2.64			2.840	2.561	-6.49	-3.85				Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2557	10/23/2026 7:41:36 AM	13.6	47.9	0.0	38.5			0.3	0.0	145.4	145.3	-6.57	-6.48			6.905	6.774	-11.55	-5.07	1379	34.4354878	-118.6464727	Valve Adjustment:Barely Open
CV-2557	10/26/2026 2:25:00 AM					1690																	AtmAA
CV-2557	10/26/2026 2:27:50 PM	17.7	45.6	0.3	36.4			0.4	121.3	142.9	142.5	-8.25	-7.91			8.194	7.949	-4.16	3.75	1393	34.4354987	-118.6465005	Valve Adjustment:No Flow Measurement,High Temp;Well Condition:Lorentz Pump Installed
CV-2558-PL	10/7/2026 10:20:00 AM					1420																	AtmAA
CV-2558-PL	10/7/2026 10:20:00 AM						79000																AtmAA; [User entered 7.9%]
CV-2558-PL	10/7/2026 10:26:07 AM	20.1	72.5	0.0	7.4			0.3	0.0	193.8	195.2	8.60	8.09			0.000	0.000	0.06	-8.03	1392	34.4352826	-118.6463073	Valve Adjustment:No Flow Measurement,High Temp,Positive Static Press.,Reduce Sys. Vac. - Flare Down
CV-2558-PL	10/15/2026 7:50:00 AM					2085																	AtmAA
CV-2558-PL	10/15/2026 7:55:07 AM	9.4	79.2	0.4	11.0			0.1	27.5	178.7	178.6	-7.64	-7.08			4.992	7.392	0.04	7.12	1374	34.4352905	-118.6463116	Valve Adjustment:No Flow Measurement,High Temp
CV-2558-PL	10/19/2026 3:01:52 PM	18.1	77.6	0.0	4.3			0.2	0.0	185.2	185.4	-2.23	-1.42			1.900	1.115	-0.04	1.38	1382	34.4352922	-118.6463004	Valve Adjustment:No Flow Measurement,High Temp
CV-2558-PL	10/26/2026 1:56:00 PM					3210																	AtmAA
CV-2558-PL	10/26/2026 2:05:56 PM	12.3	76.7	0.0	11.0			0.2	0.0	189.3	191.3	4.09	3.74			0.000	0.000	-0.11	-3.85	1392	34.4353005	-118.6463043	Valve Adjustment:No Flow Measurement,High Temp
CV-2559	10/14/2026 1:18:10 PM	11.1	74.8	0.0	14.1			0.1	0.0	119.7	119.6	-0.99	-1.01			0.972	1.005	-3.54	-2.53	1382	34.4357478	-118.6454847	
CV-2559	10/26/2026 10:35:04 AM	23.5	71.0	0.0	5.5			0.3	0.0	130.4	130.3	-3.21	-2.06			3.215	2.055	-8.15	-6.09	1378	34.4357438	-118.6454758	Valve Adjustment:Decreased Flow/Vacuum
CV-2560	10/14/2026 2:00:11 PM	10.2	75.3	0.0	14.5			0.1	0.0	121.8	121.8	-0.70	-0.69			0.708	0.694	-11.45	-10.76	1375	34.4359123	-118.6466733	
CV-2560	10/23/2026 8:16:58 AM	10.2	85.3	0.0	4.5			0.1	0.0	129.1	128.9	-0.97	-0.97			0.970	0.982	-12.64	-11.67	1397	34.4359143	-118.6466467	Valve Adjustment:Barely Open
CV-2561	10/14/2026 10:56:57 AM	15.4	36.5	1.2	46.9			0.4	39.1	97.6	97.6	-0.98	-0.98			0.928	0.939	-1.08	-0.1	1404	34.4360692	-118.6466087	Valve Adjustment:Barely Open
CV-2561	10/23/2026 8:22:59 AM	8.3	33.7	1.6	56.4			0.2	35.3	115.0	115.0	-3.04	-3.03			3.037	3.030	-8.28	-5.25	1390	34.4360923	-118.6465938	
CV-2562	10/26/2026 10:27:44 AM	33.3	51.8	0.2	14.7			0.6	73.5	128.0	128.0	-6.50	-6.12			6.862	6.402	-6.65	-0.53	1388	34.4360737	-118.6459482	Valve Adjustment:Decreased Flow/Vacuum
CV-2563	10/21/2026 8:53:45 AM	42.3	53.0	0.0	4.7			0.8	0.0	96.3	96.2	-0.29	-0.29	0.2	1.1	0.001	0.025	-2.19	-1.9	1318	34.4373355	-118.6457557	
CV-2564	10/1/2026 10:35:23 AM	32.0	57.3	0.0	10.7			0.6	0.0	117.1	117.4	-3.95	-3.27	0.0	0.0	3.960	2.925	-8.71	-5.44	1332	34.4331273	-118.6487683	,
CV-2564	10/20/2026 9:58:48 AM	27.2	65.8	0.7	6.3			0.4	9.0	112.0	112.1	-3.65	-3.52			3.659	3.514	-7.53	-4.01	1375	34.4331097	-118.6487635	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
CV-2564	10/22/2026 8:57:59 AM	29.4	70.3	0.0	0.3			0.4	0.0	107.5	107.4	-3.85	-4.14			3.865	4.165	-7.11	-2.97	1363	34.4331277	-118.6487333	Valve Adjustment:Increased Flow/Vacuum
CV-2565	10/7/2026 1:29:08 PM	39.3	44.1	0.0	16.6			0.9	0.0	118.7	118.4	-0.64	-0.64			0.652	0.653	-8.00	-7.36	1321	34.4319777	-118.6489995	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-2566	10/7/2026 1:37:30 PM	48.4	45.6	0.0	6.0			1.1	0.0	118.3	118.7	-1.68	-1.68			1.686	1.692	-7.19	-5.51	1315	34.4318077	-118.6487742	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-2566	10/20/2026 8:17:20 AM	47.8	45.0	0.0	7.2			1.1	0.0	97.3	98.5	-3.85	-2.16			3.852	2.162	-15.29	-13.13	1331	34.4318085	-118.6487808	Valve Adjustment:Decreased Flow/Vacuum;Well Repairs:Sample Port
CV-2566	10/20/2026 8:18:09 AM	47.6	45.4	0.0	7.0			1.0	0.0	98.0	97.9	-1.95	-1.94			1.959	1.950	-15.44	-13.5	1332	34.4318042	-118.6487768	
CV-2567	10/6/2026 9:56:41 AM	49.6	43.2	0.0	7.2			1.1	0.0	118.3	118.4	-3.44	-3.44			3.366	3.366	-13.07	-9.63	1361	34.4319817	-118.6480868	Valve Adjustment:Barely Open
CV-2567	10/16/2026 1:32:11 PM	47.1	46.2	0.0	6.7			1.0	0.0	110.6	105.1	-3.02	-1.79			2.985	1.705	-16.79	-15	1361	34.4319567	-118.6480623	Valve Adjustment:Decreased Flow/Vacuum
CV-2568	10/6/2026 10:15:58 AM	31.0	38.3	0.0	30.7			0.8	0.0	115.9	115.9	-1.45	-1.45			1.436	1.419	-13.25	-11.8	1356	34.4321693	-118.6477362	Valve Adjustment:Barely Open
CV-2568	10/16/2026 9:13:33 AM	25.8	37.5	0.0	36.7			0.7	0.0	100.3	95.4	-1.65	-1.23			1.661	1.308	-12.00	-10.77	1345	34.4321560	-118.6477472	Valve Adjustment:Decreased Flow/Vacuum,Barely Open,Reduce Sys. Vac. - Flare Down
CV-2569	10/7/2026 9:28:38 AM	39.5	42.8	0.2	17.6			0.9	117.1	106.6	107.4	-1.87	-1.86			1.862	1.865	-10.42	-8.56	1346	34.4322197	-118.6473822	Valve Adjustment:Reduce Sys. Vac. - Flare Down

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-2569	10/16/2026 9:27:53 AM	35.5	40.9	0.0	23.6			0.9	0.0	112.7	102.4	-2.68	-1.16			2.595	1.125	-15.62	-14.46	1346	34.4322083	-118.6473938	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-2570	10/7/2026 9:14:44 AM	49.2	42.8	0.0	8.0			1.2	0.0	107.0	106.0	-1.80	-1.80			1.799	1.797	-9.18	-7.38	1346	34.4324227	-118.6469763	Valve Adjustment:Reduce Sys. Vac. - Flare Down
CV-2570	10/16/2026 9:42:57 AM	45.1	42.6	0.0	12.3			1.1	0.0	115.5	104.9	-2.56	-1.84			2.503	1.823	-15.40	-13.56	1350	34.4324173	-118.6469828	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-2571	10/6/2026 9:29:44 AM	48.4	36.6	0.0	15.0			1.3	0.0	97.1	97.1	-10.72	-10.74	65.9	65.7	2.722	2.702	-16.00	-5.26	1136	34.4299740	-118.6457260	
CV-2572	10/25/2026 2:07:36 PM	51.1	40.0	0.0	8.9			1.3	0.0	122.5	122.5	-3.19	-3.31	36.3	39.7	3.603	4.320	-7.70	-4.39	1143	34.4298073	-118.6470653	Valve Adjustment:Increased Flow/Vacuum
CV-2572	10/25/2026 2:09:00 PM	50.6	39.8	0.0	9.6			1.3	0.0	122.5	122.5	-3.32	-3.34	39.6	39.6	4.301	4.310	-8.11	-4.77	1145	34.4297982	-118.6470607	
CV-2602	10/12/2026 1:20:30 PM	45.5	40.1	0.0	14.4			1.1	0.0	109.1	107.8	-6.33	-3.65	62.6	27.0	5.107	0.931	-13.05	-9.4	1143	34.4284610	-118.6498065	Valve Adjustment:Decreased Flow/Vacuum
CV-2602	10/12/2026 1:27:29 PM	45.3	40.6	0.0	14.1			1.1	0.0	105.7	104.2	-3.16	-2.69	28.8	22.4	1.898	1.141	-18.36	-15.67	1140	34.4284638	-118.6498008	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
CV-2602	10/12/2026 1:30:13 PM	45.2	41.0	0.0	13.8			1.1	0.0	102.8	102.7	-2.49	-2.49	22.4	22.3	1.138	1.129	-18.43	-15.94	1156	34.4284477	-118.6498122	
CV-2603	10/6/2026 10:16:01 AM	35.6	35.3	0.0	29.1			1.0	0.0	123.0	123.1	-1.82	-1.82	19.5	19.5	0.886	0.883	-10.49	-8.67	1133	34.4283460	-118.6487607	
CV-2603	10/31/2026 11:36:27 AM	32.8	31.5	0.0	35.7			1.0	0.0	118.9	118.2	-1.57	-1.22	24.7	20.5	1.419	0.974	-15.02	-13.8				Valve Adjustment:Decreased Flow/Vacuum,Barely Open
CV-2603	10/31/2026 11:37:52 AM	33.0	31.4	0.0	35.6			1.1	0.0	117.7	117.7	-1.19	-1.18	19.8	20.5	0.905	0.971	-15.25	-14.07				
CV-2605	10/19/2026 9:30:44 AM	35.3	35.7	0.0	29.0			1.0	0.0	131.2	130.5	-1.05	-0.69	16.9	9.8	6.217	2.055	-10.16	-9.47	1097	34.4275490	-118.6489678	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Decreased Flow/Vacuum
CV-2605	10/19/2026 9:33:32 AM	36.4	37.6	0.0	26.0			1.0	0.0	128.9	129.4	-0.41	-0.41	5.0	5.0	0.534	0.536	-9.57	-9.16	1096	34.4275365	-118.6489615	Valve Adjustment:Barely Open
CV-2606	10/6/2026 12:49:31 PM	43.8	40.0	0.0	16.2			1.1	0.0	125.2	124.9	-1.12	-0.78	13.4	9.7	0.418	0.220	-11.28	-10.5	1134	34.4289035	-118.6484102	Valve Adjustment:Decreased Flow/Vacuum
CV-2606	10/6/2026 1:00:30 PM	46.8	40.2	0.0	13.0			1.2	0.0	124.4	124.4	-0.63	-0.63	8.9	9.0	0.512	0.519	-11.08	-10.45	1131	34.4288885	-118.6484395	Valve Comment:1.25 inch swapped for 1 inch;Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-2608	10/6/2026 1:37:58 PM	50.5	42.0	0.0	7.5			1.2	0.0	127.3	127.3	-1.23	-1.22	19.2	18.5	0.869	0.808	-11.97	-10.75	1144	34.4293240	-118.6480945	
CV-2610	10/14/2026 2:25:38 PM	44.3	38.7	0.0	17.0			1.1	0.0	115.5	115.4	-2.88	-2.23	23.2	17.5	3.419	1.923	-19.80	-17.57	1143	34.4298190	-118.6465757	Valve Adjustment:Decreased Flow/Vacuum
CV-2610	10/14/2026 2:28:40 PM	44.9	38.9	0.0	16.2			1.2	0.0	115.4	115.5	-2.14	-2.15	17.0	17.4	1.819	1.908	-19.00	-16.85	1135	34.4298417	-118.6465630	
CV-2611	10/6/2026 9:41:09 AM	55.5	41.7	0.0	2.8			1.3	0.0	104.0	103.8	-3.68	-3.67	7.5	7.4	1.148	1.133	-14.08	-10.41	1152	34.4303287	-118.6459532	
CV-2612	10/6/2026 2:12:42 PM	51.3	44.1	0.0	4.6			1.2	0.0	128.1	128.2	-0.05	-0.07	12.8	14.0	0.453	0.536	-10.55	-10.48	1237	34.4311973	-118.6471187	Valve Adjustment:NSPS/EG CAC,Increased Flow/Vacuum
CV-2612	10/6/2026 2:15:50 PM	51.0	44.0	0.0	5.0			1.2	0.0	128.2	128.2	-0.13	-0.14	13.5	13.5	0.502	0.504	-10.83	-10.69	1240	34.4312040	-118.6471148	
CV-2612	10/23/2026 2:31:53 PM	56.4	41.3	0.0	2.3			1.4	0.0	127.2	127.5	-0.31	-0.40			0.000	0.000	-12.10	-11.7	1247	34.4311923	-118.6470982	Valve Adjustment:Increased Flow/Vacuum
CV-2612	10/25/2026 12:51:07 PM	56.8	40.2	0.0	3.0			1.4	0.0	128.5	128.9	-0.98	-1.17	15.9	18.0	0.714	0.918	-11.13	-9.96	1247	34.4311822	-118.6471032	
CV-2613	10/6/2026 12:27:53 PM	53.1	36.7	0.0	10.2			1.4	0.0	122.0	122.1	-0.01	-0.01	13.2	14.5	0.405	0.490	-10.16	-10.15	1261	34.4306343	-118.6480012	
CV-2613	10/25/2026 1:00:43 PM	50.0	39.2	0.0	10.8			1.3	0.0	121.4	121.4	-0.06	-0.09	15.3	16.8	0.542	0.657	-10.82	-10.73	1257	34.4306243	-118.6480025	
CV-2614	10/6/2026 12:49:39 PM	51.7	40.8	0.0	7.5			1.3	0.0	126.7	126.7	-0.42	-0.37	21.7	21.2	1.107	1.061	-12.46	-12.09	1256	34.4305072	-118.6484780	
CV-2614	10/25/2026 1:11:41 PM	52.8	40.7	0.0	6.5			1.3	0.0	127.2	127.3	-0.68	-0.76	22.0	23.6	1.139	1.307	-13.18	-12.42	1269	34.4304778	-118.6484630	
CV-2614	10/25/2026 1:13:05 PM	51.6	40.8	0.0	7.6			1.3	0.0	127.4	127.3	-0.76	-0.76	23.9	24.2	1.343	1.374	-13.26	-12.5	1261	34.4305033	-118.6484748	
CV-2615	10/6/2026 1:17:41 PM	45.7	47.0	0.0	7.3			1.0	0.0	117.0	117.0	-0.18	-0.18	6.0	5.3	0.763	0.581	-11.42	-11.24	1303	34.4312122	-118.6492760	
CV-2627	10/23/2026 2:47:20 PM	53.3	42.4	0.2	4.1			1.3	20.5	100.1	109.9	4.70	-0.29			0.000	0.000	-15.89	-15.6	1195	34.4309913	-118.6461867	Valve Adjustment:NSPS/EG CAI,High O2,Increased Flow/Vacuum
CV-2627	10/23/2026 2:48:03 PM	53.8	41.7	0.0	4.5			1.3	0.0	110.6	110.6	-0.37	-0.40			0.000	0.000	-15.84	-15.44	1200	34.4309955	-118.6461843	Valve Adjustment:NSPS/EG CAC
CV-2634	10/23/2026 3:05:30 PM	0.3	2.7	21.8	75.2			0.1	3.4	73.3	73.4	-16.12	-16.27	0.8	0.7	0.013	0.009	-15.91	0.36	1217	34.4313830	-118.6454765	Valve Adjustment:NSPS/EG CAI,High O2,Increased Flow/Vacuum
CV-2636	10/4/2026 12:36:28 PM	43.9	42.5	2.3	11.2			1.0	4.8	114.2	114.2	-3.71	-4.07	5.7	7.8	0.677	1.298	-12.55	-8.48	1303	34.4372455	-118.6453228	Valve Adjustment:Orifice Plate Changed (See OP Log),Reconnected this Date,Increased Flow/Vacuum
CV-2636	10/4/2026 12:37:35 PM	44.9	42.8	2.0	10.4			1.0	5.2	114.3	114.3	-4.90	-4.90	7.6	7.7	1.211	1.259	-12.53	-7.63	1307	34.4372548	-118.6453127	
CV-2636	10/4/2026 12:41:29 PM	46.0	43.9	1.4	8.7			1.0	6.2	114.5	114.8	-10.07	-8.73	15.2	10.8	1.491	0.751	-12.37	-3.64	1319	34.4372585	-118.6453315	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
CV-2637	10/4/2026 12:12:43 PM	30.4	45.7	0.0	23.9			0.7	0.0	123.3	123.4	-5.37	-5.37	4.3	4.0	0.390	0.341	-8.84	-3.47	1300	34.4370983	-118.6444123	Valve Adjustment:Orifice Plate Changed (See OP Log),Reconnected this Date
CV-2637	10/4/2026 12:19:05 PM	29.6	45.9	0.0	24.5			0.6	0.0	122.3	122.6	-5.12	-5.33	4.4	5.2	0.416	0.571	-8.60	-3.27	1297	34.4370845	-118.6444105	Valve Adjustment:Increased Flow/Vacuum
CV-2637	10/4/2026 12:20:22 PM	29.8	47.4	0.0	22.8			0.6	0.0	123.6	123.8	-5.71	-5.71	5.5	5.6	0.653	0.676	-8.83	-3.12	1305	34.4370948	-118.6444073	Valve Adjustment:Surging Liquid in Header
CV-2638	10/26/2026 1:49:28 PM	6.3	33.5	10.2	50.0			0.2	4.9	88.0	89.8	-8.93	-8.82			0.000	0.000	-8.96	-0.14	1357	34.4364012	-118.6436538	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-2638	10/26/2026 1:53:31 PM	3.8	18.1	11.5	66.6			0.2	5.8	89.9	90.8	-8.78	-8.90			0.000	0.000	-8.60	0.3	1370	34.4364128	-118.6436243	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
CV-2654	10/30/2026 1:42:21 PM	46.9	49.9	0.0	3.2			0.9	0.0	96.9	94.3	-1.07	-0.85	5.3	1.6	7.303	0.628	-15.10	-14.25	1390	34.4354388	-118.6443882	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Barely Open;Well Comment:Well Startup
CV-2656	10/30/2026 1:52:10 PM	43.7	49.1	0.0	7.2			0.9	0.0	103.9	98.5	-1.41	-1.04	6.1	0.9	9.804	0.199	-15.04	-14	1379	34.4352252	-118.6443585	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Barely Open;Well Comment:Well Startup
CV-2660	10/30/2026 2:01:04 PM	34.7	62.0	0.0	3.3			0.6	0.0	92.5	90.5	-1.42	-1.05	5.1	1.2	6.682	0.372	-14.97	-13.92	1388	34.4349837	-118.6443595	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Barely Open;Well Comment:Well Startup
CV-2663	10/15/2026 11:17:22 AM	25.3	45.1	3.2	26.4			0.6	8.3	133.4	128.0	-0.33	-1.78	12.9	6.6	1.075	0.281	-14.14	-12.36	1338	34.4350717	-118.6433355	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-2664	10/29/2026 1:45:00 PM	28.2	68.2	0.0	3.6			0.4	0.0	130.1	130.7	0.04	-0.03	4.8	6.5	0.148	0.271	-13.37	-13.34	1379	34.4347430	-118.6443745	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Increased Flow/Vacuum
CV-2664	10/29/2026 1:50:06 PM	28.1	68.7	0.0	3.2			0.4	0.0	130.5	130.5	-0.02	-0.03	8.6	8.6	1.620	1.619	-13.39	-13.36	1379	34.4347583	-118.6443756	Valve Adjustment:Orifice Plate Changed (See OP Log)
CV-2676	10/2/2026 12:59:21 PM	21.3	57.3	2.4	19.0			0.4	8.1	142.7	143.3	-15.36	-13.07			15.682	13.349	-15.56	-2.49	1319	34.4336318	-118.6434847	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
CV-2676	10/2/2026 1:01:54 PM	20.2	59.5	2.0	18.3			0.3	9.2	145.0	145.0	-12.76	-12.76			13.059	13.120	-15.94	-3.18	1321	34.4336347	-118.6434862	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2676	10/4/2026 1:15:09 PM	22.3	53.6	1.3	22.8			0.4	17.4	141.3	125.2	-14.10	-1.82			14.102	1.780	-16.38	-14.56	1320	34.4336178	-118.6435032	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,High Temp,Decreased Flow/Vacuum;Well Condition:Pnumatic Pump Installed
CV-2676	10/4/2026 1:34:55 PM	11.1	62.1	0.3	26.4			0.2	77.7	135.0	132.8	-1.19	-0.38			1.215	0.401	-16.39	-16.01	1303	34.4336232	-118.6434928	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum;Well Comment:fastened bolts on 3 flanges;Well Condition:Pnumatic Pump Installed
CV-2676	10/4/2026 1:36:45 PM	9.4	63.6	0.1	26.9			0.1	207.1	132.9	133.2	-0.58	-0.58			0.591	0.591	-16.82	-16.24	1316	34.4336215	-118.6434797	Valve Adjustment:High Temp;Well Condition:Pnumatic Pump Installed
CV-2676	10/22/2026 9:49:45 AM	18.6	78.0	0.9	2.5			0.2	2.8	140.2	140.2	-9.59	-9.67			9.571	9.609	-9.20	0.47	1316	34.4336248	-118.6434842	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-2676	10/22/2026 9:51:07 AM	18.3	77.7	0.6	3.4			0.2	5.7	140.2	140.4	-9.82	-9.82			9.823	9.823	-9.72	0.1	1321	34.4336222	-118.6434912	Valve Adjustment:NSPS/EG CAI,High Temp
CV-2680	10/12/2026 9:59:18 AM	43.7	41.2	0.0	15.1			1.1	0.0	129.5	129.1	-3.91	-3.74	7.7	6.7	6.690	5.119	-18.51	-14.77	1289	34.4353732	-118.6421153	
CV-2681	10/29/2026 1:35:25 PM	35.0	37.1	0.0	27.9			0.9	0.0	120.4	121.1	-17.43	-17.29			17.422	17.319	-17.23	0.06	1286	34.4352918	-118.6426348	
CV-2683	10/12/2026 10:47:06 AM	19.0	51.3	0.0	29.7			0.4	0.0	76.6	76.6	-6.94	-6.31	15.8	14.8	4.991	4.407	-16.63	-10.32	1280	34.4347068	-118.6424752	
CV-2684	10/15/2026 1:47:53 PM	42.7	38.8	0.2	18.3			1.1	91.5	94.9	96.4	-0.57	-0.58			0.554	0.554	-7.26	-6.68	1273	34.4342127	-118.6422015	
CV-2687	10/15/2026 12:50:35 PM	50.8	39.1	0.2	9.9			1.3	49.5	115.2	115.4	-2.68	-2.79	1.8	3.1	0.065	0.199	-21.35	-18.56	1259	34.4336002	-118.6415832	
CV-2688	10/25/2026 3:07:57 PM	57.0	41.3	0.0	1.7			1.4	0.0	122.5	122.7	-0.61	-0.84	8.4	9.8	0.446	0.607	-22.03	-21.19	1206	34.4327457	-118.6424110	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
CV-2688	10/25/2026 3:12:18 PM	55.7	42.3	0.0	2.0			1.3	0.0	124.9	125.0	-8.42	-10.67	22.6	25.6	0.679	0.880	-21.62	-10.95	1214	34.4327492	-118.6424045	Valve Adjustment:Increased Flow/Vacuum
CV-2688	10/25/2026 3:13:10 PM	55.4	42.6	0.0	2.0			1.3	0.0	125.2	125.2	-11.79	-11.79	24.9	23.7	0.834	0.757	-22.16	-10.37	1214	34.4327382	-118.6424017	
CV-2689	10/5/2026 8:53:44 AM	0.9	62.7	0.0	36.4			0.0	0.0	110.5	111.6	-14.77	-14.77			14.971	14.913	-15.11	-0.34	1241	34.4328180	-118.6433785	Valve Adjustment:Increased Flow/Vacuum,Valve 100% Open
CV-2689	10/5/2026 8:54:48 AM	0.9	61.6	0.0	37.5			0.0	0.0	112.5	112.5	-14.77	-14.77			15.054	15.068	-15.10	-0.33	1239	34.4328143	-118.6433695	Valve Adjustment:Valve 100% Open;Well Condition:Pnumatic Pump Installed
CV-2690	10/25/2026 3:22:21 PM	55.2	42.5	0.0	2.2			1.3	0.0	116.2	117.5	-18.93	-20.95	3.9	1.7	0.021	0.004	-21.54	-0.59	1208	34.4324163	-118.6429335	Valve Adjustment:Orifice Plate Changed (See OP Log),Barely Open,Plugged/Pinched Suspected
CV-2691	10/25/2026 2:18:48 PM	55.3	40.5	0.0	4.2			1.4	0.0	126.5	126.4	-3.78	-4.13	21.1	25.0	2.873	4.063	-21.47	-17.34	1209	34.4321047	-118.6431942	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
CV-2691	10/25/2026 2:21:41 PM	54.0	41.3	0.0	4.7			1.3	0.0	126.8	126.8	-4.49	-4.78	24.2	26.8	0.774	0.948	-21.24	-16.46	1220	34.4321217	-118.6431903	Valve Adjustment:Increased Flow/Vacuum
CV-2692	10/1/2026 1:22:44 PM	54.5	42.4	0.0	3.1			1.3	0.0	127.7	127.8	-0.62	-0.61	29.3	29.4	1.129	1.141	-9.22	-8.61	1212	34.4316443	-118.6444730	Valve Adjustment:Audible Flow,Reduce Sys. Vac. - Flare Down
CV-2695	10/6/2026 9:05:24 AM	53.6	42.1	0.0	4.3			1.3	0.0	115.0	115.2	-1.37	-1.58	17.9	20.4	0.411	0.536	-14.60	-13.02	1186	34.4288692	-118.6501702	Valve Adjustment:Increased Flow/Vacuum
CV-2695	10/6/2026 9:07:08 AM	53.8	41.9	0.0	4.3			1.3	0.0	115.3	115.3	-1.63	-1.60	20.6	20.0	0.546	0.514	-14.85	-13.25	1187	34.4288947	-118.6501587	
CV-48R	10/21/2026 8:40:04 AM	55.0	43.0	0.0	2.0			1.3	0.0	119.0	119.2	-2.23	-2.27	4.2	4.6	0.114	0.137	-2.33	-0.06	1314	34.4373462	-118.6458502	
CV-52D	10/29/2026 1:55:52 PM	42.9	44.7	0.0	12.4			1.0	0.0	102.3	102.7	-18.32	-18.24	1.9	1.9	1.030	1.019	-19.56	-1.32	1304	34.4359468	-118.6424698	
CV-55R	10/1/2026 3:39:53 PM	46.8	50.0	0.0	3.2			0.9	0.0	152.6	152.8	-5.40	-5.39	3.4	1.2	0.081	0.011	-14.35	-8.96	1311	34.4343637	-118.6427844	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-55R	10/1/2026 3:40:00 PM					346																	AtmAA

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
CV-55R	10/2/2026 1:31:08 PM	34.4	49.6	0.1	16.0			0.7	177.3	153.3	153.6	-5.72	-6.03	6.5	8.1	0.287	0.449	-15.00	-8.97	1304	34.4343660	-118.6427898	Valve Adjustment:NSPS/EG CAI,High Temp,Increased Flow/Vacuum
CV-55R	10/8/2026 4:21:03 PM	33.6	47.8	0.0	18.6			0.7	0.0	152.1	152.2	-1.81	-1.83	3.1	4.7	0.065	0.147	-6.23	-4.4	1307	34.4343736	-118.6427628	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-55R	10/8/2026 4:23:00 PM					337																	AtmAA
CV-55R	10/8/2026 4:23:00 PM						171500																AtmAA; [User entered 17.15%]
CV-55R	10/15/2026 12:04:54 PM	34.6	55.5	0.0	9.9			0.6	0.0	149.3	149.7	-6.79	-7.15	6.7	9.2	0.306	0.571	-15.45	-8.3	1320	34.4343865	-118.6427820	Valve Adjustment:Increased Flow/Vacuum
CV-55R	10/15/2026 2:25:00 PM					413																	AtmAA
CV-55R	10/15/2026 2:25:15 PM	31.1	53.1	0.1	15.7			0.6	157.0	148.4	148.7	-4.51	-4.34	4.2	6.0	0.120	0.245	-7.37	-3.03	1312	34.4343726	-118.6427699	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-55R	10/21/2026 7:59:43 AM	32.2	48.9	0.4	18.5			0.7	46.3	151.3	151.6	-4.01	-4.00	6.2	5.8	0.258	0.227	-8.04	-4.04	1311	34.4343815	-118.6427742	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-55R	10/21/2026 8:10:00 AM					565																	AtmAA
CV-55R	10/28/2026 10:17:30 AM	34.1	51.3	0.0	14.6			0.7	0.0	151.8	151.7	-10.01	-9.80	7.7	8.3	0.410	0.469	-15.71	-5.91	1317	34.4343723	-118.6427872	Valve Adjustment:High Temp;Well Condition:Lorentz Pump Installed
CV-55R	10/28/2026 10:18:00 AM					377																	AtmAA
CV-56D	10/5/2026 1:25:09 PM						28000																[User entered 2.8%]
CV-56D	10/5/2026 1:26:11 PM	43.7	44.0	0.0	12.4			1.0	0.0	118.5	118.7	-2.01	-2.01	19.6	19.4	8.255	8.058	-16.25	-14.24	1278	34.4337902	-118.6431765	
CV-56D	10/5/2026 1:29:58 PM	43.7	39.3	0.0	17.0			1.1	0.0	123.2	123.7	-2.59	-2.46	10.8	9.5	2.485	1.932	-16.40	-13.94	1302	34.4338033	-118.6431735	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
CV-56D	10/5/2026 1:31:19 PM	43.5	40.2	0.0	16.2			1.1	0.0	124.3	124.3	-2.49	-2.50	9.1	9.5	1.774	1.945	-16.43	-13.93	1311	34.4337852	-118.6431783	
CV-56S	10/5/2026 1:21:51 PM	40.8	37.2	0.3	21.7			1.1	77.4	120.0	120.0	-1.93	-1.98	4.1	3.6	0.353	0.276	-16.58	-14.6	1309	34.4337940	-118.6431753	
CV-56S	10/5/2026 1:23:15 PM						28000																[User entered 2.8%]
CV-57R	10/28/2026 9:01:33 AM	56.4	38.3	0.0	5.3			1.5	0.0	87.1	87.3	-1.21	-1.20	0.4	0.4	0.004	0.004	-18.32	-17.12	1350	34.4343203	-118.6435825	Valve Adjustment:NSPS/EG CAI,No Flow Measurement
CV-57R	10/28/2026 9:03:25 AM	54.7	39.7	0.0	5.6			1.4	0.0	87.8	104.8	-3.36	-4.09	5.5	5.7	0.618	0.673	-19.27	-15.18	1346	34.4343192	-118.6435880	Valve Adjustment:NSPS/EG CAC,Increased Flow/Vacuum
CV-79R	10/7/2026 10:39:08 AM	53.7	43.9	0.0	2.4			1.2	0.0	135.0	135.1	-5.63	-4.43	6.2	6.0	0.047	0.044	-9.95	-5.52	1286	34.4332393	-118.6447707	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-79R	10/7/2026 10:40:02 AM	53.3	44.1	0.0	2.6			1.2	0.0	134.8	134.8	-3.93	-3.93	5.5	5.7	0.037	0.040	-10.17	-6.24	1319	34.4332717	-118.6448863	NSPS/EG CAI,High Temp,Reduced System Vacuum
CV-94	10/7/2026 2:12:32 PM	52.4	39.2	0.0	8.4			1.3	0.0	115.6	115.6	-0.75	-0.77	0.0	0.0	-0.066	-0.654	-5.99	-5.22	1339	34.4348067	-118.6437693	Reduced System Vacuum,
CV-94	10/27/2026 8:09:55 AM	29.3	32.1	0.3	38.3			0.9	127.7	109.2	109.0	-16.15	-16.25	10.6	11.0	0.731	0.782	-17.43	-1.18	1356	34.4349008	-118.6436578	
CV-95	10/28/2026 8:50:54 AM	24.1	29.0	0.3	46.6			0.8	155.3	58.1	58.2	-0.93	-0.93	0.6	0.6	0.008	0.006	-23.75	-22.82	1349	34.4342952	-118.6436243	
CV-99	10/8/2026 7:35:00 AM					110																	Air Tech Lab
CV-99	10/8/2026 7:35:00 AM						11000																Air Tech Lab; [User entered 1.1%]
CV-99	10/13/2026 10:56:53 AM	30.3	59.4	1.7	8.6			0.5	5.1	81.9	82.0	-15.58	-15.34	1.7	1.6	0.060	0.052	-15.25	0.09	1326	34.4370515	-118.6463180	
CV-99	10/26/2026 9:07:28 AM	26.5	67.8	1.1	4.6			0.4	4.2	70.0	70.0	-11.31	-11.18	0.3	1.0	0.002	0.021	-11.13	0.05	1328	34.4370458	-118.6463270	Valve Adjustment:High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
D-02	10/29/2026 8:29:01 AM	62.6	37.0	0.0	0.4			1.7	0.0	84.0	84.1	-25.83	-25.81	11.3	10.2	0.111	0.090	-26.01	-0.2	1181	34.4311763	-118.6443023	
D-03	10/29/2026 8:33:23 AM	59.5	37.5	0.0	3.0			1.6	0.0	85.3	85.3	-2.36	-2.35	7.8	7.1	0.050	0.041	0.46	2.81	1180	34.4311758	-118.6442965	Valve Adjustment:NSPS/EG CAI
D-03	10/29/2026 8:35:45 AM	58.1	38.9	0.0	3.0			1.5	0.0	85.5	85.5	-2.34	-2.34	3.3	3.3	0.009	0.009	-2.19	0.15	1177	34.4311602	-118.6443023	Valve Adjustment:NSPS/EG CAC,Increased Flow/Vacuum
D-04	10/29/2026 2:19:49 PM	57.7	37.7	0.0	4.6			1.5	0.0	85.1	85.1	-22.88	-22.90	8.6	5.3	0.095	0.036	-22.83	0.07	1163	34.4311902	-118.6443190	
D-09	10/14/2026 1:44:01 PM	50.7	41.2	0.0	8.2			1.2	0.0	116.1	116.2	-15.22	-15.28	8.5	9.1	1.583	1.783	-16.57	-1.29	1123	34.4301145	-118.6463467	
D-09	10/14/2026 1:56:17 PM	50.7	41.0	0.0	8.3			1.2	0.0	115.7	116.0	-15.82	-16.41	9.1	9.5	0.540	0.584	-16.38	0.03	1131	34.4301145	-118.6463403	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum,Valve 100% Open
D-10	10/14/2026 9:39:12 AM	56.4	40.4	0.0	3.2			1.4	0.0	80.6	81.7	-19.57	-19.49	1.7	1.9	0.017	0.023	-19.59	-0.1	1139	34.4302168	-118.6458177	Valve Adjustment:Plugged/Pinched Suspected
FP-001	10/26/2026 8:06:22 AM	21.1	18.8	6.3	53.8			1.1	8.5	71.2	71.5	-0.38	-0.37	9.5	8.0	0.530	0.373	-15.31	-14.94	1349	34.4366500	-118.6458215	
FP-002	10/26/2026 8:17:25 AM	3.1	7.7	15.1	74.1			0.4	4.9	79.8	81.6	-0.16	-0.17	13.1	12.7	3.377	3.192	-6.37	-6.2	1354	34.4366450	-118.6461997	
FP-003	10/26/2026 8:22:11 AM	34.0	35.0	2.7	28.3			1.0	10.5	77.3	77.6	-0.14	-0.15	2.4	2.3	0.572	0.524	-7.37	-7.22	1367	34.4365860	-118.6465238	
FP-005	10/26/2026 10:47:11 AM	0.1	2.2	18.5	79.2			0.0	4.3	82.7	82.7	-0.66	-0.66	5.6	5.6	3.167	3.234	-6.90	-6.24	1359	34.4364482	-118.6472658	Valve Adjustment:NSPS/EG CAI,High O2
FP-005	10/26/2026 10:48:16 AM	0.1	2.2	18.5	79.2			0.0	4.3	82.7	82.7	-0.70	-0.70	7.0	6.9	5.071	4.943	-6.77	-6.07	1362	34.4364602	-118.6472662	Valve Adjustment:NSPS/EG CAI,High O2
FP-006	10/26/2026 7:42:53 AM	12.0	46.4	5.3	36.3			0.3	6.8	72.7	73.0	-1.95	-1.94	0.5	0.5	0.023	0.026	-7.77	-5.83	1356	34.4363967	-118.6476583	Valve Adjustment:NSPS/EG CAI,High O2
FP-006	10/26/2026 7:54:57 AM	8.1	34.1	8.6	49.2			0.2	5.7	100.6	100.7	-4.60	-4.59	5.8	5.6	3.542	3.416	-7.73	-3.14	1360	34.4363795	-118.6476368	Valve Adjustment:NSPS/EG CAI,High O2
FP-008	10/13/2026 2:08:50 PM	4.3	35.8	10.9	49.0			0.1	4.5	101.5	101.7	-9.16	-9.11	13.0	14.6	3.586	4.495	-12.07	-2.96	1355	34.4363168	-118.6481665	Valve Adjustment:NSPS/EG CAI,High O2,Valve 100% Open
FP-008	10/13/2026 2:10:07 PM	4.4	36.6	10.7	48.3			0.1	4.5	101.7	101.7	-9.41	-9.42	14.6	14.6	4.536	4.505	-13.10	-3.68	1354	34.4363173	-118.6481585	Valve Adjustment:NSPS/EG CAI,High O2

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
FP-009	10/26/2026 10:01:07 AM	11.5	69.6	2.0	16.9			0.2	8.5	103.7	103.8	-1.39	-1.35	5.0	4.8	0.510	0.480	-5.93	-4.58	1372	34.4366750	-118.6489215	
FP-010	10/26/2026 10:11:25 AM	15.3	75.4	0.4	8.9			0.2	22.3	118.8	118.6	-0.82	-0.82	10.4	9.5	2.310	1.923	-8.88	-8.06	1372	34.4366168	-118.6492608	
FP-011	10/26/2026 10:17:07 AM	17.8	35.0	6.5	40.7			0.5	6.3	82.1	82.5	-1.16	-1.16	3.4	3.4	0.231	0.231	-8.90	-7.74	1369	34.4365395	-118.6495222	Valve Adjustment:NSPS/EG CAI,High O2
FP-011	10/26/2026 10:18:24 AM	17.6	35.7	6.4	40.3			0.5	6.3	83.4	83.4	-1.66	-1.65	4.5	4.6	0.404	0.424	-8.64	-6.99	1363	34.4365625	-118.6495185	Valve Adjustment:NSPS/EG CAI,High O2
FP-012	10/1/2026 10:13:53 AM	1.2	6.0	19.6	73.2			0.2	3.7	88.6	89.4	-0.16	-0.16	0.6	0.7	0.008	0.010	-10.83	-10.67	1372	34.4366628	-118.6499175	
FP-013	10/27/2026 1:52:45 PM	4.8	5.4	16.1	73.7			0.9	4.6	77.4	79.0	-0.82	-0.81	16.8	16.7	5.634	5.589	-16.25	-15.44	1337	34.4365548	-118.6502735	
FP-014	10/26/2026 9:42:52 AM	0.9	8.0	18.8	72.3			0.1	3.8	70.7	71.1	-6.45	-6.44	3.2	3.8	0.211	0.295	-6.61	-0.17	1365	34.4365010	-118.6482295	Valve Adjustment:NSPS/EG CAI,High O2
FP-014	10/26/2026 9:45:06 AM	0.8	8.3	18.7	72.2			0.1	3.9	72.9	73.0	-6.42	-6.42	3.4	3.1	0.234	0.190	-6.53	-0.11	1359	34.4365062	-118.6482260	Valve Adjustment:NSPS/EG CAI,High O2
FP-015	10/26/2026 8:16:04 AM	1.1	7.0	19.4	72.5			0.2	3.7	58.3	58.5	-0.33	-0.33	0.5	0.4	0.004	0.003	-2.64	-2.31	1347	34.4364478	-118.6479122	
FP-015	10/26/2026 8:20:11 AM	1.8	13.9	16.5	67.8			0.1	4.1	67.4	69.3	-1.02	-1.01	2.7	2.8	0.148	0.150	-4.59	-3.58	1354	34.4364465	-118.6479167	Valve Adjustment:NSPS/EG CAI,High Temp
FP-016	10/26/2026 8:02:50 AM	0.0	1.8	21.5	76.7			0.0	3.6	58.0	58.1	-3.10	-3.10	0.9	0.8	0.014	0.013	-7.96	-4.86	1357	34.4365125	-118.6477003	Valve Adjustment:NSPS/EG CAI,High O2
FP-016	10/26/2026 8:07:54 AM	10.1	43.3	6.1	40.5			0.2	6.6	81.0	81.4	-4.27	-4.26	14.2	13.9	4.017	3.867	-7.94	-3.68	1362	34.4365120	-118.6476885	Valve Adjustment:NSPS/EG CAI,High O2
FP-017	10/14/2026 1:45:15 PM	12.4	14.9	10.6	62.1			0.8	5.9	85.0	85.1	-1.15	-1.18	10.5	10.5	2.191	2.186	-6.78	-5.6	1361	34.4343887	-118.6486573	Valve Adjustment:Surging Liquid in Well (Watered In)
FP-018	10/14/2026 1:35:36 PM	16.9	16.9	11.5	54.7			1.0	4.8	90.3	90.3	-6.36	-6.36	8.9	8.3	1.603	1.395	-11.21	-4.85	1327	34.4344530	-118.6490867	
FP-019	10/1/2026 2:46:49 PM	52.1	45.6	0.1	2.2			1.1	22.0	89.1	89.1	-0.46	-0.47	2.3	2.6	0.110	0.138	-6.57	-6.1	1321	34.4346340	-118.6491400	
FP-020	10/27/2026 1:34:08 PM	15.6	30.3	8.2	45.9			0.5	5.6	86.4	86.3	-6.48	-5.65			0.000	0.000	-11.68	-6.03	1333	34.4349392	-118.6492973	
FP-021	10/29/2026 8:55:59 AM	6.8	11.9	16.2	65.1			0.6	4.0	74.7	74.8	-6.92	-7.01			0.000	0.084	-7.32	-0.31	1353	34.4351422	-118.6495538	
FP-022	10/14/2026 1:53:39 PM	0.6	10.1	12.3	77.0			0.1	6.3	98.5	98.7	-8.03	-8.22	0.9	0.9	0.017	0.017	-9.05	-0.83	1348	34.4352078	-118.6491912	
FP-023	10/1/2026 10:10:40 AM	11.1	33.5	9.3	46.1			0.3	5.0	84.7	84.8	-0.73	-0.72	6.8	6.9	0.911	0.939	-8.45	-7.73	1355	34.4359702	-118.6495930	Valve Adjustment:Reduce Sys. Vac. - Flare Down
FP-023	10/14/2026 1:59:43 PM	0.2	1.5	19.3	79.0			0.1	4.1	90.9	91.1	-0.48	-0.46	0.4	0.3	0.003	0.001	-0.56	-0.1	1353	34.4355213	-118.6494220	
FP-024	10/14/2026 10:11:24 AM	4.6	19.7	14.4	61.3			0.2	4.3	77.2	77.5	-0.99	-0.98	1.5	1.1	0.043	0.023	-11.78	-10.8	1355	34.4355087	-118.6477905	
FP-025	10/21/2026 9:37:43 AM	6.7	13.5	13.0	66.8			0.5	5.1	75.3	75.4	-1.29	-1.31	3.4	3.2	0.220	0.207	-6.94	-5.63	1360	34.4353575	-118.6477700	
FP-026	10/28/2026 1:56:51 PM	7.9	27.7	8.4	56.0			0.3	6.7	90.5	90.6	-9.22	-9.27			9.214	9.266	-0.01	9.26	1367	34.4350878	-118.6481382	
FP-027	10/14/2026 11:06:20 AM	0.2	4.6	19.8	75.4			0.0	3.8	84.6	84.6	-1.08	-1.06	22.6	22.0	10.285	9.727	-11.34	-10.28	1360	34.4348597	-118.6482052	
FP-028	10/14/2026 11:11:01 AM	0.0	0.1	21.1	78.8			0.0	3.7	82.8	82.8	-0.68	-0.68	6.3	6.3	0.792	0.797	-11.39	-10.71	1351	34.4346853	-118.6482542	
FP-029	10/14/2026 11:10:56 AM	1.1	7.2	16.4	75.3			0.2	4.6	80.8	80.9	-1.22	-1.22	15.7	15.9	4.861	4.981	-11.55	-10.33	1345	34.4345540	-118.6482932	
FP-029	10/14/2026 1:40:35 PM	45.0	34.8	0.5	19.7			1.3	39.4	108.1	108.3	-0.21	-0.21	5.8	5.8	0.042	0.042	-6.41	-6.2	1333	34.4343653	-118.6488808	
FP-030	10/27/2026 1:20:42 PM	34.7	27.5	7.1	30.7			1.3	4.3	90.9	90.9	-1.31	-1.31	13.7	14.1	3.823	4.041	-12.08	-10.77	1342	34.4344987	-118.6497217	
FP-031	10/1/2026 2:36:36 PM	3.5	4.8	16.8	74.9			0.7	4.5	100.6	100.9	-1.82	-1.92	0.5	0.1	0.076	0.004	-7.72	-5.8	1331	34.4348108	-118.6497710	Valve Adjustment:Barely Open
FP-032	10/1/2026 2:33:13 PM	3.5	7.5	12.6	76.4			0.5	6.1	95.8	96.1	-3.04	-3.08	2.4	2.4	0.629	0.620	-7.70	-4.62	1333	34.4350767	-118.6498325	Valve Adjustment:Barely Open
FP-033	10/1/2026 2:30:35 PM	0.3	4.2	17.4	78.1			0.1	4.5	103.4	104.0	-1.85	-1.96	1.5	1.7	0.044	0.059	-4.04	-2.08	1348	34.4353245	-118.6499643	
FP-034	10/1/2026 2:28:01 PM	0.4	5.6	15.2	78.8			0.1	5.2	101.6	101.8	-0.13	-0.13	2.3	2.5	0.112	0.125	-7.70	-7.57	1352	34.4355980	-118.6500318	
FP-035	10/1/2026 2:20:56 PM	17.0	26.8	8.2	48.0			0.6	5.9	95.1	95.2	-1.73	-1.72	3.5	3.5	0.250	0.256	-7.63	-5.91	1356	34.4358420	-118.6501038	
FP-036	10/1/2026 2:16:59 PM	12.3	19.7	10.1	57.9			0.6	5.7	93.2	93.3	-1.02	-1.02	2.2	2.2	1.187	1.201	-7.19	-6.17	1355	34.4361243	-118.6501980	
FP-036	10/14/2026 1:49:15 PM	13.4	30.7	8.1	47.8			0.4	5.9	89.6	89.6	-5.42	-5.42	0.6	0.9	0.086	0.207	-9.12	-3.7	1338	34.4349388	-118.6492838	
FP-037	10/1/2026 2:14:56 PM	1.6	5.5	17.6	75.3			0.3	4.3	102.5	102.5	-0.26	-0.24			0.000	0.000	-8.27	-8.03	1361	34.4362607	-118.6502760	
FP-038	10/1/2026 11:06:27 AM	19.3	23.1	6.7	50.9			0.8	7.6	92.8	92.8	-0.43	-0.41	31.1	37.5	1.137	1.650	-4.87	-4.46	1302	34.4341320	-118.6498283	,
FP-039	10/1/2026 11:08:31 AM	24.1	23.4	6.5	46.0			1.0	7.1	92.8	93.2	-0.67	-0.61	13.6	14.8	3.627	4.310	-6.64	-6.03	1322	34.4341422	-118.6498880	,
FP-040	10/13/2026 10:44:10 AM	12.2	43.0	7.3	37.5			0.3	5.1	97.4	97.4	-1.75	-1.76	19.7	19.6	7.963	7.924	-9.35	-7.59	1308	34.4352878	-118.6510448	
FP-041	10/13/2026 10:59:04 AM	11.1	13.7	10.4	64.8			0.8	6.2	74.2	74.2	-0.50	-0.49	26.3	26.7	13.745	14.147	-5.12	-4.63	1288	34.4340343	-118.6506297	
FP-041	10/15/2026 9:50:37 AM	10.5	14.9	9.6	65.1			0.7	6.8	75.9	76.1	-0.22	-0.24	24.5	25.9	3.541	3.951	-8.83	-8.59	1291	34.4340288	-118.6506457	
FP-042	10/13/2026 9:39:27 AM	0.2	1.9	18.8	79.1			0.1	4.2	80.0	80.8	-4.10	-4.24	0.8	1.0	0.011	0.021	-3.89	0.35	1264	34.4332793	-118.6512900	Valve Adjustment:NSPS/EG CAI,High O2
FP-043	10/13/2026 10:56:16 AM	3.3	7.3	14.0	75.4			0.5	5.4	80.3	80.4	-0.78	-0.79	22.2	22.3	9.862	9.919	-13.14	-12.35	1286	34.4342457	-118.6507888	
FP-044	10/13/2026 10:53:23 AM	0.1	1.9	19.0	79.0			0.1	4.2	80.0	80.0	-0.27	-0.27	7.6	7.8	1.133	1.185	-12.71	-12.44	1286	34.4345188	-118.6507765	
FP-045	10/1/2026 11:25:06 AM	1.4	18.2	16.9	63.5			0.1	3.8	115.2	115.1	-0.04	-0.03			-0.023	-0.025			1309	34.4334880	-118.6495977	,
FP-046	10/29/2026 10:22:39 AM	8.3	28.9	10.4	52.4			0.3	5.0	87.8	87.8	-1.94	-1.93	16.9	16.9	5.806	5.827	-10.31	-8.38	1371	34.4365638	-118.6472980	
FP-047	10/26/2026 8:41:32 AM	0.9	7.9	17.7	73.5			0.1	4.2	63.7	64.4	-0.06	-0.06	1.4	1.5	0.039	0.042	-0.01	0.05	1349	34.4367125	-118.6469377	
FP-050	10/6/2026 10:42:51 AM	19.9	41.7	5.2	33.2			0.5	6.4	102.8	103.0	-0.41	-0.39	7.0	6.8	0.303	0.284	-9.66	-9.27	1372	34.4348833	-118.6472618	
FP-051	10/6/2026 10:47:24 AM	35.6	32.4	2.7	29.3			1.1	10.9	100.4	100.8	-0.38	-0.38	19.2	19.2	0.466	0.467	-9.36	-8.98	1376	34.4347073	-118.6469978	
FP-052	10/6/2026 9:19:52 AM	3.2	11.3	15.3	70.2			0.3	4.6	86.4	86.4	-0.22	-0.22	18.1	18.1	1.974	1.983	-10.56	-10.34	1351	34.4342113	-118.6480682	
FP-053	10/6/2026 9:14:10 AM	6.8	10.3	14.4	68.5			0.7	4.8	85.5	85.7	-0.33	-0.34			0.108	0.094	-10.55	-10.21	1340	34.4340393	-118.6477192	
FP-054	10/6/2026 10:30:16 AM	12.6	25.4	8.2	53.8			0.5	6.6	98.8	98.9	-0.44	-0.44			0.000	0.000	-6.17	-5.73	1375	34.4343413	-118.6470943	
FP-055	10/5/2026 1:24:34 PM	3.3	12.6	10.6	73.5			0.3	6.9	112.8	113.0	-0.12	-0.11	7.4	7.4	1.146	1.137	-9.38	-9.27	1363	34.4335837	-118.6481778	Valve Adjustment:Barely Open

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
FP-056	10/5/2026 10:17:00 AM	5.3	7.9	15.5	71.3			0.7	4.6	99.2	99.2	-0.28	-0.28	11.6	11.6	2.741	2.740	-11.26	-10.98	1365	34.4334503	-118.6486260	
FP-057	10/23/2026 12:44:40 PM	38.1	31.3	2.9	27.7			1.2	9.6	87.4	87.3	-0.95	-0.94	15.7	15.6	4.974	4.919	-10.30	-9.36	1392	34.4347797	-118.6455818	
FP-058	10/23/2026 12:41:30 PM	30.6	32.8	3.4	33.2			0.9	9.8	85.4	85.5	-2.86	-2.84	8.1	8.1	1.313	1.306	-10.00	-7.16	1386	34.4349638	-118.6458610	
FP-059	10/23/2026 1:03:30 PM	32.2	27.3	7.6	32.9			1.2	4.3	92.2	94.5	-0.71	-0.69	8.1	8.0	1.316	1.317	-11.42	-10.73	1394	34.4346245	-118.6458963	
FP-060	10/27/2026 2:59:49 PM	14.0	13.4	13.8	58.8			1.0	4.3	81.5	81.8	-0.96	-0.97	5.0	5.1	0.495	0.513	-16.84	-15.87	1372	34.4348087	-118.6461403	
FP-061	10/26/2026 8:31:17 AM	0.2	2.2	20.7	76.9			0.1	3.7	62.0	62.4	-1.91	-1.91	0.5	0.5	0.005	0.005	-6.94	-5.03	1351	34.4364407	-118.6479392	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High O2
FP-061	10/26/2026 8:34:35 AM	5.2	55.3	5.8	33.7			0.1	5.8	110.1	110.5	-4.43	-4.42	8.9	8.9	1.669	1.657	-6.84	-2.42	1369	34.4364482	-118.6479343	Valve Adjustment:NSPS/EG CAI,High O2,Increased Flow/Vacuum
FP-062	10/13/2026 10:09:19 AM	8.3	63.5	3.2	25.0			0.1	7.8	155.7	155.8	-9.32	-9.32	26.9	24.4	1.023	0.842	-10.75	-1.43	1285	34.4349348	-118.6512028	Valve Adjustment:NSPS/EG CAI,High Temp
FP-063	10/13/2026 10:14:09 AM	0.2	2.2	18.8	78.8			0.1	4.2	77.5	78.3	-10.50	-10.54	2.2	2.7	0.030	0.044	-10.42	0.12	1300	34.4349615	-118.6511787	Valve Adjustment:NSPS/EG CAI,High O2
FP-064	10/28/2026 9:54:43 AM	18.5	21.0	6.4	54.1			0.9	8.5	74.1	74.2	-0.36	-0.38	2.3	1.9	0.102	0.067	-17.02	-16.64	1388	34.4351758	-118.6442458	
FP-064	10/29/2026 1:18:50 PM	27.5	27.4	3.0	42.1			1.0	14.0	82.5	81.8	-0.25	-0.27	7.1	10.4	0.062	0.133	-17.42	-17.15	1383	34.4351799	-118.6442382	Valve Adjustment:Increased Flow/Vacuum
FP-065	10/30/2026 11:28:54 AM	17.1	18.5	7.9	56.5			0.9	7.2	68.8	68.8	-0.51	-0.49	9.4	7.7	0.511	0.346	-19.04	-18.55				Valve Adjustment:NSPS/EG CAI,Decreased Flow/Vacuum
FP-065	10/30/2026 11:31:34 AM	16.7	19.3	8.0	56.0			0.9	7.0	68.6	68.6	-0.50	-0.48	7.8	6.4	0.353	0.242	-19.19	-18.71				Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum
FP-065	10/30/2026 11:32:30 AM	17.1	19.2	7.7	56.0			0.9	7.3	68.6	68.6	-0.46	-0.45	6.4	6.4	0.236	0.240	-19.24	-18.79				
FP-066	10/28/2026 9:36:00 AM	17.7	18.6	7.5	56.2			1.0	7.5	72.5	72.6	-0.40	-0.41	5.0	5.2	0.490	0.521	-16.96	-16.55	1393	34.4354823	-118.6441240	
H-01 (EXP-(	10/11/2026 12:16:38 PM	9.7	47.6	0.0	42.7			0.2	0.0	85.8	85.9	-4.90	-4.89			4.918	4.914	-15.62	-10.73	1253	34.4376913	-118.6441733	
H-01 (EXP-(	10/21/2026 7:02:48 AM	6.1	46.2	0.0	47.7			0.1	0.0	51.3	51.3	-6.86	-6.97			6.759	6.797	-0.34	6.63	1246	34.4376895	-118.6441638	
H-02 (EXP-(	10/11/2026 12:13:55 PM	15.7	45.3	1.5	37.5			0.3	25.9	103.2	103.2	-8.02	-8.02			8.000	8.007	-15.59	-7.57	1261	34.4376805	-118.6446107	Well Repairs:Sample Port
H-02 (EXP-(	10/11/2026 12:38:00 PM	14.4	48.4	0.1	37.1			0.3	464.3	106.5	106.6	-7.57	-7.68			7.624	7.638	-15.50	-7.82	1262	34.4377013	-118.6446275	Well Repairs:Sample Port
H-02 (EXP-(	10/26/2026 2:55:41 PM	32.4	23.7	8.2	35.7			1.4	4.4	83.9	83.9	-12.68	-12.51			12.569	12.498	-0.01	12.5	1252	34.4377212	-118.6446393	Valve Comment:hard pipped
H-02 (EXP-(	10/29/2026 10:49:10 AM	15.7	58.0	0.0	26.3			0.3	0.0	106.3	103.4	-15.86	-15.54			16.455	16.193	-16.06	-0.52	1255	34.4376632	-118.6445873	Valve Comment:Hard pipped;Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-03 (EXP-(	10/11/2026 12:08:55 PM	53.9	41.2	0.0	4.9			1.3	0.0	98.9	99.3	-13.09	-13.43			13.066	13.346	-15.76	-2.33	1238	34.4377153	-118.6446258	Valve Adjustment:Increased Flow/Vacuum
H-03 (EXP-(	10/11/2026 12:10:18 PM	54.5	41.9	0.0	3.7			1.3	0.0	100.4	100.7	-14.20	-14.31			14.229	14.238	-15.54	-1.23	1237	34.4377037	-118.6446058	
H-03 (EXP-(	10/29/2026 10:43:03 AM	0.5	60.2	0.1	39.2			0.0	392.0	144.8	143.0	-15.53	-12.21			16.099	12.691	-15.69	-3.48	1252	34.4376857	-118.6446975	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-03 (EXP-(	10/29/2026 10:43:35 AM	0.3	55.7	0.0	44.0			0.0	0.0	142.4	142.2	-10.80	-10.80			11.404	11.404	-15.95	-5.15	1247	34.4376948	-118.6446977	Valve Adjustment:High Temp
H-04 (EXP-(	10/11/2026 12:02:35 PM	3.7	54.1	0.0	42.2			0.1	0.0	132.4	132.4	-14.77	-14.77			14.698	14.711	-15.39	-0.62	1250	34.4377142	-118.6447105	Valve Adjustment:High Temp
H-04 (EXP-(	10/11/2026 12:03:10 PM	3.5	54.2	0.0	42.3			0.1	0.0	132.6	132.6	-14.77	-14.77			14.716	14.662	-15.39	-0.62	1249	34.4377032	-118.6447070	Valve Adjustment:High Temp
H-04 (EXP-(	10/30/2026 12:39:04 PM	1.7	54.8	0.6	42.9			0.0	71.5	133.3	132.3	-17.12	-16.40			17.290	16.492	-17.83	-1.43	1246	34.4377072	-118.6447213	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum,Barely Open
H-04 (EXP-(	10/30/2026 12:40:01 PM	1.6	55.8	0.4	42.2			0.0	105.5	132.6	132.6	-16.09	-16.09			16.222	16.217	-17.83	-1.74	1211	34.4377338	-118.6447368	
H-08 (EXP-(	10/11/2026 11:57:19 AM	49.3	48.3	0.0	2.4			1.0	0.0	122.9	122.9	-13.32	-13.34			13.208	13.192	-14.92	-1.58	1284	34.4378113	-118.6465665	
H-08 (EXP-(	10/26/2026 2:38:02 PM	40.8	37.6	3.9	17.7			1.1	4.5	85.9	85.6	-13.18	-13.19			13.260	13.315	0.00	13.19	1292	34.4378208	-118.6465515	Valve Comment:hard pipped
H-10 (EXP-1	10/11/2026 11:52:55 AM	11.5	66.0	0.0	22.5			0.2	0.0	130.8	130.8	-9.74	-9.74			9.764	9.748	-15.03	-5.29	1293	34.4374230	-118.6471110	Valve Adjustment:NSPS/EG CAC
H-10 (EXP-1	10/21/2026 7:55:24 AM	10.3	71.2	0.0	18.5			0.1	0.0	131.1	131.2	-7.07	-7.20			7.019	7.088	-0.43	6.77	1305	34.4374418	-118.6470908	Valve Adjustment:NSPS/EG CAI,High Temp
H-10 (EXP-1	10/21/2026 7:56:38 AM	10.0	71.8	0.0	18.2			0.1	0.0	130.9	130.8	-7.27	-7.18			7.158	7.063	4.38	11.56	1308	34.4374417	-118.6470968	Valve Adjustment:NSPS/EG CAC
H-1404C	10/6/2026 1:49:43 PM	1.1	5.7	15.1	78.1			0.2	5.2	112.9	112.9	-0.58	-0.58	0.8	0.8	0.013	0.013	-10.57	-9.99	1339	34.4324363	-118.6483253	Valve Adjustment:High O2,Barely Open
H-1404C	10/21/2026 8:49:22 AM	4.1	8.3	17.3	70.4			0.5	4.1	69.6	69.5	-0.29	-0.29	0.1	0.2	0.001	0.002	-9.95	-9.66	1363	34.4324008	-118.6483025	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Reduce Sys. Vac. - Flare Down
H-1404C	10/21/2026 8:58:51 AM	10.4	29.9	0.5	59.1			0.3	113.7	77.8	77.6	-0.21	-0.20	0.3	0.3	0.007	0.007	-9.98	-9.78	1353	34.4324132	-118.6483093	Valve Adjustment:NSPS/EG CAC,Decreased Flow/Vacuum,Reduce Sys. Vac. - Flare Down
H-1404C	10/21/2026 8:59:51 AM	10.7	30.2	0.4	58.8			0.4	158.8	76.5	76.4	-0.26	-0.26	0.3	0.3	0.009	0.009	-10.49	-10.23	1350	34.4324153	-118.6483155	
H-1405C	10/1/2026 12:03:01 PM	9.6	25.1	0.6	64.7			0.4	107.8	120.7	120.9	-4.83	-4.33	5.0	5.0	0.163	0.166	-4.71	-0.38	1270	34.4325608	-118.6498338	NSPS/EG CAC,
H-1405C	10/27/2026 10:03:57 AM	1.4	36.9	16.4	45.3			0.0	2.8	75.7	75.8	-0.10	-0.12	5.5	5.3	0.177	0.167	0.22	0.34	1294	34.4325780	-118.6497258	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1406W	10/9/2026 9:40:07 AM	0.9	11.0	17.8	70.3			0.1	3.9	86.2	88.4	-14.14	-5.27	2.9	2.0	0.054	0.024	-14.14	-8.87	1252	34.4321787	-118.6507513	Valve Adjustment:High O2,Decreased Flow/Vacuum
H-1406W	10/30/2026 8:54:12 AM	0.5	5.5	19.6	74.4			0.1	3.8	62.4		-6.08		2.8		0.044		-17.76	-11.68	1261	34.4321575	-118.6507707	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
H-1408E	10/5/2026 9:47:27 AM	16.8	26.3	4.2	52.7			0.6	12.5	119.9	119.9	-1.82	-1.70	38.9	36.0	9.848	8.389	-11.24	-9.54	1394	34.4333370	-118.6471710	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-1408E	10/29/2026 8:28:36 AM	21.7	23.8	3.4	51.1			0.9	15.0	125.0	125.0	-1.08	-1.19	27.2	25.5	4.835	4.244	-19.97	-18.78	1390	34.4333302	-118.6471635	Valve Adjustment:Barely Open
H-1408W	10/14/2026 2:16:42 PM	2.6	5.8	15.5	76.1			0.4	4.9	93.8	93.7	-0.08	-0.08	2.4	2.5	0.007	0.008	-17.04	-16.96	1264	34.4311905	-118.6500027	Valve Adjustment:NSPS/EG CAI,High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1408W	10/14/2026 2:17:40 PM	3.0	6.3	14.4	76.3			0.5	5.3	93.8	93.8	-0.07	-0.09	2.9	0.8	0.011	0.001	-17.70	-17.61	1263	34.4311873	-118.6500173	Valve Adjustment:High O2,Barely Open
H-1409N	10/6/2026 2:13:47 PM	25.1	29.1	0.0	45.8			0.9	0.0	120.9	120.8	-1.21	-1.22	1.3	1.3	0.455	0.481	-13.09	-11.87	1366	34.4328883	-118.6469580	Valve Adjustment:Barely Open
H-1409N	10/16/2026 2:00:27 PM	25.1	28.0	0.0	46.9			0.9	0.0	119.0	119.0	-0.70	-0.70	0.7	0.7	0.137	0.134	-17.83	-17.13	1370	34.4328632	-118.6469330	Valve Adjustment:Barely Open
H-1410S	10/6/2026 10:16:46 AM	46.2	40.6	0.1	13.1			1.1	131.0	109.7	109.7	-9.71	-8.52	0.5	0.0	0.002	-0.011	-11.10	-2.58	1227	34.4309493	-118.6466607	,
H-1563N	10/1/2026 11:11:38 AM	30.6	31.9	0.4	37.1			1.0	92.8	127.4	127.8	-3.37	-2.53	5.7	2.0	0.204	0.026	-7.01	-4.48	1289	34.4338422	-118.6498690	,
H-1563N	10/23/2026 9:54:29 AM	29.5	36.3	0.6	33.6			0.8	56.0	126.9	127.1	-2.87	-2.89	3.4	4.0	0.073	0.105	-10.95	-8.06	1323	34.4338597	-118.6498297	Valve Adjustment:Barely Open
H-1563S	10/1/2026 12:05:41 PM	8.1	21.2	0.0	70.7			0.4	0.0	107.8	107.8	-0.32	-0.30	0.0	0.0	-0.035	-0.031	-7.84	-7.54	1266	34.4323692	-118.6495207	,
H-1563S	10/23/2026 1:32:41 PM	0.0	0.0	21.2	78.8				3.7	90.9	92.0	0.01	-0.02	1.7	2.1	0.284	0.444	-12.12	-12.1	1318	34.4324182	-118.6496515	Valve Adjustment:NSPS/EG CAI,Orifice Plate Changed (See OP Log),Positive Static Press.,Increased Flow/Vacuum
H-1563S	10/23/2026 1:34:44 PM	0.0	0.0	21.1	78.9				3.7	96.0	96.0	-0.03	-0.02	9.3	9.3	0.527	0.529	-12.11	-12.09	1316	34.4324190	-118.6496428	Valve Adjustment:NSPS/EG CAC,Barely Open,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
H-1565E	10/2/2026 9:10:38 AM	21.7	32.3	2.2	43.7			0.7	19.6	115.0	115.0	-7.76	-8.14	4.1	4.7	0.107	0.141	-8.10	0.04	1398	34.4335152	-118.6472163	Valve Adjustment:Increased Flow/Vacuum
H-1565E	10/5/2026 9:49:03 AM	12.3	23.3	3.8	60.6			0.5	15.9	117.7	118.2	-6.43	-6.34	2.7	2.8	0.047	0.050	-6.14	0.2	1387	34.4335365	-118.6472315	
H-1565E	10/28/2026 10:40:53 AM	10.1	21.6	4.6	63.7			0.5	13.8	130.9	128.7	-14.77	-12.57	4.3	3.1	0.124	0.063	-14.83	-2.26	1387	34.4335503	-118.6472228	Valve Adjustment:Decreased Flow/Vacuum
H-1568N	10/2/2026 9:19:59 AM	51.9	44.9	0.0	3.2			1.2	0.0	121.0	121.2	-2.27	-2.67	3.2	3.9	1.102	1.716	-14.01	-11.34	1394	34.4333490	-118.6471673	Valve Adjustment:Increased Flow/Vacuum
H-1568N	10/5/2026 9:44:55 AM	42.9	44.4	0.0	12.7			1.0	0.0	121.7	121.6	-2.61	-1.99	8.6	4.9	1.572	0.520	-11.00	-9.01	1410	34.4333352	-118.6471958	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-1568N	10/28/2026 10:48:27 AM	15.8	21.4	10.2	52.6			0.7	5.2	120.7	120.3	-2.99	-0.17	9.1	6.1	1.757	0.777	-14.86	-14.69	1397	34.4333580	-118.6471670	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open
H-1568N	10/28/2026 10:49:42 AM	29.1	28.7	0.7	41.5			1.0	59.3	119.4	118.1	-0.05	-0.08	6.6	6.1	0.917	0.774	-14.97	-14.89	1400	34.4333678	-118.6471605	Valve Adjustment:NSPS/EG CAC,Barely Open
H-1571S	10/7/2026 11:03:16 AM	39.2	39.0	0.0	21.8			1.0	0.0	119.2	119.2	-1.46	-1.46	0.7	0.9	0.001	0.002	-5.90	-4.44	1260	34.4321410	-118.6451548	Reduced System Vacuum,
H-1571S	10/27/2026 9:57:04 AM						34000																[User entered 3.4%]
H-1571S	10/27/2026 9:59:48 AM	39.8	41.4	0.0	18.8			1.0	0.0	110.6	111.3	-3.01	-3.00	1.2	1.3	0.029	0.033	-15.35	-12.35	1278	34.4321460	-118.6452468	
H-1571S	10/27/2026 10:05:00 AM					68.6																	AtmAA
H-1571S	10/27/2026 10:05:00 AM						23900																AtmAA; [User entered 2.39%]
H-1572N	10/20/2026 8:13:36 AM	49.1	40.5	0.0	10.4			1.2	0.0	110.2	114.4	-0.90	-0.92	3.2	3.0	0.218	0.194	-19.94	-19.02	1357	34.4337032	-118.6447377	
H-1572S	10/7/2026 11:09:46 AM	55.0	43.4	0.0	1.6			1.3	0.0	113.4	113.7	-1.27	-1.42	5.5	7.4	0.065	0.117	-4.57	-3.15	1253	34.4321920	-118.6447460	Reduced System Vacuum,
H-1753N	10/1/2026 2:48:44 PM	45.6	36.7	3.3	14.4			1.2	4.4	96.7	97.2	-0.68	-0.67	10.2	10.4	0.235	0.241	-7.69	-7.02	1327	34.4347035	-118.6493362	Valve Adjustment:Barely Open
H-1753N	10/27/2026 1:29:28 PM	48.9	36.4	2.9	11.8			1.3	4.1	90.2	90.4	-0.50	-0.49	9.4	10.0	0.196	0.223	-12.24	-11.75	1345	34.4347397	-118.6493218	Valve Adjustment:Barely Open
H-1753S	10/1/2026 11:03:46 AM	40.6	36.8	0.0	22.6			1.1	0.0	108.8	109.4	-1.57	-1.46	10.6	6.9	0.244	0.103	-3.51	-2.05	1319	34.4338785	-118.6494968	,
H-1753S	10/14/2026 2:17:10 PM	0.0	1.2	20.6	78.2			0.0	3.8	115.6	115.4	-1.91	-1.91	2.1	2.1	0.088	0.090	-6.41	-4.5	1331	34.4339230	-118.6496187	
H-1753S	10/23/2026 9:47:01 AM	33.0	35.6	0.0	31.4			0.9	0.0	112.5	112.7	-2.53	-2.54	2.9	2.9	0.170	0.180	-10.87	-8.33	1333	34.4339240	-118.6495940	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In),Reduce Sys. Vac. - Flare Down
H-1756S	10/9/2026 9:14:40 AM	5.9	10.5	14.0	69.6			0.6	5.0	87.0	87.0	-0.41	-0.42	5.2	5.1	0.034	0.032	-13.59	-13.17	1284	34.4325588	-118.6502840	Valve Adjustment:High O2,Barely Open
H-1756S	10/9/2026 9:16:21 AM	6.3	10.8	14.0	68.9			0.6	4.9	87.1	87.3	-0.43	-0.43	5.9	5.5	0.042	0.038	-14.35	-13.92	1288	34.4325582	-118.6502907	Valve Adjustment:High O2,Barely Open
H-1756S	10/23/2026 2:01:10 PM	7.7	11.9	13.5	66.9			0.6	5.0	93.2	98.2	-0.16	-0.47	3.9	20.2	0.019	0.511	-13.45	-12.98	1296	34.4325688	-118.6502952	Valve Adjustment:Increased Flow/Vacuum
H-1757S	10/1/2026 12:00:48 PM	37.0	46.2	0.0	16.8			0.8	0.0	105.5	105.3	-0.35	-0.36	0.0	0.0	-0.009	-0.013	-6.32	-5.96	1247	34.4327513	-118.6497655	,
H-1757S	10/23/2026 1:38:38 PM	0.0	0.0	21.1	78.9				3.7	103.4		-0.01		20.0		0.903		-11.71	-11.7	1317	34.4327122	-118.6497743	
H-1760S	10/5/2026 9:04:55 AM	33.3	52.6	0.0	14.1			0.6	0.0	121.7	121.5	-2.43	-1.95	6.3	3.8	0.253	0.091	-13.68	-11.73	1391	34.4327160	-118.6478953	Valve Adjustment:Decreased Flow/Vacuum
H-1760S	10/16/2026 1:01:36 PM	23.3	40.2	0.0	36.5			0.6	0.0	119.6	118.8	-1.89	-1.71	1.8	1.1	0.021	0.007	-16.83	-15.12	1391	34.4327218	-118.6478980	Valve Adjustment:Decreased Flow/Vacuum
H-1762N	10/5/2026 8:22:50 AM	27.9	35.8	0.1	36.2			0.8	362.0	119.9	120.2	-0.62	-0.62	7.4	6.8	1.175	0.988	-12.82	-12.2	1385	34.4334677	-118.6468670	Valve Adjustment:Barely Open
H-1762N	10/16/2026 1:36:47 PM	25.2	30.1	0.3	44.4			0.8	148.0	117.7	117.6	-0.17	-0.13	1.7	2.3	0.059	0.114	-13.64	-13.51	1400	34.4334373	-118.6468523	Valve Adjustment:Barely Open
H-1763N	10/5/2026 10:18:30 AM	28.9	30.4	3.9	36.8			1.0	9.4	120.8	120.9	-0.99	-0.98	19.2	19.2	2.379	2.364	-11.05	-10.07	1413	34.4335733	-118.6461862	Valve Adjustment:Barely Open
H-1763S	10/7/2026 10:49:00 AM	18.9	26.8	0.0	54.3			0.7	0.0	124.9	124.8	-1.65	-1.50	27.3	28.9	0.942	1.054	-7.91	-6.41	1286	34.4324753	-118.6461955	Reduced System Vacuum,

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
H-1764N	10/2/2026 9:37:30 AM	56.2	41.8	0.0	2.0			1.3	0.0	119.3	120.3	-1.88	-2.33	1.8	2.9	0.071	0.184	-12.22	-9.89	1364	34.4331562	-118.6456325	Valve Adjustment:Increased Flow/Vacuum
H-1764S	10/7/2026 10:56:56 AM	10.0	22.8	2.3	64.9			0.4	28.2	107.1	106.9	-0.44	-0.40	0.9	0.9	0.005	0.005	-5.65	-5.25	1302	34.4320172	-118.6452820	Reduced System Vacuum,
H-1764S	10/27/2026 10:40:43 AM						17000																[User entered 1.7%]
H-1764S	10/27/2026 10:42:15 AM	38.3	42.7	0.0	19.1			0.9	0.0	113.1	113.9	-9.25	-9.25	1.4	1.7	0.005	0.007	-14.05	-4.8	1288	34.4321595	-118.6454297	Valve Adjustment:Plugged/Pinched Suspected;Well Repairs:Flex Hose
H-1764S	10/27/2026 10:47:27 AM	34.8	41.3	0.0	23.9			0.8	0.0	112.4	112.5	-9.25	-9.25	1.9	2.1	0.073	0.091	-14.43	-5.18	1285	34.4321435	-118.6454303	Valve Adjustment:Orifice Plate Changed (See OP Log),Plugged/Pinched Suspected
H-1764S	10/27/2026 11:05:00 AM					27.4																	AtmAA
H-1764S	10/27/2026 11:05:00 AM						4600																AtmAA; [User entered 0.46%]
H-1767N	10/5/2026 9:00:49 AM						0																
H-1767N	10/5/2026 9:01:53 AM	41.2	53.4	0.0	5.4			0.8	0.0	106.3	106.4	-1.18	-0.99	20.8	16.7	0.983	0.631	-20.15	-19.16	1249	34.4326707	-118.6436085	Valve Adjustment:Decreased Flow/Vacuum
H-1767N	10/5/2026 9:02:50 AM	40.3	53.7	0.0	6.1			0.8	0.0	106.5	106.5	-0.89	-0.89	16.3	15.3	0.600	0.531	-20.48	-19.59	1242	34.4326640	-118.6435908	
H-1769N	10/1/2026 10:19:14 AM	1.2	8.5	11.7	78.6			0.1	6.7	108.0	108.0	-0.44	-0.44	4.3	2.3	0.049	0.014	-8.79	-8.35	1373	34.4370240	-118.6494760	Valve Adjustment:Barely Open
H-1769N	10/16/2026 10:47:06 AM	1.9	10.8	9.0	78.3			0.2	8.7	93.6	93.7	-0.92	-0.88	3.2	2.2	0.026	0.013	-9.71	-8.83	1364	34.4370102	-118.6495005	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1770N	10/6/2026 7:10:00 AM					130																	Air Tech Lab
H-1770N	10/6/2026 7:10:00 AM						19000																Air Tech Lab; [User entered 1.9%]
H-1770N	10/12/2026 12:51:00 PM	30.2	59.8	0.0	10.0			0.5	0.0	89.2	87.5	-2.87	-2.79	3.9	3.9	1.616	1.597	-15.39	-12.6	1354	34.4367962	-118.6500230	Valve Adjustment:Audible Flow,Decreased Flow/Vacuum,Barely Open
H-1770N	10/16/2026 10:56:15 AM	29.4	69.1	0.1	1.4			0.4	14.0	93.4	93.4	-2.08	-2.10	2.8	3.0	0.159	0.177	-12.23	-10.13	1356	34.4368122	-118.6500553	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1770S	10/1/2026 11:52:13 AM	35.0	53.7	0.0	11.3			0.7	0.0	115.1	115.8	-0.41	-0.39	1.9	1.1	0.430	0.143	-6.98	-6.59	1266	34.4330837	-118.6502382	,
H-1770S	10/27/2026 9:47:36 AM	34.5	65.2	0.0	0.3			0.5	0.0	94.8	94.8	-0.56	-0.56	1.3	1.2	0.035	0.030	-9.22	-8.66	1291	34.4331150	-118.6502248	Valve Adjustment:Barely Open
H-1771A	10/13/2026 8:39:55 AM	33.5	34.7	0.0	31.8			1.0	0.0	108.1	108.0	-0.61	-0.60	5.5	5.4	0.628	0.614	-2.56	-1.96	1368	34.4363203	-118.6464072	
H-1771B	10/7/2026 8:54:07 AM	21.8	37.6	0.3	40.3			0.6	134.3	97.4	97.5	-0.45	-0.44	0.5	0.5	0.005	0.005	-7.66	-7.22	1366	34.4355443	-118.6466325	Valve Adjustment:Barely Open,Reduce Sys. Vac. - Flare Down
H-1771B	10/23/2026 7:45:46 AM	24.1	38.1	0.5	37.3			0.6	74.6	82.5	82.9	-1.62	-1.62	0.5	0.5	0.005	0.005	-13.33	-11.71	1370	34.4355460	-118.6466703	Valve Adjustment:Barely Open
H-1774N	10/1/2026 10:32:31 AM	40.5	54.2	0.0	5.3			0.7	0.0	118.7	118.4	-1.24	-1.00	7.5	6.3	1.193	0.839	-10.40	-9.4	1353	34.4367285	-118.6507977	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-1774N	10/16/2026 11:07:49 AM	42.3	57.6	0.1	0.0			0.7	0.0	116.0	116.2	-1.79	-1.80	6.5	6.5	0.882	0.876	-12.88	-11.08	1348	34.4367428	-118.6508213	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1801S	10/20/2026 9:37:27 AM	14.5	82.1	0.0	3.4			0.2	0.0	106.5	106.9	-1.54	-1.54	2.6	2.6	0.139	0.143	-22.42	-20.88	1347	34.4337477	-118.6441003	
H-1802S	10/20/2026 7:52:10 AM	42.0	34.7	0.0	23.3			1.2	0.0	116.3	118.3	-1.29	-1.29	7.9	8.0	1.340	1.371	-20.58	-19.29	1353	34.4335563	-118.6447442	
H-1803N-P	10/5/2026 9:43:41 AM	17.8	73.5	0.0	8.7			0.2	0.0	198.0	86.4	-8.47	-6.42	76.4	73.8	8.936	6.862	-8.67	-2.25	1358	34.4370152	-118.6486037	Valve Adjustment:No Flow Measurement,High Temp
H-1803N-P	10/5/2026 9:45:00 AM					1630																	AtmAA
H-1803N-P	10/5/2026 9:45:00 AM						182100																AtmAA; [User entered 18.21%]
H-1803N-P	10/12/2026 8:45:00 AM					1870																	AtmAA
H-1803N-P	10/12/2026 8:45:17 AM	5.0	78.3	0.2	16.5			0.1	82.5	198.0	64.3	-7.10	-6.95	77.3	76.8	7.329	7.184	-7.97	-1.02	1350	34.4370105	-118.6485929	Valve Adjustment:No Flow Measurement,High Temp
H-1803N-P	10/19/2026 8:39:30 AM	7.6	78.8	0.2	13.4			0.1	67.0	194.0	69.0	-8.33	-8.10	82.4	80.3	8.408	7.946	-7.98	0.12	1346	34.4370355	-118.6485820	Valve Adjustment:No Flow Measurement,High Temp
H-1803N-P	10/26/2026 8:35:00 AM					774																	AtmAA
H-1803N-P	10/26/2026 8:36:36 AM	2.2	75.5	0.1	22.2			0.0	222.0	196.0	64.2	-7.23	-7.07	69.9	77.1	7.399	7.193	-7.32	-0.25	1356	34.4370460	-118.6485933	Valve Adjustment:No Flow Measurement,High Temp
H-1804B	10/27/2026 2:54:35 PM	56.0	44.0	0.0	0.0			1.3	0.0	111.7	111.4	-5.41	-5.32	7.9	8.7	0.399	0.478	-21.37	-16.05	1386	34.4342357	-118.6456360	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1804N	10/13/2026 8:29:44 AM	28.2	70.3	0.0	1.5			0.4	0.0	125.5	126.0	-3.09	-2.82	9.4	9.9	1.913	2.110	-4.75	-1.93	1358	34.4363648	-118.6456833	
H-1804S	10/16/2026 2:16:38 PM	40.6	36.9	0.0	22.5			1.1	0.0	116.1	116.6	-10.64	-10.83	5.6	7.6	0.201	0.371	-10.80	0.03	1357	34.4330925	-118.6456757	Valve Adjustment:Increased Flow/Vacuum
H-1805A	10/28/2026 8:48:29 AM	5.8	7.7	17.9	68.6			0.8	3.8	55.1	55.1	-2.78	-2.78	4.3	1.7	0.022	0.004	-21.39	-18.61	1396	34.4351177	-118.6451265	Valve Adjustment:NSPS/EG CAI,High O2,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected;Well Comment:Valve stuck
H-1805A	10/28/2026 8:53:42 AM	30.5	39.9	2.5	27.1			0.8	10.8	56.0	56.8	-2.78	-2.77	1.6	2.7	0.003	0.008	-21.53	-18.76	1386	34.4351490	-118.6451153	Valve Adjustment:High O2,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected;Well Comment:valve stuck
H-1805B	10/16/2026 2:05:21 PM	23.0	27.8	3.2	46.0			0.8	14.4	94.5	99.3	-0.85	-1.19	0.7	2.0	0.010	0.085	-21.13	-19.94	1370	34.4337340	-118.6451552	Valve Adjustment:Increased Flow/Vacuum
H-1805B	10/22/2026 9:40:53 AM	34.2	35.8	0.0	30.0			1.0	0.0	69.1	68.9	-9.92	-10.40	1.9	4.0	0.069	0.320	-9.76	0.64	1380	34.4337307	-118.6451660	Valve Adjustment:Increased Flow/Vacuum
H-1805S	10/7/2026 10:29:02 AM	56.0	43.0	0.0	1.0			1.3	0.0	116.2	117.5	-0.34	-0.52	0.0	3.8	-0.016	0.030	-6.80	-6.28	1299	34.4328765	-118.6452257	Reduced System Vacuum,

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
H-1806A	10/28/2026 9:39:43 AM	46.9	42.6	0.0	10.5			1.1	0.0	116.8	116.9	-1.49	-1.38	25.4	22.1	1.500	1.137	-18.31	-16.93	1389	34.4354438	-118.6442500	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1806B	10/20/2026 8:29:41 AM	15.9	27.2	0.0	56.9			0.6	0.0	109.1	115.2	-1.87	-1.87	4.9	4.7	0.511	0.467	-19.60	-17.73	1357	34.4338975	-118.6444607	
H-1806N	10/21/2026 10:16:57 AM	45.3	48.8	0.0	5.9			0.9	0.0	129.4	129.4	-2.30	-2.32	7.0	8.4	0.066	0.095	-5.46	-3.14	1365	34.4363578	-118.6442868	
H-1806S	10/28/2026 10:04:49 AM	30.8	61.4	0.0	7.8			0.5	0.0	131.7	131.7	-0.83	-0.82	8.4	8.9	0.460	0.517	-20.91	-20.09	1299	34.4328782	-118.6444572	Valve Adjustment:NSPS/EG CAI,High Temp
H-1806S	10/28/2026 10:06:37 AM	29.0	63.0	0.0	8.0			0.5	0.0	130.2	130.0	-0.38	-0.32	2.8	3.3	0.052	0.070	-21.01	-20.69	1296	34.4328783	-118.6444538	Valve Adjustment:NSPS/EG CAC
H-1807A	10/7/2026 2:09:40 PM	54.5	40.2	0.0	5.3			1.4	0.0	117.1	118.5	-5.69	-5.69	0.0	0.0	-0.469	-0.437	-6.18	-0.49	1352	34.4353228	-118.6435770	Reduced System Vacuum,
H-1807A	10/27/2026 9:30:18 AM	56.1	41.9	0.0	2.0			1.3	0.0	119.6	120.0	-19.65	-19.86	1.5	2.7	0.003	0.010	-20.71	-0.85	1344	34.4353320	-118.6436342	
H-1807N	10/26/2026 2:01:03 PM	38.2	31.3	1.8	28.7			1.2	15.9	93.0	93.3	-0.28	-0.31	0.9	1.1	0.005	0.007	-9.37	-9.06	1355	34.4364713	-118.6435170	Valve Adjustment:Barely Open
H-1807S	10/28/2026 9:29:40 AM	42.0	35.4	0.0	22.6			1.2	0.0	75.3	76.5	-6.82	-11.49	4.1	3.0	0.020	0.011	-20.32	-8.83	1315	34.4338430	-118.6434848	
H-1952S	10/6/2026 9:02:15 AM	56.6	38.0	0.1	5.3			1.5	53.0	115.5	115.5	-2.26	-2.24	14.8	14.9	4.658	4.750	-11.14	-8.9	1376	34.4338040	-118.6476125	Valve Adjustment:Barely Open
H-1952S	10/20/2026 2:07:30 PM	51.5	42.6	0.0	5.9			1.2	0.0	116.6	116.7	-1.70	-1.73	14.7	14.7	4.616	4.626	-10.44	-8.71	1369	34.4338100	-118.6476210	Valve Adjustment:Barely Open
H-1955C	10/28/2026 8:37:43 AM	16.5	21.5	5.9	56.1			0.8	9.5	59.5	59.3	-1.26	-1.13	7.9	0.7	1.195	0.009	-21.92	-20.79	1377	34.4350352	-118.6454412	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open,Surging Liquid in Well (Watered In)
H-1955C	10/28/2026 8:38:50 AM	16.5	20.6	6.1	56.8			0.8	9.3	58.6	58.6	-1.12	-1.11	0.7	0.7	0.009	0.009	-21.46	-20.35	1383	34.4350362	-118.6454478	Valve Adjustment:High O2,Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1955N	10/13/2026 8:21:57 AM	38.0	38.9	0.0	23.1			1.0	0.0	93.4	93.7	-2.41	-2.56	7.0	8.6	0.302	0.450	-4.86	-2.3	1354	34.4364770	-118.6455235	
H-1956B	10/2/2026 12:39:18 PM	38.3	56.2	0.0	5.5			0.7	0.0	127.8	127.8	-2.26	-2.28	13.8	14.1	0.452	0.471	-15.40	-13.12	1389	34.4342742	-118.6447500	
H-1956B	10/5/2026 12:40:47 PM	38.3	53.0	0.0	8.7			0.7	0.0	126.8	126.8	-2.47	-2.47	13.9	13.9	0.457	0.457	-15.93	-13.46	1391	34.4342572	-118.6447683	Valve Adjustment:Audible Flow
H-1956B	10/16/2026 1:54:23 PM	40.5	58.4	0.0	1.1			0.7	0.0	124.9	125.0	-2.96	-3.01	11.4	16.3	0.307	0.624	-18.55	-15.54	1393	34.4343043	-118.6447955	Valve Adjustment:Increased Flow/Vacuum
H-1956N	10/21/2026 10:26:37 AM	46.8	38.9	0.0	14.3			1.2	0.0	111.8	111.7	-2.59	-2.60	14.7	14.8	1.380	1.400	-4.26	-1.66	1360	34.4364630	-118.6448742	
H-1956S	10/7/2026 10:35:29 AM	47.7	39.1	0.0	13.2			1.2	0.0	112.1	112.3	-8.88	-8.46	0.0	1.8	-0.015	0.068	-9.66	-1.2	1306	34.4331743	-118.6448110	Reduced System Vacuum,
H-1957B	10/27/2026 10:19:27 AM	49.0	44.9	0.0	6.1			1.1	0.0	115.8	115.9	-2.40	-2.40	12.5	11.9	0.999	0.905	-15.33	-12.93	1364	34.4345512	-118.6441183	
H-1957N	10/21/2026 10:10:13 AM	53.0	44.0	0.0	3.0			1.2	0.0	118.5	118.5	-1.89	-1.92	7.8	7.8	0.394	0.394	-5.94	-4.02	1352	34.4364415	-118.6441938	
H-1957S	10/20/2026 9:49:20 AM	14.0	79.8	0.0	6.2			0.2	0.0	102.6	102.9	-2.97	-3.01	1.0	1.0	0.022	0.021	-6.48	-3.47	1347	34.4337572	-118.6441158	
H-1958C	10/7/2026 2:03:02 PM	52.5	41.6	0.0	5.9			1.3	0.0	117.3	122.3	0.76	-0.16	0.0	18.6	-0.004	2.082	-5.16	-5	1358	34.4354127	-118.6434328	NSPS/EG CAI,Positive Static Press.,Reduced System Vacuum
H-1958C	10/7/2026 2:06:15 PM	53.1	37.7	0.0	9.2			1.4	0.0	122.1	122.1	-0.37	-0.40	9.6	9.6	0.541	0.542	-5.91	-5.51	1302	34.4353378	-118.6434003	NSPS/EG CAC,Reduced System Vacuum
H-1958N	10/26/2026 1:58:16 PM	53.3	40.6	0.0	6.1			1.3	0.0	95.1	104.0	-0.06	-0.06	43.1	43.7	2.320	2.417	-8.44	-8.38	1342	34.4364500	-118.6435127	Valve Adjustment:Barely Open
H-1958S	10/28/2026 9:20:37 AM	39.3	30.2	4.3	26.2			1.3	6.1	70.2	70.6	-0.54	-0.54	1.4	1.2	0.011	0.009	-20.52	-19.98	1312	34.4339987	-118.6433472	
H-1962N	10/1/2026 2:01:33 PM	12.3	66.0	0.3	21.4			0.2	71.3	153.1	153.1	-0.51	-0.50			0.492	0.486	-13.70	-13.2	1359	34.4366190	-118.6501305	Valve Adjustment:NSPS/EG CAI,High Temp,Barely Open
H-1962N	10/1/2026 2:02:08 PM	14.8	66.2	0.2	18.8			0.2	94.0	153.1	153.0	-0.52	-0.52			0.523	0.522	-13.64	-13.12	1368	34.4366688	-118.6501442	Valve Adjustment:High Temp,Barely Open
H-1962N	10/5/2026 9:34:39 AM	20.6	53.7	0.3	25.4			0.4	84.7	152.7	152.6	-0.93	-0.93			0.934	0.930	-14.01	-13.08	1370	34.4366588	-118.6501247	Valve Comment:Well is hard piped;Valve Adjustment:No Flow Measurement,High Temp,Barely Open
H-1962N	10/5/2026 9:35:00 AM					751.5																	AtmAA
H-1962N	10/5/2026 9:35:00 AM						68450																AtmAA; [User entered 6.845%]
H-1962N	10/8/2026 2:17:00 PM					1620																	AtmAA
H-1962N	10/8/2026 2:17:00 PM						122300																AtmAA; [User entered 12.23%]
H-1962N	10/8/2026 2:17:28 PM	17.3	71.9	0.0	10.8			0.2	0.0	160.2	160.0	0.06	0.07			0.000	0.000	-5.42	-5.49	1365	34.4366672	-118.6501351	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,Reduce Sys. Vac. - Flare Down
H-1962N	10/9/2026 2:09:21 PM	31.7	60.6	0.4	7.3			0.5	18.3	159.1	159.2	-0.82	-0.81			0.797	0.817	-12.49	-11.68	1374	34.4366549	-118.6501316	Valve Adjustment:No Flow Measurement,High Temp,High O2,Surging Liquid in Well (Watered In)
H-1962N	10/9/2026 2:09:53 PM	31.8	60.2	0.4	7.6			0.5	19.0	159.1	159.1	-0.81	-0.82			0.806	0.801	-12.52	-11.7	1374	34.4366560	-118.6501353	Valve Adjustment:No Flow Measurement,High Temp
H-1962N	10/15/2026 9:14:09 AM	34.7	47.6	0.4	17.3			0.7	43.3	154.0	154.0	-1.22	-1.20			1.213	1.211	-14.11	-12.91	1366	34.4366678	-118.6501586	Valve Adjustment:No Flow Measurement,High Temp
H-1962N	10/15/2026 9:15:00 AM					991																	AtmAA
H-1962N	10/16/2026 10:59:53 AM	19.9	63.0	0.5	16.6			0.3	33.2	160.1	160.2	-1.00	-0.94			0.966	0.984	-12.36	-11.42	1353	34.4366603	-118.6501423	Valve Adjustment:High Temp
H-1962N	10/21/2026 8:30:00 AM					276.5																	AtmAA
H-1962N	10/21/2026 8:31:48 AM	25.6	41.8	0.6	32.0			0.6	53.3	147.6	147.6	-1.21	-1.21			1.183	1.176	-6.12	-4.91	1363	34.4366663	-118.6501240	Valve Adjustment:No Flow Measurement,High Temp
H-1962N	10/28/2026 10:41:00 AM					331																	AtmAA
H-1962N	10/28/2026 10:41:21 AM	17.4	33.3	0.3	49.0			0.5	153.2	139.1	139.1	-2.60	-2.58			2.586	2.566	-13.82	-11.24	1366	34.4366593	-118.6501270	Valve Adjustment:No Flow Measurement,High Temp

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
H-1963N	10/1/2026 10:16:26 AM	14.2	54.8	3.9	27.1			0.3	6.9	144.5	144.6	-0.73	-0.72	1.3	0.5	0.005	0.001	-8.11	-7.39	1369	34.4369340	-118.6495320	Valve Adjustment:Barely Open
H-1963N	10/16/2026 10:41:56 AM	14.4	56.4	4.0	25.2			0.3	6.3	145.8	145.9	-1.23	-1.25	1.8	2.0	0.009	0.011	-10.91	-9.66	1378	34.4369048	-118.6495538	Valve Adjustment:High Temp,Barely Open
H-1963N	10/26/2026 1:35:00 PM					1850																	AtmAA
H-1963N	10/26/2026 1:37:06 PM	23.4	62.1	1.9	12.6			0.4	6.6	147.3	147.2	-7.98	-7.79	72.4	71.9	7.382	7.279	-0.67	7.12	1377	34.4369168	-118.6495507	Valve Adjustment:High Temp
H-1966N	10/1/2026 10:40:13 AM	32.8	37.6	0.0	29.6			0.9	0.0	110.4	110.6	-0.36	-0.33	3.0	3.1	0.993	1.013	-2.66	-2.33	1346	34.4365742	-118.6507673	Valve Adjustment:Barely Open
H-1966N	10/16/2026 11:19:36 AM	33.0	37.3	0.2	29.5			0.9	147.5	109.8	110.0	-0.56	-0.59	4.8	4.9	2.492	2.595	-6.66	-6.07	1340	34.4365680	-118.6508235	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-1967E	10/14/2026 12:39:41 PM	44.1	33.6	4.2	18.1			1.3	4.3	103.6	102.6	-20.29	-13.95	5.2	2.0	0.046	0.006	-20.41	-6.46	1125	34.4301955	-118.6458277	Valve Adjustment:Decreased Flow/Vacuum
H-1967E	10/14/2026 12:49:38 PM	43.6	34.5	4.0	18.0			1.3	4.5	102.9	102.0	-14.49	-9.30	0.6	0.8	0.001	0.001	-20.25	-10.95	1131	34.4301963	-118.6458500	Valve Adjustment:Decreased Flow/Vacuum
H-1967E	10/14/2026 1:22:25 PM	43.0	34.4	4.1	18.6			1.2	4.6	101.9	101.7	-7.68	-13.85	13.7	13.3	0.238	0.228	-20.66	-6.81	1127	34.4302002	-118.6458290	Valve Adjustment:Increased Flow/Vacuum
H-1967E	10/14/2026 1:33:17 PM	43.7	34.6	4.0	17.8			1.3	4.5	104.1	104.2	-13.66	-13.65	13.7	13.7	0.244	0.242	-20.35	-6.7	1141	34.4302050	-118.6458368	
H-1967W	10/2/2026 1:40:15 PM	59.5	37.7	0.0	2.8			1.6	0.0	104.6	104.8	-6.48	-6.83	47.8	49.6	2.932	3.170	-11.22	-4.39	1197	34.4299143	-118.6508098	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-2050E	10/26/2026 2:16:12 PM	50.5	49.5	0.0	0.0			1.0	0.0	96.1	96.3	-8.99	-9.04	14.5	14.5	4.356	4.377	-13.07	-4.03	1090	34.4291298	-118.6474923	
H-2050W	10/6/2026 10:36:30 AM	23.3	30.8	0.0	45.9			0.8	0.0	107.2	106.6	-1.15	-1.04	1.2	0.0	0.146	-0.059	-4.78	-3.74	1171	34.4291333	-118.6490365	,
H-2051W	10/2/2026 1:46:39 PM	57.7	38.9	0.0	3.4			1.5	0.0	122.3	122.1	-3.71	-6.08	3.5	4.2	0.016	0.023	-11.22	-5.14	1191	34.4298928	-118.6507613	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-2053E	10/14/2026 9:59:18 AM	34.9	35.5	0.0	29.5			1.0	0.0	117.6	117.6	-4.94	-4.13	26.3	20.8	0.895	0.562	-19.03	-14.9	1138	34.4302137	-118.6458042	Valve Adjustment:Decreased Flow/Vacuum
H-2053E	10/14/2026 10:05:40 AM	33.5	36.9	0.0	29.6			0.9	0.0	117.4	117.4	-3.87	-3.85	20.0	21.3	0.519	0.584	-19.36	-15.51	1132	34.4302100	-118.6457987	
H-2055E	10/7/2026 12:39:49 PM	44.1	39.1	0.0	16.8			1.1	0.0	116.6	117.0	-0.20	-0.20	0.8	0.8	0.159	0.165	-8.10	-7.9	1271	34.4317727	-118.6466370	Valve Adjustment:Reduce Sys. Vac. - Flare Down
H-2055E	10/21/2026 11:38:40 AM	39.9	38.3	0.0	21.9			1.0	0.0	96.5	96.6	-0.73	-0.72	1.5	1.4	0.548	0.521	-15.22	-14.5	1334	34.4317398	-118.6466250	Valve Adjustment:Barely Open
H-2056B	10/26/2026 9:21:09 AM	35.6	32.1	0.0	32.3			1.1	0.0	113.9	112.3	-2.27	-0.93	8.7	2.6	1.591	0.142	-8.70	-7.77	1140	34.4297225	-118.6474612	Valve Adjustment:Decreased Flow/Vacuum
H-2056B	10/26/2026 9:24:07 AM	35.2	34.3	0.0	30.5			1.0	0.0	109.8	109.8	-0.78	-0.80	3.4	3.5	1.246	1.303	-9.41	-8.61	1137	34.4297303	-118.6474707	Valve Adjustment:Orifice Plate Changed (See OP Log)
H-2056W	10/2/2026 1:53:28 PM	57.0	39.1	0.0	3.9			1.5	0.0	115.1	114.9	-2.02	-2.50	44.4	48.4	2.552	3.030	-12.61	-10.11	1191	34.4299098	-118.6508112	Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Surging Liquid in Header
H-2057E	10/14/2026 12:18:57 PM	52.7	38.6	0.6	8.0			1.4	12.7	126.5	126.6	-15.75	-15.43	36.2	35.8	1.778	1.742	-19.73	-4.3	1130	34.4301915	-118.6458132	
H-2058E	10/14/2026 2:11:28 PM	51.7	39.9	0.0	8.4			1.3	0.0	113.4	113.5	-3.88	-4.37	25.2	27.9	1.051	1.288	-14.68	-10.31	1137	34.4300503	-118.6464562	Valve Adjustment:Increased Flow/Vacuum
H-2058E	10/14/2026 2:15:08 PM	50.3	41.0	0.0	8.7			1.2	0.0	113.5	113.6	-4.47	-4.06	30.9	27.9	1.228	1.004	-14.34	-10.28	1143	34.4300608	-118.6464453	
H-2058W	10/2/2026 1:59:44 PM	56.8	39.6	0.0	3.6			1.4	0.0	115.3	114.6	-0.60	-1.32	41.4	51.0	2.206	3.359	-11.37	-10.05	1166	34.4299412	-118.6508222	Valve Adjustment:Audible Flow,Increased Flow/Vacuum,Surging Liquid in Header
H-2059E	10/26/2026 10:02:46 AM	54.8	42.3	0.0	3.0			1.3	0.0	109.4	110.9	-14.81	-14.90	2.4	0.8	0.124	0.012	-14.88	0.02	1182	34.4306632	-118.6462727	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum,Valve 100% Open,Plugged/Pinched Suspected
H-2059E	10/26/2026 10:03:56 AM	54.6	42.1	0.0	3.4			1.3	0.0	114.8	114.5	-14.53	-14.91	5.7	7.5	0.043	0.075	-14.84	0.07	1184	34.4306732	-118.6462562	Valve Adjustment:Valve 100% Open
H-2059W	10/14/2026 2:21:22 PM	50.9	46.0	0.4	2.7			1.1	6.8	126.5	126.5	-1.48	-1.43	23.9	23.6	1.337	1.303	-21.72	-20.29	1224	34.4310812	-118.6502577	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-2161E	10/26/2026 10:09:11 AM	50.7	40.8	0.0	8.5			1.2	0.0	126.0	126.1	-6.02	-6.33	46.6	49.7	2.885	3.287	-14.50	-8.17	1189	34.4308443	-118.6464740	Valve Adjustment:Increased Flow/Vacuum
H-2161E	10/26/2026 10:11:03 AM	50.5	42.0	0.0	7.5			1.2	0.0	126.1	126.1	-7.08	-7.03	51.7	53.0	3.566	3.754	-13.90	-6.87	1187	34.4308488	-118.6464695	
H-2161W	10/30/2026 8:28:02 AM	53.6	38.7	0.4	7.3			1.4	18.3	106.2	106.2	-14.71	-15.65	38.6	36.6	1.975	1.781	-16.49	-0.84	1239	34.4309458	-118.6502013	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-2163C	10/6/2026 1:29:05 PM	43.4	42.4	0.0	14.2			1.0	0.0	109.3	109.4	-0.29	-0.30	0.1	0.1	0.003	0.002	-11.44	-11.14	1319	34.4311048	-118.6486698	Valve Adjustment:Audible Flow
H-2163C	10/19/2026 1:37:16 PM	41.1	40.4	0.0	18.5			1.0	0.0	90.1	88.5	-0.62	-0.59	0.5	0.6	0.062	0.087	-13.66	-13.07	1321	34.4310935	-118.6486700	Valve Adjustment:Barely Open
H-2163W	10/14/2026 2:07:56 PM	41.4	41.0	0.8	16.8			1.0	21.0	121.8	121.8	-3.44	-3.43	23.8	24.6	3.660	3.897	-17.80	-14.37	1262	34.4311600	-118.6498822	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-2164E	10/11/2026 1:31:15 PM	37.1	36.8	0.0	26.2			1.0	0.0	75.7	77.8	-0.81	-0.85	6.0	8.6	0.212	0.438	-7.09	-6.24	1278	34.4318967	-118.6460858	
H-2164E	10/21/2026 11:24:42 AM	39.8	51.9	0.0	8.4			0.8	0.0	121.0	121.2	-0.20	-0.19	3.3	3.2	0.227	0.223	-11.77	-11.58	1284	34.4318793	-118.6460577	Valve Adjustment:Orifice Plate Changed (See OP Log),Reduce Sys. Vac. - Flare Down
H-2165E	10/7/2026 1:07:42 PM	45.6	46.8	0.1	7.5			1.0	75.0	124.4	124.4	-2.41	-2.16	10.5	9.3	2.351	1.843	-6.88	-4.72	1211	34.4319337	-118.6451458	Reduced System Vacuum,
H-2165W	10/8/2026 2:39:54 PM	0.1	0.1	21.9	77.9			1.0	3.6	142.7	141.2	0.00	0.00	32.8	33.6	7.201	7.551	-8.13	-8.13	1272	34.4321403	-118.6504176	Valve Adjustment:NSPS/EG CAI,High Temp,Reduce Sys. Vac. - Flare Down
H-2165W	10/8/2026 2:42:00 PM					808																	AtmAA
H-2165W	10/8/2026 2:42:00 PM						39500																AtmAA; [User entered 3.95%]
H-2165W	10/9/2026 8:20:00 AM					230																	AirTech Lab

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
H-2165W	10/9/2026 8:20:00 AM						28000																AirTech Lab; [User entered 2.8%]
H-2165W	10/9/2026 1:56:27 PM	17.3	72.4	0.0	10.3			0.2	0.0	141.1	141.0	-2.47	-2.68	35.8	39.2	8.634	10.425	-12.13	-9.45	1262	34.4321532	-118.6504107	Valve Adjustment:NSPS/EG CAI,High Temp
H-2165W	10/9/2026 2:03:34 PM	19.5	70.2	0.0	10.3			0.3	0.0	141.7	140.6	-2.76	-2.74	39.0	39.2	10.347	10.394	-13.27	-10.53	1263	34.4321532	-118.6504110	Valve Adjustment:High Temp
H-2165W	10/14/2026 2:27:33 PM	20.2	19.0	10.3	50.5			1.1	4.9	113.3	113.2	-2.08	-1.55	16.0	10.6	1.604	0.706	-19.68	-18.13	1208	34.4306437	-118.6502693	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-2165W	10/28/2026 1:20:43 PM	19.0	65.9	0.2	14.9			0.3	74.5	140.2	139.6	-3.38	-3.39	100.9	100.0	14.162	13.910	-17.57	-14.18	1269	34.4321362	-118.6504207	Valve Adjustment:NSPS/EG CAI,High Temp
H-2165W	10/28/2026 1:32:37 PM	7.0	76.2	0.1	16.7			0.1	167.0	138.2	140.0	-1.22	-1.22	1.2	6.2	0.030	0.850	-16.63	-15.41	1270	34.4321455	-118.6504200	Valve Adjustment:NSPS/EG CAI,High Temp,Decreased Flow/Vacuum
H-2166E	10/27/2026 9:10:55 AM	46.2	44.3	0.0	9.5			1.0	0.0	112.7	113.7	-0.96	-0.96	11.8	12.0	0.880	0.913	-14.66	-13.7	1363	34.4356333	-118.6438530	
H-2168C	10/5/2026 12:43:48 PM	52.3	43.2	0.0	4.5			1.2	0.0	105.2	105.5	-15.46	-15.45	7.6	8.7	0.077	0.099	-15.36	0.09	1388	34.4344143	-118.6448122	Valve Adjustment:Audible Flow
H-2168E	10/27/2026 7:59:36 AM	30.9	33.9	0.0	35.2			0.9	0.0	118.3	117.9	-1.42	-1.41	11.1	10.6	0.782	0.723	-15.49	-14.08	1366	34.4345408	-118.6439077	
H-2169C	10/16/2026 1:58:37 PM	51.0	42.6	0.0	6.4			1.2	0.0	116.5	116.5	-4.52	-4.67	26.2	29.1	0.897	1.110	-18.70	-14.03	1387	34.4340457	-118.6450263	Valve Adjustment:Increased Flow/Vacuum
H-2169E	10/20/2026 8:40:25 AM	49.8	37.0	0.0	13.2			1.3	0.0	93.6	94.5	-0.47	-0.47	4.1	5.1	0.021	0.032	-19.19	-18.72	1383	34.4342115	-118.6442043	
H-2169E	10/27/2026 8:42:49 AM	39.5	35.3	0.0	25.2			1.1	0.0	118.7	118.6	-1.43	-1.43	6.6	7.0	0.056	0.064	-21.36	-19.93	1377	34.4342248	-118.6442222	
H-2170N	10/7/2026 9:18:28 AM	30.3	33.0	0.0	36.7			0.9	0.0	120.8	120.8	-1.86	-1.86	14.9	14.8	1.420	1.400	-7.68	-5.82	1271	34.4358033	-118.6414448	
H-2170S	10/15/2026 1:02:53 PM	31.0	32.5	0.2	36.3			1.0	181.5	105.9	105.3	-2.00	-2.31	5.2	6.5	0.170	0.258	-21.41	-19.1	1248	34.4335840	-118.6415052	
H-2171A	10/11/2026 1:27:07 PM	18.4	24.2	2.5	54.9			0.8	22.0	100.3	100.3	-1.83	-1.82	5.5	5.5	3.202	3.231	-4.76	-2.94	1271	34.4374277	-118.6425223	
H-2171B	10/11/2026 2:02:29 PM	39.6	32.5	0.0	27.9			1.2	0.0	113.0	113.4	-1.61	-1.66	4.8	4.6	0.149	0.136	-1.76	-0.1	1263	34.4364990	-118.6416717	
H-2171N	10/11/2026 1:16:26 PM	30.1	27.4	0.0	42.5			1.1	0.0	99.2	99.5	-1.84	-1.82	0.8	1.6	0.004	0.016	-5.17	-3.35	1264	34.4379762	-118.6433002	
H-2171N	10/19/2026 12:38:06 PM	17.2	25.5	0.0	57.3			0.7	0.0	110.6	111.5	-1.19	-1.38	2.6	4.2	0.043	0.110	-13.82	-12.44	1254	34.4379788	-118.6433372	
H-2171S	10/7/2026 9:13:55 AM	28.1	29.6	0.0	42.3			0.9	0.0	121.0	123.4	-2.94	-2.58	32.9	28.4	7.041	5.230	-8.52	-5.94	1263	34.4358018	-118.6414483	
H-2272W	10/5/2026 9:42:19 AM						9000																[User entered 0.9%]
H-2272W	10/5/2026 9:43:25 AM	29.4	34.2	0.0	36.4			0.9	0.0	128.6	128.3	-0.83	-0.79	5.9	3.7	3.887	1.544	-12.47	-11.68	1291	34.4317068	-118.6497710	Valve Adjustment:Decreased Flow/Vacuum
H-2272W	10/5/2026 9:44:12 AM	28.8	34.2	0.0	37.0			0.8	0.0	128.1	128.1	-0.78	-0.79	3.7	3.9	1.539	1.657	-12.30	-11.51	1288	34.4317120	-118.6497780	
H-2272W	10/20/2026 7:40:14 AM	23.1	30.8	0.0	46.1			0.8	0.0	120.6	118.0	-0.55	-0.55	2.4	2.2	0.607	0.522	-16.13	-15.58	1292	34.4317208	-118.6497890	
H-2273W	10/5/2026 9:15:00 AM					81																	AirTech Lab
H-2273W	10/5/2026 9:15:00 AM						8400																AirTech Lab; [User entered 0.84%]
H-2273W	10/9/2026 9:24:29 AM	15.2	32.3	0.7	51.8			0.5	74.0	126.7	126.6	-0.95	-0.95	5.6	5.6	0.201	0.201	-12.32	-11.37	1296	34.4321295	-118.6499565	Valve Adjustment:Barely Open
H-2273W	10/18/2026 1:32:49 PM	19.2	31.3	0.0	49.5			0.6	0.0	124.9	122.6	-0.42	-0.34	2.2	2.1	0.031	0.028	-12.32	-11.98	1271	34.4321768	-118.6499738	Valve Adjustment:Decreased Flow/Vacuum
H-2273W	10/18/2026 1:34:40 PM	19.1	31.2	0.0	49.7			0.6	0.0	121.7	121.3	-0.32	-0.32	3.3	3.2	0.069	0.066	-12.41	-12.09	1309	34.4321880	-118.6499705	
H-2274B	10/6/2026 2:03:38 PM	50.0	42.5	0.0	7.5			1.2	0.0	113.9	114.0	-5.06	-5.13	10.2	10.7	0.286	0.312	-11.53	-6.4	1350	34.4326700	-118.6469407	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-2274B	10/20/2026 10:11:38 AM	51.8	42.2	0.0	6.0			1.2	0.0	109.3	109.3	-6.42	-8.06	11.5	15.6	0.361	0.667	-15.10	-7.04	1360	34.4326672	-118.6469512	Valve Adjustment:Increased Flow/Vacuum
H-2274B	10/20/2026 10:13:16 AM	50.6	42.5	0.0	6.9			1.2	0.0	109.9	110.0	-8.12	-8.11	15.2	15.6	0.628	0.661	-17.06	-8.95	1357	34.4326643	-118.6469478	
H-2274W	10/9/2026 9:08:56 AM	11.8	28.1	1.9	58.2			0.4	30.6	92.0	92.4	-0.93	-0.93	0.9	0.8	0.005	0.004	-13.41	-12.48	1285	34.4327732	-118.6503693	Valve Adjustment:Barely Open
H-2274W	10/23/2026 1:56:29 PM	28.5	39.0	0.1	32.4			0.7	324.0	95.7	115.4	-0.24	-0.29	1.2	9.0	0.009	0.515	-12.75	-12.46	1305	34.4327967	-118.6503715	Valve Adjustment:Increased Flow/Vacuum
H-2275E	10/7/2026 10:45:48 AM	44.2	37.4	0.4	18.0			1.2	45.0	103.7	104.0	-1.09	-1.06	0.0	0.0	-0.015	-0.013	-8.50	-7.44	1302	34.4325265	-118.6463383	Reduced System Vacuum,
H-2275W	10/1/2026 12:13:53 PM	18.9	30.5	0.0	50.6			0.6	0.0	123.5	125.6	0.23	-0.04	16.3	14.2	1.733	1.310	-1.14	-1.1	1240	34.4322483	-118.6493415	NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum
H-2275W	10/1/2026 12:13:58 PM	18.9	30.5	0.0	50.6			0.6	0.0	123.5	125.6	0.23	-0.04	16.3	14.2	1.733	1.310	-1.14	-1.1	1266	34.4321935	-118.6493825	,
H-2275W	10/1/2026 12:14:57 PM	18.5	30.0	0.3	51.2			0.6	170.7	126.7	126.8	-0.04	-0.05	13.5	15.1	1.190	1.492	-1.19	-1.14	1283	34.4322323	-118.6492793	NSPS/EG CAC,
H-2275W	10/18/2026 1:52:04 PM	26.8	34.4	1.9	36.9			0.8	19.1	136.6	130.9	-1.30	-0.59	24.4	3.0	13.281	0.196	-12.29	-11.7	1319	34.4322537	-118.6494043	Valve Adjustment:NSPS/EG CAI,NSPS/EG CAC,Orifice Plate Changed (See OP Log),High Temp,Decreased Flow/Vacuum
H-2275W	10/18/2026 2:02:20 PM	5.0	12.9	7.6	74.5			0.4	9.9	129.7	129.4	-0.51	-0.51	2.3	2.3	0.034	0.034	-12.61	-12.1	1323	34.4322338	-118.6493765	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Barely Open
H-2275W	10/18/2026 2:06:47 PM	2.3	7.3	14.2	76.4			0.3	5.4	127.8	121.4	-0.47	-0.47	2.1	1.4	0.028	0.013	-12.47	-12	1314	34.4322358	-118.6493840	Valve Adjustment:High O2,Valve 100% Closed
H-2276A	10/5/2026 9:25:46 AM	43.1	40.1	0.4	16.4			1.1	41.0	113.6	113.3	-1.97	-1.22	6.2	4.3	0.090	0.042	-9.53	-8.31	1378	34.4328647	-118.6482832	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-2276A	10/16/2026 2:18:43 PM	33.4	40.6	0.4	25.6			0.8	64.0	112.5	112.6	-0.98	-1.05	3.9	4.3	0.034	0.043	-11.65	-10.6	1373	34.4328448	-118.6482785	Valve Adjustment:Barely Open
H-2276B	10/6/2026 2:16:14 PM	52.6	38.0	0.0	9.4			1.4	0.0	122.8	122.8	-7.93	-8.07	37.3	37.5	3.349	3.396	-13.25	-5.18	1363	34.4328888	-118.6469245	Valve Adjustment:Surging Liquid in Header,Surging Liquid in Well (Watered In)
H-2276B	10/16/2026 1:58:34 PM	51.4	37.3	0.0	11.3			1.4	0.0	122.1	122.1	-10.21	-9.45	44.2	40.7	4.702	3.983	-17.51	-8.06	1371	34.4328948	-118.6469297	Valve Adjustment:Decreased Flow/Vacuum

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
H-2276E	10/7/2026 10:26:16 AM	39.2	35.3	0.0	25.5			1.1	0.0	114.6	114.6	-0.96	-0.92	0.0	0.0	-0.001	0.000	-7.00	-6.08	1362	34.4327433	-118.6453283	Reduced System Vacuum,
H-2276W	10/1/2026 11:57:14 AM	19.9	37.8	0.0	42.3			0.5	0.0	107.1	103.5	-6.37	-5.26	0.0	0.0	-0.006	-0.018	-7.96	-2.7	1234	34.4327312	-118.6500043	,
H-2276W	10/23/2026 1:42:21 PM	0.0	0.0	21.1	78.9				3.7	100.7	101.4	-0.03	-0.05	35.3	35.4	7.753	7.810	-11.79	-11.74	1310	34.4326815	-118.6499648	
H-2277A	10/1/2026 10:32:20 AM	40.3	48.8	0.2	10.7			0.8	53.5	94.2	94.3	-5.96	-2.12	2.8	23.1	0.049	3.383	-5.58	-3.46	1332	34.4330183	-118.6487063	,
H-2277A	10/20/2026 9:55:56 AM	37.1	33.2	4.9	24.8			1.1	5.1	85.5	85.7	-5.40	-5.40	1.3	2.0	0.010	0.025	-5.15	0.25	1370	34.4330158	-118.6487362	Valve Adjustment:Barely Open,Surging Liquid in Header,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
H-2277A	10/22/2026 9:10:27 AM	41.0	37.9	4.0	17.1			1.1	4.3	58.2	58.2	-5.21	-5.40	2.4	1.9	0.035	0.020	-4.33	1.07	1353	34.4330495	-118.6487105	Valve Adjustment:Increased Flow/Vacuum
H-2277B	10/5/2026 8:34:16 AM	38.6	40.8	0.0	20.6			0.9	0.0	113.2	112.5	-4.04	-2.33	0.4	1.0	0.046	0.264	-14.12	-11.79	1386	34.4330568	-118.6469253	Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-2277B	10/16/2026 1:50:52 PM	30.0	31.9	0.0	38.1			0.9	0.0	113.7	114.4	-5.70	-3.79	1.4	0.9	0.498	0.230	-16.54	-12.75	1384	34.4330593	-118.6468948	Valve Adjustment:Decreased Flow/Vacuum
H-23 (EXP-2	10/11/2026 1:44:34 PM	3.0	69.8	0.0	27.2			0.0	0.0	80.2	80.8	-4.74	-4.72	2.7	3.3	0.016	0.024	-4.55	0.17	1258	34.4370027	-118.6421282	
H-2301E	10/19/2026 12:36:54 PM	49.7	40.4	0.0	9.9			1.2	0.0	108.6	109.0	-0.15	-0.15	12.4	12.2	0.349	0.337	-10.29	-10.14	1020	34.4270899	-118.6479936	
H-2301E	10/25/2026 3:39:18 PM	54.1	40.0	0.0	5.9			1.4	0.0	109.7	110.1	-0.48	-0.67	11.3	18.6	0.289	0.777	-11.19	-10.52	1013	34.4271120	-118.6479815	Valve Adjustment:Increased Flow/Vacuum
H-2301E	10/25/2026 3:40:09 PM	54.4	40.6	0.0	5.0			1.3	0.0	110.3	110.3	-0.77	-0.79	20.0	20.1	0.903	0.913	-11.19	-10.4	1026	34.4270728	-118.6480055	
H-2301N	10/19/2026 12:47:00 PM	43.6	52.9	0.0	3.5			0.8	0.0	122.9	122.7	-0.97	-1.55	3.6	8.5	0.017	0.094	-10.35	-8.8	1036	34.4270845	-118.6480017	Valve Adjustment:Increased Flow/Vacuum
H-2301N	10/19/2026 12:49:05 PM	43.3	52.4	0.0	4.3			0.8	0.0	122.7	122.7	-1.89	-1.98	8.1	8.1	0.086	0.085	-10.53	-8.55	1036	34.4270829	-118.6480024	
H-2301W	10/19/2026 9:14:10 AM	0.6	6.0	20.1	73.4			0.1	3.7	74.2	76.1	-8.79	-6.82	0.4	0.4	0.015	0.014	-9.68	-2.86	1122	34.4275022	-118.6506445	Valve Adjustment:NSPS/EG CAI,High O2,Decreased Flow/Vacuum,Valve 100% Closed,Plugged/Pinched Suspected
H-2301W	10/19/2026 9:15:23 AM	0.4	4.5	20.2	75.0			0.1	3.7	76.9	77.0	-7.10	-7.10	0.3	0.3	0.011	0.011	-10.05	-2.95	1115	34.4274788	-118.6506437	Valve Adjustment:High O2,Valve 100% Closed,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
H-2301W	10/19/2026 9:17:16 AM	0.2	3.6	20.2	76.0			0.1	3.8	77.4	77.5	-2.12	-2.18	0.3	0.4	0.008	0.014	-10.27	-8.09	1120	34.4274938	-118.6506305	Valve Adjustment:Valve 100% Closed
H-2302C	10/23/2026 2:17:24 PM	53.2	40.0	0.0	6.8			1.3	0.0	120.1	122.6	-0.11	-0.59	3.9	8.9	0.097	0.503	-11.17	-10.58	1119	34.4284068	-118.6490155	Valve Adjustment:Increased Flow/Vacuum,Barely Open
H-2302C	10/23/2026 2:18:40 PM	52.4	40.4	0.0	7.2			1.3	0.0	122.9	123.0	-0.66	-0.66	8.9	9.0	0.503	0.514	-11.25	-10.59	1121	34.4284063	-118.6490086	
H-2302E	10/23/2026 1:51:40 PM	57.6	40.9	0.0	1.5			1.4	0.0	100.8	100.9	-10.90	-10.81	14.4	14.0	0.266	0.250	-11.20	-0.39	1076	34.4275294	-118.6472472	
H-2303E	10/19/2026 1:11:43 PM	55.3	42.6	0.0	2.1			1.3	0.0	99.9	100.6	-7.80	-7.79	4.9	5.8	0.030	0.043	-7.53	0.26	1067	34.4279053	-118.6471872	
H-2303E	10/19/2026 1:12:42 PM	54.2	41.1	0.1	4.6			1.3	46.0	100.6	100.6	-7.87	-7.83	1.7	3.4	0.004	0.014	-7.53	0.3	1067	34.4279091	-118.6471935	Valve Adjustment:Increased Flow/Vacuum
H-2303E	10/19/2026 1:13:57 PM	55.4	40.5	0.0	4.1			1.4	0.0	100.8	100.9	-7.79	-7.76	3.8	5.0	0.018	0.031	-7.57	0.19	1067	34.4279092	-118.6471934	
H-2303E	10/19/2026 1:35:36 PM	55.7	40.4	0.0	3.9			1.4	0.0	99.4	99.9	-7.97	-7.77	0.5	1.3	0.005	0.032	-7.63	0.14	1070	34.4279015	-118.6471859	Valve Comment:op 140 to 075;Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum,Valve 100% Closed,Surging Liquid in Well (Watered In),Plugged/Pinched Suspected
H-2303N	10/6/2026 12:11:32 PM	21.4	25.6	3.6	49.4			0.8	13.7	112.9	114.2	-4.73	-2.57	44.3	19.8	2.555	0.505	-9.91	-7.34	1143	34.4290357	-118.6484317	Valve Adjustment:Decreased Flow/Vacuum
H-2303N	10/6/2026 12:36:46 PM	19.4	24.7	4.3	51.6			0.8	11.9	114.8	114.9	-1.67	-1.67	21.1	21.0	2.812	2.796	-9.86	-8.19	1141	34.4290277	-118.6484395	Valve Adjustment:Orifice Plate Changed (See OP Log)
H-2303N	10/6/2026 1:51:55 PM	21.2	26.1	3.9	48.8			0.8	12.6	115.5	114.9	-1.78	-2.49	19.0	26.0	0.465	0.875	-10.29	-7.8	1155	34.4290213	-118.6484425	Valve Adjustment:Increased Flow/Vacuum
H-2303N	10/6/2026 1:57:00 PM	21.7	25.9	3.8	48.7			0.8	13.0	115.0	115.0	-2.67	-2.65	31.2	31.5	1.259	1.286	-10.50	-7.85	1151	34.4290290	-118.6484585	
H-2303S	10/26/2026 1:50:51 PM	40.7	47.5	0.0	11.8			0.9	0.0	110.0	109.9	-2.86	-5.98	8.1	14.2	1.365	4.259	-11.87	-5.89	1108	34.4272611	-118.6496092	Valve Adjustment:Increased Flow/Vacuum
H-2303S	10/26/2026 1:52:11 PM	40.0	45.1	0.0	14.9			0.9	0.0	110.0	110.0	-6.08	-6.09	13.9	14.1	4.038	4.197	-10.29	-4.2	1109	34.4272629	-118.6496094	
H-2304E	10/19/2026 1:54:39 PM	55.2	41.6	0.0	3.2			1.3	0.0	99.0	99.4	-3.08	-3.05			0.000	0.000	-7.01	-3.96	1079	34.4282224	-118.6469094	
H-2304E	10/19/2026 2:07:04 PM	55.0	41.8	0.0	3.2			1.3	0.0	98.9	99.8	-3.11	-3.10	82.7	82.7	4.247	4.253	-6.98	-3.88	1082	34.4282262	-118.6469180	
H-2304S	10/19/2026 9:42:20 AM	38.0	35.3	0.1	26.5			1.1	189.5	124.2	121.8	-1.34	-0.07	17.7	5.0	6.713	0.522	-10.49	-10.42	1091	34.4274825	-118.6489413	Valve Adjustment:Decreased Flow/Vacuum
H-2304S	10/19/2026 9:46:32 AM	51.3	42.0	0.0	6.6			1.2	0.0	120.1	121.0	-0.01	-0.35	5.2	9.8	0.569	2.030	-10.59	-10.24	1097	34.4274900	-118.6489238	Valve Adjustment:Increased Flow/Vacuum
H-2304S	10/19/2026 9:47:12 AM	51.0	42.0	0.0	7.1			1.2	0.0	121.1	121.0	-0.36	-0.36	9.7	9.7	1.964	1.975	-10.62	-10.26	1095	34.4274857	-118.6489415	
H-2305N	10/6/2026 1:15:51 PM	18.5	30.9	0.0	50.6			0.6	0.0	108.2	106.9	-0.79	-5.23	1.6	12.3	0.006	0.347	-9.73	-4.5	1150	34.4289758	-118.6485958	Valve Comment:not fully watered in;Valve Adjustment:Increased Flow/Vacuum,Surging Liquid in Well (Watered In)
H-2305N	10/6/2026 1:24:25 PM	17.4	30.6	0.0	52.0			0.6	0.0	106.9	106.9	-5.98	-0.90	9.9	2.3	0.224	0.012	-9.77	-8.87	1149	34.4289858	-118.6486057	Valve Adjustment:Decreased Flow/Vacuum
H-2305N	10/6/2026 1:26:24 PM	17.2	29.7	0.0	53.1			0.6	0.0	106.9	106.9	-0.75	-0.74	2.4	2.4	0.013	0.013	-9.81	-9.07	1151	34.4289583	-118.6485750	

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
H-2305S	10/19/2026 9:55:47 AM	46.0	40.5	0.0	13.5			1.1	0.0	128.7	128.2	-3.67	-2.38	30.2	10.6	1.208	0.149	-12.23	-9.85	1059	34.4274523	-118.6485018	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
H-2305S	10/19/2026 10:03:20 AM	46.0	40.1	0.0	14.0			1.1	0.0	126.9	125.3	-1.45	-0.94	10.1	5.0	2.163	0.521	-11.16	-10.22	1057	34.4274558	-118.6484857	Valve Comment:changed OP to .75 decreased valve to 2 percent open
H-2306N	10/26/2026 9:35:19 AM	32.4	30.9	0.0	36.8			1.0	0.0	118.6	105.8	-2.44	-0.98	25.7	8.2	1.530	0.151	-14.61	-13.63	1124	34.4294140	-118.6475682	Valve Adjustment:Decreased Flow/Vacuum
H-2306N	10/26/2026 9:46:41 AM	38.9	35.6	0.0	25.5			1.1	0.0	108.9	109.5	-0.77	-0.77	2.5	2.6	0.132	0.134	-14.25	-13.48	1141	34.4293977	-118.6475553	Valve Adjustment:Orifice Plate Changed (See OP Log)
H-2307S	10/12/2026 2:03:58 PM	43.9	38.7	0.4	17.1			1.1	47.4	92.3	92.0	-1.61	-1.24	20.2	15.3	0.906	0.520	-20.33	-19.09	1148	34.4284430	-118.6498368	Valve Adjustment:Decreased Flow/Vacuum
H-2307S	10/12/2026 2:10:29 PM	44.3	38.6	0.5	16.6			1.1	36.1	91.4	91.2	-1.13	-1.24	15.1	15.6	0.500	0.540	-20.05	-18.81	1161	34.4284375	-118.6498407	Valve Adjustment:Increased Flow/Vacuum
H-2307S	10/12/2026 2:12:25 PM	44.8	38.5	0.4	16.3			1.2	40.8	91.1	91.0	-1.24	-1.25	16.0	16.0	0.563	0.564	-20.84	-19.59	1152	34.4284552	-118.6498508	
H-2308S	10/12/2026 1:41:18 PM	42.1	38.8	0.0	19.1			1.1	0.0	93.9	91.7	-2.07	-2.00	18.5	17.3	0.427	0.369	-18.38	-16.38	1158	34.4284430	-118.6498538	Valve Adjustment:Decreased Flow/Vacuum
H-2308S	10/12/2026 1:46:42 PM	41.4	39.2	0.0	19.4			1.1	0.0	93.4	93.4	-1.92	-1.92	18.2	18.1	0.734	0.723	-18.79	-16.87	1155	34.4284553	-118.6498308	Valve Adjustment:Orifice Plate Changed (See OP Log)
H-2309N	10/6/2026 1:02:56 PM	50.0	42.0	0.1	7.9			1.2	79.0	110.3	110.3	-7.03	-8.76	2.4	2.0	0.036	0.027	-11.62	-2.86	1292	34.4307973	-118.6489410	Valve Adjustment:Audible Flow,Increased Flow/Vacuum
H-2309S	10/23/2026 2:04:50 PM	44.5	38.5	0.0	17.0			1.2	0.0	121.4	121.4	-5.75	-5.77	35.4	35.5	2.949	2.965	-13.65	-7.88	1126	34.4281819	-118.6487479	
H-2309S	10/31/2026 11:21:47 AM	42.4	36.2	0.0	21.4			1.2	0.0	130.8	101.7	-6.46	-2.03	49.4	9.4	3.287	0.111	-15.09	-13.06				Valve Adjustment:Decreased Flow/Vacuum,Barely Open
H-2310N	10/26/2026 9:13:20 AM	36.9	33.6	0.0	29.5			1.1	0.0	113.4	112.5	-1.49	-1.10	14.1	5.3	1.242	0.174	-8.49	-7.39	1178	34.4298865	-118.6478532	Valve Adjustment:Decreased Flow/Vacuum
H-2310N	10/26/2026 9:16:40 AM	40.8	36.2	0.0	23.1			1.1	0.0	112.2	112.1	-0.91	-0.90	5.4	5.2	0.596	0.550	-9.03	-8.13	1171	34.4298718	-118.6478550	Valve Adjustment:Orifice Plate Changed (See OP Log)
H-2310S	10/26/2026 2:23:00 PM	22.4	37.2	0.0	40.4			0.6	0.0	97.0	106.9	-0.06	-6.97	0.3	6.9	0.011	5.116	-13.00	-6.03	1094	34.4291957	-118.6475656	Valve Adjustment:Increased Flow/Vacuum
H-2310S	10/26/2026 2:26:16 PM	18.4	34.1	0.1	47.4			0.5	474.0	110.6	110.5	-7.09	-7.09	6.9	6.9	5.199	5.177	-13.11	-6.02	1094	34.4291973	-118.6475645	
H-2401S	10/26/2026 8:29:41 AM	55.1	40.2	0.3	4.4			1.4	15.8	111.7	111.7	-12.15	-12.15	37.2	37.2	1.817	1.817	-14.64	-2.49	1168	34.4288737	-118.6511823	Valve Adjustment:Reduce Sys. Vac. - Flare Down
H-2401S	10/26/2026 8:45:38 AM	54.2	40.8	0.3	4.8			1.3	18.3	111.8	111.8	-12.17	-12.32	35.1	37.9	1.621	1.890	-14.50	-2.18	1193	34.4288763	-118.6511858	Valve Adjustment:Increased Flow/Vacuum
H-2401S	10/26/2026 8:46:39 AM	54.7	40.7	0.3	4.4			1.3	16.8	111.8	111.8	-12.23	-12.23	37.2	37.2	1.820	1.820	-14.36	-2.13	1213	34.4288783	-118.6512173	Valve Adjustment:Valve 100% Open
H-2402N	10/6/2026 10:48:29 AM	43.5	40.6	0.0	15.9			1.1	0.0	116.4	116.4	-0.23	-0.23	0.7	0.7	0.048	0.052	-12.08	-11.85	1181	34.4290910	-118.6503128	,
H-2402S	10/6/2026 9:47:30 AM	46.6	40.6	0.0	12.8			1.1	0.0	114.9	114.9	-0.34	-0.33	14.8	15.0	0.501	0.516	-14.23	-13.9	1212	34.4287738	-118.6504862	
H-2403N	10/6/2026 10:45:58 AM	40.9	38.1	1.5	19.5			1.1	13.0	118.8	118.8	-0.26	-0.27	6.1	6.7	0.771	0.913	-12.44	-12.17	1286	34.4293263	-118.6501628	,
H-2403S	10/6/2026 10:05:45 AM	51.6	41.7	0.4	6.4			1.2	17.2	98.7	99.7	-7.73	-8.12	3.7	4.9	0.283	0.507	-14.37	-6.25	1193	34.4287653	-118.6498972	Valve Adjustment:Increased Flow/Vacuum;Well Repairs:None
H-2403S	10/6/2026 10:16:27 AM	52.3	42.0	0.2	5.5			1.2	23.0	100.8	101.5	-5.79	-7.76	2.0	9.6	0.024	0.578	-13.97	-6.21	1190	34.4287553	-118.6498872	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
H-2403S	10/6/2026 10:24:30 AM	52.4	42.5	0.1	5.1			1.2	101.2	103.1	103.1	-7.78	-7.74	9.0	8.9	0.513	0.500	-13.72	-5.98	1184	34.4287550	-118.6498912	
H-2404N	10/6/2026 10:42:37 AM	47.5	42.2	0.0	10.3			1.1	0.0	117.3	117.4	-3.99	-3.05	13.0	8.9	3.460	1.640	-12.99	-9.94	1214	34.4293353	-118.6495290	,
H-2404S	10/6/2026 10:56:19 AM	50.9	41.0	0.0	8.1			1.2	0.0	115.4	115.5	-7.06	-7.06	18.2	19.7	0.396	0.463	-7.06	0	1112	34.4288022	-118.6493663	,
H-2405N	10/28/2026 2:45:32 PM	21.2	33.9	0.2	44.7			0.6	223.5	125.7	126.7	-0.19	-0.56	7.5	15.2	1.187	5.010	-15.29	-14.73	1257	34.4299954	-118.6495167	Valve Adjustment:Increased Flow/Vacuum
H-2405N	10/28/2026 2:47:48 PM	16.6	32.4	0.2	50.8			0.5	254.0	126.8	126.9	-0.63	-0.63	15.4	15.4	5.103	5.114	-15.76	-15.13	1258	34.4299929	-118.6495153	
H-29	10/12/2026 9:45:55 AM	16.1	44.0	1.1	38.8			0.4	35.3	125.1	126.2	-13.48	-13.92	4.8	4.3	6.398	5.208	-19.10	-5.18	1274	34.4354223	-118.6417633	
H-72	10/13/2026 10:09:38 AM	30.8	58.5	0.0	10.7			0.5	0.0	85.9	86.6	-3.65	-5.64	0.7	5.5	0.010	0.608	-15.65	-10.01	1321	34.4369100	-118.6448237	Valve Adjustment:Increased Flow/Vacuum
H-72	10/13/2026 10:10:43 AM	30.1	59.4	0.0	10.5			0.5	0.0	88.4	88.8	-11.11	-11.26	6.3	6.0	0.812	0.749	-15.31	-4.05	1318	34.4369095	-118.6447995	
H-74	10/21/2026 9:34:21 AM	49.4	41.5	0.0	9.1			1.2	0.0	99.5	100.7	-4.25	-4.32	7.1	7.5	1.044	1.167	-4.91	-0.59	1307	34.4371727	-118.6433167	
H-75	10/26/2026 12:26:31 PM	31.2	34.2	0.0	34.6			0.9	0.0	95.4	95.4	-2.94	-0.47	52.1	3.3	3.409	0.013	-16.73	-16.26	1277	34.4363932	-118.6420972	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
H-75	10/26/2026 12:29:22 PM	30.2	34.2	0.0	35.6			0.9	0.0	94.6	94.9	-1.84	-1.91	2.7	2.7	1.864	1.888	-16.66	-14.75	1276	34.4363767	-118.6421112	
H-79	10/21/2026 7:51:18 AM	46.7	48.1	0.0	5.2			1.0	0.0	119.7	119.4	-0.39	-0.39	4.2	5.7	0.023	0.043	-7.63	-7.24	1318	34.4339115	-118.6428100	Valve Adjustment:Reduce Sys. Vac. - Flare Down
P-02R	10/16/2026 12:30:19 PM	32.7	31.1	0.0	36.2			1.1	0.0	91.8	92.9	-0.17	-0.27	4.8	9.2	0.139	0.507	-15.91	-15.64	1165	34.4297522	-118.6439314	Valve Adjustment:Increased Flow/Vacuum,Barely Open
P-02R	10/16/2026 12:31:24 PM	31.9	31.0	0.0	37.1			1.0	0.0	92.8	92.8	-0.29	-0.30	9.2	9.1	0.505	0.502	-16.11	-15.81	1166	34.4297424	-118.6439448	
P-02R	10/27/2026 7:28:05 AM	23.6	28.5	0.0	47.9			0.8	0.0	84.5	84.0	-0.75	-0.69	12.4	11.1	0.923	0.727	-15.44	-14.75	1154	34.4297645	-118.6439238	
P-03R	10/12/2026 1:29:05 PM	36.3	33.0	0.0	30.7			1.1	0.0	92.8	92.9	-1.33	-1.32	2.8	2.8	0.793	0.790	-17.26	-15.94	1164	34.4298510	-118.6442052	
P-04	10/12/2026 1:04:14 PM	25.1	31.7	0.0	43.2			0.8	0.0	100.5	100.5	-0.99	-1.00			0.986	0.988	-15.91	-14.91	1148	34.4294771	-118.6445688	Valve Adjustment:No Flow Measurement
P-05	10/12/2026 1:19:21 PM	28.6	33.4	0.0	38.0			0.9	0.0	102.4	105.2	-0.26	-0.50			0.258	0.504	-14.48	-13.98	1144	34.4291660	-118.6447700	Valve Adjustment:Increased Flow/Vacuum
P-05	10/12/2026 1:21:18 PM	28.7	32.7	0.0	38.6			0.9	0.0	105.7	105.8	-0.58	-0.58			0.578	0.580	-14.13	-13.55	1144	34.4291655	-118.6447717	
P-06R	10/12/2026 12:41:17 PM	30.2	32.8	0.0	37.0			0.9	0.0	113.3	113.3	-1.53	-1.52	11.0	10.6	0.756	0.714	-13.81	-12.29	1139	34.4288606	-118.6450433	

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
P-07R	10/14/2026 1:33:57 PM	33.1	28.6	0.0	38.3			1.2	0.0	92.7	90.3	-6.92	-6.58	8.3	7.0	7.306	5.099	-16.35	-9.77	1169	34.4298356	-118.6432899	Valve Adjustment:Decreased Flow/Vacuum
P-08R	10/14/2026 2:04:43 PM	57.0	36.2	0.0	6.8			1.6	0.0	100.0	100.5	-13.54	-13.73	6.7	6.3	0.284	0.252	-14.10	-0.37	1158	34.4293959	-118.6437501	
P-08R	10/27/2026 7:22:34 AM	56.8	31.7	0.0	11.5			1.8	0.0	92.9	89.5	-9.67	-6.76	5.2	1.7	0.167	0.017	-14.20	-7.44	1171	34.4294032	-118.6437425	
P-09	10/16/2026 12:41:26 PM	47.3	36.1	0.0	16.6			1.3	0.0	93.5	98.8	-0.36	-0.34			0.354	0.347	-6.81	-6.47	1156	34.4290177	-118.6442762	Valve Adjustment:No Flow Measurement
P-10	10/16/2026 12:48:04 PM	34.2	33.6	0.0	32.2			1.0	0.0	94.5	94.5	-0.18	-0.15	2.7	2.6	0.754	0.703	-7.62	-7.47	1154	34.4287145	-118.6446265	
P-11	10/12/2026 12:27:35 PM	42.5	36.1	0.0	21.4			1.2	0.0	102.9	103.3	-0.90	-0.56	6.7	7.1	4.765	5.391	-10.58	-10.02	1140	34.4285084	-118.6449583	Valve Adjustment:Increased Flow/Vacuum,Barely Open
P-11	10/12/2026 12:29:24 PM	42.5	35.7	0.0	21.8			1.2	0.0	103.4	103.4	-0.59	-0.59	7.1	7.0	5.405	5.260	-9.76	-9.17	1143	34.4285084	-118.6449553	
P-12	10/12/2026 12:52:30 PM	56.1	40.6	0.0	3.3			1.4	0.0	81.7	82.1	-11.31	-11.39	1.5	3.3	0.003	0.013	-11.20	0.19	1118	34.4288675	-118.6456015	Valve Adjustment:Increased Flow/Vacuum,Barely Open
P-12	10/12/2026 12:55:00 PM	56.3	39.9	0.0	3.8			1.4	0.0	81.9	81.9	-11.39	-11.45	3.2	3.5	0.013	0.016	-11.35	0.1	1118	34.4288674	-118.6456017	
P-12	10/14/2026 1:39:23 PM	32.9	27.4	0.0	39.7			1.2	0.0	90.3	90.0	-7.09	-6.57	59.6	24.0	4.451	0.716	-15.36	-8.79	1171	34.4298358	-118.6432918	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
P-12	10/19/2026 10:46:46 AM	53.2	39.2	0.0	7.6			1.4	0.0	86.0	86.4	-9.90	-9.70	2.7	4.7	0.009	0.027	-9.85	-0.15	1106	34.4288464	-118.6456117	Valve Adjustment:Increased Flow/Vacuum
P-12	10/19/2026 10:48:50 AM	53.6	38.6	0.0	7.8			1.4	0.0	86.6	86.5	-9.84	-9.73	4.5	5.3	0.025	0.035	-9.76	-0.03	1107	34.4288463	-118.6456124	
P-13	10/19/2026 10:31:53 AM	51.4	34.5	0.0	14.1			1.5	0.0	87.3	86.7	-0.41	-0.41	4.4	4.4	0.386	0.381	-10.50	-10.09	1103	34.4285108	-118.6457995	
P-14	10/12/2026 12:11:45 PM	23.1	27.9	0.3	48.7			0.8	162.3	83.7	83.8	-0.97	-0.98	7.4	7.4	5.566	5.645	-11.29	-10.31	1123	34.4280306	-118.6460641	Valve Adjustment:Orifice Plate Changed (See OP Log)
P-14	10/12/2026 12:13:59 PM	22.8	27.9	0.3	49.0			0.8	163.3	83.8	83.8	-0.93	-0.93	7.4	7.4	5.584	5.643	-11.28	-10.35	1122	34.4280289	-118.6460631	
P-15R	10/1/2026 8:01:56 AM	49.9	32.9	0.0	17.2			1.5	0.0	78.8	79.0	-1.14	-1.14	1.3	1.4	0.183	0.186	-9.46	-8.32	1104	34.4277707	-118.6459242	
P-16	10/1/2026 8:21:40 AM	53.2	35.2	0.0	11.6			1.5	0.0	89.7	90.0	-2.73	-2.73	5.4	5.4	3.060	3.067	-8.59	-5.86	1107	34.4275213	-118.6456130	
P-17	10/1/2026 8:11:35 AM	36.7	31.3	0.0	32.0			1.2	0.0	103.7	112.3	-0.36	-1.06	3.4	20.1	0.015	0.516	-8.88	-7.82	1098	34.4273643	-118.6453317	Valve Adjustment:Increased Flow/Vacuum
P-17	10/1/2026 8:12:34 AM	35.5	31.0	0.0	33.5			1.1	0.0	112.8	113.0	-1.12	-1.13	19.3	19.9	0.477	0.509	-8.19	-7.06	1099	34.4273710	-118.6453477	
P-18RD	10/1/2026 8:55:33 AM	51.6	34.5	0.0	13.9			1.5	0.0	89.3	89.5	-7.35	-7.30	0.2	0.4	0.006	0.020	-7.60	-0.3	1109	34.4270743	-118.6450183	Valve Adjustment:NSPS/EG CAI,No Flow Measurement
P-18RD	10/1/2026 8:56:58 AM	50.9	35.1	0.0	14.0			1.5	0.0	89.6	89.7	-7.45	-7.23	0.6	0.2	0.037	0.004	-7.72	-0.49	1106	34.4271007	-118.6450188	Valve Adjustment:Valve 100% Open
P-18RS	10/1/2026 9:00:44 AM	43.0	32.5	0.0	24.5			1.3	0.0	94.1	94.1	-1.25	-1.25	4.6	4.7	2.244	2.290	-7.59	-6.34	1111	34.4270910	-118.6450243	
P-19	10/1/2026 8:42:28 AM	33.6	30.7	0.0	35.7			1.1	0.0	87.8	87.9	-0.94	-0.94	7.8	7.9	0.366	0.378	-6.93	-5.99	1083	34.4268678	-118.6452048	
P-20R	10/1/2026 9:46:36 AM	47.2	33.5	0.0	19.3			1.4	0.0	100.5	100.4	-1.75	-1.75	2.8	2.8	0.811	0.799	-7.25	-5.5	1111	34.4268470	-118.6448425	
P-21	10/1/2026 9:54:57 AM	27.6	29.9	0.1	42.4			0.9	424.0	93.5	93.5	-0.54	-0.54	5.1	5.5	2.696	3.099	-7.09	-6.55	1106	34.4264992	-118.6448012	
P-21RD	10/1/2026 12:34:52 PM	40.8	34.2	0.0	25.0			1.2	0.0	104.5	104.7	-2.41	-2.38	15.0	14.4	1.397	1.289	-5.11	-2.73	1128	34.4263905	-118.6443893	
P-21RS	10/1/2026 12:31:54 PM	45.4	36.9	0.0	17.7			1.2	0.0	110.3	110.3	-3.96	-3.88	25.5	24.7	1.501	1.404	-4.94	-1.06	1123	34.4263972	-118.6443942	
P-22RD	10/12/2026 10:28:30 AM	52.1	40.8	0.0	7.1			1.3	0.0	113.4	112.9	-4.75	-4.74	3.9	3.6	4.117	3.540	-8.23	-3.49	1187	34.4269049	-118.6438141	
P-22RS	10/12/2026 10:24:16 AM	31.7	30.0	0.0	38.3			1.1	0.0	120.3	120.2	-1.17	-1.17	26.1	25.9	1.592	1.563	-7.81	-6.64	1186	34.4269034	-118.6438131	
P-23	10/1/2026 10:08:09 AM	4.5	20.9	0.7	73.9			0.2	105.6	103.9	102.3	-0.22	-0.22	1.0	0.6	0.006	0.003	-6.66	-6.44	1099	34.4261302	-118.6447223	
P-24	10/1/2026 12:44:34 PM	22.7	26.3	0.0	51.0			0.9	0.0	104.1	104.2	-1.05	-1.05	3.2	3.2	1.082	1.063	-4.92	-3.87	1102	34.4260700	-118.6442837	
P-26	10/1/2026 1:06:50 PM	46.1	34.5	0.6	18.8			1.3	31.3	91.4	91.6	-1.22	-1.22	2.8	2.7	0.792	0.778	-5.18	-3.96	1123	34.4265177	-118.6432242	
P-27	10/1/2026 1:39:12 PM	24.1	25.6	0.0	50.3			0.9	0.0	100.5	100.9	-0.29	-0.35	1.8	2.3	0.867	1.368	-4.69	-4.34	1126	34.4268158	-118.6427788	
P-28	10/1/2026 1:56:43 PM	53.5	40.6	0.0	5.9			1.3	0.0	101.1	102.1	0.44	0.67	2.9	0.3	2.152	0.016	-5.51	-6.18	1138	34.4270273	-118.6422988	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Valve 100% Closed
P-28	10/1/2026 1:57:35 PM	53.3	40.1	0.0	6.6			1.3	0.0	103.1	103.4	0.70	0.70	0.3	0.3	0.020	0.020	-5.98	-6.68	1141	34.4270457	-118.6422710	Valve Adjustment:NSPS/EG CAI,Positive Static Press.
P-28	10/2/2026 8:14:33 AM	54.8	36.7	0.0	8.5			1.5	0.0	84.8	86.0	-0.69	-0.70	3.5	3.8	3.155	3.625	-7.20	-6.5	1150	34.4270603	-118.6422533	Valve Adjustment:NSPS/EG CAC,Increased Flow/Vacuum
P-29R	10/2/2026 8:21:05 AM	38.7	31.5	0.0	29.8			1.2	0.0	85.9	88.4	-0.83	-1.11	1.4	1.8	0.012	0.019	-7.09	-5.98	1154	34.4271777	-118.6418370	
P-30R	10/2/2026 8:26:14 AM	28.5	28.3	0.0	43.2			1.0	0.0	88.1	88.2	-5.17	-5.08	9.1	8.8	1.665	1.557	-6.67	-1.59	1166	34.4274112	-118.6415998	
P-32R1	10/2/2026 8:43:31 AM	30.1	31.1	0.1	38.7			1.0	387.0	112.7	112.7	-1.73	-1.73	4.5	4.4	5.333	5.116	-6.29	-4.56	1180	34.4282220	-118.6410547	
P-32R2	10/2/2026 8:51:11 AM	30.1	31.1	0.0	38.8			1.0	0.0	109.8	109.8	-1.98	-2.00	8.1	9.0	0.084	0.103	-5.43	-3.43	1183	34.4284423	-118.6409335	
P-33	10/2/2026 9:00:23 AM	35.7	34.1	0.3	29.9			1.0	99.7	94.3	94.3	-1.76	-1.78	3.5	3.5	1.273	1.245	-5.43	-3.65	1192	34.4288360	-118.6407972	
P-36	10/2/2026 9:23:04 AM	13.5	25.8	0.4	60.3			0.5	150.8	110.2	110.1	-2.47	-2.35			2.495	2.340	-3.64	-1.29	1214	34.4301813	-118.6400590	
P-36	10/2/2026 2:30:17 PM	13.9	25.5	0.3	60.3			0.5	201.0	120.3	120.3	-0.10	-0.41	1.3	3.5	0.197	1.371	-1.80	-1.39	1167	34.4302220	-118.6400648	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum
P-36	10/2/2026 2:33:29 PM	14.2	26.7	0.2	58.9			0.5	294.5	120.3	120.3	-0.50	-0.50	4.0	4.0	1.771	1.789	-1.92	-1.42	1188	34.4302222	-118.6400702	
P-37	10/1/2026 1:03:26 PM	9.4	24.2	0.3	66.1			0.4	220.3	109.1	108.8	-2.64	-2.22	3.0	2.8	2.337	1.992	-0.34	1.88	1249	34.4304617	-118.6403566	Valve Adjustment:Decreased Flow/Vacuum,Valve 100% Closed,Reduce Sys. Vac. - Flare Down
P-37	10/1/2026 1:12:50 PM	9.5	24.9	0.3	65.3			0.4	217.7	108.5	108.4	-2.30	-2.52	2.8	3.0	2.135	2.369	-0.05	2.47	1241	34.4304739	-118.6403719	
P-37	10/1/2026 2:05:04 PM	9.0	24.6	0.8	65.6			0.4	82.0	108.1	108.4	-0.19	-0.19	1.3	1.3	0.409	0.419	-2.82	-2.63	1233	34.4304809	-118.6403552	Valve Adjustment:Barely Open
P-38RD	10/2/2026 1:44:22 PM	43.6	37.2	0.0	19.2			1.2	0.0	109.2	109.1	-2.13	-2.20	19.8	20.6	0.503	0.541	-2.15	0.05	1227	34.4299712	-118.6406360	

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
P-38RS	10/2/2026 1:30:26 PM	32.3	33.1	0.0	34.6			1.0	0.0	107.9	107.9	-2.26	-2.21	4.0	3.8	1.674	1.572	-1.26	0.95	1229	34.4299662	-118.6406425	
P-39	10/5/2026 1:37:06 PM	51.4	39.6	0.2	8.8			1.3	44.0	111.7	112.6	-4.16	-4.09	1.4	1.5	0.041	0.048	-3.99	0.1	1233	34.4294890	-118.6409899	
P-41	10/2/2026 1:07:36 PM	37.0	32.1	2.4	28.5			1.2	11.9	119.1	118.3	-4.26	-4.05			0.204	0.251	-4.20	-0.15	1228	34.4288727	-118.6414248	Valve Adjustment:No Flow Measurement,Surging Liquid in Header
P-42R	10/5/2026 1:46:40 PM	51.0	41.3	0.0	7.7			1.2	0.0	116.5	116.5	-3.52	-3.55	2.2	2.2	0.518	0.504	-3.80	-0.25	1227	34.4284175	-118.6417112	
P-43	10/5/2026 1:57:07 PM	24.3	30.2	0.5	45.0			0.8	90.0	119.4	119.5	-1.83	-1.87			1.829	1.864	-3.94	-2.07	1224	34.4282702	-118.6418207	
P-44RD	10/6/2026 1:28:00 PM	49.4	37.4	0.2	13.0			1.3	65.0	110.4	111.8	-3.30	-3.30	1.1	1.1	0.124	0.124	-3.27	0.03	1231	34.4281210	-118.6419382	
P-44RS	10/5/2026 2:07:26 PM	21.1	29.2	0.1	49.6			0.7	496.0	122.5	123.2	-2.40	-2.38	9.2	9.2	0.547	0.548	-3.56	-1.18	1219	34.4281437	-118.6419033	Valve Adjustment:Decreased Flow/Vacuum
P-44RS	10/5/2026 2:09:37 PM	21.9	29.9	0.0	48.2			0.7	0.0	123.3	123.3	-2.33	-2.33	9.0	9.2	0.520	0.541	-3.44	-1.11	1219	34.4281460	-118.6419088	
P-45RD	10/6/2026 1:50:51 PM	43.0	39.3	0.0	17.7			1.1	0.0	118.9	119.1	-3.17	-3.11	5.5	5.5	0.190	0.191	-3.31	-0.2	1219	34.4277145	-118.6424660	
P-45RS	10/6/2026 1:43:31 PM	3.0	23.3	0.0	73.7			0.1	0.0	117.0	117.2	-0.06	-0.06	3.4	3.4	3.001	3.115	0.29	0.35	1218	34.4277314	-118.6424864	
P-46RD	10/6/2026 2:09:40 PM	49.5	40.7	0.0	9.8			1.2	0.0	115.4	117.7	-3.46	-3.57	1.8	1.9	0.021	0.022	-3.24	0.33	1210	34.4276571	-118.6426413	
P-46RS	10/6/2026 2:01:10 PM	19.6	30.8	0.0	49.6			0.6	0.0	122.8	122.7	-0.78	-0.78	15.1	15.2	1.452	1.472	-3.22	-2.44	1215	34.4276752	-118.6426520	
P-47	10/6/2026 2:35:57 PM	18.4	28.4	0.0	53.2			0.6	0.0	122.2	126.9	0.10	-0.24			0.012	0.000	-3.83	-3.59	1206	34.4274456	-118.6432549	Valve Comment:Swap to QED Wellhead;Valve Adjustment:NSPS/EG CAI,Orifice Plate Changed (See OP Log),Positive Static Press.,Increased Flow/Vacuum
P-47	10/6/2026 2:52:48 PM	17.1	29.4	0.0	53.5			0.6	0.0	124.3	123.9	0.05	-0.03	5.6	6.3	3.435	4.336	-3.15	-3.12	1207	34.4274419	-118.6432629	Valve Comment:Swap from 125 op to 050 op;Valve Adjustment:NSPS/EG CAI,Orifice Plate Changed (See OP Log),Positive Static Press.,Increased Flow/Vacuum,Valve 100% Open
P-47	10/6/2026 3:07:43 PM	13.5	27.7	0.1	58.7			0.5	587.0	126.2	124.1	-0.21	-0.06	14.1	4.9	4.302	0.510	-3.69	-3.63	1207	34.4274503	-118.6432567	Valve Comment:Swap 050 to 075 OP;Valve Adjustment:NSPS/EG CAC,Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
P-47	10/7/2026 12:44:16 PM	16.9	26.7	0.1	56.3			0.6	563.0	123.1	124.0	0.03	-0.02	5.1	7.1	0.554	1.085	-3.50	-3.48	1238	34.4274541	-118.6432775	Valve Adjustment:NSPS/EG CAI,Increased Flow/Vacuum,Barely Open,Reduce Sys. Vac. - Flare Down
P-47	10/7/2026 12:50:44 PM	14.9	26.6	0.1	58.4			0.6	584.0	124.4	124.5	-0.04	-0.04	6.8	6.8	0.988	0.976	-3.69	-3.65	1238	34.4274495	-118.6432651	Valve Adjustment:NSPS/EG CAC,Reduce Sys. Vac. - Flare Down
P-48	10/14/2026 1:12:48 PM	15.2	21.3	1.2	62.3			0.7	51.9	92.9	121.4	0.06	-0.84	0.6	9.9	0.002	0.627	-7.05	-6.21	1204	34.4275809	-118.6435635	Valve Adjustment:NSPS/EG CAI,Positive Static Press.,Increased Flow/Vacuum,Barely Open
P-48	10/14/2026 1:16:36 PM	17.8	23.2	0.0	59.0			0.8	0.0	129.3	131.0	-0.78	-0.79	5.3	3.2	0.179	0.064	-6.98	-6.19	1204	34.4275615	-118.6435757	Valve Adjustment:NSPS/EG CAC
P-49RD	10/7/2026 2:11:04 PM	51.2	41.6	0.0	7.2			1.2	0.0	115.2	115.2	-3.36	-3.36	7.1	7.7	0.325	0.373	-4.17	-0.81	1207	34.4279753	-118.6438398	Valve Adjustment:Reduce Sys. Vac. - Flare Down
P-49RS	10/7/2026 2:07:42 PM	33.3	34.9	0.1	31.7			1.0	317.0	115.5	115.6	-0.52	-0.52	15.4	16.0	0.548	0.590	-4.19	-3.67	1207	34.4279812	-118.6438500	Valve Adjustment:Reduce Sys. Vac. - Flare Down
P-52	10/13/2026 1:35:40 PM	29.2	33.3	0.0	37.5			0.9	0.0	116.2	116.3	-0.33	-0.32	10.4	10.4	2.279	2.265	-13.86	-13.54	1205	34.4287129	-118.6432643	
P-53	10/13/2026 1:44:08 PM	18.9	28.5	0.0	52.6			0.7	0.0	114.2	114.5	-0.62	-0.60	8.7	8.7	1.580	1.593	-14.70	-14.1	1207	34.4290977	-118.6430694	
P-53	10/13/2026 1:59:44 PM	21.1	32.9	0.0	46.0			0.6	0.0	103.4	103.5	-5.89	-5.97	28.0	28.4	4.925	5.086	-7.52	-1.55	1216	34.4293898	-118.6428873	
P-54	10/13/2026 1:57:36 PM	19.4	31.5	0.0	49.1			0.6	0.0	103.4	103.4	-6.37	-5.23	48.9	43.7	5.526	4.381	-7.54	-2.31	1215	34.4293982	-118.6428948	Valve Adjustment:Orifice Plate Changed (See OP Log),Decreased Flow/Vacuum
P-55	10/13/2026 2:07:42 PM	30.8	31.6	0.0	37.6			1.0	0.0	101.6	102.0	-2.59	-5.03			0.021	0.113	-17.03	-12	1224	34.4297268	-118.6427427	Valve Adjustment:No Flow Measurement,Increased Flow/Vacuum,Barely Open
P-55	10/13/2026 2:08:21 PM	30.6	31.2	0.0	38.2			1.0	0.0	102.0	102.0	-5.33	-5.29			0.142	0.101	-16.36	-11.07	1223	34.4297278	-118.6427406	
P-56	10/14/2026 10:39:06 AM	12.9	25.5	0.5	61.1			0.5	122.2	102.6	102.7	-1.17	-1.30			0.000	0.000	-17.19	-15.89	1229	34.4300998	-118.6428134	Valve Adjustment:No Flow Measurement,Increased Flow/Vacuum,Barely Open
P-57	10/14/2026 10:29:34 AM	9.0	20.7	3.9	66.4			0.4	17.0	83.3	83.3	-0.47	-0.49	1.6	1.9	0.003	0.004	-16.74	-16.25	1236	34.4299781	-118.6424428	
P-60R	10/14/2026 12:34:56 PM	56.5	37.6	0.0	5.9			1.5	0.0	89.4	90.0	-2.75	-2.90	2.3	2.4	0.109	0.117	-3.15	-0.25	1241	34.4307685	-118.6415505	
P-61	10/14/2026 12:27:37 PM	43.9	36.1	0.0	20.0			1.2	0.0	87.0	87.7	-0.36	-0.38	6.1	5.6	3.874	3.274	-4.00	-3.62	1243	34.4311143	-118.6411283	
P-65	10/14/2026 12:47:26 PM	30.5	29.7	0.0	39.8			1.0	0.0	87.3	87.3	-1.12	-1.11	2.2	2.2	1.257	1.246	-3.54	-2.43	1227	34.4303818	-118.6409613	
P-71	10/7/2026 1:36:52 PM	37.5	36.5	0.0	26.0			1.0	0.0	112.5	113.0	-0.43	-0.50	4.5	5.3	2.180	3.025	-5.01	-4.51	1223	34.4279725	-118.6432082	Valve Adjustment:Orifice Plate Changed (See OP Log),Increased Flow/Vacuum,Barely Open,Reduce Sys. Vac. - Flare Down
P-71	10/7/2026 1:38:43 PM	37.8	37.1	0.0	25.1			1.0	0.0	113.3	113.3	-0.53	-0.53	5.2	5.3	2.962	3.045	-4.93	-4.4	1222	34.4279720	-118.6432166	Valve Adjustment:Reduce Sys. Vac. - Flare Down
P-75	10/14/2026 10:51:42 AM	54.9	37.3	0.0	7.8			1.5	0.0	92.6	92.9	-3.53	-3.50	12.9	12.8	1.005	0.990	0.34	3.84	1234	34.4303147	-118.6415310	
P-76	10/14/2026 12:57:06 PM	23.8	29.5	0.0	46.7			0.8	0.0	109.8	110.0	-0.83	-0.80	6.5	6.5	0.863	0.860	-2.27	-1.47	1232	34.4302160	-118.6404639	
P-79	10/1/2026 8:34:34 AM	14.3	24.9	1.3	59.5			0.6	45.8	87.9	87.2	-0.25	-0.25			0.259	0.256	-5.78	-5.53	1045	34.4270132	-118.6460593	
SC-2000E	10/6/2026 10:08:44 AM	39.2	38.1	0.0	22.7			1.0	0.0	122.8	123.2	-4.54	-4.19	4.2	2.2	0.376	0.104	-10.80	-6.61	1224	34.4307253	-118.6467495	,
SC-2501E	10/5/2026 9:30:00 AM					1420																	AtmAA

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp [°F]	Adj Temp [°F]	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
SC-2501E	10/5/2026 9:30:00 AM						172800																AtmAA; [User entered 17.28%]
SC-2501E	10/5/2026 9:32:48 AM	18.0	69.8	1.0	11.2			0.3	11.2	189.3	189.3	-3.28	-3.26			3.266	3.253	-9.46	-6.2	1338	34.4366810	-118.6479287	Valve Adjustment:No Flow Measurement,High Temp
SC-2501E	10/12/2026 8:34:12 AM	6.0	73.9	1.2	18.9			0.1	15.8	189.7	189.7	-3.16	-3.14			3.148	3.111	-9.72	-6.58	1355	34.4366764	-118.6479083	Valve Adjustment:No Flow Measurement,High Temp
SC-2501E	10/12/2026 8:40:00 AM					1370																	AtmAA
SC-2501E	10/19/2026 8:32:58 AM	7.4	78.1	1.1	13.4			0.1	12.2	189.6	189.6	-3.02	-3.00	20.4	20.5	3.018	3.023	-9.83	-6.83	1349	34.4366970	-118.6479103	Valve Adjustment:No Flow Measurement,High Temp
SC-2501E	10/26/2026 8:30:00 AM					1310																	AtmAA
SC-2501E	10/26/2026 8:31:05 AM	2.2	70.0	0.4	27.4			0.0	68.5	189.0	189.0	-9.06	-8.80	35.5	35.2	9.307	9.135	-1.95	6.85	1342	34.4367045	-118.6479280	Valve Adjustment:No Flow Measurement,High Temp
SC-2501W	10/5/2026 9:52:13 AM	14.2	73.4	0.0	12.4			0.2	0.0	188.4	188.5	-3.23	-3.21	21.1	21.0	3.223	3.193	-6.59	-3.38	1357	34.4367895	-118.6485313	Valve Adjustment:No Flow Measurement,High Temp
SC-2501W	10/5/2026 9:55:00 AM					689.5																	AtmAA
SC-2501W	10/5/2026 9:55:00 AM						183900																AtmAA; [User entered 18.39%]
SC-2501W	10/12/2026 8:53:05 AM	4.5	69.9	0.0	25.6			0.1	0.0	188.1	188.0	-3.01	-2.99	20.4	20.4	3.012	2.995	-6.40	-3.41	1353	34.4367766	-118.6485206	Valve Adjustment:No Flow Measurement,High Temp
SC-2501W	10/12/2026 8:55:00 AM					629.5																	AtmAA
SC-2501W	10/19/2026 9:01:11 AM	10.8	69.2	3.6	16.4			0.2	4.6	187.1	184.7	-3.12	-2.39	20.9	18.3	3.132	2.390	-6.76	-4.37	1360	34.4367875	-118.6485268	Valve Adjustment:NSPS/EG CAI,No Flow Measurement,High Temp,High O2,Decreased Flow/Vacuum
SC-2501W	10/19/2026 9:06:10 AM	14.9	70.9	2.1	12.1			0.2	5.8	184.8	184.7	-2.35	-2.35	18.2	18.1	2.376	2.356	-8.67	-6.32	1356	34.4367858	-118.6485278	Valve Adjustment:NSPS/EG CAC,No Flow Measurement,High Temp
SC-2501W	10/26/2026 8:45:00 AM					720																	AtmAA
SC-2501W	10/26/2026 8:49:39 AM	1.8	74.5	0.4	23.3			0.0	58.3	181.7	182.3	-10.11	-9.93	37.5	37.2	10.341	10.163	-2.35	7.58	1356	34.4367955	-118.6485262	Valve Adjustment:Audible Flow,High Temp
SW-10	10/30/2026 9:36:29 AM	17.9	30.8	3.7	47.6			0.6	12.9	76.3	76.3	-14.57	-14.54	2.1	3.3	0.028	0.066	-16.29	-1.75	1340	34.4370280	-118.6503545	
SW-115	10/29/2026 1:15:22 PM	38.6	32.4	2.3	26.7			1.2	11.6	86.3	86.3	-17.74	-17.75	24.4	25.0	3.767	3.938	-21.26	-3.51	1214	34.4348128	-118.6412320	
SW-1445	10/20/2026 10:37:03 AM	0.5	0.4	20.7	78.4			1.3	3.8	85.8	86.1	-1.83	-1.83	1.8	1.7	0.004	0.004	-1.71	0.12	1228	34.4325305	-118.6520090	
SW-1455	10/20/2026 10:40:06 AM	0.3	0.1	20.7	78.9			3.0	3.8	82.7	82.9	-1.30	-1.31	1.4	1.1	0.003	0.002	-1.03	0.28	1223	34.4325225	-118.6519773	
SW-154	10/21/2026 7:27:28 AM	0.0	1.8	19.0	79.2			0.0	4.2	55.3	55.4	-7.06	-7.07			0.006	0.001	-6.88	0.19	1259	34.4379947	-118.6456285	Valve Adjustment:NSPS/EG CAI,High O2
SW-154	10/21/2026 7:28:11 AM	0.0	1.8	18.9	79.3			0.0	4.2	55.6	55.6	-7.15	-7.06		0.0	0.003	0.000	-6.96	0.1	1265	34.4379940	-118.6456350	
SW-154	10/26/2026 2:49:59 PM	0.1	1.5	19.2	79.2			0.1	4.1	87.7	88.0	-13.84	-13.52			0.006	0.020	-13.75	-0.23	1282	34.4379795	-118.6456508	
SW-17-135	10/20/2026 10:44:36 AM	18.7	16.0	3.0	62.3			1.2	20.8	93.2	93.3	-1.62	-1.62	3.2	3.1	0.013	0.012	-1.37	0.25	1229	34.4325010	-118.6519780	
SW-187	10/29/2026 2:45:40 PM	19.5	36.0	2.6	41.9			0.5	16.1	79.7	79.9	-15.54	-15.57	8.5	7.9	0.017	0.015	-15.35	0.22	1295	34.4372757	-118.6473708	
SW-20	10/14/2026 1:47:38 PM	0.1	2.3	18.2	79.4			0.0	4.4	88.6	89.8	-6.06	-6.06	1.9	2.6	0.004	0.008	-16.75	-10.69	1169	34.4302294	-118.6436472	Valve Adjustment:High O2
SW-2501D	10/20/2026 10:59:49 AM	1.3	3.8	19.7	75.2			0.3	3.8	85.8	85.8	-11.81	-11.85	1.0	0.7	0.099	0.051	-11.52	0.33	1241	34.4335307	-118.6519767	
SW-2501M	10/20/2026 11:06:20 AM	19.4	27.6	10.7	42.3			0.7	4.0	88.3	89.1	-11.98	-11.81	0.6	0.6	0.032	0.038	-11.77	0.04	1234	34.4335177	-118.6519842	
SW-2501M	10/20/2026 11:08:50 AM	24.8	59.6	2.8	12.8			0.4	4.6	84.4	84.3	-9.13	-9.29	1.9	1.8	0.022	0.020	-10.53	-1.24	1238	34.4335117	-118.6519867	Valve Adjustment:Increased Flow/Vacuum
SW-2501S	10/20/2026 11:02:56 AM	5.7	9.0	9.9	75.4			0.6	7.6	91.7	91.9	-11.55	-11.54	0.7	0.7	0.047	0.046	-11.50	0.04	1247	34.4335243	-118.6519785	
SW-30	10/20/2026 11:15:27 AM	5.5	28.0	9.8	56.7			0.2	5.8	91.2	91.3	-9.18	-9.27	3.1	4.5	0.012	0.026	-9.07	0.2	1243	34.4336673	-118.6519627	
SW-32	10/20/2026 10:53:39 AM	10.6	35.5	8.0	45.9			0.3	5.7	84.7	84.7	-9.10	-9.13			0.000	0.000	-9.02	0.11	1252	34.4335100	-118.6520123	
SW-64	10/20/2026 11:13:01 AM	17.1	82.6	0.3	0.0			0.2	0.0	86.1	86.3	-9.44	-9.48	3.0	3.4	0.011	0.014	-9.15	0.33	1237	34.4336650	-118.6519608	
SW-65	10/7/2026 1:20:41 PM	38.1	30.6	0.8	30.5			1.2	38.1	107.8	107.9	-7.27	-7.14	1.8	2.4	0.020	0.035	-7.79	-0.65	1216	34.4348303	-118.6412135	
SW-66	10/21/2026 7:18:25 AM	6.6	8.5	15.0	69.9			0.8	4.7	83.9	84.0	-6.84	-6.80			0.087	0.115	-6.75	0.05	1258	34.4379893	-118.6456373	Valve Adjustment:NSPS/EG CAI,High O2
SW-66	10/21/2026 7:31:15 AM	6.3	6.6	15.2	71.9			1.0	4.7	84.3	84.3	-7.05	-7.07			0.099	0.110	-7.00	0.07	1257	34.4379910	-118.6456365	
SW-66	10/26/2026 2:48:34 PM	5.1	6.8	14.7	73.4			0.8	5.0	87.3	87.4	-13.22	-13.16	13.1	12.9	0.383	0.372	-13.71	-0.55	1288	34.4379842	-118.6456302	
SW-68	10/20/2026 10:51:19 AM	15.1	36.2	1.9	46.8			0.4	24.6	88.7										1255	34.4335128	-118.6520138	
SW-70	10/30/2026 12:51:59 PM	15.6	66.4	1.2	16.8			0.2	14.0	87.6	87.6	-17.12	-17.14	38.5	36.7	0.362	0.330	-17.00	0.14	1314	34.4372523	-118.6473557	
SW-71	10/1/2026 12:49:09 PM	15.3	17.9	6.7	60.1			0.9	9.0	105.9	106.1	-4.42	-4.53	1.4	1.9	0.216	0.405	-4.72	-0.19	1122	34.4259735	-118.6438272	
SW-72	10/2/2026 9:15:52 AM	23.6	24.3	4.0	48.1			1.0	12.0	76.9	76.7	-4.25	-4.52	3.1	3.3	0.056	0.064	-3.83	0.69	1205	34.4296403	-118.6401632	
SW-80	10/12/2026 9:11:32 AM	29.7	28.8	0.1	41.4			1.0	414.0	78.9	78.9	-15.82	-15.88	9.5	9.5	0.562	0.556	-16.66	-0.78	1220	34.4382728	-118.6433680	
SW-9	10/21/2026 8:05:06 AM	0.3	24.5	10.9	64.3			0.0	5.9	73.9	73.9	-7.07	-7.10	5.1	6.0	0.006	0.008	-6.96	0.14	1321	34.4372342	-118.6473667	Valve Adjustment:NSPS/EG CAI,High O2
SW-9	10/21/2026 8:07:12 AM	0.3	25.8	10.6	63.3			0.0	6.0	73.4	73.5	-7.09	-7.22	5.7	5.5	0.008	0.007	-6.88	0.34	1323	34.4372408	-118.6473622	Valve Adjustment:NSPS/EG CAI,High O2
TC-1961C	10/7/2026 10:59:44 AM	21.5	30.6	0.0	47.9			0.7	0.0	120.8	120.9	-0.79	-0.75	4.4	4.3	0.044	0.043	-5.94	-5.19	1280	34.4321913	-118.6454472	Reduced System Vacuum,
TC-1961C	10/27/2026 10:57:25 AM	2.9	20.0	0.0	77.1			0.1	0.0	113.5	108.3	-2.03	-1.10	5.7	2.0	0.075	0.009	-14.35	-13.25	1284	34.4321682	-118.6454312	Valve Adjustment:Decreased Flow/Vacuum;Well Repairs:Flex Hose
TC-1961C	10/27/2026 11:00:00 AM					12.3																	AtmAA
TC-1961C	10/27/2026 11:00:00 AM						4400																AtmAA; [User entered 0.44%]
TC-1961E	10/28/2026 10:00:04 AM	50.8	42.6	0.0	6.6			1.2	0.0	121.4	121.4	-3.95	-3.98	11.6	11.9	0.316	0.330	-21.27	-17.29	1300	34.4328465	-118.6445060	

All LFG Extraction Wells - October 2026
Chiquita Canyon Landfill

Point Name	Record Date	CH4 [%]	CO2 [%]	O2 [%]	Bal Gas [%]	CO Reading [ppmv]	H2 Reading [ppmv]	CH4:CO2	BalO2 [%]	Init Temp (°F)	Adj Temp (°F)	Init Stat Press ["H2O]	Adj Stat Press ["H2O]	Init Flow [scfm]	Adj Flow [scfm]	Init Diff Press ["H2O]	Adj Diff Press ["H2O]	Sys Pressure ["H2O]	Avail Pressure ["H2O]	Elev [ft]	Latitude	Longitude	Comments
TC-2174	10/5/2026 9:12:45 AM	2.7	78.8	0.1	18.4			0.0	184.0	185.5	185.5	-4.67	-4.64			4.657	4.622	0.19	4.83	1323	34.4367394	-118.6476585	Valve Adjustment:No Flow Measurement,High Temp
TC-2174	10/5/2026 9:20:00 AM					2050																	AtmAA
TC-2174	10/5/2026 9:20:00 AM						171000																AtmAA; [User entered 17.1%]
TC-2174	10/12/2026 8:25:21 AM	4.6	78.2	0.6	16.6			0.1	27.7	185.0	64.6	-5.94	-5.70			6.050	5.914	-5.52	0.18	1344	34.4367282	-118.6476314	Valve Adjustment:No Flow Measurement,High Temp
TC-2174	10/12/2026 8:30:00 AM					2410																	AtmAA
TC-2174	10/19/2026 8:09:44 AM	4.3	80.0	0.4	15.3			0.1	38.3	185.0	66.0	-4.81	-4.76			4.791	4.781	0.00	4.76	1340	34.4367462	-118.6476253	Valve Adjustment:No Flow Measurement,High Temp
TC-2174	10/26/2026 7:39:38 AM	1.8	73.8	0.4	24.0			0.0	60.0	185.0	67.2	-6.08	-5.79			6.253	5.953	-5.01	0.78	1348	34.4367500	-118.6475992	Valve Adjustment:No Flow Measurement,High Temp
TC-2174	10/26/2026 7:45:00 AM					1820																	AtmAA
VL-02	10/29/2026 9:47:14 AM	59.6	36.2	0.1	4.1			1.6	41.0	92.6	93.2	-25.71	-25.54	26.9	24.1	0.924	0.744	-25.02	0.52	1162	34.4311838	-118.6442992	
WTD-01	10/15/2026 12:48:37 PM	24.2	53.6	0.9	21.3			0.5	22.9	149.0	148.6	-5.39	-5.43			5.395	5.388	-6.80	-1.37	1284	34.4350037	-118.6514505	
WTD-01	10/20/2026 9:05:00 AM					716																	AtmAA
WTD-01	10/20/2026 9:45:36 AM	3.3	72.6	0.0	24.1			0.0	0.0	151.5	151.6	-5.30	-5.05			5.608	5.424	0.04	5.09	1293	34.4349784	-118.6514623	Valve Adjustment:No Flow Measurement,High Temp
WTD-01	10/29/2026 1:21:00 PM					663																	AtmAA
WTD-01	10/29/2026 1:30:07 PM	35.5	56.3	1.3	6.9			0.6	5.3	151.3	151.3	-7.02	-6.97			6.970	6.932	-9.55	-2.58	1261	34.4349967	-118.6514470	Valve Adjustment:No Flow Measurement,High Temp
WTD-02	10/15/2026 12:43:22 PM	26.0	48.6	1.6	23.9			0.5	15.4	151.8	152.0	-6.10	-6.18			6.102	6.211	-8.18	-2	1274	34.4346720	-118.6513192	
WTD-02	10/20/2026 8:55:00 AM					421																	AtmAA
WTD-02	10/20/2026 9:10:37 AM	23.4	48.7	1.9	26.0			0.5	13.7	125.9	126.4	-4.93	-4.91			4.959	4.946	0.04	4.95				Valve Adjustment:No Flow Measurement,High Temp
WTD-03	10/15/2026 12:32:11 PM	19.3	35.4	8.3	37.0			0.5	4.4	93.1	93.1	-4.93	-4.96			4.929	4.929	-4.95	0.01	1261	34.4343778	-118.6514420	
WTD-03	10/30/2026 1:04:00 PM	1.1	2.5	20.5	75.9			0.4	3.7	71.3	71.5	-7.31	-7.31			7.461	7.462	-7.07	0.24	1266	34.4343815	-118.6514653	
WTD-04	10/15/2026 12:24:53 PM	23.1	38.7	4.8	33.4			0.6	6.9	91.0	92.1	-4.98	-4.92			4.971	4.954	-4.99	-0.07	1264	34.4341603	-118.6515983	
WTD-04	10/30/2026 1:07:53 PM	3.5	5.5	18.8	72.2			0.6	3.8	72.8	73.2	-7.31	-7.31			7.405	7.413	-7.07	0.24	1265	34.4341375	-118.6515932	