



**INSPECTION REPORT**

FILE NUMBER <b>04-30-04-0001-061</b>		PAGE 1	OF 1	PAGE 1
NAME OF FACILITY <b>OC Fair &amp; Event Center</b>		HOURS	MINUTES	
NAME OF BUILDING <b>Equestrian Center</b>				
ADDRESS <b>88 Fair Drive, Costa Mesa, CA 92626</b>				
DISCUSSED WITH <b>Jerry Eldridge 714-474-5983</b>		TITLE <b>Director of Facilities</b>		
ACCOMPANIED BY <b>Dean Lassiter 714-656-5598</b>		TITLE <b>Project Manager</b>		


An onsite fire watch survey was conducted by this office on August 27, 2018 at the OC Fair & Event Center accompanied by Dean Lassiter, Chief of Plant. The purpose of the visit was to verify fire watch is being completed as previously required by this office. The following was conducted:

\*A review of the fire watch logs was conducted to ensure compliance.

\*At this time the fire watch program is being followed per OSFM guidelines.

\*\*\*\*\*

END OF REPORT

RECEIVED BY <b>Jerry Eldridge</b>	DATE <b>August 27, 2018</b>
DEPUTY STATE FIRE MARSHAL <b>Jose Duenas</b> 	DATE OF INSPECTION <b>August 27, 2018</b>